

Pavement Condition Report

Frankfort Municipal Airport

Project 13801869

Prepared for:

Indiana Department of Transportation
Office of Aviation
100 N. Senate Ave.
Indianapolis, IN 46204
Indiana Department of Transportation

Prepared by:

Applied Research Associates, Inc.
6314 Odana Rd.
Madison, WI 53719
(608) 274-6409

January 2013



Executive Summary

Background


Since 1995, airports have been required to implement a pavement maintenance-management program to receive funding for any project constructed using Federal money. To assist individual airports in meeting this requirement and help improve airport pavement conditions statewide, the Indiana Department of Transportation, Office of Aviation contracted with Applied Research Associates, Inc. to provide pavement evaluation surveys at local airports. This report documents pavement condition at Frankfort Municipal Airport in August 2012.

A primary objective of the pavement management program is to determine maintenance and rehabilitation needs by comparing pavement condition to a standardized benchmark called the minimum service level (MSL), defined as the minimum pavement condition acceptable in managing Indiana's airfield pavements. The benchmark MSL values used to trigger rehabilitation at Frankfort Municipal Airport are shown below.

Runway	Taxiway	Apron
60	55	55

Pavement Condition

The overall Pavement Condition Index (PCI) for the airfield pavements was 88. Runways had an average inspected PCI of 94 and were above the desired MSL of 60. Taxiways had an average inspected PCI of 93, and ramps had an average inspected PCI of 63.



Capital Improvement Program

The table below provides a summary of the projected pavement rehabilitation needs for the next 5 years of the capital improvement program, starting in 2012. The estimated cost for the rehabilitation actions that provide the greatest increase in pavement service life is approximately \$ 565,000 in 2012 dollars. If no action is taken, the overall PCI is projected to drop to 81 by 2016.

Project Year	Calendar Year	Amount
Year 1	2012	556,313
Year 2	2013	9,136
Year 3	2014	-
Year 4	2015	-
Year 5	2016	-
5-Year Total		\$ 565,449

Maintenance

Analysis of potential maintenance projects identified approximately 1,500 square feet of patching needs and approximately 12,000 linear feet of crack sealing and crack repair needs, at an estimated total cost of approximately \$ 27,000.

Specific recommendations to help prioritize airfield maintenance are found in chapter 4 of this report. A summary of all identified maintenance needs is shown in the table below and in the figure on the following page.

Work Item	Quantity	Unit	Cost
AC PATCH	1,504	SF	\$12,795
AC RESTORATIVE CRACK REPAIR	10,810	LF	\$13,188
AC SUSTAINING CRACK REPAIR	873	LF	\$744
Total:			\$26,727

AC = asphalt concrete; PCC = portland cement concrete; S.F. = square feet; L.F. = linear feet




Table of Contents

1. Introduction	1
1.1 Objective and Scope	1
1.2 Description of Tasks Performed.....	1
2. Pavement Condition Evaluation	7
2.1 Overview.....	7
2.2 Distress Types and Frequency	12
2.3 PCI Summary.....	13
2.4 Analysis Commentary	14
3. Capital Improvement Program.....	15
3.1 Analysis	15
3.2 Cost Estimates	15
3.3 Capital Improvement Strategies	19
4. Maintenance Management Program.....	21
4.1 General Comments	21
4.2 Recommended Maintenance Actions.....	21
4.3 Pavement Deterioration	25
4.4 Best Practices.....	28
4.5 Pavement Repair Materials	31
4.6 Pavement Repair Equipment.....	31
Appendix A. AIRPAV Software.....	33
Appendix B. Feature Analysis.....	35
Appendix C. General Maintenance Techniques.....	81
Appendix D. PCI Summary.....	89
Appendix E. Distress Identification	95
Appendix F. Airport Responsibilities.....	103

Table of Figures

Figure 1-1. Pavement Numbering System	3
Figure 1-2. PCI Value and Descriptive Rating	4
Figure 2-1. Inspected Pavement Condition	8
Figure 2-2. Pavement Condition by Branch Use	9
Figure 2-3. Typical Good PCC Pavement (Feature 3015).....	9
Figure 2-4. Typical Good AC Pavement (Feature 125)	10
Figure 2-5. Typical Satisfactory AC Pavement (Feature 6205)	10
Figure 2-6. Typical Fair AC Pavement (Feature 101)	11
Figure 2-7. Typical Very Poor AC Pavement (Feature 3001)	11
Figure 3-1. Programmed CIP	19
Figure 4-1. Recommended Maintenance	24

Table of Tables

Table 1-1. Minimum Service Levels	1
Table 1-2. Inspection Density	3
Table 2-1. Definition and Distribution of PCI Ratings	7
Table 2-2. Distress Frequency in AC Pavement	12
Table 2-3. Distress Frequency in PCC Pavement	12
Table 2-4. PCI Results	13
Table 2-5. Runway Condition Distribution	14
Table 2-6. Taxiway Condition Distribution	14
Table 2-7. Apron Condition Distribution	14
Table 3-1. Unit Costs.....	16
Table 3-2. Most Comprehensive Repair	19
Table 3-3. Lowest Annual Cost Repair	20
Table 3-4. All Viable Options	20
Table 4-1. Recommend Maintenance Actions	21
Table 4-2. Recommend AC Patching	22
Table 4-3. Recommend AC Restorative Crack Repair.....	22
Table 4-4. Recommend AC Sustaining Crack Repair.....	23
Table 4-5. General Maintenance Policy (AC).....	29
Table 4-6. General Maintenance Policy (PCC).....	30

GLOSSARY OF ABBREVIATIONS

AC	- asphalt concrete
ACC	- asphalt overlay on existing asphalt
APC	- asphalt overlay on existing concrete
APMS	- airport pavement management system
ARA	- Applied Research Associates, Inc.
CADD	- computer-aided design and drafting
CIP	- capital improvement program
FAA	- Federal Aviation Administration
FOD	- foreign object damage
GIS	- geographic information system
INDOT	- Indiana Department of Transportation
L&T	- longitudinal and transverse
LTD	- longitudinal, transverse, and diagonal
M&R	- maintenance and rehabilitation
MSL	- minimum service level
PCC	- portland cement concrete
PCI	- Pavement Condition Index
PCN	- Pavement Classification Number
PDF	- portable electronic document

1. Introduction

1.1 Objective and Scope

The Indiana Department of Transportation, Office of Aviation (INDOT) retained Applied Research Associates, Inc., (ARA) to provide airfield pavement inspection, pavement evaluation, and pavement management services for Indiana’s statewide network of airfield pavements. The pavement evaluations documented in this report were performed under purchase order number 13801869.

A primary objective of INDOT’s ongoing pavement evaluation and management program is to determine maintenance and rehabilitation (M&R) needs by comparing the Pavement Condition Index (PCI) to a standardized benchmark called the minimum service level (MSL). The MSL is defined as the minimum pavement condition acceptable in managing INDOT’s airside pavement. The benchmark MSL values used to trigger rehabilitation vary by airport classification and are shown in Table 1-1.

Table 1-1. Minimum Service Levels

Facility	Primary	Commercial Service	Large GA > 3600’Rwy	Large GA < 3600’Rwy
Runway	70	65	60	55
Taxiway	65	60	55	50
Apron	65	60	55	50

Additional goals of this project were to implement a software program to manage the pavement network, develop performance curves based on historical rates of pavement deterioration, forecast future pavement conditions, identify and recommend specific M&R actions to address the root cause of the documented pavement distress, and estimate the cost and ideal timing of the recommend M&R. The following tasks were performed in support of the project goals:

- Review record documents
- Define the pavement network
- Conduct an airfield condition survey
- Update the AIRPAV database & software
- Develop a 5-year airfield M&R work plan
- Report findings to INDOT

1.2 Description of Tasks Performed

1.2.1 Records Review

A detailed records review was performed to determine the airport’s construction history and the as-built cross section for each pavement feature. Plan sets for recent projects were provided to ARA in computer-aided design and drafting (CADD) format. Older plans sets were provided as hard copies or in portable electronic document (PDF) format.

1.2.2 Define Pavement Network

Prior to the field survey, a pavement network map was developed using available aerial photography and construction plans. The map was divided into facilities, features, and sample units. A facility is defined as a complete area of the airfield that is used for a particular type of operation. Facilities are typically named for complete functional elements of pavement, such as Runway 11-29, Taxiway A, or North Terminal Apron. After facilities are defined, they are divided into features based on pavement type, construction, structure, and usage. Note that the terms branch and section may be used interchangeably with facility and feature throughout this report.

Features are divided into sample units as prescribed by ASTM D5340-11, *Standard Test Method for Airport Pavement Condition Index Surveys*. A sample unit is a subdivision of a section used exclusively to aid in the inspection process and reduce the effort needed to determine distress quantities and the PCI. The specified sample unit size for an asphalt concrete (AC) pavement is $5,000 \text{ ft}^2 \pm 2,000 \text{ ft}^2$. Sample units on portland cement concrete (PCC) pavements contain 20 ± 8 slabs.

To allow users to search, sort, and identify airport pavement quickly, a numbering system is used in conjunction with the facility, feature, and sample unit convention. The format starts with facility, then feature, and finally identifies the sample unit. The number 1605.300 is parsed as an example in Figure 1-1. Most pavement references in this report are presented in this format.

Using statistical sampling methods, the PCI procedure provides a high confidence level in evaluating overall pavement condition while sampling only a portion of the pavement surface. Table 1-2. shows the network-level inspection density used on this project. Where appropriate, “additional sample units” were identified and inspected to record pavement areas with distress patterns not representative of the overall pavement condition. The unique distress types documented in additional sample units are not extrapolated across the entire feature.

As the surveyors inspected the pavement, they were mindful to ensure that the pre-survey airfield map depicted the actual pavement, otherwise known as a “ground-truth” survey. Noticeable differences between what was present in the field and what was displayed on the maps were adjusted by a CADD technician.




Figure 1-1. Pavement Numbering System

Table 1-2. Inspection Density

Sample Unit in Feature	Inspected Sample Units
1-2	ALL
3-4	2
5-7	3
8-10	4
11-14	5
15-19	6
20-25	7
26-30	8
31-37	9
38-45	10
46-55	11
56-80	12
> 80	15%

1.2.3 Conduct Airfield Condition Survey

The pavement condition surveys were performed in accordance with ASTM D5340-11. The procedure is based on the identification and measurement of visible distress at the pavement surface. Each PCI distress will deduct from the pavement's perfect condition of 100. Using pavement management software (or curves provided in ASTM D5340-11), a deduct value is determined for each combination of distress type, severity, and measured quantity. The PCI value is then determined from the unique combination of these variables.

A primary benefit of the PCI procedure is the ability to perform objective evaluations and compare pavement condition with an easy-to-understand numerical rating. Because the combined impact of multiple distresses is not cumulative, ASTM D5340-11 provides an additional family of curves to adjust for multiple distresses. The PCI is determined by applying the individual deduct value for each distress type along with any required correction factors to account for multiple distress types.

Figure 1-2. shows the relationship between PCI values, descriptive ratings, and typical repair actions. Generally, pavement maintenance is most cost-effective when the pavement is still in satisfactory condition. Rehabilitation, such as an asphalt mill and inlay, is typically performed for pavements with PCI values between 55 and 70. When the PCI value drops below 55, a mill and inlay may not provide the desired performance, and complete reconstruction often becomes the most cost-effective means of repairing the pavement.




Figure 1-2. PCI Value and Descriptive Rating

1.2.4 Update AIRPAV Database & Software

The network definition, construction history, and data from the survey were entered into the AIRPAV pavement management system (APMS) software. After all data were entered, family curves were developed to model the change in pavement condition over time. These family curves are used to estimate future pavement condition. Typically, several curves are developed, with separate curves defined for different pavement surface types, such as AC, PCC, asphalt overlay on existing asphalt (ACC), and asphalt overlay on existing concrete (APC). The latest version of AIRPAV containing all survey data, deterioration curves, M&R policies, budgets, and construction history, was provided to INDOT on CD-ROM.

1.2.5 Develop 5-Year Airfield M&R Work Plans

A 5-year capital improvement program (CIP) was developed showing the year that each pavement feature was expected to fall below the MSL. The 5-year plan detailed in chapter 3 shows rehabilitation alternatives for each feature based on the PCI and the individual distress types observed during the pavement evaluation. The timing of each project is shown as the year that the PCI falls below the MSL and does not consider other important factors. Using reports like this for each airport in the State, INDOT engineers and planners develop a final 5-year statewide CIP plan that balances the sometimes conflicting priorities of pavement condition, operational constraints, construction staging considerations, and available funding.

1.2.6 Report Finding to INDOT

This report includes background information, PCI results and recommendations, and M&R budget scenarios. Photographs depicting typical pavement conditions observed during the survey are included in chapter 2. Appendix A contains general information about the AIRPAV pavement management software. Appendix B provides an analysis of each pavement section based on recorded distress. Appendix C contains a summary of general maintenance techniques and best practices. Appendix D provides a detailed summary of the airfield pavement condition. Appendix E describes common airfield distress types, and Appendix F contains exhibits to help the airport owner manage the airfield pavement system.

2. Pavement Condition Evaluation

2.1 Overview

Using statistical sampling methods, approximately one third of the total 1 million square feet of airside pavement was surveyed as part of this assessment. The average inspected PCI for all pavements was 88 (Good). The average inspected PCI for the runways, taxiways, and ramps were as follows: 94 (Good), 93 (Good), and 63 (Fair). Table 2-1 provides a general description of the PCI rating categories, including a simplified rating scale of Good, Fair, and Poor. This table also shows the associated distress levels and general M&R requirements for each rating category.

Table 2-1. Definition and Distribution of PCI Ratings

Simplified PCI Rating	PCI Range	Definition	Pavement Area (ft ²)	Pavement Area (%)
Good	86-100	GOOD: Pavement has minor or no distresses and requires only routine maintenance.	845,761	84%
	71-85	SATISFACTORY: Pavement has scattered low-severity distresses that need only routine maintenance.	3,950	1%
Fair	56-70	FAIR: Pavement has a combination of generally low- and medium-severity distresses. M&R needs are routine to major in the near future.	21,480	2%
Poor	41-55	POOR: Pavement has low-, medium-, and high-severity distresses that probably cause some operational problems. Near-term maintenance and repair needs may range from routine up to a requirement for reconstruction.	101,526	10%
	26-40	VERY POOR: Pavement has predominantly medium- and high-severity distresses that cause considerable maintenance and operational problems. Near-term maintenance and repair needs will be intensive in nature.	30,204	3%
	11-25	SERIOUS: Pavement has mainly high-severity distresses that cause operational restrictions; immediate repairs are needed.	-	-
	0-10	FAILED: Pavement deterioration has progressed to the point that safe operations are no longer possible; complete reconstruction is required.	-	-

Five pavement sections had a simplified PCI rating of Poor, indicating that intensive maintenance and/or major M&R is needed to maintain serviceability. The pavement within each of the PCI condition categories is shown in Figure 2-1. The inspected PCI is summarized by branch use in Figure 2-2, and the photographs in Figure 2-3 through Figure 2-7 provide examples of the condition categories.




Figure 2-1. Inspected Pavement Condition




Figure 2-2. Pavement Condition by Branch Use



Figure 2-3. Typical Good PCC Pavement (Feature 3015)



Figure 2-4. Typical Good AC Pavement (Feature 125)



Figure 2-5. Typical Satisfactory AC Pavement (Feature 6205)



Figure 2-6. Typical Fair AC Pavement (Feature 101)



Figure 2-7. Typical Very Poor AC Pavement (Feature 3001)

2.2 Distress Types and Frequency

The inspectors surveyed approximately 300,000 ft² of AC pavement. The frequency of each distress type is shown in Table 2-2. The most common distress types were longitudinal and transverse (L&T) cracking, weathering, alligator cracking, and ravelling. L&T cracking, weathering, and ravelling are climate-related distresses, and alligator cracking is a load-related distress.

Table 2-2. Distress Frequency in AC Pavement

Distress	Sample Units	% Inspected Sample Units
L&T CRACKING	54	68
WEATHERING	16	20
ALLIGATOR CRACKING	11	14
RAVELING	10	13
DEPRESSIONS	8	10
RUTTING	6	8
BLOCK CRACKING	4	5
PATCHING	2	3
OIL SPILLAGE	1	1
SLIPPAGE CRACKING	1	1
SWELL	1	1

The inspectors surveyed approximately 7,200 ft² of PCC pavement. No PCI distress types were recorded on the airfield PCC pavement at Frankfort Municipal Airport.

Table 2-3. Distress Frequency in PCC Pavement

Distress	Sample Units	% Inspected Sample Units	Slabs	% Inspected Slabs
-	-	-	-	-

2.3 PCI Summary

The branch and section PCI values are shown below, along with the surface type, area, and last year construction occurred.

Table 2-4. PCI Results

Branch ID	Branch PCI	Section	Surface	Area (ft ²)	Built	2009 PCI	2012 PCI
100 (Taxiway)	96	101	AC/AC	6,480	1990	67	56
		105	AC/AC	15,000	2003	84	70
		110	AC/AC	3,950	2008	95	83
		125	AC	79,558	2010	-	100
		130	AC	21,188	2010	-	100
		135	AC	97,166	2012	-	100
200 (Taxiway)	79	201	AC	24,486	1985	51	54
		210	AC	4,090	1990	54	46
		225	AC	35,356	2012	-	100
3000 (Ramp)	56	3001	AC	30,204	1985	45	29
		3002	AC	6,650	1985	39	48
		3015	PCC	14,500	2003	100	100
		3020	AC	7,820	2012	-	100
4100 (Hangars)	66	4105	AC	66,300	1999	54	49
		4110	AC	43,200	2005	98	92
6100 (Runway9-27)	96	6105	AC/AC	375,000	2009	-	96
6200 (Runway 4-22)	90	6205	AC/AC	96,538	2008	96	89
		6210	AC/AC	36,110	2008	96	91
		6215	AC	30,025	2009	100	90
		6220	AC/AC	9,300	2009	100	94

2.3.1 Sections with PCI increase since last inspection

During the 2009 PCI Inspection Section 201 had a total area of roughly 50,000sf. Section 201 now has a total area of roughly 25,000 because much of the original section 201 pavement was newly reconstructed as Section 225. Similar to section 201, roughly half of section 3002 was newly reconstructed as part of feature 225.

2.4 Analysis Commentary

The following pages provide a brief overview of the 2012 inspected pavement conditions for each facility. Comments are based primarily on the AIRPAV analysis but also include field notes and remarks from the pavement condition inspectors. Where appropriate, individual pavement sections are referenced within the larger facility.

2.4.1 Runways

Runway 9-27 consisted of 1 section (6105) of AAC pavement, with a total area of 375,000 ft² and an area-weighted PCI of 96 (Good). Runway 4-22 consisted of 4 sections of AC and AAC pavement, with a total area of approximately 172,000 ft² and an area-weighted PCI of 90 (Good). The distribution of runway pavement by PCI range is shown in Table 2-5.

Table 2-5. Runway Condition Distribution

PCI Range	Rating	Number of Sections	Pavement Area (ft ²)	Pavement Area (%)
100-71	Good	5	546,973	100
70-56	Fair	-	-	-
55-0	Poor	-	-	-

2.4.2 Taxiways

The taxiways consisted of 9 sections of AC and AAC pavement. The total area of the taxiways was 287,274 ft². The area-weighted average PCI was 93 (Good). The distribution of taxiway pavement area and sections by PCI range is shown in Table 2-6.

Table 2-6. Taxiway Condition Distribution

PCI Range	Rating	Number of Sections	Pavement Area (ft ²)	Pavement Area (%)
100-71	Good	5	237,218	83
70-56	Fair	2	21,480	7
55-0	Poor	2	28,576	10

2.4.3 Aprons

The aprons consisted of 6 sections of AC and PCC pavement. The total area of apron pavements was 103,154 ft², and the area-weighted average PCI was 63 (Fair). The distribution of pavement area and sections by PCI range are shown in Table 2-7.

Table 2-7. Apron Condition Distribution

PCI Range	Rating	Number of Sections	Pavement Area (ft ²)	Pavement Area (%)
100-71	Good	3	65,520	39
70-56	Fair	-	-	-
55-0	Poor	3	103,154	61

3. Capital Improvement Program

3.1 Analysis

The individual feature analyses shown in appendix B document viable rehabilitation projects that address the causes of each pavement section failure while restoring the pavement to a condition above the desired MSL. The recommended timing of each improvement action is defined as the year that the pavement condition is projected to reach the MSL. By establishing benchmark MSL targets, it is possible to plan objectively for future needs against a standard set of performance criteria. This section categorizes the identified viable options into CIP strategies based on cost and expected service life.

The airport may find it desirable to adjust the timing of projects detailed in the CIP to meet fiscal and operational constraints. For example, if different sections of a runway were projected to reach the MSL in various years ranging from 2013 to 2015, it is not operationally feasible to stage rehabilitation over a 3-year period. Instead, runway rehabilitation would be programmed in a manner that balanced the need to minimize the length of the runway closure while maximizing the remaining service life.

3.2 Cost Estimates

Project costs were estimated based on the pavement area and the unit costs shown in Table 3-1 for specific M&R activities. Project costs are presented so planners and managers can compare the relative magnitude of funding required for various alternatives. The two-page AIRPAV feature analysis (see appendix B) provides cost estimates for each identified project. These cost estimates are for planning purposes only and do not constitute an engineering estimate.

Furthermore, these costs estimates represent the improvement of existing pavement structures and associated incidental work only. Other potential project line items, such as lighting, navigational aids, and drainage modifications are not included, and estimates for those items must be developed separately and incorporated into an overall project cost.

Typical examples of work that might be included in alternatives evaluated by AIRPAV are outlined on the following pages. These example projects would meet the requirements for each selected option; however, the descriptions are not intended to imply required, or even preferred, design configurations. Rehabilitation decisions, such as overlay thickness design, should be made in conjunction with engineering design analysis.

Table 3-1. Unit Costs

Rigid Pavement (PCC)	
Reconstruction	\$12.65 /sf
Slab Replacement & Full Depth Patching	\$12.24 /sf
Patching (Partial Depth)	\$16.37 /sf
Slab Repair & Overlay	\$4.60 /sf + \$0.40 /sf/in > 4"
Joint Seal Replacement	\$2.20 /lf
Joint Seal Repair	\$0.85 /lf
Undersealing	\$4.08 /sf
Flexible Pavement (AC)	
Reconstruction	\$5.25 /sf
Resurfacing	\$1.41 /sf
Structural Overlay	\$2.21 /sf + \$0.40 /sf/in > 4"
Surface Treatment	\$0.38 /sf
Patching	\$9.74 /sf
Crack Repair (Restorative)	\$1.22 /lf
Crack Repair (Sustaining)	\$0.85 /lf

3.2.1 Rigid Pavement Work Descriptions

The following descriptions provide additional information about the typical work items covered by the unit costs shown in Table 3-1.

3.2.1.1 Reconstruction

Reconstruction is recommended when the pavement defects would not be corrected by less extensive measures. Unit prices assume removal of the existing pavement to the subgrade and reconstruction pavement with 8 inches of high strength PCC pavement on 6 inches of aggregate subbase.



3.2.1.2 Repair and Overlay

This procedure usually consists of a crack and seat process, where the existing pavement is broken into segments of approximately 2 ft on a side by dropping a heavy breaker bar onto the pavement. Properly done, aggregate interlock between pavement segments is retained and reflective cracking is reduced. A flexible surface is then placed over the recycled PCC base.



3.2.1.3 Slab Replacement

Slab replacements are typically required for high-severity blow ups, scaling, and shattered slabs. Unit prices assume removal of the selected slab to the subgrade. Prepare subgrade to bearing strength equivalent to surrounding subgrade. Provide subbase support equivalent to existing and install load transfer steel as required. Place PCC pavement level with existing surface.



3.2.1.4 Patching (Partial Depth)

While partial depth patching is most commonly used to repair joint and corner spalls, it is effective for a wide variety of distress types. Saw cut and remove area of pavement to sound concrete above reinforcing steel. Treat existing concrete to ensure firm bond. Place PCC level with existing surface.



3.2.1.5 Joint Seal Replacement

Rout joints and cracks to a depth of at least 1-1/4 inches, clean joint wall surfaces to expose fresh vital concrete, install backing rope, and apply rubberized sealant meeting ASTM D3405 specification, or equivalent.



3.2.1.6 Joint Seal Repair

Press existing sealant into joint for use as backer material; apply joint sealant meeting ASTM D3405 specification, or equivalent.

3.2.1.7 Undersealing

Undersealing is used to repair faulting between slabs or when corner breaks have settled relative to the slab. High-pressure injection is used to force material into the underlying voids and continues until the settled pavement is restored to its original elevation. Several materials have been used for undersealing, including cement grout, asphalt slurries, and proprietary formulations of expansive Styrofoam.



3.2.2 Flexible Pavement Work Descriptions

3.2.2.1 Reconstruction

Reconstruction is recommended when the pavement defects would not be corrected by less extensive measures. Unit prices assume removal of existing pavement to subgrade. Scarify and compact subgrade to 6-inch depth. Construct 4 inches of P401 AC surface course on 8 inches of aggregate base course.



3.2.2.2 Resurfacing

Resurfacing assumes a nominal 2-inch asphalt mill and inlay on existing prepared pavement.



3.2.2.3 Structural Overlay

Structural overlays are used to address load related distress or to increase pavement load bearing capacity. Apply a 4-inch AC overlay on existing prepared pavement. Add additional thickness as needed to achieve required strength.

3.2.2.4 Surface Treatment

Apply a high-quality, penetrating rejuvenating sealer. Surface treatments are a cost effective way to address weathering and raveling. They perform best when applied to pavement that is still in fair to satisfactory condition.



3.2.2.5 Patching

Apply a high-quality, penetrating rejuvenating sealer.

3.2.2.6 Crack Repair (Restorative)

Apply a high-quality, penetrating rejuvenating sealer. This is typically a large project with significant prep work.

3.2.2.7 Crack Repair (Sustaining)

Apply a high-quality, penetrating rejuvenating sealer. This is typically spot repairs of existing crack sealant.



3.3 Capital Improvement Strategies

Figure 3-1 shows a projection of the overall airport pavement condition for the next 10 years based on implementing one of three capital improvement strategies:

- No Action: No capital improvement action is undertaken
- Longest Life: The most comprehensive repair and longest life rehabilitation option
- Lowest Cost: The rehabilitation option with the projected lowest annual cost




Figure 3-1. Programmed CIP

The longest life CIP scenario is projected to cost approximately **\$590,000** over the next 10 years. The lowest annual cost scenario is projected to cost approximately **\$230,000** over the next 10 years. Examples of each capital improvement strategy and a complete listing of all viable capital projects are presented in Table 3-2 through Table 3-4.

Table 3-2. Most Comprehensive Repair

Feature	Built	Description	Action Yr	Work Item	Cost, \$
101	1990	NORTH TAXIWAY	2013	Resurfacing	9,136
105	2003	NORTH TAXIWAY	2020	Resurfacing	21,149
201	1985	TAXIWAY B	2012	Resurfacing	34,525
210	1990	TAXIWAY B	2012	Resurfacing	5,766
3001	1985	RAMP	2012	Reconstruction	158,571
3002	1985	FUELING RAMP	2012	Resurfacing	9,376
4105	1999	TEE HANGARS	2012	Reconstruction	348,075
Total					586,598

Table 3-3. Lowest Annual Cost Repair

Feature	Built	Description	Action Yr	Work Item	Cost, \$
101	1990	NORTH TAXIWAY	2013	Crack Repair	585
105	2003	NORTH TAXIWAY	2020	Surface Treatment	6,163
201	1985	TAXIWAY B	2012	Resurfacing	34,525
210	1990	TAXIWAY B	2012	Resurfacing	5,766
3001	1985	RAMP	2012	Structural Overlay	54,669
3002	1985	FUELING RAMP	2012	Resurfacing	9,376
4105	1999	TEE HANGARS	2012	Structural Overlay	120,002
				Total	231,086

Table 3-4. All Viable Options

Feature	Built	Description	Action Yr	Work Item	Cost, \$
101	1990	NORTH TAXIWAY	2013	Crack Repair	585
101	1990	NORTH TAXIWAY	2013	Surface Treatment	2,728
101	1990	NORTH TAXIWAY	2013	Resurfacing	9,136
105	2003	NORTH TAXIWAY	2020	Crack Repair	1,256
105	2003	NORTH TAXIWAY	2020	Surface Treatment	6,163
105	2003	NORTH TAXIWAY	2020	Resurfacing	21,149
201	1985	TAXIWAY B	2012	Crack Repair	2,532
201	1985	TAXIWAY B	2012	Surface Treatment	10,564
201	1985	TAXIWAY B	2012	Resurfacing	34,525
210	1990	TAXIWAY B	2012	Crack Repair	1,577
210	1990	TAXIWAY B	2012	Surface Treatment	2,063
210	1990	TAXIWAY B	2012	Resurfacing	5,766
3001	1985	RAMP	2012	Surface Treatment	12,494
3001	1985	RAMP	2012	Structural Overlay	54,669
3001	1985	RAMP	2012	Reconstruction	158,571
3002	1985	FUELING RAMP	2012	Surface Treatment	2,900
3002	1985	FUELING RAMP	2012	Resurfacing	9,376
4105	1999	TEE HANGARS	2012	Surface Treatment	27,192
4105	1999	TEE HANGARS	2012	Structural Overlay	120,002
4105	1999	TEE HANGARS	2012	Reconstruction	348,075

4. Maintenance Management Program

4.1 General Comments

Most pavement distress is classified by severity (low, medium, or high). As a general rule, high-severity distresses should be patched, and medium-severity distress should be sealed. A detailed matrix of recommended maintenance policies to address various distress types is provided near the end of this section.

4.1.1 Inspected Crack Severity

Of the inspected pavement, 68 percent of the cracks were rated at low severity and require no maintenance beyond ongoing inspection and spot repair. About 29 percent of the cracks were rated at medium severity and would benefit from sealing and repair. About 1 percent of the cracks were rated at high severity and warrant patching to maintain safe operations.

4.1.2 Other Distress

In asphalt pavement, area measured distresses such as rutting, depressions, fatigue cracks, and raveling were recorded at low severity levels 84 percent of the time, medium severity 15 percent of the time, and high severity 1 percent of the time.

4.2 Recommended Maintenance Actions

The following illustrations and tables show pavement areas that have maintenance and repair needs. Ongoing development of capital improvement projects may address some of these maintenance needs. To help budgeting and prevent duplication of effort, all pavement features recommended for maintenance should be compared to planned improvements prior to finalizing a maintenance program strategy.

Table 4-1. Recommend Maintenance Actions

Work Item	Quantity	Unit	Cost
AC PATCH	1,504	SF	\$12,795
AC RESTORATIVE CRACK REPAIR	10,810	LF	\$13,188
AC SUSTAINING CRACK REPAIR	873	LF	\$744
Total:			\$ 26,727

In the following tables, pavement features shown in **grey** text cannot be raised above MSL via maintenance alone, and need only be included in a maintenance plan to provide continued safety or serviceability until their programmed major rehabilitation is implemented.

4.2.1 Patching

Table 4-2. Recommend AC Patching

Feature	Work Item	Amount	Insp. PCI	Change	Est. PCI
101	AC PATCH	21	56	16	72
201	AC PATCH	109	54	27	81
210	AC PATCH	9	46	-	46
3001	AC PATCH	957	29	20	49
4105	AC PATCH	406	49	22	71
	TOTAL:	1,504	S.F.		
EQUIPMENT: SAW, AIR COMPRESSOR, HEATING KETTLE, HAND TOOLS					
EST. MATERIALS: 18 TONS ASPHALT PATCH					
EST. MATERIAL COST: \$1,838					
EST. CREW HOURS: 43.0					
EST. CREW COST: \$10,957					
EST. PROJECT COST: \$12,795					

4.2.2 Crack Seal

Table 4-3. Recommend AC Restorative Crack Repair

Feature	Work Item	Amount	Insp. PCI	Change	Est. PCI
101	AC RESTORATIVE CRACK REPAIR	475	56	5	61
105	AC RESTORATIVE CRACK REPAIR	1,030	70	4	74
110	AC RESTORATIVE CRACK REPAIR	107	83	8	91
201	AC RESTORATIVE CRACK REPAIR	2,076	54	2	56
210	AC RESTORATIVE CRACK REPAIR	720	46	18	64
3002	AC RESTORATIVE CRACK REPAIR	724	48	4	52
4105	AC RESTORATIVE CRACK REPAIR	5,359	49	1	50
6210	AC RESTORATIVE CRACK REPAIR	318	91	4	95
	TOTAL:	10,810	L.F.		
EQUIPMENT: AIR COMPRESSOR, HEATING KETTLE, HAND TOOLS					
EST. MATERIALS: 2,162 POUNDS ASTM D3405 SEALANT OR EQUIVALENT					
EST. MATERIAL COST: \$2,162					
EST. CREW HOURS: 54.1					
EST. CREW COST: \$11,026					
EST. PROJECT COST: \$13,188					

Table 4-4. Recommend AC Sustaining Crack Repair

Feature	Work Item	Amount	Insp. PCI	Change	Est. PCI
3001	AC SUSTAINING CRACK REPAIR	530	29	-	29
4110	AC SUSTAINING CRACK REPAIR	46	92	-	92
6205	AC SUSTAINING CRACK REPAIR	285	89	-	89
6220	AC SUSTAINING CRACK REPAIR	10	94	-	94
	TOTAL:	873	L.F.		
EQUIPMENT: AIR COMPRESSOR, HEATING KETTLE, HAND TOOLS					
EST. MATERIALS: 175 POUNDS ASTM D3405 SEALANT OR EQUIVALENT					
EST. MATERIAL COST: \$174					
EST. CREW HOURS: 3.8					
EST. CREW COST: \$569					
EST. PROJECT COST: \$744					




Figure 4-1. Recommended Maintenance

4.3 Pavement Deterioration

Before attempting maintenance and repairs, it helps to understand pavement performance and pavement deterioration. The factors that contribute most to deterioration are environmental, materials, and/or load related. Brief discussions of each are presented in the following sections.

4.3.1 *Environmental/Age-Related Deterioration*

Seasonal and daily temperature changes cause expansion and contraction of the pavement materials. The shear stresses created by expansion and contraction can cause transverse cracking in flexible pavement and mid-slab cracking in rigid pavement. Further, expansion and contraction will cause cracks, and rigid pavement joints, to open and close with changes in temperature.

Flexible pavement oxidizes as it ages, losing its lighter, volatile, components and becoming brittle with time. Surface treatments and seal coats are designed, in part, to provide a protective barrier and prevent this type of oxidation.

Subsurface water can have the greatest impact on pavement deterioration. A wet subgrade greatly reduces the ability of a pavement to support wheel loads, and the results often show up as rutting and cracking of flexible pavement. The fine materials in a wet base can be pumped up through the cracks and eventually result in a loss of support. This loss of support can be evidenced as corner breaks and faulting in rigid pavement. Moisture inside a pavement system expands when it freezes, creating stresses that cause the pavement surface to heave. Subsequent freeze-thaw cycles leave voids in the pavement structure that enable further rutting and breaking. Repeated freeze-thaw cycles eventually cause the pavement to disintegrate. Freeze-thaw deterioration requires frost-susceptible material, sub-zero temperatures, and water. If we remove one of these factors, freeze-thaw damage will not occur. One of the best ways to ensure pavement longevity is to provide drainage and keep it dry.

4.3.2 *Materials-Related Deterioration*

The pavement thickness and type of subgrade play a large role in the formation and spacing of transverse cracks. If the subgrade and base materials are smooth or rounded and allow for relatively free movement of the pavement surface, transverse cracks will often be spaced far apart (>60 feet). If the subgrade and base material are rough or angular and provide greater resistance to movement of the pavement surface, transverse cracks will be spaced more closely (<40 feet). The distance between transverse cracks also depends on the pavement thickness, as a thicker pavement can resist cracking for longer lengths. At general aviation airport pavements, around 50 feet is typical transverse crack spacing.

Aggregate is the biggest component of any pavement structure, and it is the contact between the aggregate particles that actually transfers the load and provides the strength. Aggregate durability and shape are major factors affecting pavement performance. Durability is the ability of the aggregate to perform satisfactorily over time and resist deterioration. Sharp, well-angled aggregates that interlock, compact densely, and resist movement are the most desirable.

In flexible pavement, the selection of asphalt cement can have a significant impact on pavement performance. Asphalt is visco-elastic, which means it is stiff at low temperatures and flows at high temperatures. With this in mind, we expect asphalt pavement to remain stiff on hot summer days to resist plastic deformation (rutting and shoving). In addition, we expect asphalt pavement to have

sufficient cold temperature flexible on cold winter days to resist transverse cracking. The proper selection of asphalt cement grade and maintaining adequate mix volumetrics (air voids, voids in the mineral aggregate, etc.) are key factors in the performance of flexible pavement.

As water freezes, it expands and occupies a greater volume than in a liquid state. In PCC pavement, interconnected, well-distributed air voids are required to allow for expansion of moisture with the PCC. PCC mixes with insufficient air entrainment are susceptible to freeze-thaw damage, as the expansive forces have been shown to cause concrete deterioration. Small, closely spaced, interconnected air voids provide the greatest degree of protection.

Asphalt paving mixes also require air voids, but for reasons different than for PCC pavement. When a well-constructed asphalt pavement is subjected to vehicle loading, it will nevertheless experience some minor secondary consolidation. Air voids allow for the safe movement of the asphalt binder within the mix. With insufficient air voids, the asphalt binder will migrate to the surface of the pavement—it will in essence, get squeezed out of the mix. This phenomenon is called flushing. In addition, these mixes become unstable and are prone to rutting in the wheel paths.


However, if the air voids become too high, air and water can penetrate the pavement, reducing both durability and flexibility. Air infiltration will accelerate oxidization of the binder, while water penetration will increase the moisture susceptibility of the mix (i.e., stripping of the asphalt cement from the aggregate). Air voids in flexible pavement should be kept low enough to prevent water and air from penetrating the asphalt layers, but high enough to minimize the potential of plastic deformation.

Regardless of whether the pavement binder is AC or PCC, binder materials are mixed with aggregate to coat all aggregate particles with a thin binder film. Durability of flexible asphalt pavement is increased with a thicker binder film, and the pavement becomes more resistant to age hardening; however, if the film is too thick, the asphalt acts like a lubricant, promoting ruts, shoving, and bleeding. Each asphalt mix should be customized for materials available locally.

With a concrete pavement, aggregate interlock supports the wheel loads, and the hydrated cement binder further interlocks the aggregate particles to inhibit all movement. “Hydration” is the term for the chemical reaction of portland cement with water. In the hydration process, dry cement particles react with water to form gels, and then crystals, that grow and bond with the aggregate and form a rigid interlocking structure. Hydration can continue for years, but much of the ultimate strength will be reached within 28 days. Hydration is a sensitive chemical process. Typically, any admixtures used to accelerate the hydration process will reduce durability, and admixture use should be considered carefully or avoided.

4.3.3 Load-Related Deterioration

As illustrated below, rigid and flexible pavements differ in the way loads are distributed. A concrete slab resists bending and transfers loads evenly, while an asphalt pavement is designed to bend, gradually spreading loads over wider areas.



Load-related cracks can start at the top or bottom of a pavement section. In asphalt sections, load-related (fatigue) cracks start at the bottom. If a load-related crack reaches the surface, it usually indicates structural deficiency. In rigid pavement, corner breaks are caused by tensile forces at the top of the slab, and the crack propagates downward. Mid-slab LTD cracks are distress examples resulting from tensile forces at the bottom of the slab.

Both wheel loads and environmental factors can cause spalls anytime there is movement between adjacent slabs. If non-compressible material (such as a small rock) is allowed into a joint, stresses will build up between adjacent slabs and can cause a spall. Keeping joint and crack sealant intact can help to reduce the infiltration of non-compressible material and minimize spalling.

4.4 Best Practices

4.4.1 Flexible Pavement

L&T cracks at medium severity should be filled with a good quality crack sealant material. High-severity cracks normally must be patched.

Cracks rated at low severity may be narrow unsealed cracks or sealed cracks up to 3 inches wide. The PCI procedure does not distinguish between narrow unfilled cracks and wider filled cracks. Some L&T cracks at low severity are included in the estimated sealing quantities and costs in this maintenance plan. In general, when medium- or high-severity cracking constitutes less than 25 percent of the total crack quantity, sustaining maintenance usually is more cost-effective. When 25 percent or more of the total crack quantity is at medium or high severity, a restorative program typically becomes more cost-effective.

Existing patches rated as medium and high severity should be replaced with new patches. Small areas (usually less than 100 square feet per patch) of alligator cracking and rutting at medium and high severity also may be repaired cost-effectively by patching. Larger patches should be considered if equipment can be made available to accomplish the work. Patching to repair up to 10 percent of the surface of a pavement feature that is otherwise serviceable can result in significant cost savings as compared to rehabilitation of the entire feature.

An example maintenance policy treatment matrix for flexible pavement is shown in Table 4-5. Examples of various maintenance techniques are provided in appendix C.

4.4.2 Rigid Pavement

Joint seal damage rated at medium and high severity should be repaired. If medium- and high-severity damage is limited to less than about 25 percent of the total joint length, sustaining maintenance is recommended. If medium- and high-severity damage exceeds 25 percent of the total joint length, the joint sealant should be removed and replaced under a restorative repair project.

LTD cracks at low and medium severity should be considered for sealing as part of the joint sealing project. High-severity LTD cracks require sealing, patching, or slab replacement, depending on the extent of deterioration.

Small patches are typically used to repair medium- and high-severity spalls or to replace deteriorated older patches. Restorative small patches are typically partial-depth repairs, usually to a maximum depth of 1/3 of the slab thickness. Large patches and corner breaks at medium and high severity should be repaired by full-depth large patches.

High-severity LTD cracks and shattered slabs are candidates for patching and slab replacement. Low-severity shattered slabs can be left in place pending further deterioration.

An example maintenance policy treatment matrix for rigid pavement is shown in Table 4-5. Examples of various maintenance techniques are provided in appendix C.

Table 4-5. General Maintenance Policy (AC)

Distress Type	Distress Severity	Maintenance Action
Alligator Cracking	Low	Crack Sealing - AC
	Medium	Patching - AC Deep
	High	Patching - AC Deep
Bleeding	N/A	Monitor
Depression	Low	Monitor
	Medium	Patching - AC Shallow
	High	Patching - AC Deep
Jet Blast	N/A	Patching - AC Shallow
Longitudinal, Transverse, Joint Reflective, & Block Cracking	Low	Monitor
	Medium	Crack Sealing - AC
	High	Patching - AC Deep
Oil Spill	N/A	Patching - AC Shallow
Patching	Low	Monitor
	Medium	Crack Sealing - AC
	High	Patching - AC Deep
Polished Aggregate	N/A	Monitor
Weathering / Raveling	Low	Monitor
	Medium	Surface Treatment
	High	Patching - AC Shallow
Rutting, Corrugation and Swell	Low	Monitor
	Medium	Patching - AC Deep
	High	Patching - AC Deep
Shoving	Low	Monitor
	Medium	Patching - AC Shallow
	High	Patching - AC Deep
Slippage Cracking	N/A	Patching - AC Shallow

Table 4-6. General Maintenance Policy (PCC)

Distress Type	Distress Severity	Maintenance Action
Blow Up	Low	Patching - PCC Partial Depth
	Medium	Slab Replacement - PCC
	High	Slab Replacement - PCC
Longitudinal, Transverse & Diagonal Cracking	Low	Monitor
	Medium	Crack Sealing - PCC
	High	Patching - PCC Full Depth
Durability Cracking	Low	Monitor
	Medium	Patching - PCC Full Depth
	High	Slab Replacement - PCC
Large Patch & Corner Break	Low	Monitor
	Medium	Patching - PCC Full Depth
	High	Patching - PCC Full Depth
Popout / Shrinkage Cracks	N/A	Monitor
Scaling	Low	Monitor
	Medium	Patching - PCC Partial Depth
	High	Slab Replacement - PCC
Faulting	Low	Monitor
	Medium	Grinding (Localized)
	High	Grinding (Localized)
Shattered Slab	Low	Monitor
	Medium	Crack Sealing - PCC
	High	Slab Replacement - PCC
Joint Spall, Corner Spall & Small Patch	Low	Monitor
	Medium	Patching - PCC Partial Depth
	High	Patching - PCC Partial Depth

4.5 Pavement Repair Materials

New pavement repair materials are introduced and improved regularly. This section provides information on products compatible with airport needs.

4.5.1 Joint and Crack Sealer

Hot-poured, pressure-injected, polymeric rubberized asphalt sealant meeting ASTM D3405 specifications is suitable for most sealing requirements. This product is relatively inexpensive, durable, and suitable for both rigid and flexible pavements. Other, more expensive, hot-applied sealants that promise longer life are being developed for specialty applications. Twin component cold applied sealants also have been used with success. Contact your local distributor.

4.5.2 Flexible Pavement Patch

High-performance plant mixed cold patching products that can be stockpiled on-site can be used for short term repairs to maintain safety. Long-term patches should be made with high-quality plant mixed hot asphalt having a ¾-inch maximum aggregate size and meeting Federal Aviation Administration (FAA) P401, or highest quality highway specifications. Low-quality packaged materials available from local hardware type stores should be avoided.

4.5.3 Rigid Pavement Patch

Permanent patches in rigid pavement should be made with air-entrained concrete with 1-inch maximum size aggregate. If the area must be quickly opened to traffic, high early concrete should be considered. Concrete should have zero slump and a coarse texture. As with asphalt patches, low-quality packaged materials should be used only as temporary patches to maintain safety and service until a more permanent repair can be made.

4.6 Pavement Repair Equipment

Many pavement repair and sealing products are available. Specialized tools and equipment help ensure high-quality repairs. This section discusses equipment compatible with airport needs.

4.6.1 Air Compressor

Used to remove non-compressible sand and debris from prepared cracks and joints, the compressor should have a sustained capacity of 120 cubic feet per minute with a nozzle velocity of 100 psi. Trailer-mounted compressors typically have capacities in this range.

4.6.2 Concrete Saw

A saw capable of making a minimum 3-inch-deep cut is required. The saw should be capable of making cuts in both asphalt and concrete. Gasoline-powered 5- to 25-hp wheel-mounted saws typically are preferred for this type of work, but electric and pneumatic tools also are available.

4.6.3 Heating Kettle

Applying sealant is the most time-consuming operation, and a sealing machine with heating and pressure application capabilities is a critical item in a successful sealing program. The capacity of the sealing equipment dictates the rate at which a crew progresses. For large sealing projects, a minimum 100-gallons/hour sustained capacity is recommended. The unit should be a double boiler type, with mechanical agitators or continuous recirculation. Kettle temperature must be monitored to ensure that the sealant is not “burned.” Overheating the sealant will prematurely age harden the material.

4.6.4 Router

A concrete saw can be used to prepare joints, but for random cracking, a mechanical router with a vertical impact mechanism is preferred. When cracks are being routed, this activity will dictate the speed of the crew. Crack routers in the 25-hp range are commonly used and are available from a variety of manufacturers.

4.6.5 Sand Cleaner

A sand blaster helps to clean loose particles and dust from prepared cracks. The unit must have sufficient force to expose fresh, vital pavement to bond with sealant and patching materials.

4.6.6 Vibratory Roller or Plate Compactor

Required to compact plant mixed and packaged patching materials properly. Small rollers are best for pothole type applications; plate compactors are best for large areas.

4.6.7 Other Equipment

Other general use equipment that can be helpful in a maintenance program includes bucket loaders, dump trucks, water tanks, and a power sweeper unit.

Appendix A. AIRPAV Software

The Software

Data analysis was performed using the AIRPAV pavement evaluation and management software. In addition to calculating and documenting PCI values, AIRPAV evaluates the collected inspection data and recommends rehabilitation actions that address the cause of pavement distress. AIRPAV can incorporate traffic and structural capacity evaluations into the pavement evaluation matrix, and AIRPAV also performs preliminary life cycle cost analysis of the various rehabilitation alternatives, providing guidance on the lowest annual cost repair strategy.



A complete database, along with an updated version of AIRPAV, is provided on INDOT computers for ongoing management of the INDOT pavement systems.

Capital Improvements

AIRPAV creates interactive CIPs, providing the user with the ability to control unit costs, develop new projects, move projects between years, and even increase or decrease the scope and cost of individual projects.

Maintenance

AIRPAV calculates and develops maintenance work orders organized by type of work. Maintenance work orders can be printed and issued directly to maintenance crews.

Traffic

AIRPAV provides the ability to model aircraft ground movements. Traffic can be sorted by airline, aircraft type, destination gate or ramp, and runway used. The program graphically displays each taxi path, accumulates total operations, automatically determines design aircraft, and calculates structural overlay requirements for each pavement feature. The software can provide Pavement Classification Numbers (PCN) for each pavement feature or report results directly as inches of overlay required.

Maps


AIRPAV permits viewing and printing of PCI maps. Inspection layout, pavement condition, and other views are available from within the software.

Query

The AIRPAV query function is a powerful search tool that allows users to extract useful reports meeting various criteria. As examples, lists can be created for taxiway pavement, asphalt pavement, or areas below MSL at the time of inspection.

Global Information System (GIS) Integration

AIRPAV is fully GIS-enabled. A single click in AIRPAV exports all data to an MS Access database that can be linked to shape files used in an ESRI product. In this way, virtually all data in the pavement management database can be accessed in GIS format.



Appendix B. Feature Analysis


Pavement Performance Models

Projected performance is determined by relating current pavement condition to expected pavement condition. Projected performance varies based on pavement type. There are four pavement types in Indiana: AC, PCC, ACC, and APC. Each pavement type has a unique deterioration curve, created by plotting all data for that group as PCI vs. age and then finding a performance curve to best fit the data. These curves represent the historic performance of pavement in the group and become the baseline for future projections. The baseline curves are modeled with a third order polynomial equation as shown below.

$$PCI = X(\text{Age})^3 + Y(\text{Age})^2 + Z(\text{Age}) + C$$

Current Condition (rotating the curves)


Starting with the baseline curve for comparison, current pavement condition is plotted, and the baseline curve is rotated to meet the current condition. The rotated curve provides the starting point for projecting the future pavement condition.



Advanced Analysis (accounting for distress)


Some types of pavement distress have a greater impact on pavement deterioration than others. Rutting and alligator (fatigue) cracking are major structural failures and can lead to rapid pavement deterioration. Other distress types, like L&T cracking, develop slowly over time and typically do not cause a significant deviation from the baseline curve.

After current condition is accounted for with the curve rotation, pavement distress is addressed in the advanced analysis by compressing or expanding the baseline curve to account for the expected rate of pavement deterioration.



Projected PCI (near term vs. longer term)

Projecting pavement condition with advanced analysis is a combination of rotating, expanding, and contracting the baseline curves. This projection method provides good short-term results for all pavement sections and fair long-term projections on pavement sections with conditions near the baseline model. The long-term accuracy of outlier data is discussed on the following page.




Projected PCI (why some features have unexpected projections)

Long-term PCI projections can be very useful for planning purposes. However, projections in excess of 10 years are well beyond the intended scope of the PCI procedure. FAA Advisory Circular 150/5380-6B establishes a maximum 3-year interval between detailed PCI surveys.

Curve rotation, expansion, and contraction are performed to produce the best possible accuracy of future pavement condition over the next 3 to 5 years. This methodology can overemphasize certain performance trends in the long term. This is especially true for outlier data, such as pavement features that are performing much better or worse than is typical.

The curve below shows an example of a performance trend being overemphasized in the long-term projection. Because the pavement feature is performing much better than the baseline curve, the long-term projection shows the pavement lasting an additional 30+ years before reaching the MSL. Rotation of the curve to provide the most accurate projection over 3 to 5 years has resulted in a long-term projection that is likely unrealistic.



When long-term projections such as this are encountered, airport managers should not rely on projections in excess of 10 years. Managers can be confident that the pavement is performing much better than average and will not require rehabilitation within the current 5-year CIP planning window. As new distress develops over time, future PCI surveys will determine the ideal timing for rehabilitation.

Feature Analysis

As part of the PCI evaluation, a detailed analysis is presented for each airside pavement feature using the two-page format depicted below.

Page 1

The first page of the analysis is a feature summary. Located near the top left-hand corner is the feature number and pavement description. Construction history and inspector comments are listed below, along with a photo of the pavement section if available. Distress totals recorded during the PCI survey are listed next, and an approximation of the cause of the pavement deterioration is shown at the bottom. If the pavement is projected to fall below the desired MSL during the next 12 years, the analysis year will be shown along with the optimum year for pavement rehabilitation.

AIRPAV

AIRPORT: BLOOMINGTON/MONROE COUNTY
AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 5007

ANALYSIS YEAR: 2011 **OPTIMIZED FOR: 2019**

PAVEMENT TYPE: AC
FEATURE AREA: 1,278,750
INSPECTED AREA: 40,000
MINIMUM SERVICE LEVEL: 0.5

DESCRIPTION: RUNWAY 17-35 KEEL

INSPECTION DATE: 8-11-11
FEATURE'S HIGH PCI: 72
FEATURE'S LOW PCI: 59
AVERAGE PCI: 69 GOOD
ESTIMATED PCI IS: 65 in 2019

COMMENTS/HISTORY FOR FEATURE 5007, RUNWAY 17-35 KEEL

1989: 4" P401 / 5" P401 / 13" P209
*
*

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF ALL DISTRESS
ALLIGATOR CRACKING	LOW	66	2,199	S.F.	8.3
LONG & TRANS. CRACK	MED	995	31,808	L.F.	30.4
LONG & TRANS. CRACK	LOW	2,824	90,279	L.F.	34.8
RAVELING/WEATHERING	LOW	9,450	302,104	S.F.	26.3

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	8 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	52 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	39 %

PAGE 1

Description & Feature # →

Optimized Rehab Year →

Construction History ←

Distress Totals ←

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 101	DESCRIPTION: NORTH TAXIWAY
ANALYSIS YEAR: 2012 OPTIMIZED FOR: 2013	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC OVERLAY	FEATURE'S HIGH PCI: 64
FEATURE AREA: 6,480	FEATURE'S LOW PCI: 48
INSPECTED AREA: 5,850	AVERAGE PCI: 56 FAIR
MINIMUM SERVICE LEVEL: 55	ESTIMATED PCI IS: 54 in 2013

COMMENTS/HISTORY FOR FEATURE 101, NORTH TAXIWAY

1990 2" P401 OVERLAY
 1974 2 INCH AC
 6 INCH P209
 *

DISTRESS QUANTITIES FOR FEATURE 101

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
ALLIGATOR CRACKING	MED	13	14	S.F.	12.7
ALLIGATOR CRACKING	LOW	32	35	S.F.	13.4
DEPRESSION	MED	12	13	S.F.	5.6
DEPRESSION	LOW	35	38	S.F.	3.4
LONG.& TRANS. CRACK	HIGH	5	5	L.F.	5.2
LONG.& TRANS. CRACK	MED	193	213	L.F.	26.6
LONG.& TRANS. CRACK	LOW	237	262	L.F.	15.2
PATCH & UTILITY CUT	MED	7	7	S.F.	5.7
RAVELING	HIGH	4	4	S.F.	6.6
WEATHERING	LOW	2,200	2,436	S.F.	5

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	30 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	46 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	24 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 101

DESCRIPTION: NORTH TAXIWAY

ANALYSIS YEAR: 2012 OPTIMIZED FOR: 2013

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC OVERLAY

AVERAGE PCI AT INSPECTION: 56 FAIR

CONSTRUCTION YEAR: 1990

ESTIMATED PCI IS: 54 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 54

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$9,136	23 YEARS
▼	SURFACE TREATMENT	\$2,728	6 YEARS
◆	CRACK REPAIR	\$585	2 YEARS
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 105	DESCRIPTION: NORTH TAXIWAY
ANALYSIS YEAR: 2012 OPTIMIZED FOR: 2020	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC OVERLAY	FEATURE'S HIGH PCI: 80
FEATURE AREA: 15,000	FEATURE'S LOW PCI: 63
INSPECTED AREA: 9,750	AVERAGE PCI: 70 FAIR
MINIMUM SERVICE LEVEL: 55	ESTIMATED PCI IS: 53 in 2020

COMMENTS/HISTORY FOR FEATURE 105, NORTH TAXIWAY

2003: 1" AC Inlay / Tack Coat / Unknown Existing Ac

*
*
*

DISTRESS QUANTITIES FOR FEATURE 105

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
DEPRESSION	LOW	40	61	S.F.	3.7
LONG.& TRANS. CRACK	MED	247	380	L.F.	45.2
LONG.& TRANS. CRACK	LOW	423	650	L.F.	33.4
RAVELING	MED	51	78	S.F.	6.9
RAVELING	LOW	210	323	S.F.	7.7
WEATHERING	LOW	800	1,230	S.F.	2.8

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	62 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	38 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 105

DESCRIPTION: NORTH TAXIWAY

ANALYSIS YEAR: 2012 OPTIMIZED FOR: 2020

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC OVERLAY

AVERAGE PCI AT INSPECTION: 70 FAIR

CONSTRUCTION YEAR: 2003

ESTIMATED PCI IS: 53 in 2020


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 64

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$21,149	23 YEARS
▼	SURFACE TREATMENT	\$6,163	8 YEARS
◆	CRACK REPAIR	\$1,256	1 YEAR
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 110	DESCRIPTION: NORTH TAXIWAY
ANALYSIS YEAR: 2012 OPTIMIZED FOR: 2023	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC OVERLAY	FEATURE'S HIGH PCI: 83
FEATURE AREA: 3,950	FEATURE'S LOW PCI: 83
INSPECTED AREA: 3,020	AVERAGE PCI: 83 SATISFACTORY
MINIMUM SERVICE LEVEL: 55	ESTIMATED PCI IS: 53 in 2023

COMMENTS/HISTORY FOR FEATURE 110, NORTH TAXIWAY

2008 AC OVERLAY

*
*
*

DISTRESS QUANTITIES FOR FEATURE 110

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	MED	42	54	L.F.	70.4
LONG.& TRANS. CRACK	LOW	41	53	L.F.	29.5

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 110

DESCRIPTION: NORTH TAXIWAY

ANALYSIS YEAR: 2012 OPTIMIZED FOR: 2023

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC OVERLAY

AVERAGE PCI AT INSPECTION: 83 SATISFACTORY

CONSTRUCTION YEAR: 2008

ESTIMATED PCI IS: 53 in 2023


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 67

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$5,569	23 YEARS
▼	CRACK REPAIR	\$130	2 YEARS
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 125	DESCRIPTION: TAXIWAY A
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC +	FEATURE'S HIGH PCI: 100
FEATURE AREA: 79,558	FEATURE'S LOW PCI: 100
INSPECTED AREA: 17,500	AVERAGE PCI: 100 GOOD
MINIMUM SERVICE LEVEL: 55	ESTIMATED PCI IS: 96 in 2012

COMMENTS/HISTORY FOR FEATURE 125, TAXIWAY A

2010 AC 2" P-401/5" P-401 base/6" P-209
 With under drains
 *
 *

DISTRESS QUANTITIES FOR FEATURE 125

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
---------------	----------	-------------------	--------------------------	-------	----------------------------

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	0 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 125

DESCRIPTION: TAXIWAY A

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC +

AVERAGE PCI AT INSPECTION: 100 GOOD

CONSTRUCTION YEAR: 2010

ESTIMATED PCI IS: 96 in 2012


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 96

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 130	DESCRIPTION: TAXIWAY A-1
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC +	FEATURE'S HIGH PCI: 100
FEATURE AREA: 21,188	FEATURE'S LOW PCI: 100
INSPECTED AREA: 7,000	AVERAGE PCI: 100 GOOD
MINIMUM SERVICE LEVEL: 55	ESTIMATED PCI IS: 96 in 2012

COMMENTS/HISTORY FOR FEATURE 130, TAXIWAY A-1

2010 AC 2" P-401/5" P-401 base/6" P-209

*
*
*

DISTRESS QUANTITIES FOR FEATURE 130

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
---------------	----------	----------------------	-----------------------------	-------	-------------------------------

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	0 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 130

DESCRIPTION: TAXIWAY A-1

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC +

AVERAGE PCI AT INSPECTION: 100 GOOD

CONSTRUCTION YEAR: 2010

ESTIMATED PCI IS: 96 in 2012


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 96

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 135	DESCRIPTION: TAXIWAY A
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC	FEATURE'S HIGH PCI: 100
FEATURE AREA: 97,166	FEATURE'S LOW PCI: 100
INSPECTED AREA: 28,000	AVERAGE PCI: 100 GOOD
MINIMUM SERVICE LEVEL: 55	ESTIMATED PCI IS: 100 in 2012

COMMENTS/HISTORY FOR FEATURE 135, TAXIWAY A

2012 AC 2" P-401/5" P-401 base/6" P-209
 With under drains entire length of Taxiway A
 *
 *

DISTRESS QUANTITIES FOR FEATURE 135

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
---------------	----------	----------------------	-----------------------------	-------	-------------------------------

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	0 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 135

DESCRIPTION: TAXIWAY A

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 100 GOOD

CONSTRUCTION YEAR: 2012

ESTIMATED PCI IS: 100 in 2012


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 100

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 201

DESCRIPTION: TAXIWAY B

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC

FEATURE'S HIGH PCI: 57

FEATURE AREA: 24,486

FEATURE'S LOW PCI: 47

INSPECTED AREA: 9,600

AVERAGE PCI: 54 POOR

MINIMUM SERVICE LEVEL: 55

ESTIMATED PCI IS: 54 in 2012

COMMENTS/HISTORY FOR FEATURE 201, TAXIWAY B

1985 5 INCH P401

8 INCH P208

*

*

DISTRESS QUANTITIES FOR FEATURE 201

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
ALLIGATOR CRACKING	MED	6	15	S.F.	4.8
ALLIGATOR CRACKING	LOW	99	252	S.F.	24.6
DEPRESSION	LOW	100	255	S.F.	7
LONG.& TRANS. CRACK	MED	405	1,033	L.F.	26.6
LONG.& TRANS. CRACK	LOW	409	1,043	L.F.	14.1
RUTTING	HIGH	5	12	S.F.	7.2
RUTTING	MED	20	51	S.F.	6.8
RUTTING	LOW	26	66	S.F.	4.8
WEATHERING	LOW	3,300	8,417	S.F.	3.6

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	42 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	42 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	16 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 201

DESCRIPTION: TAXIWAY B

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 54 POOR

CONSTRUCTION YEAR: 1985

ESTIMATED PCI IS: 54 in 2012


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 48

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$34,525	23 YEARS
▼	SURFACE TREATMENT	\$10,564	5 YEARS
◆	CRACK REPAIR	\$2,532	1 YEAR
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 210

DESCRIPTION: TAXIWAY B

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC

FEATURE'S HIGH PCI: 46

FEATURE AREA: 4,090

FEATURE'S LOW PCI: 46

INSPECTED AREA: 4,090

AVERAGE PCI: 46 POOR

MINIMUM SERVICE LEVEL: 55

ESTIMATED PCI IS: 46 in 2012

COMMENTS/HISTORY FOR FEATURE 210, TAXIWAY B

1990 AC est

*
*
*

DISTRESS QUANTITIES FOR FEATURE 210

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
BLOCK CRACKING	MED	488	488	S.F.	28.2
BLOCK CRACKING	LOW	1,400	1,400	S.F.	28.1
LONG.& TRANS. CRACK	HIGH	6	6	L.F.	8.9
LONG.& TRANS. CRACK	MED	119	119	L.F.	19.6
LONG.& TRANS. CRACK	LOW	35	35	L.F.	5.2
SWELL	LOW	40	40	S.F.	3.7
WEATHERING	LOW	3,800	3,800	S.F.	5.9

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	28 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	72 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 210

DESCRIPTION: TAXIWAY B

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 46 POOR

CONSTRUCTION YEAR: 1990

ESTIMATED PCI IS: 46 in 2012


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 58

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$5,766	23 YEARS
▼	SURFACE TREATMENT	\$2,063	7 YEARS
◆	CRACK REPAIR	\$1,577	2 YEARS
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 225	DESCRIPTION: TAXIWAY B
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC	FEATURE'S HIGH PCI: 100
FEATURE AREA: 35,356	FEATURE'S LOW PCI: 100
INSPECTED AREA: 14,000	AVERAGE PCI: 100 GOOD
MINIMUM SERVICE LEVEL: 55	ESTIMATED PCI IS: 100 in 2012

COMMENTS/HISTORY FOR FEATURE 225, TAXIWAY B

2012 AC 2" P-401/5" P-401 base/6" P-209

*
*
*

DISTRESS QUANTITIES FOR FEATURE 225

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
---------------	----------	----------------------	-----------------------------	-------	-------------------------------

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	0 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 225

DESCRIPTION: TAXIWAY B

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 100 GOOD

CONSTRUCTION YEAR: 2012

ESTIMATED PCI IS: 100 in 2012


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 100

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3001

DESCRIPTION: RAMP

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC

FEATURE'S HIGH PCI: 32

FEATURE AREA: 30,204

FEATURE'S LOW PCI: 24

INSPECTED AREA: 14,250

AVERAGE PCI: 29 VERY POOR

MINIMUM SERVICE LEVEL: 55

ESTIMATED PCI IS: 29 in 2012

COMMENTS/HISTORY FOR FEATURE 3001, RAMP

1985 P401 est with Emulsion Seal

Estimate Same as F201 (1985: 5 INCH P401 / 8 INCH P208)

*

*

DISTRESS QUANTITIES FOR FEATURE 3001

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
ALLIGATOR CRACKING	HIGH	18	38	S.F.	5
ALLIGATOR CRACKING	MED	292	618	S.F.	20.3
BLOCK CRACKING	LOW	500	1,059	S.F.	5.3
LONG.& TRANS. CRACK	HIGH	35	74	L.F.	3.5
LONG.& TRANS. CRACK	MED	359	760	L.F.	9.5
LONG.& TRANS. CRACK	LOW	1,161	2,460	L.F.	11.8
PATCH & UTILITY CUT	LOW	52	110	S.F.	.7
RAVELING	HIGH	70	148	S.F.	4.8
RAVELING	MED	1,325	2,808	S.F.	11.7
RAVELING	LOW	11,200	23,739	S.F.	14.3
RUTTING	MED	60	127	S.F.	4.9
RUTTING	LOW	160	339	S.F.	4.1
SLIPPAGE CRACKING	N/A	80	169	S.F.	3.5

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	32 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	34 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	34 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3001

DESCRIPTION: RAMP

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 29 VERY POOR

CONSTRUCTION YEAR: 1985

ESTIMATED PCI IS: 29 in 2012


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 48

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RECONSTRUCTION	\$158,571	24 YEARS
▼	STRUCTURAL OVERLAY	\$54,669	23 YEARS
◆	SURFACE TREATMENT	\$12,494	3 YEARS
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3002	DESCRIPTION: FUELING RAMP
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC	FEATURE'S HIGH PCI: 57
FEATURE AREA: 6,650	FEATURE'S LOW PCI: 39
INSPECTED AREA: 6,650	AVERAGE PCI: 48 POOR
MINIMUM SERVICE LEVEL: 55	ESTIMATED PCI IS: 48 in 2012

COMMENTS/HISTORY FOR FEATURE 3002, FUELING RAMP

1985 AC est with emulsion seal
 Estimate Same as F201 (1985: 5 INCH P401 / 8 INCH P208)

*
 *

DISTRESS QUANTITIES FOR FEATURE 3002

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
DEPRESSION	LOW	72	72	S.F.	5.5
LONG.& TRANS. CRACK	MED	306	306	L.F.	24.9
LONG.& TRANS. CRACK	LOW	418	418	L.F.	18.7
RAVELING	HIGH	8	8	S.F.	4.2
RAVELING	MED	1,200	1,200	S.F.	18.6
RAVELING	LOW	5,442	5,442	S.F.	27.6

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	52 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	48 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3002

DESCRIPTION: FUELING RAMP

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 48 POOR

CONSTRUCTION YEAR: 1985

ESTIMATED PCI IS: 48 in 2012


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 48

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$9,376	23 YEARS
▼	SURFACE TREATMENT	\$2,900	7 YEARS
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3015	DESCRIPTION: TERMINAL RAMP
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: PCC	FEATURE'S HIGH PCI: 100
FEATURE AREA: 14,500	FEATURE'S LOW PCI: 100
INSPECTED AREA: 7,200	AVERAGE PCI: 100 GOOD
MINIMUM SERVICE LEVEL: 55	ESTIMATED PCI IS: 100 in 2012

COMMENTS/HISTORY FOR FEATURE 3015, TERMINAL RAMP

2003: 6" P501 / 4" P209

*
*
*

DISTRESS QUANTITIES FOR FEATURE 3015

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
---------------	----------	-------------------	--------------------------	-------	----------------------------

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	0 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3015

DESCRIPTION: TERMINAL RAMP

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: PCC

AVERAGE PCI AT INSPECTION: 100 GOOD

CONSTRUCTION YEAR: 2003

ESTIMATED PCI IS: 100 in 2012


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 93

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3020	DESCRIPTION: SOUTH RAMP
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC	FEATURE'S HIGH PCI: 100
FEATURE AREA: 7,820	FEATURE'S LOW PCI: 100
INSPECTED AREA: 7,540	AVERAGE PCI: 100 GOOD
MINIMUM SERVICE LEVEL: 55	ESTIMATED PCI IS: 100 in 2012

COMMENTS/HISTORY FOR FEATURE 3020, SOUTH RAMP

2012 AC 2" P-401/5" P-401 base/6" P-209

*
*
*

DISTRESS QUANTITIES FOR FEATURE 3020

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
---------------	----------	----------------------	-----------------------------	-------	-------------------------------

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	0 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3020

DESCRIPTION: SOUTH RAMP

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 100 GOOD

CONSTRUCTION YEAR: 2012

ESTIMATED PCI IS: 100 in 2012


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 100

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 4105	DESCRIPTION: TEE HANGARS
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC	FEATURE'S HIGH PCI: 62
FEATURE AREA: 66,300	FEATURE'S LOW PCI: 38
INSPECTED AREA: 24,000	AVERAGE PCI: 49 POOR
MINIMUM SERVICE LEVEL: 55	ESTIMATED PCI IS: 49 in 2012

COMMENTS/HISTORY FOR FEATURE 4105, TEE HANGARS

1999 AC est

*
*
*

DISTRESS QUANTITIES FOR FEATURE 4105

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
ALLIGATOR CRACKING	MED	34	93	S.F.	8.6
ALLIGATOR CRACKING	LOW	309	853	S.F.	16.3
BLOCK CRACKING	LOW	198	547	S.F.	2.9
DEPRESSION	LOW	60	165	S.F.	1.5
LONG.& TRANS. CRACK	MED	593	1,638	L.F.	15.9
LONG.& TRANS. CRACK	LOW	1,288	3,558	L.F.	14.6
OIL SPILLAGE	N/A	16	44	S.F.	.5
RAVELING	HIGH	42	116	S.F.	3.5
RAVELING	MED	280	773	S.F.	5.5
RAVELING	LOW	375	1,035	S.F.	1.9
RUTTING	MED	76	209	S.F.	10.8
RUTTING	LOW	666	1,839	S.F.	15.6
WEATHERING	MED	100	276	S.F.	.1
WEATHERING	LOW	4,500	12,431	S.F.	1.6

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	43 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	35 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	22 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 4105

DESCRIPTION: TEE HANGARS

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 49 POOR

CONSTRUCTION YEAR: 1999

ESTIMATED PCI IS: 49 in 2012


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 71

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RECONSTRUCTION	\$348,075	24 YEARS
▼	STRUCTURAL OVERLAY	\$120,002	23 YEARS
◆	SURFACE TREATMENT	\$27,192	4 YEARS
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 4110	DESCRIPTION: TEE HANGARS
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC	FEATURE'S HIGH PCI: 95
FEATURE AREA: 43,200	FEATURE'S LOW PCI: 85
INSPECTED AREA: 21,460	AVERAGE PCI: 92 GOOD
MINIMUM SERVICE LEVEL: 55	ESTIMATED PCI IS: 83 in 2012

COMMENTS/HISTORY FOR FEATURE 4110, TEE HANGARS

2005 AC
*
*
*

DISTRESS QUANTITIES FOR FEATURE 4110

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
DEPRESSION	LOW	16	32	S.F.	1
LONG.& TRANS. CRACK	MED	30	60	L.F.	23.7
LONG.& TRANS. CRACK	LOW	126	253	L.F.	37.3
WEATHERING	MED	300	603	S.F.	8.9
WEATHERING	LOW	7,520	15,138	S.F.	28.9

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	54 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	46 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 4110

DESCRIPTION: TEE HANGARS

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 92 GOOD

CONSTRUCTION YEAR: 2005

ESTIMATED PCI IS: 83 in 2012


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 81

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 6105	DESCRIPTION: RUNWAY 9-27
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC OVERLAY	FEATURE'S HIGH PCI: 100
FEATURE AREA: 375,000	FEATURE'S LOW PCI: 90
INSPECTED AREA: 56,250	AVERAGE PCI: 96 GOOD
MINIMUM SERVICE LEVEL: 60	ESTIMATED PCI IS: 91 in 2012

COMMENTS/HISTORY FOR FEATURE 6105, RUNWAY 9-27

2009 1" mill and 2" AC OVERLAY/
 1998 5" P401/8" P209(east 1000 feet)
 First 4000 feet est 1990 AC
 With under drains

DISTRESS QUANTITIES FOR FEATURE 6105

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	LOW	624	4,160	L.F.	100

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 6105

DESCRIPTION: RUNWAY 9-27

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC OVERLAY

AVERAGE PCI AT INSPECTION: 96 GOOD

CONSTRUCTION YEAR: 2009

ESTIMATED PCI IS: 91 in 2012


MINIMUM SERVICE LEVEL: 60

NORMAL PCI FOR THIS AGE: 89

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 60		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 6205	DESCRIPTION: RUNWAY 4-22 KEEL
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC OVERLAY	FEATURE'S HIGH PCI: 92
FEATURE AREA: 96,538	FEATURE'S LOW PCI: 87
INSPECTED AREA: 30,000	AVERAGE PCI: 89 GOOD
MINIMUM SERVICE LEVEL: 60	ESTIMATED PCI IS: 89 in 2012

COMMENTS/HISTORY FOR FEATURE 6205, RUNWAY 4-22 KEEL

2008 1/4" scarifying mill and 2" AC Overlay/ 1990 2" AC Overlay
 1974 2" AC/
 6" P209
 *

DISTRESS QUANTITIES FOR FEATURE 6205

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	MED	97	312	L.F.	48.2
LONG.& TRANS. CRACK	LOW	494	1,589	L.F.	51.7

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 6205

DESCRIPTION: RUNWAY 4-22 KEEL

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC OVERLAY

AVERAGE PCI AT INSPECTION: 89 GOOD

CONSTRUCTION YEAR: 2008

ESTIMATED PCI IS: 89 in 2012


MINIMUM SERVICE LEVEL: 60

NORMAL PCI FOR THIS AGE: 86

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 60		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 6210	DESCRIPTION: RUNWAY 4-22 WING
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC OVERLAY	FEATURE'S HIGH PCI: 100
FEATURE AREA: 36,110	FEATURE'S LOW PCI: 86
INSPECTED AREA: 12,000	AVERAGE PCI: 91 GOOD
MINIMUM SERVICE LEVEL: 60	ESTIMATED PCI IS: 90 in 2012

COMMENTS/HISTORY FOR FEATURE 6210, RUNWAY 4-22 WING

2008 1/4" scarifying mill and 2" AC Overlay/ 1990 2" AC OVERLAY
 UNKNOWN EXISTING

*
 *

DISTRESS QUANTITIES FOR FEATURE 6210

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	MED	57	171	L.F.	69.9
LONG.& TRANS. CRACK	LOW	49	147	L.F.	30

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 6210

DESCRIPTION: RUNWAY 4-22 WING

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC OVERLAY

AVERAGE PCI AT INSPECTION: 91 GOOD

CONSTRUCTION YEAR: 2008

ESTIMATED PCI IS: 90 in 2012


MINIMUM SERVICE LEVEL: 60

NORMAL PCI FOR THIS AGE: 86

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 60		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 6215	DESCRIPTION: RUNWAY 4-22
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC	FEATURE'S HIGH PCI: 95
FEATURE AREA: 30,025	FEATURE'S LOW PCI: 86
INSPECTED AREA: 15,000	AVERAGE PCI: 90 GOOD
MINIMUM SERVICE LEVEL: 60	ESTIMATED PCI IS: 90 in 2012

COMMENTS/HISTORY FOR FEATURE 6215, RUNWAY 4-22

2009 2" AC OVERLAY/ 1990 2" AC OVERLAY
 1974 2 INCH AC
 6 INCH P209
 *

DISTRESS QUANTITIES FOR FEATURE 6215

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	MED	4	8	L.F.	26.9
LONG.& TRANS. CRACK	LOW	344	688	L.F.	73

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 6215

DESCRIPTION: RUNWAY 4-22

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 90 GOOD

CONSTRUCTION YEAR: 2009

ESTIMATED PCI IS: 90 in 2012


MINIMUM SERVICE LEVEL: 60

NORMAL PCI FOR THIS AGE: 91

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 60		

PROJECTED PERFORMANCE



AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 6220	DESCRIPTION: RUNWAY 4-22
ANALYSIS YEAR: 2012	INSPECTION DATE: 8-23-12
PAVEMENT TYPE: AC OVERLAY	FEATURE'S HIGH PCI: 98
FEATURE AREA: 9,300	FEATURE'S LOW PCI: 89
INSPECTED AREA: 9,300	AVERAGE PCI: 94 GOOD
MINIMUM SERVICE LEVEL: 60	ESTIMATED PCI IS: 91 in 2012

COMMENTS/HISTORY FOR FEATURE 6220, RUNWAY 4-22

2009 2" AC OVERLAY/ 1990 2" AC OVERLAY
 UNKNOWN EXISTING

*
 *

DISTRESS QUANTITIES FOR FEATURE 6220

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	MED	4	4	L.F.	28.2
LONG.& TRANS. CRACK	LOW	66	66	L.F.	71.7

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %

AIRPORT: FRANKFORT MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 6220

DESCRIPTION: RUNWAY 4-22

ANALYSIS YEAR: 2012

INSPECTION DATE: 8-23-12

PAVEMENT TYPE: AC OVERLAY

AVERAGE PCI AT INSPECTION: 94 GOOD

CONSTRUCTION YEAR: 2009

ESTIMATED PCI IS: 91 in 2012


MINIMUM SERVICE LEVEL: 60

NORMAL PCI FOR THIS AGE: 89

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 60		


PROJECTED PERFORMANCE



Appendix C. General Maintenance Techniques

Crack Sealing

- Cracks over ¼ inches wide should be sealed.
- Cracks wider than 3 inches should be patched.
- Sealant depth above the backer rope should be equal to the width of the reservoir, or as recommended by the manufacturer.
- Routed cracks should be sand blasted, to prepare for bonding with the sealant.
- Clean cracks with compressed air prior to sealing.
- Backing material should always be placed into the cracks. Commercial products are available. Several sizes of rope should be available to accommodate various crack sizes.
- Apply sealant after placing the backer rope. Follow the manufacturer's instructions. Sealant should be applied to within ¼ inch of the pavement surface.
- The final activity is to clean the surrounding pavement areas. A vacuum sweeper works well for this. Allow the sealant time to set before using a broom.
- Consider hot-applied, pourable patch material for cracks > ½ inch and any subsidence or depressions.



Overband Technique


An alternate crack sealing technique using the procedures outlined below.

Material

- Blend grade 20 or equivalent asphalt cement and latex rubber at 5 percent by weight asphalt.
- Again, at 5 percent by weight of asphalt, add polyester fibers into agitator tank.
- Maintain blended asphalt temperature at least 20 degrees below flash point.
- Continuously recycle hot blended asphalt through pumps and hoses when heating kettle is in standby mode.


Application

- Sealant should be applied to dry pavement, with ambient temperatures above 40 degrees.
- Cracks should be sand cleaned and blown free of debris immediately before sealing.
- Application of sealant immediately follows cleaning of the crack.
- Sealant should be pressure applied from a wand-type applicator with “overband” nozzle.
- Seat the sealant with a steel-wheeled roller immediately after placement.
- In wider cracks, a backer rope is recommended to limit material quantities required.




Joint Repair (portland cement)

- Rout a reservoir for the sealant ½ inch wide and 1 inch deep.
- Cracks wider than ½ inch should have reservoirs ¼ inch wider than the crack. Reservoir height above backer rope should be less than reservoir width, or as recommended by manufacturer.
- Routed cracks should be cleaned to expose fresh, vital pavement on the vertical crack edge.
- Cracks should be cleaned to remove all sand, debris, and other materials from the crack.
- Backing material should be placed into the crack.
- Apply sealant to within ¼ inch of pavement surface, following manufacturer’s instructions.
- Clean the surrounding pavement area.





Typical failed joint sealant, w/ debris and incompressibles.

Clean joints exposing fresh, clean concrete and stone. Retain existing reservoir shape.



Patching (bituminous material)


- Examine distressed area and mark patch outline.
- Cut patch area with saw, no less than 3 inches deep.
- Remove enclosed pavement, leaving the vertical sawed edges undamaged.
- Clean sides and bottom and blow out with compressed air
- Paint sides and bottom with rapid curing asphalt tack coat. Prevent pooling on bottom.
- Allow tack coat to cure until it reaches a gummy consistency.
- Place hot mixed asphalt concrete and mound slightly, allowing for compaction.
- Compact with vibratory roller or plate compactor, in layers no greater than 6 inches.



Patching (pourable materials)

Hot-applied, pourable materials generally are used to repair deficiencies larger than can be repaired by sealants, but smaller than those where traditional techniques would be required. Suggested uses for this type of repair include cracks over 2 inches wide, potholes less than 4 inches deep, as a leveling for small depressions, as a cap for settled utility cuts, and as a skin patch for areas of alligator cracking.



- Examine and mark the patch outline. Boundaries should extend to sound pavement.
- Apply patch material to clean, dry surfaces.
- A heating lance to preheat or dry existing pavement is recommended in cold or wet conditions.
- Patch material should be poured into the area to be repaired and leveled as appropriate.
- Patch edges should be sealed after application to assure good adhesion, preventing surface moisture from migrating under patch edges.



Patching (PCC)

The technique outlined here simulates a thin bonded PCC overlay. This procedure has been proven effective in service throughout the country.

- Examine and mark patch outline.
- Saw cut area to a depth of 2 inches. The enclosed area is then chipped or jack hammered to solid pavement, but not less than a 2-inch nominal depth.
- The sides and bottom are sand cleaned and air-blasted to expose vital, clean concrete.
- A 25 percent solution of muriatic acid is applied to all exposed surfaces within the patch.
- The muriatic acid solution is thoroughly flushed from the patch area with water.
- Compressed air is used to remove excess water from the area, but exposed concrete must be maintained in a moist condition.
- The sides and bottom of the area are then coated with approximately a 1/16-inch layer of cement grout applied at the consistency of paste. The grout acts as an adhesive to bond the fresh concrete to existing concrete.
- If the patch is adjacent to joints, the continuity of the joint must be maintained by placing inserts approximately the shape of the desired joint against the wall of the patch.
- Before concrete grout begins to dry, concrete is placed in the patch area and is compacted into position with hand tampers or a vibrating plate tamper.
- When the patch has been struck to the proper slope and elevation, a surface texture is applied to approximate the texture of adjacent pavement.
- Joint edges may be edged slightly to remove sharp edges. The patch should be covered with polyethylene or sprayed with a curing compound.
- Clean the surrounding pavement before concrete spillover has a chance to set up.
- The patch may be open to traffic in 72 hours.



Appendix D. PCI Summary

The PCI summary provides an index of pavement conditions at the airport. The letter in the first column indicates the type of pavement, asphalt or portland cement. The last column lists the distress types found in each sample unit. The distress types are listed by a numbering code for each type of pavement, shown at the beginning of the summary.

AIRPAV							
CONDITION SURVEY SUMMARY							
AIRPORT: 417 GREENCASTLE-PUTNAM COUNTY				DATE: 12-30-2009			
"A" FLEXIBLE PAVEMENT DISTRESS CODES				"T" RIGID PAVEMENT DISTRESS CODES			
1. ALLIGATOR CRACKING 2. BLEEDING 3. BLOCK CRACKING 4. CORRUGATION 5. DEPRESSION 6. JET BLAST EROSION 7. JOINT REFL. CRACKING 8. LONG. & TRANS. CRACKING 9. OIL SPILL 10. PATCHING 11. POLISHED AGGREGATE 12. RAVELLING/WEATHERING 13. RUTTING 14. SHOIVING FROM PCC SLAB 15. SLIPPAGE CRACKING 16. SWELLING				1. BLOW UP 2. CORNER BREAK 3. LTD CRACKING 4. "D" CRACKING 5. JOINT SEAL DAMAGE 6. SMALL PATCH 7. LARGE PATCH 8. POPOUTS 9. PUMPING 10. SCALING-MAP CRACKING/CRAZING 11. FAULTING 12. SHATTERED SLAB 13. SHRINKAGE CRACKING 14. JOINT SPALLING 15. CORNER SPALLING			
FEATURE:	SAMPLE UNIT:	AREA:	DATE:	SURVEYED BY:	PCI:	DISTRESSES PRESENT:	
	105 A	105.100	3750	8-16-09	JB	83	8 12
	105 A	105.103	3500	8-16-09	JB	79	8 12
	105 A	105.105	3500	8-16-09	JB	63	5 8 10 12*
	105 A	105.106	3500	8-16-09	AN	79	1 8
	105 A	105.109	3500	8-16-09	AN	86	8
	105 A	105.112	3500	8-16-09	AN	84	8 12
MEAN FEATURE PCI = 81 BASED ON A SAMPLED AREA OF 21250 SQUARE FEET - PCI SPREAD FOR FEATURE = 22.74 DESCRIPTION: TAXIWAY A							
	110 A	110.102	3500	8-16-09	JB	100	
	110 A	110.106	3500	8-16-09	JB	100	
	110 A	110.110	3500	8-16-09	JB	100	
	110 A	110.112	3500	8-16-09	JB	100	
	110 A	110.114	3500	8-16-09	JB	100	
	110 A	110.118	1750	8-16-09	JB	94	8
AVERAGE FEATURE PCI = 99 BASED ON A SAMPLED AREA OF 19250 SQUARE FEET - PCI SPREAD FOR FEATURE = 6.20 DESCRIPTION: TAXIWAY A							
	115 A	115.118	1750	8-16-09	JB	94	8
	115 A	115.122	3500	8-16-09	JB	95	8
	115 A	115.126	3500	8-16-09	JB	96	8
	115 A	115.130	3500	8-16-09	JB	96	8
	115 A	115.134	3500	8-16-09	JB	96	8
	115 A	115.136	3500	8-16-09	JB	94	8
	115 A	115.138	3500	8-16-09	JB	96	8
	115 A	115.142	3500	8-16-09	AN	93	8
AVERAGE FEATURE PCI = 95 BASED ON A SAMPLED AREA OF 26250 SQUARE FEET - PCI SPREAD FOR FEATURE = 3.38 DESCRIPTION: TAXIWAY A							
	210 A	210.200	3500	8-16-09	AN	94	8
	210 A	210.201	3500	8-16-09	AN	94	8
	210 A	210.202	1190	8-16-09	AN	86	8
AVERAGE FEATURE PCI = 91 BASED ON A SAMPLED AREA OF 8190 SQUARE FEET - PCI SPREAD FOR FEATURE = 7.93 DESCRIPTION: CONNECTOR TAXIWAY B							

Sample units marked with an asterisk (*) are additional sample units. Additional sample units do not represent the typical condition of surrounding sample units in the pavement features.

The PCI summary provides a quick overview of the pavement condition and consistency. Are the distress types similar? Do the individual sample units have consistent PCI ratings? Answering these questions is a start to understanding your dynamic pavement system.

CONDITION SURVEY SUMMARY

AIRPORT: FKR FRANKFORT MUNICIPAL

DATE: 12-09-2012

"A" FLEXIBLE PAVEMENT DISTRESS CODES

1. ALLIGATOR CRACKING
2. BLEEDING
3. BLOCK CRACKING
4. CORRUGATION
5. DEPRESSION
6. JET BLAST EROSION
7. JOINT REFL. CRACKING
8. LONG. & TRANS. CRACKING
9. OIL SPILL
10. PATCHING
11. POLISHED AGGREGATE
12. RAVELLING
13. RUTTING
14. SHOVING FROM PCC SLAB
15. SLIPPAGE CRACKING
16. SWELLING
17. WEATHERING

"P" RIGID PAVEMENT DISTRESS CODES

1. BLOW UP
2. CORNER BREAK
3. LTD CRACKING
4. "D" CRACKING
5. JOINT SEAL DAMAGE
6. SMALL PATCH
7. LARGE PATCH
8. POPOUTS
9. PUMPING
10. SCALING/MAP CRACKING/CRAZING
11. FAULTING
12. SHATTERED SLAB
13. SHRINKAGE CRACKING
14. JOINT SPALLING
15. CORNER SPALLING
16. ALKALI SILICA REACTION

FEATURE:	SAMPLE UNIT:	AREA:	DATE:	SURVEYED BY:	PCI:	DISTRESSES PRESENT:
101 A	101.100	1350	8-23-12	EOJ	64	8 10 12 17
101 A	101.101	4500	8-23-12	EOJ	48	1 5 8 17

AVERAGE FEATURE PCI = 56**BASED ON A SAMPLED AREA OF 5850 SQUARE FEET - PCI SPREAD FOR FEATURE = 16.24****DESCRIPTION: NORTH TAXIWAY**

105 A	105.103	2250	8-23-12	EOJ	63	8 12 17
105 A	105.105	2000	8-23-12	EOJ	80	8 17
105 A	105.203	5500	8-23-12	ABN	68	5 8 12 17

AVERAGE FEATURE PCI = 70**BASED ON A SAMPLED AREA OF 9750 SQUARE FEET - PCI SPREAD FOR FEATURE = 17.44****DESCRIPTION: NORTH TAXIWAY**

110 A	110.100	3020	8-23-12	EOJ	83	8
-------	---------	------	---------	-----	----	---

AVERAGE FEATURE PCI = 83**BASED ON A SAMPLED AREA OF 3020 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.00****DESCRIPTION: NORTH TAXIWAY**

125 A	125.101	3500	8-23-12	EOJ	100	
125 A	125.105	3500	8-23-12	EOJ	100	
125 A	125.110	3500	8-23-12	EOJ	100	
125 A	125.115	3500	8-23-12	EOJ	100	
125 A	125.120	3500	8-23-12	EOJ	100	

AVERAGE FEATURE PCI = 100**BASED ON A SAMPLED AREA OF 17500 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.00****DESCRIPTION: TAXIWAY A**

130 A	130.101	3500	8-23-12	DMY	100	
130 A	130.102	3500	8-23-12	DMY	100	

AVERAGE FEATURE PCI = 100**BASED ON A SAMPLED AREA OF 7000 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.00****DESCRIPTION: TAXIWAY A-1**

FEATURE: SAMPLE UNIT: AREA: DATE: SURVEYED BY: PCI: DISTRESSES PRESENT:

135 A	135.125	3500	8-23-12	DMY	100	
135 A	135.130	3500	8-23-12	DMY	100	
135 A	135.132	3500	8-23-12	DMY	100	
135 A	135.135	3500	8-23-12	DMY	100	
135 A	135.140	3500	8-23-12	DMY	100	
135 A	135.142	3500	8-23-12	DMY	100	
135 A	135.145	3500	8-23-12	DMY	100	
135 A	135.147	3500	8-23-12	DMY	100	

**AVERAGE FEATURE PCI = 100
 BASED ON A SAMPLED AREA OF 28000 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.00
 DESCRIPTION: TAXIWAY A**

201 A	201.107	2500	8-23-12	ABN	47	1 8 13 17
201 A	201.109	2500	8-23-12	ABN	54	1 8 13 17
201 A	201.111	2300	8-23-12	ABN	57	1 5 8 17
201 A	201.112	2300	8-23-12	ABN	56	1 5 8 17

**AVERAGE FEATURE PCI = 54
 BASED ON A SAMPLED AREA OF 9600 SQUARE FEET - PCI SPREAD FOR FEATURE = 10.10
 DESCRIPTION: TAXIWAY B**

210 A	210.114	4090	8-23-12	ABN	46	3 8 16 17
-------	---------	------	---------	-----	----	-----------

**AVERAGE FEATURE PCI = 46
 BASED ON A SAMPLED AREA OF 4090 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.00
 DESCRIPTION: TAXIWAY B**

225 A	225.101	3500	8-23-12	DMY	100	
225 A	225.102	3500	8-23-12	DMY	100	
225 A	225.104	3500	8-23-12	DMY	100	
225 A	225.105	3500	8-23-12	DMY	100	

**AVERAGE FEATURE PCI = 100
 BASED ON A SAMPLED AREA OF 14000 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.00
 DESCRIPTION: TAXIWAY B**

3001 A	3001.100	5000	8-23-12	DMY	32	1 3 8 10 12
3001 A	3001.201	5000	8-23-12	DMY	24	1 8 12 13 15
3001 A	3001.300	4250	8-23-12	EOJ	30	1 3 8 12

**AVERAGE FEATURE PCI = 29
 BASED ON A SAMPLED AREA OF 14250 SQUARE FEET - PCI SPREAD FOR FEATURE = 7.84
 DESCRIPTION: RAMP**

3002 A	3002.200	2650	8-23-12	ABN	57	8 12
3002 A	3002.201	4000	8-23-12	ABN	39	5 8 12

**AVERAGE FEATURE PCI = 48
 BASED ON A SAMPLED AREA OF 6650 SQUARE FEET - PCI SPREAD FOR FEATURE = 18.61
 DESCRIPTION: FUELING RAMP**

3015 P	3015.101	3600	8-23-12	ABN	100	
3015 P	3015.200	3600	8-23-12	ABN	100	

**AVERAGE FEATURE PCI = 100
 BASED ON A SAMPLED AREA OF 7200 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.00
 DESCRIPTION: TERMINAL RAMP**

3020 A	3020.206	3760	8-23-12	DMY	100	
3020 A	3020.301	3780	8-23-12	DMY	100	

**AVERAGE FEATURE PCI = 100
 BASED ON A SAMPLED AREA OF 7540 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.00
 DESCRIPTION: SOUTH RAMP**

4105 A	4105.100	6000	8-23-12	EOJ	38	1 8 12 13
4105 A	4105.102	6000	8-23-12	ABN	40	1 8 13 17
4105 A	4105.300	6000	8-23-12	EOJ	54	1 3 5 8 9 12

FEATURE: SAMPLE UNIT: AREA: DATE: SURVEYED BY: PCI: DISTRESSES PRESENT:

4105 A 4105.302 6000 8-23-12 ABN 62 8 13 17

**AVERAGE FEATURE PCI = 49
 BASED ON A SAMPLED AREA OF 24000 SQUARE FEET - PCI SPREAD FOR FEATURE = 24.06
 DESCRIPTION: TEE HANGARS**

4110 A 4110.401 3300 8-23-12 ABN 85 8
 4110 A 4110.500 4160 8-23-12 EOJ 95 5 8 17
 4110 A 4110.601 3000 8-23-12 ABN 90 8 17
 4110 A 4110.700 5000 8-23-12 EOJ 93 5 8 17
 4110 A 4110.701 6000 8-23-12 ABN 95 17

**AVERAGE FEATURE PCI = 92
 BASED ON A SAMPLED AREA OF 21460 SQUARE FEET - PCI SPREAD FOR FEATURE = 10.81
 DESCRIPTION: TEE HANGARS**

6105 A 6105.101 3750 8-23-12 EOJ 100
 6105 A 6105.107 3750 8-23-12 EOJ 95 8
 6105 A 6105.114 3750 8-23-12 EOJ 95 8
 6105 A 6105.121 3750 8-23-12 EOJ 93 8
 6105 A 6105.128 3750 8-23-12 EOJ 95 8
 6105 A 6105.135 3750 8-23-12 EOJ 96 8
 6105 A 6105.141 3750 8-23-12 EOJ 95 8
 6105 A 6105.149 3750 8-23-12 EOJ 97 8
 6105 A 6105.156 3750 8-23-12 EOJ 100
 6105 A 6105.163 3750 8-23-12 EOJ 95 8
 6105 A 6105.172 3750 8-23-12 EOJ 95 8
 6105 A 6105.178 3750 8-23-12 EOJ 90 8
 6105 A 6105.185 3750 8-23-12 EOJ 96 8
 6105 A 6105.191 3750 8-23-12 EOJ 95 8
 6105 A 6105.197 3750 8-23-12 EOJ 96 8

**AVERAGE FEATURE PCI = 96
 BASED ON A SAMPLED AREA OF 56250 SQUARE FEET - PCI SPREAD FOR FEATURE = 9.75
 DESCRIPTION: RUNWAY 9-27**

6205 A 6205.108 5000 8-23-12 ARA 87 8
 6205 A 6205.111 5000 8-23-12 ARA 90 8
 6205 A 6205.114 5000 8-23-12 ARA 89 8
 6205 A 6205.116 5000 8-23-12 ARA 87 8
 6205 A 6205.118 5000 8-23-12 ARA 92 8
 6205 A 6205.122 5000 8-23-12 ARA 89 8

**AVERAGE FEATURE PCI = 89
 BASED ON A SAMPLED AREA OF 30000 SQUARE FEET - PCI SPREAD FOR FEATURE = 5.54
 DESCRIPTION: RUNWAY 4-22 KEEL**

6210 A 6210.208 2000 8-23-12 ARA 86 8
 6210 A 6210.211 2000 8-23-12 ARA 91 8
 6210 A 6210.214 2000 8-23-12 ARA 89 8
 6210 A 6210.216 2000 8-23-12 ARA 88 8
 6210 A 6210.218 2000 8-23-12 ARA 100
 6210 A 6210.222 2000 8-23-12 ARA 89 8

**AVERAGE FEATURE PCI = 91
 BASED ON A SAMPLED AREA OF 12000 SQUARE FEET - PCI SPREAD FOR FEATURE = 13.75
 DESCRIPTION: RUNWAY 4-22 WING**

6215 A 6215.100 5000 8-23-12 ARA 86 8
 6215 A 6215.104 5000 8-23-12 ARA 89 8
 6215 A 6215.105 5000 8-23-12 ARA 95 8

**AVERAGE FEATURE PCI = 90
 BASED ON A SAMPLED AREA OF 15000 SQUARE FEET - PCI SPREAD FOR FEATURE = 9.45
 DESCRIPTION: RUNWAY 4-22**

6220 A 6220.200 5300 8-23-12 ARA 98 8
 6220 A 6220.204 2000 8-23-12 ARA 89 8
 6220 A 6220.205 2000 8-23-12 ARA 95 8

**AVERAGE FEATURE PCI = 94
 BASED ON A SAMPLED AREA OF 9300 SQUARE FEET - PCI SPREAD FOR FEATURE = 8.58
 DESCRIPTION: RUNWAY 4-22**

TOTAL NUMBER OF INSPECTED FEATURES = 20
TOTAL NUMBER OF INSPECTED SAMPLE UNITS = 81

TOTAL AREA OF INSPECTED PAVEMENT = 302,460 S.F.

*** INDICATES "ADDITIONAL" SAMPLE UNITS.**

Appendix E. Distress Identification

This chapter describes pavement distress types commonly identified during airport PCI inspections.

Rigid Pavement Distress

Longitudinal, Transverse & Diagonal Cracking

LTD cracking is often a result of load or temperature deformations. External loads cause flexure. Temperature changes can cause curling. When any of these stresses exceed the slab strength, cracking occurs.

LTD cracking is recorded at low, medium, or high severity, depending on the width of crack opening and degree of deterioration.

At low severity, a crack is less than 1/8 inch wide with little spalling, and no corrective action is indicated. At medium severity, LTD cracks can be up to 1 inch wide with moderate spalling and should be repaired using procedures similar to joint sealing. At high severity, cracks exceed 1 inch in width and may be severely spalled. High-severity LTD cracking is evidence of serious load failure, and correction may require patching or slab replacement. If distress occurs in several adjacent slabs at medium or high severity, major rehabilitation of that area is indicated.

A slab divided into four or more pieces is said to be “divided” or “shattered.” Shattered slab is a separate distress category and indicates a significant structural failure. A shattered slab has lost its ability to distribute loads. Shattered slabs are rated in three severities, but the recommended action in any case is slab replacement.



Shrinkage Cracking

Shrinkage cracks are small, non-working cracks visible at the pavement surface but not penetrating the full depth of concrete. Shrinkage cracks most commonly occur shortly after construction due to concrete shrinkage during the curing process.

Shrinkage cracks are usually so small that they are not visible until staining or loss of material at crack edges begins to take place. Shrinkage cracks do not represent structural weakness, and no corrective action is prescribed.



Durability Cracking

Durability cracking (D-cracking) is caused by environmental factors, the most common being freeze/thaw. D-cracking usually appears as either a pattern of hairline cracks running parallel to a joint or crack, or in a corner, where water tends to collect. D-cracking eventually leads to disintegration of the pavement, creating foreign object damage (FOD) potential.

At low severity, D-cracking is evident, but no disintegration has occurred. Medium severity is evident over a significant area of the slab, and some disintegration and FOD potential exist. High-severity D-cracking is evidenced by extensive cracking with loose and missing pieces and significant FOD potential.



Joint Spall and Corner Spall

Spalls at slab joints and corners are caused by excessive internal stress in the pavement. Spalls occur when these stresses exceed the shear strength of the concrete.

Spalling usually results from thermal expansion during hot weather when slabs push and expand against one another. If the joints are filled with incompressible material, such as sand, stresses can become severe, causing spalls. Spalling can be reduced significantly by maintenance of joint sealant.

Spall repair requires patching. The extent and severity of spalling suggests the appropriate action. At low severity, spalled concrete remains securely in place in the slab. A low-severity spall should be monitored closely for further deterioration and should be patched when spalled particles become loose, or during the next scheduled patching activity. Medium- and high-severity spalls should be repaired immediately to prevent FOD. If the pavement can be restored to serviceable condition, spalls should be patched for long-term service. If the pavement is beyond repair, temporary patching should be considered to control FOD.



Patches, Large and Small

Large and small patches, by PCI inspection criteria, are distress conditions. Patches indicate deterioration and aging of pavement that contributes to shortened service life. However, patching also indicates that pavement is being maintained.

A patch that is performing well and shows no outward distress is recorded at low severity, and no corrective action is required. Medium-severity patches are serviceable but are beginning to deteriorate. Maintenance or replacement is indicated. At high severity, replacement is indicated.

By definition, small patches are smaller than 5 square feet in surface area, and they usually result from spall repair at slab joints and corners.

Large patches also may be the result of spall repair, but they often indicate more serious deficiencies, such as corner breaks or other full-depth failure smaller than panel size.



Joint Seal Damage

When joint sealant is in perfect condition (no damage), there is no distress.

At low severity, at least 10 percent of the sealant is debonded but still in contact with the joint edges. Medium-severity joint seal damage is recorded when at least 10 percent of the sealant has visible gaps smaller than 1/8 inch and is an indicator that replacement should be programmed as soon as is practical. In the meantime, aggressive inspection and sustaining maintenance is recommended to minimize subsurface damage from moisture penetration. At high severity, visible gaps exceed 1/8 inch, and the amount and degree of joint seal damage typically requires complete removal and replacement of the existing sealant.

On serviceable pavement, deteriorated joint sealant should be repaired or replaced to preserve pavement and subgrade integrity and prolong service life. The issue is not so clear-cut with unserviceable pavement. Pavement that can be restored to serviceable condition by maintenance activities such as patching and joint seal repair, or by slab replacement, should be so maintained as long as the process is cost-effective. However, when age and condition preclude economical return to serviceable condition by such means, joint seal repair would no longer be cost-effective and should be suspended except for an interim maintenance program to control FOD potential.



Flexible Pavement Distress

Longitudinal & Trans. Cracking

L&T cracks are caused by age, construction, and subsurface conditions. Age-related cracking occurs as oxidizing pavement loses components to the atmosphere and becomes more brittle. Consistent application of seal coats can help to prevent age-related cracks.

Construction-related cracking often develops along paving joints. Ensuring that joints are made when both sides are still hot, and near the same temperature, is one of the best ways to mitigate this potential problem.

Seasonal movement caused by changes in subsurface moisture or temperature differences also can cause pavement cracking. Asphalt pavement placed over a PCC pavement or cement stabilized base course may evidence reflective cracking from the underlying material. Wheel loads do not cause L&T cracks, although traffic may worsen their condition.

Low-severity L&T cracks are less than ¼ inch wide, or if sealed with suitable filler material in satisfactory condition can be any width less than 3 inches, if they are not spalled. Maintenance usually is not indicated for low-severity cracking. Moderately spalled cracks and cracks wider than ¼ inch which are not satisfactorily sealed are at medium severity. Medium-severity cracks should be sealed with a high-quality crack filling material. Severely spalled cracks and cracks wider than 3 inches are at high severity. High-severity L&T cracks normally require patching.



Alligator Cracking

Alligator cracks are a series of interconnected load-related cracks caused by fatigue of the asphalt surface. Alligator cracking is a significant structural distress and develops only in places subject to traffic loads. These cracks typically initiate at the bottom of the asphalt layer and propagate upward. Once a fatigue crack is visible at the surface, significant damage has already occurred.

At low severity, alligator cracks are evidenced by a series of parallel hairline cracks (usually in a wheel path). Medium-severity alligator cracking is a well-defined pattern of interconnected cracks, and some spalling may be present. High-severity alligator cracks have lost aggregate interlock between adjacent pieces, and the cracks may be severely spalled with FOD potential. Most likely, the pieces will move freely under traffic.

Alligator cracking is a serious structural failure that cannot be repaired with sealant. The proper repair is patching.



Raveling/Weathering

Raveling and weathering are the wearing away of the pavement surface. Failure can be caused by the dislodging of aggregate particles or the loss of asphalt binder. These distresses are usually evident over large areas and may indicate that the asphalt binder has hardened significantly.

Raveling is the loss of coarse aggregate, weathering is the loss of fine aggregate or binder.

Raveling: At low severity, 5 to 20 coarse aggregate particles are missing per square yard. Medium severity is defined by 20 to 40 missing coarse aggregate particles per square yard. At high severity, more than 40 coarse aggregate particles are missing per square yard, and the top layer of aggregate has eroded away.

Weathering: At low severity, edges of coarse aggregate are exposed less than 1 mm. At medium severity, loss of fine aggregate is noticeable and edges of coarse aggregate are exposed up to 6 mm (1/4 inch). High severity weathering has edges of coarse aggregate exposed > 6 mm, with considerable loss of fine aggregate matrix and potential for loss of coarse aggregate.




Rutting

Ruts are localized areas of pavement having elevations lower than the surrounding sections.

Rutting is due to base and subgrade consolidation caused by excessive wheel loads or poor compaction. Ruts indicate structural failure and can cause hydroplaning.

At low severity, ruts have an average depth of ¼ to ½ inches. At medium severity, ruts have an average depth of ½ to 1 inch. At high severity, ruts have an average depth greater than 1 inch. Patching is the appropriate repair for ruts.



Appendix F. Airport Responsibilities

Grant Assurances

In 1995, Congress mandated that the FAA require, as a condition of grant funding, that airport sponsors prepare documentation of a maintenance management program on pavement that has been constructed, reconstructed, or repaired with Federal assistance.

This report fulfills many of the grant assurance requirements, including documenting:

- Locating all runways, taxiways, and aprons.
- Documenting pavement dimensions.
- Documenting types of pavement.
- Documenting year of construction or most recent major rehabilitation.

The airport owners must be an active participant in maintaining compliance. Actions taken to ensure compliance include:

- Annotating areas constructed or repaired with Federal aid.
- Conducting monthly drive-by inspections to detect changes in pavement condition.
- Recording each drive-by inspection and any maintenance performed as a result.
- Keeping complete records of all maintenance activities.
- Keeping records for 5 years.
- Documenting detailed inspection information with a history of recorded pavement deterioration by PCI survey (e.g., this report).

ASSURANCES Airport Sponsors	
A. General.	<ol style="list-style-type: none"> 1. These assurances shall be complied with in the performance of grant agreements for airport development, airport planning, and noise compatibility program grants for airport sponsors. 2. These assurances are required to be submitted as part of the project application by sponsors requesting funds under the provisions of Title 49, U.S.C., subtitle VII, as amended. As used herein, the term "public agency sponsor" means a public agency with control of a public-use airport; the term "private sponsor" means a private owner of a public-use airport; and the term "sponsor" includes both public agency sponsors and private sponsors. 3. Upon acceptance of the grant offer by the sponsor, these assurances are incorporated in and become part of the grant agreement.
B. Duration and Applicability.	<ol style="list-style-type: none"> 1. Airport development or Noise Compatibility Program Projects Undertaken by a Public Agency Sponsor. The terms, conditions and assurances of the grant agreement shall remain in full force and effect throughout the useful life of the facilities developed or equipment acquired for an airport development or noise compatibility program project, or throughout the useful life of the project items installed within a facility under a noise compatibility program project, but in any event not to exceed twenty (20) years from the date of acceptance of a grant offer of Federal funds for the project. However, there shall be no limit on the duration of the assurances regarding Exclusive Rights and Airport Revenue so long as the airport is used as an airport. There shall be no limit on the duration of the terms, conditions, and assurances with respect to real property acquired with federal funds. Furthermore, the duration of the Civil Rights assurance shall be specified in the assurances. 2. Airport Development or Noise Compatibility Projects Undertaken by a Private Sponsor. The preceding paragraph 1 also applies to a private sponsor except that the useful life of project items installed within a facility or the useful life of the facilities developed or equipment acquired under an airport development or noise compatibility program project shall be no less than ten (10) years from the date of acceptance of Federal aid for the project. 3. Airport Planning Undertaken by a Sponsor. Unless otherwise specified in the grant agreement, only Assurances 1, 2, 3, 5, 6, 13, 18, 30, 32, 33, and 34 in section C apply to planning projects. The terms, conditions, and assurances of the grant agreement shall remain in full force and effect during the life of the project.
C. Sponsor Certification.	<p>The sponsor hereby assures and certifies, with respect to this grant that:</p> <ol style="list-style-type: none"> 1. General Federal Requirements. It will comply with all applicable Federal laws, regulations, executive orders, policies, guidelines, and requirements as they relate to the application, acceptance and use of Federal funds for this project including but not limited to the following: <ul style="list-style-type: none"> Federal Legislation <ol style="list-style-type: none"> a. Title 49, U.S.C., subtitle VII, as amended. b. Davis-Bacon Act - 40 U.S.C. 276(a), <i>et seq.</i>¹ c. Federal Fair Labor Standards Act - 29 U.S.C. 201, <i>et seq.</i> d. Hatch Act - 5 U.S.C. 1501, <i>et seq.</i>²
Airport Assurances (3/2005)	

The table on the following pages is available for maintaining a record of drive-by inspections and maintenance repairs.

Frankfort Municipal Airport 2012 PCI Inspection

