

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G380	X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	X3) DATE SURVEY COMPLETED 01/08/2016
--	---	---	---

NAME OF PROVIDER OR SUPPLIER LIFE DESIGNS INC	STREET ADDRESS, CITY, STATE, ZIP CODE 1701 WINSLOW RD BLOOMINGTON, IN 47401
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 0000 Bldg. 01	<p>A Life Safety Code Recertification Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j).</p> <p>Survey Date: 01/08/16</p> <p>Facility Number: 000894 Provider Number: 15G380 AIM Number: 100239710</p> <p>At this Life Safety Code survey, Life Designs Inc. was found not in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2000 Edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies.</p> <p>This two story building with a basement was determined to be fully sprinklered. The facility has a monitored fire alarm system with smoke detection on all levels in corridors, in sleeping rooms and in all living areas. The facility has a capacity of 6 and had a census of 4 at the time of this survey.</p> <p>Calculation of the Evacuation Difficulty</p>	K 0000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G380	X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	X3) DATE SURVEY COMPLETED 01/08/2016
--	---	---	---

NAME OF PROVIDER OR SUPPLIER LIFE DESIGNS INC	STREET ADDRESS, CITY, STATE, ZIP CODE 1701 WINSLOW RD BLOOMINGTON, IN 47401
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K S053 Bldg. 01	<p>Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Prompt with an E-Score of 1.2.</p> <p>Quality Review on 01/13/16 - DA</p> <p>483.470(j)(1)(i) LIFE SAFETY CODE STANDARD Approved smoke alarms are provided in accordance with 9.6.2.10. These alarms are powered from the building electrical system and when activated, initiate an alarm that is audible in all sleeping areas. Smoke alarms are installed on all levels, including basements but excluding crawl spaces and unfinished attics. Additional smoke alarms are installed for living rooms, dens, day rooms, and similar spaces. 33.2.3.4.3.</p> <p>Exception No 1: Buildings protected throughout by an approved automatic sprinkler system, in accordance with 33.2.3.5, that uses quick response or residential sprinklers, and protected with approved smoke alarms installed in each sleeping room in accordance with 9.6.2.10, that are powered by the building electrical system.</p> <p>Exception No. 2: Where buildings are protected throughout by an approved automatic sprinkler system, in accordance with 32.3.2.5, that uses quick-response or residential sprinklers, with existing battery-powered smoke alarms in each sleeping room, and where, in the opinion of the authority having jurisdiction, the facility has demonstrated that testing, maintenance, and a battery replacement program ensure the reliability of power to smoke alarms.</p>			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G380		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 01/08/2016	
NAME OF PROVIDER OR SUPPLIER LIFE DESIGNS INC				STREET ADDRESS, CITY, STATE, ZIP CODE 1701 WINSLOW RD BLOOMINGTON, IN 47401			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
	Based on record review and interview, the facility failed to ensure 7 of 12 smoke detectors were within their listed and marked sensitivity range. LSC Section 9.6.2.10.1 refers to NFPA 72, National Fire Alarm Code. NFPA 72, at 7-3 requires testing to be in accordance with Section 7-3, Inspection and Testing Frequency. NFPA 72, 7-3.2.1 states detector sensitivity shall be checked within 1 year of installation, and every alternate year thereafter. After the second required calibration test, if sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range, the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. If the frequency is extended, records of detector caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show an increase over the previous year, calibration tests shall be performed. To ensure that each smoke detector is within its listed and marked sensitivity range, it shall be tested using any of the methods: (1) Calibrated test method. (2) Manufacturer's calibrated sensitivity test instrument. (3) Listed control equipment arranged for the purpose. (4) Smoke detector/control unit	K S053	To correct the deficient practice and ensure it does not continue, the 7 smoke heads that were not tested were replaced with smoke heads that can be sensitivity tested. The new smoke heads were sensitivity tested at the time of installation. LifeDesigns has an agreement in place with Koorsen to ensure sensitivity testing of all smoke heads every 2 years. Ongoing monitoring will be accomplished by the Maintenance Supervisor's review of the agreement, as well as the Network Director/ QDDP regular review of the LifeSafety book that is maintained in the home.	01/25/2016			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G380		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 01/08/2016	
NAME OF PROVIDER OR SUPPLIER LIFE DESIGNS INC				STREET ADDRESS, CITY, STATE, ZIP CODE 1701 WINSLOW RD BLOOMINGTON, IN 47401			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
	<p>arrangement whereby the detector causes a signal at the control unit where its sensitivity is outside its listed sensitivity range.</p> <p>(5) Other calibrated sensitivity method acceptable to the authority having jurisdiction.</p> <p>Detectors found to have sensitivity outside the listed and marked sensitivity range shall be cleaned and recalibrated, or replaced.</p> <p>The detector sensitivity cannot be tested or measured using any spray device that administers an unmeasured concentration of aerosol into the detector. This deficient practice could affect all clients, staff, and visitors.</p> <p>Findings include:</p> <p>Based on review of Koorsen Fire & Security "Sensitivity and Detection Inspection Report" documentation dated 08/19/15 with the Network Director during record review from 10:20 a.m. to 11:10 a.m. on 01/08/16, documentation of smoke detector sensitivity testing for 7 of 12 smoke detectors within the most recent two year period was not available for review. Koorsen's 08/19/15 documentation for 7 of 12 smoke detector locations in the facility did not list the sensitivity range and did not list a sensitivity alarm point. Based on</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G380	X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____		X3) DATE SURVEY COMPLETED 01/08/2016
NAME OF PROVIDER OR SUPPLIER LIFE DESIGNS INC			STREET ADDRESS, CITY, STATE, ZIP CODE 1701 WINSLOW RD BLOOMINGTON, IN 47401		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
	interview at the time of record review, the Network Director acknowledged written smoke detector sensitivity documentation for the most recent two year period for 7 of 12 smoke detectors was not available for review.				