

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G435	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED 02/24/2012
--	---	--	---

NAME OF PROVIDER OR SUPPLIER TRANSITIONAL SERVICES SUB LLC	STREET ADDRESS, CITY, STATE, ZIP CODE 4155 RAY ST INDIANAPOLIS, IN 46241
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PERCEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K0000	<p>A Life Safety Code Recertification Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j).</p> <p>Survey Date: 02/24/12</p> <p>Facility Number: 000949 Provider Number: 15G435 AIM Number: 100244680</p> <p>Surveyor: Mark Caraher, Life Safety Code Specialist,</p> <p>At this Life Safety Code survey, Transitional Services Sub LLC was found not in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2000 Edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies.</p> <p>This one story building was determined to be fully sprinklered. The facility has a fire alarm system with smoke detection in corridors, sleeping rooms and all living areas. The facility has a capacity of 8 and had a census of 8 at the time of this survey.</p>	K0000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G435	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED 02/24/2012
--	---	--	---

NAME OF PROVIDER OR SUPPLIER TRANSITIONAL SERVICES SUB LLC	STREET ADDRESS, CITY, STATE, ZIP CODE 4155 RAY ST INDIANAPOLIS, IN 46241
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 2.8.</p> <p>Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 02/27/12.</p> <p>The facility was found not in compliance with the aforementioned regulatory requirements as evidenced by the following:</p>			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G435		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 02/24/2012	
NAME OF PROVIDER OR SUPPLIER TRANSITIONAL SERVICES SUB LLC				STREET ADDRESS, CITY, STATE, ZIP CODE 4155 RAY ST INDIANAPOLIS, IN 46241			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
K0130	<p>Based on observation and interview, the facility failed to ensure 1 of 2 smoke barrier door sets held open by devices arranged to automatically close would self close when the fire alarm system was activated. LSC 4.6.12.2 states existing life safety features obvious to the public, if not required by the Code, shall be either maintained or removed. This deficient practice could affect 4 of 8 clients.</p> <p>Findings include:</p> <p>Based on observation with the Direct Services Provider (DSP) during a tour of the facility from 1:30 p.m. to 1:50 p.m. on 02/24/12, the east corridor smoke barrier door set which is held open by a magnetic hold open device did not self close because the astragal on the west door was stuck to the floor when the fire alarm system was activated. Based on interview at the time of observation, the DSP acknowledged the east corridor smoke barrier door set did not self close when the fire alarm system was activated because the astragal on the west door was stuck to the floor.</p>	K0130	<p>The Area Director will ensure that US Automatic repairs the smoke barrier door, which did not release and close when the fire alarm system was activated.</p> <p>The Area Director will train the Home Manager on reporting to the Area Director when equipment fails to work correctly during fire/evacuation drills to ensure that issues are repaired immediately.</p> <p>The Program Director will check the fire safety related equipment at the home and note in her review of the home that all is in working order when she visits at the home every other week for 4 weeks after the assigned completion date.</p> <p>Responsible party: Area Director, Program Director and Home Manager.</p> <p>Completion Date: 03/25/2012</p>	03/25/2012			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G435	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 02/24/2012
NAME OF PROVIDER OR SUPPLIER TRANSITIONAL SERVICES SUB LLC			STREET ADDRESS, CITY, STATE, ZIP CODE 4155 RAY ST INDIANAPOLIS, IN 46241		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
KS152	<p>483.470(j)(1)(i) LIFE SAFETY CODE STANDARD</p> <p>(1) The facility holds evacuation drills at least quarterly for each shift of personnel and under varied conditions to -</p> <p>(i) Ensure that all personnel on all shifts are trained to perform assigned tasks;</p> <p>(ii) Ensure that all personnel on all shifts are familiar with the use of the facility's emergency and disaster plans and procedures.</p> <p>(2) The facility must -</p> <p>(i) Actually evacuate clients during at least one drill each year on each shift;</p> <p>(ii) Make special provisions for the evacuation of clients with physical disabilities:</p> <p>(iii) File a report and evaluation on each drill:</p> <p>(iv) Investigate all problems with evacuation drills, including accidents and take corrective action: and</p> <p>(v) During fire drills, clients may be evacuated to a safe area in facilities certified under the Health Care Occupancies Chapter of the Life Safety Code.</p> <p>(3) Facilities must meet the requirements of paragraphs (i) (1) and (2) of this section for any live-in and relief staff that they utilize.</p> <p>Based on record review and interview, the facility failed to conduct fire drills under varied conditions for 4 of 4 third shift fire drills. This deficient practice affects all clients and staff.</p> <p>Findings include:</p> <p>Based on review of "Fire Drill Report" documentation with the Area Director</p>	KS152	<p>The Evacuation drill schedule for 2012 was written so that drills each month are scheduled in varied time frames throughout the year.</p> <p>The Area Director will retrain the Home Manager and Program Director on ensuring evacuation drills are completed during the</p>	03/25/2012	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G435	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 02/24/2012
NAME OF PROVIDER OR SUPPLIER TRANSITIONAL SERVICES SUB LLC			STREET ADDRESS, CITY, STATE, ZIP CODE 4155 RAY ST INDIANAPOLIS, IN 46241		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
	during record review from 10:50 a.m. to 11:15 a.m. on 02/24/12, all four third shift fire drills conducted on 03/09/11, 06/06/11, 09/07/11 and 12/16/11 were conducted between 2:35 a.m. and 3:30 a.m. Based on interview at the time of record review, it was acknowledged by the Area Director, third shift fire drills were not conducted under varied conditions.		time specified on the 2012 schedule. The Home Manager will retrain staff on completing evacuation drills during the time frame specified in the 2012 drill schedule. The monthly evacuation drills are submitted to the Quality Assurance Specialist monthly to ensure that drills are completed accurately and during the specified drill time. Responsible party: Area Director, Program Director, Home Manager, Quality Assurance Specialist Completion Date: 03/25/2012		