

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155468	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED  07/19/2016
--	---	--	---

NAME OF PROVIDER OR SUPPLIER  BRECKENRIDGE HEALTH & REHABILITATION	STREET ADDRESS, CITY, STATE, ZIP CODE 325 W NORTHWOOD DR SULLIVAN, IN 47882
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
--------------------	--	---------------	---	----------------------

K 0000  Bldg. 01	<p>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 07/19/16</p> <p>Facility Number: 000525 Provider Number: 155468 AIM Number: 100267010</p> <p>At this Life Safety Code survey, Breckenridge Health and Rehabilitation Center was found not in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>This one story facility was determined to be of Type V (000) construction and was fully sprinklered. The facility has a fire alarm system with hard wired smoke detectors in the corridors and spaces open to the corridors, and the 300 hall resident rooms, plus battery operated smoke alarms in all resident sleeping rooms on</p>	K 0000	<p>Submission of this plan of correction does not constitute admission or agreement by the provider of the truth of facts alleged or correction set forth on the statement of deficiencies. The plan of correction is prepared and submitted because of requirement under state and federal law. Please accept this plan of correction as our credible allegation of compliance. Please find enclosed this plan of correction for this survey. Due to the nature of the survey finding, please find the sufficient documentation providing evidence of compliance with the plan of correction. The documentation serves to confirm the facility's allegation of compliance. Thus, the facility respectfully requests the granting of paper compliance. Should additional information be necessary to confirm said compliance, feel free to contact me.</p>	
------------------------	---	--------	--	--

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155468	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED  07/19/2016
--	---	--	---

NAME OF PROVIDER OR SUPPLIER  BRECKENRIDGE HEALTH & REHABILITATION	STREET ADDRESS, CITY, STATE, ZIP CODE 325 W NORTHWOOD DR SULLIVAN, IN 47882
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 0051 SS=F Bldg. 01	<p>the 100 and 200 halls. The facility has a capacity of 77 and had a census of 32 at the time of this survey.</p> <p>All areas where the residents have customary access were sprinklered and all areas providing facility services were sprinklered, except a garage used for a maintenance shop, plus two wood storage sheds.</p> <p>Quality Review completed on 07/21/16 - DA</p> <p>NFPA 101 LIFE SAFETY CODE STANDARD A fire alarm system is installed with systems and components approved for the purpose in accordance with NFPA 70, National Electric Code and NFPA 72, National Fire Alarm Code to provide effective warning of fire in any part of the building. Fire alarm system wiring or other transmission paths are monitored for integrity. Initiation of the fire alarm system is by manual means and by any required sprinkler system alarm, detection device, or detection system. Manual alarm boxes are provided in the path of egress near each required exit. Manual alarm boxes in patient sleeping areas shall not be required at exits if manual alarm boxes are located at all nurse's stations. Occupant notification is provided by audible and visual signals. In critical care areas, visual alarms are sufficient. The fire alarm system transmits the alarm automatically to notify emergency forces in the event of fire. The fire alarm automatically activates required control functions. System records</p>			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155468		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED  07/19/2016	
NAME OF PROVIDER OR SUPPLIER  BRECKENRIDGE HEALTH & REHABILITATION				STREET ADDRESS, CITY, STATE, ZIP CODE 325 W NORTHWOOD DR SULLIVAN, IN 47882			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
	<p>are maintained and readily available. 18.3.4, 19.3.4, 9.6</p> <p>Based on observation and interview, the facility failed to maintain 1 of 1 fire alarm systems in accordance with NFPA 72. NFPA 72, 1-5.4.6 requires trouble signals to be located in an area where it is likely to be heard. NFPA 72, 1-5.4.4 requires fire alarms, supervisory signals, and trouble signals to be distinctive and descriptively annunciated. This deficient practice could affect all residents, staff and visitors in the facility.</p> <p>Findings include:</p> <p>Based on observation on 07/19/16 at 11:05 a.m. during a tour of the facility with Maintenance Supervisor, the Digital Alarm Communicator Transmitter (DACT) was located in the room with the fire alarm control panel (FACP) and generator transfer panel. When the DACT was placed in trouble from phone line failure between 11:11 a.m. and 11:19 a.m. it did not actuate a local audible trouble signal at the DACT or FACP, however, the "Line 1" yellow light was illuminated and the "Trouble" yellow light was flashing on the DACT. Based on phone conversation, the fire alarm monitoring company did receive a trouble signal for phone line failure. Based on interview at the time of observation, the</p>	K 0051	<p>K 051 requires a fire alarm system be installed with systems and components approved for the purpose.</p> <ol style="list-style-type: none"> <li>1. No residents were harmed.</li> <li>2. All residents have the potential to be affected, thus the following corrective actions have been taken;</li> <li>3. As a means to ensure ongoing compliance, a contractor was called to the facility to complete the necessary repairs to ensure there is an audible trouble alarm.</li> <li>4. As a means of quality assurance, the fire system will continue to be reviewed as part of the facility preventative maintenance program. The preventative maintenance audits will be reviewed as part of the monthly quality assurance meetings with the plan of action adjusted accordingly, as warranted.</li> <li>5. The above corrective measures will be completed on or before August 18, 2016.</li> </ol>	08/18/2016			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155468	X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	X3) DATE SURVEY COMPLETED  07/19/2016
--	---	---	---

NAME OF PROVIDER OR SUPPLIER  BRECKENRIDGE HEALTH & REHABILITATION	STREET ADDRESS, CITY, STATE, ZIP CODE 325 W NORTHWOOD DR SULLIVAN, IN 47882
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 0144 SS=C Bldg. 01	<p>Maintenance Supervisor acknowledged the phone line failure did not actuate an audible trouble signal at the DACT or FACP.</p> <p>3.1-19(b)</p> <p>NFPA 101 LIFE SAFETY CODE STANDARD Generators inspected weekly and exercised under load for 30 minutes per month and shall be in accordance with NFPA 99 and NFPA 110. 3-4.4.1 and 8-4.2 (NFPA 99), Chapter 6 (NFPA 110)</p> <p>Based on record review and interview, the facility failed to ensure there was documentation 1 of 1 emergency generators was allowed a 5 minute cool down period after a load test. LSC 19.2.9.1 refers to LSC 7.9 which refers to LSC 7.9.2.3 which requires generators to be installed, tested and maintained in accordance with NFPA 110, Standard for Emergency and Standby Power Systems, 1999 Edition. NFPA 110, 4-2.4.8 Time Delay on Engine Shutdown requires that a minimum time delay of 5 minutes shall be provided for unloaded running of the Emergency Power Supply (EPS) prior to shutdown. This delay provides additional engine cool down. This time delay shall not be required on small (15 kW or less) air-cooled prime movers. This deficient practice could affect all residents, as well as staff and visitors in the facility.</p>	K 0144	<p>K144 requires generators be inspected weekly and exercised under load for 30 minutes per month.</p> <ol style="list-style-type: none"> <li>1. No residents were harmed.</li> <li>2. All residents have the potential to be affected, thus the following corrective actions have been taken;</li> <li>3. As a means to ensure ongoing compliance, the form utilized to document the exercising of the generator has been revised to include documentation regarding generator cool down following a load test, (See Attachment A).</li> <li>4. As a means of quality assurance, the monthly load testing of the generator will continue to be completes as part of the facility preventative maintenance program. The preventative maintenance audits will be reviewed as part of the monthly quality assurance meetings with the plan of action</li> </ol>	08/18/2016

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155468	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED  07/19/2016
--	---	--	---

NAME OF PROVIDER OR SUPPLIER  BRECKENRIDGE HEALTH & REHABILITATION	STREET ADDRESS, CITY, STATE, ZIP CODE 325 W NORTHWOOD DR SULLIVAN, IN 47882
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>Findings include:</p> <p>Based on review of the facility's emergency generator monthly load test log on 07/19/16 at 10:25 a.m. with Maintenance Supervisor present, the generator log form documented the generator was tested monthly for 30 minutes under load, however, there was no documentation on the form that showed the generator had a cool down time following its load test. During an interview at the time of record review, Maintenance Supervisor confirmed the monthly generator log did not include documentation of a cool down time being recorded.</p> <p>3.1-19(b)</p>		<p>adjusted accordingly, as warranted.</p> <p>5. The above corrective measures will be completed on or before August 18, 2016.</p>	