DEPARTMENT OF HEALTH AND HUMAN SERVICES	
CENTERS FOR MEDICARE & MEDICAID SERVICES	

	NT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 150045	A. BU	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 05/25/2021	
NAME OF	PROVIDER OR SUPPLIEF		•		ADDRESS, CITY, STATE, ZIP COD SEVENTH ST	•	
PARKVII	EW DEKALB HOSP	ITAL		AUBUR	RN, IN 46706		
(X4) ID PREFIX	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL		ID PREFIX	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROF DEFICIENCY)	BE	(X5) COMPLETION
TAG E 0000	REGULATORY OF	R LSC IDENTIFYING INFORMATION		TAG	BEIGERET		DATE
Bldg		paredness Survey was Idiana State Department of	E 0	000			
	Health in accordance Survey Date: 05/24	ee with 42 CFR 482.15 4/21 through 05/25/21					
	Facility Number: 0 Provider Number: AIM Number: 100	150045 269460A					
	Dekalb Hospital wa Emergency Prepare	Preparedness survey, Parkview as found in compliance with edness Requirements for caid Participating Providers SFR 482.15					
	18 on 05/24/21 and	apacity of 56 with a census of a census of 22 on 05/25/21.					
	Quality Review col	npleted on 05/27/21					
K 0000							
Bldg. 01		Recertification Survey was adiana Department of Health in CFR 482.41(b).	K 0	000			
	Survey Date: 05/24	1/21 through 05/25/21					
	Facility Number: 0 Provider Number: AIM Number: 100	150045					
		Code survey, Parkview Dekalb not in compliance with articipation in					
LABORATOI	RY DIRECTOR'S OR PRO	VIDER/SUPPLIER REPRESENTATIVE'S SI	GNATUR	<u> </u>	TITLE		(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

(X6) DATE

Any defiency statement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: 3Z5N21 Facility ID: 005041 If continuation sheet Page 1 of 14

PRINTED: 07/28/2021 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTIFICATION NUMBER 150045		, ,	5 <u>01</u>	COM	IPLETED 25/2021
		1316	E SEVENTH ST	P COD	
		ID PREFIX	(EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE	N SHOULD BE HE APPROPRIATE	(X5) COMPLETION
		TAG	DEFICIENCY)	DATE
National Fire Protec	tion Association (NFPA) 101,				
1964 building and the additions was deterronstruction and the Department addition	ne 1976, 1992, 2001, 2014 mined to be Type I (332) 2008 and 2011 Emergency n was determined to be Type I				
exception of the wal has a monitored fire detection in the corr corridors and in the is protected with a T generators. The faci	k-in cooler and freezer, and alarm system with smoke idors and spaces open to the operating rooms. The facility Type 1 EES by three lity has a capacity of 56 with a				
05/25/21.					
NFPA 101	Doore				'
Horizontal-Sliding Horizontal-sliding of that are not autom single leaf and sha mechanism to ens rebound. Horizontal-sliding of load fewer than 10 providing all of the o Area served by hazard contents. o Door is operate special knowledge o Force required	Doors doors permitted by 7.2.1.14 atic-closing are limited to a all have a latch or other ure the door will not doors serving an occupant a shall be permitted, following criteria are met: a the door has no high the from either side without a or effort. It to operate the door in the				
	SUMMARY S (EACH DEFICIENCY REGULATORY OR Medicare/Medicaid, Life Safety from Fir National Fire Protect Life Safety Code, Coccupancies. The facility is a three 1964 building and the additions was determated to construction and the Department addition (222). The facility is exception of the wall has a monitored fired detection in the correction of the wall has a monitored fired detection in the correction of the wall has a monitored fired detection in the correction of the wall has a monitored fired detection in the corrections of 18 on 05/25/25/21. Quality Review com NFPA 101 Horizontal Sliding Horizontal-Sliding Horizontal-Sliding Horizontal-sliding of that are not autom single leaf and shame chanism to ensingle leaf and shame chanism to	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION Medicare/Medicaid, 42 CFR Subpart 482.41(b), Life Safety from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code, Chapter 19 Existing Health Care occupancies. The facility is a three-story building. The original 1964 building and the 1976, 1992, 2001, 2014 additions was determined to be Type I (332) construction and the 2008 and 2011 Emergency Department addition was determined to be Type I (222). The facility is fully sprinklered, with exception of the walk-in cooler and freezer, and has a monitored fire alarm system with smoke detection in the corridors and spaces open to the corridors and in the operating rooms. The facility is protected with a Type 1 EES by three generators. The facility has a capacity of 56 with a census of 18 on 05/24/21 and a census of 22 on 05/25/21. Quality Review completed on 05/27/21 NFPA 101 Horizontal-Sliding Doors Horizontal-Sliding Doors Horizontal-Sliding Doors Horizontal-sliding doors permitted by 7.2.1.14 that are not automatic-closing are limited to a single leaf and shall have a latch or other mechanism to ensure the door will not rebound. Horizontal-sliding doors serving an occupant load fewer than 10 shall be permitted, providing all of the following criteria are met: o Area served by the door has no high hazard contents. o Door is operable from either side without special knowledge or effort.	STRETAIL SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION Medicare/Medicaid, 42 CFR Subpart 482.41(b), Life Safety from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code, Chapter 19 Existing Health Care occupancies. The facility is a three-story building. The original 1964 building and the 1976, 1992, 2001, 2014 additions was determined to be Type I (332) construction and the 2008 and 2011 Emergency Department addition was determined to be Type I (222). The facility is fully sprinklered, with exception of the walk-in cooler and freezer, and has a monitored fire alarm system with smoke detection in the corridors and spaces open to the corridors and in the operating rooms. The facility is protected with a Type 1 EES by three generators. The facility has a capacity of 56 with a census of 18 on 05/24/21 and a census of 22 on 05/25/21. Quality Review completed on 05/27/21 NFPA 101 Horizontal-Sliding Doors Horizontal-Sliding doors permitted by 7.2.1.14 that are not automatic-closing are limited to a single leaf and shall have a latch or other mechanism to ensure the door will not rebound. Horizontal-sliding doors serving an occupant load fewer than 10 shall be permitted, providing all of the following criteria are met: O Area served by the door has no high hazard contents. O Door is operable from either side without special knowledge or effort. O Force required to operate the door in the	ROVIDER OR SUPPLIER EW DEKALB HOSPITAL SUMMARY STATEMENT OF DEFICIENCIE (RECHI DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION Medicare/Medicaid, 42 CFR Subpart 482.41(b), Life Safety from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety From Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code, Chapter 19 Existing Health Care occupancies. The facility is at three-story building. The original 1964 building and the 1976, 1992, 2001, 2014 additions was determined to be Type I (222). The facility is fully sprinklered, with exception of the walk-in cooler and freezer, and has a monitored fire alarm system with smoke detection in the corridors and spaces open to the corridors and in the operating rooms. The facility is protected with a Type I EES by three generators. The facility has a capacity of 56 with a census of 18 on 05/24/21 and a census of 22 on 05/25/21. Quality Review completed on 05/27/21 NFPA 101 Horizontal-Sliding Doors Horizontal-sliding doors permitted by 7.2.1.14 that are not automatic-closing are limited to a single leaf and shall have a latch or other mechanism to ensure the door will not rebound. Horizontal-sliding doors serving an occupant load fewer than 10 shall be permitted, providing all of the following criteria are met: O Area served by the door has no high hazard contents. O Door is operable from either side without special knowledge or effort. O Force required to operate the door in the	ROVIDER OR SUPPLIER EW DEKALB HOSPITAL SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INSPORMATION Medicare/Medicaid, 42 CFR Subpart 482.41(b), Life Safety from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code, Chapter 19 Existing Health Care occupancies. The facility is a three-story building. The original 1964 building and the 1976, 1992, 2001, 2014 additions was determined to be Type I (222). The facility is fully sprinklered, with exception of the walk-in-cooler and freezer, and has a monitored fire alarm system with smoke detection in the corridors and spaces open to the corridors and in the operating rooms. The facility is protected with a Type I EES by three generators. The facility has a capacity of 56 with a census of 18 on 05/24/21 and a census of 22 on 05/25/21. Quality Review completed on 05/27/21 NFPA 101 Horizontal Sliding Doors Horizontal-sliding doors permitted by 7.2.1.14 that are not automatic-closing are limited to a single leaf and shall have a latch or other mechanism to ensure the door will not rebound. Horizontal-sliding doors serving an occupant load fewer than 10 shall be permitted, providing all of the following criteria are met: O Area served by the door has no high hazard contents. Door is operable from either side without special knowledge or effort. O Force required to operate the door in the

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

3Z5N21

Facility ID: 005041

If continuation sheet

Page 2 of 14

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

	IT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 150045	ľ í	JILDING	ONSTRUCTION 01	(X3) DATE COMPL 05/25/	LETED
	PROVIDER OR SUPPLIEF			1316 E	ADDRESS, CITY, STATE, ZIP COD SEVENTH ST RN, IN 46706		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	ATE	(X5) COMPLETION DATE
	lbf to set the door equal to 15 lbf to or equal to 15 lbf to or required width. o Assembly is a where rated, is se automatic-closing 7.2.1.8, and install o Where required latch or other medium will not rebound. 19.2.2.2.10 Based on observation failed to ensure 5 or doors in ICU and the provided with mean LSC 19.3.6.3.5 states a means for keeping acceptable to the aux LSC 19.2.2.2.10.1 states a permitted by 7.2 automatic-closing stands shall have a latter ensures that the door partially open position deficient practice construction. Findings include: Based on observation with the Vice President Manager, and the States and 6 in ICU and Department were produced to the doors. The doors with the doors with the steed the doors.	in motion and less than or close or open to the ppropriately fire rated, and lf-closing or by smoke detection per led per NFPA 80. ed to latch, the door has a chanism to ensure the door on and interview, the facility ff 15 horizontal-sliding room are Emergency Department were as for keeping the door closed. ed doors shall be provided with g the door closed that is athority having jurisdiction. states horizontal-sliding doors,	K 0	224	1. How are you, the provider, going to correct the finding and/or deficiency? If already corrected, include the following steps and state date of correction. a. The door latch for Roce 9 in the emergency departments. b. Memo to mangers of each departments with the finding steps and state does not be a considered and the finding and for deficiency from the future, even already corrected? a. To prevent this from the future, we will ensure that door latches are checked during the future for the finding and for deficiency from the future, we will ensure that door latches are checked during the future for the finding and for deficiency from the future, we will ensure that door latches are checked during the future for the finding staff to create work orders when issues within their	ne te om ent 1, 2,	06/03/2021
	door latches will ne	ed to be repaired.			department are identified.		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

3Z5N21

Facility ID: 005041

If continuation sheet Page 3 of 14

PRINTED: 07/28/2021 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 150045		(X2) MULTIPLE CO A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 05/25/2021			
	ROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 1316 E SEVENTH ST AUBURN, IN 46706				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	DATE		
	_	riewed with the Vice President cilities Manager, and the Safety the exit conference.		3. Who is going to be responsible for numbers and 2 above, i.e. administrat director of nursing, head housekeeper, dietary supervisor, maintenance supervisor, etc.? a. Environment of Care Team will be responsible for identifying issues with door latches during rounding in department biannually. b. Facilities Manager or designee(s) will be responsifor fixing future identified issues with latches. c. Unit manager or designee will be responsible for as needed work orders being placed when issues w latches identified. 4. By what date anyou the provider going to hat the finding and/or deficiency corrected? a. The room 9 ER door was fixed as of 6/2/2021 and the CCU door latches were fixed on 6/3/2021.	1 or, ble ith re ve		
K 0232 Bldg. 01	NFPA 101 Aisle, Corridor, or Aisle, Corridor or I	•					
	unobstructed) servat least 4 feet and						

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

3Z5N21

Facility ID: 005041

If continuation sheet

Page 4 of 14

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 150045		r í	ILDING	onstruction <u>01</u>	(X3) DATE SURVEY COMPLETED 05/25/2021	
	PROVIDER OR SUPPLIER			1316 E	ADDRESS, CITY, STATE, ZIP COD SEVENTH ST RN, IN 46706	
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OF	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	(X5) COMPLETION DATE
	the clear width requester corridors or met an 19.2.3.4(5) states we least 8 feet, projection shall be permitted for all of the following (a) the fixed furniture floor or to the wall. (b) the fixed furniture the corridor of the corridor. (d) the fixed furniture floor or to the wall. (e) the fixed furniture from the corridor. (d) the fixed furniture from the corridor. (d) the fixed furniture floor flo	re is securely attached to the re does not reduce the clear or width to less than six feet, by 19.2.3.4(2). re is located only on one side re is grouped such that each exceed an area of 50 square re groupings addressed in reparated from each other by a 10 feet. re is located so as to not uilding service and fire nt. hout the smoke compartment relectrically supervised rection system in accordance fixed furniture spaces are d to allow direct supervision from a nurse's station or similar reartment is protected reproved, supervised automatic accordance with 19.3.5.8 re could affect 20 patients in	K 02	232	1. How are you, the provider, going to correct the finding and/or deficiency? already corrected, include the following steps and state do of correction. a. The furniture was removed for the OB Outpate //Cardiac Rehab exit hallway 5/27/2021. 2. How are you, the provider, going to prevent the finding and/or deficiency for recurring in the future, ever already corrected? a. Furniture will not be reinstalled in this hallway unless it meets the guideling as stated in LSC 19.2.3.4(5). 3. Who is going to be responsible for numbers 1 and 2 above? a. Facilities manager will be responsible for ensuring that if furniture is installed in will meet the LSC 19.2.3.4(5) guidelines. 4. By what date are you, the provider, going to have finding or deficiency corrected? a. This deficiency was corrected on 05/27/2021.	If the the ate ient y on the om n if and II dit iit

PRINTED: 07/28/2021 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER 150045		ľ	ILDING	01	COMPL 05/25/	ETED	
	PROVIDER OR SUPPLIER			1316 E S	.ddress, city, state, zip cod SEVENTH ST N, IN 46706		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA* DEFICIENCY)	ΓE	(X5) COMPLETION DATE
	Manager, and the Sa at 1:20 p.m., chairs OB/Rehab outpatier two feet into the corthe floor or to the winterview at the time Facilities Manager a were not securely at wall when tested.	lent of Facilities, the Facilities afety Coordinator on 05/25/21 and a bench were in the at exit corridor, extended about rridor, and were not affixed to all when tested. Based on e of the observations, the agreed the chairs and bench trached to the floor or to the					
	_	cilities Manager, and the Safety					
K 0321	NFPA 101 Hazardous Areas	Enclosure					
Bldg. 01	Hazardous Areas Hazardous areas a barrier having 1-ho (with 3/4 hour fire automatic fire extir accordance with 8 approved automat option is used, the from other spaces partitions and door Doors shall be self automatic-closing nonrated or field-a do not exceed 48 the door.	are protected by a fire our fire resistance rating rated doors) or an anguishing system in 1.7.1 or 19.3.5.9. When the ic fire extinguishing system areas shall be separated by smoke resisting rs in accordance with 8.4. If-closing or and permitted to have applied protective plates that inches from the bottom of					
	Area Separation a. Boiler and Fuel-	Automatic Sprinkler N/A -Fired Heater Rooms					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

3Z5N21

Facility ID: 005041

If continuation sheet

Page 6 of 14

STATEMEN	STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION (X3) D			(X3) DATE	SURVEY
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	JILDING	01	COMPL	ETED
		150045	B. WING 05/25/2021			2021	
NAME OF P	ROVIDER OR SUPPLIER	t			ADDRESS, CITY, STATE, ZIP COD		
D 4 D 1 0 /1 E					SEVENTH ST		
PARKVIEW DEKALB HOSPITAL				AUBUR	RN, IN 46706		
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE			ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	тс	COMPLETION
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	b. Laundries (large	er than 100 square feet)					
	, -	nance, and Paint Shops					
	d. Soiled Linen Ro	ooms (exceeding 64					
	gallons)	,					
	e. Trash Collection	n Rooms					
	(exceeding 64 gal	lons)					
	, , ,	orage Rooms/Spaces					
	(over 50 square fe	-					
	•	classified as Severe					
	Hazard - see K32	2)					
	Based on observation	on and interview, the facility	K 0	321			06/02/2021
	failed to ensure 1 of	f 1 walk-in clinic janitor closets			1. How are you, the		
	containing trash and	d soiled linens was protected			provider, going to correct the	е	
	as a hazardous area	. This deficient practice could			finding and/or deficiency? If	•	
	affect 10 patients in	the walk-in clinic.			already corrected, include th	е	
					following steps and state dat	te	
	Findings include:				of correction.		
					a. Facilities installed an		
		on during a tour of the facility			automatic closure on the do	or	
		dent of Facilities, the Facilities			in question on 6/2/2021		
	-	afety Coordinator on 05/25/21			2. How are you, the		
	_	lk-in clinic janitor closet			provider, going to prevent th	e	
	~	rash and soiled linens. The			finding and/or deficiency from	m	
	•	ected as a hazardous area			recurring in the future, even	if	
		r door to the closet was not			already corrected.		
	_	matic closing. Based on			a. Now that the automation		
		e of observation, the Facilities			closure is in place this will n	ot	
		janitor closet contained			recur.		
		ash, and the corridor door to			3. Who is going to be		
	the room was not se	elf-closing.			responsible for 1 & 2 above?	•	
	TE1 (* 1'	1 14 4 17 5 11 .			a. Facilities manager		
	•	viewed with the Vice President			4. By what date are you,	_	
		cilities Manager, and the Safety			the provider, going to have t	ne	
	Coordinator during	the exit conference.			finding and/or deficiency		
					corrected?		
					a. The automatic closure		
					was installed on the door in	uie	
					Walk-in-Clinic on 6/2/2021.		

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: 3Z5N21 Facility ID: 005041 If continuation sheet Page 7 of 14

, in the second		XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 150045	(X2) MULTIPLE CONSTRUCTION A. BUILDING D1 B. WING			(X3) DATE SURVEY COMPLETED 05/25/2021	
	PROVIDER OR SUPPLIER			STREET A 1316 E S AUBUR			
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	PR	ID REFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	ιΤΕ	(X5) COMPLETION DATE
K 0351 Bldg. 01	by construction ty throughout by an a sprinkler system in 13, Standard for the Systems. In Type I and II constituted for sprinklers. In hospitals, sprinklers. In hospitals, sprinklers. In hospitals, sprinklers. In hospitals, sprinklers clothes closets of where the area of 6 square feet and the closet footprin Standard for Instandard for the Instandard for the Instandard for the Instandard for the Instandard for Instandard	Installation Ind hospitals where required be, are protected approved automatic accordance with NFPA he Installation of Sprinkler Instruction, alternative es are permitted to be inkler protection in specific or local regulations prohibit alternative sters are not required in patient sleeping rooms the closet does not exceed sprinkler coverage covers as required by NFPA 13, and interview, the facility aplete automatic sprinkler	K 035	51	1. How are you, the provider, going to correct the finding and/or deficiency? If already corrected, include the following steps and state date of correction. a. New sprinklers will be installed in the walk-in-freeze and walk-in-cooler by a Fire Systems Company contracted by the hospital. 2. How are you, the provider, going to prevent the finding and/or deficiency froe recurring in the future, even already corrected.	f ne er ed m	08/24/2021

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

3Z5N21

Facility ID: 005041

If continuation sheet

Page 8 of 14

	NT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 150045	(X2) MULTIPLE C A. BUILDING B. WING	onstruction <u>01</u>	COM	TE SURVEY PLETED 25/2021
	PROVIDER OR SUPPLIER		1316 E	ADDRESS, CITY, STATE, ZIP (E SEVENTH ST RN, IN 46706	COD	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF COI (EACH CORRECTIVE ACTION S CROSS-REFERENCED TO THE DEFICIENCY)	RRECTION SHOULD BE APPROPRIATE	(X5) COMPLETION DATE
	coverage. Based on the Facilities Mana, and freezer were no The finding was rev of Facilities, the Fac	not provided with sprinkler interview during observation, ger agreed the walk-in cooler t provided with sprinklers. Viewed with the Vice President cilities Manager, and the Safety the exit conference.		a. Once installed, sprinkler systems in areas will be compliathis will not recur. 3. Who is going to responsible for number above? a. Facilities mana 4. By what date athe provider, going to finding and/or deficiencorrected? a. Received quote Fire Systems comparate, 2021 for the sprink installation in both the walk-in-refrigerator in dietary department. b. Working with contour schedule installation date by A 24th, 2021.	these ant and be bers 1 & 2 ger re you, be have the ency e from the ny on June cler ne n the ontractor on with	
K 0353 Bldg. 01	Sprinkler System Automatic sprinkle are inspected, tes accordance with N Inspection, Testin Water-based Fire Records of system inspection and tes secure location ar	<u> </u>				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING			(X3) DATE SURVEY COMPLETED 05/25/2021	
		150045	B. WI	NG		05/25/	2021
NAME OF I	PROVIDER OR SUPPLIEF				ADDRESS, CITY, STATE, ZIP COD		
PARKVIE	EW DEKALB HOSP	PITAL			SEVENTH ST N, IN 46706		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	`	ICY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	ATE	COMPLETION
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	coverage for any automatic sprinkle 9.7.5, 9.7.7, 9.7.8 1. Based on record facility failed to ma accordance with 19 14.2.1 states except 14.2.1.4 an inspectic conditions shall be opening a flushing main and by remove of one branch line if for the presence of material. This defice occupants. Findings include: Based on records record facilities, the Facilities, the Facilities, the Facilities, the Facoordinator on 05/2 no documentation to internal pipe inspection paper system, of due. Based on interreview, the Facilities when the last interreconducted and coul inspection paperword. 2. Based on observative failed to maintain the sprinkle operate at a specific edition, 8.5.4.11 states prinkler deflector as sprinkler deflector as sprinkler deflector and could be sprinkler deflector as sprinkler deflector.	, and NFPA 25 review and interview, the sintain 1 of 1 sprinkler system in .3.5.3. NFPA 25, 2011 Edition, as discussed in 14.2.1.1 and on of piping and branch line conducted every 5 years by connection at the end of one ing a sprinkler toward the end for the purpose of inspecting foreign organic and inorganic tient practice could affect all eview with the Vice President cilities Manager, and the Safety 24/21 at 10:34 a.m., there was o show when the last time an action was conducted on the r when the next inspection was view at the time of record as Manager did not know if or hal pipe inspection was d not find internal pipe	K 02	353	1. How are you, the provider, going to correct th finding and/or deficiency? It already corrected, include th following steps and state da of correction. a. The internal sprinkler system pipe inspection will I conducted by the Fire System Company contracted by the hospital. 2. How are you, the provider, going to prevent the finding and/or deficiency from recurring in the future, even already corrected? a. This service will be performed every 5 years in accordance with 19.3.5.3. NF 25, 2011 Edition, 14.2.1, by a Fire Systems Company contracted by the hospital. 3. Who is going to be responsible for numbers 1 & a. Facilities manager will be responsible for scheduling contracted service with the foundation of the fire Systems. 4. By what date are you to provider going to have the finding and/or deficiency corrected? a. A quote was obtained from the Fire Systems.	fine te te be ms if FPA	08/24/2021

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY			URVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. B	A. BUILDING <u>01</u> COMPLETED			ETED
		150045	B. W	B. WING 05/25/2021			2021
				CTREET	ADDRESS, CITY, STATE, ZIP COD		
NAME OF P	ROVIDER OR SUPPLIER				SEVENTH ST		
	EW DEKALB HOSP	ITAI					
PARKVIE	W DENALD HOSP	ITAL		AUBUR	N, IN 46706		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE.	COMPLETION
TAG	REGULATORY OR LSC IDENTIFYING INFORMATION			TAG	DEFICIENCY)	DATE	
	type of construction	. This deficient practice			Company on May 26, 2021 fo	r	
	could affect 5 patier	nts in suite five.			the internal sprinkler pipe		
	Findings include:				inspection.		
					b. The internal sprinkler		
					system pipe inspection will b	эе	
	Based on observation during a tour of the facility				scheduled with completion b	y	
	with the Vice President of Facilities, the Facilities				August 24, 2021.		
	-	afety Coordinator on 05/25/21					
	-	spended ceiling in the suite five					
		eiling tiles missing. This					
	condition could delay the activation of the sprinklers installed on the suspended ceiling.						
	Based on interview						
		icilities Manager stated the					
	-	not replace the tiles after					
	completing work.						
	TELL OF 1						
	-	eviewed with the Vice					
		es, the Facilities Manager, and					
	the Safety Coordina	tor during the exit conference.					
K 0920	NFPA 101						
1 0320	_	ent - Power Cords and					
Bldg. 01	Extens	ent - Fower Cords and					
Diag. 01		ent - Power Cords and					
	Extension Cords	Sit I owel colds allu					
		patient care vicinity are only					
	used for compone	-					
	-	ed electrical equipment					
	-	les that have been					
	, ,	ilified personnel and meet					
	• •	0.2.3.6. Power strips in					
		cinity may not be used for					
	-	personal electronics),					
	, -	n care resident rooms that					
	do not use PCRE	E. Power strips for PCREE					
	meet UL 1363A or	UL 60601-1. Power strips					
	for non-PCREE in	the patient care rooms					
	(outside of vicinity) meet UL 1363. In					
	non-patient care re	ooms, power strips meet					
			1				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

3Z5N21

Facility ID: 005041

If continuation sheet

Page 11 of 14

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER	_ 		COMPL		
150045		B. WING 05/			05/25/	/2021	
NAME OF PROVIDER OR SUPPLIER PARKVIEW DEKALB HOSPITAL			STREET ADDRESS, CITY, STATE, ZIP COD 1316 E SEVENTH ST AUBURN, IN 46706				
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE		ID		PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION		PREFIX TAG		(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG					DEFICIENCY)		DATE
	used with general cords are not used wiring of a structu temporarily are re completion of the installed and mee 10.2.3.6 (NFPA 99 (NFPA 70), 590.3 Based on observation failed to ensure 4 of as a substitute for five equipment with a hink NFPA-70/2011, 400 permitted in 400.7 into the used for (1) and the	20.8 state unless specifically flexible cords and cables shall as a substitute for fixed wiring. ice could affect staff and the building on during a tour of the facility dent of Facilities, the Facilities afety Coordinator on 05/25/21 and 2:00 p.m., refrigerators, offeepots which are high power are plugged into and supplied trips in several staff offices management office and in the sed on interview at the time of cilities Manager acknowledged upplying power to high power	K 0	920	1. How are you, the provider, going to correct the finding and/or deficiency fro recurring in the future, even already corrected? a. Ceiling tiles identified missing in Suite 5, IT room were replaced on 5/27/2021 2. How are you, the provider, going to prevent the finding and/or deficiency fro recurring in the future, even already corrected. a. Contractors will be educated about the important of making sure all ceiling tiles are replaced when they are finished with a job. b. Ceiling tiles will be observed during Environment of Care (EOC) rounds Biannually and as needed. 3. Who is going to be responsible for numbers 1 & above? a. Facilities Manager b. EOC rounding team 4. By what date are you, the provider going to have the finding and/or deficiency corrected?	m if as as ae m if nce as	05/27/2021

PRINTED: 07/28/2021 FORM APPROVED OMB NO. 0938-039

	OF CORRECTION	IDENTIFICATION NUMBER 150045	A. BUILDING B. WING	01	COM	PLETED 25/2021
	ROVIDER OR SUPPLIEF		1316 E	ADDRESS, CITY, STATE, ZIP CO SEVENTH ST RN, IN 46706	D	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)			(X5) COMPLETION DATE
				a. This was corrected 5/27/2021. Response 1. How are you, the provider going to correfinding and/or deficient already corrected, included following steps and date correction. a. All power strips identified during the LS were immediately remore from use on 5/25/2021. 2. How are you, the provider, going to previnding and/or deficient recurring in the future, already corrected? a. Education to state what devices can be plinto power strips and we needs to be plug direct outlet. b. Will observe for improper use of power when conducting Environ for Care rounds in all arms. Who is going to be responsible for number above? a. Safety Officer will out education to all state proper use of power state. EOC team will be responsible for conduction observations during road. By what date are the provider, going to be finding and/or deficient corrected?	ect the cy? If ude the te of S survey oved The survey o	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

3Z5N21

Facility ID: 005041

If continuation sheet

Page 13 of 14

PRINTED: 07/28/2021 FORM APPROVED OMB NO. 0938-039

STATEMEN	ATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE C	ONSTRUCTION	(X3) DATE SURVEY	
AND PLAN	AND PLAN OF CORRECTION IDENTIFICATION NUMBER A.		A. BUILDING	01	COMPLETED	
150045		B. WING		05/25/2021		
NAME OF PROVIDER OR SUPPLIER PARKVIEW DEKALB HOSPITAL			STREET ADDRESS, CITY, STATE, ZIP COD 1316 E SEVENTH ST AUBURN, IN 46706			
(X4) ID	SUMMARY S	STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CORRECTION	(X5)	
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	COMPLETION	
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION	TAG	DEFICIENCY)	DATE	
				a. Power strips were removed on 5/25/2021. b. Education of staff will completed by 6/24/2021.	be	

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: 3Z5N21 Facility ID: 005041 If continuation sheet Page 14 of 14