CENTERS FOR MEDICARE & MEDICA	AID SERVICES			OMB NO. 0938-039	
STATEMENT OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE C	ONSTRUCTION	(X3) DATE SURVEY	
AND PLAN OF CORRECTION IDENTIFICATION NUMBER		A. BUILDING	<u></u>	COMPLETED	
	155510	B. WING		08/23/2023	
NAME OF PROVIDER OR SUPPLIER CENTURY VILLA HEALTH O		705 N	ADDRESS, CITY, STATE, ZIP COD MERIDIAN ST NTOWN, IN 46936		
(X4) ID SUMMARY S	STATEMENT OF DEFICIENCIE	ID	T	(X5)	
	CY MUST BE PRECEDED BY FULL	PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE	COMPLETION	
, i	LSC IDENTIFYING INFORMATION	TAG	CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	DATE	
conducted by the Inaccordance with 42  Survey Date: 08/23  Facility Number: 00  Provider Number: 1  AIM Number: 1002  At this Emergency I  Villa Health Care w  Emergency Prepared  Medicare and Medicand Suppliers, 42 C.	20549 55510 267470 Preparedness survey, Century as found in compliance with dness Requirements for caid Participating Providers FR 483.73. The facility has a laid a census of 60 at the time	E 0000	Deficiency ID: E and K_0000 Completion Date 9/11/23 12:0 AM  Plan of Correction Text:  Allegation of Compliance  Please accept the following please correction for the Life Safety survey completed on August 2023.  Preparation and/or execution this plan of correction does not constitute admission or agree by the provider of the truth fact alleged or conclusion set forth the statement of deficiencies. plan of correction is prepared and/or executed solely because is required by the provision of federal and state laws. This fact appreciated the time and dedication of the surveyor; the facility will accept the survey at tool for our facility to use in continuing to better the quality care provided to the residents our community.  We respectfully request consideration for a desk review	of ot ment ots in This se it is the acility eas a y of s in	

Michael Gerig ED 09/14/2023

TITLE

(X6) DATE

Any defiency statement ending with an asterisk (\*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: 0K9S21 Facility ID: 000549 If continuation sheet Page 1 of 10

PRINTED: 09/21/2023 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTIFICATION NUMBER  155510		A. BUILDING B. WING	onstruction 	COMPLETED 08/23/2023		
NAME OF PROVIDER OR SUPPLIER  CENTURY VILLA HEALTH CARE		STREET ADDRESS, CITY, STATE, ZIP COD 705 N MERIDIAN ST GREENTOWN, IN 46936				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE	
K 0000				and paper compliance.		
Bldg. 01	Licensure Survey w	Recertification and State as conducted by the Indiana th in accordance with 42 CFR	K 0000	Deficiency ID: E and K_0000 Completion Date 9/11/23 12:0 AM	0:00	
	Survey Date: 08/23	/2023		Plan of Correction Text:		
	Facility Number: 0 Provider Number: 1 AIM Number: 1002	55510		Allegation of Compliance		
	Health Care was for Requirements for Pa Medicare/Medicaid Life Safety from Fire	Code survey, Century Villa and not in compliance with articipation in 42 CFR Subpart 483.90(a), re and the 2012 edition of the ction Association (NFPA) 101,		Please accept the following pl correction for the Life Safety survey completed on August , 2023.		
		SC), Chapter 19, Existing ancies and 410 IAC 16.2.		Preparation and/or execution this plan of correction does no constitute admission or agree	ot	
	Type V111 construction The facility has a find the correction in the correction and smokes sleeping rooms. The	ty was determined to be of etion and was fully sprinklered. The alarm system with smoke ridors, areas open to the detection in the resident defacility has a capacity of 84 at the time of this survey.		by the provider of the truth factories alleged or conclusion set forth the statement of deficiencies. plan of correction is prepared and/or executed solely because is required by the provision of federal and state laws. This factories appreciated the time and	ets in This se it the	
		residents have customary ered. All areas providing re sprinklered.		dedication of the surveyor; the facility will accept the survey a tool for our facility to use in		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

0K9S21

Facility ID: 000549

If continuation sheet

Page 2 of 10

PRINTED: 09/21/2023 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTIFICATION NUMBER  155510		A. BUILDING <u>01</u>		COMPLETED  08/23/2023	
	PROVIDER OR SUPPLIER		705 N N	ADDRESS, CITY, STATE, ZIP COD MERIDIAN ST NTOWN, IN 46936	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	DATE
	Quality Review con	npleted on 08/31/23		continuing to better the quality care provided to the residents our community.  We respectfully request consideration for a desk review and paper compliance.	in
K 0222 SS=E Bldg. 01	be equipped with a requires the use of egress side unless special locking arr. CLINICAL NEEDS LOCKING Where special lock clinical security neused, only one loc permitted on each be made for the raby: remote control locks or keys carriother such reliable staff at all times. 18.2.2.2.5.1, 18.2. 19.2.2.2.6 SPECIAL NEEDS ARRANGEMENTS Where special lock safety needs of the the Clinical or Secare being met. In a	con SECURITY THREAT  rangements for the eds of the patient are king device shall be door and provisions shall pid removal of occupants of locks; keying of all ed by staff at all times; or means available to the 2.2.6, 19.2.2.2.5.1,			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

0K9S21

Facility ID: 000549

If continuation sheet

Page 3 of 10

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA	r í	(X2) MULTIPLE CONSTRUCTION  A. BUILDING  01		(X3) DATE SURVEY COMPLETED	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER 155510	A. BU B. W		<u>01</u>	08/23	
		.55010	D. W.	_	ADDRESS SITE OF THE SITE OF	00/20/	
NAME OF I	PROVIDER OR SUPPLIEF	2			ADDRESS, CITY, STATE, ZIP COD MERIDIAN ST		
CENTUR	RY VILLA HEALTH (	CARE			NTOWN, IN 46936		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	`	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG		R LSC IDENTIFYING INFORMATION	-	TAG	DEFICIENCY)		DATE
		of power to the device; the					
		ed by a supervised					
		er system and the locked					
		d by a complete smoke					
		or is constantly monitored cation within the locked					
		the sprinkler and detection					
		iged to unlock the doors					
	upon activation.	igod to dillock the doors					
	18.2.2.2.5.2, 19.2	2.2.5.2. TIA 12-4					
	DELAYED-EGRE						
	ARRANGEMENT						
		- lelayed-egress locking					
		in accordance with					
	7.2.1.6.1 shall be						
		g low and ordinary hazard					
		igs protected throughout by					
	an approved, sup	ervised automatic fire					
	detection system	or an approved, supervised					
	automatic sprinkle	er system.					
	18.2.2.2.4, 19.2.2	.2.4					
	ACCESS-CONTR	OLLED EGRESS					
	LOCKING ARRAI						
		d Egress Door assemblies					
		lance with 7.2.1.6.2 shall					
	be permitted.						
	18.2.2.2.4, 19.2.2						
		BY EXIT ACCESS					
	LOCKING ARRAN						
		t access door locking in					
		7.2.1.6.3 shall be permitted					
		es in buildings protected					
		approved, supervised					
		ection system and an ised automatic sprinkler					
	system.	sed automatic spilikiei					
	18.2.2.2.4, 19.2.2	2.4					
		on and interview, the facility	K O	222	K-222		09/11/2023
		means of egress through 1 of	K U	<i></i>	The corrective action that will t	take	09/11/2023
		facility were readily accessible			place for egress on main door		

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155510		(X2) MULTIPLE C A. BUILDING B. WING	onstruction <u>01</u>	(X3) DATE SURVEY  COMPLETED  08/23/2023	
	ROVIDER OR SUPPLIER		705 N	ADDRESS, CITY, STATE, ZIP COD MERIDIAN ST NTOWN, IN 46936	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
	for residents withou specialized security required means of e	t a clinical diagnosis requiring measures. Doors within a gress shall not be equipped that requires the use of a tool		be the display of the 4-digit co for those that need to use it to come and go, and in emerger	•
	permitted by LSC 1 arrangements shall	ess side unless otherwise 9.2.2.2.4. Door-locking be permitted in accordance This deficient practice could		There could be up to 20 peop affected by of correct display notification.	le
	affect 20 residents.  Findings include:			The display of the 4-digit code be put in a visible area by electronic exit pad.	e will
	Director on 08/23/2 the Main Entrance vand could be opened	on with the Maintenance 3 at 1:20 p.m., the exit door at was marked as a facility exit d by entering a four-digit code		This will be inspected weekly the 4-digit code is on display a recorded by maintenance state	and f.
	posted at the exit. B of observation, the l the code to open the the access control p dementia residents i	ol pad, but the code was not assed on interview at the time Maintenance Director stated exit door was not posted on ad because the facility has mixed in with residents without lid not want to risk an		This will be implemented by S 11,2023 and checked weekly moving forward.	ept
	_	viewed with the Administrator irector during the exit			
	3.1-19(b)				
K 0355 SS=E Bldg. 01	installed, inspecte accordance with N Portable Fire Extir 18.3.5.12, 19.3.5.	nguishers guishers are selected, d, and maintained in IFPA 10, Standard for nguishers.	K 0355	K-355 Portable Fire Extinguis	her 09/11/2023

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA  AND PLAN OF CORRECTION IDENTIFICATION NUMBER  155510		(X2) MULTIPLE CO A. BUILDING B. WING	onstruction <u>01</u>	(X3) DATE SURVEY  COMPLETED  08/23/2023	
	PROVIDER OR SUPPLIER		705 N	ADDRESS, CITY, STATE, ZIP COD MERIDIAN ST NTOWN, IN 46936	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
1.70	failed to inspect 4 of each month. NFPA Extinguishers, Sective extinguishers shall by means of an electron minimum of 30-day periodic inspection extinguishers shall in following items:  (1) Location in desi (2) No obstruction to (3) Pressure gauge to operable range or periodic inspection of the cartridge-operated (5) Condition of tirce in ozzle for wheeled (6) Indicator for not using push to-test periodic inspections shall ke extinguishers inspections shall ke extinguishers inspection of the conducted, the date performed and the inperforming the inspection of 7.2.4.4 requare conducted, reconshall be kept on a talextinguisher, on an maintained on file, Section 7.2.4.5 requirements in the cartridge of the conducted of the conducted on file, Section 7.2.4.5 requirements that at	f 20 portable fire extinguishers 10, Standard for Portable Fire ion 7.2.1.2 states fire be inspected either manually or tronic device / system at a r intervals. Section 7.2.2 states or electronic monitoring of fire include a check of at least the  gnated place o access or visibility reading or indicator in the osition ined by weighing or hefting for extinguishers, and pump tanks es, wheels, carriage, hose, and extinguishers rescure indicators. es personnel making manual eep records of all fire oted, including those found to etion. Section 7.2.4.3 requires hly manual inspections are the manual inspections are the manual inspections are the manual inspections of the person ection shall be recorded. hires where manual inspections of or label attached to the fire inspection checklist or by an electronic method. hires records shall be kept to least the last 12 monthly en performed. This deficient		Check Monthly The monthly check for Fire Extinguishers can affect up to people in the facility.  Other residents could be affer if this isn't done correctly on a monthly basis.  The extinguisher tag audit will and a spreadsheet will be add for quick doublecheck of duty Maintenance Director.  This added audit sheet will be checked at the first of every n by Director to that all extinguichecks are done on time and notated accurately.  Compliance date 9-11-23	ted  be ded by

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

0K9S21

Facility ID: 000549

If continuation sheet

Page 6 of 10

PRINTED: 09/21/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155510		,	ILDING	nstruction  01	(X3) DATE : COMPL 08/23/	ETED	
	PROVIDER OR SUPPLIER			705 N N	DDRESS, CITY, STATE, ZIP COD IERIDIAN ST TOWN, IN 46936		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	:	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	ΓE	(X5) COMPLETION DATE
K 0363 SS=E Bldg. 01	with the Maintenand between 01:20 p.m. inspection tag on the located in the maint documentation of a 2023 and one had be and December of 20 thereafter. The fire of lacked documentation July 2023 and the fixitchen lacked documentation inspection for June interview at the time confirmed the fire exercising month.  These findings were Administrator and Mainistrator and Mainistrato	orridor openings in other osures of vertical openings, areas resist the passage made of 1 3/4 inch wood or other material g fire for at least 20 fully sprinklered smoke only required to resist the . Corridor doors and doors g flammable or itals have positive latching atches are prohibited by hese requirements do not spaces that do not contain					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

0K9S21

Facility ID: 000549

If continuation sheet

Page 7 of 10

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE O	CONSTRUCTION	(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BUILDING	01	COMPLETED	
155510		B. WING	B. WING 08/23			
NAME OF I	PROVIDER OR SUPPLIER	2	STREET	ADDRESS, CITY, STATE, ZIP COD		
				MERIDIAN ST		
CENTUR	RY VILLA HEALTH (	CARE	GREE	NTOWN, IN 46936		
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION	(X5)	
PREFIX	`	ICY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		
TAG		R LSC IDENTIFYING INFORMATION	TAG	DEFICIENCE	DATE	
	_	en bottom of door and floor ceeding 1 inch. Powered				
		with 7.2.1.9 are permissible				
		device capable of keeping				
		then a force of 5 lbf is				
		no impediment to the				
		rs. Hold open devices that				
	_	door is pushed or pulled are				
	permitted. Nonrat	ed protective plates of				
	unlimited height a	re permitted. Dutch doors				
	1	6 are permitted. Door				
		beled and made of steel or				
		compliance with 8.3,				
	unless the smoke	•				
	1 -	I fire window assemblies are				
	•	n sprinklered compartments				
		ictions in area or fire				
	assemblies.	s or frames in window				
	assemblies.					
	19.3.6.3, 42 CFR	Parts 403, 418, 460, 482,				
	483, and 485					
	Show in REMARK	(S details of doors such as				
	fire protection rati	ngs, automatics closing				
	devices, etc.					
		on and interview, the facility	K 0363	K-363	09/11/2023	
		y hold open devices that		The deficiency to have door s	· ·	
		por is pushed or pulled was		on Community Room could at	fect	
		rridor doors. This deficient		the safety of 20 residents.		
	_	et 20 residents in the		Other residents and staff coul		
	Community room.			affected by having doorstop in	1	
	Findings include:			place for egress.  The door stop was removed a	and	
	i manigo metade.			there no longer is anything to	П	
	Based on observation	on with the Maintenance		impede the doors from swingi	na	
		23 at 02:00 p.m., the two corridor		freely at all times.		
		unity room were held open		The photos attached are proo	f that	
		op on the front of each door,		it is gone.		
	and the doors would	d not close by just pulling or		Compliance date 9-11-23.		
	pushing them. Based on interview at the time of			1		

0K9S21

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155510		(X2) MULTIPLE CO A. BUILDING B. WING	onstruction <u>01</u>	(X3) DATE SURVEY COMPLETED 08/23/2023	
	ROVIDER OR SUPPLIER		705 N I	ADDRESS, CITY, STATE, ZIP COD MERIDIAN ST NTOWN, IN 46936	
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OR	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT DEFICIENCY)	(X5) COMPLETION DATE
K 0511 SS=E Bldg. 01	kick stops were hole not close the doors first.  This finding was redicted by the conference.  3.1-19(b)  NFPA 101  Utilities - Gas and Equipment using a complies with NFF Code, electrical was complies with NFF Code. Existing inspection against electron against	Electric gas or related gas piping PA 54, National Fuel Gas iring and equipment PA 70, National Electric tallations can continue in to hazard to life. 9.1.1, 9.1.2 on and interview, the facility Fover 50 ground fault circuit were properly maintained for lectric shock. NFPA 70, NEC	K 0511	K-511 The deficiency to have 3 GFCI electrical receptacles fail to trip in 3 residents rooms. This could affect the 6 resident these 3 rooms and any staff working for and with said residents. The 3 GFCI's in question were replaced with hospital grade receptacles. Photographic evidence is inclu with this survey to prove this was completed. Compliance date 9-11-23.	es of

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

0K9S21

Facility ID: 000549

If continuation sheet

Page 9 of 10

PRINTED: 09/21/2023 FORM APPROVED OMB NO. 0938-039

	IT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155510	r í	ILDING	onstruction 01	(X3) DATE COMPL 08/23/	ETED
NAME OF PROVIDER OR SUPPLIER CENTURY VILLA HEALTH CARE			STREET ADDRESS, CITY, STATE, ZIP COD 705 N MERIDIAN ST GREENTOWN, IN 46936				
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE		COMPLETION
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	circuit. Based on in	terview at the time of					
	observation, the Ma	intenance Director agreed the					
	GFCI electric recep	tacles identified did not					
	properly work when	n tested.					
	These findings were						
	Administrator and t	he Maintenance Director					
	during the exit conf	erence.					
	3.1-19(b)						

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: 0K9S21 Facility ID: 000549 If continuation sheet Page 10 of 10