PRINTED: 08/15/2023

DEPARTMEN	T OF HEALTH AND HU	JMAN SERVICES				FOI	RM APPROVED	
	R MEDICARE & MEDIC						B NO. 0938-039	
	NT OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	l í		ONSTRUCTION	(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER		JILDING		COMPL		
		155379	B. Wl	NG _		07/25/2023		
NAME OF	PROVIDER OR SUPPLIE	R			ADDRESS, CITY, STATE, ZIP COD			
	DE 05NT5D 05 D	0.0115.0755		827 W 13TH ST				
LIFE CA	RE CENTER OF R	OCHESTER		ROCH	ESTER, IN 46975 			
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	(EACH DEFICIE)	NCY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	ATE	COMPLETION	
TAG	REGULATORY O	R LSC IDENTIFYING INFORMATION	TAG DEFICIENCY)			DATE		
E 0000								
Bldg								
Ü	An Emergency Pre	eparedness Survey was	E 00	000	This plan of correction is prep	ared		
	conducted by the I	ndiana Department of Health in			and executed because the			
	accordance with 42	•			provisions of state and federa	ıl law		
					require it and not because Life			
	Survey Date: 07/2	5/23			Care Center of Rochester agr			
				with the allegations and citati				
	Facility Number:	000325		listed. Life Care Center of				
	Provider Number:	155379			Rochester maintains that the			
	AIM Number: 100	0274300			alleged deficiencies do not			
					jeopardize the health and safe	ety of		
	At this Emergency	Preparedness survey, Life Care			the residents nor is it of such			
	Center of Rocheste	er was found not in compliance			character to limit our capabilit	ies		
	with Emergency P	reparedness Requirements for			to render adequate care. Plea	ase		
	Medicare and Med	licaid Participating Providers			accept this plan of correction	as		
	and Suppliers, 42 (CFR 483.73.			our credible allegation of			
					compliance that the alleged			
		1 certified beds. At the time of			deficiencies have or will be co	orrect		
	the survey, the cen	sus was 55.			by the date indicated to remain			
					compliance with state and fed			
	Quality Review co	impleted on 07/27/23			regulations, the facility has tal			
					or will take the actions set for	th in		
					this plan of correction. We			
					respectfully request paper			
					compliance.			
E 0039	403.748(d)(2). 41	6.54(d)(2), 418.113(d)(2),						
SS=F		32.15(d)(2), 483.475(d)(2),						
Bldg		I.102(d)(2), 485.625(d)(2),						

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

485.68(d)(2), 485.727(d)(2), 485.920(d)(2), 486.360(d)(2), 491.12(d)(2), 494.62(d)(2)

§416.54(d)(2), §418.113(d)(2), §441.184(d)(2), §460.84(d)(2), §482.15(d)(2), §483.73(d)(2), §483.475(d)(2), §484.102(d)(2), §485.68(d)(2), §485.625(d)(2), §485.727(d)(2), §485.920(d)

EP Testing Requirements

(2), §491.12(d)(2), §494.62(d)(2).

TITLE (X6) DATE

Executive Director 08/12/2023 Suzanne Wagner

Any defiencystatement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: 40J021 Facility ID: 000325 Page 1 of 31 If continuation sheet

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) M	ULTIPLE CC	ONSTRUCTION	(X3) DATE	SURVEY	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	JILDING	<u></u>	COMPLETED	
		155379	B. WI	ING		07/25	/2023
3143 m c=	DOLUBER OF STREET			STREET A	ADDRESS, CITY, STATE, ZIP COD	-	
NAME OF F	PROVIDER OR SUPPLIE	К		827 W	13TH ST		
LIFE CAF	RE CENTER OF R	OCHESTER		ROCHE	ESTER, IN 46975		
(X4) ID		STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	`	NCY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPR		COMPLETION
TAG		R LSC IDENTIFYING INFORMATION	+	TAG	DEFICIENCY)		DATE
	_	16.54, CORFs at §485.68,					
		ons" under §485.727,					
	_	920, RHCs/FQHCs at					
	₉ 491.12, and ESI 	RD Facilities at §494.62]:					
	(2) Testina. The f	facility] must conduct					
		the emergency plan					
		cility] must do all of the					
	following:	••					
	() D (:						
		full-scale exercise that is					
	· ·	l every 2 years; or					
	. ,	munity-based exercise is					
		onduct a facility-based					
		e every 2 years; or					
		ility] experiences an actual					
		ade emergency that requires					
		emergency plan, the [facility] ngaging in its next required					
	-	Igaging in its next required I or individual, facility-based					
	I -	e following the onset of the					
	actual event.	o lonowing the offset of the					
		Iditional exercise at least					
	1 ' '	posite the year the full-scale					
		cise under paragraph (d)(2)					
		is conducted, that may					
	1 ' '	limited to the following:					
		scale exercise that is					
	1 ' '	l or individual, facility-based					
	functional exercis						
	(B) A mock disast	ter drill; or					
	(C) A tabletop exe	ercise or workshop that is					
	led by a facilitator	and includes a group					
	discussion using						
	I -	emergency scenario, and a					
		atements, directed					
		pared questions designed					
	to challenge an e	- · ·					
		acility's] response to and					
	maintain docume	ntation of all drills, tabletop					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 2 of 31

	ENT OF DEFICIENCIES N OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155379	ì	UILDING	NSTRUCTION	COMP	E SURVEY PLETED 5/2023	
	PROVIDER OR SUPPLIE		STREET ADDRESS, CITY, STATE, ZIP COD 827 W 13TH ST ROCHESTER, IN 46975					
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD I CROSS-REFERENCED TO THE APPROP		(X5) COMPLETION DATE	
	exercises, and en	mergency events, and revise ergency plan, as needed.						
	the patient's homoconduct exercises plan at least annuithe following: (i) Participate in a community based (A) When a community based functional (B) If the hospice man-made emerged of the emergency exempt from engascale community-facility-based functional exercise of this section is of this section is of include, but is not (A) A second full community-based functional exercise (B) A mock disast (C) A tabletop exempt from engascale community-based functional exercise of this section is of include, but is not (A) A second full community-based functional exercise (B) A mock disast (C) A tabletop exempt for a facilitator discussion using clinically-relevant set of problem star messages, or preto challenge an exercise (3) Testing for ho	espices that provide care in e. The hospice must is to test the emergency cally. The hospice must do a full-scale exercise that is devery 2 years; or munity based exercise is not act an individual facility exercise every 2 years; or experiences a natural or gency that requires activation a plan, the hospital is aging in its next required full ebased exercise or individual ctional exercise following the regency event. In the difference of the full-scale or see under paragraph (d)(2)(i) conducted, that may to the following: -scale exercise that is do or a facility based se; or ster drill; or sercise or workshop that is a rand includes a group a narrated, a emergency scenario, and a stements, directed epared questions designed mergency plan.						
	, ,	e hospice must conduct						

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet Page 3 of 31

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION (X3			(X3) DATE S	(3) DATE SURVEY	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	JILDING		COMPL	ETED
		155379	B. W	ING		07/25/	2023
				STREET A	ADDRESS, CITY, STATE, ZIP COD		
NAME OF P	PROVIDER OR SUPPLIER				13TH ST		
LIFF CAF	RE CENTER OF RO	CHESTER			STER, IN 46975		
				L			
(X4) ID		STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	,	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	TE	COMPLETION
TAG		LSC IDENTIFYING INFORMATION	-	TAG	DEFICIENCY		DATE
		ne emergency plan twice					
		spice must do the following:					
	• • •	n annual full-scale exercise					
	that is community-						
	• •	unity-based exercise is not					
		ct an annual individual					
	facility-based func	experiences a natural or					
		ency that requires activation					
	-	plan, the hospice is					
		ging in its next required					
		ity based or facility-based					
		e following the onset of the					
	emergency event.	•					
		Iditional annual exercise					
	, ,	but is not limited to the					
	following:						
	•	scale exercise that is					
	community-based						
	functional exercise						
	(B) A mock disast						
	• •	ercise or workshop led by a					
	, ,	ıdes a group discussion					
	using a narrated, o	clinically-relevant					
	emergency scena	rio, and a set of problem					
	statements, direct	ed messages, or prepared					
	questions designe	d to challenge an					
	emergency plan.						
	(iii) Analyze the h	ospice's response to and					
	maintain documer	tation of all drills, tabletop					
		ergency events and revise					
	the hospice's eme	rgency plan, as needed.					
	_	41.184(d), Hospitals at					
	§482.15(d), CAHs	- , , -					
		PRTF, Hospital, CAH] must					
		to test the emergency					
		r. The [PRTF, Hospital,					
	CAH] must do the	following:					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet Page 4 of 31

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155379		(X2) MULTIPLE CO A. BUILDING B. WING	ONSTRUCTION	(X3) DATE SURVEY COMPLETED 07/25/2023	
NAME OF F	PROVIDER OR SUPPLIER	·		ADDRESS, CITY, STATE, ZIP COD	-
LIFE CAF	RE CENTER OF RO	OCHESTER		13TH ST ESTER, IN 46975	
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CORRECT	
PREFIX	`	CY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPR	OPRIATE
TAG		R LSC IDENTIFYING INFORMATION	TAG	DEFICIENCY)	DATE
		n annual full-scale exercise			
	that is community				
	' '	nunity-based exercise is not			
		ct an annual individual, ctional exercise; or			
		Hospital, CAH] experiences			
		or man-made emergency			
		ation of the emergency			
	-	is exempt from engaging in			
		ull-scale community based			
	-	ty-based functional exercise			
		et of the emergency event.			
	(ii) Conduct a	an [additional] annual			
	exercise or and th	at may include, but is not			
	limited to the follo	wing:			
	(A) A second full-	scale exercise that is			
	community-based	or individual, a			
	facility-based fund	tional exercise; or			
	, ,	ock disaster drill; or			
	, ,	exercise or workshop that			
		or and includes a group			
	discussion, using				
	1	emergency scenario, and a			
	set of problem sta				
		pared questions designed			
	to challenge an er				
	, ,	he [facility's] response to			
		umentation of all drills, s, and emergency events			
		cility's] emergency plan, as			
	needed.	Sinty of ciriorgency plant, as			
	*[For PACE at §46	60.84(d):]			
	(2) Testing. The P	ACE organization must			
	conduct exercises	to test the emergency			
	plan at least annu	ally. The PACE			
	organization must				
		an annual full-scale exercise			
	that is community	-based; or			
	(A) When a comm	nunity-based exercise is not			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 5 of 31

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA						SURVEY	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER		JILDING		COMPL	
		155379	B. W.	ING		07/25	/2023
NAME OF F	DDOMDED OF GIRDI ICI	•		STREET A	ADDRESS, CITY, STATE, ZIP COD		
NAME OF I	PROVIDER OR SUPPLIEF				13TH ST		
LIFE CAI	RE CENTER OF RO	OCHESTER		ROCHE	STER, IN 46975		
(X4) ID		STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	`	ICY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG		R LSC IDENTIFYING INFORMATION	_	TAG	DEFICIENCY)		DATE
		ıct an annual individual,					
	-	ctional exercise; or					
	' '	xperiences an actual natural					
		ergency that requires					
		mergency plan, the PACE					
		gaging in its next required					
		nity based or individual, ctional exercise following the					
	onset of the emer						
		in additional exercise every					
		the year the full-scale or					
		e under paragraph (d)(2)(i)					
		conducted that may include,					
	but is not limited to						
		scale exercise that is					
	' '	or individual, a facility					
	based functional	-					
	(B) A mock disas						
		ercise or workshop that is					
		and includes a group					
	discussion, using						
	clinically-relevant	emergency scenario, and a					
	set of problem sta	tements, directed					
	messages, or pre	pared questions designed					
	to challenge an er	mergency plan.					
	(iii) Analyze the F	PACE's response to and					
	maintain documer	ntation of all drills, tabletop					
	exercises, and em	nergency events and revise					
	the PACE's emerg	gency plan, as needed.					
	*[For LTC Facilitie	es at §483.73(d):]					
	-	ity] must conduct exercises					
	I ' ' -	ency plan at least twice per					
	year, including un	announced staff drills using					
	the emergency pr	ocedures. The [LTC facility,					
	ICF/IID] must do t	he following:					
	(i) Participate in a	an annual full-scale exercise					
	that is community	-based; or					
	(A) When a comm	nunity-based exercise is not					
	accessible, condu	ıct an annual individual,					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet Page 6 of 31

STATEMEN	STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) M	ULTIPLE CC	ONSTRUCTION	(X3) DATE SURVEY	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	JILDING		COMPI	LETED
		155379	B. W	ING		07/25	/2023
NAME OF T	DDOMNED OF CURPLES	D		STREET A	ADDRESS, CITY, STATE, ZIP COD	1	
NAME OF F	PROVIDER OR SUPPLIE	K			13TH ST		
LIFE CAF	RE CENTER OF R	OCHESTER		ROCHE	ESTER, IN 46975		
(X4) ID		STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	`	NCY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPE		COMPLETION
TAG		R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	facility-based fund						
	. , _	cility] facility experiences an					
		man-made emergency that					
		n of the emergency plan, the					
	-	empt from engaging its next					
		ale community-based or					
		-based functional exercise					
	_	et of the emergency event.					
	` '	dditional annual exercise					
	<u> </u>	but is not limited to the					
	following:	and aversing that is					
	• •	-scale exercise that is d or an individual, facility					
	based functional	_					
	(B) A mock disas	*					
	` '	ercise or workshop that is					
	led by a facilitator						
	discussion, using	- · · · · · · · · · · · · · · · · · · ·					
	_	emergency scenario, and a					
	· ·	atements, directed					
	-	pared questions designed					
	to challenge an e	·					
	_	LTC facility] facility's					
		maintain documentation of					
		exercises, and emergency					
		e the [LTC facility] facility's					
	emergency plan,						
]						
	*[For ICF/IIDs at {	§483.475(d)]:					
	(2) Testing. The I	CF/IID must conduct					
		the emergency plan at least					
	twice per year. Th	ne ICF/IID must do the					
	following:						
		n annual full-scale exercise					
	that is community						
	, ,	nunity-based exercise is not					
		uct an annual individual,					
	_	ctional exercise; or.					
		experiences an actual					
	natural or man-m	ade emergency that requires					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 7 of 31

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155379		A. B	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING			(X3) DATE SURVEY COMPLETED 07/25/2023	
	PROVIDER OR SUPPLIED		•	827 W 1	ADDRESS, CITY, STATE, ZIP COD 13TH ST STER, IN 46975		
(VA) ID	CIDOLADY	CTATEMENT OF DEPLOYENCE	1	ID.			(7/5)
(X4) ID PREFIX		STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL		ID PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE		
	,				CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	COMPLETION
TAG		R LSC IDENTIFYING INFORMATION		TAG	DLI ICLLICIT		DATE
		mergency plan, the ICF/IID					
		ngaging in its next required					
		nity-based or individual,					
	1	ctional exercise following the					
	onset of the emer	-					
		Iditional annual exercise					
	· ·	but is not limited to the					
	following:	scale exercise that is					
	community-based						
		ctional exercise; or					
	(B) A mock disast						
		ercise or workshop that is					
	` '	and includes a group					
	discussion, using						
		emergency scenario, and a					
		atements, directed					
		pared questions designed					
	to challenge an e						
	_	CF/IID's response to and					
	. , , .	ntation of all drills, tabletop					
		nergency events, and revise					
		rgency plan, as needed.					
	*[For HHAs at §48						
	` ' ' '	e HHA must conduct					
		he emergency plan at					
	-	e HHA must do the					
	following:	full analy aversion that is					
		full-scale exercise that is					
	community-based	r; or community-based exercise					
		conduct an annual					
		based functional exercise					
	every 2 years; or.						
	1	A experiences an actual					
		ade emergency that requires					
		emergency plan, the HHA is					
		aging in its next required					
		nity-based or individual,					
	I an obaic oblining	my bacca of marriada,	I				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 8 of 31

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/15/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION			(X3) DATE	SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	JILDING		COMPL	COMPLETED	
		155379	B. W	ING		07/25/	/2023	
				STREET A	ADDRESS, CITY, STATE, ZIP COD			
NAME OF P	PROVIDER OR SUPPLIEF	8			13TH ST			
LIFE CAF	RE CENTER OF RO	OCHESTER			STER, IN 46975			
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	(EACH DEFICIEN	ICY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION	
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE	
	1	tional exercise following the						
	onset of the emer	_ ,						
	1 ' '	ditional exercise every 2						
		e year the full-scale or						
		e under paragraph (d)(2)(i)						
	of this section is c	•						
		limited to the following:						
	, ,	full-scale exercise that is						
	community-based							
	facility-based fund							
	, ,	isaster drill; or						
		o exercise or workshop that						
		or and includes a group						
	discussion, using							
	I -	emergency scenario, and a						
	set of problem sta							
	to challenge an er	pared questions designed						
	_	HA's response to and						
	1 ' '	ntation of all drills, tabletop						
		nergency events, and revise						
		ency plan, as needed.						
	_							
	*[For OPOs at §48	<u>-</u>						
		e OPO must conduct						
		he emergency plan. The						
	OPO must do the	•						
	1 ''	er-based, tabletop exercise						
	I	ast annually. A tabletop						
	· ·	a facilitator and includes a						
		using a narrated, clinically						
	_	cy scenario, and a set of						
	I -	nts, directed messages, or						
	1	ns designed to challenge an						
		If the OPO experiences an						
		man-made emergency that						
	-	n of the emergency plan, the						
	1	om engaging in its next						
		xercise following the onset						
	of the emergency	event.						

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 9 of 31

AND PLAN OF CORRECTION AND PLAN OF CORRECTION 155379			LDING	NSTRUCTION	(X3) DATE SURVEY COMPLETED 07/25/2023			
	F PROVIDER OR SUPPLIE		STREET ADDRESS, CITY, STATE, ZIP COD 827 W 13TH ST ROCHESTER, IN 46975					
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	P	ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		TE	(X5) COMPLETION DATE	
	maintain docume exercises, and en the [RNHCl's and needed. *[RNCHIs at §40 (d)(2) Testing. The exercises to test to RNHCl must do to the conduct apapent least annually. Group discussion narrated, clinically scenario, and a social designed to challe (ii) Analyze the Romaintain docume exercises, and enthe RNHCl's ementailed to conduct explan at least twice punannounced staff procedures. The Lofollowing: (i) Participate in an is community-base a. When a community-base a. When a community-base function of the emergency promengaging its rocommunity-based of the emergency promengaging i	e RNHCI must conduct the emergency plan. The ne following: er-based, tabletop exercise A tabletop exercise is a led by a facilitator, using a y-relevant emergency et of problem statements, es, or prepared questions enge an emergency plan. NHCI's response to and ntation of all tabletop nergency events, and revise rgency plan, as needed. view and interview, the facility tercises to test the emergency er year, including drills using the emergency for facility must do the annual full-scale exercise that d; or inty-based exercise is not an annual individual, ional exercise. by experiences an actual natural gency that requires activation lan, the LTC facility is exempt ext required full-scale in a or individual, facility-based I exercise for I year following	E 003	39	Even though the facility did not have a second emergency dril code, the facility did have an ewhere it in-acted its emergency plan related to a Covid-19 outbreak. The outbreak starte 12/4/22 thru 1/18/23. We will submit our after action report from compliance. The staff have be educated on requirements for emergency disaster drills. In-acting the facility emergency plan also meets code requirements. The Executive Director and/or leadership will review monthly through QAPI to ensure emergency drills are complete.	Il per event cy ed on for een	08/18/2023	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet Page 10 of 31

	IT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155379	(X2) MULTIPLE C A. BUILDING B. WING	ONSTRUCTION	(X3) DATE SURVEY COMPLETED 07/25/2023
	PROVIDER OR SUPPLIER		STREET 827 W ROCH		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	(X5) COMPLETION DATE
	a. A second full-sca community-based of functional exercise. b. A mock disaster of c. A tabletop exercifacilitator that inclua a narrated, clinically and a set of problem messages, or prepar challenge an emerg (iii) Analyze the LT maintain documenta exercises, and emer LTC facility's emergaccordance with 42 deficient practice of Findings include: Based on record rev Director on 07/25/2 p.m., documentation an evacuation/fire of the survey. However second exercise of Grand Based on interview at the time of record unaware if a second within the past 12 m Director and Execution.	drill; or se or workshop that is led by a des a group discussion, using y-relevant emergency scenario, in statements, directed red questions designed to ency plan. To facility's response to and ation of all drills, tabletop gency events, and revise the gency plan, as needed in CFR 483.73(d)(2). This build affect all occupants. The with the Maintenance of the facility-based exercise of disaster was provided during for, no documentation of a choice could be provided. With the Maintenance Director of review, he stated that he was a exercise has been completed months. Both the Maintenance tive Director both missing drill during the exit		per code.	
K 0000					
Bldg. 01	Licensure Survey w	Recertification and State vas conducted by the Indiana th in accordance with 42 CFR	K 0000	This plan of correction is prepand executed because the provisions of state and federa	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 11 of 31

	VT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155379	A. BU	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING			(X3) DATE SURVEY COMPLETED 07/25/2023	
NAME OF I	PROVIDER OR SUPPLIEF	?			ADDRESS, CITY, STATE, ZIP COD			
LIFE CAI	RE CENTER OF RO	OCHESTER			13TH ST ESTER, IN 46975			
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	•	ICY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION	
TAG		R LSC IDENTIFYING INFORMATION	_	TAG	DEFICIENCY)		DATE	
	483.90(a).				require it and not because Life			
	Survey Date: 07/25	5/23			Care Center of Rochester agr with the allegations and citation			
	Facility Number: 000325				listed. Life Care Center of			
	Provider Number: 0				Rochester maintains that the alleged deficiencies do not			
	AIM Number: 100				jeopardize the health and safe	ty of		
	121111111111111111111111111111111111111	_, .550			the residents nor is it of such	rty Oi		
	At this Life Safety	Code survey, Life Care Center			character to limit our capabiliti	es		
	-	ound not in compliance with			to render adequate care. Plea			
	Requirements for P	articipation in			accept this plan of correction			
	Medicare/Medicaid	, 42 CFR Subpart 483.90(a),			our credible allegation of			
		re, and the 2012 edition of the			compliance that the alleged			
	National Fire Prote	ction Association (NFPA) 101,			deficiencies have or will be co	rrect		
	Life Safety Code (I	LSC), Chapter 19, Existing			by the date indicated to remai	n in		
	Health Care Occup	ancies and 410 IAC 16.2.			compliance with state and fed	eral		
					regulations, the facility has tal			
	-	ity was determined to be of			or will take the actions set fort	h in		
		ruction and was fully			this plan of correction. We			
	_	cility has a fire alarm system			respectfully request paper			
		on in the corridors, all areas			compliance.			
	_	and battery powered smoke						
		dent sleeping rooms. The						
		ity of 141 and had a census of						
	55 at the time of thi	is survey.						
	All areas where res	idents have customary access						
	were sprinklered.	The facility had one detached						
	garage which was r	not sprinklered.						
	Quality Review con	mpleted on 07/27/23						
K 0211	NFPA 101							
SS=E	Means of Egress	- General						
Bldg. 01	Means of Egress							
J	_	ays, corridors, exit						
		ocations, and accesses are						
		h Chapter 7, and the means						
		nuously maintained free of						
	_	full use in case of						

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 12 of 31

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) M	(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	A. BUILDING <u>01</u>		COMPLETED		
		155379	B. W	B. WING			07/25/2023	
				STREET A	ADDRESS, CITY, STATE, ZIP COD			
NAME OF P	PROVIDER OR SUPPLIER	L	827 W 13TH ST					
LIFE CAF	RE CENTER OF RO	OCHESTER		ROCHE	ESTER, IN 46975			
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE			ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	· ·	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	COMPLETION	
TAG		LSC IDENTIFYING INFORMATION	-	TAG	DEFICIENCY		DATE	
		s modified by 18/19.2.2						
	through 18/19.2.1 ¹ 18.2.1, 19.2.1, 7.1							
		on and interview, the facility	K 0	211	The lock on the goit was		08/18/2023	
		f 1 exit discharge paths that	K U	211	immediately removed and the	The lock on the gait was		
	lead through courtyard was readily accessible at all times. This deficient practice could affect				latch for the gait was moved u			
					Other residents have the potential			
		esidents and staff in the facility.			to be affected by the deficient			
		•			practice, therefore maintenance			
	Findings include:				removed the lock and the late			
					was moved up on the gait.			
	Based on observation	ons and interview with the			All courtyards were audited ar	nd		
		or during a tour of the facility			any issues were identified and	t		
	on 07/25/2023 between 12:25 p.m. and 2:35 p.m., the main dining hall exit door had a sticker				immediately addressed.			
					Education was completed by t			
		stating that it was an			Executive Director on 8-11-23			
		is aforementioned door led into			which included the maintenan			
		d which serves as the resident			director, Housekeeping Super			
		discharge exit from the fenced			and the Activity Director relate			
		ocked gate before accessing			ensuring exit discharge paths	are		
		gate was locked with a			ready accessible at all times.	d/		
	_	intenance Director stated it ton-authorized personnel to			The Maintenance Director and			
	gain access to the co	•			Designee to conduct courtyard audits 1x weekly for 6 months			
	-	for stated that the gate does			Any concerns identified will be			
		lable and ready to use at the			addressed immediately. Audit			
	gate.	adole and ready to use at the			will be presented to QAPI x 6	3		
					months then QAPI will determ	ine		
	Findings were discu	issed with the Maintenance			the need for further audits.			
	•	tive Director at exit conference.						
	3.1-19(b)							
K 0291	NFPA 101							
SS=C	Emergency Lightir	na						
Bldg. 01	Emergency Lightir	_						
		g of at least 1-1/2-hour						
	duration is provide	_						
	accordance with 7	-						
	18.2.9.1, 19.2.9.1							

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet Page 13 of 31

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155379		A. BUII	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 07/25/2023		
	PROVIDER OR SUPPLIED			827 W ²	ADDRESS, CITY, STATE, ZIP COD 13TH ST ESTER, IN 46975		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID REFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	(X5) COMPLETION DATE
	failed to maintain in inspections and test lights. Section 7.9. Itesting shall be comminimum of 3 week between tests, for much a mainimum of 1 1/2 system is battery performed of visual inspection the owner for insperior in the owner for insperior in the factor of the owner for insperior of the owner for inspection of the owner for	eview and interview, the facility temized records of the ts for 1 of 1 battery backup (3.1.1 (1) requires functional iducted monthly, with a ks and a maximum of 5 weeks not less than 30 seconds, (3) shall be conducted annually for 2 hours if the emergency lighting owered and (5) Written records and tests shall be kept by section by the authority having deficient practice could affect all idity. Eview with the Maintenance 23 between 08:48 a.m. and 12:21 list was provided when reviewing light testing forms. However, monthly emergency battery the computer system 'TELS' did its tested within the facility. It with the Maintenance Director direview, he stated that he was becumentation would have to be a fix the aforementioned eviewed with the Maintenance citive Director at exit conference.	K 029	91	TELS was reviewed and audit completed. TELS was notified that an audit tool was needed the preventive maintenance. No residents have the potential be affected by the deficient practice but does have the potential to effect maintenance and housekeeping staff. Education was completed by the Executive Director on 8-11-23 the maintenance director to ensure that weekly audits will an itemized list. TELS will be notified that an itemized list need to be added to the weekly cheat The Maintenance Director and Designee to conduct emergen lighting 1x weekly for the next months. Any concerns identified will be addressed immediately Audits will be presented to QAX6 months then QAPI will determine the need for further audits Compliance date: 8/18/23. The Administrator at Life Care Cerof Rochester is responsible in ensuring compliance in the Plat Correction.	d in all to e he with have eeds cks. d/or icy 6 ied r. PI	08/18/2023
K 0293 SS=E Bldg. 01	NFPA 101 Exit Signage Exit Signage 2012 EXISTING Exit and direction	al signs are displayed in					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 14 of 31

	OF CORRECTION	IDENTIFICATION NUMBER 155379	A. BUILDING B. WING	01	COMPLETED 07/25/2023		
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 827 W 13TH ST ROCHESTER, IN 46975				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE		
	illumination also so lighting system. 19.2.10.1 (Indicate N/A in or occupancies with where the line of eased on observation failed to ensure 2 of continuously illuminated affect approximation in two smoke comparts in two smoke comparts. Based on observation of the facility from Maintenance Direct exit doors near residuluminated. Based Maintenance Direct the Maintenance Direct the Maintenance Direct the Maintenance Direct the indirect of the exit signs were operation at that time continued to acknow signs were not illuminated. Findings were discussional systems were discussed in the systems of the continued to acknow signs were not illuminated.	less than 30 occupants exit travel is obvious.) on and interview, the facility of 12 exit signs were nated. This deficient practice imately 20 residents and staff artments. ons on 07/25/23 during a tour 12:25 p.m. to 2:35 p.m. with the or, the exit signs above the dent room 226 and 117 were not on an interview with the or at the time of observations, rector stated that inspections are recently done and were in the The Maintenance Director evoledge and agreed that two	K 0293	The exit lights were repaired. Residents have the potential affected by the deficient pract therefore Maintenance repaire exit light. All exit lights were audited a any issues were identified and immediately addressed. Education was completed by Executive Director on 8-11-23 the maintenance director relato ensuring exit lights are in working order. 1. The Maintenance Direct and/or Designee will conduct weekly audits for the next 6 months to ensure exit lights a continuously illuminated utiliz the TELS system. Any conceidentified will be addressed immediately. Audits will be presented to QAPI x6 months then QAPI will determine the for further audits. Compliance date: 8/18/23. Till Administrator at Life Care Ce of Rochester is responsible in ensuring compliance in the Pic Correction.	to be tice red the and d the 3 with ated ctor 1x are ting terns s need the enter n		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet Page 15 of 31

NAME OF PROVIDER OR SUPPLIER 827 W 13TH ST)			
LIFE CARE CENTER OF ROCHESTER ROCHESTER, IN 46975	STREET ADDRESS, CITY, STATE, ZIP COD 827 W 13TH ST ROCHESTER, IN 46975			
(X4) ID SUMMARY STATEMENT OF DEFICIENCIE ID PROVIDER'S PLAN OF CORRE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE ACTION SHOT CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF CORRECTIVE	JLD BE	(X5) COMPLETION DATE		
NSPA 101 SS=F Protection - Other List in the REMARKS section any LSC Section 18.3 and 19.3 Protection requirements that are not addressed by the provided K-tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567. 1. Based on record review, interview, and observation, the facility failed to ensure documentation for the preventative maintenance of 55 of 55 battery operated smoke alarms in resident rooms was complete. NFPA 101 in 4.6.12.3 states existing life safety features obvious to the public, if not required by the Code, shall be maintained. NFPA 72, 29.10 Maintenance and Tests. Fire-warning equipment shall be maintained and tested in accordance with the manufacturer's published instructions and per the requirements of Chapter 14. NFPA 72, 14.2.1.1.1 Inspection, testing, and maintenance programs shall satisfy the requirements of this Code and conform to the equipment manufacturer's published instructions. This deficient practice could affect all residents, staff, and visitors. Findings include: Based on records review with the Maintenance Director on 07/25/23 between 08:48 a.m. and 12:21 p.m., Documentation of battery-operated smoke detectors were twe manufacturer recommen The audit in TELIs. will be to include pass/fail and It replacement The audit in TELIs. will be to include pass/fail and It replacement p="" paraid="15715151 pa	e potential icient enance ectors with with any ectors nd new d. 8-4b13-b28 ompleted r on eance ng all ithin dations. e updated pattery 5" 57-4b8d-b7 The d/or dits in 5	08/18/2023		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 16 of 31

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	A. BUILDING <u>01</u> COMPLET			LETED
		155379	B. W	ING		07/25	
			<u> </u>				
NAME OF F	PROVIDER OR SUPPLIEF	₹			ADDRESS, CITY, STATE, ZIP COD		
					13TH ST		
LIFE CAF	RE CENTER OF RO	OCHESTER		ROCHE	ESTER, IN 46975		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	ICY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	During an interview	v at the time of record review,			identified will be immediately		
	the Maintenance Di	irector stated that he was			addressed and all results will l	be	
	unaware that the lis	at had to be itemized and			discussed, and system		
	further stated that h	e had replaced a few batteries			components will be reviewed		
		in some smoke detectors and did not document			monthly by the QA Committee	;	
	the battery replacement.				with subsequent plans of		
		7 1			correction developed and		
	Findings were disci	Findings were discussed with the Maintenance			implemented as deemed		
	_	tive Director at exit conference.			necessary. QA will determine	the	
					need for further audits.		
	3.1-19(b)				need for farther dudies.		
					Compliance date: 8/18/23. Th	ne	
	2. Based on observation and interview, the facility				Administrator at Life Care Cer		
	failed to ensure 2 of over 50 battery operated				of Rochester is responsible in		
		lled in resident sleeping rooms			ensuring compliance in the Pla		
		ears old in accordance with			Correction.	uii oi	
		2, 2010 Edition, Section 14.4.8.1			Correction.		
		vise recommended by the					
		lished instructions, single- and					
	_	oke alarms shall be replaced					
	_	spond to operability tests but					
	· ·	service longer than 10 years					
		nufacture. This deficient					
		et over 10 residents, staff, and					
	_	ity of Rooms 303 and 324.					
		,					
	Findings include:						
	Based on observation	ons with the Maintenance					
	Director on 07/25/2	23 during a tour of the facility					
	from 12:25 p.m. to	2:35 p.m., manufacturer's					
	documentation affix	xed to the battery operated					
	smoke alarms installed on the ceilings in resident						
	sleeping rooms 303 and 324 indicated each device						
	was manufactured 06/26/2012 respectively. Based						
	on interview at the time of each observation, the						
	Maintenance Director agreed the aforementioned						
		more than ten years old and					
		lge, all resident room smoke					
	detectors were the same.						

CENTERS FOI	R MEDICARE & MEDIC	AID SERVICES				ON	IB NO. 0938-039
STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155379		A. BU	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 07/25/2023		
NAME OF I	PROVIDER OR SUPPLIEF	₹			ADDRESS, CITY, STATE, ZIP COD		
LIFE CA	RE CENTER OF RO	OCHESTER			STER, IN 46975		
(X4) ID PREFIX	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL		ID PREFIX	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPR DEFICIENCY)	D BE	(X5) COMPLETION
TAG	These findings wer	e reviewed with the Executive enance Director during the exit		TAG	DEFICIENCE		DATE
K 0321 SS=E Bldg. 01	NFPA 101 Hazardous Areas - Enclosure Hazardous Areas - Enclosure Hazardous areas are protected by a fire barrier having 1-hour fire resistance rating (with 3/4 hour fire rated doors) or an automatic fire extinguishing system in accordance with 8.7.1 or 19.3.5.9. When the approved automatic fire extinguishing system option is used, the areas shall be separated from other spaces by smoke resisting partitions and doors in accordance with 8.4. Doors shall be self-closing or automatic-closing and permitted to have nonrated or field-applied protective plates that do not exceed 48 inches from the bottom of the door. Describe the floor and zone locations of hazardous areas that are deficient in REMARKS. 19.3.2.1, 19.3.5.9						
	a. Boiler and Fuel b. Laundries (larg c. Repair, Mainter						

FORM CMS-2567(02-99) Previous Versions Obsolete

(over 50 square feet)

f. Combustible Storage Rooms/Spaces

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 18 of 31

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155379		(X2) MULTIPLE (A. BUILDING B. WING	construction 01	(X3) DATE SURVEY COMPLETED 07/25/2023	
	PROVIDER OR SUPPLIER		827 W	r address, city, state, zip cod V 13TH ST HESTER, IN 46975	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	(X5) COMPLETION DATE
	Hazard - see K32: Based on observation failed to ensure the hazardous rooms we self-closing device automatically close. This deficient praction 10 residents and state of Findings include: Based on observation with the Maintenance between 12:25 p.m. room adjacent to the larger than 50 squar of paper and cardbowhich had a door the on interview at the Maintenance Direct hazardous area and. This finding was recommended.	on and interview, the facility corridor doors to 1 of 1	K 0321	The file storage room was cleand the door closure will be replaced on or before 8/11/23. No residents were affected by deficient practice, however administrative staff could be affected by the deficient prace Education was completed by Executive Director on 8-11-23 the maintenance director and Administrative staff related to hazardous areas. The Executive Director and/of Designee to conduct a inspect of facility storage rooms and corridors 1x weekly for 6 mor Any concerns identified will be addressed immediately. Aud will be presented to QAPI x6 months then QAPI will determ the need for further audits. Compliance date: 8/18/23. The Administrator at Life Care Ce of Rochester is responsible in ensuring compliance in the Picorrection.	y this tice.: the 3 with 4 or ction onths. ee lits nine the enter n
K 0324 SS=E Bldg. 01	Ventilation Contro Commercial Cook * residential cookin appliances such a toasters) are used	nt is protected in IFPA 96, Standard for I and Fire Protection of ing Operations, unless: ng equipment (i.e., small s microwaves, hot plates, I for food warming or limited			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 19 of 31

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	JILDING	01	COMPLETED	
		155379	B. WING 07/25/2023				/2023
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 827 W 13TH ST ROCHESTER, IN 46975				
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE	ID				(X5)
PREFIX		CY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE	TE	COMPLETION
TAG	REGULATORY OR	R LSC IDENTIFYING INFORMATION	TAG CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		IE	DATE	
	smoke compartments patients comply with 30 or fewer proconditions under 10 Cooking facilities with 30 or fewer proconditions under 11 Cooking facilities in NFPA 96 per 9.2.3 enclosed as hazard be open to the cor 18.3.2.5.1 through through 19.3.2.5.5 Based on observation failed to ensure 1 of extinguishing system working order. NFP 10.1.2 requires cooking equipment fire-extinguishing ecooking equipment fire-extinguishing ecooking equipment fire-extinguishing synonoperational or in practice could affect who use the dining and also affect kitch. Findings include: Based on observation p.m. and 2:35 p.m. the Maintenance Diextinguishing system positioned over the hood and pushed up the range hood. Based in the system of the process of the process of the positioned over the hood and pushed up the range hood. Based on the patients of the pat	tin smoke compartments atients comply with 18.3.2.5.4, 19.3.2.5.4. protected according to 3 are not required to be rdous areas, but shall not rridor. 18.3.2.5.4, 19.3.2.5.1 19.9.2.3, TIA 12-2 10 and interview, the facility of 1 kitchen range hood ms was maintained in proper PA 96, 2011 edition, Section king equipment that produces and that might be a source of a the hood, grease removal 1 be protected by quipment. Section 11.1.6 states shall not be operated while its ystem or exhaust system is mpaired. This deficient approximately 20 residents area connected to the kitchen	K 0	324	The kitchen range hood extinguishing system nozzles were immediately properly positioned over the cooking equipment. Residents and staff have the potential to be affected by the deficient practice therefore the extinguishing nozzles were properly positioned. Education was completed by the Executive Director on 8-11-23 the maintenance director and dietary staff related to ensuring hood extinguishing nozzles are appropriately placed over the cooking equipment. The Maintenance Director and designee will conduct audits 1 weekly for 6 months. Any concerns identified will be addressed immediately. Audit will be presented to QAPI x6 months then QAPI will determ the need for further audits. Compliance date: 8/18/23. The	the with all g the e	08/18/2023

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet Page 20 of 31

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MU	(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BUI	a. building <u>01</u>			ETED
		155379	B. WIN	B. WING 07/25			2023
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 827 W 13TH ST ROCHESTER, IN 46975				
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID			(X5)
PREFIX		CY MUST BE PRECEDED BY FULL		PREFIX PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE		COMPLETION	
TAG	`	LSC IDENTIFYING INFORMATION		TAG	CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	TE	DATE
	area and did not kno inside the hood. This finding was rev	completely cover the cooking ow why they were pushed up viewed with the Maintenance tive Director at the exit			Administrator at Life Care Cen of Rochester is responsible in ensuring compliance in the Pla Correction.		
K 0346 SS=F Bldg. 01	services for more period, the authoribe notified, and the evacuated or an aprovided for all pashutdown until the been returned to see 9.6.1.6 Based on record reversal failed to provide 1 of the protection of rest to be followed in the hast obe placed out more in a twenty for with LSC, Section 9 affects all occupants Findings include: Based on records reprinciple of the protection of t	e alarm system is out of than 4 hours in a 24-hour ty having jurisdiction shall be building shall be pproved fire watch shall be rities left unprotected by the fire alarm system has service. The wand interview, the facility of 1 correct written policy for cidents indicating procedures be event the fire alarm system of service for four hours or the unique period in accordance 0.6.1.6. This deficient practice	K 03	46	The Fire Watch Policy in the Emergency Preparedness bind was updated with the gateway for contacting the Incident Reporting System located on to IDOH Gateway. Residents and staff have the potential to be affected by the deficient practice, therefore the Emergency Preparedness bind was updated. Education was completed by the Executive Director on 8-11-23 which included the Maintenand Director and facility leadership The Fire Watch Policy will be reviewed by the Executive Director and/or designee 1x monthly for	e der he ce .	08/18/2023

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 21 of 31

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155379		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 07/25/2023	
	PROVIDER OR SUPPLIER RE CENTER OF ROCHESTER	STREET A 827 W 1 ROCHE			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE	
	the Indiana State Department of Health via the ISDH Gateway link at https://gateway.isdh.in.gov as the primary method or by the secondary method when the ISDH Gateway is nonoperational by completing the Incident Reporting form and e-mailing it to incidents@isdh.in.gov b.) Staff must be qualified and trained to conduct fire watch and shall have no other duties c.) A fire watch must be conducted every 15 minutes d.) Fire watch must be conducted if the sprinkler system is out for more than 10 hours in a 24 hour period. The second policy provided was missing all of the following plus indicating that a fire watch must be conducted if the fire alarm is out for more than 4 hours in a 24 hour period. Based on interview at the time of record review, the Maintenance Director stated that he was unaware which policy was the correct one the facility uses and agreed information was missing from the documentation's. Findings were discussed with the Maintenance Director and Executive Director at exit conference.		months. Any concerns identific will be addressed immediately Audits will be presented to QA x6 months then QAPI will determine the need for further audits. Compliance date: 8/18/23. Th Administrator at Life Care Centof Rochester is responsible in ensuring compliance in the Plat Correction.	PI e ter	
K 0353 SS=F Bldg. 01	NFPA 101 Sprinkler System - Maintenance and Testing Sprinkler System - Maintenance and Testing Automatic sprinkler and standpipe systems are inspected, tested, and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintaining of Water-based Fire Protection Systems. Records of system design, maintenance, inspection and testing are maintained in a secure location and readily available. a) Date sprinkler system last checked				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 22 of 31

08/15/2023 PRINTED: FORM APPROVED OMB NO. 0938-039

DEPARTMENT OF HEALTH AND HUMAN SERVICES STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X2) MULTIPLE CONSTRUCTION X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER A. BUILDING COMPLETED 01 B. WING 07/25/2023 155379 STREET ADDRESS, CITY, STATE, ZIP COD NAME OF PROVIDER OR SUPPLIER 827 W 13TH ST LIFE CARE CENTER OF ROCHESTER ROCHESTER, IN 46975 (X4) ID SUMMARY STATEMENT OF DEFICIENCIE ID (X5) PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX COMPLETION TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG DEFICIENCY) DATE b) Who provided system test c) Water system supply source Provide in REMARKS information on coverage for any non-required or partial automatic sprinkler system. 9.7.5, 9.7.7, 9.7.8, and NFPA 25 Based on record review and interview, the facility K 0353 The TELS system will be used 08/18/2023 failed to maintain 2 of 2 sprinkler system in with the appropriate accordance with LSC 9.7.5. LSC 9.7.5 requires all documentation. Missing automatic sprinkler systems shall be inspected documentation was from prior year and maintained in accordance with NFPA 25, under past maintenance director. Standard for the Inspection, Testing, and New maintenance director was Maintenance of Water-Based Fire Protection hired in October of 2022 with Systems. NFPA 25, 2011 edition, Table 5.1.1.2 documentation current since that indicates the required frequency of inspection and time testing. NFPA 25, 5.2.4.1 states gauges on wet Residents and staff have the pipe sprinkler systems shall be inspected monthly potential to be affected by the and gauges on dry systems (5.2.4.2) shall be deficient practice. inspected weekly to ensure normal water or air The TELS system will be utilized pressure is being maintained. NFPA 25 13.3.2.1 and supporting documentation will states valves should be inspected weekly or be completed. New maintenance valves secured locks or supervised (13.3.2.1.1) director hired October 2022 with shall be permitted to be inspected monthly. This education provided on TELS deficient practice could affect all occupants. system with documentation current since that time. Findings include: The Maintenance Director will continue to utilize the TELS Based on records review with the Maintenance system along with the supporting Director on 07/25/23 between 08:48 a.m. and 12:21 documentation for the monthly p.m., Documentation of a monthly wet sprinkler checks/audit for preventive system inspection was not available for the maintenance. Any concerns months of July and August of 2022. Furthermore, identified will be addressed no weekly dry sprinkler system inspections were immediately. Audits will be available for the months of July, August and presented to QAPI x6 months September of 2022. Gauge and valve checks for then QAPI will determine the need

FORM CMS-2567(02-99) Previous Versions Obsolete

the facility were documented on the computer

listed above were marked as completed by the

program 'TELS.' During record review, the months

40J021 Event ID:

Facility ID: 000325

for further audits.

Compliance date: 8/18/23. The

Administrator at Life Care Center

If continuation sheet

Page 23 of 31

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155379		A. BUIL	(x2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 07/25/2023		
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 827 W 13TH ST ROCHESTER, IN 46975				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	PR	ID REFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT DEFICIENCY)	Ē	(X5) COMPLETION DATE
	were visually inspecting passed/failed. Based record review, the Mathematical that there were missistated he was hired not at the facility.	able to verify that the gauges ection or whether they d on interview at the time of Maintenance Director agreed sing gauge inspections and in October of 2022 and was			of Rochester is responsible in ensuring compliance in the Pla Correction.	n of	
Findings were discussed with the Maintenance Director and Executive Director at exit conference. 3.1-19(b)							
K 0354 SS=F Bldg. 01	extent and duration been determined, are inspected and recommendations management or duration duration in the sprinkler system of the sprinkler of the	- Out of Service er system is impaired, the on of the impairment has areas or buildings involved d risks are determined, s are submitted to designated representative, the three thr					
	failed to provide 1 of the event the autom placed out-of-service 24-hour period in ac 9.7.5. LSC 9.7.6 rec procedures comply the Standard for the	view and interview, the facility of 1 correct written policies in natic sprinkler system has to be ce for 10 hours or more in a ccordance with LSC, Section quires sprinkler impairment with NFPA 25, 2011 Edition, the Inspection, Testing and atter-Based Fire Protection	K 035	4	The correct Fire Watch Policy identified in the Emergency Management Manual. Residents and staff have the potential to be affected by the deficient practice, therefore the correct policy was made availated all staff. Education will be completed by	e ible	08/18/2023

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet Page 24 of 31

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155379		A. BU	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 07/25/2023			
	OF PROVIDER OR SUPPLIED		STREET ADDRESS, CITY, STATE, ZIP COD 827 W 13TH ST ROCHESTER, IN 46975					
(X4) ID PREFIX	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	ΓE	(X5) COMPLETION DATE	
TAG	Systems. NFPA 25 procedures that the follow. A.15.5.2 (4 consist of trained p patrol the affected a extinguishers and the fire department consider. During the should not only be sure that the other f building such as eg are available and for deficient practice of facility. Findings include: Based on records re Director on 07/25/2 p.m., the facility pr One titled "Loss of one titled "Loss of one titled "Alarm a The fire watch poli Protection Systems the Indiana State D ISDH Gateway link as the primary meth method when the Is nonoperational by of Reporting form and incidents@isdh.in.g and trained to cond no other duties c.) conducted every 15 be conducted if the more than 10 hours second policy prov following plus indi conducted if the fire	completing the Incident		TAG	the Executive Director by 8-18 with facility staff to ensure staff educated on the correct Fire Watch Policy. The Executive Director and/or Designee will conduct random interviews with staff utilizing a questionnaire related to the Fit Watch policy 1x a week for 6 months. Any concerns identifie will be addressed immediately Audits will be presented to QA x6 months then QAPI will determine the need for further audits. Compliance date: 8/18/23. The Administrator at Life Care Cent of Rochester is responsible in ensuring compliance in the Plat Correction.	f are re ed . PI e ter	DATE	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 25 of 31

		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155379	(X2) MULTIPLE A. BUILDING B. WING	E CONSTRUCTION O O O	(X3) DATE SURVEY COMPLETED 07/25/2023			
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF ROCHESTER			STREET ADDRESS, CITY, STATE, ZIP COD 827 W 13TH ST ROCHESTER, IN 46975					
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE			
	Director stated that was the correct one information was mi documentation's.	eview, the Maintenance he was unaware which policy the facility uses and agreed ssing from the assed with the Maintenance tive Director at exit conference.						
K 0374 SS=E Bldg. 01			K 0374	The bracket on the fire door was repaired immediately Residents and staff have the potential to be affected by the deficient practice, therefore the bracket on the fire door was repaired, eliminating the gap between the doors when the owere shut. Education was completed by Executive Director on 8-11-23	e doors			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet Page 26 of 31

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION (IDENTIFICATION NUMBER) 155379		(X2) MULTIPLE CO A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 07/25/2023				
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF ROCHESTER			STREET ADDRESS, CITY, STATE, ZIP COD 827 W 13TH ST ROCHESTER, IN 46975					
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OR	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	DATE			
	Findings include: Based on observation with the Maintenance Director on 07/25/23 between 12:25 p.m. and 2:35 p.m., the sets of smoke barrier doors by resident room 314 would not fully close due to the coordinating device on the door frame not correctly working. When tested, the coordinating device would hold both doors open when the door without the astragal was shut first. This condition creates an approximately two-inch gap between the doors when shut. Based on interview during the time of observations, the Maintenance Director stated the coordinating device was not function properly and not allowing the doors to completely shut. The finding was reviewed with the Maintenance Director and Executive Director during the exit conference. 3.1-19(b)			the maintenance director relate to ensuring all fire doors are in proper working order. The Executive Director and/or Designee will conduct walk throughs 3x monthly for 3 more and then 1x monthly for 3 more and then 1x monthly for 3 more addressed immediately. Audit will be presented to QAPI x6 months then QAPI will determ the need for further audits. Compliance date: 8/18/23. The Administrator at Life Care Cerof Rochester is responsible in ensuring compliance in the PI Correction.	nths nths. e s s ine e nter			
K 0522 SS=E Bldg. 01	heating plant, is do combustible mater device, and has a and shut down equexcessive temperatuel fired, the devitable is chimney or vetakes air for comator provides for a confrom occupied are 19.5.2.2 Based on observation	ng Device e, other than a central esigned and installed so rials cannot be ignited by safety feature to stop fuel uipment if there is ature or ignition failure. If ce also: nt connected. bustion from outside. embustion system separate a atmosphere. on and interview, the facility	K 0522	The fresh air intake vent was	08/18/2023			
	failed to ensure 1 of 1 laundry rooms were			cleaned out.				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 27 of 31

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155379		A. BU	(X2) MULTIPLE CONSTRUCTION (X3) DATE A. BUILDING 01 COMPI B. WING 07/25			LETED	
NAME OF F	PROVIDER OR SUPPLIER				ADDRESS, CITY, STATE, ZIP COD		
LIFE CAF	RE CENTER OF RO	OCHESTER			13TH ST ESTER, IN 46975		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	`	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		COMPLETION
TAG		R LSC IDENTIFYING INFORMATION		TAG			DATE
	1 ^	e combustion air from the			Residents and staff have the		
		ontaining fuel fired equipment. ice could create an atmosphere			potential to be affected by the		
	•	onoxide which could cause			deficient practice, therefore to fresh air vent was cleaned ou		
		For approximately 5 staff and an			Education was completed wi		
	unknown number of				Housekeeping Supervisor an		
	unknown number o	residents.			laundry staff to ensure the fre		
	Findings include:				intake vent is functioning	Jon all	
	D 1 1 2	to a set o			appropriately.		
		on with the Maintenance 3 between 12:25 p.m. and 2:35			The Housekeeping Supervise		
		om had fuel-fired dryers with a			and/or designee will conduct		
					inspections of the fresh air in 1x weekly for 6 months. Any	ıake	
fresh air intake that had automatic louvers that would open when the dryers are running, but				concerns identified will be			
	_				addressed immediately. Aud	te	
	when a dryer was turned on the louvers did not open. This condition does not allow for fresh air				will be presented to QAPI x6	ıs	
	to completely enter the room when the dryers are				months then QAPI will detern	nina	
	turned on. Upon further examination, the area between the louver intake and vent outside the				the need for further audits.	illio	
					Compliance date: 8/18/23. T	he	
		etely filled in with twigs,			Administrator at Life Care Ce		
		t blocked the vent from			of Rochester is responsible in		
	1	Based on an interview at the			ensuring compliance in the P		
		, the Maintenance Director			Correction.		
		is an automatic louver and					
	agreed that the louv	ers were not working when					
	the dryer was turned	d on.					
	This finding was re	viewed with the Executive					
	Director and Maintenance Director at the exit						
	conference.						
	3.1-19(b)						
K 0914	NFPA 101						
SS=C	Electrical Systems	s - Maintenance and					
Bldg. 01	Testing						
	I -	s - Maintenance and					
	Testing						
		ceptacles at patient bed					
locations and where deep sedation or general		ı				1	

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155379		(X2) MULTIPLE CO A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 07/25/2023			
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF ROCHESTER			STREET ADDRESS, CITY, STATE, ZIP COD 827 W 13TH ST ROCHESTER, IN 46975				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE		
	initial installation, Additional testing defined by docume Receptacles not lithese locations are exceeding 12 mor (LIM), if installed, a less than or equal the LIM test switch activates both visually LIM circuits with a manual test is per than or equal to 12 tested per 6.3.3.3 renovation to the Records are main associated repairs containing date, results. 6.3.4 (NFPA 99) Based on record revialled to ensure the grade electrical recessive sleeping rooms show tested. NFPA 99, Edition, section 6.3 record shall contain tested, and an indicator have failed to me requirements of this practice could affect. Findings include: Based on record revial Director on 07/25/2 p.m., a form provident Assessment Workships and the strength of the second shall contain tested.	riew and interview, the facility testing form for the hospital eptacles in 55 of 55 resident wed that each receptacle was lealth Care Facilities Code 2012 4.2.1.2 states at a minimum, the the date, the rooms or areas ation of which items have met, et, the performance a chapter. This deficient	K 0914	The correct NFPA99 Risk Assessment form for testing hospital grade electrical receptacles was identified by Executive Director. Residents had the potential to affected by the deficient pract therefore the correct NFPA99 Assessment form will be implemented. Education was completed by Executive Director on 8-15-23 the maintenance director rela to ensuring the correct NFPA99 Risk Assessment form is utiliz to ensure each electrical system was inspected and document correctly. The Maintenance Director will	b be ice, Risk the 3 with ted 99 ced em ed		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 29 of 31

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/15/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION (IDENTIFICATION NUMBER) 155379		(X2) MUL' A. BUIL B. WINC	DING	NSTRUCTION 01		SURVEY LETED 5/2023			
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF ROCHESTER				STREET ADDRESS, CITY, STATE, ZIP COD 827 W 13TH ST ROCHESTER, IN 46975					
(X4) ID PREFIX TAG	(EACH DEFICIEN		PR	ID REFIX FAG	PROVIDER'S PLAN OF CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPRODEFICIENCY)	TION LD BE COPRIATE	(X5) COMPLETION DATE		
K 0920 SS=E Bldg. 01	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION as either a "3" or "4". On the testing form, a "3" indicates that failure of such equipment or systems is likely to result in no injury but cause discomfort and a "4" indicates failure of such equipment would have no effect on residents. The form did not show if each receptacle passed its retention/grounding testing. The form used by the facility is a risk assessment used for emergency preparedness. Based on interview at the time of record review, the Maintenance Director stated that the numbers do not correlate with the indicated listings on the form and are representing the results taken from the tool used during receptacle testing. The Maintenance Director further stated that he agreed the form caused confusion with the testing results and was not clear if the receptacles passed or failed its indicated testing. Findings were discussed with the Maintenance Director and Executive Director at exit conference. 3.1-19(b) NFPA 101 Electrical Equipment - Power Cords and				retest prior to 8-18-2023 to facility hospital grade electroceptacles to ensure resproperly documented. The Maintenance Director utilize the NFPA99 Risk Assessment form for annotesting of hospital grade of receptacles. This process monitored and tracked the TELS system. Any conceidentified will be addressed immediately. TELS audits/inspections be presequently and the process of	etrical ults are r will ual electrical s will be rough the rns ed sented to further d. The c Center le in			
Diug. U i	Extension Cords Power strips in a pused for compone patient-care-relate (PCREE) assemble assembled by quathe conditions of 1 the patient care vinon-PCREE (e.g., except in long-terrido not use PCREE	ent - Power Cords and patient care vicinity are only ints of movable de electrical equipment des that have been diffied personnel and meet 0.2.3.6. Power strips in cinity may not be used for personal electronics), in care resident rooms that E. Power strips for PCREE TUL 60601-1. Power strips							

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

40J021

Facility ID: 000325

If continuation sheet

Page 30 of 31

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY		
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER			COMPL	COMPLETED	
1		155379	B. WING			07/25/2023	
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF ROCHESTER			STREET ADDRESS, CITY, STATE, ZIP COD 827 W 13TH ST ROCHESTER, IN 46975				
(X4) ID		STATEMENT OF DEFICIENCIE	ID PREFIX		PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	`	CY MUST BE PRECEDED BY FULL			(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	COMPLETION
TAG		the patient care rooms		TAG	DLI ICILICI I		DATE
	(outside of vicinity non-patient care roother UL standard used with general cords are not used wiring of a structure temporarily are recompletion of the installed and meet 10.2.3.6 (NFPA 98 (NFPA 70), 590.3 (Based on observation failed to ensure 1 of in patient care locat rating of 1363A or affect approximately. Findings include: Based on observation with the Maintenand between 12:25 p.m. there was a power stresident care area the 60601-1. Based on observation, the Mapower strips were indid not meet 1363A. The findings were resident care area the findings w	meet UL 1363. In pooms, power strips meet s. All power strips are precautions. Extension d as a substitute for fixed re. Extension cords used moved immediately upon purpose for which it was to the conditions of 10.2.4. (D) (NFPA 70), TIA 12-5 on and interview, the facility of 1 flexible cords power strips ions met the required UL 60601-1. This deficient practice by two residents. (D) (NFPA 70), TIA 12-5 on and interview of 1 flexible cords power strips ions met the required UL 60601-1. This deficient practice by two residents.	K 0º	920	The power strip in room #217 immediately removed. Residents have the potential to affected by the deficient practitherefore a facility audit was completed. Any issues identifivia this audit was immediately addressed. Education was completed by the Executive Director on 8-15-23 the maintenance director relatito ensuring power strips are not utilized in the facility. The Maintenance Director and designee will conduct facility audits 1x per week for 6 month Any concerns identified will be addressed immediately. Audit will be presented to QAPI x6 months then QAPI will determ the need for further audits. Compliance date: 8/18/23. The Administrator at Life Care Cerof Rochester is responsible in ensuring compliance in the Plat Correction.	o be ce, ied he with ed ot l/or hs. ets ine he eter	08/18/2023

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: 40J021 Facility ID: 000325 If continuation sheet Page 31 of 31