PRINTED: 06/24/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155481		(X2) MULTIPLE CO A. BUILDING B. WING	ONSTRUCTION	(X3) DATE SURVEY COMPLETED 06/04/2024	
	PROVIDER OR SUPPLIE	R LIVING COMMUNITY	3701 H	ADDRESS, CITY, STATE, ZIP COD IODGIN RD IOND, IN 47374	
(X4) ID PREFIX TAG E 0000	(EACH DEFICIE	Y STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL OR LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	(X5) COMPLETION DATE
Bldg	conducted by the laccordance with 4 Survey Date: 06/0 Facility Number: Provider Number: AIM Number: 10 At this Emergency Trace Health & Licompliance with Exequirements for Participating Prov 483.73. The facility has a chealthcare portion 101 certified beds time of this visit.	04/24 000455 155481	E 0000		
K 0000 Bldg. 02					
Bidg. 02	Licensure Survey	000455 155481	K 0000	June 21, 2024 Brenda Buroker, Director Long-Term Care Division Indiana State Department of Health 2 North Meridian Street Indianapolis, IN 46204	
LABORATOI	RY DIRECTOR'S OR PRO	DVIDER/SUPPLIER REPRESENTATIVE'S S	IGNATURE	TITLE	(X6) DATE
Shelli Ros	S		RN/HFA		06/21/2024

Any defiencystatement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclodays following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to

continued program participation.

PRINTED: 06/24/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155481		(X2) MULTIPLE C A. BUILDING B. WING	onstruction 02	(X3) DATE SURVEY COMPLETED 06/04/2024				
NAME OF PROVIDER OR SUPPLIER ARBOR TRACE HEALTH & LIVING COMMUNITY			3701 F	STREET ADDRESS, CITY, STATE, ZIP COD 3701 HODGIN RD RICHMOND, IN 47374				
(X4) ID PREFIX TAG	At this Life Safety (Health & Living Cocompliance with Research Medicare/Medicaid Life Safety Code (Life Safety Code (Li	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION Code survey, Arbor Trace community was found not in equirements for Participation in equirements for Participation in equirements for Participation of the extraction Association (NFPA) 101, extraction Association	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPE DEFICIENCY) Re: Allegation of Complia Event ID: 64N721 Dear Mrs. Buroker: Please find enclosed the Pla Correction for the State Lice Survey conducted on June 4 2024. This letter is to inform that the plan of correction attached is to serve as Arbot Trace Health and Living crec allegation of compliance. W allege substantial compliance July 19, 2024. We are reque paper compliance for this pla correction. If you have any further quest please do not hesitate to cor me at 765-939-3701. Sincerely, Shellie Ross RN, HFA	ance DATE ance In of Insure In you If It dible If If e If e If on If e If on If it in the interval is a second content of It in the interval is a second content of It in the interval is a second content of It in the interval is a second content of it in the interval is a second			
K 0353 SS=F Bldg. 02 NFPA 101 Sprinkler System - Maintenance and Testing Sprinkler System - Maintenance and Testing Automatic sprinkler and standpipe systems are inspected, tested, and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintaining of Water-based Fire Protection Systems.			Administrator Arbor Trace Heath and Livin	g				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

64N721

Facility ID: 000455

Page 2 of 10 If continuation sheet

PRINTED: 06/24/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X2) MULTIPLE CONSTRUCTION X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER A. BUILDING COMPLETED 02 B. WING 06/04/2024 155481 STREET ADDRESS, CITY, STATE, ZIP COD NAME OF PROVIDER OR SUPPLIER 3701 HODGIN RD ARBOR TRACE HEALTH & LIVING COMMUNITY RICHMOND, IN 47374 (X4) ID SUMMARY STATEMENT OF DEFICIENCIE ID (X5) PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX COMPLETION TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG DEFICIENCY) DATE Records of system design, maintenance, inspection and testing are maintained in a secure location and readily available. a) Date sprinkler system last checked b) Who provided system test c) Water system supply source Provide in REMARKS information on coverage for any non-required or partial automatic sprinkler system. 9.7.5, 9.7.7, 9.7.8, and NFPA 25 K 0353 07/19/2024 1. Based on record review and interview, the facility failed to ensure a full hydrostatic flush was K 353 performed on 1 of 1 automatic sprinkler piping systems that were internally inspected as required I. The corrective actions to be by NFPA 25, 2011 edition, the Standard for the accomplished for those Inspection, Testing and Maintenance of residents found to have been Water-Based Fire Protection Systems in Chapter affected by the deficient 14, Obstruction Prevention. Section 14.3.2 practice. requires systems shall be examined for internal obstructions where conditions exist that could Observation 1- The community cause obstructed piping. Section 14.3.3, states if failed to ensure that the an obstruction investigation indicates the hydrostatic flush the was presence of sufficient material to obstruct pipe or recommended by the provider was sprinklers, a complete flushing program shall be ever performed. The Maintenance conducted by qualified personnel. Section 14.3.1 Supervisor has contracted with states if the condition has not been corrected or Safecare to complete an entire the condition is one that could result in flush of the sprinkler system obstruction of piping despite any previous starting the week of July 15th. flushing procedures that have been performed, See attached letter labeled the system shall be examined internally for "Arbor Trace Flush Letter." obstructions every 5 years. This deficient practice could affect all residents, as well as staff Observation 2- The community and visitors in the facility. failed to ensure that the dry pipe sprinkler head in the freezer was Findings include: debris and corrosion free. The Maintenance Supervisor has

FORM CMS-2567(02-99) Previous Versions Obsolete

Based on records review and interview with the

Event ID:

64N721

Facility ID: 000455

contracted with Safecare to

If continuation sheet

Page 3 of 10

PRINTED: 06/24/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X2) MULTIPLE CONSTRUCTION X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER A. BUILDING COMPLETED 02 B. WING 06/04/2024 155481 STREET ADDRESS, CITY, STATE, ZIP COD NAME OF PROVIDER OR SUPPLIER 3701 HODGIN RD ARBOR TRACE HEALTH & LIVING COMMUNITY RICHMOND, IN 47374 (X4) ID SUMMARY STATEMENT OF DEFICIENCIE ID (X5) PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX COMPLETION TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG DEFICIENCY) DATE Maintenance Director (MD) on 06/04/24 between replace the sprinkler head. 11:10 a.m. and 1:45 p.m., the Internal Pipe Safecare has measured the dry Inspection Letter from the facility's contractor head and it is on order for dated 11/01/23 stated on 10/20/23 a 5-year internal replacement. Estimated install pipe inspection was performed and revealed that date is the week of July 1st. the "branch lines were ½ full of hardened debris and could not be removed by hand." Also, "some sections of the grooved ends on the mains were II. The facility will identify partially missing from corrosion." Furthermore, the other residents that may report stated that "we found that numerous potentially be affected by the amounts of the pipe did not have the correct pitch deficient practice. and were holding water. We suggest flushing the system to remove debris and to repatch the pipe All staff and residents could have and add additional low point drains to ensure all the potential to be affected by this water is removed from the dry system." The deficient practice. aforementioned report also included pictures of the pipe obstructions. The MD stated that no work had been done on the sprinkler system to III. The facility will put into correct these issued and that they were waiting on place the following systematic a quote from the vendor, since November of 2023. changes to ensure that the The MD stated that he would begin immediately deficient practice does not to seek another company to make the repairs and recur. corrections recommended in the report. Observation 1- The Maintenance This finding was acknowledged by the MD at the Supervisor has been re educated time of discovery and again at the exit conference to ensure the recommendations with the MD and Executive Director present. from this inspection are completed. 2. Based on observation and interview, the facility failed to ensure 1 of 1 sprinklers in the freezer free Observation 1- There is a current of corrosion. NFPA 25, 2011 edition, at 5.2.1.1.1 TELS task to have all sprinkler sprinklers shall not show signs of leakage; shall heads in the community visually be free of corrosion, foreign materials, paint, and inspected annually. See attached physical damage; and shall be installed in the TELS work order labeled "Arbor correct orientation (e.g., up-right, pendent, or Trace Visual Sprinkler Inspection." sidewall). Furthermore, at 5.2.1.1.2 any sprinkler that shows signs of any of the following shall be replaced: (1) Leakage (2) Corrosion (3) Physical IV The facility will monitor Damage (4) Loss of fluid in the glass bulb heat the corrective action by

responsive element (5) Loading (6) Painting

implementing the following

PRINTED: 06/24/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155481		X2) MULTIPLE CONSTRUCTION X3) DATE SURV A. BUILDING 02 COMPLETED B. WING 06/04/2024			PLETED	
	PROVIDER OR SUPPLIER	LIVING COMMUNITY	3701 H	ADDRESS, CITY, STATE, ZIP O HODGIN RD MOND, IN 47374	COD	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF COI (EACH CORRECTIVE ACTION S CROSS-REFERENCED TO THE DEFICIENCY)	RRECTION SHOULD BE APPROPRIATE	(X5) COMPLETION DATE
		ne sprinkler manufacturer. This bould affect staff and up to 20 bke compartment.		measures. CarDon Corporate F monitor these issues of Site Visits and annual	during their	
	tour of the facility we on 06/04/24 between sprinkler head in the formed around it what was extending a forming an icicle. But observation, the MI kitchen freezer was			V. Plan of Correction completion date. Plan of Completion da 19th, 2024.		
	time of discovery as	knowledged by the MD at the and again at the exit conference executive Director present.				
K 0363 SS=E Bldg. 02	than required enclexits, or hazardou of smoke and are solid-bonded core capable of resistin minutes. Doors in compartments are passage of smoke to rooms containing combustible mater hardware. Roller It CMS regulation. T	rials have positive latching atches are prohibited by These requirements do not spaces that do not contain				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

64N721

Facility ID: 000455

If continuation sheet

Page 5 of 10

PRINTED: 06/24/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/		X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION (X3) DATE SURV			SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BUILDING <u>02</u>			COMPL	COMPLETED	
155481		B. WING 06/04/2024			/2024			
				STREET A	ADDRESS, CITY, STATE, ZIP COD			
NAME OF PROVIDER OR SUPPLIER					ODGIN RD			
ARBOR -	TRACE HEALTH &	LIVING COMMUNITY			OND, IN 47374			
					. ,		T	
(X4) ID		STATEMENT OF DEFICIENCIE	ID PREFIX		PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	,	CY MUST BE PRECEDED BY FULL			(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		COMPLETION	
TAG		R LSC IDENTIFYING INFORMATION	+	TAG	DEFICIENCY		DATE	
		en bottom of door and floor						
	-	ceeding 1 inch. Powered						
		vith 7.2.1.9 are permissible						
		device capable of keeping hen a force of 5 lbf is						
		no impediment to the						
		rs. Hold open devices that						
	-	door is pushed or pulled are						
		ed protective plates of						
	•	re permitted. Dutch doors						
		6 are permitted. Door						
	•	beled and made of steel or						
		compliance with 8.3,						
	unless the smoke	-						
		fire window assemblies are						
	-	n sprinklered compartments						
	there are no restri	ctions in area or fire						
	resistance of glass	s or frames in window						
	assemblies.							
	19.3.6.3, 42 CFR	Parts 403, 418, 460, 482,						
	483, and 485							
		S details of doors such as						
		ngs, automatics closing						
	devices, etc.		1					
		on and interview, the facility	K 0	363	K 363		07/19/2024	
		f over 50 corridor doors had no]			
	-	ing and latching into the door			I. The corrective actions to b	oe		
		sist the passage of smoke.			accomplished for those			
	-	ice could affect 6 staff and 15			residents found to have been	n		
	residents.				affected by the deficient			
	Findings include:				practice.			
					Observation 1- The communit	v		
	Rased on observativ	ons and interview during a			failed to ensure that the doubl	-		
		with the Maintenance Director			of doors leading to the dining	C 261		
	-	on 1:15 p.m. and 3:15 p.m., the			would shut and latch. The			
		doors failed to latch positively			Maintenance Supervisor have			
	into their respective				reworked the set of doors to	:		
	-	of doors leading into the			ensure they close and latch			
	a) The double set of	1 doors reading into the			Chaute they dose and laten		İ	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

64N721

Facility ID: 000455

If continuation sheet Page 6 of 10

PRINTED: 06/24/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155481		A. BUILDING <u>02</u> CC		(X3) DATE SURVEY COMPLETED 06/04/2024	
	PROVIDER OR SUPPLIER	LIVING COMMUNITY	3701 H	ADDRESS, CITY, STATE, ZIP COD HODGIN RD HOND, IN 47374	
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OR	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDERS PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	(X5) COMPLETION DATE
	device. b) The Employee E equipped with a sellatching hardware a the door frame. This finding was actime of discovery at with the MD and Ex	Entrance corridor door, f-closing device, did not have and did not latch positively into knowledged by the MD at the and again at the exit conference executive Director present.		properly. Observation 2- The communifailed to ensure that the emplihallway entrance door system not have latching hardware. Maintenance Supervisor has installed latching hardware of door system.	oyee n did The
	3.1-19(b)			II. The facility will identify other residents that may potentially be affected by the deficient practice. All staff and residents could the potential to be affected by deficient practice. III. The facility will put into place the following systemate changes to ensure that the deficient practice does not recur. A Monthly TELS task has been created to inspect all corridor doors and fire doors to ensure they shut and latch properly, attached TELS task labeled "Trace Door Inspection TELS" IV The facility will monitor the corrective action by implementing the following measures. CarDon Corporate Facilities of	have y this tic e See Arbor Task"

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

64N721

Facility ID: 000455

If continuation sheet

Page 7 of 10

PRINTED: 06/24/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155481		(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY A. BUILDING 02 COMPLETED B. WING 06/04/2024			
	PROVIDER OR SUPPLIER	LIVING COMMUNITY	3701 H	ADDRESS, CITY, STATE, ZIP COD HODGIN RD MOND, IN 47374	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
				monitor these areas during thei Site Visits and CQR.	r
				V. Plan of Correction completion date.	
				Plan of Completion date is July 19th, 2024.	
K 0522 SS=E Bldg. 02	heating plant, is do combustible mater device, and has a and shut down eq excessive tempera fuel fired, the devi- * is chimney or ve- * takes air for com	ng Device e, other than a central esigned and installed so rials cannot be ignited by safety feature to stop fuel uipment if there is ature or ignition failure. If ce also: nt connected. bustion from outside. imbustion system separate			
	failed to ensure 1 of with intake combus rooms containing fu Section 19.5.2.2(2) device, other than a designed and install combustion directly deficient practice cowith carbon monoximals.	on and interview, the facility I laundry room was provided tion air from the outside for tel fired equipment. NFPA 101, requires any fuel-fired heating central heating plant, shall be ted so they shall take air for from the outside. This fould create an atmosphere rich tide which could cause physical in the laundry room.	K 0522	I. The corrective actions to be accomplished for those residents found to have been affected by the deficient practice. Observation – The community failed to provide the louvers for dryer combustion air did not opeand operate properly. The Maintenance Supervisor has	the

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

64N721

Facility ID: 000455

If continuation sheet

Page 8 of 10

PRINTED: 06/24/2024 FORM APPROVED OMB NO. 0938-039

	OF CORRECTION	IDENTIFICATION NUMBER 155481	A. BUILDING B. WING	02	COMPLETED 06/04/2024
	ROVIDER OR SUPPLIER	LIVING COMMUNITY	3701 H	ADDRESS, CITY, STATE, ZIP COD ODGIN RD IOND, IN 47374	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
TAG	Based on observation tour of the facility won 06/04/24 between laundry room had fur automatic louver systopen when the dryer from the outside. The time of observation, were closed. The M to ensure they would need to be fixed to compare the control of the fixed to contro		TAG	replaced to damper motor. II. The facility will identify other residents that may potentially be affected by the deficient practice. All Associates that work in the laundry room have the potentibeing affected by this deficient practice. III. The facility will put into place the following systematic changes to ensure that the deficient practice does not recur. There is a newly created week TELS task to inspect the dryed dampers and louvers to ensure they are operating correctly. Sattached TELS task labeled "A Trace Dryer Inspection."	e de la dela de
				measures. CarDon Corporate Facilities we inspect the dryer dampers and louvers during their site visits annual CQR to ensure the opercorrectly.	d and
				V. Plan of Correction	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

64N721

Facility ID: 000455

If continuation sheet

Page 9 of 10

PRINTED: 06/24/2024 FORM APPROVED OMB NO. 0938-039

	T OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
AND FLAN	OF CORRECTION	155481	B. WING	<u>02</u>	06/04/2024		
	ROVIDER OR SUPPLIER	LIVING COMMUNITY	STREET ADDRESS, CITY, STATE, ZIP COD 3701 HODGIN RD RICHMOND, IN 47374				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL . LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	E	(X5) COMPLETION DATE	
				completion date. Plan of Completion date is J 19th, 2024.	uly		

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: 64N721 Facility ID: 000455 If continuation sheet Page 10 of 10