PRINTED: 10/28/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY			SURVEY			
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER	A. BUILDING		COMPLETED			
155436		155436	B. WIN	B. WING			10/15/2024	
	STREET ADDRESS, CITY, STATE, ZIP COD							
NAME OF P	ROVIDER OR SUPPLIEF	8		515 E 1				
HICKORY CREEK AT WINAMAC					AC, IN 46996			
HICKOR	T CREEK AT WINA	IIVIAC		VVIINAIVI	AC, IN 40990			
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE			ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL		P	REFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATION OF THE APPROPRIATION	TE	COMPLETION	
TAG	REGULATORY OR LSC IDENTIFYING INFORMATION			TAG	DEFICIENCY)		DATE	
E 0000								
Bldg								
	An Emergency Preparedness Survey was		E 000	00				
	conducted by the In	diana Department of Health in						
	accordance with 42	CFR 483.73.						
	Survey Date: 10/15	/24						
	Facility Number: 00	00414						
	Provider Number: 155436							
	AIM Number: 100288550							
	At this Emergency	Preparedness survey, Hickory						
	Creek at Winamac was found in compliance with							
	Emergency Preparedness Requirements for							
	Medicare and Medicaid Participating Providers							
	and Suppliers, 42 CFR 483.73							
	The facility has 36 certified beds. At the time of							
	the survey, the census was 32.							
	Quality Review cor	npleted on 10/16/24						
K 0000								
Bldg. 01								
	_	Recertification and State	K 000	00				
		lucted by the Indiana			Hickory Creek at Winamac			
	Department of Heal	th in accordance with 42 CFR			respectfully requests a desk			
	483.90(a).				review for paper compliance. A	All		
					in-service and supporting			
	Survey Date: 10/15	/24			documentation is attached for			
					review. Thank you.			
	Facility Number: 00				The creation and submission of			
	Provider Number: 1	55436			this plan of correction does no	t		
	AIM Number: 1002	288550			constitute an admission by the	;		
					provider of any conclusion set	forth		
	At this Life Safety Code survey, Hickory Creek at				in the statement of deficiencies	s, or		
	Winamac was found	d not in compliance with			of any violation of regulation.			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Colleen Nan Folkers Executive Director 10/22/2024

Any define cycletement and ingravith an actorick (*) denotes a deficancy which the institution may be excused from correcting providing it is determine

Any defiencystatement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclodays following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: BPXB21 Facility ID: 000414 If continuation sheet Page 1 of 4

PRINTED: 10/28/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER	A. BUILDING <u>01</u> C			COMPL	COMPLETED	
		155436	B. WING			10/15	10/15/2024	
				CED FIELD	ADDRESS STEV STATE STR SOD			
NAME OF P	ROVIDER OR SUPPLIER	t			ADDRESS, CITY, STATE, ZIP COD			
					3TH ST			
HICKOR	Y CREEK AT WINA	MAC		WINAMAC, IN 46996				
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE			ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL			PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION	
TAG	REGULATORY OR LSC IDENTIFYING INFORMATION			TAG DEFICIENCY)			DATE	
	Requirements for P	articipation in						
	Medicare/Medicaid	, 42 CFR Subpart 483.90(a),						
	Life Safety from Fi	re and the 2012 edition of the						
	National Fire Protect	ction Association (NFPA) 101,						
	Life Safety Code (L	LSC), Chapter 19, Existing						
	Health Care Occupa	ancies and 410 IAC 16.2.						
	This one-story facil	ity was determined to be of						
	Type II (222) const	ruction and was fully						
	sprinklered. The fac	cility has a fire alarm system						
	with hardwired smo	oke detection in the corridors						
	and spaces open to	the corridors. Resident rooms						
	were equipped with	battery operated smoke						
	detectors. The facili	ity has the capacity for 36 and						
	had a census of 32 at the time of this survey.							
	All areas within the facility where residents have customary access were sprinklered. All areas providing facility services were sprinklered except							
	three detached build	dings: one used for oxygen						
	storage, the second is the maintenance office, and the third is used for miscellaneous equipment and storage.							
	Quality Review cor	npleted on 10/16/24						
K 0374	NFPA 101							
SS=E	Subdivision of Bui	ilding Spaces - Smoke						
Bldg. 01	Barrie							
		on and interview, the facility	K 0	374	Hickory Creek at Winamac		10/28/2024	
	failed to ensure 1 of	f 2 sets of smoke barrier doors			respectfully requests a desk			
		novement of smoke for at least			review for paper compliance.	All		
		9.3.7.8 requires doors in smoke			in-service and supporting			
		ly with LSC Section 8.5.4. LSC			documentation is attached for			
	•	ors in smoke barrier shall close			review. Thank you.			
		only the minimum clearance			The creation and submission	of		
		r operation. This deficient			this plan of correction does no	ot		
	*	et as many as 16 residents, 6			constitute an admission by the	9		
	staff, and 2 visitors.				provider of any conclusion set	forth		
					in the statement of deficiencie			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

BPXB21

Facility ID: 000414

If continuation sheet

Page 2 of 4

PRINTED: 10/28/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTI			(X3) DATE SURVEY	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER	A. BUILDING <u>01</u>		01	COMPLETED	
155436		B. WING 10/15/2024					
NAME OF PROVIDER OR SUPPLIER HICKORY CREEK AT WINAMAC			STREET ADDRESS, CITY, STATE, ZIP COD 515 E 13TH ST WINAMAC, IN 46996				
HICKORT CREEK AT WINAWAC					T		
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE			ID	PROVIDER'S PLAN OF CORRECTION	(X5)	
PREFIX TAG	(EACH DEFICIENCY MUST BE PRECEDED BY FULL			PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		
TAG	G REGULATORY OR LSC IDENTIFYING INFORMATION Findings include:			TAG	of any violation of regulation.	DATE	
	i maniga merade.				or arry violation of regulation.		
	Based on observation	on made during a tour of the			K 374 What corrective action	ı	
		intenance Director on 10/15/24			will be accomplished for tho		
	-	of smoke barrier doors nearest			residents found to have been		
	to resident room #4	did not close completely when		affected by the deficient			
	•	rate occasions. There was a			practice:		
		en the doors when closed to			The Executive Director comple		
		on interview during the time of			education with the Maintenand		
	· · · · · · · · · · · · · · · · · · ·	aintenance Director			Director for K374 Subdivision		
	acknowledged the smoke barrier doors did not				Building Space-Smoke Barrie	rs.	
	close completely and while looking that them				(Attachments #1 and #1a.)		
	noticed that they had been recently repainted, and				Harrist the same of the same to be a standard	41	
	the paint was rubbing at the top of the doors not				How other residents having		
	allowing them too fully close.				potential to be affected by the		
	This finding was reviewed with the Maintenance				same deficient practice will li identified and what corrective		
	Director only as the Executive Director was				action(s) will be taken:	e	
	unavailable at the time the exit conference dur to a				The identified set of smoke ba	arrier	
	prior engagement.				doors were repaired/adjusted,		
	prior engagement.				allowing them to close fully.		
	3.1-19(b)				(Attachments #2 and #2A).		
					What measures will be put ir	nto	
					place or what systemic		
					changes will be made to		
					ensure that the deficient		
					practice does not recur:	arriar	
					There were no other smoke be doors affected by the alleged	amer	
					deficient or identified during th	ne	
					survey. The Maintenance Dire		
					will ensure the smoke barrier		
					doors fully close monthly.		
					,,.		
					How will the corrective		
					action(s) will be monitored to	o	
					ensure the deficient practice		
					will not recur, i.e., what qual	- I	
					assurance program will be p	ut	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

BPXB21 Facility ID: 000414

If continuation sheet Page 3 of 4

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/28/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155436	X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 10/15/2024		
NAME OF PROVIDER OR SUPPLIER HICKORY CREEK AT WINAMAC			STREET ADDRESS, CITY, STATE, ZIP COD 515 E 13TH ST WINAMAC, IN 46996				
(X4) ID PREFIX TAG	(EACH DEFICIE)	STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		ΛΤΕ	(X5) COMPLETION DATE	
				into place: The Executive Director will more the two smoke barrier doors monthly to ensure they fully claccording to K 374 Subdivision Building Spaces – Smoke Barn Doors regulation. (Attachment If a threshold of 100% is not man action plan will be developed Findings will be submitted to the Quality Assurance and Performance Committee for reand follow-up.	ose n of rier t #3). net, ed.		

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: BPXB21 Facility ID: 000414 If continuation sheet Page 4 of 4