PRINTED: 05/29/2024

	OF HEALTH AND HUI						RM APPROVED
CENTERS FOR MEDICARE & MEDIC STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155333	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		OMB NO. 0938-039 (X3) DATE SURVEY COMPLETED 05/08/2024		
NAME OF I	PROVIDER OR SUPPLIEF	₹			ADDRESS, CITY, STATE, ZIP COD LONGEST ST		
PAOLI H	EALTH AND LIVING	G COMMUNITY		PAOLI	, IN 47454		
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE		ID		PROVIDER'S PLAN OF CORRECTION	(X5)	
PREFIX		ICY MUST BE PRECEDED BY FULL	PREFIX		(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		COMPLETION
TAG K 0000	REGULATORY OF	R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY		DATE
Bldg. 01	Code Recertificatio conducted on 03/12	000226	K 0	000	Reliable F3-56 Pendant 155 degree SR White were replace on 5/08/2024 by P.I.P.E INC. License #CP81062831. See attached documentation of the sprinkler heads that were replaced.		
	AIM Number: 100 At this PSR to the I Health and Living (in compliance with in Medicare/Medica Life Safety from Fi National Fire Protea Life Safety Code (I Health Care Occupa This one story facil determined to be of was sprinklered. The system with hard was corridors, spaces of resident sleeping rof furthermore, battery were located in all of	Life Safety Code survey, Paoli Community Inc. was found not Requirements for Participation aid, 42 CFR Subpart 483.90(a), re and the 2012 edition of the ction Association (NFPA) 101, LSC), Chapter 19, Existing ancies and 410 IAC 16.2. Type V (111) construction and the facility has a fire alarm fired smoke detectors in the common in the 400 and 500 halls, by operated smoke detectors other resident sleeping rooms. Tapacity of 109 and had a					

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

All areas where residents have customary access were sprinklered and all areas providing facility services were sprinklered, except two detached wood sheds and one metal shed used for facility

storage.

TITLE (X6) DATE

Marquetta Motsinger Administrator 05/22/2024

Any defiencystatement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: C77X22 Facility ID: 000226 If continuation sheet Page 1 of 3

PRINTED: 05/29/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER 155333	A. BUILDING <u>01</u> B. WING		COMPLETED 05/08/2024	
		100000			03/00/2024	
NAME OF P	ROVIDER OR SUPPLIER			ADDRESS, CITY, STATE, ZIP COD LONGEST ST		
PAOLI HI	EALTH AND LIVING	G COMMUNITY		IN 47454		
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION	(X5)	
PREFIX TAG		CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION	PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		COMPLETION DATE	
TAG	REGULATORT OR	LISC IDENTIFFING INFORMATION	IAG		DATE	
	Quality Review con	npleted on 05/10/24				
K 0351	NFPA 101					
SS=E	Sprinkler System -					
Bldg. 01	Spinkler System - Installation 2012 EXISTING					
		nd hospitals where required				
	by construction type	pe, are protected approved automatic				
		n accordance with NFPA				
	•	ne Installation of Sprinkler				
	Systems.					
	* *	nstruction, alternative				
	•	es are permitted to be				
		inkler protection in specific or local regulations prohibit				
	sprinklers.	or local regulations profilibit				
	•	klers are not required in				
		patient sleeping rooms				
		the closet does not exceed				
	•	sprinkler coverage covers				
	-	t as required by NFPA 13,				
	Standard for Insta Systems.	liation of Sprinkler				
		, 19.3.5.3, 19.3.5.4,				
		9.3.5.10, 9.7, 9.7.1.1(1)				
	Based on observation	on and interview, the facility	K 0351	Reliable F3-56 Pendant 155	05/08/2024	
		y one type of sprinkler head,		degree SR White were replace	ed	
		or standard sprinklers were		on 5/08/2024 by P.I.P.E INC.		
		noke compartments. NFPA 13, lation of Sprinkler Systems,		License #CP81062831. See		
		es where quick-response		attached documentation of the sprinkler heads that were	;	
		led, all sprinklers within a		replaced.		
	•	pe quick-response unless		'		
	_	in Section 8.3.3.3 Section				
		existing light hazard systems				
		e quick response or residential				
		klers in a compartmented space This deficient practice could				
	man oc changed. I	ms deficient practice could				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

C77X22

Facility ID: 000226

If continuation sheet

Page 2 of 3

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 05/29/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155333	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 05/08/2024			
NAME OF PROVIDER OR SUPPLIER PAOLI HEALTH AND LIVING COMMUNITY			STREET ADDRESS, CITY, STATE, ZIP COD 559 W LONGEST ST PAOLI, IN 47454					
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE			ID	DROWIDERIC BLAN OF CORRECTION	(X5)		
PREFIX	(EACH DEFICIEN	ICY MUST BE PRECEDED BY FULL	PROVIDER'S PLAN OF CORRECTION BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE CODES PREFERED TO THE ADDRESSMENT)		\TE	COMPLETION		
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATION		TAG	CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		DATE	
	affect at least 20 res	sidents, staff, and visitors.						
	Findings include:							
	Based on observations on 05/08/24 between 10:00							
	a.m. and 12:00 p.m. during a tour of the facility							
	with the Director of	f Environmental Services, the						
	front lounge near the entrance to the 300 hall was							
	open to the front lobby. The front lounge was							
	equipped with two quick response sprinkler heads							
	and the remainder of the sprinkler heads in the							
	front lobby were standard response sprinkler							
	heads.							
		at the time observation, this						
	was acknowledged	•						
		vices, and agreed there were a						
		t type sprinkler heads within						
	this compartmented	space.						
	_	viewed with the Director of vices during the exit						
	3.1-19(b)							
	_	rice was cited on 03/12/24. The plement a systemic plan of nt recurrence.						

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: C77X22 Facility ID: 000226 If continuation sheet Page 3 of 3