PRINTED: 12/04/2023

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES							FORM APPROVED OMB NO. 0938-039	
STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155270		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING			(X3) DATE SURVEY COMPLETED 11/01/2023			
NAME OF F	PROVIDER OR SUPPLIEI F DALE	ર		510 W	ADDRESS, CITY, STATE, ZIP COD MEDCALF ROAD IN 47523			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION			ID PREFIX TAG	PROVIDERS PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE		
E 0000 Bldg	Preparedness Survey conducted by the In accordance with 42 Survey Date: 11/0 Facility Number: (Provider Number: AIM Number: 100 At this PSR to the survey, Core of Da with Emergency Prepared and Suppliers, 42 Center of The facility has 60 the survey, the center of the survey of the su	200170 155270 287490 Emergency Preparedness le was found in compliance reparedness Requirements for icaid Participating Providers CFR 483.73. certified beds. At the time of	EO	000	Preparation and/or execution this plan do not constitute admission or agreement by the provider that a deficiency exist. This response is also not to be construed as an admission of by the facility, its employees, agents or other individuals where the discussed in the response and plan of correction. This plan of correction is submitted as the facility's creat allegation of compliance. The facility is requesting parcompliance for this tag.	ne e fault no his on.		
K 0000								
Bldg. 02	Code Recertification conducted on 08/29	isit (PSR) to the Life Safety on and State Licensure Survey 0/23 was conducted by the t of Health in accordance with	K 0	0000	Preparation and/or execution this plan do not constitute admission or agreement by the provider that a deficiency exist This response is also not to be construed as an admission of by the facility, its employees,	ie its. e		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Facility Number: 000170

Provider Number: 155270

AIM Number: 100287490

(X6) DATE

agents or other individuals who

draft or may be discussed in this

response and plan of correction.

submitted as the facility's credible

This plan of correction is

TITLE

Charles Brazzell Manager 11/23/2023

Any defiencystatement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: CU6622 Facility ID: 000170 If continuation sheet Page 1 of 5

PRINTED: 12/04/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA	(X2) M	(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER	A. BUILDING <u>02</u>		02	COMPLETED	
155270		B. WING 11/01/2023			/2023		
				STREET 4	ADDRESS, CITY, STATE, ZIP COD		
NAME OF PROVIDER OR SUPPLIER					MEDCALF ROAD		
CORE OF DALE					N 47523		
	Г	OT A TEMPLIT OF DEPLOYATION	1				OV.5
(X4) ID PREFIX		STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE		(X5) COMPLETION
TAG	·	CY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		PREFIX TAG	CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	DPRIATE DATE	
TAG		Life Safety Code survey, Core		TAU	allegation of compliance.		DATE
	of Dale was found i				The facility is requesting par	or	
	Requirements for P	-			compliance for this tag.		
	_	, 42 CFR Subpart 483.90(a),			compliance for this tag.		
		re and the 2012 edition of the					
		etion Association (NFPA) 101,					
		LSC), Chapter 19, Existing					
		ancies and 410 IAC 16.2.					
	1						
		ity was determined to be of					
	Type V (000) const	ruction and was fully					
	sprinklered. The fa	cility has a fire alarm system					
	with hard wired smoke detectors in the corridors and spaces open to the corridors, plus battery operated smoke alarms in all resident sleeping rooms. The facility has a capacity of 60 and had a						
	census of 38 at the t	time of this survey.					
	All areas where the	residents have customary					
		ered and all areas providing					
	facility services were sprinklered, except a						
detached laundry building.							
	, c						
	Quality Review completed on 11/02/23						
K 0374	NFPA 101						
SS=E	_	lding Spaces - Smoke					1
Bldg. 02	Barrie	•					
		lding Spaces - Smoke					
	Barrier Doors						
	2012 EXISTING						
	Doors in smoke ba	arriers are 1-3/4-inch thick					
	solid bonded wood-core doors or of						
	construction that resists fire for 20 minutes.						1
	Nonrated protective plates of unlimited height						1
	are permitted. Doors are permitted to have						
	fixed fire window assemblies per 8.5. Doors						
	1	automatic-closing, do not					
		nd are not required to swing					
	in the direction of	egress travel. Door opening					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

CU6622

Facility ID: 000170

If continuation sheet

Page 2 of 5

PRINTED: 12/04/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION (X3) D		(X3) DATE SURVEY	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER	A. BUILDING <u>02</u>		COMPLETED	
155270		155270	B. WING		11/01/2023	
NAME OF PROVIDER OR SUPPLIER			510 W	ADDRESS, CITY, STATE, ZIP COD MEDCALF ROAD		
CORE O	F DALE		DALE,	IN 47523		
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION	(X5)	
PREFIX	`	ICY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA		
TAG		R LSC IDENTIFYING INFORMATION	TAG	DEFICIENCY)	DATE	
	l ·	um clear width of 32 inches				
	for swinging or ho					
	19.3.7.6, 19.3.7.8	, 19.3.7.9 on and interview, the facility	V 0274	Propagation and/or execution	of 12/27/2022	
		f 3 sets of smoke barrier doors	K 0374	Preparation and/or execution	of 12/27/2023	
		etely to form a smoke resistant		this plan do not constitute admission or agreement by th	_	
	_	on 19.3.7.8 requires that doors		provider that a deficiency exis		
		hall comply with LSC, Section		This response is also not to be		
		n 8.5.4.1 requires doors in smoke		construed as an admission of		
		opening leaving only the		by the facility, its employees,		
		e necessary for proper operation		agents or other individuals wh	0	
	which is defined as 1/8 inch to restrict the			draft or may be discussed in t		
		e. This deficient practice could		response and plan of correction		
		sidents, as well as staff and		This plan of correction is		
	visitors.			submitted as the facility's cred	lible	
				allegation of compliance.		
	Findings include:			The facility is requesting par	per	
				compliance for this tag.		
		ons on 11/01/23 between 9:30				
		during a tour of the facility		1 Immediate action(s) take		
		ce Supervisor, the set of		for the resident(s) found to ha	ve	
		s between the 100 Unit and the		been affected include:		
		not close completely when		Maintenance staff had previou	•	
		a eight inch gap between the		identified the problem with the		
	entire length of the doors when closed fully. The			smoke barrier door on the 100		
	north side door was damaged at the top portion			and an order for the doors wa		
	on the hinge side of the door. This was acknowledged by the Maintenance Supervisor at			placed on 8/25/23, prior to Life Safety survey. The invoice/ord		
	the time of observation, who further said this set			was given to surveyor at the ti		
	of smoke barrier doors are going to be replaced			of survey, The facility is still		
	when the new smoke barrier doors are delivered,			awaiting delivery and installati	on of	
		to be in mid November.		the doors as of this plan of	J. J.	
	This finding was reviewed with the Maintenance			correction submission due to	the	
				supply chain on materials. Em		
	Supervisor during t			were sent for an updated		
				estimated time of		
	This deficient pract	ice was cited on 08/29/23. The		delivery/installation which is s	till	
	facility failed to implement proper corrective action.			currently 11/30/23. Upda		
				smoke Barrier Doors will be		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

CU6622

Facility ID: 000170

If continuation sheet

repaired on 11/22/2023 with metal

Page 3 of 5

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/04/2023 FORM APPROVED OMB NO. 0938-039

OE. (TEMS 1 01)	T OF PERSONNESS	Later De Carres (carres (carres)			NAME AND ADDRESS OF THE PARTY O	G	2110101000
		X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER	A. BUILDING <u>02</u>		02	COMPLETED	
	155270 B. WING 11/0 ²		11/01/	/2023			
NAME OF PROVIDER OR SUPPLIER CORE OF DALE			STREET ADDRESS, CITY, STATE, ZIP COD 510 W MEDCALF ROAD DALE, IN 47523				
(VA) ID	CIDANADY	CTATEMENT OF DEFICIENCIE	1	ID			(7/5)
(X4) ID		STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE		(X5)
PREFIX	`	CY MUST BE PRECEDED BY FULL		PREFIX	CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	.TE	COMPLETION
TAG		R LSC IDENTIFYING INFORMATION	-	TAG			DATE
	3.1-19(b)				plates so doors close properly		
					The doors will still be replaced		
					soon as possible. Estimated to	o be	
					around 12/27/2023		
					2 Identification of other		
					residents having the potential	to	
					be affected was accomplished	l by:	
					The facility has determined that	at all	
					residents have the potential to be		
					affected.		
					3 Actions taken/systems	put	
					into place to reduce the risk	-	
					future occurrence include:		
					Maintenance staff had previou	ıslv	
					identified the problem with the	-	
					smoke barrier door on the 100		
					and an order for the doors was		
					placed on 8/25/23, prior to the		
					Safety survey. The invoice/ord		
					was given to surveyor at the ti	me	
					of survey, The facility is still		
					awaiting delivery and installati	on of	
					the doors as of this plan of		
					correction submission due to t		
					supply chain on materials. Em	ails	
					were sent for an updated		
					estimated time of		
					delivery/installation which is st	ill	
					currently 11/30/23. Updated	ł	
					delivery date 12/27/2023 Lynn	1	
					Norman of ADA Automated De	oors	
					Stated that the factory change	;d	
					the delivery date again. He als	30	
					stated that he could repair the		
					existing smoke barrier doors to		
					close properly using metal pla		
					to secure the hinge. He will re		
					the doors on 11/22/2023 so th	-	
					they close properly. Fire doors		
					be replaced as soon as possib		
			1		I ne rehiacen as soon as hossir	лG.	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

CU6622

Facility ID: 000170

If continuation sheet

Page 4 of 5

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/04/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155270	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 11/01/2023		
NAME OF PROVIDER OR SUPPLIER CORE OF DALE			STREET ADDRESS, CITY, STATE, ZIP COD 510 W MEDCALF ROAD DALE, IN 47523				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	ATE	(X5) COMPLETION DATE	
	ALGOLATORI O			4 How the corrective action(s) will be monitored to ensure the practice will not recur: Maintenance did conduct fire drills daily until fire doors were repaired and functioning proper Updated ADA Door Systems repaired the Smoke Barrier Doon 11/22/23 and they are closs properly. The maintenance director will complete 5 audits a week for important to ensure all smoke barrier doors are maintained it good condition and working on Thereafter, maintenance direct will complete 1 weekly audit for months and then one monthly ongoing to ensure doors remain compliance. The facility will ensure smoke barrier doors close properly to the passage of smoke or flame. Ongoing, the Administrator and designee will monitor smoke barrier doors to ensure continuous compliance. Audit records will be reviewed the monthly Quality Assurance. Committee until such a time consistent substantial complianas been achieved as determine by the committee. Corrective action completion of 12/27/23	e e e e e e e e e e e e e e e e e e e		

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: CU6622 Facility ID: 000170 If continuation sheet Page 5 of 5