STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CO	ONSTRUCTION	(X3) DATE SURVEY	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER	A. BUILDING		COMPLETED	
		155198	B. WING		02/25/2025	
	PROVIDER OR SUPPLIE	R	8140 T	ADDRESS, CITY, STATE, ZIP COD OWNSHIP LINE RD		
MARQUI	=11E		INDIAN	NAPOLIS, IN 46260		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CORRECTION	(X5)	
PREFIX		NCY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA		
TAG	REGULATORY O	R LSC IDENTIFYING INFORMATION	TAG	DEFICIENCY)	DATE	
E 0000						
Bldg						
Blug.		eparedness Survey was ndiana Department of Health in 2 CFR 483.73.	E 0000			
	Survey Date: 02/2:	5/25				
	Facility Number: 000105 Provider Number: 155198 AIM Number: N/A					
	Marquette was fou Emergency Prepar	Preparedness survey, nd in compliance with edness Requirements for licaid Participating Providers CFR 483.73.				
	The facility has 57 the survey, the cen	certified beds. At the time of sus was 54.				
	Quality Review co	mpleted on 02/27/25				
K 0000						
Bldg. 01						
	Licensure Survey	e Recertification and State was conducted by the Indiana alth in accordance with 42 CFR	K 0000	The preparation and implementation of this plan of correction does not constitute admission or agreement by Marquette regarding the accu of the facts alleged in this statement of deficiencies and	racy	
	Facility Number: (000105		of correction. Rather, this plan	-	
	Provider Number:			submitted solely to comply with		
	AIM Number: N/A	L		state and federal requirement Marquette reserves the right t	S.	
		Code survey, Marquette was		contest, through legal		
	found not in comp	liance with Requirements for		proceedings, any deficiencies	,	
LABORATOF	RY DIRECTOR'S OR PRO	OVIDER/SUPPLIER REPRESENTATIVE'S S	IGNATURE	TITLE	(X6) DATE	

Jeffrey Cox Administrator 03/13/2025

Any defiency statement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable

Any defiencystatement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclodays following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: E0PK21 Facility ID: 000105 If continuation sheet Page 1 of 12

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155198		A. BUILDING <u>01</u> CO		(X3) DATE SURVEY COMPLETED 02/25/2025	
NAME OF P	ROVIDER OR SUPPLIER		8140 T	ADDRESS, CITY, STATE, ZIP COD OWNSHIP LINE RD IAPOLIS, IN 46260	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
	483.90(a), Life Safe edition of the Nation (NFPA) 101, Life S	dicare, 42 CFR Subpart ety from Fire and the 2012 anal Fire Protection Association afety Code (LSC), Chapter 19, e Occupancies and 410 IAC		statements, findings, facts, or conclusions underlying the cite deficiency. This plan of correct serves as an allegation of compliance.	
	determined to be of was fully sprinklere system with smoke all areas open to the smoke detectors har system installed in a The facility has a ca of 54 at the time of	dents have customary access Il areas providing facility dered.		Marquette respectfully reques desk review of the following ite	
K 0321 SS=E Bldg. 01	NFPA 101 Hazardous Areas	- Enclosure			
-	failed to ensure the hazardous areas, such rooms over 50 squal boiler rooms, were provided with small deficient practice of and 2 visitors. Findings include:	on and interview, the facility corridor door to 1 of 6 ch as combustible storage re feet, soiled linen rooms, and provided with self-closing d cause the doors to and latch into the door frames toke resistant partitions. This buld affect 14 residents, 4 staff	K 0321	1. What corrective action will be accomplished for those residents found to have been affected by the deficient practice? No residents were directly affected by this deficiency. However, immediately following the surve a hinge spring self-closing device was installed on the medical records storage room door to ensure compliance with NFPA 101 requirements for hazardous areas.	n ected vey,

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

E0PK21 Facility ID: 000105

If continuation sheet

Page 2 of 12

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE	CONSTRUCTION	(X3) DATE SURVEY		
AND PLAN OF CORRECTION IDENTIFICATION NUMBE		IDENTIFICATION NUMBER	A. BUILDING <u>01</u>		COMPLETED	
	155198		B. WING 02/25/2025			
			STREE	T ADDRESS, CITY, STATE, ZIP COD		
NAME OF I	PROVIDER OR SUPPLIE	IR.		TOWNSHIP LINE RD		
MARQUI	ETTE			ANAPOLIS, IN 46260		
WAINQUI			INDIA			
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CORRECTION	(X5)	
PREFIX	(EACH DEFICIE	NCY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI	ATE COMPLETION	
TAG		R LSC IDENTIFYING INFORMATION	TAG	DEFICIENCY)	DATE	
	_	at 11:55 a.m. with the Health		2. How will other residents		
		r, the medical records storage		having the potential to be		
		d floor had numerous boxes		affected by the same deficie	ent	
		records stored throughout the		practice be identified, and		
		neasured approximately 20 feet		what corrective action will be	oe e	
	1 -	tained enough combustible files		taken?		
	_	considered a hazardous room.		14 residents, 4 staff, and 2 vi		
		r to the medical records storage		could potentially be impacted	-	
		a self-closing device attached		the alleged deficient practice		
		interview at the time of the		Immediately following the sur	-	
		ealth Care Administrator		a hinge spring self-closing de		
		have a self-closing device or		was installed on the identified	d door	
		loser added to the door as soon		-compliant with NFPA 101.		
	as possible.			3. What measures will be pu		
				into place, or what systemic	;	
		sussed again with the Health		changes will be made to		
		r at the exit conference on		ensure that the deficient		
	02/25/25.			practice does not recur?		
	2.1.10(1)			The following systemic cha	_	
	3.1-19(b)			will be implemented to ensure		
				the alleged deficient practice	does	
				not recur:		
				·A hinge spring self-clos	-	
				device has been installed on	tne	
				identified door.	:11	
				·Facility management w		
				implement a Hazardous Area		
				Storage and Safety Compliar		
				Policy that complies Life Safe	•	
				Code (NFPA 101) - see attac		
				will be provided to facility Hea	·	
				Center Plant staff highlighting		
				requirements for NFPA 101 -		
				Hazardous Areas – Enclosur		
				Including proper storage and		
				compliance (see attached).	4001	
				·The Plant Director or		
				designee will inspect the		
				identified hazardous storage	area	
Ī			1	I racinina nazarabus sibrage	urva	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

E0PK21 Facility ID: 000105

If continuation sheet Page 3 of 12

	OF CORRECTION	IDENTIFICATION NUMBER 155198	A. BUILDING B. WING	01	COMPLETED 02/25/2025
NAME OF F	PROVIDER OR SUPPLIEF		8140 T	ADDRESS, CITY, STATE, ZIP COD OWNSHIP LINE RD JAPOLIS, IN 46260	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
				to ensure compliance with Life Safety Code regulations (see below for details). 4. How will the corrective action be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be printo place? The Plant Director or designee will conduct and document audit inspections of the identified hazardous storateria, ensuring that the hinge spring self-closing device on the door is operational. These audits will occur week for four weeks, bi-weekly for foweeks, and then monthly for a total duration of six months. Findings will be reviewed in facility's Quality Assurance and Performance Improvement meeting to ensure ongoing compliance. Any non-compliance issues be addressed immediately, and retraining will be provided as needed. 5. Compliance Date: 3/25/25	re t ut of ge he ekkly bur the nd
K 0324 SS=E Bldg. 01	NFPA 101 Cooking Facilities				
	failed to provide an returning cooking a when the kitchen ho was designed and in	on and interview, the facility approved method for ppliances to where they were nod extinguishing equipment astalled for 1 of 1 kitchen hood m. NFPA 96, Standard for	K 0324	What corrective action will be accomplished for those residents found to have been affected by the deficient practice? No residents were affected by	1

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

E0PK21

Facility ID: 000105

If continuation sheet

Page 4 of 12

PRINTED: 03/14/2025 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155198		A. BU	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 02/25/2025			
NAME OF PROVIDER OR SUPPLIER MARQUETTE				STREET ADDRESS, CITY, STATE, ZIP COD 8140 TOWNSHIP LINE RD INDIANAPOLIS, IN 46260				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	(X5) COMPLETION DATE	
TAG	Ventilation Control Commercial Cooking Edition Section 12. requiring protection or rearranged without fire-extinguishing so or servicing agent, the design of the fire-extinguishing so or servicing agent, the design of the fire-extinguishing so or servicing agent, the design of the fire-extinguishing so or servicing agent, the design of the fire-extinguishing section 12.1.2.3 states system shall not recooking appliances are return location prior to condisconnected fire-extinguishing accordance with the manual. Section 12 method shall be propliance is returned location. The deficit many as 22 resident facility. Findings include: Based on observating facility with the Heromany and the flat grill which under the hood in the with an approved in the appliance was relocation after it had and/or cleaning. But the observation, the stated that he was reshould be provided was returned to an	and Fire Protection of ng Operations Section 2011 1.2.2, states cooking appliances in shall not be moved, modified, but prior re-evaluation of the system by the system installer unless otherwise allowed by re extinguishing system. It is the fire-extinguishing quire reevaluation where the are moved for the purposes of eaning, provided the med to approved design oking operations, and any extinguishing system nozzles iances are reconnected in the manufacturer's listed design and approved design ovided that will ensure that the red to an approved design ent practice could affect as tas, 6 staff, and 2 visitors in the state of the extinguishing system nozzles iances are reconnected in the manufacturer's listed design and the could be stated to an approved design the state of the extinct of the salth Care Administrator on the six (6) burner stove and was located on the cooking line me kitchen was not provided the extinct of the moved for maintenance and the cooking line method that would ensure that the time of the Health Care Administrator and the cooking line moved for maintenance and proved design location after an approved location after an approved location after an approved loc		IAU	alleged deficient practice. However, to ensure compliance and safety, the facility has installed an approved appliant positioning system (floor-mounted positioning devito guarantee that the six-burned stove and flat grill are always returned to their designated locations under the hood suppression system after clear or maintenance. 2. How will other residents having the potential to be affected by the same deficient practice be identified, and what corrective action will be taken? This alleged deficient practice could affect as many as 22 residents, 6 staff, and 2 visitor the event of a fire. To prevent risk: A review of all commercial cooking equipment under fire suppression systems was conducted to verify compliance. The kitchen appliances requiring designated placement have been assessed, and corrective measures have been taken where necessary – inclute installation of approved appliance positioning systems (see attached image of correct measures). 3. What measures will be put into place, or what systemic changes will be made to ensure that the deficient	nice rice) er ning nt s in this e. nt n ding	DATE	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

E0PK21

Facility ID: 000105

If continuation sheet

Page 5 of 12

PRINTED: 03/14/2025 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155198		(X2) MULTIPLE C A. BUILDING B. WING	construction 01	(X3) DATE SURVEY COMPLETED 02/25/2025		
NAME OF P	ROVIDER OR SUPPLIER		8140 7	ADDRESS, CITY, STATE, ZIP COD FOWNSHIP LINE RD NAPOLIS, IN 46260		
(X4) ID PREFIX		STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL	ID PREFIX	PROVIDER'S PLAN OF CORRECTION		
TAG		LISC IDENTIFYING INFORMATION The kitchen stove or floor to	TAG	practice does not recur?	DATE	
	_	nce as soon as possible.		·The following systemic cha	-	
	This item was discu	assed again with the Health at the exit conference on		will be implemented to ensure the alleged deficient practice on trecur: The facility has installed an approved appliance positioning system (floor-mounted position device) to guarantee that the six-burner stove and flat grill a always returned to their designated locations under the hood suppression system following movement (cleaning/maintenance). Facility management will implement a Cooking Equipm Safety and Compliance Police that complies with Life Safety Code (NFPA 96/101) - see attached. Education/in-service trainwill be provided to facility Hear Center Plant and Kitchen staff highlighting the requirements NFPA 101 – Cooking Facilities Including proper equipment placement, and how to confirm that appliances are in their compositions before cooking operations occur. The Plant Director or designee will routinely inspect the identified cooking facility the ensure the appliance position systems are in working order in-compliance with Life Safety Code regulations (see below the details).	e that does g ning are e II nent cy ining lth f for s. m rrect t o ing and	
			1	4. How will the corrective		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

E0PK21

Facility ID: 000105

If continuation sheet

Page 6 of 12

PRINTED: 03/14/2025 FORM APPROVED OMB NO. 0938-039

	OF CORRECTION	IDENTIFICATION NUMBER 155198	A. BUILDING B. WING	01	COMPLETED 02/25/2025
NAME OF PROVIDER OR SUPPLIER MARQUETTE		STREET ADDRESS, CITY, STATE, ZIP COD 8140 TOWNSHIP LINE RD INDIANAPOLIS, IN 46260			
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
				action be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be pinto place? The Plant Director or design will conduct audit inspections kitchen equipment placement ensure compliance with Life Safety standards. This audit will occur weekly four weeks, bi-weekly for four weeks, and then monthly for a total duration of six months. An audit checklist has bee implemented for staff to verify proper appliance positioning a each cleaning or maintenance session (see attached). Compliance will be reviewed the facility's Quality Assurance and Performance Improvement Meeting, and any issues will be addressed immediately with additional training or corrective actions. 5. Compliance Date: 3/25/25	t ut gnee s of and for n fter ce ent pe
K 0351 SS=E Bldg. 01	NFPA 101 Sprinkler System				
	failed to maintain the central supply office Standard for the Instance NFPA 13, 2010 edited plates, escutcheons, cover the annular special be metallic, or shall	on and interview, the facility the ceiling construction in 1 of 1 the in accordance with NFPA 13, ttallation of Sprinkler Systems. tion, Section 6.2.7.1 states or other devices used to bace around a sprinkler shall the listed for use around a cient practice could affect staff	K 0351	1. What corrective action will be accomplished for those residents found to have been affected by the deficient practice? No residents were affected by alleged deficiency. However, to escutcheon around the sprinkly head was immediately repaired.	the che

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

E0PK21

Facility ID: 000105

If continuation sheet

Page 7 of 12

03/14/2025 PRINTED:

	I OF HEALTH AND HU! R MEDICARE & MEDIC				FORM APPROVED OMB NO. 0938-039
	NT OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE C	CONSTRUCTION	(X3) DATE SURVEY
AND PLAN OF CORRECTION IDENTIFICATION NUMBER		A. BUILDING 01		COMPLETED	
		155198	B. WING	_ 	02/25/2025
			STREET	ADDRESS, CITY, STATE, ZIP COD	
NAME OF I	PROVIDER OR SUPPLIER	8		TOWNSHIP LINE RD	
MARQUI	ETTE			NAPOLIS, IN 46260	
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CORRECTION	(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	COMPLETION
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATION	TAG	DEFICIENCY)	DATE
	and up to 1 resident	t, 2 staff and 1 visitor.		ensuring the annular space ar	ound
				the sprinkler head is correctly	
	Findings include:			sealed in compliance with NFI	PA
				13 standards.	
		ons with the Health Care		2. How will other residents	
		2/25/25 at 11:17 p.m., the central		having the potential to be	
		loose escutcheon with		affected by the same deficien	nt
		quarter inch gap of annular		practice be identified, and	
	-	orinkler head. Based on		what corrective action will be	9
		e of observation, the Health		taken?	
		acknowledged the annular		1 resident, 2 staff, and 1 visito	
	space at the escutch			the facility could potentially be	
		asurement, and called a		impacted if the identified fire	
		look into fixing the		suppression system is not	
	escutcheon as soon	as possible.		functioning correctly. To ensur	re
		1 1 14 4 77 14		safety:	
		assed again with the Health		The identified deficiency wa	
		at the exit conference on		corrected immediately to meet	
	02/25/25.			standards set by NFPA 13. Th	
	2 1 10(%)			escutcheon identified during the	
	3.1-19(b)			survey has been repaired (see	†
				attached image). •A facility-wide inspection	will
				be conducted to check all	VVIII
				sprinkler heads for any gaps of	nr
				improperly fitted escutcheons.	
				3. What measures will be put	
				into place, or what systemic	
				changes will be made to	
				ensure that the deficient	
				practice does not recur?	
				·The following systemic char	nges
				will be implemented to ensure	
				the alleged deficient practice of	
				not recur:	
				·The escutcheon identifie	ed
				during the survey has been	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

E0PK21

Facility ID: 000105

repaired (see attached image). ·Education/in-service training will be provided to Health

If continuation sheet

Page 8 of 12

PRINTED: 03/14/2025 FORM APPROVED OMB NO. 0938-039

	OF CORRECTION	IDENTIFICATION NUMBER 155198	A. BUILDING B. WING	01	COMPLETED 02/25/2025
NAME OF P	ROVIDER OR SUPPLIER ETTE		8140 T	ADDRESS, CITY, STATE, ZIP COD OWNSHIP LINE RD IAPOLIS, IN 46260	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
				Center Plant staff highlighting NFPA 13 standards, particular focusing on the community's policy for ensuring proper installation and maintenance of sprinkler system escutcheons. The Plant Director or designee will routinely audit/inspect sprinkler heads are escutcheon's throughout facility ensure compliance with Life Safety Code regulations (see below for details). 4. How will the corrective action be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be pinto place? The Plant Director or designee will conduct audit inspections of all sprinkler he and escutcheons in the facility. This audit will occur weekly four weeks, bi-weekly for four weeks, and then monthly for a total duration of six months. An audit checklist has bee implemented for Plant staff to verify proper positioning and installation of escutcheons. Compliance will be reviewed the facility's Quality Assurance and Performance Improvemented Meeting, and any issues will be addressed immediately with additional training or corrective actions. 5. Compliance Date: 3/25/25	of and ty to re t ut ads / for n d in ce ent pe

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

E0PK21 Facility ID: 000105

If continuation sheet

Page 9 of 12

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155198		a. building <u>01</u> co		(X3) DATE SURVEY COMPLETED 02/25/2025	
NAME OF I	PROVIDER OR SUPPLIER		8140 T	ADDRESS, CITY, STATE, ZIP COD TOWNSHIP LINE RD NAPOLIS, IN 46260	
	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION NFPA 101 Fire Drills Based on record review and interview, the facility failed to conduct quarterly fire drills for 1 of 4 quarters. LSC 19.7.1.6 requires drills to be conducted quarterly on each shift under varied conditions. This deficient practice affects all staff and residents. Findings include: Based on record review of the documentation entitled "Fire Drill" form with the Health Care Administrator on 02/25/25 at 9:32 a.m., there was no documentation for a third shift fire drill being conducted in the second quarter (April, May, and June) of 2024. Based on interview at the time of record review, the Health Care Administrator acknowledged the aforementioned fire drill as not				DATE O3/25/2025 octed oty, a ted, uded nally
		ssed again with the Health at the exit conference on		affected by the same deficient practice be identified, and what corrective action will be taken? All residents, staff, and visitors the facility could potentially be affected by fire evacuation procedures. To prevent recurred a review of the fire drill scheduling process has been conducted to ensure that all required drills will be complete each shift for the current and future quarters. Additionally, a schedule reminder for the required drills has been programmed into the community's work ordereminder system. 3. What measures will be put	e s in ence: n ed on elired ed ed er

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

E0PK21 Facility ID: 000105

If continuation sheet

Page 10 of 12

03/14/2025 PRINTED: FORM APPROVED OMB NO. 0938-039

CENTERS FOR MEDICARE & MEDICAID SERVICES STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X2) MULTIPLE CONSTRUCTION X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER A. BUILDING COMPLETED 01 B. WING 02/25/2025 155198 STREET ADDRESS, CITY, STATE, ZIP COD NAME OF PROVIDER OR SUPPLIER 8140 TOWNSHIP LINE RD **MARQUETTE** INDIANAPOLIS, IN 46260 (X4) ID SUMMARY STATEMENT OF DEFICIENCIE ID (X5) PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX PREFIX COMPLETION (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG DEFICIENCY) DATE into place, or what systemic changes will be made to ensure that the deficient practice does not recur? The following systemic changes will be implemented to ensure that the alleged deficient practice does not recur: ·A schedule and reminder **system** has been implemented to ensure fire drills are conducted on time for all shifts each quarter (via community's work order tracking/reminder system). ·Education/in-service training will be provided to Health Center Plant staff highlighting the policy requirements for fire drill scheduling and compliance (see attached policy and in-service) ·The Health Care Administrator and Plant **Director** will audit/review fire drill schedules and documentation to ensure that drills are conducted as required (see below for details of audit). 4. How will the corrective action be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be put into place? ·The Plant Director or

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

E0PK21

Facility ID: 000105

If continuation sheet

designee will conduct audit inspections of all fire drill records to ensure that all shifts have completed the required drills. ·This audit will occur bi-monthly (every two months - prior to end of

Page 11 of 12

PRINTED: 03/14/2025 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTI		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155198	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 02/25/2025		
		155196	b. wind		02/23/	2025	
NAME OF PROVIDER OR SUPPLIER MARQUETTE			STREET ADDRESS, CITY, STATE, ZIP COD 8140 TOWNSHIP LINE RD INDIANAPOLIS, IN 46260				
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	(EACH DEFICIEN	ICY MUST BE PRECEDED BY FULL	PREFIX			COMPLETION	
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATION	TAG			DATE	
				each quarter) for a total duration twelve months. An audit checklist has been implemented for Plant Director verify completion of fire drills. Compliance will be reviewed the facility's Quality Assurance and Performance Improvement Meeting, and any issues will be addressed immediately with additional training or corrective actions. 5. Compliance Date: 3/25/25	n r to d in ce ent		

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: E0PK21 Facility ID: 000105 If continuation sheet Page 12 of 12