PRINTED: 11/09/2023

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES							FORM APPROVED OMB NO. 0938-039	
STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155237		(X2) MULT A. BUILI B. WING	DING	NSTRUCTION	(X3) DATE SURVEY COMPLETED 10/24/2023			
	PROVIDER OR SUPPLIEF	3	3	518 S	.DDRESS, CITY, STATE, ZIP COD SHELBY ST APOLIS, IN 46227			
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	PR	D EFIX 'AG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	кТЕ	(X5) COMPLETION DATE	
E 0000 Bldg	0000		E 0000		Disclaimer: The creation and submission of this Plan of Correction does not constitute an admission by this provider of any conclusion set forth in the statement of deficiencies, or of any violation of regulation. This provider respectfully requests that this 2567 Plan of Correction be considered the Letter of Credible Allegation of Compliance and requests a desk review in lieu of annual survey review on or after November 6th, 2023.			
K 0000 Bldg. 01	the survey, the cens Quality Review con A Life Safety Code Licensure Survey w Department of Hea 483.90(a). Survey Date: 10/24 Facility Number: 0 Provider Number: AIM Number: 100	Recertification and State vas conducted by the Indiana lth in accordance with 42 CFR 4/23 100142 155237	K 0000	0	Disclaimer: The creation and submission this Plan of Correction does constitute an admission by t provider of any conclusion s forth in the statement of deficiencies, or of any violat of regulation. This provider respectfully requests that this 2567 Plan Correction be considered the Letter of Credible Allegation	not this set ion of		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

was found not in compliance with Requirements

(X6) DATE

Compliance and requests a

TITLE

KAVITA BERI **HFA** 11/06/2023

Any defiencystatement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: EQ3C21 Facility ID: 000142 If continuation sheet Page 1 of 19

PRINTED: 11/09/2023 FORM APPROVED OMB NO. 0938-039

	IT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155237	ľ í	UILDING	onstruction 01	(X3) DATE COMPL 10/24/	ETED
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP COD 3518 S SHELBY ST INDIANAPOLIS, IN 46227			
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OR	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	(X5) COMPLETION DATE
	Subpart 483.90(a), 2012 Edition of the Association (NFPA and 410 IAC 16.2. 0202, the Therapy F 2012, were each sur Existing Health Car				desk review in lieu of annual survey review on or after November 6th, 2023.		
	building of Type V(0101 was determined construction and full was determined to be construction and full a fire alarm system corridors and in all The facility has smo- fire alarm system in	lly sprinklered. The facility has with smoke detection in the areas open to the corridor. Oke detectors hard wired to the istalled in all resident sleeping has a capacity of 100 and had					
	were sprinklered an	idents have customary access d all areas providing facility klered, except for one detached appleted on 10/25/23					
K 0321 SS=E Bldg. 01	barrier having 1-he (with 3/4 hour fire automatic fire exting accordance with 8 approved automate option is used, the						

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet Page 2 of 19

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	JILDING	01	COMPL	LETED
		155237	B. W	ING _		10/24	/2023
				STREET	ADDRESS, CITY, STATE, ZIP COD		
NAME OF F	PROVIDER OR SUPPLIEF	₹			SHELBY ST		
BETHAN	Y VILLAGE				IAPOLIS, IN 46227		
	Г				T		ı
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	`	ICY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG		R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	· ·	ors in accordance with 8.4.					
	Doors shall be sel	_					
	_	and permitted to have					
		applied protective plates that					
		inches from the bottom of					
	the door.	and zone legations of					
		and zone locations of					
	nazardous areas i REMARKS.	that are deficient in					
	19.3.2.1, 19.3.5.9						
	19.3.2.1, 19.3.3.9						
	Area	Automatic Sprinkler					
	Separation	-					
		-Fired Heater Rooms					
		er than 100 square feet)					
		nance, and Paint Shops					
		ooms (exceeding 64					
	gallons)	(
	e. Trash Collectio	n Rooms					
	(exceeding 64 gal	llons)					
	1 '	orage Rooms/Spaces					
	(over 50 square fe	eet)					
	g. Laboratories (if	classified as Severe					
	Hazard - see K32	2)					
	Based on observation	on and interview, the facility	K 0	321	POC for tag 321		11/06/2023
		f 11 hazardous areas such as a			SS-E		
		was separated from other					
		sistant partitions and doors.			What corrective action(s) wil	II	
		closing or automatic closing in			be accomplished for those		
		SC 7.2.1.8. This deficient			residents found to have been	n	
	_	et 20 residents, staff and			affected by the deficient		
		ity of the Soiled Utility room			practice?		
	near the Moving Fo	orward nurse's station.					
	Findings in alud-				The corridor door to the soiled		
	Findings include:				utility room across the hall from		
	Rosed on absorbed	on with the Maintenance			moving forward nurses' station		
		on with the Maintenance ntenance Supervisor and			the soiled utility room doors a	e	
	· ·	•			now both fixed.		
		during a tour of the facility :30 p.m. on 10/24/23, the corridor					
	_ 110111 1.13 p.111. t0 2		1		İ		1

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet Page 3 of 19

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA			(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY				
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. B	UILDING	<u>01</u>	COMPL	
		155237	B. W	ING		10/24/	2023
	PROVIDER OR SUPPLIER		•	3518 S	ADDRESS, CITY, STATE, ZIP COD SHELBY ST APOLIS, IN 46227		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE	1	ID		CTION (X5)	
PREFIX		CY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA		COMPLETION
TAG	``	LSC IDENTIFYING INFORMATION		TAG	CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	IE	DATE
	the Moving Forward with a self-closing of latch into the door of separate times. After did not positively lautility room contain soiled articles and a full of articles. Based observation, the Mandaintenance Supervision.	d nurse's station was equipped device but the door failed to frame when tested three er swinging to close, the door teth into the frame. The soiled ed a 55 gallon container full of 45 gallon container partially ed on interview at the time of cintenance Director and Field wisor confirmed the corridor			how other residents having to potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken. All residents have the potential be affected by the alleged definition practice. All the facility doors we audited to ensure that all door are latching appropriately with	e e il to icient vere s	
	door to the aforementioned hazardous area failed to latch into the door frame after self closing.				self-closing device.		
	Director, Field Main	viewed with the Executive intenance Supervisor and or at the exit conference.			What measures will be put in place and what systemic changes will be made to ensure that the deficient practice does not recur. Maintenance director/designed conduct an audit every two we to ensure that all the doors are latched into the door frame wit self-closing device. If any deficient practice is identified, then the Maintenance director/designed immediately fix the door.	e will eeks e th cient	
					how the corrective action(s) will be monitored to ensure to deficient practice will not recur, i.e., what quality assurance program will be printo place; and Maintenance director /designation will be responsible for the completing the audit biweekly	ut ee	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet Page 4 of 19

PRINTED: 11/09/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) M	(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	A. BUILDING <u>01</u>			COMPLETED	
		155237	B. W	ING		10/24/	2023	
			-	STREET A	ADDRESS, CITY, STATE, ZIP COD	<u> </u>		
NAME OF P	ROVIDER OR SUPPLIER				SHELBY ST			
BETHAN'	Y VILLAGE			INDIANAPOLIS, IN 46227				
(X4) ID	SUMMARY S	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPR		TE	COMPLETION	
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY		DATE	
K 0351 SS=E Bldg. 01	NFPA 101 Sprinkler System - Spinkler System - 2012 EXISTING Nursing homes, and	· Installation Installation and hospitals where required		140	weeks, monthly for 6 months at then quarterly to ensure all the doors are latching into door frawith self-closing device. The results of these audits will be reviewed by the committee overseen by the ED. If the threshold of 95% is not achieved an action plan will be developed ensure compliance. Deficiency will be completed by November 6th, 2023.	e ame red ed to	DATE	
		n accordance with NFPA ne Installation of Sprinkler						
	In Type I and II co	nstruction, alternative es are permitted to be						
	areas where state	inkler protection in specific or local regulations prohibit						
	sprinklers. In hospitals, sprink	klers are not required in						
		patient sleeping rooms						
		the closet does not exceed						
	6 square feet and	sprinkler coverage covers						

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet

Page 5 of 19

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155237		A. BU	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 10/24/2023		
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 3518 S SHELBY ST INDIANAPOLIS, IN 46227				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	1	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	IATE	(X5) COMPLETION DATE
	Standard for Insta Systems. 19.3.5.1, 19.3.5.2, 19.3.5.5, 19.4.2, 1 Based on observation failed to maintain the Baths in accordance the Installation of S 2010 edition, Section escutcheons, or othe annular space around or shall be listed for deficient practice corresidents and staff in compartment. Findings include: Based on observation Director, Field Main Executive Director Bath located near the with an escutcheon exposed the attic spansing the attic spansing the attic spansing the attic spansing or had falled exposing the attic spansing th	t as required by NFPA 13, llation of Sprinkler 19.3.5.3, 19.3.5.4, 9.3.5.10, 9.7, 9.7.1.1(1) on and interview, the facility are ceiling construction in 1 of 3 to with NFPA 13, Standard for prinkler Systems. NFPA 13, on 6.2.7.1 states plates, or devices used to cover the add a sprinkler shall be metallic, to use around a sprinkler. This bould affect staff and up to 24 on the 500 & 600 hall smoke on with the Maintenance on tenance Supervisor and the conton 10/24/23 at 1:40 p.m., the see 500 hall had a sprinkler head not flush to the ceiling which acc. There was another at two inch by two inch are ceiling around the sprinkler, bace. Based on interview at the sprinkler of the ceiling around the sprinkler, bace. Based on interview at the sprinkler of the ceiling around the sprinkler of the ceiling around the sprinkler, bace. Based on interview at the sprinkler of the ceiling around the sprinkler of the ceiling around the sprinkler of the ceiling around the ceiling, bace.	K 03	351	POC for tag 351 SS-E What corrective action(s) we be accomplished for those residents found to have be affected by the deficient practice? The sprinkler head with escutcheon not flush to the converse when exposed the attic space the other sprinkler head in be which had the opening in the ceiling around the sprinkler we fixed within 60 days. Services been scheduled. how other residents having potential to be affected by the same deficient practice will identified and what correcting action(s) will be taken. All residents have the potential be affected by the alleged depractice. All the facility sprink heads were audited to ensure there is no opening in the cell around sprinkler heads. What measures will be put in place and what systemic	eiling e and ath vill be s had the be ve ial to eficient cler e	12/23/2023

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet Page 6 of 19

PRINTED: 11/09/2023 FORM APPROVED OMB NO. 0938-039

	T OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155237	(X2) MULTIPLE CO A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 10/24/2023				
	ROVIDER OR SUPPLIEI Y VILLAGE		3518 S	STREET ADDRESS, CITY, STATE, ZIP COD 3518 S SHELBY ST INDIANAPOLIS, IN 46227					
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROF DEFICIENCY)	N (X5) BE COMPLETION DATE				
				changes will be made to ensure that the deficient practice does not recur. Maintenance director/desig conduct an audit every two to ensure that there is no openings in the ceiling arous sprinkler head. If any deficient practice is identified, then the Maintenance director/desig immediately fix the ceiling. how the corrective action will be monitored to ensure deficient practice will not recur, i.e., what quality assurance program will be into place; and Maintenance director /desi will be responsible for the completing the audit biweel weeks, monthly for 6 month then quarterly to ensure all sprinkler heads with flush to ceiling does not have any of the results of these audits reviewed by the committee overseen by the ED. If the threshold of 95% is not ach an action plan will be develensure compliance. Deficiency will be complete December 23, 2024.	weeks and the ent ne nee will (s) re the e put gnee kly for 4 ns and the o the opening. will be ieved oped to				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet

Page 7 of 19

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) M	ULTIPLE CO	ONSTRUCTION	(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	A. BUILDING <u>01</u>		COMPLETED	
		155237	B. W	ING		10/24/2023	
	PROVIDER OR SUPPLIER		<u>, </u>	STREET ADDRESS, CITY, STATE, ZIP COD 3518 S SHELBY ST INDIANAPOLIS, IN 46227			
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
K 0355	NFPA 101						
SS=E	Portable Fire Extir	nguishers					
Bldg. 01	Portable Fire Extir	nguishers					
	Portable fire exting	guishers are selected,					
	installed, inspecte	d, and maintained in					
		IFPA 10, Standard for					
	Portable Fire Extir	•					
	18.3.5.12, 19.3.5. ²						
		on, record review and	K 0	355	POC for tag 355		11/06/2023
		ty failed to ensure 1 of 16			SS-E		
	portable fire extingu						
	-	ods not more than one year			What corrective action(s) wil	ll	
		e Standard for Portable Fire			be accomplished for those		
	-	ection 7.3.1.1.1 requires that fire			residents found to have been	n	
	-	be subjected to maintenance at			affected by the deficient		
		re than 1 year, at the time of			practice?		
		when specifically indicated by			The fire extinguishes priceing t	f	
	-	ctronic notification. Section guisher maintenance as a			The fire extinguisher missing t		
		on of the fire extinguisher that			the annual testing inspection of the Auguste cottage is now	ווכ	
	-	naximum assurance that a fire			inspected.		
	_	perate effectively and safely			inspecied.		
		physical damage or condition					
	· ·	ration, if any repair or			how other residents having t	the	
		ssary, and if hydrostatic			potential to be affected by th		
	•	naintenance is required.			same deficient practice will be		
	-	each fire extinguisher shall			identified and what correctiv		
		securely attached that			action(s) will be taken.		
	indicates the month	and year the maintenance was					
	performed, identifie	es the person performing the			All residents have the potentia	al to	
	work, and identifies	the name of the agency			be affected by the alleged def		
	performing the world	k. This deficient practice could			practice. All the facility fire		
	affect 22 residents,	as well as staff in the Auguste			extinguishers had been audite	ed for	
	Cottage smoke com	partment.			annual fire extinguisher testing	g. If	
					any extinguisher is missing the	e	
	Findings include:				annual inspection will be		
					immediately inspected.		
		ation with the Executive					
		ntenance Supervisor and					
	Maintenance Direct	or on 10/24/23 at 1:47 p.m., the			What measures will be put ir	nto	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet Page 8 of 19

PRINTED: 11/09/2023 FORM APPROVED OMB NO. 0938-039

	IT OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155237	(X2) MULTIPLE C A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 10/24/2023				
	PROVIDER OR SUPPLIEF	· · · · · · · · · · · · · · · · · · ·	3518 5	STREET ADDRESS, CITY, STATE, ZIP COD 3518 S SHELBY ST INDIANAPOLIS, IN 46227					
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OF	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APP DEFICIENCY)	CTION (X5) JLD BE COMPLETION DATE				
	Auguste Cottage had of March 2022. Base annual fire extingui 03/16/2023 by the family Based on interview Field Maintenance were aware the fire more than 12 month vendor to do annual. This finding was re Director, Field Maintenance Director.	guisher in the lounge of ad an annual inspection date sed on record review, the sher testing occured on facility's contracted vendor. at the time of observation, the Supervisor stated that they extinguisher was inspected as ago and had contacted the I maintenance. viewed with the Executive intenance Supervisor and tor at the exit conference.		place and what systemichanges will be made to ensure that the deficient practice does not recur Maintenance director/deconduct an audit every to ensure that no fire extis missing from the annuinspection. If any deficient is identified, then the Madirector/designee will import the problem.	t it signee will wo weeks inguisher al nt practice intenance mediately				
	3.1-19(b)			how the corrective action will be monitored to ensure deficient practice will not recur, i.e., what quality assurance program will into place; and Maintenance director /dowill be responsible for the completing the audit bind weeks, monthly for 6 monthen quarterly to ensure fire extinguisher in the famissing any annual inspective overseen by the ED. If the threshold of 95% is not a an action plan will be devenued by the completing the audit overseen by the ED. If the threshold of 95% is not a section plan will be devenued by the compliance.	be put esignee ee eekly for 4 nths and that no cility is ection. Its will be ee ee lee lee lechieved				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet

Page 9 of 19

PRINTED: 11/09/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA	(X2) MU	(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	ILDING	01	COMPLETED		
		155237	B. WI	NG		10/24/	/2023	
NAME OF D	DOVIDED OD CUDDI IED		•	STREET A	ADDRESS, CITY, STATE, ZIP COD	<u> </u>		
NAME OF F	ROVIDER OR SUPPLIER	-		3518 S	SHELBY ST			
BETHAN'	Y VILLAGE			INDIAN.	APOLIS, IN 46227			
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX		CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION	
TAG	REGULATORY OR	R LSC IDENTIFYING INFORMATION	-	TAG	DEFICIENCY)		DATE	
					- Deficiency will be completed b November 6th, 2023.	у		
K 0363	NFPA 101							
SS=E Bldg. 01	Corridor - Doors							
ыug. U I	Corridor - Doors	corridor openings in other						
		losures of vertical openings,						
	-	s areas resist the passage						
		made of 1 3/4 inch						
		wood or other material						
	capable of resistin	ng fire for at least 20						
	minutes. Doors in	fully sprinklered smoke						
	-	e only required to resist the						
		e. Corridor doors and doors						
	to rooms containing	_						
		rials have positive latching						
		atches are prohibited by						
	_	hese requirements do not spaces that do not contain						
	flammable or com	- Table 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1						
		en bottom of door and floor						
		ceeding 1 inch. Powered						
	_	vith 7.2.1.9 are permissible						
		device capable of keeping						
	the door closed wi	hen a force of 5 lbf is						
	applied. There is	no impediment to the						
	closing of the door	rs. Hold open devices that						
		door is pushed or pulled are						
		ed protective plates of						
		re permitted. Dutch doors						
	•	6 are permitted. Door						
		beled and made of steel or						
		compliance with 8.3,						
	unless the smoke							
	sprinklered. Fixed	fire window assemblies are				ļ		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet

Page 10 of 19

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) M	ULTIPLE CO	ONSTRUCTION	(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	JILDING			ETED
		155237	B. W	ING	_	10/24/	2023
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 3518 S SHELBY ST INDIANAPOLIS, IN 46227				
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDENCE NEARLOS CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	DATE
TAG	allowed per 8.3. In there are no restri resistance of glass assemblies. 19.3.6.3, 42 CFR 483, and 485 Show in REMARK fire protection ratin devices, etc. Based on observation failed to ensure 1 of impediment to closs frame and would redeficient practice of staff and visitors in Findings include: Based on observation Field Maintenance Direct from 1:13 p.m. to 2 latching mechanism resident sleeping Relatching plate on the was tested to close interview at the tim Maintenance Direct Room 110 would not ensure the door worksmoke. This finding was redeficient practice, Field Maintenance Direct Room 110 would not ensure the door worksmoke.	r sprinklered compartments ctions in area or fire sor frames in window Parts 403, 418, 460, 482, AS details of doors such as ngs, automatics closing on and interview, the facility fover 50 corridor doors had no ang and latching into the door sist the passage of smoke. This build affect over 10 residents, the vicinity of Room 110.	K 0		POC for tag 363 SS-E What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice? The corridor door to the reside sleeping room 110 is now late into the latching plate on the difframe is now fixed. how other residents having the potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken. All residents have the potential be affected by the alleged definition practice. All the facility doors wanted to ensure that all door are latching appropriately into latching plate.	ent hing door the ne ne icient were	11/06/2023
	3.1-19(b)				What measures will be put ir place and what systemic	nto	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet Page 11 of 19

PRINTED: 11/09/2023 FORM APPROVED OMB NO. 0938-039

	NT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155237	(X2) MULTIPLE C A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 10/24/2023			
	PROVIDER OR SUPPLIE	R	STREET ADDRESS, CITY, STATE, ZIP COD 3518 S SHELBY ST INDIANAPOLIS, IN 46227					
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDERS PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE				
				changes will be made to ensure that the deficient practice does not recur. Maintenance director/design conduct an audit every two to ensure that all the doors latched into the door frame latching plate. If any deficient practice is identified, then the Maintenance director/design immediately fix the door.	o weeks s are e with ent the			
				how the corrective action will be monitored to ensu deficient practice will not recur, i.e., what quality assurance program will b into place; and	re the			
				Maintenance director /des will be responsible for the completing the audit biwee weeks, monthly for 6 month then quarterly to ensure all doors are latching into doo with latching plate. The rest these audits will be reviewed the committee overseen by ED. If the threshold of 95% achieved an action plan will developed to ensure comp	ekly for 4 hs and I the or frame sults of ed by y the o is not II be			
				- Deficiency will be complete	ed by			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet

Page 12 of 19

DEPARTMENT OF HEALTH AND HUMAN SERVICE	S
CENTERS FOR MEDICARE & MEDICAID SERVICES	š

STATEMEN	T OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) M				ATE SURVEY	
AND PLAN	AND PLAN OF CORRECTION IDENTIFICATION NUMBER		A. BUILDING <u>01</u> CO			COMPL	COMPLETED	
		155237	B. W	NG		10/24/	2023	
NAME OF PROVIDER OR SUPPLIER BETHANY VILLAGE			STREET ADDRESS, CITY, STATE, ZIP COD 3518 S SHELBY ST INDIANAPOLIS, IN 46227					
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE			ID PROVIDER'S PLAN OF CORRECTION			(X5)	
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION			PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT DEFICIENCY)	ΓE	COMPLETION	
TAG	REGULATORY OR LSC IDENTIFYING INFORMATION			TAG	November 6th, 2023.		DATE	
K 0374 SS=E Bldg. 01	Barrie Subdivision of Buil Barrier Doors 2012 EXISTING Doors in smoke be solid bonded wood construction that re Nonrated protective are permitted. Door fixed fire window as are self-closing or require latching, as in the direction of oprovides a minimus for swinging or hor 19.3.7.6, 19.3.7.8, Based on observation failed to ensure 1 of would restrict the ms 20 minutes. LSC 19 barriers shall comples. 5.4.1 requires doon the opening leaving necessary for proper as 1/8 inch. This def least 20 residents. Findings include: Based on observation facility with the Execution Maintenance Supervised.	resists fire for 20 minutes. The plates of unlimited height ors are permitted to have assemblies per 8.5. Doors automatic-closing, do not and are not required to swing regress travel. Door opening m clear width of 32 inches rizontal doors.	K 0	374	POC for tag 374 SS-E What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice? The smoke barrier door nearesthe salon is now fixed and can fully latch and close. how other residents having the potential to be affected by the same deficient practice will be identified and what corrective.	st to he e e	11/06/2023	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet Page 13 of 19

STATEMEN	STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA					(X3) DATE SURVEY	
AND PLAN	AND PLAN OF CORRECTION IDENTIFICATION NUMBER		A. BUILDING <u>01</u> COMPLET			ETED	
	155237		B. WING 10/24/202				2023
NAME OF PROVIDER OR SUPPLIER BETHANY VILLAGE				3518 S	ADDRESS, CITY, STATE, ZIP COD SHELBY ST APOLIS, IN 46227		
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE			ID			(X5)
PREFIX		CY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	COMPLETION	
TAG	REGULATORY OR LSC IDENTIFYING INFORMATION			TAG CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)			DATE
	from 1:13 p.m. to 2:30 p.m., the smoke barrier door				action(s) will be taken.		
		lon failed to fully close and					
	_	ted on three separate			All residents have the potentia		
		an an interview at the time of			be affected by the alleged def		
	the observation, the				practice. All the facility doors v		
	-	ed the barrier door set did not look at the door set and fix the			audited to ensure that all door	S	
	issue as soon as he				are latching and closing appropriately.		
	issue as soon as ne	was able to do so.			αρριοριιαίοις.		
	This finding was re	viewed with the Executive			What measures will be put in	ito	
	_	ntenance Supervisor, and the			place and what systemic		
	Maintenance Direct	for at the exit conference.			changes will be made to		
					ensure that the deficient		
	3.1-19(b)				practice does not recur.		
					Maintenance director/designe		
					conduct an audit every two we		
					to ensure that all the doors are latched and close. If any defic		
					practice is identified, then the	ieni	
					Maintenance director/designe	e will	
					immediately fix the door.	· · · · · ·	
					,		
					how the corrective action(s)		
					will be monitored to ensure t	ne	
					deficient practice will not recur, i.e., what quality		
					assurance program will be p	ut	
					into place; and	ut	
					piaco, and		
					Maintenance director /design	ee	
					will be responsible for the		
					completing the audit biweekly		
					weeks, monthly for 6 months a		
					then quarterly to ensure all the		
					doors are latching and closing		
					appropriately. The results of the	nese	
					audits will be reviewed by the	7 If	
					committee overseen by the EI	J. IT	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet Page 14 of 19

PRINTED: 11/09/2023 FORM APPROVED OMB NO. 0938-039

STATEMEN	T OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE	CONSTRUCTION	(X3) DATE SURVEY
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BUILDING	01	COMPLETED
		155237	B. WING		10/24/2023
			STREE	ET ADDRESS, CITY, STATE, ZIP COD	
NAME OF P	PROVIDER OR SUPPLIE	R	3518	S SHELBY ST	
BETHAN	Y VILLAGE		INDI	ANAPOLIS, IN 46227	
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CORRECTION	(X5)
PREFIX	`	NCY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI	
TAG	REGULATORY O	R LSC IDENTIFYING INFORMATION	TAG	DEFICIENCY)	DATE
				the threshold of 95% is not achieved an action plan will b	10
				developed to ensure complian	
				developed to chadre compilar	ioc.
				- Deficiency will be completed	by
				November 6th, 2023.	Jy
				1404011111011 0111, 2020.	
14 0740	NEDA 404				
K 0712 SS=C	NFPA 101 Fire Drills				
Bldg. 01	Fire Drills				
Diag. 01		the transmission of a fire			
		simulation of emergency fire			
	-	rills are held at expected			
		imes under varying			
		st quarterly on each shift.			
		ar with procedures and is			
		are part of established			
	9:00 PM and 6:00	rills are conducted between			
		ay be used instead of			
	audible alarms.	ay be deed inclode of			
	19.7.1.4 through	19.7.1.7			
	Based on record re	view and interview, the facility	K 0712	POC for tag 712	11/06/2023
		uarterly fire drills at unexpected		SS-C	
	_	g conditions on all shifts for 3			
	_	deficient practice could affect		What corrective action(s) wi	II
	all residents, staff a	and visitors in the facility.		be accomplished for those	
	Findings include:			residents found to have bee affected by the deficient	n
	i manigs meiade.			practice?	
	Based on review or	f "Fire Drill Report"		F. 400.00	
		h the Executive Director, Field		Fire drills on second and third	1

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 F

Facility ID: 000142

If continuation sheet

Page 15 of 19

	IT OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155237	(X2) MULTIPLE CO A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 10/24/2023
	PROVIDER OR SUPPLIER Y VILLAGE		3518 S	ADDRESS, CITY, STATE, ZIP COD SHELBY ST NAPOLIS, IN 46227	
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OR	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
	Director during reco 1:13 p.m. on 10/24/ conducted on 02/28	visor and Maintenance ord review from 10:23 a.m. to 23, second shift fire drills /23, 05/09/23, 09/25/23 and ucted at, respectively, 3:30		shifts are now conducted at unexpected times under varyi conditions.	ing
	p.m., 3:10 p.m., 4:0 Additionally, third s 03/29/23, 05/03/23, conducted at, respect a.m. and 6:00 a.m. of record review, th	0 p.m. and 4:00 p.m. shift fire drills conducted on 09/06/23 and 11/15/22 were etfully, 6:00 a.m., 6:20 a.m., 4:34 Based on interview at the time e Executive Director and Field		how other residents having potential to be affected by the same deficient practice will identified and what corrective action(s) will be taken.	ne be
	were not conducted varying conditions.	visor confirmed the ond and third shift fire drills at unexpected times under viewed with the Executive		All residents have the potential be affected by the alleged determined practice. All the facility fire drivill be audited on a regular batto ensure that the facility is defire drills at unexpected times	ficient lls asis oing
	Director, Field Mair	ntenance Supervisor and or at the exit conference.		under varying conditions.	
	3.1-19(b) 3.1-51(c)			What measures will be put in place and what systemic changes will be made to ensure that the deficient practice does not recur.	nto
				how the corrective action(s) will be monitored to ensure deficient practice will not recur, i.e., what quality assurance program will be pinto place; and	the
				biweekly for 4 weeks, monthl 6 months and then quarterly the ensure that fire drills are held unexpected times under varying conditions. The results of the audits will be reviewed by the committee overseen by the E the threshold of 95% is not	at ng

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21

Facility ID: 000142

If continuation sheet

Page 16 of 19

PRINTED: 11/09/2023 FORM APPROVED OMB NO. 0938-039

	IT OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155237	r í	JILDING	onstruction 01	(X3) DATE : COMPL 10/24/	ETED	
NAME OF PROVIDER OR SUPPLIER BETHANY VILLAGE				STREET ADDRESS, CITY, STATE, ZIP COD 3518 S SHELBY ST INDIANAPOLIS, IN 46227				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT DEFICIENCY)		(X5) COMPLETION DATE	
					achieved an action plan will be developed to ensure complian			
					Deficiency will be completed by November 6th, 2023.	у		
K 0920 SS=B Bldg. 01	Extens Electrical Equipme Extension Cords Power strips in a pused for compone patient-care-relate (PCREE) assemble assembled by qua the conditions of 1 the patient care via non-PCREE (e.g., except in long-terr do not use PCREE meet UL 1363A or for non-PCREE in (outside of vicinity non-patient care ro other UL standard used with general cords are not used wiring of a structur temporarily are rer completion of the printstalled and meet 10.2.3.6 (NFPA 98 (NFPA 70), 590.30	ent - Power Cords and ent - Power Cords and catient care vicinity are only ents of movable ed electrical equipment les that have been alified personnel and meet 10.2.3.6. Power strips in cinity may not be used for personal electronics), m care resident rooms that E. Power strips for PCREE T UL 60601-1. Power strips the patient care rooms b) meet UL 1363. In coms, power strips meet ls. All power strips are precautions. Extension d as a substitute for fixed re. Extension cords used moved immediately upon purpose for which it was ts the conditions of 10.2.4. e), 10.2.4 (NFPA 99), 400-8 (D) (NFPA 70), TIA 12-5 on and interview, the facility	K 09	920	POC for tag 920		11/06/2023	
			K 09	920	POC for tag 920		11/06/2023	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

EQ3C21 Facility ID: 000142

If continuation sheet Page 17 of 19

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER		UILDING	01	COMPLETED		
155237		155237	B. W	B. WING		10/24/2023		
				CTREET	ADDRESS CITY STATE ZIR COD			
NAME OF PROVIDER OR SUPPLIER					ADDRESS, CITY, STATE, ZIP COD SHELBY ST			
DETLIAN	V VIII I ACE							
BETHANY VILLAGE				INDIAN	IAPOLIS, IN 46227			
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE			ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL			PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE		COMPLETION	
TAG	REGULATORY OR LSC IDENTIFYING INFORMATION			TAG	DEFICIENCY)		DATE	
	failed to ensure 1 of 1 flexible cords were not used as a substitute for fixed wiring. NFPA-70/2011,				SS-B			
	400.8 state unless s	pecifically permitted in 400.7			What corrective action(s) wil	iI		
	flexible cords and c	ables shall not be used for (1)			be accomplished for those			
	as a substitute for fi	xed wiring. This deficient			residents found to have been	n		
	practice could affect	et approximately 20 residents			affected by the deficient			
	and staff in August	e Cottage smoke compartment.			practice?			
					_			
	Findings include:				The extension cord was			
					immediately removed to ensur	re		
	Based on observation	on during a tour of the facility			one of the one flexible cords v	vere		
	with the Executive Director, Field Maintenance				not used as substitute for fixed	d		
	Supervisor and Maintenance Director on 10/24/23				wiring.			
	at 1:45 p.m., there was an extension cord in the							
	nurse station area o	f Auguste Cottage that						
	powered a compute	r and a small fan. Based on			how other residents having t	the		
	interview at the tim	e of observation, the Field			potential to be affected by th			
	Maintenance Super	visor confirmed that a			same deficient practice will I	oe		
	computer and fan w	vas plugged into an extension			identified and what correctiv	re		
	cord, and removed	the extension cord upon			action(s) will be taken.			
	observation.							
					All residents have the potentia	al to		
	The finding was rev	viewed with the Executive			be affected by the alleged def	icient		
	Director, Field Mai	ntenance Supervisor and			practice. All the facility will be			
	Maintenance Direct	tor during the exit conference.			audited on a regular basis to			
					ensure that there is no flexible	;		
	3.1-19(b)				cords were used for a substitu	ıte		
					for fixed wiring			
					What measures will be put ir	ıto		
					place and what systemic			
					changes will be made to			
					ensure that the deficient			
					practice does not recur.			
					Maintenance director/designe	e will		
					conduct an audit every two we	eks		
					to ensure that there is no flexi	ble		
					cords used to substitute for fix	red		
					wiring. If any deficient practice	is is		

PRINTED: 11/09/2023 FORM APPROVED OMB NO. 0938-039

STATEMEN	T OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY	
AND PLAN	AND PLAN OF CORRECTION IDENTIFICATION NUMBER		A. BUILDING	<u>01</u>	COMPLETED	
		155237	B. WING		10/24/2023	
	PROVIDER OR SUPPLIEI	R	3518	T ADDRESS, CITY, STATE, ZIP COD S SHELBY ST NAPOLIS, IN 46227		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CORRECTION	(X5)	
PREFIX	(EACH DEFICIEN	NCY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI, DEFICIENCY)	COMPLETION	N
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATION	TAG	DEFICIENCY)	DATE	
				identified, then the Maintenar director/designee will immedifix the problem immediately. how the corrective action(s)	ately	
				will be monitored to ensure		
				deficient practice will not		
				recur, i.e., what quality		
				assurance program will be p	out	
				into place; and Maintenance director /desig	nee	
				will be responsible for the completing the audit biweekly	for 4	
				weeks, monthly for 6 months	and	
			then quarterly to ensure that there is no flexible cords are being		here	
				used. The results of these au	dits	
				will be reviewed by the comm	ittee	
				overseen by the ED. If the threshold of 95% is not achie	/ed	
				an action plan will be develop		
				ensure compliance.		
				Deficiency will be completed	ру	
				November 6th, 2023.		

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: EQ3C21 Facility ID: 000142 If continuation sheet Page 19 of 19