STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155286		IDENTIFICATION NUMBER	(X2) MULTIPLE CONSTRUCTION (X3) DATE SU A. BUILDING COMPLET B. WING 02/02/20			ETED	
	PROVIDER OR SUPPLIER VILLAGE	3		STREET ADDRESS, CITY, STATE, ZIP COD 200 KINGSTON CIR LIGONIER, IN 46767			
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	ATE	(X5) COMPLETION DATE
E 0000 Bldg	conducted by the Ir accordance with 42 Survey Date: 02/02 Facility Number: 02/02 Provider Number: 100 At this Emergency Village was found if Preparedness Required Participat CFR 483.73. The face	2/2023 20184 255286 267210 Preparedness survey, Avalon no compliance with Emergency irements for Medicare and sing Providers and Suppliers, 42 actility has a capacity of 67 and at the time of this survey.	E 00	000	Submission of this plan of correction does not constitute admission or agreement by th provider of the truth of facts alleged or correction set forth the statement of deficiencies. plan of correction is prepared submitted because of requirer under state and federal law. Please accept this plan of correction as our credible allegation of compliance Requesting Desk Review	e on This and	
Bldg. 01	A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a). Survey Date: 02/02/2023 Facility Number: 000184 Provider Number: 155286 AIM Number: 100267210 At this Life Safety Code survey, Avalon Village was found not in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety from Fire and the		K 00	K 0000 Submission of this plan of correction does not constitute admission or agreement by provider of the truth of facts alleged or correction set for the statement of deficiencies plan of correction is prepare submitted because of requiunder state and federal law Please accept this plan of correction as our credible allegation of compliance Requesting Desk Review		e on This and	

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

(X6) DATE

TITLE

Jessica Slone Executive Director 02/17/2023

Any defiencystatement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: G6AX21 Facility ID: 000184 If continuation sheet Page 1 of 11

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 02/21/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155286		 UILDING	nstruction 01	(X3) DATE : COMPL 02/02/	ETED	
	ROVIDER OR SUPPLIER VILLAGE		200 KIN	NDDRESS, CITY, STATE, ZIP COD IGSTON CIR ER, IN 46767		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	ΤE	(X5) COMPLETION DATE
K 0321 SS=E Bldg. 01	Association (NFPA) Chapter 19, Existing 410 IAC 16.2. This one story facility on the corridors and detectors in the resic capacity of 67 and hof this survey. All areas where the access were sprinkle facility services were very considered and the corridors and detectors in the resic capacity of 67 and hof this survey. All areas where the access were sprinkle facility services were very considered and the corridors and the corridors are as a barrier having 1-hof (with 3/4 hour fire automatic fire exting accordance with 8 approved automatic option is used, the from other spaces partitions and door Doors shall be self-automatic-closing nonrated or field-ad do not exceed 48 if the door.	- Enclosure - Enclosure - Enclosure are protected by a fire our fire resistance rating rated doors) or an nguishing system in .7.1 or 19.3.5.9. When the ic fire extinguishing system areas shall be separated by smoke resisting rs in accordance with 8.4. f-closing or and permitted to have pplied protective plates that inches from the bottom of				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

 $G6AX21 \qquad {\tt Facility \, ID:} \quad 000184$

If continuation sheet

Page 2 of 11

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA			PLE CONSTRUCTION NG 01	(X3) DATE SURVEY		
AND PLA	N OF CORRECTION	IDENTIFICATION NUMBER	A. BUILDII	COMPLETED		
		155286	B. WING		02/02/2023	
AVALO	F PROVIDER OR SUPPLIER		20 LIC	REET ADDRESS, CITY, STATE, ZIP C 10 KINGSTON CIR GONIER, IN 46767		
(X4) ID		STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF COR		
PREFIX	`	ICY MUST BE PRECEDED BY FULL	PREFIX (EACH CORRECTIVE ACTION SHOULD I CROSS-REFERENCED TO THE APPROFIDENCY) TAG DEFICIENCY)		APPROPRIATE	
TAG		R LSC IDENTIFYING INFORMATION	1A	G	DATE	_
	Area Separation a. Boiler and Fuel b. Laundries (larg c. Repair, Mainter d. Soiled Linen Ro gallons) e. Trash Collectio (exceeding 64 gal f. Combustible Sto (over 50 square fe g. Laboratories (if Hazard - see K32 Based on observation failed to ensure the housekeeping supparea containing con than 50 square feet self-closing device automatically close This deficient pract service hall. Findings include: Based on observation with the Maintenan p.m., the housekeep storage room that w was equipped with not latch into the frointerview at the tim Maintenance Direct as storage, was larg stated the door to the did not latch into the	Automatic Sprinkler N/A -Fired Heater Rooms er than 100 square feet) nance, and Paint Shops coms (exceeding 64 In Rooms llons) orage Rooms/Spaces eet) classified as Severe 2) on and interview, the facility corridor doors to 1 of 1 lly rooms which is a hazardous abustible storage and greater was provided with a which would cause the door to and latch into the door frame. ice could affect staff in the ons during a tour of the facility ce Director on 02/02/23 at 2:35 oing storage room, a hazardous vas greater than 50 square feet, a self-closing device but did ame when tested. Based on the of observation, the tor agreed the room was used	K 0321	Requesting Desk Rev K 321 Hazardous Are Enclosure What corrective action be accomplished for residents found to hat affected by the deficit practice: Repair was made and the housekeeping stor now latches into the from How other residents is potential to be affected same deficient practic identified and what contact in the story identified and what contact in the story identified and what contact in the story inspected, and all door compliance. What measures will be place or what system changes will be made ensure that the deficit practice does not recontact.	view 02/17/2023 on(s) will those ave been ent d the door to rage room ame. having the ed by the ce will be orrective on: potential to doors were rs are in one put into nice e to ient	

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 02/21/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MI	(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	A. BUILDING <u>01</u>			COMPLETED	
		155286	B. WING 02/02/2023				2023	
				STREET A	ADDRESS, CITY, STATE, ZIP COD			
NAME OF P	ROVIDER OR SUPPLIER				IGSTON CIR			
AVALON	VILLAGE				ER, IN 46767			
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	TE	COMPLETION	
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION	FYING INFORMATION TAG DEFICIENCY)			DATE		
	and Maintenance D	irector at the exit conference.			Maintenance Director has bee	n		
					educated on K321 requiring th	at		
	3.1-19(b)				doors latch into the frame. The	,		
					QAPI and PM calendar was			
					updated for the Executive			
					Director/Maintenance Director	to		
					review that all doors latch prop	erly		
					into their frames.			
					How the corrective action(s)			
					will be monitored to ensure t	he		
					deficient practice will not			
					recur, i.e., what quality			
					assurance program will be p	ut		
					into place:			
					The Executive Director will rou			
					with the maintenance director			
					to the compliance date to ensu			
					all doors latch into their frames			
					The Executive Director will rev	iew		
					the preventative maintenance			
					checks performed by the			
					maintenance director monthly	and		
					sign off that the checks were			
					completed.			
					Completion Date: 2/17/23			
K 0353	NFPA 101							
SS=C	_	- Maintenance and Testing						
Bldg. 01		- Maintenance and Testing						
2.49.0.	-	er and standpipe systems						
	-	ted, and maintained in						
	•	IFPA 25, Standard for the						
		g, and Maintaining of						
		Protection Systems.						
		n design, maintenance,						
	_	ting are maintained in a						
	•	id readily available.						
		system last checked						
	, 2 a. 5 opi i i i i i	-,						
	b) Who provided	svstem test						

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

G6AX21 Facility ID: 000184

If continuation sheet Page 4 of 11

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		` ′		ONSTRUCTION	(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BUILDING <u>01</u> COMPL				
		155286	B. W	B. WING 02/02/2023			2023
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 200 KINGSTON CIR LIGONIER, IN 46767				
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDENCE NEARLOS CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA		COMPLETION
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)	116	DATE
	c) Water system supply source Provide in REMARKS information on coverage for any non-required or partial automatic sprinkler system.						
	failed to ensure 1 of provided with spare cabinet and a sprink NFPA 25, Standard and Maintenance of Systems, 2011 Editi supply of spare sprinthe premises so that operated or damage replaced. The sprintypes and temperate the property. The scabinet located whe they are subjected with degrees Fahrenheit. shall be provided arrused in the removal This deficient practicand staff in the facil Findings include: Based on observation with the Maintenance p.m., in the spare sprinkle at the time of the observation of the observatio	on and interview, the facility of 1 sprinkler systems were e sprinklers, a spare sprinkler cler wrench on the premises. for the Inspection, Testing, of Water-Based Fire Protection ion, Section 5.4.1.4 states a nklers shall be maintained on any sprinklers that have been d in any way can be promptly cklers shall correspond to the are ratings of the sprinklers on prinklers shall be kept in a are the temperature in which will at no time exceed 100 A special sprinkler wrench and kept in the cabinet to be and installation of sprinklers. ice could affect all residents lity. Ons during a tour of the facility one Director on 02/02/23 at 1:45 rinkler cabinet in the riser room sprinkler heads, 2 of which on protected slot, being stored or cabinet. Based on interview observation, the Maintenance spare sprinkler cabinet had 2	K 0	353	Requesting Desk Review K 353 Sprinkler System - Maintenance and Testing What corrective action(s) wi be accomplished for those residents found to have beer affected by the deficient practice: the spare sprinkler heads were placed in their own protected selected by the same deficient practice will be identified and what corrective action(s) will be taken: All residents have the potential be affected. All other sprinkler heads were assessed and in to own protected slot What measures will be put in place or what systemic changes will be made to ensure that the deficient practice does not recur: Maintenance Director educate that the spare sprinkler heads must be placed in their own protected slot. The QAPI and PM calendar w updated for the Maintenance Director to check that all spare sprinkler heads are placed in to own protected slots.	e slot. the e e e e e e e e e e e e e e e e e e	02/17/2023

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

G6AX21 Facility ID: 000184

If continuation sheet Page 5 of 11

PRINTED: 02/21/2023

	OF HEALTH AND HUN R MEDICARE & MEDIC						RM APPROVED B NO. 0938-039
STATEMEN		XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155286	X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING (X3) DATE SURVEY COMPLETED 02/02/2023				
	PROVIDER OR SUPPLIER	1	STREET ADDRESS, CITY, STATE, ZIP COD 200 KINGSTON CIR LIGONIER, IN 46767				
(X4) ID PREFIX TAG	EFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL			ID PROVIDER'S PLAN OF CORRECTION			(X5) COMPLETION DATE
	This finding was re	viewed with the Administrator irector at the exit conference.			How the corrective action(s) will be monitored to ensure to deficient practice will not recur, i.e., what quality assurance program will be printo place: The Executive Director will row with the maintenance director to the compliance date to ensurall spare sprinkler heads are placed in their own protectives. The Executive Director will revente the preventative maintenance checks performed by the maintenance director monthly sign off that the checks were completed. By what date the systemic changes will be completed: 2/17/23	ut Ind prior Ire slot. iew	
K 0361 SS=E Bldg. 01	waiting areas, nur and cooking facilit in accordance with and 19.3.6.1. 18.3.6.1, 19.3.6.1 Based on observation failed to ensure 1 of pass-through window		K 0	361	Requesting Desk Review K 361 Corridors - Areas Open Corridor What corrective action(s) wi		02/17/2023

FORM CMS-2567(02-99) Previous Versions Obsolete

corridor. LSC 19.3.6.1(7) states that spaces other

than patient sleeping rooms, treatment rooms, and

hazardous areas shall be open to the corridor and

corridors which the space opens onto in the same

unlimited in area, provided: (a) The space and

Event ID:

G6AX21

Facility ID: 000184

practice:

If continuation sheet

be accomplished for those

affected by the deficient

The nurses station is now

residents found to have been

Page 6 of 11

	NT OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155286	(X2) MULTIPLE C A. BUILDING B. WING	onstruction 01	(X3) DATE COMPI 02/02	LETED
	PROVIDER OR SUPPLIEF	2	200 KI	ADDRESS, CITY, STATE, ZIP COI NGSTON CIR IIER, IN 46767)	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORREGE (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APP DEFICIENCY)	CTION ULD BE PROPRIATE	(X5) COMPLETION DATE
	smoke compartment electrically supervisus system in accordant space is protected by the space does required exits. LCS openings, such as no pass-through windows, and cash shall be permitted the or doors without space both of the following (1) The aggregate and exceed 20 inches (2) The openings and distance from the flat This deficient pract 10 residents in one. Findings include: Based on observation of the space of	at are protected by an sed automatic smoke detection ce with 19.3.4, and (b) Each by an automatic sprinklers, and not to obstruct access to a 19.3.6.5.1 states miscellaneous nail slots, pharmacy lows, laboratory pass-through the pass-through windows, to be installed in vision panels ecial protection, provided that are criteria are met: are of openings per room does be squared (0.015 m2). The installed at or below half the coor to the room ceiling. The installed at or below half the coor to the room ceiling. The installed at or below half the coor to the room ceiling. The installed at or below half the coor to the room ceiling. The installed at or below half the coor to the room ceiling. The installed are could affect staff and up to smoke compartments.		protected by a smoke de How other residents ha potential to be affected same deficient practice identified and what corraction(s) will be taken: All residents have the pobe affected. All other are building were assessed compliance with K 361. What measures will be place or what systemic changes will be made to ensure that the deficient practice does not reocci. Maintenance Director was educated on K 361 and pushed affected on K 361 and pushed the systemic changes will be made to ensure that the deficient practice does not reocci. Maintenance Director was educated on K 361 and pushed affected on K 361 and pushed the system of the practice will be monitored to the number of the precedit of the compliance with K 361. How the corrective action will be monitored to ensure the practice will number of the compliance with K 361. How the corrective action will be monitored to ensure the practice will number of the compliance date to th	etector. ving the by the will be rective etential to eas in the eand in put into out cur: es providing a ersing gh square M or the review on(s) sure the ot I be put vill round ector prior o ensure cough square ector. vill review elector.	

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155286		(X2) MULTIPLE CO A. BUILDING B. WING	onstruction <u>01</u>	(X3) DATE SURVEY COMPLETED 02/02/2023	
	ROVIDER OR SUPPLIER VILLAGE		STREET ADDRESS, CITY, STATE, ZIP COD 200 KINGSTON CIR LIGONIER, IN 46767		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
				maintenance director monthly sign off that the checks were completed.	and
				By what date the systemic changes will be completed: 2/17/23	
K 0511 SS=E Bldg. 01	complies with NFF Code, electrical with Code, electrical with Code. Existing instance provided in 18.5.1.1, 19.5.1.1, 1. Based on observation of room 303 contained protected from dam Article 406.6, Receplates), requires receinstalled so as to cound seat against the 2011 Edition. Article Receptacles shall be terminals are not extended to the complete containing include: Based on observation Director on 02/02/2303 there was an elector plate. Based of cover plate. Based of cover plate.	Electric gas or related gas piping PA 54, National Fuel Gas ring and equipment PA 70, National Electric tallations can continue in o hazard to life. 9.1.1, 9.1.2 tion and interview, the facility 1 electrical outlets in resident a cover plate and was age. NFPA 70, 2011 Edition. otacle Faceplates (Cover eptacle faceplates shall be impletely cover the opening mounting surface. NFPA 70, e 406.5 (F) Exposed Terminals, e enclosed so that live wiring posed to contact. This ould affect 2 residents in on with the Maintenance 3 at 2:10 p.m., in resident room extrical outlet with a broken on interview at the time of intenance Director agreed the	K 0511	Requesting Desk Review K 511 Utilities - Gas and Elect What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice: The electrical outlet in resident room 303 was repaired. The list switch in the kitchen walk-in refrigerator was repaired. How other residents having potential to be affected by the same deficient practice will lidentified and what corrective action(s) will be taken: All residents have the potential be affected. All other outlets at light switches were assessed immediately. All outlets and switches are in compliance. What measures will be put in	n tte ight the ie be re al to and

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

 $G6AX21 \qquad {\tt Facility\ ID:} \quad 000184$

If continuation sheet

Page 8 of 11

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155286		A. BUIL	(X2) MULTIPLE CONSTRUCTION (X3) DATE: A. BUILDING 01 COMPL B. WING 02/02/		LETED		
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 200 KINGSTON CIR LIGONIER, IN 46767				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION		ID REFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	ATE	(X5) COMPLETION DATE
	This finding was re Director and Admir conference. 3.1-19(b) 2. Based on observation for the walk-in refriprotected. NFPA 70 Receptacle Faceplate completely cover the mounting surface. The affect 4 employees Findings include: Based on observation with the Maintenance Direct was brown interview at the tim Maintenance Direct aforementioned control of the process	viewed with the Maintenance histrator during the exit ation and interview, the facility of 1 electrical light switch outlet gerator in the kitchen was 0, 2011 Edition. Article 406.6, tes (Cover Plates), requires as shall be installed so as to be opening and seat against the Chis deficient practice could in the kitchen. On during a tour of the facility the Director on 02/02/23 at 2:40 the in the kitchen walk-in the kitchen walk-in the kitchen walk-in the correction of the facility of the correction of the co			place or what systemic changes will be made to ensure that the deficient practice does not reoccur: Maintenance Director was educated to check all outlets light switches to ensure compliance with K 511. The cand PM calendar was update the Maintenance Director to outlets and light switches for compliance. How the corrective action(swill be monitored to ensure deficient practice will not recur, i.e., what quality assurance program will be into place: The Executive Director will rewith the maintenance director to the compliance date to ensure deficient practice will not recur, i.e., what quality assurance program will be into place: The Executive Director will rewith the maintenance director to the compliance date to ensure from damage. The Executive Director will review the preventantenance checks perform the maintenance director monand sign off that the checks we completed. By what date the systemic changes will be completed: 2/17/23	QAPI ed for check the the out r prior sure free entative ed by nthly vere	
K 0920 SS=D Bldg. 01	Extens Electrical Equipme Extension Cords	ent - Power Cords and ent - Power Cords and patient care vicinity are only					

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		X2) MULTIPLE CONSTRUCTION (X3) DATE SU			SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BUILDING 01 COMPLETED				ETED
		155286	B. WING 02/02/2023				
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 200 KINGSTON CIR LIGONIER, IN 46767				
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	(PCREE) assemble assembled by quarthe conditions of 1 the patient care vinon-PCREE (e.g., except in long-terr do not use PCREE meet UL 1363A or for non-PCREE in (outside of vicinity non-patient care rother UL standard used with general cords are not used wiring of a structur temporarily are recompletion of the installed and meet 10.2.3.6 (NFPA 99 (NFPA 70), 590.3 (Based on observation).	ents of movable and electrical equipment alles that have been allified personnel and meet 0.2.3.6. Power strips in cinity may not be used for personal electronics), and care resident rooms that E. Power strips for PCREE and UL 60601-1. Power strips the patient care rooms and the patient care rooms are meet UL 1363. In come, power strips meet as. All power strips are precautions. Extension as a substitute for fixed are. Extension cords used moved immediately upon purpose for which it was astate conditions of 10.2.4. Enditor of the property of the polymer	K 09	920	Requesting Desk Review K 920 Electrical Equipment -		02/17/2023
	multi-plug adaptors wiring. LSC 9.1.2 requipment shall be National Electrical (Article 400.8 requir permitted, flexible cused as a substitute This deficient practification of the Electron of the National Electrical (Electron of the National Electrical Capacitation) as a substitute of the National Electron of the National Electrical (Electron of the National Electron of the National Electrical (Electron of the National Electron of the	as a substitute for fixed equires electrical wiring and in accordance with NFPA 70, Code. NFPA 70, 2011 Edition, test that, unless specifically cords and cables shall not be for fixed wiring of a structure. ice affects 2 residents. On with the Maintenance 3 at 1:55 p.m., resident room lti-plug adaptor powering . Based on interview at the , the Maintenance Director			Power Cords and Extens What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice: multi-plug adaptor powering personal equipment was remote from resident room 203 How other residents having to potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken: All residents have the potential be affected. All rooms were	oved the e oe	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

G6AX21 Facility ID: 000184

If continuation sheet Page 10 of 11

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 02/21/2023 FORM APPROVED OMB NO. 0938-039

	IT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155286	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 02/02/2023			
NAME OF PROVIDER OR SUPPLIER AVALON VILLAGE			STREET ADDRESS, CITY, STATE, ZIP COD 200 KINGSTON CIR LIGONIER, IN 46767					
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE			
	room 203. This finding was re	viewed with the Administrator irector at the exit conference.		checked for multi-plug adaptors/extension cords. The were none found. What measures will be put in place or what systemic changes will be made to ensure that the deficient practice does not recur: Maintenance Director will be educated on not using multi-padaptors as a substitute for fix wiring. The QAPI and PM calendar was updated for the Maintenance Director to check multi plug adaptors/extension cords to ensure compliance. How the corrective action(s) will be monitored to ensure deficient practice will not recur, i.e., what quality assurance program will be pinto place: /p> By what date the systemic changes will be completed: 2/17/23	lug ked k for			

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: G6AX21 Facility ID: 000184 If continuation sheet Page 11 of 11