CENTERS FOR MEDICARE & MEDICAID SERVICES					OMB NO. 0938-039	
	NT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155298	(X2) MULTIPLE C A. BUILDING B. WING	ONSTRUCTION :	X3) DATE SURVEY COMPLETED 03/08/2018	
	PROVIDER OR SUPPLIEI D POINT POST-AC	UTE REHABILITATION CENTER	STREET ADDRESS, CITY, STATE, ZIP COD 8530 TOWNSHIP LINE RD INDIANAPOLIS, IN 46260			
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT DEFICIENCY)	(X5) COMPLETION DATE	
E 0000	conducted by the Ir Health in accordance Survey Date: 03/08 Facility Number: 0 Provider Number: AIM Number: 100 At this Emergency Point Post-Acute R in substantial comp Preparedness Requ Medicaid Participar CFR 483.73. The facility has 133 the survey, the censure Quality Review con	200195 155298 267690 Preparedness survey, Pyramid ehabilitation Center was found liance with Emergency irements for Medicare and ring Providers and Suppliers, 42 5 certified beds. At the time of sus was 38. Impleted on 03/14/18 - DA 42 CFR, Subpart 483.73 is NOT	E 0000	The plan of correction constitute the facility's written credible allegation of compliance. Preparation and/or execution of this Plan of Correction does not constitute admission or agreemed by the provider of the truth of the facts alleged or the conclusion forth in the Statement of Deficiencies. This plan of correction is prepared and/or executed solely because it is required by the provisions of the health and safety code section 1280 and 42 CFR 483.	of to nent ne set	
E 0039 SS=C Bldg	failed to conduct explan at least annual staff drills using the LTC facility must oparticipate in a full-	view and interview, the facility tercises to test the emergency ly, including unannounced e emergency procedures. The lo all of the following: (i) escale exercise that is or when a community-based	E 0039	E039: 1. See attached Document (see below) which is the facilitie EP testing procedures for Emergency Response per Position and Emergency Event	es	

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

exercise is not accessible, an individual,

TITLE

Pyramid Point Post-Acute

(X6) DATE

Any defiency statement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: GFHC21 Facility ID: 000195 If continuation sheet Page 1 of 20

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/11/2018 FORM APPROVED OMB NO. 0938-039

Page 2 of 20

	IT OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155298	(X2) MULTIPLE C A. BUILDING B. WING	ONSTRUCTION	(X3) DATE SURVEY COMPLETED 03/08/2018
	ROVIDER OR SUPPLIER	UTE REHABILITATION CENTER	8530 T	ADDRESS, CITY, STATE, ZIP COD TOWNSHIP LINE RD NAPOLIS, IN 46260	
PYRAMIU (X4) ID PREFIX TAG	summary si (EACH DEFICIEN REGULATORY OR facility-based. If the actual natural or ma requires activation of LTC facility is exercommunity-based of full-scale exercise for the actual event; (ii) exercise that may in following: (A) a secommunity-based of a tabletop exercise that discussion led by a clinically-relevant e of problem statement prepared questions of emergency plan; (iii) response to and main drills, tabletop exercise that Director during record in accordant This deficient practice. Based on review of Plan" documentation Director during record 1:10 p.m. on 03/08/the facility's emergent twice within the modular was not available for at the time of record Director stated the facility based director activation of actual natural or main requires activation of the second	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION The LTC facility experiences an en-made emergency that of the emergency plan, the enterprise from engaging in a resolution in the enterprise for a conduct an additional clude, but is not limited to the end full-scale exercise that is resolution in the exercise that is resolution in the enterprise facility-based. (B) that includes a group facilitator, using a narrated, emergency scenario, and a set ents, directed messages, or designed to challenge and enterprise facility's emergency events, facility's emergency events, facility's emergency events, facility's emergency plan, as ce with 42 CFR 483.73(d)(2). The could affect all occupants. "Emergency Preparedness in with the Maintenance ord review from 9:25 a.m. to 18, documentation for testing ency preparedness program is trecent twelve month period or review. Based on interview is review, the Maintenance facility has not conducted is aster drills, experienced an in-made emergency plan or one exercise on the facility's			DATE DATE DATE DATE DATE DATE
	pian within the mos	t recent twelve month period.			

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: GFHC21 Facility ID: 000195 If continuation sheet

	NT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155298	X2) MULTIPLE CONSTRUCTION (X3) DATE A. BUILDING 01 COMPL B. WING 03/08/			ETED	
	PROVIDER OR SUPPLIED	CUTE REHABILITATION CENTER		8530 T	ADDRESS, CITY, STATE, ZIP COD OWNSHIP LINE RD APOLIS, IN 46260		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAL DEFICIENCY)	TE	(X5) COMPLETION DATE
TAG K 0000 Bldg. 01	A Life Safety Code Licensure Survey v State Department of CFR 483.90(a). Survey Date: 03/06 Facility Number: 0 Provider Number: 100 At this Life Safety Post-Acute Rehabil in compliance with in Medicare/Medic Life Safety from Fi National Fire Prote Life Safety Code (I Health Care Occup This three story fac Type II (222) const The facility has a fi detection in the cor the corridor. The fi smoke detectors in The facility has a c census of 38 at the All areas where res were sprinklered. buildings providing which were not spr	2000195 155298 267690 Code survey, Pyramid Point litation Center was found not Requirements for Participation aid, 42 CFR Subpart 483.90(a), re and the 2012 Edition of the ction Association (NFPA) 101, LSC), Chapter 19, Existing ancies and 410 IAC 16.2. Allity was determined to be of cruction and fully sprinklered. The alarm system with smoke ridors and in all areas open to acility has battery operated all resident sleeping rooms. The apacity of 135 and had a time of this visit.	K 00	TAG 000	The plan of correction constitute the facility's written credible allegation of compliance. Preparation and/or execution of this Plan of Correction does not constitute admission or agreed by the provider of the truth of the facts alleged or the conclusion forth in the Statement of Deficiencies. This plan of correction is prepared and/or executed solely because it is required by the provisions of the health and safety code section 1280 and 42 CFR 483.	of ot ment the n set	DATE

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: GFHC21 Facility ID: 000195 If continuation sheet Page 3 of 20

	IT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155298		ILDING	instruction <u>01</u>	COMPL	C3) DATE SURVEY COMPLETED 03/08/2018	
	PROVIDER OR SUPPLIER D POINT POST-AC	UTE REHABILITATION CENTER		8530 TC	ADDRESS, CITY, STATE, ZIP COD DWNSHIP LINE RD APOLIS, IN 46260			
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OR	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	ΓE	(X5) COMPLETION DATE	
K 0346 SS=C Bldg. 01	NFPA 101 Fire Alarm System Fire Alarm - Out o Where required fir services for more period, the authori be notified, and th evacuated or an a provided for all pa shutdown until the been returned to s 9.6.1.6 Based on record rev failed to provide a c protection of resider be followed in the e to be placed out of s in a twenty four hou	n - Out of Service of Service re alarm system is out of than 4 hours in a 24-hour tity having jurisdiction shall re building shall be pproved fire watch shall be rties left unprotected by the refire alarm system has service. The with the fire alarm system has review and interview, the facility complete written policy for the rust indicating procedures to revent the fire alarm system has service for four hours or more ar period in accordance with 6. This deficient practice	K 03		K346: 1. It is the policy of Pyrami Point Post-Acute Rehabilitation Center to properly notify the appropriate agencies per polici (see attachment #2) 2. All residents could be affected. 3. Policy has been up-date to reflect the appropriate	n y od	04/07/2018	
Based on review of "Emergency Procedure - Fire Watch" documentation with the Maintenance Director during record review from 9:25 a.m. to 1:10 p.m. on 03/08/18, the fire watch plan for fire alarm system impairment was incomplete. The plan failed to include contacting the Indiana State Department of Health via the ISDH Gateway link at https://gateway.isdh.in.gov as the primary method or by the secondary method when the ISDH Gateway is nonoperational by completing the Incident Reporting form and e-mailing it to incidents@isdh.in.gov. Based on interview at the time of record review, the Maintenance Director agreed the fire watch documentation for fire alarm system impairment did not state to contact the Indiana State Department of Health via the ISDH Gateway link or at the e-mail address listed above.				notification of State agencies of gateway. Executive Director at QAA Committee will monitor monthly/annually for up-dates. 4. The QAA Committee will review policy and procedures monthly/annually and all appropriate members will document/sign the review.	nd			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

GFHC21 Facility ID: 000195

If continuation sheet Page 4 of 20

	NT OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155298	A. BUILDING <u>01</u> COM		COMPL	TE SURVEY MPLETED 08/2018	
	PROVIDER OR SUPPLIER D POINT POST-AC	UTE REHABILITATION CENTER		STREET ADDRESS, CITY, STATE, ZIP COD 8530 TOWNSHIP LINE RD INDIANAPOLIS, IN 46260			
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID REFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	(X5) COMPLETION DATE
K 0353 SS=E Bldg. 01	Sprinkler System - Automatic sprinkle are inspected, tes accordance with N Inspection, Testing Water-based Fire Records of system inspection and tes secure location an a) Date sprinkler b) Who provided c) Water system Provide in REMAF coverage for any r automatic sprinkle 9.7.5, 9.7.7, 9.7.8, 1. Based on record interview; the facili fire hydrants were contested periodically. Standard for the Ins Maintenance of Wa Systems, Table 7.1. hydrants to be inspendent of the insertion of the insertion of the inspendent of the insertion. This def residents, staff and the insertion of the insertion. This def residents, staff and the insertion of the ins	supply source RKS information on non-required or partial r system. and NFPA 25 review, observation and try failed to ensure all private ontinuously maintained in ondition and inspected and NFPA 25, 2011 Edition, the pection, Testing, and ter-Based Fire Protection 1.2 requires wet and dry barrel exted annually and after each icient practice affects all	K 03:	53	K 353 1. It is the policy of Pyrami Point Post-Acute Rehabilitatio Center to have fire hydrants te at a minimum of annually and operation. Also curtains will no block sprinkler heads for 18 inches from ceiling, from proproperation. 2. All residents could be potentially affected. 3. The fire hydrants were tested 3/22/18, and curtains removed from the shower area the bath house room.	n ested after ot	04/07/2018

NAME OF PROVIDER OR SUPPLIER PYRAMID POINT POST-ACUTE REHABILITATION CENTER STREET ADDRESS, CITY, STATE, ZIP COD 8530 TOWNSHIP LINE RD INDIANAPOLIS, IN 46260	
l '	
TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
03/28/16 with the Maintenance Director during record review from 9:25 a.m. to 1:10 p.m. on 03/08/18, documentation of fire hydrant inspection within the most recent twelve month period was not available for review. Based on interview at the time of record review, the Maintenance Director stated documentation of fire hydrant inspection within the most recent twelve month period was not available for review. Based on observations with the Maintenance Director and the Van Driver/Maintenance Assistant from 1:10 p.m. to 3:00 p.m. on 03/08/18, the facility has two fire hydrants. 3.1-19(b) 2. Based on observation and interview, the facility failed to ensure clearance of at least 18 inches was maintained below the level of the sprinkler deflectors in 1 of over 50 rooms. NFPA 25, 2011 Edition, Section 5.2.1.2 states the minimum clearance required by the installation standard shall be maintained below all sprinkler deflectors. Further NFPA 13, Standard for the Installation of Sprinkler Systems, 2010 edition, Section 8.6.5.2.2 attaste the sittance from sprinklers to privacy curtains in light hazard occupancies shall be in accordance with Table 8.6.5.2.2 and Figure 8.6.5.2.2. Istates, in light hazard occupancies, privacy curtains shall not be considered obstructions where all of the following are met: (1) The curtains are supported by fabric mesh on ceiling track. (2) Openings in the mesh are equal to 70 percent or greater.	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

GFHC21 Facility ID: 000195

If continuation sheet Page 6 of 20

		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155298	(X2) MULTIPLE A. BUILDING B. WING	CONSTRUCTION 01	(X3) DATE COMPI 03/08	LETED
	PROVIDER OR SUPPLIER D POINT POST-AC	UTE REHABILITATION CENTER	8530	T ADDRESS, CITY, STATE, ZIP COD TOWNSHIP LINE RD ANAPOLIS, IN 46260		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPR DEFICIENCY)	TION D BE OPRIATE	(X5) COMPLETION DATE
	down from the ceilin NFPA 25, Section 2 noncontinuous obstr 18 inches below the the spray pattern frod deficient practice costaff and visitors in the third floor. Finding includes: Based on observation Director and the Var Assistant from 1:10 the privacy curtain in House on the third frod with the top of the 18 inches from the control provided with a from sprinkler cover Bath House outside interview at the time Maintenance Direct aforementioned privates provided with a from the ceiling. 3.1-19(b)	ds a minimum of 22 inches ing. 5-5.5.1 says a continuous or ruction less than or equal to sprinkler deflector prevents om fully developing. This ould affect over 10 residents, the vicinity of Bath House on				
K 0354 SS=C Bldg. 01	extent and duratio been determined, are inspected and recommendations management or de	Out of Service or system is impaired, the n of the impairment has areas or buildings involved risks are determined,				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

GFHC21 Facility ID: 000195

If continuation sheet

Page 7 of 20

	IENT OF DEFICIENCIES AN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155298	· ′	JILDING	ONSTRUCTION 01	(X3) DATE COMPI 03/08	LETED
	OF PROVIDER OR SUPPLIE MID POINT POST-AC	R CUTE REHABILITATION CENTER		8530 T	ADDRESS, CITY, STATE, ZIP COD OWNSHIP LINE RD APOLIS, IN 46260		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI/ DEFICIENCY)	ATE	(X5) COMPLETION DATE
	the sprinkler syste than 10 hours in a building or portion evacuated or an a provided until the returned to service 18.3.5.1, 19.3.5.1 Based on record refailed to provide a containing procedu protection of 38 of automatic sprinkler out-of-service for 1 period in accordant 9.7.5 requires sprincomply with NFPA for the Inspection, Water-Based Fire 15.5.2 requires nimi impairment coording deficient practice of and visitors. Findings include: Based on review of Watch" documenta Director during recent 1:10 p.m. on 03/08 sprinkler system in plan failed to inclu Department of Heat at https://gateway.imethod or by the set ISDH Gateway is rethe Incident Report incidents@isdh.in.plan for sprinkler in plan for sprinkler in pla	in have been notified. Where them is out of service for more as 24-hour period, the in of the building affected are approved fire watch is sprinkler system has been bee. 1, 9.7.5, 15.5.2 (NFPA 25) wiew and interview, the facility complete written policy them in the event them is as residents in the event them is system has to be placed to hours or more in a 24-hour concern with LSC, Section 9.7.5. LSC abler impairment procedures as 25, 2011 Edition, the Standard Testing and Maintenance of Protection Systems. NFPA 25, the procedures that them is procedures that them is procedures that them is procedure and them is suffered to the system of the system o	K 0:	354	K354 1. It is the policy of Pyram Point Post-Acute Rehabilitatic Center to have in the Fire Wa policy the appropriate State Notification for a Fire Watch. 2. All residents affected. 3. The policy has been up-dated to reflect the ISDH gateway website and email to notify the State of Indiana of a watch situation. (see attachm #3) 4. The QAA Committee w review Policy and Procedures Emergency Plan monthly/ann and all appropriate members document/sign the review.	on tch a fire ent ill s of ually	04/07/2018

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION			NSTRUCTION	(X3) DATE	SURVEY		
AND PLAN (OF CORRECTION	IDENTIFICATION NUMBER	A. BUILDING <u>01</u> COMPLET		ETED		
		155298	B. WI	NG		03/08/	2018
				CTREET A	DDDECC CITY CTATE ZID COD		
NAME OF P	ROVIDER OR SUPPLIER				ADDRESS, CITY, STATE, ZIP COD DWNSHIP LINE RD		
		LITE DELIADII ITATION CENTED					
PTRAWIL	POINT POST-AC	UTE REHABILITATION CENTER		INDIAN	APOLIS, IN 46260		
(X4) ID	SUMMARY S	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	ΓE	COMPLETION
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)	-	DATE
	building owner. Ba	sed on interview at the time of					
	record review, agree	ed the fire watch					
	documentation for s	prinkler system impairment					
	did not state to conta	act the Indiana State					
	Department of Heal	th via the ISDH Gateway link					
	or at the e-mail addr	ress listed above and did not					
	state to contact the i	insurance carrier and the					
	building owner.						
	3.1-19(b)						
K 0363	NFPA 101						
SS=E	Corridor - Doors						
Bldg. 01	Corridor - Doors						
		corridor openings in other					
	than required encl	osures of vertical openings,					
	exits, or hazardous	s areas resist the passage					
	of smoke and are	made of 1 3/4 inch					
		wood or other material					
	•	g fire for at least 20					
		fully sprinklered smoke					
		only required to resist the					
		e. Corridor doors and doors					
	to rooms containing	_					
		rials have positive latching					
		atches are prohibited by					
	_	hese requirements do not					
	apply to auxiliary s	spaces that do not contain					
	flammable or com	bustible material.					
	Clearance betwee	n bottom of door and floor					
	covering is not exc	ceeding 1 inch. Powered					
		vith 7.2.1.9 are permissible					
	if provided with a	device capable of keeping					
		hen a force of 5 lbf is					
		no impediment to the					
	•	rs. Hold open devices that					
		door is pushed or pulled are					
	•	ed protective plates of					
		re permitted. Dutch doors					
	meeting 19.3.6.3.6	6 are permitted. Door					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

GFHC21 Facility ID: 000195

If continuation sheet Page 9 of 20

STATEMEN	T OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION (X3) DATE S		SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	ILDING	01	COMPL	ETED
		155298	B. WI	NG		03/08/	2018
NAME OF P	ROVIDER OR SUPPLIER	:			ADDRESS, CITY, STATE, ZIP COD		
PYRAMI	D POINT POST-AC	UTE REHABILITATION CENTER			APOLIS, IN 46260		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	other materials in unless the smoke sprinklered. Fixed allowed per 8.3. In there are no restrict resistance of glass assemblies. 19.3.6.3, 42 CFR 1483, and 485 Show in REMARK fire protection rating devices, etc. Based on observation failed to ensure 1 of provided with a meadoor closed, had no latching and would This deficient practice residents staff and work occupational Therest Findings include: Based on observation Director and the Variance Assistant from 1:10 the corridor door to Room on the first floopen position with a under the door. Based the observations, the agreed the door had	compliance with 8.3, compartment is fire window assemblies are a sprinklered compartments ctions in area or fire or frames in window Parts 403, 418, 460, 482, and interview, the facility over 50 corridor doors were ans suitable for keeping the impediment to closing, resist the passage of smoke. It is could affect over five initions in the vicinity of the py Room on the first floor. The with the Maintenance or more publication of the more publication of the following proposed in the fully a wedge placed on the floor and impediment to closing, not resist the passage of	K 03	363	K 363: 1. It is the policy of Pyrami Point Post-Acute Rehabilitatio Center to have Corridor Doors close correctly and are not impediment prevent door form closing correctly 2. Only residents who wou be in Occupational Therapy rowould be affected. 3. Impediment was immediately removed during survey by Maintenance. Maintenance Director or Desigwill check doors for impediment times a week for 2 months or 100% compliance achieved affeonths. Staff will be in-service use if impediments to keep do opened. 4. Findings will be brought the QAA Committee for review further evaluation if needed	n that Id om Inee ots 3 Iter 2 od on ors Ito	04/07/2018

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

GFHC21 Facility ID: 000195

If continuation sheet Page 10 of 20

NAME OF PROVIDER OR SUPPLIER PYRAMID POINT POST-ACUTE REHABILITATION CENTER (CX4) ID PREFIX TAO SUMMARY STATEMENT OF DEFICIENCY TAO REGULATORY OR LSC IDENTIFYING INFORMATION K 0531 NFPA 101 Elevators Elevators Elevators Elevators comply with the provision of 9.4. Elevators comply with the provision of 9.4. Elevators and Escalators. All existing elevators or below the level that best serves the needs of emergency personnel for firefighter's Service Requirements of ASME/ANSI A17.3, Safety Code for Elevators and Escalators. All existing elevators having a travel distance of ASME/ANSI A17.3, (Includes firefighter's service Phase I key recall and smoke detector automatic recall, firefighter's service Phase I key recall and existed and interview; the facility failed to document testing of 2 of 2 clevator freshight's service recall in accordance with 9.4.6, Elevator Testing. LSC 9.4.6.2 states that all elevators with fire fighters' emergency operations in accordance with 9.4.5 alsals that all elevators with fire fighters' emergency operations in accordance with 9.4.3 shall be subject to a monthly operation with a written record of the findings made and kept on the premises as required by ASME A17.1/CSA B44, Safety Code for Elevators and Escalators. This deficient practice could affect over five residents, staff and visitors. Endings include: STREET ADDRESS OWNSHIP LINE RD ID MONANAPOLIS, IN 462600 DATE TAG STREET ADDRESS CITY, STATE, 20 COMPLETION PROFITS AND ASSOCIATION ASSOCIATION ASSOCIATION AND ASSOCIATION AND ASSOCIATION ASSOCIATION ASSOCIATION ASSOCIATION ASSOCIATION ASSOCIATION ASSOCIATION ASSOCIATION ASSOC		T OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155298	(X2) MULTIPLE CO A. BUILDING B. WING	ONSTRUCTION 01	(X3) DATE SURVEY COMPLETED 03/08/2018
PREFIX TAG REGULATORY OR ISC IDENTIFYING INFORMATION K 0531 NFPA 101 Elevators Elevators Elevators Elevators 2012 EXISTING Elevators are inspected and tested as specified in ASME A17.1, Safety Code for Elevators and Escalators. Firefighter's Service is operated monthly with a written record. Existing elevators conform to ASME/ANSI A17.3, Safety Code for Existing Elevators and Escalators. All existing elevators and Escalators. This deficient practice could affect over five residents, staff and visitors. PREFIX TAG P				8530 T	OWNSHIP LINE RD	
Elevators Elevators Elevators Elevators Elevators 2012 EXISTING Elevators comply with the provision of 9.4. Elevators are inspected and tested as specified in ASME A17.1, Safety Code for Elevators and Escalators. Firefighter's Service is operated monthly with a written record. Existing elevators conform to ASME/ANSI A17.3, Safety Code for Existing Elevators and Escalators. All existing elevators having a travel distance of 25 feet or more above or below the level that best services the needs of emergency personnel for firefighting purposes, conform with Firefighter's service Phase I key recall and smoke detector automatic recall, firefighter's service Phase I emergency in-car key operation, machine room smoke detectors, and elevator lobby s	PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	COMPLETION
4. Findings will be reported to	SS=E	Elevators Elevators 2012 EXISTING Elevators comply of Elevators are inspecified in ASME Elevators and Esconservice is operate record. Existing elevators A17.3, Safety Cod and Escalators. All a travel distance of below the level that emergency persor purposes, conform Requirements of A (Includes firefighter's service key operation, madetectors, and eledetectors.) 19.5.3, 9.4.2, 9.4.3 Based on record revinterview; the facility 2 of 2 elevator firefighter's cordance with 9.4 9.4.6.2 states that all emergency operations shall be subject to a written record of the the premises as requirements as requirements as requirements.	ected and tested as A17.1, Safety Code for alators. Firefighter's d monthly with a written conform to ASME/ANSI le for Existing Elevators I existing elevators, having of 25 feet or more above or at best serves the needs of anel for firefighting n with Firefighter's Service ASME/ANSI A17.3. er's service Phase I key detector automatic recall, e Phase II emergency in-car chine room smoke vator lobby smoke 3 riew, observation and ty failed to document testing of ighter's service recall in 6, Elevator Testing. LSC I elevators with fire fighters' as in accordance with 9.4.3 monthly operation with a e findings made and kept on aired by ASME A17.1/CSA or Elevators and Escalators. fice could affect over five	K 0531	It is the policy of Pyram Point Post-Acute Rehabilitatio Center to have documented firefighter's service recall test per regulation All residents could be affected. Firefighter's service call System is to be inspected by Elevator company on a month basis and findings reported to Maintenance Director or Designation.	id in ed ally gnee.

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

GFHC21 Facility ID: 000195

If continuation sheet Page 11 of 20

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/11/2018 FORM APPROVED OMB NO. 0938-039

	T OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155298		ILDING	nstruction <u>01</u>	(X3) DATE COMPL 03/08 /	ETED
	ROVIDER OR SUPPLIER	UTE REHABILITATION CENTER		8530 TC	DDRESS, CITY, STATE, ZIP COD DWNSHIP LINE RD APOLIS, IN 46260		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	•	CY MUST BE PRECEDED BY FULL]	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	ГЕ	COMPLETION
TAG		LISC IDENTIFYING INFORMATION View with the Maintenance		TAG	QAA Committee on a monthly		DATE
	Director during reco	ord review from 9:25 a.m. to			basis for further input as need	ed.	
	-	18, documentation of monthly					
	_	recall testing for the most					
		h period was not available for observations with the					
	Maintenance Direct						
		e Assistant from 1:10 p.m. to					
		18, the facility has two					
	elevators equipped with firefighter's service recall. Thyssen Krupp had "Hydraulic Maintenance Task" documentation for each elevator in the elevator machine room which documented monthly inspections for each elevator but the						
	documentation did not include monthly						
		recall testing. Based on					
		e of record review and of the					
		aintenance Director stated the					
		rform elevator recall testing					
		actor checks and agreed service recall testing could					
		oth elevators during the most					
	recent twelve month	-					
	3.1-19(b)						
K 0712	NFPA 101						
SS=F	Fire Drills						
Bldg. 01	Fire Drills						
		the transmission of a fire					
		simulation of emergency fire ills are held at expected					
		mes under varying					
	-	t quarterly on each shift.					
		r with procedures and is					
		re part of established					
	routine. Where dr 9:00 PM and 6:00	rills are conducted between					
		ay be used instead of					
	audible alarms.	.,					
			1				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

GFHC21 Facility ID: 000195

If continuation sheet

Page 12 of 20

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLI		X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY		
AND PLAN	AND PLAN OF CORRECTION IDENTIFICATION NUMBER		A. BUILDING <u>01</u>			COMPLETED		
	155298		B. WI	B. WING			03/08/2018	
		l .		CTDEET /	ADDRESS, CITY, STATE, ZIP COD	<u> </u>		
NAME OF P	ROVIDER OR SUPPLIER	₹			OWNSHIP LINE RD			
DVDAMI		UTE REHABILITATION CENTER			IAPOLIS, IN 46260			
I IIVAIVIIL	51 OINT 1 OS1-AC	OTE REHABIEITATION CENTER		IIIDIAII				
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	(EACH DEFICIEN	ICY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION	
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE	
	19.7.1.4 through 1							
		review and interview, the	K 0'	712	K 712:		04/07/2018	
		ovide documentation of a fire			1. It is the policy of Pyrami	d		
	drill conducted on t	the third shift for 1 of 4			Point Post-Acute Rehabilitatio	n		
	_	cient practice affects all			Center to have fire drills condu	ıcted		
	residents, staff and	visitors.			monthly at different times on			
					different shifts throughout the	year.		
	Findings include:				All residents could be affected.			
	Based on review of	"Fire Drill Report Form"			3. Executive Director and			
		the Maintenance Director			QAA Committee will do audits	to		
	during record revie	w from 9:25 a.m. to 1:10 p.m. on			insure that drills are conducted			
	_	tation of a fire drill conducted			monthly and at different times			
	on the third shift for	r the third quarter of 2017 was			through out the year.			
	not available for rev	view. Based interview at the			4. QAA committee will			
	time of record revie	ew, the Maintenance Director			monitor monthly for compliance	e		
	stated a fire drill for	r that shift and quarter was			and make recommendations a	ıs		
	conducted but agree	ed documentation of a fire drill			needed.			
	conducted on the af	forementioned shift and						
	quarter was not ava	ilable for review.						
	3.1-19(b)							
		review and interview, the						
	•	nduct quarterly fire drills at						
	_	nder varying conditions on the						
		f 4 quarters. This deficient						
	_	et all residents, staff and						
	visitors.							
	Findings include:							
	Themes merue.							
	Based on review of "Fire Drill Report Form"							
	documentation with the Maintenance Director							
	during record review	w from 9:25 a.m. to 1:10 p.m. on						
	_	nift fire drills conducted on						
		, 08/31/17 and 11/30/17 were						
		ctively, 2:25 p.m., 2:00 p.m.,						
	_	p.m. Based on interview at the						
	_	ew, the Maintenance Director						

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION (X3) DATE S			SURVEY	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER	A. BUILDING <u>01</u>			COMPLETED	
155298		B. WING 03/08/2018					
				STREET A	ADDRESS, CITY, STATE, ZIP COD		
NAME OF P	ROVIDER OR SUPPLIER				DWNSHIP LINE RD		
PYRAMIC	POINT POST-AC	UTE REHABILITATION CENTER			APOLIS, IN 46260		
(X4) ID	SUMMARY S	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	ΓE	COMPLETION
TAG		LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	•	ntioned second shift fire drills					
		at unexpected times under					
	varying conditions.						
	3.1-19(b)						
K 0918	NFPA 101						
SS=F		s - Essential Electric Syste					
Bldg. 01	•	s - Essential Electric					
-	System Maintenar						
	The generator or	other alternate power					
	source and associ	ated equipment is capable					
		ce within 10 seconds. If the					
		n is not met during the					
	•	ocess shall be provided to					
		his capability for the life					
		branches. Maintenance					
	_	generator and transfer					
	NFPA 110.	rmed in accordance with					
		e inspected weekly,					
		oad 30 minutes 12 times a					
	•	intervals, and exercised					
		nths for 4 continuous hours.					
		der load conditions include					
	a complete simula	ual transfer of all EES					
		nducted by competent					
		nance and testing of stored					
	•	rces (Type 3 EES) are in					
	•••	IFPA 111. Main and feeder					
		e inspected annually, and a					
		dically exercising the					
		ablished according to					
	manufacturer requ	irements. Written records					
		nd testing are maintained					
	•	ole. EES electrical panels					
		arked, readily identifiable,					
	•	normal power circuits.					
	Minimizing the pos	ssibility of damage of the					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

GFHC21 Facility ID: 000195

If continuation sheet Page 14 of 20

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155298			JILDING	onstruction 01	(X3) DATE COMPI 03/08/	LETED	
	PROVIDER OR SUPPLIEF	UTE REHABILITATION CENTER		8530 TO	ADDRESS, CITY, STATE, ZIP COD OWNSHIP LINE RD APOLIS, IN 46260		
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OF	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	ATE	(X5) COMPLETION DATE
	emergency power consideration for r 6.4.4, 6.5.4, 6.6.4 NFPA 111, 700.10 1. Based on record facility failed to do the generator for 1 or requirements of NF Standard for Emerg Systems, Chapter 8 generator sets in set once monthly, for a one of the following (1) Loading that magas temperatures as manufacturer (2) Under operating not less than 30 per Power Supply) nam Section 8.4.2.3 state installations that do 8.4.2 shall be exerc EPSS (Emergency) shall be exercised a loads at not less than nameplate kW ratin and at not less than nameplate kW ratin total test duration o hours. This deficie residents, staff and Findings include: Based on review of documentation with during record review of 3/08/18, monthly 10 December 2017 wa	resource is a design new installations. (NFPA 99), NFPA 110, 10 (NFPA 70) review and interview, the rument the facility exercised of 12 months to meet the PA 110, 2010 Edition, the ency and Standby Powers 4.2. Section 8.4.2 states diesel vice shall be exercised at least minimum of 30 minutes, using gmethods: aintains the minimum exhaust recommended by the recommended by the remperature conditions and at cent of the EPS (Emergency replate kW rating. The sed diesel-powered EPS not meet the requirements of itsed monthly with the available recommended by the resolution of the EPS grown of the EPS g	K 0	918	K918: 1. It is the policy of Pyram Point Post-Acute rehabilitation Center to test monthly the Generator, recording findings a 30% load test at least once yearly 2. All residents could be affected. 3. Test will be conducted monthly as specified in regular and findings recorded by Maintenance and a load test who be performed annually by contractor to insure proper load test is performed. Batter for the generator have been ordered by Maintenance. Repfrom vendor will be reviewed Executive Director for items needing replaced. 4. Findings will be present to the QAA Committee for revenonthly and as needed for furecommendations.	and and ation will ries ports with	04/07/2018

	T OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155298	(X2) MUL' A. BUIL B. WINC	DING	NSTRUCTION 01	(X3) DATE (COMPL 03/08/	ETED
NAME OF PROVIDER OR SUPPLIER PYRAMID POINT POST-ACUTE REHABILITATION CENTER				8530 TO	DDRESS, CITY, STATE, ZIP COD WNSHIP LINE RD APOLIS, IN 46260		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	PR	ID REFIX FAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	ΓE	(X5) COMPLETION DATE
TAG	the Maintenance Diconducted a monthle but load testing doc was not available for 3.1-19(b) 2. Based on record interview; the facility generator annually to NFPA 110, 2010 Edit Emergency and States. Section 8.4.2 Service shall be exert for a minimum of 3 following methods: (1) Loading that magas temperatures as manufacturer (2) Under operating not less than 30 per Power Supply) name Section 8.4.2.3 states installations that do 8.4.2 shall be exercised a loads (Load Bank Tof the EPS namepla minutes and at not 1 nameplate kW ratin total test duration of	rector stated the facility y load test in December 2017 umentation for the load test or review. review, observation and ty failed to exercise the to meet the requirements of dition, the Standard for ndby Powers Systems, Section e states diesel generator sets in reised at least once monthly, 0 minutes, using one of the unitains the minimum exhaust recommended by the g temperature conditions and at cent of the EPS (Emergency heplate kW rating. The se diesel-powered EPS not meet the requirements of fised monthly with the available review Supply System) load and nunually with supplemental fest) at not less than 50 percent the kW rating for 30 continuous tess than 75 percent of the EPS g for 1 continuous hour for a f not less than 1.5 continuous ant practice could affect all		TAG	DEFICIENCY		DATE
	documentation with	"Weekly Generator Test" the Maintenance Director w from 9:25 a.m. to 1:10 p.m. on					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

GFHC21 Facility ID: 000195

If continuation sheet

Page 16 of 20

AND PLAN OF CORRECTION AND PLAN OF CORRECTION 155298		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING			(X3) DATE SURVEY COMPLETED 03/08/2018				
	ROVIDER OR SUPPLIER	UTE REHABILITATION CENTER	STREET ADDRESS, CITY, STATE, ZIP COD 8530 TOWNSHIP LINE RD INDIANAPOLIS, IN 46260						
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	(X5) COMPLETION DATE			
	the twelve month per February 2018 did not conducted under load minimum exhaust grecommended by the operating temperatures than 30 percent rating. Monthly load December 2017 was In addition, annual adocumentation with month period was a Based on interview the Maintenance Ditested under load or documentation does achieves 30% of the supplemental load to also not available for observations with the Van Driver/Mai p.m. to 3:00 p.m. or to the diesel fired grat 175 kW. 3.1-19(b) 3. Based on record interview; the facility batteries for the emmaintained in accord NFPA 110, 2010 Edemergency and States Section 5.6.4.5.5 states service shall have be shall have demonstrated in accord authority having juriside and read authority having juriside states and supplementation and read authority having juriside states.	the manufacturer or under the conditions achieving not at of the EPS nameplate kW and testing documentation for a salso not available for review. Supplemental load testing the most recent twelve also not available for review. The time of record review, at the time of record review, rector stated the generator is							

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

GFHC21 Facility ID: 000195

If continuation sheet Page 17 of 20

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155298		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING			(X3) DATE SURVEY COMPLETED 03/08/2018			
	ROVIDER OR SUPPLIER D POINT POST-AC	UTE REHABILITATION CENTER	STREET ADDRESS, CITY, STATE, ZIP COD 8530 TOWNSHIP LINE RD INDIANAPOLIS, IN 46260					
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT DEFICIENCY)	Έ	(X5) COMPLETION DATE	
	exercising, operatio maintained and read	em (EPSS) inspections, tests, in and repairs shall be lily available. This deficient t all residents, staff and						
	1 Inspection" document the Maintenance Diffrom 9:25 a.m. to 1: need replace due to the time of record reductor stated the semergency generated or after 03/05/18, the replaced but document or proposal for replaced but document or proposal for replaced but document of a variable for observations with the Van Driver/Mai p.m. to 3:00 p.m. or	ne Maintenance Director and ntenance Assistant from 1:10 n 03/08/18, documentation g batteries indicated they						
K 0920 SS=E Bldg. 01	Extens Electrical Equipme Extension Cords Power strips in a pused for compone patient-care-relate (PCREE) assemble assembled by qua the conditions of 1	d electrical equipment						

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

GFHC21 Facility ID: 000195

If continuation sheet

Page 18 of 20

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION (X3) DATE SUR				SURVEY	
AND PLAN OF CORRECTION IDENTIFICATION NUMBER		A. BUILDING <u>01</u> CC			COMPL	COMPLETED	
		155298	B. WING 03/08/2018				
NAME OF PROVIDER OR SUPPLIER PYRAMID POINT POST-ACUTE REHABILITATION CENTER				8530 TO	ADDRESS, CITY, STATE, ZIP COD DWNSHIP LINE RD APOLIS, IN 46260		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID			(X5)
					PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE		
	`				CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	
PREFIX TAG	non-PCREE (e.g., except in long-terr do not use PCREE meet UL 1363A or for non-PCREE in (outside of vicinity non-patient care rother UL standard used with general cords are not used wiring of a structur temporarily are recompletion of the installed and meet 10.2.3.6 (NFPA 99 (NFPA 70), 590.30 Based on observation failed to ensure 1 of power strips were not fixed wiring. LSC comply with Section electrical wiring and NFPA 70, National NFPA 70, Article 4 specifically permitted shall not be used as a structure. LSC Seservice equipment of safety shall be design accordance with NFPA 99, Standard	CY MUST BE PRECEDED BY FULL LESC IDENTIFYING INFORMATION personal electronics), in care resident rooms that E. Power strips for PCREE if UL 60601-1. Power strips the patient care rooms) meet UL 1363. In coms, power strips meet is. All power strips are precautions. Extension d as a substitute for fixed if it. Extension cords used moved immediately upon purpose for which it was its the conditions of 10.2.4. Equipolate (D) (NFPA 70), TIA 12-5 on and interview, the facility if 1 extension cords including of used as a substitute for 19.5.1 requires utilities to in 9.1. LSC 9.1.2 requires d equipment to comply with Electrical Code, 2011 Edition. 00.8 requires that, unless ed, flexible cords and cables a substitute for fixed wiring of percent in the cords and provided for life great, installed and approved all applicable NFPA standards. for Health Care Facilities, 2012 ent care areas as any portion	K 0	PREFIX TAG	K920; 1. It is the policy of Pyrami Point Post-Acute rehabilitation Center to not use power strips those items in resident room to are for non patient care-relate electrical equipment. 2. All residents could be affected. 3. Maintenance has remove the power strip in question from room. Rooms will be randomly checked 3 times a week by Maintenance Director or Design for compliance	dd a for hat d	COMPLETION DATE 04/07/2018
		lity wherein patients are			 Findings will be brought QAA Committee Monthly for 		
		nined or treated. Patient care			review and for other		
		s a space, within a location			recommendations as needed.		
	· ·	umination and treatment of			. 555/////oridations do nooded.		
		6 ft (1.8 m) beyond the normal					
		chair, table, treadmill, or other					
	device that supports						
		eatment. A patient care vicinity					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

GFHC21 Facility ID: 000195

If continuation sheet Page 19 of 20

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/11/2018 FORM APPROVED OMB NO. 0938-039

	STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155298		X2) MULTIPLE CONSTRUCTION A. BUILDING D1 B. WING			(X3) DATE SURVEY COMPLETED 03/08/2018	
NAME OF PROVIDER OR SUPPLIER PYRAMID POINT POST-ACUTE REHABILITATION CENTER				8530 T	ADDRESS, CITY, STATE, ZIP COD DWNSHIP LINE RD APOLIS, IN 46260		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI, DEFICIENCY)	(X5) COMPLETION DATE	
	floor. NFPA 99, or office appliance grounding conduct be permitted proven the patient care vicould affect over the vicinity of Rosensia and the vicinity of the observation agreed a power structure for fixe	to 7 ft 6 in. (2.3 m) above the Section 10.4.2.3 states household es not commonly equipped with stors in their power cords shall ided they are not located within cinity. This deficient practice 10 residents, staff and visitors in om 332. It ions with the Maintenance Van Driver/Maintenance 10 p.m. to 3:00 p.m. on 03/08/18, a lugged into a power strip placed eet from the resident bed in JL listing of the power strip could 1. Based on interview at the time is, the Maintenance Director rip was being used as a d wiring in the patient care rementioned location.					

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: GFHC21 Facility ID: 000195 If continuation sheet Page 20 of 20