OT 1 TE 1	TO OF DEFICIENT AND A	NATIONAL PROPERTY OF THE PROPE	772.3	II MIDI D	NAMEDIACETONI	7/2) F : ==	CLIDATEN	
STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	A. BUILDING		COMPLETED		
		155207	B. WING			03/05/2025		
	PROVIDER OR SUPPLIER		•	1201 D	ADDRESS, CITY, STATE, ZIP COD ALY DRIVE			
MAJEST	IC CARE OF NEW	HAVEN		INEVV I	AVEN, IN 46774			
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	ATE	COMPLETION	
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE	
E 0000								
Bldg	An Emergency Preparedness Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.73. Survey Date: 03/05/25. Facility Number: 000114 Provider Number: 155207 AIM Number: 100266640 At this Emergency Preparedness survey, Majestic Care of New Haven was found in substantial compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73. The facility has a capacity of 120 and had a census of 69 at the time of this survey.		E 00	000	Preparation and/or execution of this plan do not constitute admission or agreement by the provider that a deficiency exists. This response is also not to be construed as an admission of fault by the facility, its employees, agents or other individuals who draft or may be discussed in this response and plan of correction. This plan of correction is submitted as the facility's credible allegation of compliance. The facility is requesting a Paper Compliance review.			
E 0037 SS=C Bldg	Quality Review completed on 03/06/25 403.748(d)(1), 416.54(d)(1), 418.113(d)(EP Training Program Based on record review and interview, the facility failed to conduct annual training and testing for the Emergency Preparedness Program (EPP). The LTC facility must do all of the following: (i) Initial training in emergency preparedness policies and procedures to all new and existing staff, individuals providing services under arrangement, and volunteers, consistent with their expected roles; (ii) Provide emergency preparedness training at least annually; (iii) Maintain documentation of all emergency preparedness training; (iv) Demonstrate staff knowledge of emergency procedures in accordance with 42 CFR 483.73(d) (1). This deficient practice could affect		E 00	E 0037 1 Immediate action(s) taker the resident(s) found to have the affected include: No residents were found to be affected by this deficient pract All staff were in-serviced regard the facility policy for Emergency Preparedness, including RACI and PASS, with return demonstration knowledge of the training. 2 Identification of other residents having the potential		been itice. rding cy E	03/18/2025	

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Lorri Maples Administrator 03/20/2025

Any defiency statement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclodays following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: ICOD21 Facility ID: 000114 If continuation sheet Page 1 of 10

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/21/2025 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155207		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 03/05/2025	
	ROVIDER OR SUPPLIER		1201 🛭	ADDRESS, CITY, STATE, ZIP COD DALY DRIVE HAVEN, IN 46774	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION acility.	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY) The facility has determined the residents have the notential to	DATE nat all
	Findings include: Based on records re and the Maintenance a.m., annual EPP st 05/22/24, but no do review to show if st knowledge of the E interview at the tim Maintenance Direct stated the EPP train last year but demon was not conducted. This finding was re	view with the Administrator e Director on 03/05/25 at 10:11 aff training was conducted on cumentation was available for aff could demonstrate PP training. Based on an e of records review, the or and the Administrator ing was conducted within the stration of knowledge for staff viewed with the Administrator irector during the exit		The facility has determined the residents have the potential to affected. 3 Actions taken/systems into place to reduce the risk future occurrence include: All staff were in-serviced regard the facility policy for Emerger Preparedness, including RAC and PASS, with return demonstration knowledge of training. 4 How the corrective action(s) will be monitored to ensure the practice will not recur: The maintenance director completed the in-service with staff for the EPP training and return demonstration knowled. Anyone not passing the return demonstration was reeducated ensure knowledge of the EPP training and demonstrate as evidence. The maintenance director will incorporate this training in the weekly orientation of new hire that includes return demonstration. Anyone not passing the return demonstration will be reeducated to ensure knowledge of the EPP trainin demonstrate as evidenced. Inservice/orientation records be reviewed by the Safety Committee Until such time consistent substantial complia	put c of arding ncy CE the to all dge. rn ed to c l ees ation g and will ee
				has been achieved as determ	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

ICOD21

Facility ID: 000114

If continuation sheet

Page 2 of 10

AND PLAN OF CORRECTION IDENT		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER		(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
		155207	B. W			03/05/2025		
	ROVIDER OR SUPPLIER			1201 D	ADDRESS, CITY, STATE, ZIP COD ALY DRIVE AVEN, IN 46774			
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE			ID	DDOVIDEDIC DI AN OE CODDECTION		(X5)	
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TF.	COMPLETION	
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE	
					by the committee.			
K 0000								
Bldg. 01								
Bldg. 01	Licensure Survey w Department of Heal 483.90(a). Survey Date: 03/05 Facility Number: 0 Provider Number: 1002 At this Life Safety O Haven Center was f Requirements for Pa	00114 155207 266640 Code survey, Majestic Care of Cound not in compliance with articipation in	K 0	000	Preparation and/or execution this plan do not constitute admission or agreement by the provider that a deficiency exist. This response is also not to be construed as an admission of by the facility, its employees, agents or other individuals where different terms and plan of corrections. This plan of correction is submitted as the facility's creat allegation of compliance. The facility is requesting a	e ts. e fault o his		
	Life Safety from Fin National Fire Protec Life Safety Code (L	, 42 CFR Subpart 483.90(a), re and the 2012 edition of the etion Association (NFPA) 101, .SC), Chapter 19, Existing ancies and 410 IAC 16.2.			Paper Compliance review.			
	Type V (000) constructions sprinklered. The faction with smoke detection to the corridors and operated smoke detection facility is partial forward of the facility is partial forward	ity was determined to be of ruction and was fully cility has a fire alarm system on in the corridors, areas open single station battery ector in the resident rooms. Ally protected by a Type II EES red generator. The facility has a had a census of 69 at the time residents have customary ered. All areas providing						
	facility services wer	re sprinklered which the thed building housing the						

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

ICOD21 Facility ID: 000114

If continuation sheet Page 3 of 10

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155207		(X2) MULTIPLE CO A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 03/05/2025		
NAME OF PROVIDER OR SUPPLIER MAJESTIC CARE OF NEW HAVEN		STREET ADDRESS, CITY, STATE, ZIP COD 1201 DALY DRIVE NEW HAVEN, IN 46774				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL . LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE	
K 0100 SS=E	maintenance equipm Quality Review com NFPA 101	npleted on 03/06/25				
Bldg. 01	failed to maintain last smoke barrier doors life safety features or required by the Cod removed. This deficience residents in two smooth frindings include: Based on observation Director on 03/05/2 barrier doors by rooth latching hardware by when tested. Based observation, the Master smoke doors were earned the doors did not this finding was revenue.	on and interview, the facility atching hardware on 1 of 5. LSC 4.6.12.3 requires existing obvious to the public if not e, shall be either maintained or cient practice could affect 30	K 0100	1 Immediate action(s) taker the resident(s) found to have a affected include: Fire door vendor was called in inspect smoke barrier doors be room 108. The problem was found corrected at the time of service. 2 Identification of other residents having the potential be affected was accomplished. The facility has determined the residents have the potential to affected. 3 Actions taken/systems printo place to reduce the risk future occurrence include: Maintenance was in-serviced the Administrator to perform weekly/monthly preventative maintenance checks on all sm barrier doors to ensure they remain in good working order times. Fire door vendor was called in inspect smoke barrier doors be room 108. The problem was found corrected at time of service 4. How the corrective action(s) will be monitored to ensure the practice will not recur:	to y bund to d by: at all be but of by noke at all ito y bund ce.	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

ICOD21

Facility ID: 000114

If continuation sheet

Page 4 of 10

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/21/2025 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES		XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155207	(X2) MULTIPLE CO A. BUILDING B. WING	onstruction ;	(X3) DATE SURVEY COMPLETED 03/05/2025	
NAME OF PROVIDER OR SUPPLIER MAJESTIC CARE OF NEW HAVEN			1201 🗅	ADDRESS, CITY, STATE, ZIP COD DALY DRIVE HAVEN, IN 46774		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 0222 SS=E	NFPA 101			The maintenance director will complete weekly maintenance checks of smoke barrier doors is six (6) months, to ensure they a in good working order. Any doo found not to latch into the frame will be fixed immediately. Preventative maintenance check will be performed monthly thereafter. Weekly maintenance checks/documentation will be reviewed by the monthly Safety Committee/Quality Assurance Committee until such time consistent substantial complian has been achieved as determined by the committee.	are or es, cks	
Bldg. 01	facility failed to ens locking arrangemen with LSC 7.2.1.6.1(process shall release egress within 15 sec approved by the aut upon application of required in 7.2.1.5.1 conditions: (a) The force shall refer to the force shall recontinuously applie (c) The initiation of	rvation and Interview, the sure 1 of 6 delayed egress ats were installed in accordance (3) which states an irreversible the the lock in the direction of conds, or 30 seconds where thority having jurisdiction, a force to the release device 10 under all of the following that the required to exceed 15 lbf and be required to be d for more than 3 seconds. The release process shall signal in the vicinity of the	K 0222	1 Immediate action(s) taken the resident(s) found to have be affected include: 1 The delayed egress on the front door is scheduled to be corrected/completed on 3/21/25 2 A. The north exit door to th courtyard now has a code poste B. The courtyard gate in the courtyard exit now has a new loand will release when the combination is entered. 2 Identification of other residents having the potential to be affected was accomplished that	een 5. e ed ock by:	

FORM CMS-2567(02-99) Previous Versions Obsolete

door opening.

Event ID:

ICOD21

Facility ID: 000114

If continuation sheet

residents have the potential to be

Page 5 of 10

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155207		(X2) MULTIPLE C A. BUILDING B. WING	ONSTRUCTION 01	(X3) DATE SURVEY COMPLETED 03/05/2025	
NAME OF I	PROVIDER OR SUPPLIER	<u>.</u>		ADDRESS, CITY, STATE, ZIP COD	
	IC CARE OF NEW			DALY DRIVE HAVEN, IN 46774	
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CORRECTION	(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	COMPLETION
TAG		R LSC IDENTIFYING INFORMATION	TAG	DEFICIENCY)	DATE
		as been released by the		affected.	
		to the releasing device,		3 Actions taken/systems p	
	relocking shall be b	y manual means only.		into place to reduce the risk	of
				future occurrence include:	
		rvation and interview, the		The delayed egress on the	e
		sure the means of egress		front door is scheduled to be	
	1	tyard exit doors were readily		corrected/completed on 3/21/2	
		ents without a clinical		2. A. The north exit door to the	
		specialized security measures.		courtyard now has a code pos	sted
	_	ired means of egress shall not		B. The courtyard gate in the	
		latch or lock that requires the		courtyard exit now has a new	
		from the egress side unless		and will release when combin	ation
		1 by LSC 19.2.2.2.4.		is entered.	
	Door-locking arrangements shall be permitted in accordance with 19.2.2.2.5.2.			Staff was in-serviced on the n	
				combination lock and location	of
				code for the courtyard.	
		ces could affect 40 residents		4 How the corrective	
	evacuating two smo	oke compartments.		action(s) will be monitored to	0
				ensure the practice will not	
	Findings include:			recur:	
				The maintenance director will	
		on with the Maintenance		complete a weekly test of all	
		5 between 11:20 a.m. and 12:30		delayed egress doors to ensu	
	p.m., The following	g was observed:		are in working order, for 6 mo	nths.
	(U1) FI 6 : 1:	4 4 44		After the 6 months, checking	
		door was equipped with a		delayed egress doors will be	
	I	egress. When the exit door		placed on the preventative	
		ersible process to release the		maintenance program for mor	•
		ed. Based on an interview at		checks. Any door that fails tes	-
		tion, the Maintenance Director		will be immediately corrected.	
		activate the delayed egress		The maintenance director will	
	I -	red egress was not working		weekly check of the combinat	ion
	and will need to be	герангеа.		lock on the courtyard gate to	Liter an
	(#2) (a.) Th	arit do an that lad into the		ensure it remains in good wor	-
		exit door that led into the		condition. After the 6 months,	
	1	marked as a facility exit, was		checking the lock will be place	
		l, and could be opened by		on the preventative maintenar	
		t code on the access control		program for monthly checks.	
		ey FOB, but the code was not		lock will be immediately chang	
	posted by the acces	s control pad and only staff		should it fail to open upon ent	erina l

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155207		(X2) MULTIPLE C A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 03/05/2025				
	PROVIDER OR SUPPLIER		1201 🛭	STREET ADDRESS, CITY, STATE, ZIP COD 1201 DALY DRIVE NEW HAVEN, IN 46774				
(X4) ID PREFIX	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL		ID PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)				
TAG	carried a key FOB. time of observation, agreed the code to coposted by the access carried a key FOB. (#2) (b.) The courty discharge was locked combination is used open the gate, but wentered the padlock Maintenance Direct (WD-40) to spray the unlocked after the Wan interview at the the Maintenance Direct not open on the first unlock the pad lock. The findings were respected to the control of the pad lock.	eviewed with the Maintenance Director during	TAG	the combination. Audit records will be reviewed the Safety Committee/Quality Assurance Committee until su time consistent substantial compliance has been achieved determined by the committee.	ch			
K 0741 SS=E Bldg. 01	NFPA 101 Smoking Regulation	ons						
j	failed to ensure 1 of maintained by disport or noncombustible of cover devices. This staff by the service. Findings include: Based on observation Director on 03/05/2	on and interview, the facility 3 smoking areas were using cigarette butts in a metal container with self-closing deficient practice could affect hall exit. on with the Maintenance 5 at 12:28 p.m., in the staff le the employee exit by the	K 0741	1 Immediate action(s) taken the resident(s) found to have the affected include: The cigarette butts found in the staff smoke area were cleaned immediately. 2 Identification of other residents having the potential be affected was accomplished. The facility has determined the residents have the potential to affected.	eeen d up to by: at all			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

ICOD21

Facility ID: 000114

If continuation sheet

Page 7 of 10

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155207		(X2) MULTIPLE C A. BUILDING B. WING	CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED 03/05/2025		
	PROVIDER OR SUPPLIER		1201 [FADDRESS, CITY, STATE, ZIP COD DALY DRIVE HAVEN, IN 46774		
(X4) ID PREFIX TAG	REFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL		ID PREFIX TAG	PROVIDERS PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE		
K 0753	container with a sel cigarette butts dispo outside of the staff of interview at the tim Maintenance Direct butts on the ground	ntained a noncombustible f-closing cover, had over 35 psed on the ground inside and smoking area. Based on an ele of observations, the for agreed there were cigarette in the staff smoking area. Viewed with the Administrator irrector during the exit		3 Actions taken/systems p into place to reduce the risk future occurrence include: Maintenance was in-serviced of ensuring all smoke areas are checked for cleanliness and saweekly. All staff were in-serviced on ensuring that cigarette butts and disposed of in the noncombus container provided in the smolareas. 4 How the corrective action(s) will be monitored to ensure the practice will not recur: The maintenance director will complete weekly checks for 6 months, of all smoke areas to ensure butts are disposed of properly in the noncombustible containers. The rounds will the be placed on the Preventative Maintenance program to check smoke areas monthly for continued compliance. Audit records will be reviewed the Safety Committee/Quality Assurance Committee until surtime consistent substantial compliance has been achieved determined by the committee.	of on afety re tible se en k by ch	
SS=E Bldg. 01	Based on observation failed to ensure 1 of	on and interview, the facility f 9 corridor doors in the dining rtment covered by decorations	K 0753	Immediate action(s) taken the resident(s) found to have be affected include:		

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY		
AND PLAN OF CORRECTION IDENTIFIC.		IDENTIFICATION NUMBER	A. BU	a. Building <u>01</u>		COMPLETED	
155207		B. W	B. WING 03/05/2025			25	
				STREET	ADDRESS, CITY, STATE, ZIP COD	<u> </u>	
NAME OF I	PROVIDER OR SUPPLIEF	8			ALY DRIVE		
MAJEST	IC CARE OF NEW	HAVEN			IAVEN, IN 46774		
	Г		<u> </u>		1		
(X4) ID		STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	`	ICY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE CC	OMPLETION
TAG		R LSC IDENTIFYING INFORMATION		TAG			DATE
		ercent of the door. LSC 19.7.5.6			All decorations/items on the		
		decorations shall be prohibited			activity door were removed.		
	I	ccupancy, unless one of the			2 Identification of other		
	following criteria is				residents having the potential		
		retardant or are treated with			be affected was accomplished	-	
		lant coating that is listed and			The facility has determined the		
		ion to the material to which it is			residents have the potential to affected.) be	
	applied.	meet the requirements of					
	1 1	d Methods of Fire Tests for			3 Actions taken/systems p		
		of Textiles and Films.			into place to reduce the risk future occurrence include:	oi	
		exhibit a heat release rate not			The decorations/items were		
	` '	when tested in accordance with		removed from the activity door.		r	
	_	d Method of Fire Test for		The activity staff were in-serviced			
		kages, using the 20 kW			regarding not hanging combustible		
	ignition source.	Rages, using the 20 kW			paper decorations/items on any		
	_	s, such as photographs,			corridor doors.	'y	
	1 1	art, are attached directly to			4 How the corrective		
		nd non-fire-rated doors in			action(s) will be monitored to	,	
	accordance with the				ensure the practice will not		
		non-fire-rated doors do not			recur:		
		peration or any required			The maintenance supervisor v	vill	
		and do not exceed the area			complete weekly rounds for 6		
	limitations of 19.7.				months to ensure corridor doc	ors	
		not exceed 20 percent of the			do not have combustible items		
		oor areas inside any room or			attached to them. Rounds will		
	I -	ompartment that is not			then be monthly thereafter to		
	_	at by an approved automatic			ensure continued compliance.		
	1 -	accordance with Section 9.7.			Records will be reviewed by the		
		not exceed 30 percent of the			Safety Committee/Quality		
		oor areas inside any room or			Assurance Committee until su	ch	
	space of a smoke co	ompartment that is protected			time consistent substantial		
	throughout by an ap	pproved supervised automatic			compliance has been achieve	d as	
		accordance with Section 9.7.			determined by the committee.		
	(d) Decorations do	not exceed 50 percent of the					
	wall, ceiling, and de	oor areas inside patient					
	sleeping rooms hav	ing a capacity not exceeding					
		moke compartment that is					
	protected throughou	at by an approved, supervised					
	automatic sprinkler system in accordance with						

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/21/2025 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155207	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING			(X3) DATE SURVEY COMPLETED 03/05/2025	
NAME OF PROVIDER OR SUPPLIER MAJESTIC CARE OF NEW HAVEN			STREET ADDRESS, CITY, STATE, ZIP COD 1201 DALY DRIVE NEW HAVEN, IN 46774				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION			ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPE TAG DEFICIENCY)		ATE	(X5) COMPLETION DATE
	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION Section 9.7. This deficient practice could affect 30 residents in one smoke compartment. Findings include: Based on an observation with the Maintenance Director on 03/05/25 at 12:51 p.m., the activities room door had paper clover leaves covering 90% of the door. Based on interview at the time of the observation, the Maintenance Director agreed the corridor door was covered with combustible decorations and stated the decorations will be removed. This finding was reviewed with the Administrator and Maintenance Director during the exit conference.						

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: ICOD21 Facility ID: 000114 If continuation sheet Page 10 of 10