

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/11/2023
FORM APPROVED
OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155171		X2) MULTIPLE CONSTRUCTION A. BUILDING -- B. WING _____		X3) DATE SURVEY COMPLETED 11/16/2023	
NAME OF PROVIDER OR SUPPLIER FRANKLIN MEADOWS				STREET ADDRESS, CITY, STATE, ZIP COD 1285 W JEFFERSON ST FRANKLIN, IN 46131			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
E 0000 Bldg. --	<p>An Emergency Preparedness Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.73.</p> <p>Survey Date: 11/16/23</p> <p>Facility Number: 000087 Provider Number: 155171 AIM Number: 100289890</p> <p>At this Emergency Preparedness survey, Franklin Meadows was found in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73.</p> <p>The facility has 114 certified beds. At the time of the survey, the census was 81.</p> <p>Quality Review completed on 11/20/23</p>			E 0000			
K 0000 Bldg. 01	<p>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a).</p> <p>Survey Date: 11/16/23</p> <p>Facility Number: 000087 Provider Number: 155171 AIM Number: 100289890</p> <p>At this Life Safety Code Survey, Franklin Meadows was found not in compliance with</p>			K 0000	<p>Please find enclosed the Plan of Correction to the annual survey, Survey Event ID J71R21, that was conducted on November 16th, 2023, resulting in three citations K-300, K-324, and K-353. This letter is to inform you that the plan of correction attached is to serve as Franklin Meadow's credible allegation of compliance. We allege compliance on 12/15/2023.</p> <p>Submission of this plan of</p>		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Jason Kennedy

Executive Director

12/07/2023

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/11/2023
FORM APPROVED
OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155171		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 11/16/2023	
NAME OF PROVIDER OR SUPPLIER FRANKLIN MEADOWS				STREET ADDRESS, CITY, STATE, ZIP CODE 1285 W JEFFERSON ST FRANKLIN, IN 46131			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 0300 SS=E Bldg. 01	<p>Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>This one story facility was determined to be of Type V (000) construction and is fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and in all areas open to the corridor. Battery operated smoke detectors are installed in all resident sleeping rooms. The facility has a capacity of 114 and had a census of 81 at the time of this visit.</p> <p>All areas where residents have customary access were sprinklered. All areas providing facility services were sprinklered except three detached wooden sheds providing facility storage.</p> <p>Quality Review completed on 11/20/23</p> <p>NFPA 101 Protection - Other Protection - Other List in the REMARKS section any LSC Section 18.3 and 19.3 Protection requirements that are not addressed by the provided K-tags, but are deficient. This information, along with the applicable Life Safety Code or NFPA standard citation, should be included on Form CMS-2567.</p> <p>Based on observation and interview, the facility failed to replace battery operated smoke alarms installed in 1 of 58 resident sleeping rooms in accordance with NFPA 72. NFPA 72, 2010 Edition, Section 14.4.8.1 states unless otherwise recommended by the manufacturer's published instructions, single- and multiple-station smoke</p>			K 0300	<p>correction does not constitute an admission by Franklin Meadows or its management company that the allegations contained in the survey report are a true and accurate portrayal of nursing care and other services in this facility. Nor does this provision constitute an agreement or admission of the survey allegations. We cordially ask for a desk review of these alleged deficient practices.</p> <p>Please find enclosed the Plan of Correction to the annual survey, Survey Event ID J71R21, that was conducted on November 16th, 2023, resulting in three citations K-300, K-324, and K-353. This letter is to inform you that the plan</p>		12/15/2023

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/11/2023
FORM APPROVED
OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155171		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 11/16/2023	
NAME OF PROVIDER OR SUPPLIER FRANKLIN MEADOWS				STREET ADDRESS, CITY, STATE, ZIP CODE 1285 W JEFFERSON ST FRANKLIN, IN 46131			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>alarms shall be replaced when they fail to respond to operability tests but shall not remain in service longer than 10 years from the date of manufacture. This deficient practice could affect over 30 residents, staff and visitors in the vicinity of resident sleeping Room 124.</p> <p>Findings include:</p> <p>Based on observations with the Executive Director, the Maintenance Director and the Field Maintenance Supervisor during a tour of the facility from 11:30 a.m. to 12:50 p.m. on 11/16/23, manufacturer's documentation affixed to the First Alert Model SA 340 battery operated smoke alarm installed on the ceiling in resident sleeping Room 124 indicated the smoke alarm was manufactured 08/17/11. Based on interview at the time of the observations, the Maintenance Director stated each resident sleeping room has a battery operated smoke alarm installed in the room, all battery operated smoke alarms in the facility were replaced within the most recent twelve month period but the battery operated smoke alarm replacement for Room 124 must have been missed and agreed the resident sleeping room battery operated smoke alarm installed in Room 124 was more than ten years old.</p> <p>These findings were reviewed with the Executive Director, the Maintenance Director and the Field Maintenance Supervisor during the exit conference.</p> <p>3.1-19(b)</p>				<p>of correction attached is to serve as Franklin Meadow's credible allegation of compliance. We allege compliance on 12/15/2023.</p> <p>Submission of this plan of correction does not constitute an admission by Franklin Meadows or its management company that the allegations contained in the survey report are a true and accurate portrayal of nursing care and other services in this facility. Nor does this provision constitute an agreement or admission of the survey allegations. We cordially ask for a desk review of these alleged deficient practices.</p> <p>K-300 Protection- Other; What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice?</p> <p>Facility failed to replace battery-operated smoke alarms in 1 of 58 resident sleeping rooms.</p> <p>How will you identify other residents having the potential to be affected by the same deficient practice and what corrective action will be taken?</p> <p>All residents have the potential to be affected by the alleged deficiency.</p> <p>Entire building audit (attachment A) will be completed</p>		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/11/2023
FORM APPROVED
OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155171	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 11/16/2023
NAME OF PROVIDER OR SUPPLIER FRANKLIN MEADOWS			STREET ADDRESS, CITY, STATE, ZIP COD 1285 W JEFFERSON ST FRANKLIN, IN 46131		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
			<p>to ensure that no other expired battery-powered smoke detectors are still in service by the Maintenance Director, or designee.</p> <p>In-service (attachment B) will be completed by ED/designee to the environmental department regarding the importance of proper non-expired smoke detectors being used moving forward.</p> <p>The X1 smoke detector that was not within compliance was replaced immediately on 11/16/23 with a brand-new battery smoke detector within manufacturer guidelines.</p> <p>What measures will be put into place or what systemic changes you will make to ensure that the deficient practice does not recur?</p> <p>POC QAPI Audit tool (attachment C) to be completed by the Maintenance Director, or designee, to be utilized to ensure all battery-powered smoke detectors are of the correct type and within the manufacturer's recommendation for the detector's life expectancy of the unit moving forward.</p> <p>Any deficiencies identified during the audit will be addressed immediately by ED/designee</p> <p>How the corrective action (s) will be monitored to ensure the deficient practice will not recur, i.e., what quality</p>		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/11/2023
FORM APPROVED
OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155171	X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____		X3) DATE SURVEY COMPLETED 11/16/2023
NAME OF PROVIDER OR SUPPLIER FRANKLIN MEADOWS			STREET ADDRESS, CITY, STATE, ZIP COD 1285 W JEFFERSON ST FRANKLIN, IN 46131		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 0324 SS=D Bldg. 01	NFPA 101 Cooking Facilities Cooking Facilities Cooking equipment is protected in accordance with NFPA 96, Standard for Ventilation Control and Fire Protection of Commercial Cooking Operations, unless: * residential cooking equipment (i.e., small appliances such as microwaves, hot plates, toasters) are used for food warming or limited cooking in accordance with 18.3.2.5.2, 19.3.2.5.2 * cooking facilities open to the corridor in smoke compartments with 30 or fewer patients comply with the conditions under 18.3.2.5.3, 19.3.2.5.3, or * cooking facilities in smoke compartments with 30 or fewer patients comply with conditions under 18.3.2.5.4, 19.3.2.5.4.		assurance program will be put into place? POC QAPI Tool (attachment C) completed by the Maintenance Director, or designee, will be utilized weekly x 4 weeks, monthly x 6 months, and quarterly thereafter for one year to ensure all battery-operated smoke detectors are within the manufacturer guidelines, with results reported to the Quality Assurance and Performance Improvement Committee overseen by the Executive Director If a threshold of 100% is not achieved, an action plan will be developed to ensure compliance Total compliance date; 12/15/2023		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/11/2023
FORM APPROVED
OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155171		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 11/16/2023	
NAME OF PROVIDER OR SUPPLIER FRANKLIN MEADOWS				STREET ADDRESS, CITY, STATE, ZIP COD 1285 W JEFFERSON ST FRANKLIN, IN 46131			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>Cooking facilities protected according to NFPA 96 per 9.2.3 are not required to be enclosed as hazardous areas, but shall not be open to the corridor.</p> <p>18.3.2.5.1 through 18.3.2.5.4, 19.3.2.5.1 through 19.3.2.5.5, 9.2.3, TIA 12-2</p> <p>Based on observation and interview, the facility failed to ensure 1 of 1 kitchen range hood extinguishing systems was maintained in proper working order. NFPA 96, 2011 edition, Section 10.1.2 requires cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. Section 11.1.6 states cooking equipment shall not be operated while its fire-extinguishing system or exhaust system is nonoperational or impaired. This deficient practice over two kitchen staff.</p> <p>Findings include:</p> <p>Based on observations with the Executive Director, the Maintenance Director and the Field Maintenance Supervisor during a tour of the facility from 11:30 a.m. to 12:50 p.m. on 11/16/23, four of four kitchen range hood extinguishing system nozzles were not properly positioned over the cooking equipment under the hood. All four range hood extinguishing system nozzles were pointed directly at the range hood baffles under the hood and not pointed downward over the natural gas fired range and griddle below the nozzles. Based on interview at the time of the observations, the Maintenance Director stated the range hood inspection contractor must have repositioned the nozzles during their most recent semiannual inspection and agreed the nozzles were not pointed downward over the cooking equipment below and had facility staff reposition</p>			K 0324	<p>Please find enclosed the Plan of Correction to the annual survey, Survey Event ID J71R21, that was conducted on November 16th, 2023, resulting in three citations K-300, K-324, and K-353. This letter is to inform you that the plan of correction attached is to serve as Franklin Meadow's credible allegation of compliance. We allege compliance on 12/15/2023.</p> <p>Submission of this plan of correction does not constitute an admission by Franklin Meadows or its management company that the allegations contained in the survey report are a true and accurate portrayal of nursing care and other services in this facility. Nor does this provision constitute an agreement or admission of the survey allegations.</p> <p>We cordially ask for a desk review of these alleged deficient practices.</p> <p>K-324 Cooking Facilities;</p> <p>What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice?</p> <p>Facility failed to ensure 1 of 1 kitchen range hood</p>		12/15/2023

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/11/2023
FORM APPROVED
OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155171	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 11/16/2023
NAME OF PROVIDER OR SUPPLIER FRANKLIN MEADOWS			STREET ADDRESS, CITY, STATE, ZIP COD 1285 W JEFFERSON ST FRANKLIN, IN 46131		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
	<p>the nozzles during the survey.</p> <p>These findings were reviewed with the Executive Director, the Maintenance Director and the Field Maintenance Supervisor during the exit conference.</p> <p>3.1-19(b)</p>		<p>extinguishing systems were maintained in proper working order.</p> <p>How will you identify other residents having the potential to be affected by the same deficient practice and what corrective action will be taken?</p> <p>All residents have the potential to be affected by the alleged deficiency.</p> <p>In-service (attachment D) will be completed by ED/designee to the environmental department regarding the kitchen hood nozzles being in the proper orientation for fire protection services.</p> <p>The 1 of 1 kitchen Ansul Nozzles were immediately adjusted and set back into the proper position of orientation on 11/16/23.</p> <p>What measures will be put into place or what systemic changes you will make to ensure that the deficient practice does not recur?</p> <p>POC QAPI tool (attachment E) will be utilized to ensure proper orientation of the Ansul kitchen nozzles.</p> <p>TELS task for Ansul Hood systems "Owners inspection" put in place monthly to ensure Nozzles are in proper orientation.</p> <p>Any deficiencies identified during the audit/TELS task will be</p>		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/11/2023
FORM APPROVED
OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155171		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 11/16/2023	
NAME OF PROVIDER OR SUPPLIER FRANKLIN MEADOWS				STREET ADDRESS, CITY, STATE, ZIP COD 1285 W JEFFERSON ST FRANKLIN, IN 46131			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 0353 SS=F Bldg. 01	<p>NFPA 101 Sprinkler System - Maintenance and Testing Sprinkler System - Maintenance and Testing Automatic sprinkler and standpipe systems are inspected, tested, and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintaining of Water-based Fire Protection Systems. Records of system design, maintenance, inspection and testing are maintained in a secure location and readily available. a) Date sprinkler system last checked</p>				<p>addressed immediately by ED/designee How the corrective action (s) will be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be put into place? POC QAPI Tool (attachment E) completed by the Maintenance Director, or designee, will be utilized weekly x 4 weeks, monthly x 6 months, and quarterly thereafter for one year to ensure all Ansul chemical nozzles are in proper orientation, with results reported to the Quality Assurance and Performance Improvement Committee overseen by the Executive Director If a threshold of 100% is not achieved, an action plan will be developed to ensure compliance Total compliance date; 12/15/2023</p>		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/11/2023

FORM APPROVED

OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155171		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 11/16/2023	
NAME OF PROVIDER OR SUPPLIER FRANKLIN MEADOWS				STREET ADDRESS, CITY, STATE, ZIP CODE 1285 W JEFFERSON ST FRANKLIN, IN 46131			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>b) Who provided system test</p> <p>c) Water system supply source</p> <p>Provide in REMARKS information on coverage for any non-required or partial automatic sprinkler system. 9.7.5, 9.7.7, 9.7.8, and NFPA 25</p> <p>Based on observation and interview, the facility failed to maintain the ceiling construction in 11 of 58 resident sleeping rooms. NFPA 13, 2010 edition, Section 3.3.5.4 defines a smooth ceiling as a continuous ceiling free from significant irregularities, lumps, or indentations. The ceiling traps hot air and gases around the sprinkler and cause the sprinkler to operate at a specified temperature. Section 8.5.4.1.1 states the distance between the sprinkler deflector and the ceiling above shall be selected based on the type of sprinkler and the type of construction. This deficient practice could affect all residents, staff, and visitors.</p> <p>Findings include:</p> <p>Based on observations with the Executive Director, the Maintenance Director and the Field Maintenance Supervisor during a tour of the facility from 11:30 a.m. to 12:50 p.m. on 11/16/23, a hole was noted in the ceiling of resident sleeping Room 106, 110, 121, 142, 143, 149, 152, 153, 156, 157 and 160 which was covered over with an open metal grate. Each hole exposed the interstitial space above the drywall ceiling for the room or was covered over with cardboard. Based on interview at the time of the observations, the Maintenance Director and the Field Maintenance Supervisor agreed the holes in the ceiling of each of the eleven resident sleeping rooms did not maintain the ceiling construction in the room and</p>			K 0353	<p>Please find enclosed the Plan of Correction to the annual survey, Survey Event ID J71R21, that was conducted on November 16th, 2023, resulting in three citations K-300, K-324, and K-353. This letter is to inform you that the plan of correction attached is to serve as Franklin Meadow's credible allegation of compliance. We allege compliance on 12/15/2023.</p> <p>Submission of this plan of correction does not constitute an admission by Franklin Meadows or its management company that the allegations contained in the survey report are a true and accurate portrayal of nursing care and other services in this facility. Nor does this provision constitute an agreement or admission of the survey allegations. We cordially ask for a desk review of these alleged deficient practices.</p> <p>K-353 Sprinkler System-Maintenance and Testing; What corrective action(s) will be accomplished for those residents found to have been</p>		12/15/2023

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/11/2023
FORM APPROVED
OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155171	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 11/16/2023
NAME OF PROVIDER OR SUPPLIER FRANKLIN MEADOWS			STREET ADDRESS, CITY, STATE, ZIP CODE 1285 W JEFFERSON ST FRANKLIN, IN 46131		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
	<p>could delay activation of the sprinklers in the rooms.</p> <p>These findings were reviewed with the Executive Director, the Maintenance Director and the Field Maintenance Supervisor during the exit conference.</p> <p>3.1-19(b)</p>		<p>affected by the deficient practice?</p> <p>Facility failed to maintain the ceiling construction in 11 of 58 resident sleeping rooms.</p> <p>How will you identify other residents having the potential to be affected by the same deficient practice and what corrective action will be taken?</p> <p>All residents have the potential to be affected by the alleged deficiency.</p> <p>Total facility audit (attachment F) of all resident sleeping rooms completed by Maintenance Director, or designee to ensure no other cardboard coverings are being used. Completed on 11/17/23.</p> <p>In-service (attachment G) will be completed by ED/designee to the environmental department regarding the ceiling grates not being blocked by cardboard sections.</p> <p>The 11 of 58 resident sleeping rooms that were affected by these cardboard coverings have been removed as of 11/16/23.</p> <p>What measures will be put into place or what systemic changes you will make to ensure that the deficient practice does not recur?</p> <p>POC QAPI tool (attachment H) will be utilized by the Maintenance Director, or designee</p>		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/11/2023
FORM APPROVED
OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155171	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 11/16/2023
NAME OF PROVIDER OR SUPPLIER FRANKLIN MEADOWS			STREET ADDRESS, CITY, STATE, ZIP CODE 1285 W JEFFERSON ST FRANKLIN, IN 46131		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
			<p>to ensure no other cardboard coverings are being used throughout the facility moving forward in resident sleeping rooms.</p> <p>Any deficiencies identified during the audit/TELS task will be addressed immediately by the ED</p> <p>How the corrective action (s) will be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be put into place?</p> <p>POC QAPI Tool (attachment H) completed by the Maintenance Director, or designee, will be utilized weekly x 4 weeks, monthly x 6 months, and quarterly thereafter for one year to ensure all resident sleeping rooms have no cardboard coverings put in place into the ceiling spaces, with results reported to the Quality Assurance and Performance Improvement Committee overseen by the Executive Director</p> <p>If a threshold of 100% is not achieved, an action plan will be developed to ensure compliance</p> <p>Total compliance date; 12/15/2023</p>		