PRINTED: 07/08/2024 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		1 ' '	JLTIPLE CONSTRUCTION DING <b>02, 03</b>			(X3) DATE SURVEY COMPLETED	
		155280	B. WING	B. WING		R <b>06/27/2024</b>	
	ROVIDER OR SUPPLIER  DF DILLSBORO-ROSS I	MANOR, THE		1	STREET ADDRESS, CITY, STATE, ZIP CODE 12803 LENOVER ST DILLSBORO, IN 47018	, 33.	
(X4) ID PREFIX TAG			ID PREFIX TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE
{E 000}	Initial Comments		{E 0	)00}			
{K 000}	Preparedness Survey conducted by the Indiaccordance with 42 (Survey Date: 06/27/2 Facility Number: 000 Provider Number: 18 AIM Number: 10027 At this PSR survey to Preparedness survey Dillsboro-Ross Manowith Emergency Prep Medicare and Medica and Suppliers, 42 CF The facility has 123 of the survey, the census Quality Review comp INITIAL COMMENTS A Fire Safety Evalua Post Survey Revisit (Recertification and Sconducted on 04/29/3	2024 20178 205280 20840 20 the Emergency 20 The Waters of 20 r was found in compliance 20 paredness Requirements for 20 paredn	{K 0	000)			
	42 CFR 483.90(a). Survey Date: 06/27/	24					
	Facility Number: 000 Provider Number: 18 AIM Number: 10027	55280					
ADODATODY	DIDECTORIC OR DROV (SEE	CURRULER REPRESENTATIVE'S SIGNATUR			TITLE		(V6) DATE

ABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TLE (X6) DATI

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:				(X3) DATE SURVEY COMPLETED		
		155280	B. WING _		,	R 6/ <b>27/2024</b>		
	NAME OF PROVIDER OR SUPPLIER  WATERS OF DILLSBORO-ROSS MANOR, THE			STREET ADDRESS, CITY, STATE, ZIP COD 12803 LENOVER ST DILLSBORO, IN 47018				
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CC X (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	N SHOULD BE	(X5) COMPLETION DATE		
{K 000}	with National Fire Pro 101A, Chapter 4, Fire for Health Care Occu PSR to the Life Safet State Licensure Surviscore on the FSES stoccupancies found in Guide on Alternative 2013 Edition, shows the Life Safety at least ecoby NFPA 101, Life Safacility was surveyed Health Care Occupant The Waters of Dillsbottwo separate building Building 02, is a two sand was determined to be Typfully sprinklered. Bott system with smoke downward with smoke downward for Dillsboro building including the the corridors, and has detectors in all reside Waters of Dillsboro building. The Waters has a capacity of 123 the time of this visit.	rvey, The Waters of r was found in compliance stection Association (NFPA) a Safety Evaluation System pancies in regard to the y Code Recertification and ay. Achieving a passing creating a passing creating a passing creating and a servey for Health Care of Chapter 4 of NFPA 101A, Approaches to Life Safety, the facility provides a level of quivalent to that prescribed fety Code (LSC). The with Chapter 19, Existing incies and 410 IAC 16.2.  The Waters of Dillsboro, story facility with a basement to be of Type V (000) sprinklered. Ross Manor, story facility and was e V (111) construction and in facilities have a fire alarm election on all levels of the cuilding and Ross Manor corridors, spaces open to so battery operated smoke int sleeping rooms in the cuilding and the Ross Manor of Dillsboro-Ross Manor and had a census of 70 at ents have customary access I areas providing facility ered.	{K 0	00}				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		I ' '	(X2) MULTIPLE CONSTRUCTION  A. BUILDING 02, 03			(X3) DATE SURVEY COMPLETED		
		155280	B. WING			l	⋜ 27/2024	
	ROVIDER OR SUPPLIER  OF DILLSBORO-ROSS N	IANOR, THE		1280	ET ADDRESS, CITY, STATE, ZIP CODE 3 LENOVER ST SBORO, IN 47018	1 00/	21/2024	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE	
{K 000}	INITIAL COMMENTS		{K (	000}				
	Post Survey Revisit ( Recertification and Si conducted on 04/29/2 Indiana Department of 42 CFR 483.90(a).  Survey Date: 06/27/2 Facility Number: 000 Provider Number: 15 AIM Number: 10027;  At this FSES PSR su Dillsboro-Ross Mano with National Fire Pro 101A, Chapter 4, Fire for Health Care Occu PSR to the Life Safet State Licensure Surve score on the FSES si Occupancies found in Guide on Alternative of 2013 Edition, shows of Life Safety at least ed by NFPA 101, Life Safacility was surveyed Health Care Occupant The Waters of Dillsbot two separate building Building 02, is a two sand was determined of construction and fully Building 03, is a one determined to be Typ	178 15280 3840  rvey, The Waters of r was found in compliance of tection Association (NFPA) as Safety Evaluation System pancies in regard to the y Code Recertification and ey. Achieving a passing curvey for Health Care of Chapter 4 of NFPA 101A, Approaches to Life Safety, the facility provides a level of quivalent to that prescribed fety Code (LSC). The with Chapter 19, Existing incies and 410 IAC 16.2.  To-Ross Manor consisted of s. The Waters of Dillsboro, story facility with a basement to be of Type V (000) sprinklered. Ross Manor,						

	OF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>02</b> , <b>03</b>		(X3) DATE SURVEY COMPLETED		
		155280	B. WING _	B. WING		R 06/27/2024	
	ROVIDER OR SUPPLIER  DF DILLSBORO-ROSS M			12	TREET ADDRESS, CITY, STATE, ZIP CODE 2803 LENOVER ST ILLSBORO, IN 47018	00/	21/2024
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
{K 000}	Waters of Dillsboro bubuilding including the the corridors, and has detectors in all reside Waters of Dillsboro bubuilding. The Waters has a capacity of 123 the time of this visit.  All areas where reside were sprinkled and all	etection on all levels of the uilding and Ross Manor corridors, spaces open to be battery operated smoke int sleeping rooms in the uilding and the Ross Manor of Dillsboro-Ross Manor and had a census of 70 at ents have customary access I areas providing facility	{K 0	00}			
{K 161} SS=F	CFR(s): NFPA 101  Building Construction 2012 EXISTING Building construction	Type and Height  Type and Height  type and stories meets otherwise permitted by	{K 1	61}			
	Construction 1 I (442), I (33 stories  sprinklered 2 II (111) non-sprinklered  sprinklered 3 II (000) non-sprinklered						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:				(X3) DATE SURVEY COMPLETED	
		155280	B. WING		R <b>06/27/2024</b>		
	ROVIDER OR SUPPLIER  OF DILLSBORO-ROSS N	IANOR, THE		12	TREET ADDRESS, CITY, STATE, ZIP CODE 2803 LENOVER ST ILLSBORO, IN 47018	1 0011	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	х	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
{K 161}	system in accordance 19.3.5) Give a brief description construction, the numbasements, floors on location of smoke or fapproval. Complete splan of the building as This REQUIREMENT by:  1. Based on observation facility failed to ensurate constructed with a 1 h. The minimum building allowed for a two stor requiring the floor/ceil floors to have a one h. This deficient practice reside in the Waters of Findings include:  Based on observation and the Maintenance facility from 1:50 p.m. the basement was se with exposed wood floors.	Not allowed  Maximum 1 story  ust be sprinklered roved, supervised automatic with section 9.7. (See  on, in REMARKS, of the aber of stories, including which patients are located, fire barriers and dates of ketch or attach small floor is appropriate. I is not met as evidenced  tion and interview, the e 1 of 2 floors was nour rated floor structure. It is construction classification by building is Type V (111) ling assembly between the flour fire resistive rating. I affects all residents who of Dillsboro building.  Ins with the Dietary Director Director during a tour of the to 3:20 p.m. on 04/29/24, parated from the first floor	{K 1	61}	Correction obviated - Passed FSES		

AND DLAN OF CORRECTION IDENTIFICATION NUMBER			TIPLE CONSTRUCTION ING <b>02, 03</b>	(X	(X3) DATE SURVEY COMPLETED		
		155280	B WING	B. WING		R	
NAME OF PROVIDER OR SUPPLIER  WATERS OF DILLSBORO-ROSS MANOR, THE			B. WING	STREET ADDRESS, CITY, STATE, ZIP COD 12803 LENOVER ST DILLSBORO, IN 47018	I_	06/27/2024	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		SHOULD BE	(X5) COMPLETION DATE	
{K 161}	boiler room and the n maintenance workshot construction type of the Based on interview at observations, the Mai first floor is constructed with vinyl flooring through fire rated material. The one hour construction Maintenance Director Maintenance Director of Operations the Maintenance Director of Operations the Maintenance Director for the Maintenance Director for the Maintenance Director for the Maintenance Director of Operations the Maintenance Director for the Maintenance for the Maintenance Director for the Maintenance Director	orthwest basement op room which classifies the ne building as Type V (000). It the time of the intenance Director stated the ed of one half inch plywood aughout the first floor with no ne basement ceiling lacking in was confirmed by the at the time of observations. The eviewed with the Regional so, the Dietary Manager and ctor during the exit the moke barrier construction to the required number of extending to the underside of in 19.3.7.3 states any er shall be constructed in ion 8.5 and shall have a the resistance rating, unless the provide of the following: shall not apply where an out of the following criteria at the time of the total conduction of the following criteria.	{K 1	161}			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	` ′	TIPLE CONSTRUCTION NG 02, 03		(X3) DATE SURVEY COMPLETED	
		155280	B WING	B. WING		R	
		155260	D. WING _		I	06/27/2024	
NAME OF PI	ROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CO	DE		
WATERS (	OF DILLSBORO-ROSS M	IANOR. THE		12803 LENOVER ST			
William of Billiam Room in Moral III.			DILLSBORO, IN 47018				
(X4) ID PREFIX TAG	(EACH DEFICIENCY	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF C (EACH CORRECTIVE ACTIC CROSS-REFERENCED TO TH DEFICIENCY	ON SHOULD BE HE APPROPRIATE	(X5) COMPLETION DATE	
{K 161}	Continued From page	÷ 6	{K 1	61}			
{K 161}	heating, ventilating, a where an approved, s sprinkler system in ac been provided for sme to the smoke barrier. Section 8.5.2.1 states this Code shall be cor wall to an outside wal from a smoke barrier use of a combination states smoke barriers through all concealed found above a ceiling spaces. Section 8.5.2 required by this Code outside wall to an outside wall to an outside wall to an outside, or from a smoke or by use of a combin 8.3.1.2* Fire barriers at wall to outside wall or another, or a combina continuity through all those found above a composition of the spaces.  (2) The fire barriers at wall to outside wall or another, and from the interstitial space, provassembly forming the space has a fire resist that of the fire barrier. This deficient practice	and air-conditioning systems supervised automatic coordance with 19.3.5.8 has oke compartments adjacent a smoke barriers required by attinuous from an outside I, from a floor to a floor, or to a smoke barrier, or by thereof. Section 8.5.2.2 a shall be continuous spaces, such as those i, including interstitial 2.3 states smoke barriers shall be continuous from an aside wall, from a floor to a shall comply with one of the are continuous from outside from one fire barrier to ation thereof, including concealed spaces, such as ceiling, including interstitial are continuous from outside from one fire barrier to a floor to the bottom of the vided that the construction bottom of the interstitial tance rating not less than	{K 1	61}			
	Findings include:						
		ew with the Dietary Manager :50 p.m. on 04/29/24, facility					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X'		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:				(X3) DATE SURVEY COMPLETED	
		155280	B. WING	B. WING		R <b>06/27/2024</b>	
	ROVIDER OR SUPPLIER  DF DILLSBORO-ROSS N	IANOR, THE		12	TREET ADDRESS, CITY, STATE, ZIP CODE 2803 LENOVER ST ILLSBORO, IN 47018	1 00/	2112024
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG	PREFIX (EACH CORRECTIVE ACTION SHOULD			(X5) COMPLETION DATE
{K 311} SS=F	review. Documentation rating of the second flows also not available observations with the Maintenance Director from 1:50 p.m. to 3:20 exact location of smowalls could not be desprinklered and was recontained no smoke extending to the undeabove.  These findings were represented by the Director of Operations the Maintenance Director of Operations the Maintenance Director for the Maintenance D	con was not available for on of the fire resistance coor ceiling smoke barrier of for review. Based on Dietary Director and the during a tour of the facility of p.m. on 04/29/24, the ke barrier and fire barrier termined. The attic was fully not used for storage but or fire barrier walls erside of the roof deck reviewed with the Regional straight and ctor during the exit exists. Iight and ventilation her vertical openings inclosed with construction ce rating of at least 1 hour. Each in accordance with 8.61.6 are properly enclosed with grat least a 2-hour fire	{K 1				
	by: 1. Based on observa	tion and interview, the			Correction Obviated - Passed FSES		

PRINTED: 07/08/2024 FORM APPROVED OMB NO. 0938-0391 (X3) DATE SURVEY

	EMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 02, 03			(X3) DATE SURVEY COMPLETED			
		155280	B. WING			R <b>06/27/2024</b>	
NAME OF D	ROVIDER OR SUPPLIER	133230	J	Г	STREET ADDRESS, CITY, STATE, ZIP CODE	06/	27/2024
NAME OF FI	NOVIDER OR SUFFLIER						
WATERS (	OF DILLSBORO-ROSS M	IANOR, THE			12803 LENOVER ST		
					DILLSBORO, IN 47018		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
{K 311}	facility failed to maintainterior stairwells. LS openings shall be end accordance with Sect every floor that separashall be constructed a 8.6.5 states see 7.1.3 LSC 7.1.3.2.1 states the minimum 1-hr fire resistence assemblies are in accordance three stories assemblies are in accordance under the best maximum of 3/4th's in could affect over 20 referring include:  Based on observation and the Maintenance facility from 1:50 p.m. the following was note a. the stairwell door of and on the second flour not equipped with a find the stairwell door set on the stairwell doors were not stairwell doors were not stairwell doors were not resistance rating labe resistance rating labe by Room 24 was painted.  These findings were referred that second flour second flour second flour that stairwell doors were not stairwell doors	ain protection of 2 of 4 C 19.3.1 requires vertical closed or protected in ion 8.6. LSC 8.6.1 requires ates stories in a building as a smoke barrier. LSC 6.2.1 for enclosures of exits. The separation shall have a istance rating where the exit is or less. Fire doors cordance with NFPA 80, ors and Other Opening 0, Section 4.8.4.1 states the pottom of a door shall be a nich. This deficient practice residents, staff and visitors.  The with the Dietary Director Director during a tour of the to 3:20 p.m. on 04/29/24, red:  In the first floor by Room 7 for by Room 37 were each are resistance rating label. In the first floor by Room 24  If the time of the tary Director agreed the not equipped with fire I and one of the two fire II and one of the stairwell door set	{K 3	311	}		
	the Maintenance Dire						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>02</b> , <b>03</b>			(X3) DATE SURVEY COMPLETED	
		155280	B. WING	B. WING		R <b>06/27/2024</b>	
	NAME OF PROVIDER OR SUPPLIER  WATERS OF DILLSBORO-ROSS MANOR, THE			1	TREET ADDRESS, CITY, STATE, ZIP CODE 2803 LENOVER ST DILLSBORO, IN 47018		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
{K 311}	failed to ensure the p chutes and the two-s in accordance of 19.3 where enclosure is poshall have not less the rating. LSC 8.3.4.2 serating for opening proaccordance with Table otherwise permitted is 8.3.4.2 requires fire construction rating shall be used in vertical opin lieu of the minimum required in Table 8.3. could affect over 20 refindings include:  Based on observation and the Maintenance facility from 1:50 p.m. the soiled linen chuter Room 39 on the second by Room 5 contains a construction of the should on the first story.	tion and interview, the facility protection of the soiled linen tory convenience stairs was 3.1. LSC 19.3.1.1 states rovided, the construction an a 1-hour fire resistance states the fire protection of tectives shall be in the 8.3.4.2 except as an 8.3.4.3 or 8.3.4.4. Table door assemblies in vertical aways, to have a 1-hour fire to 8.3.4.3 states existing fire fing a minimum 3/4-hour fire 1 be permitted to continue to b	{K 3	311}	DEFICIENCY)		
	underside of the susp system. Removing the exposes the wood to	n 26 only extends to the pended acoustical tile ceiling the tile in the ceiling system plate and edge of the ssembly. The existing					

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:			FIPLE CONSTRUCTION  NG <b>02, 03</b>	(2	(X3) DATE SURVEY COMPLETED		
		155280	B. WING			R <b>06/27/2024</b>	
	ROVIDER OR SUPPLIER  OF DILLSBORO-ROSS N	L		STREET ADDRESS, CITY, STATE, Z 12803 LENOVER ST DILLSBORO, IN 47018	ZIP CODE	00/2//2024	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFI TAG		ACTION SHOULD BE TO THE APPROPRIATI	(X5) COMPLETION DATE	
{K 311}	two-story convenience appear to be enclose fire-rated construction time of the observation agreed the soiled line convenience stairs diwith fire-rated assemble.  These findings were in	e stair opening does not d by a minimum one-hour n. Based on interview at the on, the Maintenance Director en chute and the two story d not appear to be complete blies.  reviewed with the Regional s, the Dietary Manager and	{K 3	311}			