CENTERS FO	R MEDICARE & MEDIC	AID SERVICES				OM	B NO. 0938-039
	NT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155699	A. BU	(X2) MULTIPLE CONSTRUCTION  A. BUILDING  B. WING		(X3) DATE SURVEY  COMPLETED  02/21/2023	
	PROVIDER OR SUPPLIEF		STREET ADDRESS, CITY, STATE, ZIP COD 715 N MILL ST HARTFORD CITY, IN 47348				
(X4) ID PREFIX TAG E 0000	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION			ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		NTE .	(X5) COMPLETION DATE
Bldg	conducted by the Irraccordance with 42  Survey Date: 02/21  Facility Number: 00  Provider Number: 100  At this Emergency of Hartford City was Emergency Prepare Medicare and Mediand Suppliers, 42 C capacity of 78 and 1 of this survey.	1/23 00290 155699	E 00	000	Submission of this plan of correction does not constitute admission or agreement by th provider of the truth of facts alleged or corrections set forth the statement of deficiencies. plan of correction is prepared submitted because of requirements under state and federal laws. Please accept the plan of correction as our credicallegation of compliance.	e n on This and	
K 0000 Bldg. 01	Licensure Survey w	Recertification and State vas conducted by the Indiana Ith in accordance with 42 CFR	K 00	000	Submission of this plan of correction does not constitute admission or agreement by th provider of the truth of facts	е	
		000290			alleged or corrections set forth the statement of deficiencies. plan of correction is prepared submitted because of requirements under state and federal laws. Please accept the plan of correction as our creditallegation of compliance.	This and nis	

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Requirements for Participation in

TITLE (X6) DATE

Tammy Bledsoe Executive Director 03/10/2023

Any defiency statement ending with an asterisk (\*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: KX7421 Facility ID: 000290 If continuation sheet Page 1 of 14

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155699		(X2) MULTIPLE CO A. BUILDING B. WING	ONSTRUCTION  01	(X3) DATE SURVEY COMPLETED 02/21/2023			
	ROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 715 N MILL ST HARTFORD CITY, IN 47348				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPF DEFICIENCY)	E COMPLETION		
K 0223 SS=E Bldg. 01	Medicare/Medicaid. Life Safety from Fir National Fire Protect Life Safety Code (L. Health Care Occupated) This one story facility on the sprinklered. The far with smoke detection to the corridors and detectors in the resist capacity of 78 and from this survey.  All areas where the access were sprinkle facility services were very constant of the survey of the survey.  All areas where the access were sprinkle facility services were prinkle facility services were very constant of the survey	the and the 2012 edition of the etion Association (NFPA) 101, SC), Chapter 19, Existing ancies and 410 IAC 16.2.  It was determined to be of ruction and was fully cility has a fire alarm system in the corridors, areas open battery operated smoke dent rooms. The facility has a fire alarm serious of 33 at the time and a census of 33 at the time residents have customary ered. All areas providing the sprinklered.  Inpleted on 02/23/23  Inspection of the etion	K 0223	К 223	03/10/2023		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

KX7421

Facility ID: 000290

If continuation sheet

Page 2 of 14

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY					
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BUILI		01	COMPLET	
		155699	B. WING			02/21/20	JZ3
NAME OF P	PROVIDER OR SUPPLIER				DDRESS, CITY, STATE, ZIP COD		
	OE HADTEODD O'	TV	715 N MILL ST HARTFORD CITY, IN 47348				
EINVIVE (	OF HARTFORD CI	I T		JAK IF	UND UII I, III 4/348		
(X4) ID		STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	`	CY MUST BE PRECEDED BY FULL		PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)			COMPLETION
TAG		corridor doors to 1 of 1	1	AG	BEFELENCT		DATE
		osure were self-closing and			What corrective action(s) wil	.	
	kept in the closed position. This deficient practice				be accomplished for those	'	
		d residents in the corridor by			residents found to have been	,	
	the kitchen dishwas				affected by the deficient		
					practice.		
	Findings include:						
					No residents were affected by	this	
		on with the Maintenance			alleged deficient practice.		
		3 at 1:10 p.m., the corridor door			How other residents having to		
	to the kitchen dishwashing room was equipped				potential to be affected by th		
	with a self-closing device, but the self-closing				same deficient practice will be		
device would not fully close and latch to keep the door in the closed position. Based on interview at				identified and what correctiv action(s) will be taken.	e		
	the time of observation, the Maintenance Director				action(s) will be taken.		
		ing device on the door was			All residents in the corridor by	the	
	-	perly as it did allow the door			kitchen dishwashing room hav	l l	
	to latch.	•			the potential to be affected.		
					What measures will be put in	ito	
	-	viewed with the Executive			place and what systemic		
		enance Director during the exit			changes will be made to		
	conference.				ensure that the deficient		
	2.1.10/13				practice does not recur;		
	3.1-19(b)				A self-closing device has been		
					placed on door in the corridor the kitchen dish room.	ιυ	
					Maintenance Director has bee	n	
					educated on K223 citation.	"	
					TELOGICA OTT TELO OTTATION.		
					How the corrective action(s)		
					will be monitored to ensure t	he	
					deficient practice will not		
					recur, i.e., what quality		
					assurance program will be p	ut	
					into place; and		
					b <="" bmonitoring="" be=""		
					reviewed="" during="" monthly	/=""	
					quality="" assurance=""		
					meetings="" and="" ongoing=" continued="" compliance.<=""		
				l	continued compliance.	1	

PRINTED: 03/24/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION (IDENTIFICATION NUMBER) 155699		(X2) MULTIPLE CO A. BUILDING B. WING	onstruction 01	COM	TE SURVEY MPLETED 21/2023		
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 715 N MILL ST HARTFORD CITY, IN 47348				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	ORRECTION SHOULD BE E APPROPRIATE	(X5) COMPLETION DATE	
K 0363	NFPA 101			p="">			
SS=D Bldg. 01	than required enclexits, or hazardou of smoke and are solid-bonded core capable of resistin minutes. Doors in compartments are passage of smoke to rooms containing combustible mater hardware. Roller land CMS regulation. The apply to auxiliary a flammable or complying to a complying the doors complying the doors complying the door closed what applied. There is closing of the door release when the permitted. Nonrate unlimited height a meeting 19.3.6.3.6 frames shall be laid other materials in unless the smoke sprinklered. Fixed allowed per 8.3. In there are no restricts.	rials have positive latching atches are prohibited by these requirements do not spaces that do not contain bustible material. In bottom of door and floor ceeding 1 inch. Powered with 7.2.1.9 are permissible device capable of keeping then a force of 5 lbf is no impediment to the rs. Hold open devices that door is pushed or pulled are red protective plates of re permitted. Dutch doors of are permitted. Door beled and made of steel or compliance with 8.3,					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

KX7421

Facility ID: 000290

If continuation sheet

Page 4 of 14

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155699		(X2) MULTIPLE C A. BUILDING B. WING	ONSTRUCTION  01	(X3) DATE SURVEY  COMPLETED  02/21/2023		
	ENVIVE	ROVIDER OR SUPPLIER	ТҮ	715 N HARTI	ADDRESS, CITY, STATE, ZIP COD MILL ST FORD CITY, IN 47348	
	(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
		483, and 485 Show in REMARK fire protection ration devices, etc. Based on observation failed to ensure 1 or doors was provided keeping the door closing, latching an smoke. This deficit resident in room 20 Findings include:  Based on observation Director on 02/21/2 to resident room 20 frame when tested of observation, the the corridor door we frame because the bopening.  The finding was revenue.	Parts 403, 418, 460, 482,  (S details of doors such as ngs, automatics closing on and interview, the facility of 1 resident room corridor with a means suitable for losed, had no impediment to do would resist the passage of ent practice could affect 1 on with the Maintenance of at 1:40 p.m., the corridor door of would not close into the Based on interview at the time of Maintenance Director stated ould not close into the door oned was obstructing the object of during the exit with the Executive enance Director d	K 0363	What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice.  No residents were affected by alleged deficient practice.  How other residents having a potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken.  All residents have the potential be affected.  What measures will be put in place and what systemic changes will be made to ensure that the deficient practice does not recur; Bed was removed and replace with a regular size bed allowing the door to close.  Maintenance Director has been educated on K363 citation.  How the corrective action(s) will be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be possible process.	this the ne be re all to nto  ed ng en

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155699		(X2) MULTIPLE CO A. BUILDING B. WING	onstruction <u>01</u>	(X3) DATE SURVEY COMPLETED 02/21/2023	
	PROVIDER OR SUPPLIER		715 N	ADDRESS, CITY, STATE, ZIP COD MILL ST FORD CITY, IN 47348	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL . LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
				into place; and b <="" bmonitoring="" be="" reviewed="" during="" monthly quality="" assurance="" meetings="" and="" ongoing=" continued="" compliance.<="" p="">	
K 0500 SS=F Bldg. 01	Section 18.5 and requirements that provided K-tags, be information, along Safety Code or NF should be included		K 0500	K 500	03/10/2023
	current inspection of heaters were in safe 101, Section 19.1.1. to be designed consoperated to minimizemergency requirin This deficient practin the building.  Findings include:	24 fuel fired water heaters had ertificates to ensure the water operating condition. NFPA 3.1 requires all health facilities tructed, maintained and the the possibility of a fire g the evacuation of occupants. In the could affect all occupants		What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice.  No residents were affected by alleged deficient practice.  How other residents having to potential to be affected by the same deficient practice will be affected by the same deficient practice.	this the e oe
	with the Maintenan 12:45 p.m., the four certificates with an Based on interview the Maintenance Di	on during a tour of the facility the Director on 02/21/23 at a boilers had inspection expiration date of 03/13/21. The time of the observation, rector stated the inspection been completed but they have g the permits.		identified and what corrective action(s) will be taken.  All residents have the potentiate be affected.  What measures will be put in place and what systemic changes will be made to	ıl to

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

KX7421

Facility ID: 000290

If continuation sheet

Page 6 of 14

PRINTED: 03/24/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155699		(X2) MULTIPLE CONSTRUCTION  A. BUILDING  B. WING		(X3) DATE SURVEY COMPLETED 02/21/2023	
	PROVIDER OR SUPPLIE		715 N	ADDRESS, CITY, STATE, ZIP COD MILL ST FORD CITY, IN 47348	
(X4) ID PREFIX TAG	(EACH DEFICIE)	STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
		viewed with the Executive tenance Director at the exit		ensure that the deficient practice does not recur; All boiler permits have been obtained and posted.	
	3.1-19(b)			How the corrective action(s) will be monitored to ensure to deficient practice will not recur, i.e., what quality assurance program will be p into place; and b <="" bmonitoring="" will="" be="" reviewed="" during="" monthly="" quality="" assurance="" meetings="" and ongoing="" for="" continued=" compliance.<="" p="">	the out
K 0511 SS=F Bldg. 01	complies with NF Code, electrical w complies with NF Code. Existing in service provided 18.5.1.1, 19.5.1.1 Based on observati failed to ensure exp kitchen was protec Article 406.5 (F) E shall be enclosed s	d Electric gas or related gas piping PA 54, National Fuel Gas wiring and equipment PA 70, National Electric stallations can continue in no hazard to life. 1, 9.1.1, 9.1.2 on and interview, the facility posed wiring located in the ted. NFPA 70, 2011 Edition. Exposed Terminals, Receptacles to that live wiring terminals are tact. This deficient practice	K 0511	K 511  What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice.  No residents were affected by alleged deficient practice.	n
	Based on observati	ons during a tour of the facility		alleged deficient practice.  How other residents having	the

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

KX7421

Facility ID: 000290

If continuation sheet

Page 7 of 14

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155699		(X2) MULTIPLE CONSTRUCTION  A. BUILDING  B. WING		(X3) DATE SURVEY COMPLETED 02/21/2023	
	PROVIDER OR SUPPLIE OF HARTFORD CI		715 N	ADDRESS, CITY, STATE, ZIP COD MILL ST FORD CITY, IN 47348	
(X4) ID PREFIX TAG	SUMMARY (EACH DEFICIEN REGULATORY OF with the Maintenan at 1:15 p.m., there is exposed on the larg the end of the powe the time of observa exposed wiring on kitchen where the p cord. The finding was re-	STATEMENT OF DEFICIENCIE SICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION TO Director (MD) on 02/21/23 TWAS electrical wiring that was ge refrigerator/freezer plug at er cord. Based on interview at tion, the MD agreed there were the refrigerator/freezer in the plug attaches to the power  Viewed with the Executive during the exit conference.	ID PREFIX TAG	PROVIDERS PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)  potential to be affected by th same deficient practice will be identified and what corrective action(s) will be taken.  All residents have the potential be affected. What measures will be put in place and what systemic changes will be made to ensure that the deficient practice does not recur; Maintenance Director has been educated on K511 citation. Maintenance will check after a outside work is done to ensure they have left the area safe ar will pass inspection.	e DATE  e De e  e lil to lito
K 0761 SS=F Bldg. 01	Based on observati	on, records review, and	K 0761	How the corrective action(s) will be monitored to ensure to deficient practice will not recur, i.e., what quality assurance program will be pointo place; and body body body body body body body bod	ut !=""
	interview, the facili	ity failed to ensure annual ng of fire door assemblies accordance of LSC 19.1.1.4.1.1	10701	What corrective action(s) will be accomplished for those	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

KX7421

Facility ID: 000290

If continuation sheet

Page 8 of 14

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155699		(X2) MULTIPI A. BUILDIN B. WING	LE CONSTRUCTION  G  01	(X3) DATE SURVEY  COMPLETED  02/21/2023	
	PROVIDER OR SUPPLIER		715	EET ADDRESS, CITY, STATE, ZIP COI 5 N MILL ST RTFORD CITY, IN 47348	D
(X4) ID PREFIX	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFI	CROSS-REFERENCED TO THE APP	ULD BE COMPLETION COMPLETION
	communicating oper required by 19.1.1.4 corridors and shall be self-closing fire doc 8.3.) LSC 8.3.3.1 Oprotection rating by protected by approvassemblies and fire accompanying hard closing devices, and accordance with the Standard for Fire Deprotectives, except Code. NFPA 80 5.2 shall be inspected a annually, and a write shall be signed and AHJ. NFPA 80, 5.2 shall be visually insubstantial be visually insubstantial be signed and AHJ. NFPA 80, 5.2 shall be visually insubstantial be	cy MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION nings in dividing fire barriers 1.1 shall be permitted only in the protected by approved or assemblies. (See also Section penings required to have a fire Table 8.3.4.2 shall be ted, listed, labeled fire door window assemblies and their ware, including all frames, thorage, and sills in trequirements of NFPA 80, thorage, and other Opening as otherwise specified in this 1.1 states fire door assemblies and tested not less than ten record of the inspection kept for inspection by the 1.4.1 states fire door assemblies pected from both sides to ondition of door assembly. ates as a minimum, the ll be verified: r breaks exist in surfaces of tame. light frames, and glazing beads tely fastened in place, if so the product of the signs of the signs of broken. The protected by approved to the protected by the secured, aligned, the with no visible signs of		X (EACH CORRECTIVE ACTION SHOWN CROSS-REFERENCED TO THE APP	completion DATE  Completion DATE
	from the full open p (7) If a coordinator closes before the ac	osition. is installed, the inactive leaf			

PRINTED: 03/24/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155699		ľ	JILDING	nstruction <u>01</u>	(X3) DATE : COMPL 02/21/	ETED	
	ROVIDER OR SUPPLIER OF HARTFORD CI		STREET ADDRESS, CITY, STATE, ZIP COD 715 N MILL ST HARTFORD CITY, IN 47348				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	ΓE	(X5) COMPLETION DATE
	prohibit operation a frame.  (10) No field modif have been performe (11) Gasketing and inspected to verify this deficient pract.  Findings include:  Based on record rev. Director on 02/21/2 annual inspection for not available for rev. door inspection was interview at the tim observation, the Ma annual fire door inswithin the last year.  This finding was rev.	rare items that interfere or re not installed on the door assembly did that void the label.  edge seals, where required, are their presence and integrity. Ite could affect all residents.  Friew with the Maintenance of an or the fire door assemblies was riew. The last record of fire is completed in 2021. Based on the of records review and dintenance Director stated the pection was not completed					
K 0914 SS=F Bldg. 01	Testing Electrical Systems Testing Hospital-grade reclocations and whe anesthesia is adm initial installation, Additional testing defined by docum	s - Maintenance and s - Maintenance and ceptacles at patient bed are deep sedation or general ainistered, are tested after replacement or servicing. is performed at intervals ented performance data. sted as hospital-grade at					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

KX7421

Facility ID: 000290

If continuation sheet

Page 10 of 14

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION (IDENTIFICATION NUMBER) 155699		(X2) MULTIPLE ( A. BUILDING B. WING	O1	(X3) DATE SURVEY COMPLETED 02/21/2023	
	PROVIDER OR SUPPLIEF		STREET ADDRESS, CITY, STATE, ZIP COD 715 N MILL ST HARTFORD CITY, IN 47348		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	(X5) COMPLETION DATE
	exceeding 12 mor (LIM), if installed, less than or equal the LIM test switch activates both visit. LIM circuits with a manual test is per than or equal to 1 tested per 6.3.3.3 renovation to the Records are main associated repairs containing date, results. 6.3.4 (NFPA 99) Based on observation interview, the facility grade electrical recessleeping rooms were NFPA 99, Health Consection 6.3.4.1.3 stands hospital-grade, at plocations where decanesthesia is adminimervals not exceed section 6.3.3.2, Recommon requires the receptacle shall be a receptacles) shall be a receptacles.	e tested at intervals not on this. Line isolation monitors are tested at intervals of to 1 month by actuating on per 6.3.2.6.3.6, which used and audible alarm. For utomated self-testing, this formed at intervals less 2 months. LIM circuits are 1.2 after any repair or electric distribution system. Itained of required tests and its or modifications, from or area tested, and for modifications, from or area tested, and for establishment of the tested at least annually. For each of the tested at least annually, for estation or general intervals are facilities. Additionally, the separate of the tested at ling 12 months. Additionally, the practice of the tested at ling 12 months. Additionally, the practice of the tested at ling 12 months. Additionally, the practice of the tested at ling 12 months. Additionally, the practice of the tested at ling 12 months. Additionally, the practice of the tested at ling 12 months. Additionally, the practice of the tested at ling 12 months. Additionally, the practice of the tested at ling 12 months. Additionally, the practice of the tested at ling 12 months. Additionally, the practice of the tested at line grounding circuit in each the shall be verified. Correct and neutral connections in practice shall be confirmed; and the grounding blade of each the tested at line	K 0914	K 914  What corrective action(s) who accomplished for those residents found to have be affected by the deficient practice.  No residents were affected by alleged deficient practice.  How other residents having potential to be affected by same deficient practice will identified and what correct action(s) will be taken.  All residents have the potent be affected.  What measures will be put place and what systemic changes will be made to ensure that the deficient practice does not recur; Maintenance Director has be	en  by this  the the be ive  ial to  into

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

KX7421

Facility ID: 000290

If continuation sheet

Page 11 of 14

AND PLAN OF CORRECTION  AND PLAN OF CORRECTION  155699		(X2) MULTIPLE C A. BUILDING B. WING	ONSTRUCTION  01	COMI	E SURVEY PLETED 1/2023
NAME OF PROVIDER OR SUPPLIED		715 N	ADDRESS, CITY, STATE, Z MILL ST FORD CITY, IN 47348		
PREFIX (EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE ACTI CROSS-REFERENCED TO DEFICIENC	ION SHOULD BE THE APPROPRIATE (Y)	(X5) COMPLETION DATE
with the Maintenant between 12:30 p.m resident sleeping ro non-hospital-grade on records review a was available to sh receptacles in resid tested. Based on in observation and records review a was available to sh receptacles in resid tested. Based on in observation and records review a was available to sh receptacles in resid tested. Based on in observation and records resident sleepin hospital-grade and time the annual test.  This finding was reduced by the conference.  3.1-19(b)  K 0920  SS=E  Bldg. 01  Electrical Equipm Extension Cords Power strips in a used for component patient-care-related (PCREE) assemble assembled by quathe conditions of the patient care version-PCREE (e.g. except in long-terned on the patient care version of the patient care version long-terned on the patient care version long-terned long-t	estated it is unknown the last ting was completed.  Eviewed with the Executive enance Director during the exit  ent - Power Cords and ent - Power Cords and patient care vicinity are only		educated on K 914 receptacles have be logged. How the corrective will be monitored to deficient practice or recur, i.e., what que assurance programe into place; and be""> monitoring will during monthly qua meetings for 6 monologoing for continuations.	een tested and e action(s) to ensure the will not lality m will be put ill be reviewed ality assurance oths and will be	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

KX7421

Facility ID: 000290

If continuation sheet

Page 12 of 14

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CO		ONSTRUCTION	(X3) DATE SURVEY			
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER	A. BUILDING		01	COMPLETED			
		155699	B. W	ING	_	02/21/2023			
	PROVIDER OR SUPPLIER		<u> </u>	STREET ADDRESS, CITY, STATE, ZIP COD 715 N MILL ST HARTFORD CITY, IN 47348					
(X4) ID	ID SUMMARY STATEMENT OF DEFICIENCIE			ID	BROWINEDIC DI ANI OF CORDECTION		(X5)		
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION			PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	ATE	COMPLETION		
TAG				TAG	DEFICIENCY)		DATE		
	other UL standard used with general cords are not used wiring of a structur temporarily are relected completion of the installed and meet 10.2.3.6 (NFPA 98 (NFPA 70), 590.30	ooms, power strips meet ls. All power strips are precautions. Extension d as a substitute for fixed re. Extension cords used moved immediately upon purpose for which it was ts the conditions of 10.2.4. Poly, 10.2.4 (NFPA 99), 400-8 (D) (NFPA 70), TIA 12-5 ation and interview, the facility of 1 flexible cords were not used exed wiring. NFPA-70/2011, pecifically permitted in 400.7 ables shall not be used for (1) exed wiring. This deficient it up to all staff in the kitchen.  The kitchen was plugged into by an extension cord. Based time of observation, the cor acknowledged an extension he kitchen.  The wiewed with the Executive enance Director during the exit ation and interview, the facility of 1 power strips for non-PCREE delectrical equipment) in side of resident care vicinity) is deficient practice affects two	K 0	920	What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice.  The power strip and extension cord were removed.  No residents were affected by alleged deficient practice.  How other residents having a potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken.  All residents have the potential be affected.  What measures will be put in place and what systemic changes will be made to ensure that the deficient practice does not recur;  Maintenance Director has been educated on K920 citation State was in serviced on not using power strips or extension cord How the corrective action(s) will be monitored to ensure the	n  this  the  the  the  the  the  the  the  th	03/10/2023		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: KX7421

Facility ID: 000290

If continuation sheet Page 13 of 14

PRINTED: 03/24/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155699	(X2) MULTIPLE CONSTRUCTION  A. BUILDING  B. WING			(X3) DATE SURVEY COMPLETED 02/21/2023			
NAME OF PROVIDER OR SUPPLIER ENVIVE OF HARTFORD CITY				STREET ADDRESS, CITY, STATE, ZIP COD 715 N MILL ST HARTFORD CITY, IN 47348					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION		PREFIX (EACH CORRECTIVE ACTION SHOULD		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	ΤE	(X5) COMPLETION DATE		
	Findings include:  Based on observation with the Maintenance Director on 02/21/23 at 11:50 a.m., in the Activity room there was a power strip in use that did not meet UL-1363. Based on interview at the time of observation, the Maintenance Director agreed a power strip was in use in the Activity room that did not meet UL-1363.  The finding was reviewed with the Executive Director and the Maintenance Director during the exit conference.  3.1-19(b)			deficient practice will not recur, i.e., what quality assurance program will be into place; and ="" b="">monitoring will be reviewed during monthly quassurance meetings for 6 m and will be ongoing for cont compliance.		ty iths			

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: KX7421 Facility ID: 000290 If continuation sheet Page 14 of 14