

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: <b>155432</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>--</u> B. WING <u>      </u>	(X3) DATE SURVEY COMPLETED <b>01/04/2022</b>
NAME OF PROVIDER OR SUPPLIER <b>ALBANY HEALTH CARE &amp; REHABILITATION CENTER</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>910 W WALNUT ST ALBANY, IN 47320</b>	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
E 0000  Bldg. --	<p>An Emergency Preparedness Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.73.</p> <p>Survey Date: 01/04/22</p> <p>Facility Number: 000309 Provider Number: 155432 AIM Number: 100288960</p> <p>At this Emergency Preparedness survey, Albany Health Care &amp; Rehabilitation Center was found in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73</p> <p>The facility has 102 certified beds. At the time of the survey, the census was 72.</p> <p>Quality Review completed on 01/05/22</p>		E 0000	<p>The completion of this plan of correction does not constitute an admission that the alleged deficiencies exists. The plan of correction is provided as evidence of the facilities desire to comply with the regulations and continue to provide quality care in a safe environment.</p> <p>The facility is requesting a desk review for compliance.</p>
K 0000  Bldg. 01	<p>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a).</p> <p>Survey Date: 01/04/22</p> <p>Facility Number: 000309 Provider Number: 155432 AIM Number: 100288960</p> <p>At this Life Safety Code survey, Albany Health</p>		K 0000	<p>The completion of this plan of correction does not constitute an admission that the alleged deficiencies exists. The plan of correction is provided as evidence of the facilities desire to comply with the regulations and continue to provide quality care in a safe environment.</p> <p>The facility is requesting a desk review for compliance.</p>

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: <b>155432</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01</b> B. WING _____	(X3) DATE SURVEY COMPLETED <b>01/04/2022</b>
NAME OF PROVIDER OR SUPPLIER <b>ALBANY HEALTH CARE &amp; REHABILITATION CENTER</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>910 W WALNUT ST ALBANY, IN 47320</b>	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
K 0222 SS=F Bldg. 01	<p>Care and Rehabilitation Center was found not in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies.</p> <p>This one-story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors, spaces open to the corridors and hard-wired smoke detectors in the resident rooms. The facility has a capacity of 102 and had a census of 72 at the time of this survey.</p> <p>All areas where the residents have customary access were sprinklered. All areas providing facility services were sprinklered except a barn for beds and wheelchairs and a garage for maintenance equipment which were not sprinklered.</p> <p>Quality Review completed on 01/05/22</p> <p>NFPA 101 Egress Doors Egress Doors Doors in a required means of egress shall not be equipped with a latch or a lock that requires the use of a tool or key from the egress side unless using one of the following special locking arrangements: CLINICAL NEEDS OR SECURITY THREAT LOCKING Where special locking arrangements for the clinical security needs of the patient are used, only one locking device shall be</p>			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	(X3) DATE SURVEY COMPLETED 01/04/2022
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
	<p>permitted on each door and provisions shall be made for the rapid removal of occupants by: remote control of locks; keying of all locks or keys carried by staff at all times; or other such reliable means available to the staff at all times.</p> <p>18.2.2.2.5.1, 18.2.2.2.6, 19.2.2.2.5.1, 19.2.2.2.6</p> <p><b>SPECIAL NEEDS LOCKING ARRANGEMENTS</b></p> <p>Where special locking arrangements for the safety needs of the patient are used, all of the Clinical or Security Locking requirements are being met. In addition, the locks must be electrical locks that fail safely so as to release upon loss of power to the device; the building is protected by a supervised automatic sprinkler system and the locked space is protected by a complete smoke detection system (or is constantly monitored at an attended location within the locked space); and both the sprinkler and detection systems are arranged to unlock the doors upon activation.</p> <p>18.2.2.2.5.2, 19.2.2.2.5.2, TIA 12-4</p> <p><b>DELAYED-EGRESS LOCKING ARRANGEMENTS</b></p> <p>Approved, listed delayed-egress locking systems installed in accordance with 7.2.1.6.1 shall be permitted on door assemblies serving low and ordinary hazard contents in buildings protected throughout by an approved, supervised automatic fire detection system or an approved, supervised automatic sprinkler system.</p> <p>18.2.2.2.4, 19.2.2.2.4</p> <p><b>ACCESS-CONTROLLED EGRESS LOCKING ARRANGEMENTS</b></p> <p>Access-Controlled Egress Door assemblies installed in accordance with 7.2.1.6.2 shall</p>			(X5) COMPLETION DATE

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING  01	(X3) DATE SURVEY COMPLETED 01/04/2022	
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>be permitted. 18.2.2.2.4, 19.2.2.2.4</p> <p><b>ELEVATOR LOBBY EXIT ACCESS LOCKING ARRANGEMENTS</b></p> <p>Elevator lobby exit access door locking in accordance with 7.2.1.6.3 shall be permitted on door assemblies in buildings protected throughout by an approved, supervised automatic fire detection system and an approved, supervised automatic sprinkler system.</p> <p>18.2.2.2.4, 19.2.2.2.4</p> <p>Based on observation and interview, the facility failed to ensure the means of egress for all exit doors was readily accessible for residents without a clinical diagnosis requiring specialized security measures. Doors within a required means of egress shall not be equipped with a latch or lock that requires the use of a tool or key from the egress side unless otherwise permitted by LSC 19.2.2.2.4. Door-locking arrangements shall be permitted in accordance with 19.2.2.2.5.2. This deficient practice could affect all staff, residents and visitors when needing to exit the facility.</p> <p>Findings include:</p> <p>Based on observations and interview during a tour of the facility with the Maintenance Director on 01/04/22 between 12:15 p.m. and 2:30 p.m., the main exit doors in the front of the facility were posted with a code which was located on the bottom of the magnetic door closer. This placement was several feet away from the keypad and could be confusing and excessively difficult for a guest to figure out in the event of an emergency exit. This finding was acknowledged by the Maintenance Director at the time of observation and again at the exit</p>		K 0222	<p><b>1. What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice?</b></p> <p>No residents were harmed by this alleged deficiency. The maintenance supervisor relocated the code for the magnetic door closer and placed it directly on the keypad where it is readily accessible.</p> <p><b>2. How other residents having the potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken?</b></p> <p>All residents, staff, and visitors have the potential to be affected by this alleged deficiency. The code to the magnetic door closer is now available on the keypad.</p> <p><b>3. What measures will be put into place or what systemic changes will be made to ensure that deficient practice does not</b></p>	01/17/2022

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING  01	(X3) DATE SURVEY COMPLETED 01/04/2022
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
K 0321 SS=E Bldg. 01	<p>conference with the Maintenance Director present at 3:00 p.m.</p> <p>3.1-19(b)</p> <p>NFPA 101</p> <p>Hazardous Areas - Enclosure</p> <p>Hazardous Areas - Enclosure</p> <p>Hazardous areas are protected by a fire barrier having 1-hour fire resistance rating (with 3/4 hour fire rated doors) or an automatic fire extinguishing system in accordance with 8.7.1 or 19.3.5.9. When the approved automatic fire extinguishing system option is used, the areas shall be separated from other spaces by smoke resisting partitions and doors in accordance with 8.4. Doors shall be self-closing or</p>			<p><b>recur?</b></p> <p>Maintenance staff were educated on the requirement of facility egress doors. The Director of Plant Operations or his designee will make rounds on all facility egress doors weekly for 4 weeks and until 100% compliance is achieved, then monthly thereafter.</p> <p><b>4. How will the corrective action(s) be monitored to ensure the deficient practice will not recur?</b></p> <p>ie: what QA program will be put into place and by what date will they be completed.</p> <p>The findings of these audits will be presented during the facility's monthly QAPI meetings for review. The facility through the QAPI program, will review, update, and make changes to the Plan of Correction as needed for sustaining compliance for no less than 6 months.</p>



STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	(X3) DATE SURVEY COMPLETED 01/04/2022
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
	<p>interview at the time of observation, the Maintenance Director acknowledged the aforementioned condition and stated they would prepare the popcorn in the kitchen or outside away from the canopy. This finding was acknowledged by the Maintenance Director at the time of observation and again at the exit conference with the Maintenance Director present at 3:00 p.m.</p> <p>3.1-19(b)</p>			<p>visitors have the potential to be affected by this alleged deficiency. The popcorn machine will be removed and stored outside of the facility until a suitable room that is properly identified/equipped as a "hazardous room" has been identified. Popcorn will be prepared in the kitchen underneath the Automatic Fire Extinguishing hood system or outdoors away from the canopy.</p> <p><b>3. What measures will be put into place or what systemic changes will be made to ensure that deficient practice does not recur?</b></p> <p>Maintenance staff were educated on the requirement for using a popcorn machine as it relates to a hazardous area. The Director of Plant Operations or his designee will make rounds through the facility checking for hazardous areas, twice weekly for 4 weeks and until 100% compliance is achieved, then weekly thereafter.</p> <p><b>4. How will the corrective action(s) be monitored to ensure the deficient practice will not recur?</b></p> <p>ie: what QA program will be put into place and by what date will they be completed.</p> <p>The findings of these audits will be presented during the facility's monthly QAPI meetings for review. The facility through the</p>

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING  01	(X3) DATE SURVEY COMPLETED 01/04/2022
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 0353 SS=E Bldg. 01	<p>NFPA 101</p> <p>Sprinkler System - Maintenance and Testing</p> <p>Sprinkler System - Maintenance and Testing</p> <p>Automatic sprinkler and standpipe systems are inspected, tested, and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintaining of Water-based Fire Protection Systems.</p> <p>Records of system design, maintenance, inspection and testing are maintained in a secure location and readily available.</p> <p>a) Date sprinkler system last checked</p> <p>_____</p> <p>b) Who provided system test</p> <p>_____</p> <p>c) Water system supply source</p> <p>_____</p> <p>Provide in REMARKS information on coverage for any non-required or partial automatic sprinkler system.</p> <p>9.7.5, 9.7.7, 9.7.8, and NFPA 25</p> <p>Based on observation and interview, the facility failed to ensure sprinkler heads in the laundry were not loaded or covered with foreign material in accordance with LSC 9.7.5. NFPA 25, 2011 edition, at 5.2.1.1.1 sprinklers shall not show signs of leakage; shall be free of corrosion, foreign materials, paint, and physical damage; and shall be installed in the correct orientation (e.g., up-right, pendent, or sidewall). Furthermore, at 5.2.1.1.2 any sprinkler that shows signs of any of the following shall be replaced: (1) Leakage (2) Corrosion (3) Physical Damage (4) Loss of fluid in the glass bulb heat responsive element (5)</p>	K 0353	<p>QAPI program, will review, update, and make changes to the Plan of Correction as needed for sustaining compliance for no less than 6 months.</p> <p>_____</p> <p>1. <b>What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice?</b></p> <p>No residents were harmed by this alleged deficiency. The two sprinkler heads in the laundry area were immediately cleaned to remove the dust that had accumulated on them.</p> <p>_____</p> <p>2. <b>How other residents</b></p>	01/17/2022

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	(X3) DATE SURVEY COMPLETED 01/04/2022
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>Loading (6) Painting unless painted by the sprinkler manufacturer. This deficient practice could affect 3 staff in the laundry area.</p> <p>Findings include:</p> <p>Based on observations and interview during a tour of the facility with the Maintenance Director on 01/04/22 between 12:15 p.m. and 2:30 p.m., 2 of 2 sprinkler heads in the laundry area were coved in dust or showed signs of loading.</p> <p>This finding was acknowledged by the Maintenance Director at the time of observation and again at the exit conference with the Maintenance Director present at 3:00 p.m.</p> <p>3.1-19(b)</p>		<p><b>having the potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken?</b></p> <p>Only laundry staff have the potential to be affected by this alleged deficiency. The maintenance supervisor immediately cleaned the 2 sprinkler heads.</p> <p><b>3. What measures will be put into place or what systemic changes will be made to ensure that deficient practice does not recur?</b></p> <p>Maintenance/environmental staff were educated on the requirement of maintaining our sprinkler systems. The Director of Plant Operations or his designee will make rounds on all sprinkler heads twice weekly for 4 weeks and until 100% compliance is achieved, then weekly thereafter.</p> <p><b>4. How will the corrective action(s) be monitored to ensure the deficient practice will not recur?</b></p> <p>ie: what QA program will be put into place and by what date will they be completed.</p> <p>The findings of these audits will be presented during the facility's monthly QAPI meetings for review. The facility through the QAPI program, will review, update, and make changes to the Plan of Correction as needed for</p>	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING  01	(X3) DATE SURVEY COMPLETED 01/04/2022
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
K 0372 SS=E Bldg. 01	<p>NFPA 101</p> <p>Subdivision of Building Spaces - Smoke Barrie</p> <p>Subdivision of Building Spaces - Smoke Barrier Construction</p> <p>2012 EXISTING</p> <p>Smoke barriers shall be constructed to a 1/2-hour fire resistance rating per 8.5.</p> <p>Smoke barriers shall be permitted to terminate at an atrium wall. Smoke dampers are not required in duct penetrations in fully ducted HVAC systems where an approved sprinkler system is installed for smoke compartments adjacent to the smoke barrier.</p> <p>19.3.7.3, 8.6.7.1(1)</p> <p>Describe any mechanical smoke control system in REMARKS.</p> <p>Based on observation and interview, the facility failed to ensure unsealed holes in 1 of 1 ceiling smoke barriers were protected to maintain the smoke resistance of the ceiling smoke barrier.</p> <p>LSC Section 19.3.7.5 requires smoke barriers to be constructed in accordance with LSC Section 8.5 and shall have a minimum ½ hour fire resistive rating. LSC Section 8.5.2.1 requires smoke barriers to be continuous from an outside wall to an outside wall, from a floor to a floor, or from a smoke barrier to a smoke barrier, or by use of a combination thereof. 8.5.6.2 requires penetrations for cables, cable trays, conduits, pipes, tubes, vents, wires, and similar items to accommodate electrical, mechanical, plumbing, and communications systems that pass through a wall, floor, or floor/ceiling assembly constructed as a smoke barrier, or through the ceiling membrane of the roof/ceiling of a smoke</p>		K 0372	<p>sustaining compliance for no less than 6 months.</p> <p><b>1. What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice?</b> No residents were harmed by this alleged deficiency. Fire caulk was immediately applied around the penetration in the area above the ice machine in the south dining room.</p> <p><b>2. How other residents having the potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken?</b> All residents, staff, and visitors</p>

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	(X3) DATE SURVEY COMPLETED 01/04/2022	
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 0511 SS=E Bldg. 01	<p>barrier assembly, shall be protected by a system or material capable of restricting the movement of smoke. This deficient practice could affect staff in the dining and common area and 20 residents in the dining room.</p> <p>Findings include:</p> <p>Based on observations and interview during a tour of the facility with the Maintenance Director on 01/04/22 between 12:15 p.m. and 2:30 p.m., above the ice machine in the south dining area in the ceiling smoke barrier there was approximately a 4-inch unsealed hole around the wiring to the new ice machine.</p> <p>This finding was acknowledged by the Maintenance Director at the time of observation and again at the exit conference with the Maintenance Director present at 3:00 p.m.</p> <p>3.1-19(b)</p>			<p>have the potential to be affected by this alleged deficiency. The maintenance supervisor immediately fire caulked around the penetration.</p> <p><b>3. What measures will be put into place or what systemic changes will be made to ensure that deficient practice does not recur?</b></p> <p>Maintenance staff were educated on the requirement of maintaining facility smoke barriers. The Director of Plant Operations or his designee will make rounds on all facility smoke barrier walls twice weekly for 4 weeks and until 100% compliance is achieved, then weekly thereafter.</p> <p><b>4. How will the corrective action(s) be monitored to ensure the deficient practice will not recur?</b></p> <p><b>ie: what QA program will be put into place and by what date will they be completed.</b></p> <p>The findings of these audits will be presented during the facility's monthly QAPI meetings for review. The facility through the QAPI program, will review, update, and make changes to the Plan of Correction as needed for sustaining compliance for no less than 6 months.</p>	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING  01	(X3) DATE SURVEY COMPLETED 01/04/2022
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>Equipment using gas or related gas piping complies with NFPA 54, National Fuel Gas Code, electrical wiring and equipment complies with NFPA 70, National Electric Code. Existing installations can continue in service provided no hazard to life.</p> <p>18.5.1.1, 19.5.1.1, 9.1.1, 9.1.2</p> <p>1. Based on observation and interview, the facility failed to ensure 2 of over 10 wet locations were provided with ground fault circuit interrupter (GFCI) protection against electric shock. LSC 19.5.1.1 requires utilities comply with Section 9.1. LSC 9.1.2 requires electrical wiring and equipment to comply with NFPA 70, National Electrical Code. NFPA 70, NEC 2011 Edition at 210.8 Ground-Fault Circuit-Interrupter Protection for Personnel, states, ground-fault circuit-interruption for personnel shall be provided as required in 210.8(A) through (C). The ground-fault circuit-interrupter shall be installed in a readily accessible location.</p> <p>(B) Other Than Dwelling Units. All 125-volt, single-phase, 15- and 20-ampere receptacles installed in the locations specified in 210.8(B) (1) through (8) shall have ground-fault circuit-interrupter protection for personnel.</p> <p>(1) Bathrooms (2) Kitchens (3) Rooftops (4) Outdoors</p> <p>Exception No. 1 to (3) and (4): Receptacles that are not readily accessible and are supplied by a branch circuit dedicated to electric snow-melting, deicing, or pipeline and vessel heating equipment shall be permitted to be installed in accordance with 426.28 or 427.22, as applicable.</p> <p>Exception No. 2 to (4): In industrial establishments only, where the conditions of</p>	K 0511	<p><b>1. What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice?</b></p> <p>No residents were harmed by this alleged deficiency. An electrician was immediately hired to install a GFCI outlet dedicated to the Ice machine. The Maintenance Supervisor immediately installed locks on the two electrical panels that are located in the corridor.</p> <p><b>2. How other residents having the potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken?</b></p> <p>All residents, staff, and visitors have the potential to be affected by this alleged deficiency. The maintenance supervisor immediately hired an electrician to come and install a GFCI outlet dedicated to the Ice machine. The maintenance supervisor immediately installed locks on two electrical panels located in the corridor.</p> <p><b>3. What measures will be put into place or what systemic changes will be made to ensure</b></p>	01/17/2022

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	(X3) DATE SURVEY COMPLETED 01/04/2022	
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>maintenance and supervision ensure that only qualified personnel are involved, an assured equipment grounding conductor program as specified in 590.6(B)(2) shall be permitted for only those receptacle outlets used to supply equipment that would create a greater hazard if power is interrupted or having a design that is not compatible with GFCI protection.</p> <p>(5) Sinks - where receptacles are installed within 1.8 m (6 ft.) of the outside edge of the sink. Exception No. 1 to (5): In industrial laboratories, receptacles used to supply equipment where removal of power would introduce a greater hazard shall be permitted to be installed without GFCI protection.</p> <p>Exception No. 2 to (5): For receptacles located in patient bed locations of general care or critical care areas of health care facilities other than those covered under 210.8(B)(1), GFCI protection shall not be required.</p> <p>(6) Indoor wet locations</p> <p>(7) Locker rooms with associated showering facilities</p> <p>(8) Garages, service bays, and similar areas where electrical diagnostic equipment, electrical hand tools.</p> <p>NFPA 70, 517-20 Wet Locations, requires all receptacles and fixed equipment within the area of the wet location to have ground-fault circuit interrupter (GFCI) protection. Note: Moisture can reduce the contact resistance of the body, and electrical insulation is more subject to failure. This deficient practice could affect staff and up to 4 residents while at the ice machine, and 2 staff in the Nutrition Pantry.</p> <p>Findings include:</p> <p>Based on observations and interview during a</p>		<p><b>that deficient practice does not recur?</b></p> <p>Maintenance staff were educated on the requirement of maintaining and auditing the facility wet locations as well as the security of the electrical panels. The Director of Plant Operations or his designee will make rounds on all wet locations and electrical panels twice weekly for 4 weeks and until 100% compliance is achieved, then weekly thereafter.</p> <p><b>4. How will the corrective action(s) be monitored to ensure the deficient practice will not recur?</b></p> <p><b>ie: what QA program will be put into place and by what date will they be completed.</b></p> <p>The findings of these audits will be presented during the facility's monthly QAPI meetings for review. The facility through the QAPI program, will review, update, and make changes to the Plan of Correction as needed for sustaining compliance for no less than 6 months.</p>		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	(X3) DATE SURVEY COMPLETED 01/04/2022
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>tour of the facility with the Maintenance Director on 01/04/22 between 12:15 p.m. and 2:30 p.m., the ice machine (1) in the South Dining and common area was connected to an electric receptacle which was being used to power the freestanding ice machine, with it's own water supply. The ice machine was located within 3 feet of the electric receptacle, and not provided with ground fault circuit interruption (GFCI). The Maintenance Director at the time of observation stated he did not believe the receptacle was on a GFCI circuit.</p> <p>This finding was acknowledged by the Maintenance Director at the time of observation and again at the exit conference with the Maintenance Director present at 3:00 p.m.</p> <p>2. Based on observation and interview, the facility failed to ensure all electrical panels in the corridors were secured from non-authorized personnel. NFPA 70, 2011 edition states 230.62 Energized parts of service equipment shall be enclosed as specified in 230.62(A) or guarded as specified in 230.62(B).</p> <p>(A) Enclosed. Energized parts shall be enclosed so that they will not be exposed to accidental contact or shall be guarded as in 230.62(B).</p> <p>(B) Guarded. Energized parts that are not enclosed shall be installed on a switchboard, panelboard, or control board and guarded in accordance with 110.18 and 110.27. Where energized parts are guarded as provided in 110.27(A)(1) and (A)(2), a means for locking or sealing doors providing access to energized parts shall be provided. This deficient practice could affect residents and staff in the 100 and 200 halls.</p> <p>Findings include:</p>			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	(X3) DATE SURVEY COMPLETED 01/04/2022
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
K 0920 SS=D Bldg. 01	<p>Based on observations and interview during a tour of the facility with the Maintenance Director on 01/04/22 between 12:15 p.m. and 2:30 p.m., two electrical panels, (1) in the 100 hall and (2) in the 200 hall were unlocked when tested. Based on interview at the time of observation, the Maintenance Director stated the electrical panel will need to be locked. This finding was acknowledged by the Maintenance Director at the time of observation and again at the exit conference with the Maintenance Director present at 3:00 p.m.</p> <p>3.1-19(b)</p> <p>NFPA 101 Electrical Equipment - Power Cords and Extens Electrical Equipment - Power Cords and Extension Cords Power strips in a patient care vicinity are only used for components of movable patient-care-related electrical equipment (PCREE) assemblies that have been assembled by qualified personnel and meet the conditions of 10.2.3.6. Power strips in the patient care vicinity may not be used for non-PCREE (e.g., personal electronics), except in long-term care resident rooms that do not use PCREE. Power strips for PCREE meet UL 1363A or UL 60601-1. Power strips for non-PCREE in the patient care rooms (outside of vicinity) meet UL 1363. In non-patient care rooms, power strips meet other UL standards. All power strips are used with general precautions. Extension cords are not used as a substitute for fixed wiring of a structure. Extension cords used temporarily are removed immediately upon completion of the purpose for which it was</p>			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	(X3) DATE SURVEY COMPLETED 01/04/2022	
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>installed and meets the conditions of 10.2.4. 10.2.3.6 (NFPA 99), 10.2.4 (NFPA 99), 400-8 (NFPA 70), 590.3(D) (NFPA 70), TIA 12-5</p> <p>Based on observation and interview, the facility failed to ensure 1 of 1 flexible cords were not used as a substitute for fixed wiring. NFPA-70/2011, 400.8 state unless specifically permitted in 400.7 flexible cords and cables shall not be used for (1) as a substitute for fixed wiring. This deficient practice could affect up to 1 staff in the mechanical room.</p> <p>Findings include:</p> <p>Based on observations and interview during a tour of the facility with the Maintenance Director on 01/04/22 between 12:15 p.m. and 2:30 p.m., in the mechanical room on the 100 hall the water softener transformers were being powered by an extension cord what was plugged into a wall outlet approximately 8 feet away from the aforementioned transformers. Based on interview at the time of observation, the Maintenance Director acknowledged an extension cord was in use as described above and stated the water softeners were fairly new.</p> <p>This finding was acknowledged by the Maintenance Director at the time of observation and again at the exit conference with the Maintenance Director present at 3:00 p.m.</p> <p>3.1-19(b)</p>		K 0920	<p><b>1. What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice?</b></p> <p>No residents were harmed by this alleged deficiency. The Maintenance Supervisor immediately hired an electrician to install a dedicated outlet to the water softener, eliminating the need for an extension cord.</p> <p><b>2. How other residents having the potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken?</b></p> <p>All residents, staff, and visitors have the potential to be affected by this alleged deficiency. The maintenance supervisor immediately hired an electrician to come and install an outlet dedicated to the water softener.</p> <p><b>3. What measures will be put into place or what systemic changes will be made to ensure that deficient practice does not recur?</b></p> <p>Maintenance staff were educated on the requirement of maintaining and auditing power cords/power strips for proper use. The Director of Plant Operations or his designee will make rounds</p>	01/17/2022

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155432	(X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	(X3) DATE SURVEY COMPLETED 01/04/2022
NAME OF PROVIDER OR SUPPLIER  ALBANY HEALTH CARE & REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE  910 W WALNUT ST ALBANY, IN 47320	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)
				<p>through facility twice weekly for 4 weeks and until 100% compliance is achieved, then weekly thereafter.</p> <p><b>4. How will the corrective action(s) be monitored to ensure the deficient practice will not recur?</b></p> <p>ie: what QA program will be put into place and by what date will they be completed.</p> <p>The findings of these audits will be presented during the facility's monthly QAPI meetings for review. The facility through the QAPI program, will review, update, and make changes to the Plan of Correction as needed for sustaining compliance for no less than 6 months.</p>