PRINTED: 11/15/2022

DEPARTMENT OF HEALTH AND HU	FORM APPROVED			
CENTERS FOR MEDICARE & MEDIC	OMB NO. 0938-039			
STATEMENT OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) MU	JLTIPLE CONSTRUCTION	(X3) DATE SURVEY
AND PLAN OF CORRECTION	IDENTIFICATION NUMBER	A. BU	ILDING	COMPLETED
	155292	B. WI	NG	10/18/2022
NAME OF PROVIDER OR SUPPLIEF	<u> </u>		STREET ADDRESS, CITY, STATE, ZIP COD 2026 EAST 54TH ST INDIANAPOLIS, IN 46220	•

AIVIERIC	AN VILLAGE	INDIAN	INDIANAPOLIS, IN 46220				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
E 0000	REGULATORY OR ESC IDENTIFY THIS INFORMATION	TAG		DATE			
Blda							
Bldg	An Emergency Preparedness Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.73. Survey Date: 10/18/22 Facility Number: 000189 Provider Number: 155292 AIM Number: 100267330 At this Emergency Preparedness survey, American Village was found in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73. The facility has 150 certified beds. At the time of the survey, the census was 113. Quality Review completed on 10/21/22	E 0000	This Plan of correction constitutes this facility's written allegation of compliance for the deficiencies cited. The submission of this plan of correction is not an admission of or agreement with the deficiencies or conclusions contained in the Indiana Department of Health's inspection report. American Village respectfully requests consideration for a desk review of this plan of correction.				
Bldg. 01							
J ·	A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a). Survey Date: 10/18/22 Facility Number: 000189 Provider Number: 155292 AIM Number: 100267330 At this Life Safety Code survey, American Village was found not in compliance with Requirements	K 0000	This Plan of correction constitutes this facility's written allegation of compliance for the deficiencies cited. The submission of this plan of correction is not an admission of or agreement with the deficiencies or conclusions contained in the Indiana Department of Health's inspection report. American Village respectfully requests consideration for a desk review of this plan of correction.				

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Gina Couch **Executive Director** 11/04/2022

Any defiencystatement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: TRCV21 Facility ID: 000189 If continuation sheet Page 1 of 10

	IT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155292	(X2) MULTIPLE CO A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 10/18/2022
	PROVIDER OR SUPPLIEF		2026 E	ADDRESS, CITY, STATE, ZIP COD AST 54TH ST JAPOLIS, IN 46220	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	(X5) COMPLETION DATE
	Subpart 483.90(a), 2012 Edition of the Association (NFPA Chapter 19, Existing 410 IAC 16.2. American Village of Hall which is one stores to be of Type III (2 sprinklered. The east Washington Manor rehab wing. The fact with smoke detection and in all areas open has battery operated resident sleeping rode tectors hard wires system in 23 of 82 of facility has a capacital at the time of the All areas where residents were sprinklered. As services were sprinklered. As services were sprinklered and repair services were sprinklered and repair services were sprinklered.	idents have customary access All areas providing facility klered except for a detached			
K 0291 SS=F Bldg. 01	duration is provide accordance with 7 18.2.9.1, 19.2.9.1 Based on observation failed to ensure 14 of	ng g of at least 1-1/2-hour ed automatically in	K 0291	K291 Emergency Lighting What corrective action(s) will be accomplished for those	11/11/2022

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

 $TRCV21 \hspace{0.5cm} \textit{Facility ID:} \hspace{0.5cm} 000189$

If continuation sheet

Page 2 of 10

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155292		(X2) MULTII A. BUILDI B. WING		nstruction 01	(X3) DATE SURVEY COMPLETED 10/18/2022		
	PROVIDER OR SUPPLIEF		20)26 EA	DDRESS, CITY, STATE, ZIP COD AST 54TH ST APOLIS, IN 46220		
(X4) ID PREFIX	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	JLL PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPER OF THE CROSS-REFERENCY)		(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA		
TAG	year to ensure the liduring periods of perecord of visual insprovided. Section 7 testing shall be condiminimum of 3 week between tests, for new Functional testing so a minimum of 1 1/2 system is battery period of visual inspection the owner for insperior insperior in the facility of visual inspection. This depression is the facility of the facility of the report of visual inspection. This depression is necessionally inspection. This depression is the facility of the report of the report of the report of the report had a slass through August of 2 inspections being not the time of record record inspections being not the time of record record inspections being not the time of the battery on the began soon as he took over position. Based on tour of the facility for was noted that the final battery-operated emplocations throughout.	riew of the document entitled mergency light inspection the facility outgoing or, on 10/19/22 at 12:35 p.m., which through January 2022 2022 with no documented oted. Based on interview at eview, the outgoing or acknowledged that he ery-operated emergency lights thing but added that the facility tenance person for that period in to document the checks as in the Maintenance Director observations made during a from 12:40 p.m. to 2:40 p.m. it facility did indeed have the property of the facility at various	TA	AG .	residents found to have bee affected by the deficient practice All 14 of 14 Battery-operated emergency lights were tested recorded. How other residents having potential to be affected by the same deficient practice will identified and what corrective action(s) will be taken No residents were affected by alleged deficient practice. All residents, visitors and staff have the potential to be affected by the alleged deficient practice. What measures will be put in place or what systemic changes will be made to ensure that the deficient practice does not recur Maintenance Director has been educated on required monthly second battery-operated emergency lighting testing allowith recording A maintenance audit tool will completed to ensure the batter operated lights are being testing allowith recording. How the corrective action(s) will be monitored to ensure deficient practice will not recur, ie., what quality assurance program will be put into place The POC QAPI Tool will utilized by ED/designee week 4 weeks, monthly x 6 months quarterly thereafter for one years.	the he be ve y the fited ce nto en y 30 ong be ery ed. the the be the the the the the the the the the th	

	OF CORRECTION	IDENTIFICATION NUMBER 155292	A. BUILDING B. WING	01	COMPLETED 10/18/2022
	ROVIDER OR SUPPLIER		2026 E	ADDRESS, CITY, STATE, ZIP COD AST 54TH ST NAPOLIS, IN 46220	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
	at the exit conference 3.1-19(b)	re held on 10/18/22 at 2:45 p.m.		with results reported to the Qu Assurance and Performance Improvement Committee over by the Executive Director If a threshold of 95% is n achieved, an action plan will b developed to ensure complian	seen ot e
K 0300 SS=F Bldg. 01	Section 18.3 and 1 requirements that provided K-tags, b information, along Safety Code or NF should be included K300 - Based on recobservation, the faci documentation for the public, if not maintained. NFPA Tests. Fire-warning and tested in accord published instruction of Chapter 14. NFPA testing, and mainten the requirements of equipment manufact This deficient practice staff, and visitors. Findings include:	are not addressed by the ut are deficient. This with the applicable Life FPA standard citation, d on Form CMS-2567. cord review, interview and	K 0300	K300 Protection - Other What corrective action(s) will be accomplished for those residents found to have beer affected by the deficient practice All 59 of 59 smoke alarms were tested and recorded. How other residents having a potential to be affected by the same deficient practice will a identified and what corrective action(s) will be taken No residents were affected by alleged deficient practice. All residents, visitors and staff have the potential to be affecte by the alleged deficient practice What measures will be put in place or what systemic changes will be made to ensure that the deficient	the e ce the e ce

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

 $TRCV21 \hspace{0.5cm} \textit{Facility ID:} \hspace{0.5cm} 000189$

If continuation sheet

Page 4 of 10

PRINTED: 11/15/2022 FORM APPROVED

CENTERS FOI	R MEDICARE & MEDIC	AID SERVICES				OM	B NO. 0938-039
STATEMEN	NT OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) MU	LTIPLE CO	ONSTRUCTION	(X3) DATE	SURVEY
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	ILDING	01	COMPL	ETED
		155292	B. WI	NG		10/18/	2022
	PROVIDER OR SUPPLIER AN VILLAGE SUMMARY	STATEMENT OF DEFICIENCIE		2026 E	ADDRESS, CITY, STATE, ZIP COD AST 54TH ST IAPOLIS, IN 46220		(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE		COMPLETION
TAG	,	R LSC IDENTIFYING INFORMATION		TAG	CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	DATE
	Maintenance Direct there was no itemiz operated smoke ala: 2022 through Auguinterview at the tim outgoing Maintenan battery-operated sm recommendations cadded that the faciliperson for that periodocument the check Maintenance Direct observations made from 12:40 p.m. to sleeping rooms survindeed have battery within them. This finding was re Administrator, the cand the incoming Maintenance Direct observations made from 12:40 p.m. to sleeping rooms survindeed have battery within them.	the facility outgoing for, on 10/19/22 at 12:02 p.m., ed list of resident room battery rms testing for January 1st st 14th of 2022. Based on e of record review, the nee Director acknowledged the toke detector manufacturer alled for monthly testing but the was without a Maintenance and of time, so he began to as as soon as he took over the tor position. Based on during a tour of the facility 2:40 p.m., 59 of 82 resident veyed within the facility did operated smoke detectors viewed with the facility butgoing Maintenance Director faintenance Director at the exit 10/18/22 at 2:45 p.m.			practice does not recur Maintenance Director has bee educated on testing and recor battery operated smoke alarm A maintenance audit tool will be completed to ensure all batter operated smoke alarms are te in accordance with the manufacturer's guidelines How the corrective action(s) will be monitored to ensure the deficient practice will not recur, ie., what quality assurance program will be positive into place The POC QAPI Tool will utilized by ED/designee weeks a weeks, monthly x 6 months, quarterly thereafter for one year with results reported to the Quantal Assurance and Performance and Performance and Performance in the provement Committee over by the Executive Director If a threshold of 95% is not achieved, an action plan will be developed to ensure compliant.	ding s. see y sted he ut be y x and ar adity seen ot e	
K 0355 SS=E Bldg. 01	installed, inspecte accordance with N Portable Fire Extir 18.3.5.12, 19.3.5.	orguishers guishers are selected, d, and maintained in NFPA 10, Standard for nguishers. 12, NFPA 10					
	failed to ensure 1 of	on and interview, the facility f 1 portable fire extinguishers in installed in accordance with	K 03	355	K355 Portable Fire Extinguish What corrective actions will accomplished for those		11/11/2022

NFPA 10, Standard for Portable Fire Extinguishers,

residents found to have been

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) M	(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	a. building <u>01</u>			COMPLETED	
		155292	B. W	ING		10/18/	2022	
		<u> </u>		CTDEET /	ADDRESS, CITY, STATE, ZIP COD			
NAME OF F	PROVIDER OR SUPPLIEF	₹			AST 54TH ST			
AMEDIC	AN VILLAGE							
AWERICA	AN VILLAGE			INDIAN	APOLIS, IN 46220			
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	(EACH DEFICIEN	ICY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	TE	COMPLETION	
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE	
	2010 Edition. Section				affected by the deficient			
	_	be conspicuously located			practice			
	1	readily accessible and			The walker and wheelchair we	re		
	· ·	ble in the event of a fire.			immediately removed from in f	ront		
	1	ll be located along normal			of the portable fire extinguishe	r		
	1 ~	uding exits from areas. This			located in the lobby.			
	_	yould affect as many as 2			How other residents having t			
	residents, 2 staff an	d 1 visitor.			potential to be affected by th	е		
					same deficient practice will b	е		
	Findings include:				identified and what corrective	е		
					action(s) will be taken			
		ons made upon entering the			No residents were affected by	the		
	1	2 at 9:03 a.m., the portable fire			alleged deficient practice.			
	_	d in the lobby of the facility			All residents, visitors and staff			
	· ·	walker and a well as a			have the potential to be affected	ed		
		sed on interview during a tour			by the alleged deficient practic	e.		
		:40 p.m. with the facility			What measures will be put in	to		
		outgoing Maintenance			place or what systemic			
		coming Maintenance Director			changes will be made to			
		e portable fire extinguisher was			ensure that the deficient			
		en asked if items were			practice does not occur			
		e area, the Administrator stated			Maintenance Director has bee			
	I -	supposed to be kept there and			educated on that all portable A	ABC		
	· ·	I the walked and the relocation			fire extinguishers are readily			
		a removing the obstructions.			accessible without any			
	1	s removed prior to my exiting of			obstruction.			
		n discussed at the exit			A maintenance audit tool will b			
		e facility Administrator, the			completed to ensure that porta			
	1	nce Director and the incoming			fire extinguishers are checked	and		
		tor at the exit conference held			maintained.			
	on 10/18/22 at 2:45	p.m.			How the corrective action(s)			
					will be monitored to ensure t	he		
	3.1-19(b)				deficient practice will not			
					recur, ie., what quality			
					assurance program will be p	ut		
					in place			
					· The POC QAPI Tool will			
					utilized by ED/designee weekl	-		
					4 weeks, monthly x 6 months,			
			1		quarterly thereafter for one ver	ar		

PRINTED: 11/15/2022

PARTMENT OF HEALTH AND HUMAN SERVICES						
NTERS FOR MEDICARE & MEDICA	AID SERVICES		OMB NO. 0938-039			
STATEMENT OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY			
AND PLAN OF CORRECTION	IDENTIFICATION NUMBER	A. BUILDING <u>01</u>	COMPLETED			

AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER 155292	A. BUILDING B. WING	01	COMPLETED 10/18/2022
	PROVIDER OR SUPPLIE	ER	2026	ET ADDRESS, CITY, STATE, ZIP COD EAST 54TH ST ANAPOLIS, IN 46220	
(X4) ID PREFIX TAG	(EACH DEFICIE	Y STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL OR LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY) With results reported to the Qu	DATE
				Assurance and Performance Improvement Committee over by the Executive Director If a threshold of 95% is n achieved, an action plan will b developed to ensure complian	oot ve
K 0521 SS=F Bldg. 01	comply with 9.2	on, and air conditioning shall and shall be installed in the manufacturer's 1, 9.2			
	interview; the faci dampers in the fac provided necessar four years in accor 9.2.1 requires heat conditioning (HV equipment shall be Standard for the Ir and Ventilating Sy Section 5.4.8.1 sta maintained in accor for Fire Doors and NFPA 80, 2010 E	eview, observation, and lity failed to ensure 7 of 7 fire ility were inspected and y maintenance at least every rdance with NFPA 90A. LSC ring, ventilating and air AC) ductwork and related e in accordance with NFPA 90A, astallation of Air-Conditioning yetems. NFPA 90A, 2012 Edition, tes fire dampers shall be ordance with NFPA 80, Standard I Other Opening Protectives. dition, Section 19.4.1 states each	K 0521	K521HVAC What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice All fire dampers were inspected July 29, 2022. How other residents having to potential to be affected by the same deficient practice will be identified and what corrective action(s) will be taken No residents were affected by	n ed on the le oe e
	damper shall be te installation. Section	sted and inspected 1 year after on 19.4.1.1 states the test and icy shall then be every 4 years		alleged deficient practice. All residents, visitors and staff have the potential to be affected.	

TRCV21 Facility ID: 000189 Page 7 of 10 FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: If continuation sheet

by the alleged deficient practice

What measures will be put into

Maintenance Director has been

place or what systemic

changes will be made to

ensure that the deficient

practice does not recur

except for hospitals where the frequency is every

6 years. If the damper is equipped with a fusible

link, the link shall be removed for testing to ensure

full closure and lock-in-place if so equipped. The

damper shall not be blocked from closure in any

documented, indicating the location of the fire

way. All inspections and testing shall be

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155292		(X2) MULTIPLE C A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 10/18/2022	
	PROVIDER OR SUPPLIER		2026 E	ADDRESS, CITY, STATE, ZIP COD EAST 54TH ST NAPOLIS, IN 46220	į.
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
	damper, date of instance deficiencies discove have a space to indideficiencies were controlled to the practice could affect visitors. Findings include: Based on record reversities / Smoke Damp 07/05/18 with the far Director, on 10/19/2 that this inspection reversity ago. When ast the inspection could readily located. The maintenance conduct throughout the facil outgoing Maintenance.	pection, name of inspector and pred. The documentation shall cate when and how the prected. This deficient all residents, staff, and the per Maintenance Record dated per Maintenance Record dated actility outgoing Maintenance 22 at 11:31 a.m., it was noted was completed more than four seed if a more recent copy of the provided, it could not be lack of a current four-year cited on the fire dampers ity was verified by the	TAG	educated on record keeping a on regulations of testing/inspecting fire dampers. A maintenance audit tool will be completed annually to ensure dampers are working properly inspected by certified company. How the corrective action(s) will be monitored to ensure to deficient practice will not recur, ie., what quality assurance program will be printo place The POC QAPI Tool will utilized by ED/designee weekled 4 weeks, monthly x 6 months, quarterly thereafter for one year with results reported to the Quantity Assurance and Performance Improvement Committee oversely the Executive Director If a threshold of 95% is not achieved, an action plan will be developed to ensure compliant.	nd s. se fire and y. he ut be y x and ar ality seen ot e
K 0781 SS=E Bldg. 01	prohibited in all he except, unless use employee areas w do not exceed 212 degrees Celsius). 18.7.8, 19.7.8 Based on record revinterview; the facility portable space heate facility. This deficies		K 0781	K781 Portable Space Heaters What corrective action(s) wil be accomplished for those residents found to have beer affected by the deficient	

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 11/15/2022 FORM APPROVED OMB NO. 0938-039

	NT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155292	(X2) MULTIPLE C A. BUILDING B. WING	onstruction 01	(X3) DATE COMPL 10/18/	ETED
	PROVIDER OR SUPPLIEI AN VILLAGE	₹	2026 E	ADDRESS, CITY, STATE, ZIP CO EAST 54TH ST NAPOLIS, IN 46220	DD	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORR (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE AF DEFICIENCY)	ECTION DULD BE PROPRIATE	(X5) COMPLETION DATE
	Findings include: Based on observating facility on 10/18/22 heater was in use by Manufacturer's doe portable space heat temperature achieved interview at the beg facility at 12:40 p.r. space heater had be longer in use. When asked about a policing heaters, she advised one. Later it was defacility Administration the use of portable that she was sure th			practice The space heater in the was immediately remove How other residents has potential to be affected same deficient practice identified and what conditional action(s) will be taken. No residents were affected alleged deficient practice. All residents, visitors and have the potential to be by the alleged deficient. What measures will be place or what systemic changes will be made ensure that the deficient practice does not recurred. Maintenance Director heducated on facilities proportional to complete to ensure the space heater has been. How the corrective act will be monitored to endeficient practice will recur, ie., what quality assurance program with into place The POC QAPI To utilized by ED/designed 4 weeks, monthly x 6 mind place with results reported to Assurance and Perform Improvement Committee by the Executive Director.	aving the d by the e will be rective eted by the e. d staff affected practice e put into c to nt r as been ractice of s. ol will be e portable removed. If be put into the experiment of the ex	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

 $TRCV21 \hspace{0.5cm} \textit{Facility ID:} \hspace{0.5cm} 000189$

If continuation sheet

Page 9 of 10

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 11/15/2022 FORM APPROVED OMB NO. 0938-039

		_					
STATEMEN	IT OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	ILDING	01	COMPLETED	
		155292	B. WI	NG		10/18/2022	
NAME OF PROVIDER OR SUPPLIER AMERICAN VILLAGE STREET ADDRESS, CIT 2026 EAST 54TH 3 INDIANAPOLIS, IN							
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID PROVIDER'S PLAN OF CORRECTION			(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT	TE	COMPLETION
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
					If a threshold of 95% is not achieved, an action plan will be developed to ensure compliant.	е	

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: TRCV21 Facility ID: 000189 If continuation sheet Page 10 of 10