06/13/2024

DEPARTMENT OF HEALTH AND HUMAN SERVICES	
CENTERS FOR MEDICARE & MEDICAID SERVICES	

Patrick Ngene

	TATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION ND PLAN OF CORRECTION IDENTIFICATION NUMBER A. BUILDING 155741 B. WING			ONSTRUCTION	(X3) DATE COMPL 05/28/	ETED	
	PROVIDER OR SUPPLIER		•	2630 S	ADDRESS, CITY, STATE, ZIP COD KEYSTONE AVE JAPOLIS, IN 46203	•	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	ATE	(X5) COMPLETION DATE
Bldg	An Emergency Preparedness Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.73. Survey Date: 05/28/24 Facility Number: 004700 Provider Number: 155741 AIM Number: 100266630 At this Emergency Preparedness survey, Fairway Village was found in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73. The facility has 53 certified beds. At the time of the survey, the census was 46. Quality Review completed on 05/29/24 A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a). Survey Date: 05/28/24 Facility Number: 004700 Provider Number: 155741 AIM Number: 100266630 At this Life Safety Code survey, Fairway Village was found not in compliance with Requirements		E 00	000			
K 0000 Bldg. 01			K 0		Please accept this as our hor plan pf correction for the deficiencies cited. We are respectfully requesting a desk review for this plan of correct	<	(X6) DATE

Any defiency statement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: UGD621 Facility ID: 004700 If continuation sheet Page 1 of 17

HFA

PRINTED: 06/18/2024 FORM APPROVED OMB NO. 0938-039

	AND PLAN OF CORRECTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155741		l í	UILDING	01	COMPL 05/28/	ETED
	PROVIDER OR SUPPLIER Y VILLAGE			2630 S	DDRESS, CITY, STATE, ZIP COD KEYSTONE AVE APOLIS, IN 46203		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	(X5) COMPLETION DATE
K 0321	Subpart 483.90(a), I 2012 Edition of the Association (NFPA' Chapter 19, Existing 410 IAC 16.2. This one story facility determined to be of fully sprinklered. T system with smoke corridor and in all a facility has smoke d alarm system install rooms. The facility census of 46 at the t All areas where resi were sprinklered. A	dents have customary access All areas providing facility Elered except for one detached					
SS=D Bldg. 01	Hazardous Areas Hazardous Areas Hazardous areas barrier having 1-he (with 3/4 hour fire automatic fire extiraccordance with 8 approved automat option is used, the from other spaces partitions and doo Doors shall be sel automatic-closing nonrated or field-a	- Enclosure are protected by a fire our fire resistance rating rated doors) or an nguishing system in .7.1 or 19.3.5.9. When the ic fire extinguishing system e areas shall be separated by smoke resisting rs in accordance with 8.4.					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

UGD621 Facility ID: 004700

If continuation sheet

Page 2 of 17

	NT OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155741	(X2) MUI A. BUII B. WIN	LDING	nstruction 01	(X3) DATE COMPL 05/28 /	ETED
	PROVIDER OR SUPPLIEI Y VILLAGE			2630 S	DDRESS, CITY, STATE, ZIP COD KEYSTONE AVE APOLIS, IN 46203		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	Р.	ID REFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	(X5) COMPLETION DATE
	hazardous areas REMARKS. 19.3.2.1, 19.3.5.9 Area Separation a. Boiler and Fuel b. Laundries (larg c. Repair, Mainter d. Soiled Linen Regallons) e. Trash Collection (exceeding 64 gaf f. Combustible Ste (over 50 square for g. Laboratories (if Hazard - see K32 Based on observation failed to ensure 1 of as boiler and fuel first separated from other partitions and doors or automatic closin This deficient pract and visitors in the beautomatic failed to ensure 1 of as boiler and fuel first separated from other partitions and doors or automatic closin This deficient pract and visitors in the beautomatic field main failed to ensure 1 of the field main failed to ensure 1 of the field main failed to the door failed to the door frame	lons) prage Rooms/Spaces pet) classified as Severe 2) pon and interview, the facility f over 9 hazardous areas such red heater rooms were er spaces by smoke resistant s. Doors shall be self-closing g in accordance with 7.2.1.8. ice could affect over 2 staff	K 03.	21	What corrective actions will be accomplished for those reside found to have been affected be deficiency practice. The self-enclosure has been adjusted so that it can close properly on 6/12/24. How other residents having the potential to be affected by the same deficient practice will be identified and what corrective action will be taken All residents have the potential be affected by this deficiency practice. What measures will be put in place and what systemic chan will be made to ensure that the deficient practice does not	nts y the e al to	06/27/2024

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

UGD621 Facility ID: 004700

If continuation sheet Page 3 of 17

	IT OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155741	(X2) MULTIPLE C A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 05/28/2024	
	PROVIDER OR SUPPLIEF		2630 S	ADDRESS, CITY, STATE, ZIP COD S KEYSTONE AVE NAPOLIS, IN 46203		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE COL		
	natural gas fired wa interview at the tim Maintenance Direct hazardous area was spaces by smoke re These findings were Maintenance Direct	ter heaters. Based on e of the observations, the or agreed the aforementioned not separated from other sistant partitions and doors.		reoccur. The Maintenance Director or designee will audit all doors if facility that are equipped with self-enclosure mechanism for proper functioning by 6/27/24 Ed and or designee will educate the Maintenance Director by 6/27/24 on self-closing doors How the corrective actions we monitored to ensure the deficity practice will not recur, I e, who quality assurance program we put into place and by what do the systemic changes for each deficiency will be completed. To ensure compliance, the executive director or designer audit the entire facility for compliance of this deficiency. The self-enclosure on the downward will be inspected twice a week for eight weeks, then once week for eight weeks and monthly for two months. The results of the inspection will be reviewed by the idt team for compliance. If 100 not achieved, an action plat will be developed to ensure	n the n r I. The ill be cient nat rill be ate ch e will coors eek a ns % is n	
K 0351 SS=D Bldg. 01	NFPA 101 Sprinkler System Spinkler System - 2012 EXISTING Nursing homes, a			compliance.		

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X2) MULTIPLE CONSTRUCTION X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER A. BUILDING COMPLETED 01 B. WING 05/28/2024 155741 STREET ADDRESS, CITY, STATE, ZIP COD NAME OF PROVIDER OR SUPPLIER 2630 S KEYSTONE AVE INDIANAPOLIS, IN 46203 **FAIRWAY VILLAGE** (X4) ID SUMMARY STATEMENT OF DEFICIENCIE ID (X5) PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX COMPLETION TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG DEFICIENCY) DATE by construction type, are protected throughout by an approved automatic sprinkler system in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems. In Type I and II construction, alternative protection measures are permitted to be substituted for sprinkler protection in specific areas where state or local regulations prohibit sprinklers. In hospitals, sprinklers are not required in clothes closets of patient sleeping rooms where the area of the closet does not exceed 6 square feet and sprinkler coverage covers the closet footprint as required by NFPA 13, Standard for Installation of Sprinkler Systems. 19.3.5.1, 19.3.5.2, 19.3.5.3, 19.3.5.4, 19.3.5.5, 19.4.2, 19.3.5.10, 9.7, 9.7.1.1(1) What corrective actions will be 1. Based on record review and interview, the K 0351 06/27/2024 facility failed to ensure 2 of over 100 sprinklers accomplished for those residents were installed in accordance with NFPA 13. found to have been affected by the NFPA 13, Standard for the Installation of Sprinkler deficiency practice. Systems, 2010 Edition, Section 8.3.2.1 states The sidewall sprinklers heads in unless the requirements of 8.3.2.2, 8.3.2.3, 8.3.2.4 the kitchen have been inspected or 8.3.2.5 are met, ordinary- and and replacements will be intermediate-temperature sprinklers shall be used concluded by 6/27/24 to ensure throughout the buildings. This deficient practice regulatory compliance. could affect over four staff and visitors in the Additionally, boxes were kitchen. removed from the storage room to allow for the 18 inch Findings include: rule to be followed and improve the spray pattern of Based on review of the sprinkler system the sprinkler heads. inspection contractor's "Form for Inspection, How other residents having the Testing and Maintenance of Dry Pipe Fire potential to be affected by the Sprinkler Systems" documentation dated 04/15/24 same deficient practice will be with the Maintenance Director, Field Maintenance identified and what corrective Supervisor and Executive Director during record action will be taken review from 8:45 a.m. to 12:25 p.m. on 05/28/24, All residents, staff and visitors

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

UGD621

Facility ID: 004700

If continuation sheet

Page 5 of 17

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER		(X2) MULTIPLE CO	ONSTRUCTION 01	(X3) DATE SURVEY COMPLETED	
		155741	B. WING		05/28/2024
	PROVIDER OR SUPPLIEF		2630 S	ADDRESS, CITY, STATE, ZIP COD KEYSTONE AVE JAPOLIS, IN 46203	
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE	ID		(X5)
PREFIX TAG	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	
IAU	two sidewall sprink replaced. The "Def the 04/15/24 inspect vertical sidewall chanced to be changed standard response be interview at the time Executive Director from the contractor replace the two sprifacility's e-mail response. These findings were maintenance Direct Supervisor and Execonference. 3.1-19(b) 2. Based on observational failed to ensure the heads were not obstitus accordance with edition, Section 8.5 located so as to mindischarge as defined 8.5.5.3 or additional ensure adequate consure adequate c	lers in the kitchen need to be iciency Summary" section of tion report stated "(2) 1/2" rome 155 * standard response to 1/2" vertical sidewall 200* y Kitchen hood". Based on e of record review, the provided an e-mail proposal dated 05/28/24 at 12:05 p.m. to nkler heads along with the ponse to the contractor at 12:09 asap".	IAU	have the potential to be affected by this deficiency. All sprinkle heads will be audited and any needed changes made. What measures will be put in place and what systemic chan will be made to ensure that the deficient practice does not reoccur. The maintenance directed designee will audit all the sprin heads and ensuring proper spip patterns are followed in the fact by 6/27/24. The Executive Director on propersprinkler heads and the 18 incrule by 6/27/24 To ensure compliance, the executive director or designee audit the entire facility for compliance of this deficiency. The sprinkler system installation and the 18 inch clearance will be inspected twice a week for eight weeks then once a week for eight weeks then once a week for eight weeks and monthly for 2 months. The results of the inspections will be reviewed the idt team for compliance. It is not achieved, an actiplan will be developed to ensure compliance.	ges or or okler ray cility ector he er h will

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

UGD621

Facility ID: 004700

If continuation sheet

Page 6 of 17

PRINTED: 06/18/2024 FORM APPROVED OMB NO. 0938-039

	NT OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155741	JILDING	nstruction 01	(X3) DATE COMPL 05/28/	ETED
	PROVIDER OR SUPPLIER Y VILLAGE	2	2630 S	DDRESS, CITY, STATE, ZIP COD KEYSTONE AVE APOLIS, IN 46203		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	ATE	(X5) COMPLETION DATE
	Director, Field Mair Executive during a p.m. to 1:50 p.m. or storage on shelving basement was in a hinches below the up deflector in the roor sprinkler's spray par on top of metal file storage room inside in a horizontal plan upright pendant spromain which would obstrupattern. Based on it observations, the Maintenance Direct Maintenance Direct	-				
K 0353 SS=E Bldg. 01	Sprinkler System Automatic sprinkle are inspected, tes accordance with N Inspection, Testin Water-based Fire Records of system inspection and tes secure location ar	- Maintenance and Testing - Maintenance and Testing er and standpipe systems ted, and maintained in NFPA 25, Standard for the g, and Maintaining of Protection Systems. In design, maintenance, etting are maintained in a and readily available. system last checked system test				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

UGD621

Facility ID: 004700

If continuation sheet

Page 7 of 17

	ENT OF DEFICIENCIES N OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155741	(X2) MULTIPLE CO A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 05/28/2024		
	F PROVIDER OR SUPPLIE	R	STREET ADDRESS, CITY, STATE, ZIP COD 2630 S KEYSTONE AVE INDIANAPOLIS, IN 46203				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	(X5) COMPLETION DATE		
	c) Water system	supply source					
	Provide in REMA coverage for any automatic sprinkle 9.7.5, 9.7.7, 9.7.8 1. Based on record facility failed to en heads in the facility replaced in accorda Standard for the Immaintenance of Wasystems, 2011 Edit sprinklers shall not be free of corrosion physical damage; a correct orientation sidewall). Furthern that shows signs of replaced: (1) Leakage (2) Corrosion (3) Physical Damage (4) Loss of fluid in element (5) Loading (6) Painting unless manufacturer. In lieu of replacing dust, it is permitted compressed air or be equipment does no This deficient practi	RKS information on non-required or partial er system. 3, and NFPA 25 review and interview, the sure 5 of over 100 sprinkler which were painted were ance with NFPA 25. NFPA 25, spection, Testing, and ater-Based Fire Protection tion, Section 5.2.1.1.1 states a show signs of leakage; shall an, foreign materials, paint, and and shall be installed in the (e.g., up-right, pendent, or more, at 5.2.1.1.2 any sprinkler cany of the following shall be	K 0353	What corrective actions will be accomplished for those reside found to have been affected be deficiency practice. The 5 sprinklers in the south hall have been replaced as well as the 2 harsh environmental sprinklers in semi-recessed canopy. How other residents having the potential to be affected by the same deficient practice will be identified and what corrective action will be taken All residents, staff and visite have the potential to be affected by this deficiency. sprinkler heads in the facility will be inspected by the Maintenance Director or designee, and any needed changes made by 6/27/24. What measures will be put in place and what systemic charwill be made to ensure that the deficient practice does not reoccur. The maintenance director designee will audit all the	ents by the the the ce ce ce ce ce ce ce ce ce		
		f the sprinkler system		sprinkler heads in the facility by 6/27/24. The Ed and or	у		
i	I inspection contract	or's "Form for Inspection.	I	designee will educate the	I		

PRINTED: 06/18/2024 FORM APPROVED OMB NO. 0938-039

	NT OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155741	i '	UILDING	onstruction 01	(X3) DATE (COMPL 05/28/	ETED
	PROVIDER OR SUPPLIEI	3	STREET ADDRESS, CITY, STATE, ZIP COD 2630 S KEYSTONE AVE INDIANAPOLIS, IN 46203				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	(X5) COMPLETION DATE
	Sprinkler Systems" with the Maintenan Supervisor and Exe review from 8:45 a five sprinklers insta painted and need to Summary" section report stated "(5) S	nance of Dry Pipe Fire documentation dated 04/15/24 ce Director, Field Maintenance ceutive Director during record .m. to 12:25 p.m. on 05/28/24, alled in the South Hall were be replaced. The "Deficiency of the 04/15/24 inspection idewall chrome 155 * standard			Maintenance Director on appropriate sprinkler heads 6/27/24. How the corrective actions wil monitored to ensure the defici practice will not recur, I e, what quality assurance program will put into place and by what dat	I be ent at I be	
	response to the que materials including the time of record r provided an e-mail dated 05/28/24 at 1 sprinkler heads alor	gly painted in South Hall" in stion "Free of foreign paint?". Based on interview at eview, the Executive Director proposal from the contractor 2:05 p.m. to replace the five ng with the facility's e-mail tractor at 12:09 p.m. to "Get it			the systemic changes for each deficiency will be completed. The sprinkler heads will be inspected twice a week for eight weeks, then once a week for eight weeks and monthly for 2 months. The results of inspections will be reviewed the idt team for compliance. 100% is not achieved, an act	ek the by If	
	Maintenance Direc	e reviewed with the tor, Field Maintenance ceutive Director during the exit			plan will be developed to ensure compliance.		
	facility failed to ma systems in accordar requires all sprinkle tested, and maintain 25, Standard for the Maintenance of Wa Systems. NFPA 25 states where sprink environments, inclu- and corrosive water either sprinklers sh- representative sprin	review and interview, the sintain automatic sprinkler nee with NFPA 25. LSC 9.7.5 er systems shall be inspected, ned in accordance with NFPA and Inspection, Testing, and ster-Based Fire Protection 5, 2011 Edition, Section 5.3.1.1.2 lers are subject to harsh ading corrosive atmospheres as supplies, on a 5-year basis, all be replaced, or skler samples shall be tested.					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

UGD621 Facility ID: 004700

If continuation sheet Page 9 of 17

PRINTED: 06/18/2024 FORM APPROVED OMB NO. 0938-039

	OF CORRECTION	IDENTIFICATION NUMBER 155741	A. BUILDING B. WING	01	COMPLETED 05/28/2024	
NAME OF I	PROVIDER OR SUPPLIEF			ADDRESS, CITY, STATE, ZIP COD S KEYSTONE AVE		
FAIRWA	Y VILLAGE			NAPOLIS, IN 46203		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE	
	or repair deficiencie found during the in required by this star shall be performed personnel or a quality. I requires recordinspections, tests, a components and shauthority having jurdeficient practice of visitors in the facility. Findings include: Based on review of inspection contractor Testing and Mainter Sprinkler Systems with the Maintenant Supervisor and Exercive from 8:45 at two harsh environm semi-recessed canon "Deficiency Summainspection report starts and and response pendants are dated in response to the quality harsh environments tested in the last 5 yield the following the standard response to the quality harsh environment tested in the last 5 yield the time of record reprovided an e-mail dated 05/28/24 at 15 harsh environment facility's e-mail response to "Get it done".	The sprinkler system or's "Form for Inspection, nance of Dry Pipe Fire documentation dated 04/15/24 ce Director, Field Maintenance cutive Director during record and to 12:25 p.m. on 05/28/24, nent sprinklers installed in a py need to be replaced. The ary" section of the 04/15/24 ated "(2) Chrome pendant 155 e semi-recessed canopy 2017 and need to be replaced" uestion "Sprinklers subject to a replaced or successfully years?". Based on interview at eview, the Executive Director proposal from the contractor 2:05 p.m. to replace the two sprinkler heads along with the ponse to the contractor at 12:09 e asap".				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

UGD621 Facility ID: 004700

If continuation sheet Page 10 of 17

PRINTED: 06/18/2024 FORM APPROVED OMB NO. 0938-039

	NT OF DEFICIENCIES OF CORRECTION	(XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155741	ľ	UILDING	NSTRUCTION 01	(X3) DATE COMPI 05/28	ETED
NAME OF I	PROVIDER OR SUPPLIER				DDRESS, CITY, STATE, ZIP COD KEYSTONE AVE		
FAIRWA	Y VILLAGE			INDIAN	APOLIS, IN 46203		
(X4) ID		IMMARY STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	`	ICY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPI DEFICIENCY)	RIATE	COMPLETION
TAG	 	R LSC IDENTIFYING INFORMATION	_	TAG	DEFICIENC!)		DATE
	conference.	cutive Director during the exit					
	conference.						
	3.1-19(b)						
K 0363	NFPA 101						
SS=F	Corridor - Doors						
Bldg. 01	Corridor - Doors						
		corridor openings in other					
	· ·	losures of vertical openings,					
		s areas resist the passage					
		made of 1 3/4 inch					
		wood or other material					
	1	ng fire for at least 20					
		fully sprinklered smoke e only required to resist the					
		e. Corridor doors and doors					
	to rooms containir						
		rials have positive latching					
		atches are prohibited by					
		hese requirements do not					
	_	spaces that do not contain					
	flammable or com	bustible material.					
	Clearance betwee	en bottom of door and floor					
		ceeding 1 inch. Powered					
		vith 7.2.1.9 are permissible					
		device capable of keeping					
		hen a force of 5 lbf is					
		no impediment to the					
	-	rs. Hold open devices that					
		door is pushed or pulled are					
		ed protective plates of					
	_	re permitted. Dutch doors 6 are permitted. Door					
	_	beled and made of steel or					
		compliance with 8.3,	1				
	unless the smoke	•					
		fire window assemblies are	1				
		n sprinklered compartments					
	· ·	ctions in area or fire					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

UGD621 Facility ID: 004700

If continuation sheet Page 11 of 17

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X2) MULTIPLE CONSTRUCTION X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER A. BUILDING COMPLETED 01 155741 B. WING 05/28/2024 STREET ADDRESS, CITY, STATE, ZIP COD NAME OF PROVIDER OR SUPPLIER 2630 S KEYSTONE AVE INDIANAPOLIS, IN 46203 **FAIRWAY VILLAGE** (X4) ID SUMMARY STATEMENT OF DEFICIENCIE ID (X5) PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX COMPLETION TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG DEFICIENCY) DATE resistance of glass or frames in window assemblies. 19.3.6.3, 42 CFR Parts 403, 418, 460, 482, 483. and 485 Show in REMARKS details of doors such as fire protection ratings, automatics closing devices, etc. Based on observation and interview, the facility K 0363 What corrective actions will be 06/27/2024 failed to ensure 3 of over 30 corridor doors would accomplished for those residents resist the passage of smoke. This deficient found to have been affected by the practice could affect all residents, staff and deficiency practice. visitors. Findings include: Corridor doors have been adjusted to reduce the gaps on Based on observations with the Maintenance door 101, 105, and above Dutch Director, Field Maintenance Supervisor and doors in kitchen. Executive during a tour of the facility from 12:25 How other residents having the p.m. to 1:50 p.m. on 05/28/24, a three quarter inch potential to be affected by the gap between the edge of the door and the door same deficient practice will be stop on the handle side of the door near the top of identified and what corrective the door was noted for the corridor door to Room action will be taken 101 and Room 105 when each door was in the closed and latched position. In addition, a one All residents have the potential inch gap was noted in between the edge of the to be affected by this top leaf in the Dutch door and the door stop on deficiency. All gaps have been the handle side of the door for the door to the corrected to meet regulatory kitchen from the main dining room when the door guidelines by 6/15/24. was in the fully closed and latched position. The corner of the door frame near the top leaf of the What measures will be put in door was separated which caused the gap when place and what systemic changes the door was closed. The main dining room was will be made to ensure that the open to the corridor. Based on interview at the deficient practice does not time of the observations, the Maintenance reoccur. Director agreed the gap in between the three The Maintenance Director or corridor doors and their respective door stops designee will audit all doors in would not resist the passage of smoke when fully the facility by 6/27/24. This will closed and latched. be followed by the Administrator and or designee

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

UGD621

Facility ID: 004700

If continuation sheet

Page 12 of 17

PRINTED: 06/18/2024 FORM APPROVED OMB NO. 0938-039

	STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155741		r í	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING			(X3) DATE SURVEY COMPLETED 05/28/2024	
	PROVIDER OR SUPPLIER		2	630 S	ADDRESS, CITY, STATE, ZIP COD KEYSTONE AVE APOLIS, IN 46203			
(X4) ID PREFIX TAG	REFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION These findings were reviewed with the Maintenance Director, Field Maintenance		PRI	D EFIX 'AG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY) educating the Maintenance	TE	(X5) COMPLETION DATE	
		cutive Director during the exit			Director on proper gaps on doors and door frames by 6/27/24 How the corrective actions will	be		
					monitored to ensure the deficience will not recur, I e, what quality assurance program will put into place and by what dat the systemic changes for each deficiency will be completed.	ent t be e		
					To ensure compliance, the executive director or designs will audit the entire facility for compliance of this deficiency. The space between the doors will be inspected twice a week for eight weeks, then once a week for eight weeks and monthly for two months. The results of the inspection will be reviewed by the idt team for compliance. If 100% not achieved, an action plan will be developed to ensure compliance.	r /. s sk sk		
K 0522 SS=F Bldg. 01	heating plant, is do combustible mate device, and has a and shut down eq	ng Device e, other than a central esigned and installed so rials cannot be ignited by safety feature to stop fuel uipment if there is ature or ignition failure. If						

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

UGD621 Facility ID: 004700

If continuation sheet Page 13 of 17

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION		ONSTRUCTION	(X3) DATE SURVEY	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER				COMPLETED	
155741		155741	B. WING			05/28/2024	
NAME OF PROVIDER OR SUPPLIER				STREET A	ADDRESS, CITY, STATE, ZIP COD	•	
					KEYSTONE AVE		
FAIRWAY VILLAGE				INDIAN	IAPOLIS, IN 46203		
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE			ID	PROVIDER'S PLAN OF CORRECTION	(X5)	
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL		PREFIX		(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	COMPLETION	
TAG	REGULATORY OR LSC IDENTIFYING INFORMATION		+	TAG	DET TELENCT)	DATE	
	* is chimney or vent connected.						
	* takes air for combustion from outside. * provides for a combustion system separate						
	from occupied are	•					
	19.5.2.2	ла антоортого.					
	Based on observation and interview, the facility		K 0	522	What corrective actions will be	9 06/27/2024	
		f 1 Electrical Rooms in the	11 0322		accomplished for those reside	00.27.202.	
	basement was provided with intake combustion				found to have been affected b		
	air from the outside for rooms containing fuel fired				deficiency practice.		
	equipment. This deficient practice could create an				The HVAC unit has been		
	^	th carbon monoxide which			inspected by the regional		
	could cause physical problems for all staff in the				director of maintenance and		
		n. This deficient practice could			has determined that an intak	(e	
	affect all residents, staff and visitors.				vent for outside will be		
					installed in the Hvac room by	у	
	Findings include:				6/27/24.		
					How other residents having th		
	Based on observations with the Maintenance				potential to be affected by the same deficient practice will be		
	Director, Field Maintenance Supervisor and Executive during a tour of the facility from 12:25				identified and what corrective		
	p.m. to 1:50 p.m. on 05/28/24, it could not be				action will be taken		
		atural gas fired furnace in the			All residents have the		
		the basement which contained			potential to be negatively		
		ire alarm control panel was			impacted by this deficient		
	continually provided with combustion air supply				practice.		
	taken directly from the outside. Based on				What measures will be put in		
	interview at the time of the observations, the				place and what systemic char	nges	
	Maintenance Director agreed it could not be				will be made to ensure that the	е	
	determined if the natural gas fired furnace in the				deficient practice does not		
	basement Electrical Room was continually				reoccur.		
	_	oustion air supply taken			A new air vent will		
	directly from the ou	itside.			be installed in the room to		
	T1 (* 1.	1 1 14 4			provide intake combustion a		
	These findings were reviewed with the				from outside into the area by	/	
	Maintenance Director, Field Maintenance Supervisor and Executive Director during the exit				6/27/24. This will provide		
	conference.	curve Director during the exit			ventilation into the electrical		
	conference.				room and provide circulation the electrical room and	1 III	
	3.1-19(b)				eliminate carbon monoxide		
					from the room.		

PRINTED: 06/18/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155741	(X2) MULTIP A. BUILDIN B. WING	LE CONSTRUCTION IG <u>01</u>	(X3) DATE SURVEY COMPLETED 05/28/2024			
NAME OF PROVIDER OR SUPPLIER FAIRWAY VILLAGE			263	STREET ADDRESS, CITY, STATE, ZIP COD 2630 S KEYSTONE AVE INDIANAPOLIS, IN 46203				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFI TAC	CROSS-REFERENCED TO THE APP	JLD BE ROPRIATE COMPLETION DATE			
				the Administrator and of designee to the Mainter Director on proper vent for gas fired appliances closed areas by 6/27/24 How the corrective action monitored to ensure the practice will not recur, I equality assurance prograput into place and by who the systemic changes for deficiency will be completed. To ensure compliance, executive director or dewill audit the entire faci compliance of this defice the air vents on the eleroom will be inspected week for eight weeks, the once a week for eight wand monthly for 2 monto the results of the inspective will be reviewed by the team for compliance. If not achieved, an action will be developed to encompliance.	or nance ilation in . ns will be deficient a, what m will be at date r each sted. the esignee lity for ciency. ctrical twice a nen eeks hs. ections idt 100% is plan			
K 0712 SS=C Bldg. 01	alarm signal and conditions. Fire d and unexpected t conditions, at leas	the transmission of a fire simulation of emergency fire rills are held at expected imes under varying st quarterly on each shift. ar with procedures and is						

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

 $UGD621 \quad \ \ \text{Facility ID:} \quad \ 004700$

If continuation sheet

Page 15 of 17

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION		ONSTRUCTION	(X3) DATE SURVEY	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER	A. BUILDING <u>01</u>			COMPLETED	
155741		B. WING			05/28	05/28/2024	
				STREET A	ADDRESS, CITY, STATE, ZIP COD		
NAME OF PROVIDER OR SUPPLIER					KEYSTONE AVE		
FAIRWAY VILLAGE					APOLIS, IN 46203		
							1
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE		ID		PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL			REFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	COMPLETION
TAG	REGULATORY OR LSC IDENTIFYING INFORMATION			TAG	DEFICIENCT		DATE
	aware that drills are part of established routine. Where drills are conducted between 9:00 PM and 6:00 AM, a coded announcement may be used instead of audible alarms. 19.7.1.4 through 19.7.1.7						
	Based on record review and interview, the facility failed to conduct quarterly fire drills at unexpected		K 071	2	What corrective actions will be	2	06/27/2024
			10/1	. 2	accomplished for those reside		00/2//2024
	times under varying conditions on the third shift				found to have been affected by the		
		This deficient practice could			deficiency practice.	,	
	affect all residents, staff and visitors.				A schedule has been		
	,				developed to ensure that fire	•	
	Findings include:				drills are done in line with		
					regulatory requirements.		
	Based on review of	Direct Supply TELS "Fire			How other residents having the	е	
	Drills" documentati	ion with the Maintenance			potential to be affected by the		
		intenance Supervisor and			same deficient practice will be		
		during record review from 8:45			identified and what corrective		
	a.m. to 12:25 p.m. on 05/28/24, twelve of twelve				action will be taken		
	third shift fire drills conducted within the most				All residents, Staff and visito	rs	
		h period on 06/29/23, 07/26/23,			have the potential to be	_	
		, 10/28/23, 11/27/23, 12/22/23,			affected by this deficiency ar		
		, 03/28/24, 04/15/24 and on			proper timeliness of fire drill	S	
		ducted at, respectively, 4:45 0 a.m., 5:15 a.m., 5:31 a.m., 5:32			will be established.		
					What measures will be put in place and what systemic chan	aoc	
	a.m., 5:20 a.m., 5:15 a.m., 5:24 a.m., 5:20 a.m., 5:23 a.m. and 4:58 a.m. Based on interview at the time				will be made to ensure that the		
	of record review, the Maintenance Director stated				deficient practice does not		
	the facility operates three shifts per day and				reoccur.		
		ntioned third shift fire drills			The Maintenance Director or		
	_	l at unexpected times under			designee will conduct fire dr		1
	varying conditions.	-			in the facility at different time		
					in the facility in accordance		
	These findings were reviewed with the				with developed schedule and	t	
	Maintenance Direct	tor, Field Maintenance			in regulatory compliance. Th		1
	Supervisor and Exe	ecutive Director during the exit			Ed and or designee will		
	conference.				educate the Maintenance		
					Director on timeliness of fire		
	3.1-19(b) and 3.1-51(c)				drills in accordance with		
		1		regulatory standards by 6/27	124	I	

PRINTED: 06/18/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155741	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 05/28/2024			
NAME OF PROVIDER OR SUPPLIER FAIRWAY VILLAGE				STREET ADDRESS, CITY, STATE, ZIP COD 2630 S KEYSTONE AVE INDIANAPOLIS, IN 46203				
(X4) ID PREFIX TAG	(EACH DEFICIE)	STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
					How the corrective actions will monitored to ensure the deficie practice will not recur, I e, wha quality assurance program will put into place and by what date the systemic changes for each deficiency will be completed. To ensure compliance, the executive director or designe will audit the fire drill times monthly for the facility. The results of the inspections will be reviewed by the idt team for compliance. If 100% is not achieved, an action plan will be developed to ensure compliance.	ent t be e		

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: UGD621 Facility ID: 004700 If continuation sheet Page 17 of 17