PRINTED: 09/12/2022 FORM APPROVED

CENTERS FOR MEDICARE & MEDICAID SERVICES					OMB NO	D. 0938-039
STATEME	TEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X2) MULTIPLE CONSTRUCTION  IDENTIFICATION NUMBER A. BUILDING  155523 B. WING		ONSTRUCTION	(X3) DATE SURVEY COMPLETED 08/22/2022		
	PROVIDER OR SUPPLIEI	M HEALTH CARE CENTER	5911 S	ADDRESS, CITY, STATE, ZIP COD TATE ROAD 46 TSVILLE, IN 47429		
(X4) ID PREFIX TAG E 0000	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT DEFICIENCY)	TE CC	(X5) OMPLETION DATE
Bldg	conducted by the Ir accordance with 42  Survey Date: 08/22  Facility Number: 0  Provider Number: 100  At this Emergency Bean Blossom Hea compliance with En Requirements for N Participating Provid 483.73  The facility has a chad a census of 46	2/22 000558 155523	E 0000	The facility respectfully requests paper compliance for this citation  This plan of correction is the centers credible allegation of compliance.  Preparation and/or execution this plan of correction does not constitute admission or agreement by the provider of the truth of the facts alleged conclusions set forth in the statement of deficiencies. The plan of correction is prepared and/or executed solely becauthe provisions of federal and state law require it.	f n of not f or ne d	
Bldg. 01	Licensure Survey v	00558	K 0000	The facility respectfully requests paper compliance for this citation  This plan of correction is the centers credible allegation of compliance.  Preparation and/or execution this plan of correction does in constitute admission or	f n of	

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

At this Life Safety Code survey, Richland Bean

AIM Number: 100267550

TITLE

agreement by the provider of the truth of the facts alleged or

conclusions set forth in the

(X6) DATE

Any defiencystatement ending with an asterisk (\*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: V7K421 Facility ID: 000558 If continuation sheet Page 1 of 17

PRINTED: 09/12/2022 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155523		 JILDING	nstruction 01	(X3) DATE COMPL <b>08/22</b> /	ETED		
	PROVIDER OR SUPPLIER		E CENTER	5911 S	ADDRESS, CITY, STATE, ZIP COD FATE ROAD 46 FSVILLE, IN 47429		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEF CY MUST BE PRECE R LSC IDENTIFYING	DED BY FULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	(X5) COMPLETION DATE
	Blossom Health Car compliance with Re Medicare/Medicaid Life Safety from Fir National Fire Protect Life Safety Code (L Health Care Occupa This one story facility Type V (000) constructions sprinklered. The fawith hardwired smo and spaces open to the rooms were equipped alarms. The facility residents and had a	equirements for Pa, 42 CFR Subpart of the 2012 eduction Association (LSC), Chapter 19, I ancies and 410 IAC ity was determined ruction and was furcility has a fire all obtained with battery power has the capacity of the the capacity o	rticipation in 483.90(a), ition of the NFPA) 101, Existing C 16.2. I to be of ally arm system be corridors resident wered smoke for 79		statement of deficiencies. The plan of correction is prepare and/or executed solely becathe provisions of federal and state law require it.	d use	
	this survey.  All areas where resi were sprinklered an services were sprink buildings used for famaintenance.  Quality Review con	idents have custom d all areas providi klered, except thre acility storage and	nary access ng facility e detached				
K 0161 SS=E Bldg. 01		tion Type and He ion type and stor less otherwise p 19.1.6.7	eight ies meets ermitted by				
	1 I (442), I of stories	(332), II (222) non-sprinkle	Any number ered and				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

V7K421

Facility ID: 000558

If continuation sheet Page 2 of 17

CENTERS FOR	R MEDICARE & MEDIC	AID SERVICES			OMB NO. 0938-039
	NT OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE C	ſ	(X3) DATE SURVEY
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BUILDING	<u>01</u>	COMPLETED
		155523	B. WING		08/22/2022
NAME OF E	PROVIDER OR SUPPLIEF			ADDRESS, CITY, STATE, ZIP COD	
				STATE ROAD 46	
RICHLAN	RICHLAND BEAN BLOSSOM HEALTH CARE CENTER			TSVILLE, IN 47429	
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CORRECTION	(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT	COMPLETION
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATION	TAG	DEFICIENCY)	DATE
	2 II (111)	One story			
	non-sprinklered				
	Maximum 3 stories				
	sprinklered				
	3 II (000)	Not allowed			
	non-sprinklered	. tet alle trea			
	4 ' III (211)	Maximum 2 stories			
	sprinklered				
	5 IV (2HH)				
	6 V (111)				
	7 III (200)	Not allowed			
	non-sprinklered				
	8 V (000)	Maximum 1 story			
	sprinklered				
	•	s must be sprinklered			
		approved, supervised			
	automatic system 9.7. (See 19.3.5)	in accordance with section			
		iption, in REMARKS, of the			
		number of stories, including			
		on which patients are			
	•	of smoke or fire barriers and			
		Complete sketch or attach			
		the building as appropriate.			
		on and interview, the facility	K 0161	Immediate action taken	09/09/2022
		ne building construction type		The three foot by three-foot	037.037.2022
		deficient practice could affect		section of drywall opening was	
	all occupants within	-		corrected leaving no further	
	•	•		openings in the ceiling above the	ne
	Findings include:			drop ceiling in the corridor by the	<b>I</b>
				activities room.	
	Based on observation	ons on 08/22/22 during a tour		2. How the facility identified	
	of the facility at 1:1	4 p.m. with the Maintenance		other similar building constructi	ion
	Director, the ceiling	g above the drop ceiling in the		non-compliance.	
	corridor by the Acti	ivities Room had a three foot			
	by three foot section	n of drywall opening in the		A random audit was conducted	of

FORM CMS-2567(02-99) Previous Versions Obsolete

ceiling. The section of drywall was lying on top of

Event ID:

V7K421

Facility ID: 000558

If continuation sheet

the ceiling above the drop ceiling

Page 3 of 17

PRINTED: 09/12/2022 FORM APPROVED OMB NO. 0938-039

	NT OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155523	(X2) MULTIPLE C A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 08/22/2022
	PROVIDER OR SUPPLIER	M HEALTH CARE CENTER	5911 S	ADDRESS, CITY, STATE, ZIP COD STATE ROAD 46 'TSVILLE, IN 47429	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
	Based on interview Maintenance Direct construction was not did not know that the ceiling and would go This finding was re	posing the above attic space. at the time of observation, the for confirmed that the building at maintained and stated he here was an opening in the test it fixed.  viewed with the Administrator irector at the exit conference.		(8/25/22) to identify any further building/ construction concern. No new concerns identified duthis audit.  3. Measures put into place system changes  A monthly facility audit put into place on the ceiling structure between the drop ceiling and attic. The Maintenance Direct designee will randomly audit 3 sections of the ceiling 5 days week x 4 weeks, then 3 times week x 4 weeks, then 1 x a we for 4 weeks then monthly x 3 months to ensure substantial compliance.  4. How the corrective action will be monitored; The results of these audits will reviewed in the Quality Assura Meeting monthly for 6 months until 100% compliance is achi x 3 consecutive months. The committee will identify any tre or patterns and make recommendations to revise the plan as indicated.	ss. uring  /  the or or a a eeek  n I be ance or eved QA nds
K 0351 SS=E Bldg. 01	by construction ty throughout by an	Installation  nd hospitals where required			

09/12/2022 PRINTED: FORM APPROVED

CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-039 STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X2) MULTIPLE CONSTRUCTION X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER A. BUILDING COMPLETED 01 B. WING 08/22/2022 155523 STREET ADDRESS, CITY, STATE, ZIP COD NAME OF PROVIDER OR SUPPLIER 5911 STATE ROAD 46 RICHLAND BEAN BLOSSOM HEALTH CARE CENTER ELLETTSVILLE, IN 47429 (X4) ID SUMMARY STATEMENT OF DEFICIENCIE ID (X5) PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX PREFIX COMPLETION (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG DEFICIENCY) DATE 13, Standard for the Installation of Sprinkler Systems. In Type I and II construction, alternative protection measures are permitted to be substituted for sprinkler protection in specific areas where state or local regulations prohibit sprinklers. In hospitals, sprinklers are not required in clothes closets of patient sleeping rooms where the area of the closet does not exceed 6 square feet and sprinkler coverage covers the closet footprint as required by NFPA 13, Standard for Installation of Sprinkler Systems. 19.3.5.1, 19.3.5.2, 19.3.5.3, 19.3.5.4, 19.3.5.5, 19.4.2, 19.3.5.10, 9.7, 9.7.1.1(1) Based on observation and interview, the facility K 0351 Immediate action taken 09/09/2022 failed to maintain the ceiling construction in 1 of 1 The miss escutcheon identified Memory Care Dining Room in accordance with was replaced. NFPA 13, Standard for the Installation of Sprinkler How the facility plans to Systems. NFPA 13, 2010 edition, Section 6.2.7.1 establish compliance states plates, escutcheons, or other devices used to cover the annular space around a sprinkler shall A random audit throughout the be metallic, or shall be listed for use around a facility of sprinkler heads/ missing sprinkler. This deficient practice could affect staff escutcheon was completed with and at least 12 residents in the 400 Hall smoke corrective measures taken for compartment. identified missing escutcheon's. Findings include: Measures put into place/ system changes Based on observation with the Administrator and the Maintenance Director during a tour of the A monthly facility audit has been facility from 12:25 p.m. to 1:17 p.m. on 08/22/22, a put into place to ensure that all sprinkler in the dining room across the corridor annular space around the sprinkler from resident room 404 in the Memory Care wing is covered with an escutcheon had a missing escutcheon. Based on interview at cover. The Maintenance Director the time of observation, the Maintenance Director or designee will randomly audit 5 confirmed the escutcheon was missing, and would sprinklers throughout the facility, 5

FORM CMS-2567(02-99) Previous Versions Obsolete

have it replaced.

Event ID: V7K421

Facility ID: 000558

days a week x 4 weeks, then 3 times a week x 4 weeks, then 1 x

If continuation sheet

Page 5 of 17

PRINTED: 09/12/2022 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION (IDENTIFICATION NUMBER) 155523		(X2) MULTIPLE C A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 08/22/2022	
	PROVIDER OR SUPPLIEF	M HEALTH CARE CENTER	5911 S	ADDRESS, CITY, STATE, ZIP COD STATE ROAD 46 TSVILLE, IN 47429	
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OF	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL & LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	5.112
	_	viewed with the Administrator e Director at the exit		a week for 4 weeks then mon x 3 months to ensure substar compliance.	- I
	3.1-19(b)			4. How the corrective action will be monitored; The results of these audits will reviewed in the Quality Assur Meeting monthly for 6 months until 100% compliance is ach x 3 consecutive months. The committee will identify any tree or patterns and make recommendations to revise the plan as indicated.	II be ance s or ieved QA ends
K 0353 SS=C Bldg. 01	Sprinkler System Automatic sprinkle are inspected, tes accordance with N Inspection, Testin Water-based Fire Records of system inspection and tes secure location ar a) Date sprinkler b) Who provided c) Water system  Provide in REMAR coverage for any automatic sprinkler	supply source  RKS information on non-required or partial er system.			
	failed to document	riew and interview, the facility sprinkler system inspections in FPA 25. NFPA 25, Standard for	K 0353	Immediate action taken Review of the TELs data syst indicates that the weekly sprii	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

V7K421

Facility ID: 000558

If continuation sheet

Page 6 of 17

PRINTED: 09/12/2022 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155523		(X2) MULTIPLE C A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 08/22/2022	
RICHLAN	PROVIDER OR SUPPLIER	M HEALTH CARE CENTER	5911 8	TADDRESS, CITY, STATE, ZIP COD STATE ROAD 46 ITSVILLE, IN 47429	
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OF	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	DATE
	Water-Based Fire F Edition, Section 5.2 sprinkler systems slensure that normal being maintained. fire department contested, and maintain 13. Section 13.1.1.2 utilized for inspectivalves, valve compostates records shall tests, and maintenate components and shauthority having judeficient practice of and visitors.  Findings include:  Based on review of recent twelve monta.m. to 12:25 p.m. weekly dry sprinkled documentation for week period was not weeks of 10/18/21, 11/15/21 had no spread ocumentation. Base record review, the I has only been on the November 2021 and gauge and control week was not available.	the aforementioned weekly		system inspections have been completed and documented as of 11/21/22.  2. How the facility plans to establish compliance  A random audit of the TEL's documentation was complete ensure accuracy of the week sprinkler system/ gauge react inspection with no further ideconcerns.  3. Measures put into place system changes  A monthly facility audit has be put into place to ensure that weekly sprinkler system checare completed. The Administ or designee will randomly au weekly documentation 1 day week x 12 weeks, then mont 3 months to ensure substant compliance.  4. How the corrective activill be monitored; The results of these audits wereviewed in the Quality Assu Meeting monthly for 6 month until 100% compliance is act x 3 consecutive months. The committee will identify any troor patterns and make recommendations to revise to plan as indicated.	ed to ed to ely ling entified  e/  een the cks crator dit the a hly x ial  on fill be rance s or nieved e QA ends

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

V7K421

Facility ID: 000558

If continuation sheet

Page 7 of 17

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X2) MULTIPLE CONSTRUCTION X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER A. BUILDING COMPLETED 01 155523 B. WING 08/22/2022 STREET ADDRESS, CITY, STATE, ZIP COD NAME OF PROVIDER OR SUPPLIER 5911 STATE ROAD 46 RICHLAND BEAN BLOSSOM HEALTH CARE CENTER ELLETTSVILLE. IN 47429 (X4) ID SUMMARY STATEMENT OF DEFICIENCIE ID (X5) PROVIDER'S PLAN OF CORRECTION PROVIDERS PLAN OF CORRECTION
(EACH CORRECTIVE ACTION SHOULD BE
CROSS-REFERENCED TO THE APPROPRIATE
DEFICIENCY) PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX COMPLETION TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG DATE 3.1-19(b) K 0372 **NFPA 101** SS=E Subdivision of Building Spaces - Smoke Bldg. 01 Barrie Subdivision of Building Spaces - Smoke **Barrier Construction** 2012 EXISTING Smoke barriers shall be constructed to a 1/2-hour fire resistance rating per 8.5. Smoke barriers shall be permitted to terminate at an atrium wall. Smoke dampers are not required in duct penetrations in fully ducted HVAC systems where an approved sprinkler system is installed for smoke compartments adjacent to the smoke barrier. 19.3.7.3, 8.6.7.1(1) Describe any mechanical smoke control system in REMARKS. Based on observation and interview, the facility K 0372 Immediate action taken 09/09/2022 failed to ensure the penetrations caused by the The unsealed penetration of a passage of wire and/or conduit through 1 of 3 quarter inch gap around 2 wires in smoke barrier walls were protected to maintain the the smoke barrier near resident smoke resistance of each smoke barrier. LSC room 101 was sealed Section 19.3.7.5 requires smoke barriers to be How the facility plans to constructed in accordance with LSC Section 8.5 establish compliance and shall have a minimum 1/2 hour fire resistive rating. This deficient practice could affect staff A random audit of the buildings and at least 31 residents. smoker barrier system was completed with no further Findings include: findings. Based on observation with the Maintenance Measures put into place/ Director on 08/22/22 at 1:14 p.m., an unsealed system changes penetration of a quarter inch gap around 2 wires in the smoke barrier near resident room 101 was A monthly facility audit has been discovered. Based on interview at the time of put into place to ensure the observation, the Maintenance Director confirmed integrality of the smoke barrier

FORM CMS-2567(02-99) Previous Versions Obsolete

resident room 101.

the unsealed smoke barrier penetration by

Event ID:

V7K421

Facility ID: 000558

If continuation sheet

system is compliant. The

Maintenance director or designee

Page 8 of 17

PRINTED: 09/12/2022 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155523		r í	(X2) MULTIPLE CONSTRUCTION       (X3) DATE SURVEY         A. BUILDING       01       COMPLETED         B. WING       08/22/2022		
	PROVIDER OR SUPPLIER	M HEALTH CARE CENTER	591	EET ADDRESS, CITY, STATE, ZIP COD 1 STATE ROAD 46 LETTSVILLE, IN 47429	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	CROSS-REFERENCED TO THE APPROPR	(X5) E COMPLETION DATE
		viewed with the Administrator e Director at the exit		will randomly audit the 2 sec of the smoke barrier system facility 1 day a week x 12 we then monthly x 3 months to ensure substantial complian  4. How the corrective act will be monitored; The results of these audits vereviewed in the Quality Assumeting monthly for 6 month until 100% compliance is ac x 3 consecutive months. The committee will identify any troor patterns and make recommendations to revise a plan as indicated.	in the eeks, ce. ion vill be urance ns or hieved e QA rends
K 0511 SS=E Bldg. 01	complies with NFF Code, electrical with NFF Code. Existing inside service provided in 18.5.1.1, 19.5.1.1, Based on observation failed to ensure 1 of room, was provided interrupter (GFCI) is shock. NFPA 70, Normal Ground-Fault Circuit Personnel, states, ground-Fault Circuit Personnel shall be 210.8(A) through (Coircuit-interrupter shacessible location.	Electric gas or related gas piping PA 54, National Fuel Gas iring and equipment PA 70, National Electric tallations can continue in to hazard to life.	K 0511	1. Immediate action take. The receptacle next to the h washing sink in the dining rowas replaced. 2. How the facility plans testablish compliance.  A random audit of the building wet location receptacles was completed to ensure all receptacles and fixed equipments.	and com  to  ngs s ment

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

V7K421

Facility ID: 000558

If continuation sheet Page 9 of 17

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY			SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	UILDING	01	COMPL	ETED
		155523	B. W	ING	·	08/22/	/2022
		<u> </u>	<u> </u>	CTREET	ADDRESS CITY STATE ZID COD		
NAME OF I	PROVIDER OR SUPPLIE	R			ADDRESS, CITY, STATE, ZIP COD TATE ROAD 46		
	ND BEAN BLOSSO	M HEALTH CARE CENTER					
RICHLAND BEAN BLOSSOM HEALTH CARE CENTER			ELLET	TSVILLE, IN 47429			
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE			ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	ICY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	circuit interrupter p	rotection for personnel on			have working ground-fault circ	:uit	
	feeders.				interrupter protection. No furth	er	
	(B) Other Than Dw	velling Units. All 125-volt,			concerns identified during the		
	single-phase, 15- ar	nd 20-ampere receptacles			audit.		
	installed in the loca	ations specified in 210.8(B)(1)					
	through (8) shall ha	eve ground-fault			3. Measures put into place	/	
	circuit-interrupter p	protection for personnel.			system changes		
	(1) Bathrooms						
	(2) Kitchens				A monthly facility audit has be	en	
	(3) Rooftops				put into place to ensure the		
	(4) Outdoors				integrality of all wet location		
	Exception No. 1 to	(3) and (4): Receptacles that are			receptacles. The Maintenance	;	
	not readily accessib	ole and are supplied by a			director or designee will rando	mly	
	branch circuit dedic	cated to electric snow-melting,			audit 3 wet location receptacle	es	
	deicing, or pipeline	and vessel heating equipment			for proper GFCI protection 5 d	ays	
	shall be permitted t	to be installed in accordance			a week x 4 weeks, then 3 time	es a	
	with 426.28 or 427	.22, as applicable.			week x 4 weeks, then 1 x a we	ek	
	Exception No. 2 to	(4): In industrial establishments			for 4 weeks then monthly x 3		
	only, where the cor	nditions of maintenance and			months to ensure substantial		
	supervision ensure	that only qualified personnel			compliance.		
	are involved, an ass	sured equipment grounding					
	conductor program	as specified in 590.6(B)(2)					
	shall be permitted f	for only those receptacle			4. How the corrective action	n	
	outlets used to supp	ply equipment that would			will be monitored;		
	create a greater haz	ard if power is interrupted or			The results of these audits will	l be	
	having a design tha	t is not compatible with GFCI			reviewed in the Quality Assura	ance	
	protection.				Meeting monthly for 6 months	or	
	(5) Sinks - where re	eceptacles are installed within			until 100% compliance is achie	eved	
	1.8 m (6 ft.) of the	outside edge of the sink.			x 3 consecutive months. The 0	QΑ	
	Exception No. 1 to	(5): In industrial laboratories,			committee will identify any trei	nds	
	receptacles used to	supply equipment where			or patterns and make		
	_	vould introduce a greater			recommendations to revise the	е	
	_	mitted to be installed without			plan as indicated.		
	GFCI protection.						
	-	(5): For receptacles located in					
	patient bed location	ns of general care or critical					
	care areas of health	care facilities other than those					
	covered under						
	210.8(B)(1), GFCI	protection shall not be required.					

FORM CMS-2567(02-99) Previous Versions Obsolete

(6) Indoor wet locations

Event ID:

V7K421

Facility ID: 000558

If continuation sheet Page 10 of 17

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155523		X2) MULTIPLE CONSTRUCTION  A. BUILDING  B. WING  (X3) DATE SURVEY  COMPLETED  08/22/2022			LETED	
	PROVIDER OR SUPPLIER	M HEALTH CARE CENTER	5911 S	ADDRESS, CITY, STATE, ZIP COD STATE ROAD 46 TSVILLE, IN 47429	-	
(X4) ID PREFIX	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL	ID PREFIX	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOUL) CROSS-REFERENCED TO THE APPRO	D BE	(X5) COMPLETION
TAG	(7) Locker rooms w	LISC IDENTIFYING INFORMATION rith associated showering	TAG	DEFICIENCY)		DATE
	electrical diagnostic equipme	e bays, and similar areas where  nt, electrical hand tools.				
	receptacles and fixe	Vet Locations, requires all equipment within the area of				
		nave ground-fault circuit protection. Note: Moisture can				
	reduce the contact resistance of the body, and electrical insulation is more subject to failure. This					
		ould affect at least 20 residents				
	Findings include:					
	p.m. and 1:17 p.m. the Maintenance Di next to the hand wa was provided with a when tested with a break the circuit. Be observation, the Ma receptacle was not 0					
	_	viewed with the Administrator irector during the exit				
	3.1-19(b)					
K 0712 SS=F Bldg. 01	alarm signal and s conditions. Fire dr and unexpected ti	the transmission of a fire simulation of emergency fire ills are held at expected mes under varying t quarterly on each shift.				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

V7K421

Facility ID: 000558

If continuation sheet

Page 11 of 17

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X2) MULTIPLE CONSTRUCTION X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER A. BUILDING COMPLETED 01 B. WING 08/22/2022 155523 STREET ADDRESS, CITY, STATE, ZIP COD NAME OF PROVIDER OR SUPPLIER 5911 STATE ROAD 46 RICHLAND BEAN BLOSSOM HEALTH CARE CENTER ELLETTSVILLE, IN 47429 (X4) ID SUMMARY STATEMENT OF DEFICIENCIE ID (X5) PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX PREFIX COMPLETION TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG DEFICIENCY) DATE The staff is familiar with procedures and is aware that drills are part of established routine. Where drills are conducted between 9:00 PM and 6:00 AM, a coded announcement may be used instead of audible alarms. 19.7.1.4 through 19.7.1.7 1. Based on record review and interview, the K 0712 09/09/2022 Immediate action taken facility failed to conduct fire drills or documented A Fire Drill was completed on orientation training on each shift for 2 of 4 8/31/2022 during the 2nd shift. The quarters. LSC 19.7.1.6 states drills shall be fire monitoring company was conducted quarterly on each shift to familiarize notified of the fire drill. Staff facility personnel (nurses, interns, maintenance education with documentation was engineers, and administrative staff) with the completed and added to the life signals and emergency action required under safety binder. varied conditions. QSO-20-31 1135 temporary How the facility plans to waiver states in lieu of a physical fire drill, a establish compliance. documented orientation training program related to the current fire plan, which considers current The facility initiated a fire drill facility conditions, is acceptable. The training will activity log to ensure/ plan all instruct employees, including existing, new or future fire drill activity in a temporary employees, on their current duties, life comprehensive manner amongst safety procedures and the fire protection devices all shifts at varying times. in their assigned area. This deficient practice affects all occupants. Measures put into place/ system changes Findings include: A monthly facility audit has been Based on record review with the Administrator put into place to ensure that the and Maintenance Director on 08/22/22 between monthly fire drills are completed 9:45 a.m. and 12:25 p.m., the following quarters and conducted in a comprehensive and shifts were missing documentation of a manner. The Administrator or completed fire drill or documented orientation designee will randomly audit the training: monthly fire drills to ensure a) Second and Third shift of the third quarter completion and timing of drills 2021/2022. monthly x 6 months. c) Second shift of the Fourth Quarter of 2021. Based on interview with the Maintenance Director How the corrective action at the time of record review, he confirmed the will be monitored: aforementioned fire drills were not available for The results of these audits will be

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

V7K421

Facility ID: 000558

If continuation sheet

Page 12 of 17

PRINTED: 09/12/2022 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155523		(X2) MULTIPLE C A. BUILDING B. WING	<del></del>		
	PROVIDER OR SUPPLIER		5911 8	STATE ROAD 46	
RICHLAN	ND BEAN BLOSSO	M HEALTH CARE CENTER	I ELLE	FTSVILLE, IN 47429	
(X4) ID PREFIX	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	
TAG	review at the time of	the survey.	IAG	reviewed in the Quality Assu	rance
	and the Maintenance conference.  2. Based on record of facility failed to ensure the verification of the signal to the monitor conducted between last 4 quarters. LSC health care occupant transmission of a fin of emergency fire conference.	viewed with the Administrator e Director at the exit  review and interview, the sure 1 of 12 fire drills included ransmission of the fire alarm oring station in fire drills 9:00 p.m. and 6:00 a.m. for the C 19.7.1.4 requires fire drills in scies shall include the re alarm signal and simulation onditions. This deficient residents in the facility as well		Meeting monthly for 6 month until 100% compliance is act x 3 consecutive months. The committee will identify any tr or patterns and make recommendations to revise t plan as indicated.	nieved e QA ends
	Findings include:				
	with the Maintenand 10:02 a.m., the fire 1:01 a.m. did not in of the fire alarm sig time of record revies confirmed the afore include the verification.	riew of titled "Fire Drill Log" ce Director on 08/22/22 at drill conducted on 03/01/22 at clude documented transmission nal. Based on interview at the two, the Maintenance Director mentioned fire drill did not the conduction of the alarm transmission.			
	_	viewed with the Administrator e Director at the exit			
	3.1-19(b) 3.1-51(c)				
K 0918 SS=F Bldg. 01	_	s - Essential Electric Syste s - Essential Electric nce and Testing			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

V7K421

Facility ID: 000558

If continuation sheet

Page 13 of 17

PRINTED: 09/12/2022 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155523		(X2) MUI A. BUII B. WIN	LDING	nstruction 01	(X3) DATE S COMPL 08/22/	ETED	
	PROVIDER OR SUPPLIER	M HEALTH CARE CENTER		5911 ST	DDRESS, CITY, STATE, ZIP COD FATE ROAD 46 SVILLE, IN 47429		
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OR	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID REFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT DEFICIENCY)	Ē	(X5) COMPLETION DATE
	source and associon of supplying service 10-second criterion monthly test, a programmally confirm the safety and critical and testing of the switches are performed in 10-second critical and testing of the switches are performed in 20-40 day once every 36 moscheduled test under a complete simula automatic or manuloads, and are compersonnel. Mainte energy power sou accordance with noticicuit breakers are program for period components is est manufacturer requipitation of maintenance and readily available and circuits are mand separate from Minimizing the postemergency power consideration for reformed in 111, 700.10	ual transfer of all EES inducted by competent nance and testing of stored rces (Type 3 EES) are in IFPA 111. Main and feeder is inspected annually, and a dically exercising the rablished according to uirements. Written records ind testing are maintained ble. EES electrical panels arked, readily identifiable, in normal power circuits. sibility of damage of the source is a design new installations. (NFPA 99), NFPA 110, 0 (NFPA 70)					
	failed to maintain a monthly generator l months. Chapter 6. requires monthly te	complete written record of oad testing for 10 of the last 12 4.4.1.1.4(a) of 2012 NFPA 99 sting of the generator serving trical system to be in	K 09	18	1. Immediate action taken The generator was tested under load x 30 minutes with no complications. The monthly tes was documented with in the TB system to reflect the most curre	st EL's	09/09/2022

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

V7K421

Facility ID: 000558

If continuation sheet

Page 14 of 17

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155523		A. BUILDING <u>01</u> COMPLET		(X3) DATE SURVEY COMPLETED 08/22/2022	
	PROVIDER OR SUPPLIER	M HEALTH CARE CENTER	591 <sup>-</sup>	ET ADDRESS, CITY, STATE, ZIP COD 1 STATE ROAD 46 ETTSVILLE, IN 47429	
(X4) ID PREFIX TAG	(EACH DEFICIENT REGULATORY OF accordance with NI Emergency and State 8. NFPA 110 8.4.2 service to be exerci minimum of 30 min 99 requires a written performance, exercing generator to be regular for inspection by the	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION FPA 110, the Standard for Indby Powers Systems, Chapter requires diesel generator sets in sed at least once monthly, for a nutes. Chapter 6.4.4.2 of NFPA In record of inspection, ising period, and repairs for the ularly maintained and available the authority having deficient practice could affect all	ID PREFIX TAG	PROVIDERS PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPRO DEFICIENCY)  guidelines.  2. How the facility plans establish compliance.  Education was completed maintenance director accord the stated guidelines for the monthly generator testing.  3. Measures put into pla system changes  A monthly facility audit has	DBE COMPLETION DATE  s to  with the ording to be acce/
	Based on record rev Director on 08/22/2 documentation for since December 20 ran for 5 minutes us Additionally, there testing for Novemb Based on an intervi the Maintenance Di the requirement tha minimum of 30 min and confirmed no le November 2021 was This finding was re and the Maintenance conference.  3.1-19(b)	view with the Maintenance 22 from 12:15 p.m. to 1:17 p.m., monthly generator load testing 21 shows the generator only order load for each month.  was no monthly generator load er 2021 available for review.  ew at the time of record review, frector stated he was unware of the monthly load had to be a mutes and would start doing so; and testing documentation for as available for review.  Eviewed with the Administrator are Director at the exit		put into place to ensure the monthly load testing for the generator is completed an documented in a comprehe manner. The Administrator designee will randomly automothly generator testing ensure completion and account the generator load testimonthly x 6 months.  4. How the corrective a will be monitored; The results of these audits reviewed in the Quality As Meeting monthly for 6 more until 100% compliance is a x 3 consecutive months. To committee will identify any or patterns and make recommendations to revise plan as indicated.	at the e d densive r or dit the to curacy ng  ction s will be surance nths or achieved he QA trends
K 0920 SS=B Bldg. 01	Extens	ent - Power Cords and			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155523	(X2) MULTIPLE CONSTRUCTION  A. BUILDING  B. WING			(X3) DATE SURVEY COMPLETED 08/22/2022		
NAME OF PROVIDER OR SUPPLIER RICHLAND BEAN BLOSSOM HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP COD 5911 STATE ROAD 46 ELLETTSVILLE, IN 47429				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE  (EACH DEFICIENCY MUST BE PRECEDED BY FULL  REGULATORY OR LSC IDENTIFYING INFORMATION			ID PROVIDER'S PLAN OF CORRI PREFIX (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE AP DEFICIENCY)		ATE	(X5) COMPLETION DATE	
	Extension Cords Power strips in a pused for compone patient-care-relate (PCREE) assemble assembled by quathe conditions of 1 the patient care vinon-PCREE (e.g., except in long-terredo not use PCREI meet UL 1363A of for non-PCREE in (outside of vicinity non-patient care resorted with general cords are not used with general cords are not used wiring of a structu temporarily are recompletion of the installed and mee 10.2.3.6 (NFPA 99 (NFPA 70), 590.3). Based on observation failed to ensure 1 of flexible cords as a seguine selection of the inaccordance with the securior of the substitute for fixed deficient practice of and staff near the Bush of the securior of the substitute for fixed deficient practice of and staff near the Bush of the securior of	patient care vicinity are only ents of movable ed electrical equipment les that have been alified personnel and meet 10.2.3.6. Power strips in cinity may not be used for a personal electronics), m care resident rooms that E. Power strips for PCREE or UL 60601-1. Power strips the patient care rooms of the patient care precautions. Extension das a substitute for fixed or the patient of the patie	K 09		1. Immediate action taken The refrigerator and coffee m where immediately unplugged the power strip. 2. How the facility plans to establish compliance.  A random facility audit was completed to ensure the prop use of all power strips. No fur concerns identified at this time 3. Measures put into place system changes  A monthly facility audit has be	er ther e.	09/09/2022	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

V7K421

Facility ID: 000558

If continuation sheet

Page 16 of 17

PRINTED: 09/12/2022 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155523	(X2) MULTIPLE C A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY  COMPLETED  08/22/2022			
		M HEALTH CARE CENTER STATEMENT OF DEFICIENCIE	STREET ADDRESS, CITY, STATE, ZIP COD  5911 STATE ROAD 46  ELLETTSVILLE, IN 47429  ID PROVIDER'S PLAN OF CORRECTION (X5)					
PREFIX TAG	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION		PREFIX (EACH CORRECTIVE ACTION SHO		D BE COMPLETION			
	·		PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE		omly r use en 3 i 1 x thly itial  on  Il be ance s or ieved QA ends			

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: V7K421 Facility ID: 000558 If continuation sheet Page 17 of 17