						PRINT	ED: 01/09/2022	+
DEPARTMENT OF HEALTH	AND HUN	MAN SERVICES				FOR	M APPROVED	
CENTERS FOR MEDICARE	& MEDIC	AID SERVICES				OMI	B NO. 0938-039	
STATEMENT OF DEFICIE	ENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) MU	JLTIPLE CO	NSTRUCTION	(X3) DATE S	SURVEY	
AND PLAN OF CORRECTI	ION	IDENTIFICATION NUMBER	A. BU	ILDING	<u></u>	COMPLE	ETED	
		155332	B. WI	NG		12/11/2	2023	
NAME OF PROVIDER OR				281 S C	ADDRESS, CITY, STATE, ZIP COD COUNTY ROAD 200 EAST			
HERITAGE HOUSE	REHAB	ILITATION & HEALTH CARE CEN	TEI	CONNE	ERSVILLE, IN 47331			
(V4) ID SI	IMMARV	STATEMENT OF DEFICIENCIE		ID			(Y5)	

HEINITAG	SE 1100SE REHABILITATION & HEALTH CARE CEN	12.	ENSVILLE, IN 47551	
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CORRECTION	(X5)
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE	COMPLETION
TAG	REGULATORY OR LSC IDENTIFYING INFORMATION	TAG	CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	DATE
E 0000				
Bldg				
	An Emergency Preparedness Survey was	E 0000		
	conducted by the Indiana Department of Health in			
	accordance with 42 CFR 483.73.			
	G D : 10/11/02			
	Survey Date: 12/11/23			
	Facility Number: 000225			
	Provider Number: 155332			
	AIM Number: 100267670			
	ZEIN PURIOCI. 10020/0/0			
	At this Emergency Preparedness survey, Heritage			
	House Rehabilitation & Health Care Center was			
	found in compliance with Emergency			
	Preparedness Requirements for Medicare and			
	Medicaid Participating Providers and Suppliers, 42			
	CFR 483.73.			
	The facility has 98 certified beds. At the time of			
	the survey, the census was 88.			
	Quality Review completed on 12/13/23			
C 0000				
Bldg. 01				
	A Life Safety Code Recertification and State	K 0000	This provider respectfully requests	
	Licensure Survey was conducted by the Indiana		that this 2567 Plan of Correction	
	Department of Health in accordance with 42 CFR		be considered the Letter of	
	483.90(a).		Credible Allegation of Compliance	
			and requests a desk review in lieu	
	Survey Date: 12/11/23		of a post survey review on or after	
			12/28/2023.	
	Facility Number: 000225			
	Provider Number: 155332			
	AIM Number: 100267670			
	At this Life Safety Code survey, Heritage House	I	İ	Ī

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Stacey Ware **Executive Director** 12/21/2023

Any defiencystatement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclo days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Event ID: W01421 Facility ID: 000225 Page 1 of 6

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 01/09/2024 FORM APPROVED OMB NO. 0938-039

	NT OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155332	ľ	UILDING	nstruction 01	(X3) DATE COMPL 12/11	ETED		
NAME OF PROVIDER OR SUPPLIER HERITAGE HOUSE REHABILITATION & HEALTH CARE CENT			NTEI	STREET ADDRESS, CITY, STATE, ZIP COD 281 S COUNTY ROAD 200 EAST ONNERSVILLE, IN 47331					
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	ATE	(X5) COMPLETION DATE		
	not in compliance v Participation in Mesubpart 483.90(a), 2012 Edition of the Association (NFPA Chapter 19, Existing 410 IAC 16.2. This one-story facil Type V (111) const The facility has a find etection in the corridor.	ealth Care Center was found with Requirements for dicare/Medicaid, 42 CFR Life Safety from Fire and the National Fire Protection 1) 101, Life Safety Code (LSC), g Health Care Occupancies and lity was determined to be of ruction and fully sprinklered. The alarm system with smoke ridors and in all areas open to acility has smoke detectors are alarm system installed in all soms. The facility has a census of 88. Idents have customary access All areas providing facility klered. The facility has one nich was not sprinklered.							
K 0753 SS=E Bldg. 01	unless one of the o Flame retarda fire-retardant coat for product. o Decorations of than 100 kilowatts 289. o Decorations, paintings and other	orations orations shall be prohibited							

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

W01421 Facility ID: 000225

If continuation sheet Page 2 of 6

PRINTED: 01/09/2024 FORM APPROVED OMB NO. 0938-039

i '		(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	JILDING	01	COMPLETED	
		155332	B. WING		12/1		2023
				STREET	ADDRESS, CITY, STATE, ZIP COD	<u> </u>	
NAME OF PROVIDER OR SUPPLIER					COUNTY ROAD 200 EAST		
HERITAC	GE HOUSE REHAB	ILITATION & HEALTH CARE CEN	NTEI		ERSVILLE, IN 47331		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	ATE	COMPLETION
TAG		R LSC IDENTIFYING INFORMATION	-	TAG	DEFICIENCY)		DATE
		8.7.5.6(4) or 19.7.5.6(4).					
		ons in existing occupancies					
		I quantities that a hazard of					
		or spread is not present.					
	19.7.5.6		17.0	7.52	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	L -	10/00/0022
		on and interview, the facility f over 50 rooms were	K 0	133	What corrective action(s) will be accomplished for those reside		12/28/2023
		dance with 18.7.5.6. 18.7.5.6			accomplished for those reside		
		decorations shall be prohibited			found to have been affected b	y ine	
		•			deficient practice: No residents were identif	fied	
	following criteria is	ccupancy, unless one of the					
	_	retardant or are treated with			as being affected by the alleged deficient practice.	eu	
		dant coating that is listed and			The decorations were		
		ion to the material to which it is			immediately taken off the doo	ro	
	applied.	ion to the material to which it is			How other residents having		
		meet the requirements of			potential to be affected by th		
		d Methods of Fire Tests for			same deficient practice will I		
		of Textiles and Films.			identified and what corrective		
		exhibit a heat release rate not			action(s) will be taken:	C	
		when tested in accordance with			Over 5 residents have th	Δ	
	_	d Method of Fire Test for			potential to be affected by the		
		kages, using the 20 kW			alleged deficient practice.		
	ignition source.				The decorations were		
		s, such as photographs,			immediately taken off the doo	rs.	
		art, are attached directly to			Management staff were		
		nd non-fire-rated doors in			educated 12/20/23 on door ar	nd	
	accordance with the				wall decoration requirements.		
		non-fire-rated doors do not			All other rooms were		
		peration or any required			checked for door and wall		
	latching of the door	and do not exceed the area			decorations by the Maintenan	ce	
	limitations of 18.7.5	5.6(b), (c), or (d).			director.		
	(b) Decorations do	not exceed 20 percent of the			What measures will be put in	nto	
	wall, ceiling, and do	oor areas inside any room or			place or what systemic		
	_	ompartment that is not			changes will be made to		
		at by an approved automatic			ensure that the deficient		
		accordance with Section 9.7.			practice does not recur:		
		not exceed 30 percent of the			Maintenance		
	_	oor areas inside any room or			Director/designee will check d		
	_	ompartment that is protected			decorations prior to them bein	ıg	
	throughout by an ar	pproved supervised automatic	1		hung to ensure compliance wi	ith	

PRINTED: 01/09/2024 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION			(X3) DATE SURVEY			
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. B	UILDING	01	COMPLETED		
		155332	B. WING 12/11/2023					
		<u> </u>		STREET A	ADDRESS, CITY, STATE, ZIP COD			
NAME OF P	PROVIDER OR SUPPLIER	8			COUNTY ROAD 200 EAST			
HERITAC	GE HOUSE REHAB	ILITATION & HEALTH CARE CEI	NTEI		ERSVILLE, IN 47331			
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION	(X5)		
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	COMPLETION		
TAG	REGULATORY OR	R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)	DATE		
		accordance with Section 9.7.			fire safety regulations.			
	* /	not exceed 50 percent of the						
	_	oor areas inside patient			How the corrective action(s)			
		ing a capacity not exceeding			will be monitored to ensure t	he		
	-	noke compartment that is			deficient practice will not			
		at by an approved, supervised			recur, what quality assuranc			
	_	system in accordance with			program will be put into place	e:		
	Section 9.7.				Maintenance			
		ice could affect over five staff,			Director/designee to complete			
	residents and visitor	rs.			Flame Spread/Fire Retardant			
	F' 1' ' 1 1				Treatment Documentation we	ekly		
	Findings include:				x 4 weeks then monthly for 6	_		
	Dagad on observation	ons and interview during a			months to monitor the holiday			
		with the Maintenance Director			The results will be reviewed by CQI committee overseen by the	•		
		on 1:15 p.m. and 3:00 p.m., the			ED.	ie		
		the Social Services office and			ED.			
		sing Services Office was			By what date the systemic			
		with Christmas themed paper			changes will be completed:			
		on interview at the time of the			Completion Date: 12/28/2023			
		aintenance Director stated the			Completion Bate: 12/20/2020			
	· ·	g of the decorations was not						
		, the product was not treated						
		naterial and agreed the surface						
		which the decorations were						
	attached was substa	ntially more than 30%.						
	Th: - £ 1	1						
	This finding was ac							
		tor at the time of observation						
		t conference with the cor and Executive Director						
	present.	of and Executive Director						
	present.							
	3.1-19(b)							
K 0920	NFPA 101							
SS=E		ent - Power Cords and						
Bldg. 01	Extens							
		ent - Power Cords and						
	Extension Cords							

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

W01421

Facility ID: 000225

If continuation sheet

Page 4 of 6

PRINTED: 01/09/2024 FORM APPROVED OMB NO. 0938-039

CENTERS FO	R MEDICARE & MEDIC	CAID SERVICES				OM	B NO. 0938-039
STATEME	NT OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) N	IULTIPLE CO	ONSTRUCTION	X3) DATE	SURVEY
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. B	UILDING	<u>01 </u>	COMPL	ETED
		155332	B. W	'ING		12/11/	/2023
		<u> </u>		CTREET	ADDRESS, CITY, STATE, ZIP COD		
NAME OF	PROVIDER OR SUPPLIEF	R			COUNTY ROAD 200 EAST		
HERITA	GE HOUSE REHAP	BILITATION & HEALTH CARE C	NTFI		ERSVILLE, IN 47331		
	Т				1		1
(X4) ID		STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	`	NCY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATI	E	COMPLETION
TAG	1	R LSC IDENTIFYING INFORMATION	_	TAG	DEFICIENCY)		DATE
		patient care vicinity are only					
	used for compone						
	1 -	ed electrical equipment					
	, ,	les that have been					
	1	alified personnel and meet					
		10.2.3.6. Power strips in					
		icinity may not be used for					
	, -	, personal electronics),					
	except in long-teri	m care resident rooms that					
	do not use PCRE	E. Power strips for PCREE					
	meet UL 1363A or UL 60601-1. Power strips						
	for non-PCREE in the patient care rooms						
	(outside of vicinity	/) meet UL 1363. In					
	non-patient care r	ooms, power strips meet					
	other UL standard	ds. All power strips are					
	used with general	precautions. Extension					
	cords are not use	d as a substitute for fixed					
	wiring of a structu	re. Extension cords used					
	temporarily are re	moved immediately upon					
	completion of the	purpose for which it was					
	installed and mee	ts the conditions of 10.2.4.					
	10.2.3.6 (NFPA 9	9), 10.2.4 (NFPA 99), 400-8					
		(D) (NFPA 70), TIA 12-5					
		on and interview, the facility	K (920	What corrective action(s) will be	е	12/28/2023
		f 1 flexible cords were installed			accomplished for those residen		
		n a safe manor. NFPA 99,			found to have been affected by	the	
		ates adapters and extension			deficient practice:		
	_	requirements of 10.2.4.2.1			No residents were identified	∍d	
	_	shall be permitted. Section			as being affected by the alleged	d	
		e cabling shall comply with			deficient practice.		
		2.3.5.1 states cord strain relief			The power strip was		
	_	t the attachment of the power			immediately mounted and secu	ıred	
		ce so that mechanical stress,			to the wall in the maintenance		
	_	r bend, is not transmitted to			office.		
	internal connection	s. This deficient practice could	1		How other residents having the	1e	
	affect 2 staff in the	Maintenance Office.			potential to be affected by the)	
					same deficient practice will be	e	
	Findings include:				identified and what corrective	:	
					action(s) will be taken:		

FORM CMS-2567(02-99) Previous Versions Obsolete

Based on observations and interview during a

Event ID:

W01421

Facility ID: 000225

]

No residents have the

If continuation sheet Page 5 of 6

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 01/09/2024 FORM APPROVED OMB NO. 0938-039

tour of the facility with the Maintenance Director on 12/11/23 between 1:15 p.m. and 3:00 p.m., in the Maintenance office a power strip was being used to power electronic equipment and was not secured, dangling from the wall. This condition could put stress on the power cord causing damage to the power cord. Based on interview at the time of observations, the Maintenance Director stated he had recently installed/replaced the power strip and had not gotten around to attaching it to the wall. This finding was acknowledged by the Maintenance Director at the time of observation and again at the exit conference with the Maintenance Director and Executive Director TAG POERTIENTY TAG POERTIENTY POERTIENTY POERTIENTY POERTIENTY POERTIENTY POERTIENTY POENTIENTY POERTIENTY The power strip was immediately mounted and secured to the wall in the maintenance office. All other areas in facility were inspected for dangling power cords by Maintenance director. What measures will be put into place or what systemic changes will be made to ensure that the deficient practice does not recur: Maintenance Maintenance Maintenance POERTIENTY POERTIENTY POERTIENTY POERTIENTY The power strip was immediately mounted and secured to the wall in the maintenance office. All other areas in facility were inspected for dangling power cords by Maintenance director. What measures will be put into place or what systemic changes will be made to ensure that the deficient practice does not recur: Maintenance Maintenance	STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155332		(X2) MULTIPLE CONSTRUCTION (X3) DATE SURV A. BUILDING 01 COMPLETED B. WING 12/11/2023			ETED		
PREFIX TAG (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION tour of the facility with the Maintenance Director on 12/11/23 between 1:15 p.m. and 3:00 p.m., in the Maintenance office a power strip was being used to power electronic equipment and was not secured, dangling from the wall. This condition could put stress on the power cord causing damage to the power cord. Based on interview at the time of observations, the Maintenance Director at the time of observation and again at the exit conference with the Maintenance Director and Executive Director TAG PREFIX TAG CORRECTIVE ACTION SHOLLD BE CATION SHOLLD BE CATON SHOLLD BE				NTEI	281 S C	COUNTY ROAD 200 EAST		
on 12/11/23 between 1:15 p.m. and 3:00 p.m., in the Maintenance office a power strip was being used to power electronic equipment and was not secured, dangling from the wall. This condition could put stress on the power cord causing damage to the power cord. Based on interview at the time of observations, the Maintenance Director stated he had recently installed/replaced the power strip and had not gotten around to attaching it to the wall. This finding was acknowledged by the Maintenance Director at the time of observation and again at the exit conference with the Maintenance Director and Executive Director alleged deficient practice. The power strip was immediately mounted and secured to the wall in the maintenance office. All other areas in facility were inspected for dangling power cords by Maintenance director. What measures will be put into place or what systemic changes will be made to ensure that the deficient practice does not recur: Maintenance	PREFIX	(EACH DEFICIEN	NCY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
facility regularly to ensure power strips are properly mounted. How the corrective action(s) will be monitored to ensure the deficient practice will not recur, what quality assurance program will be put into place: Maintenance director/designee to complete the Power Strip safety audit daily x 1 week, weekly x 4 weeks, then monthly x 5 months. The results will be reviewed by the CQI committee overseen by the ED. By what date the systemic changes will be completed: Completion Date: 12/28/2023		tour of the facility on 12/11/23 between Maintenance office to power electronic secured, dangling for could put stress on damage to the power the time of observation Director stated he has the power strip and attaching it to the way. This finding was accompany to the way. This finding was accompany to the way. This finding was accompany to the way. The finding was accompany to the way. The finding was accompany to the way.	with the Maintenance Director en 1:15 p.m. and 3:00 p.m., in the e a power strip was being used e equipment and was not from the wall. This condition the power cord causing er cord. Based on interview at ations, the Maintenance had recently installed/replaced had not gotten around to wall. eknowledged by the tor at the time of observation it conference with the			alleged deficient practice. The power strip was immediately mounted and sect to the wall in the maintenance office. All other areas in facility were inspected for dangling pocords by Maintenance director. What measures will be put in place or what systemic changes will be made to ensure that the deficient practice does not recur: Maintenance Director/designee will inspect facility regularly to ensure powstrips are properly mounted. How the corrective action(s) will be monitored to ensure the deficient practice will not recur, what quality assurance program will be put into place. Maintenance director/designee to complete Power Strip safety audit daily sweek, weekly x 4 weeks, then monthly x 5 months. The resuluil be reviewed by the CQI committee overseen by the ED. By what date the systemic changes will be completed:	ower f. he e e the x 1	

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: W01421 Facility ID: 000225 If continuation sheet Page 6 of 6