CENTERS FOR MEDICARE & MEDICAID SERVICES					OMB NO. 0938-039	
	NT OF DEFICIENCIES N OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155358	(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 05/01/2023	
	PROVIDER OR SUPPLIE		3300 F	ADDRESS, CITY, STATE, ZIP COD POPLAR ST E HAUTE, IN 47803		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	(X5) COMPLETION DATE	
E 0000						
Bldg	conducted by the In accordance with 42 Survey Date: 05/0 Facility Number: 0 Provider Number: AIM Number: 100 At this Emergency Care of Deming Pawith Emergency Provider and Medicare and Medicare and Medicare and Suppliers, 42 Company of the Survey, the centre of the survey of the Su	1/23 000249 155358 0267640 Preparedness survey, Majestic ark was found not in compliance reparedness Requirements for icaid Participating Providers CFR 483.73 certified beds. At the time of	E 0000	By submitting the enclosed materials, we are not admitting truth or accuracy of any specifindings or allegations. We result the right to contest the finding allegations as part of any proceedings and submit these responses pursuant to our regulatory obligations. The frequest that the plan of corresponsible considered our allegation compliance effective 6-01-23 life safety survey completed 5-1-2023. We respectfully reap paper review and will proviped additional information requesting the safety survey.	eserve gs or se facility ection of s to the on equest de any	
E 0039 SS=C Bldg	441.184(d)(2), 484 483.73(d)(2), 484 485.68(d)(2), 485 486.360(d)(2), 49 EP Testing Requist (4)(2), \$4 \$460.84(d)(2), \$4 \$483.475(d)(2), \$4 \$483.475(d)(2), \$6 (2), \$491.12(d)(2) *[For ASCs at \$4 OPO, "Organization CMHCs at \$485.9	18.113(d)(2), §441.184(d)(2), 82.15(d)(2), §483.73(d)(2), 484.102(d)(2), §485.68(d)(2), 485.727(d)(2), §485.920(d)				

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Pamela Clevenger 05/25/2023

Any defiency statement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclodays following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: XNG621 Facility ID: 000249 If continuation sheet Page 1 of 35

PRINTED: 06/01/2023 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358		A. BUILDING COMPLETED B. WING 05/01/2023				ETED	
	ROVIDER OR SUPPLIER			3300 PG	NDDRESS, CITY, STATE, ZIP COD OPLAR ST HAUTE, IN 47803		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	.TE	(X5) COMPLETION DATE
	(2) Testing. The [fexercises to test the annually. The [fact following: (i) Participate in a community-based (A) When a community-based (B) If the [fact natural or man-materization of the ending exercises actual event. (ii) Conduct an additional exercises actual event. (iii) Conduct an additional exercises actual event. (ii) Conduct an additional exercises actual event. (ii) Of this section is include, but is not (A) A second full-secommunity-based functional exercises (B) A mock disaste (C) A tabletop exelled by a facilitator discussion using a clinically-relevant set of problem stal messages, or prefixed.	acility] must conduct he emergency plan ility] must do all of the full-scale exercise that is every 2 years; or nunity-based exercise is induct a facility-based every 2 years; or lity] experiences an actual ade emergency that requires imergency plan, the [facility] gaging in its next required or individual, facility-based e following the onset of the ditional exercise at least posite the year the full-scale cise under paragraph (d)(2) is conducted, that may limited to the following: scale exercise that is or individual, facility-based e; or er drill; or ercise or workshop that is and includes a group a narrated, emergency scenario, and a tements, directed pared questions designed			CROSS-REFERENCED TO THE APPROPRIA	NTE	
	maintain documer exercises, and em	nergency plan. acility's] response to and ntation of all drills, tabletop nergency events, and revise rgency plan, as needed.					
	*[For Hospices at	418.113(d):]					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet Page 2 of 35

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358		X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING (X3) DATE SURVEY COMPLETED 05/01/2023				ETED	
	PROVIDER OR SUPPLIER			3300 PC	ODDRESS, CITY, STATE, ZIP COD OPLAR ST HAUTE, IN 47803		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	ATE	(X5) COMPLETION DATE
	(2) Testing for ho the patient's home conduct exercises plan at least annuthe following: (i) Participate in a community based (A) When a commaccessible, condubased functional et (B) If the hospice man-made emerging of the emergency exempt from engascale community-lacility-based functional exercise of the emerging of the emerging of the emerging scale community-based functional exercise of this section is conclude, but is not (A) A second full-community-based functional exercise (B) A mock disassi (C) A tabletop exelled by a facilitator discussion using a clinically-relevant set of problem star messages, or prepto challenge an ereconsistent of the community of the community-based functional exercises (B) A mock disassi (C) A tabletop exelled by a facilitator discussion using a clinically-relevant set of problem star messages, or prepto challenge an ereconsistent of the exercises to test the per year. The hospital conduction of the problem star messages, or prepto challenge an ereconsistent of the performance of the performan	spices that provide care in a control of the contro					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621

Facility ID: 000249

If continuation sheet

Page 3 of 35

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358		(X2) MULTIPLE CONSTRUCTION (X3) DATE SUR A. BUILDING COMPLETE B. WING 05/01/202				ETED	
	PROVIDER OR SUPPLIEF			3300 PC	DDRESS, CITY, STATE, ZIP COD DPLAR ST HAUTE, IN 47803	•	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	IATE	(X5) COMPLETION DATE
	(A) When a commaccessible, conduct facility-based functional emergency exempt from engatull-scale community functional exercise emergency event. (ii) Conduct an activat may include, following: (A) A second full-community-based functional exercise functional exercise (B) A mock disas (C) A tabletop extendilitator that inclusing a narrated, emergency scena statements, direct questions designed emergency plan. (iii) Analyze the hamintain documer exercises, and em the hospice's emergency scena statements are the hospice's emergency plan. (iii) Analyze the hamintain documer exercises, and em the hospice's emergency scena statements are the hospice's emergency plan. (iii) Analyze the hamintain documer exercises, and em the hospice's emergency plan the hospice's emergency plan. (iii) Analyze the hamintain documer exercises, and em the hospice's emergency plan. (iii) Analyze the hamintain documer exercises, and em the hospice's emergency plan. (iii) Analyze the hamintain documer exercises and em the hospice's emergency plan. (iii) Analyze the hamintain documer exercises and em the hospice's emergency plan. (iii) Analyze the hamintain documer exercises and em the hospice's emergency plan. (iii) Analyze the hamintain documer exercises and em the hospice's emergency plan. (iii) Analyze the hamintain documer exercises and em the hospice's emergency plan. (iii) Analyze the hamintain documer exercises and em the hospice's emergency plan. (iii) Analyze the hamintain documer exercises and em the hospice's emergency plan. (iii) Analyze the hamintain documer exercises and em the hospice's emergency plan. (iii) Analyze the hamintain documer exercises and em the hospice's emergency plan. (iii) Analyze the hamintain documer exercises and em the hospice's emergency plan. (iii) Analyze the hamintain documer exercises and em the hospice's emergency plan.	unity-based exercise is not ct an annual individual tional exercise; or experiences a natural or ency that requires activation plan, the hospice is ging in its next required ity based or facility-based e following the onset of the ditional annual exercise but is not limited to the scale exercise that is or a facility based e; or ter drill; or ercise or workshop led by a udes a group discussion clinically-relevant rio, and a set of problem ed messages, or prepared ed to challenge an cospice's response to and entation of all drills, tabletop tergency events and revise regency plan, as needed. 41.184(d), Hospitals at at §485.625(d):] PRTF, Hospital, CAH] must to test the emergency exercise is not considered.					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet Page 4 of 35

PRINTED: 06/01/2023

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES					FORM APPROVED OMB NO. 0938-039		
	NT OF DEFICIENCIES I OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155358	(X2) MULTIPLE CO A. BUILDING B. WING	ONSTRUCTION	(X3) DATE SURVEY COMPLETED 05/01/2023		
NAME OF	PROVIDER OR SUPPLIER			ADDRESS, CITY, STATE, ZIP COD OPLAR ST			
MAJES	TIC CARE OF DEMI	NG PARK		HAUTE, IN 47803			
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	E	(X5) COMPLETION DATE	
	facility-based fund (B) If the [PRTF, Interpretation of the property of the pr	ctional exercise; or clospital, CAH] experiences or man-made emergency ation of the emergency as exempt from engaging in cull-scale community based ty-based functional exercise at of the emergency event. an [additional] annual cut may include, but is not wing: scale exercise that is or individual, a ctional exercise; or cock disaster drill; or or exercise or workshop that for and includes a group a narrated, emergency scenario, and a attements, directed pared questions designed mergency plan. the [facility's] response to cumentation of all drills, and emergency events cultity's] emergency plan, as 60.84(d):] CACE organization must at to test the emergency ally. The PACE and annual full-scale exercise					

FORM CMS-2567(02-99) Previous Versions Obsolete

facility-based functional exercise; or

(B) If the PACE experiences an actual natural or man-made emergency that requires

Event ID:

XNG621

Facility ID: 000249

If continuation sheet

Page 5 of 35

PRINTED: 06/01/2023 FORM APPROVED OMB NO. 0938-039

	STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING			(X3) DATE SURVEY COMPLETED 05/01/2023	
	PROVIDER OR SUPPLIE			3300 P	ADDRESS, CITY, STATE, ZIP COD OPLAR ST E HAUTE, IN 47803		
(X4) ID PREFIX		STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL		ID PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPRO	BE	(X5) COMPLETION
TAG	REGULATORY O	R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	activation of the	emergency plan, the PACE					
	is exempt from e	ngaging in its next required					
	full-scale community based or individual,						
	facility-based fun	ctional exercise following the					
	onset of the eme						
	(ii) Conduct	an additional exercise every					
	2 years opposite	the year the full-scale or					
	functional exercise under paragraph (d)(2)(i)						
	of this section is	conducted that may include,					
	but is not limited	-					
	(A) A second full-scale exercise that is community-based or individual, a facility based functional exercise; or(B) A mock disaster drill; or						
		kercise or workshop that is					
		r and includes a group					
	discussion, using						
		t emergency scenario, and a					
	1	atements, directed					
	1	epared questions designed					
	to challenge an e						
		PACE's response to and					
		entation of all drills, tabletop					
		mergency events and revise					
	the PACE's emer	rgency plan, as needed.					
		es at §483.73(d):]					
	_ ` ′ -	lity] must conduct exercises					
	_	ency plan at least twice per					
		nannounced staff drills using					
		rocedures. The [LTC facility,					
	ICF/IID] must do						
	(i) Participate in an annual full-scale exercise						
	that is community						
	1 ' '	munity-based exercise is not					
	accessible, conduct an annual individual, facility-based functional exercise.						
		cility] facility experiences an					
		man-made emergency that on of the emergency plan, the					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

 $XNG621 \qquad {\it Facility ID:} \quad 000249$

If continuation sheet

Page 6 of 35

STATEME	NT OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) M	ULTIPLE CC	ONSTRUCTION	(X3) DATE	SURVEY
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	JILDING		COMPL	ETED
		155358	B. W	ING	_	05/01/	2023
				STREET A	ADDRESS, CITY, STATE, ZIP COD	1	
NAME OF	PROVIDER OR SUPPLIEI	₹			OPLAR ST		
MAJEST	TIC CARE OF DEMI	NG PARK		TERRE	HAUTE, IN 47803		
(X4) ID		STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX		ICY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPR		COMPLETION
TAG	1	R LSC IDENTIFYING INFORMATION	-	TAG	DEFICIENCY)		DATE
	1	mpt from engaging its next					
	1	ale community-based or					
	_	based functional exercise					
	following the onset of the emergency event.						
	(ii) Conduct an additional annual exercise						
	1	but is not limited to the					
	following:	and avenue that:					
	(A) A second full-scale exercise that is						
	community-based or an individual, facility						
	based functional exercise; or						
	(B) A mock disaster drill; or						
	(C) A tabletop exercise or workshop that is						
	led by a facilitator includes a group discussion, using a narrated,						
	_						
		emergency scenario, and a					
	1	ntements, directed					
	to challenge an e	pared questions designed					
	_	LTC facility] facility's					
		naintain documentation of					
	1	exercises, and emergency					
	· ·	e the [LTC facility] facility's					
	emergency plan,						
	Cificing circy plant,	as needed.					
	*[For ICF/IIDs at §	\$483.475(d)1:					
		CF/IID must conduct					
		he emergency plan at least					
		ne ICF/IID must do the					
	following:	- ,					
	_	n annual full-scale exercise					
	that is community						
	1	nunity-based exercise is not					
		ict an annual individual,					
		ctional exercise; or.					
	1	experiences an actual					
	1 ' '	ade emergency that requires					
		mergency plan, the ICF/IID					
		ngaging in its next required					
		nity-based or individual,					
		ctional exercise following the					

PRINTED: 06/01/2023 FORM APPROVED

CENTERS FOR MEDICARE & MEDICAID SERVICES						ON	IB NO. 0938-039
STATEMEN	NT OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CO	NSTRUCTION	(X3) DATE	SURVEY
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER		A. BUILDING		COMPI	LETED
		155358		B. WING		05/01	/2023
	PROVIDER OR SUPPLIEF			3300 PG	ADDRESS, CITY, STATE, ZIP COI	D	
MAJEST	IC CARE OF DEMI	NG PARK		TERRE	HAUTE, IN 47803		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRE	CTION	(X5)
PREFIX	(EACH DEFICIEN	ICY MUST BE PRECEDED BY FU	LL	PREFIX	(EACH CORRECTIVE ACTION SHO) CROSS-REFERENCED TO THE APP	ULD BE	COMPLETION
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATI	ON	TAG	DEFICIENCY)		DATE
	onset of the emer	gency event.					
	(ii) Conduct an ad	ditional annual exercise					
	that may include, but is not limited to the						
	following:						
	(A) A second full-scale exercise that is						
	community-based or an individual,						
	I	ctional exercise; or					
	(B) A mock disast						
	1 ' '						
	, ,	ercise or workshop that is					
		and includes a group					
	discussion, using a narrated,						
	clinically-relevant emergency scenario, and a		a				
	set of problem statements, directed						
		pared questions designed					
	to challenge an er						
	(iii) Analyze the IC	CF/IID's response to and					
	maintain documer	ntation of all drills, tabletop					
	exercises, and em	nergency events, and revis	е				
	the ICF/IID's eme	rgency plan, as needed.					
	 *[For HHAs at §48	84 1021					
		e HHA must conduct					
		he emergency plan at					
		e HHA must do the					
	following:						
		full-scale exercise that is					
	community-based						
	` '	ommunity-based exercise					
		conduct an annual					
	individual, facility-	based functional exercise					
	every 2 years; or.						
	(B) If the HH	A experiences an actual					
	natural or man-ma	ade emergency that require	es				
	activation of the e	mergency plan, the HHA is	;				
	exempt from enga	aging in its next required					
	full-scale community-based or individual,						
		tional exercise following th	e l				
	onset of the emer						
		ditional exercise every 2					
		e year the full-scale	or				
	J yours, opposite th	o your the full-scale	J1				I

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet

Page 8 of 35

	NT OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155358	(X2) MULTIPLE CO A. BUILDING B. WING	ONSTRUCTION	COM	e survey pleted 1/2023
	PROVIDER OR SUPPLIEF		3300 P	ADDRESS, CITY, STATE, ZIP CO OPLAR ST E HAUTE, IN 47803	OD C	_
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORR (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE AF DEFICIENCY)	OULD BE	(X5) COMPLETION DATE
	of this section is of include, but is not (A) A second community-based facility-based function (B) A mock d (C) A tableton is led by a facilitated discussion, using clinically-relevant set of problem statemessages, or preto challenge an erection (iii) Analyze the Hemaintain documer exercises, and enthe HHA's emergen the HHA's emergen or workshop at lease exercise is led by group discussion, relevant emergen problem statemer prepared question emergency plantactual natural or requires activation OPO is exempt for required testing ending of the emergency (ii) Analyze the Ofmaintain documer exercises, and emergency group discussion, actual natural or required testing ending exercises, and emergency (iii) Analyze the Ofmaintain documer exercises, and emergency exercises, and emergency is not exercises.	limited to the following: full-scale exercise that is or an individual, ctional exercise; or isaster drill; or o exercise or workshop that for and includes a group a narrated, emergency scenario, and a itements, directed pared questions designed mergency plan. HA's response to and intation of all drills, tabletop mergency events, and revise ency plan, as needed. 86.360] e OPO must conduct the emergency plan. The following: er-based, tabletop exercise ast annually. A tabletop a facilitator and includes a using a narrated, clinically cy scenario, and a set of ints, directed messages, or ins designed to challenge an lif the OPO experiences an inan-made emergency plan, the om engaging in its next exercise following the onset				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet

Page 9 of 35

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION (IDENTIFICATION NUMBER) 155358		X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING (X3) DATE SURVEY COMPLETED 05/01/2023			
	PROVIDER OR SUPPLIEI		33	REET ADDRESS, CITY, STATE, ZIP COD 300 POPLAR ST ERRE HAUTE, IN 47803	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREI TA	FIX PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD F CROSS-REFERENCED TO THE APPROP	N (X5) SE COMPLETION DATE
	exercises to test to RNHCI must do to the RNHCI must do to the conduct a paper at least annually. It is group discussion narrated, clinically scenario, and a sed directed message designed to challed (ii) Analyze the RI maintain document exercises, and enthe RNHCI's eme Based on record regalled to conduct explan at least twice punannounced staff procedures. The LT following: (i) Participate in an is community-based a. When a community-based a. When a community or man-made emerging the emergency perform engaging its man-made emerging the emergency performed the onset of the activation of the conset of the activation of the conset of the activation of th	e RNHCI must conduct the emergency plan. The ne following: er-based, tabletop exercise A tabletop exercise is a led by a facilitator, using a r-relevant emergency et of problem statements, s, or prepared questions enge an emergency plan. NHCI's response to and ntation of all tabletop nergency events, and revise regency plan, as needed. riew and interview, the facility tercises to test the emergency per year, including drills using the emergency for facility must do the annual full-scale exercise that dt; or ity-based exercise is not an annual individual, ional exercise. The experiences an actual natural gency that requires activation lan, the LTC facility is exempt ext required full-scale in a per individual, facility-based I exercise for 1 year following tale event. itional exercise that may imited to the following: tale exercise that is tale an individual, facility-based	E 0039	It is the practice of this facilitest emergency plan at leas per year, including unannous staff drills using the emerge procedures. The corrective action taken those residents found to be affected by the deficient practice includes: There as identified residents How other residents that he the potential to be affected the same defective practice will be identified and what corrective action will be taken. All residents have the potential to be affected but a were identified. An elopement exercise was completed on 2.22.2023. The maintenance director was unable to located.	t twice inced incy In for e re no ave I by e e none ent

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet Page 10 of 35

	AND PLAN OF CORRECTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358		ONSTRUCTION	(X3) DATE SURVEY COMPLETED 05/01/2023	
	PROVIDER OR SUPPLIER FIC CARE OF DEMING PARK	3300 P	ADDRESS, CITY, STATE, ZIP COD OPLAR ST E HAUTE, IN 47803		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	(X5) COMPLETION DATE	
	b. A mock disaster drill; or c. A tabletop exercise or workshop that is led by a facilitator that includes a group discussion, using a narrated, clinically-relevant emergency scenario, and a set of problem statements, directed messages, or prepared questions designed to challenge an emergency plan. (iii) Analyze the LTC facility's response to and maintain documentation of all drills, tabletop exercises, and emergency events, and revise the LTC facility's emergency plan, as needed in accordance with 42 CFR 483.73(d)(2). This deficient practice could affect all occupants. Findings include: Based on records review with the Maintenance Director on 05/01/23 at 12:30 p.m., there was documentation for a tabletop exercise on December 5, 2022; but no documentation of an additional exercise of choice was available for review. Based on interview at the time of records review, the Maintenance Director stated no other emergency preparedness exercise documentation was available for review. This finding was reviewed with the Executive Director and Maintenance Director during the exit conference.		documentation which had be uploaded to the TELS system the time of survey. See attachment #1, #2, and #3. What measures will be put it place and what systemic changes will be made to ensure that the deficient practice does not recur: The maintenance director was on TELS system and how to retrinformation. All emergency exercises will continue to be completed in a timely manne. How the corrective action who be monitored to ensure the deficient practice will not recur, i.e., what qualessurance program will be into place: An audit will be conducted quarterly with the quality assurance committee to assurance the emergency prepared plan has conducted exercise test the emergency plan. Documentation of these drills/exercises will be review the quality assurance commit	into e the rieve r. vill e dility put ure dness s to	
E 0041 SS=F Bldg	482.15(e), 483.73(e), 485.625(e) Hospital CAH and LTC Emergency Power §482.15(e) Condition for Participation: (e) Emergency and standby power systems. The hospital must implement emergency and				

PRINTED: 06/01/2023 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358		ľ í	UILDING	nstruction 	COMPL 05/01/	ETED	
	PROVIDER OR SUPPLIER			3300 PC	DDRESS, CITY, STATE, ZIP COD DPLAR ST HAUTE, IN 47803		
(X4) ID PREFIX	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LIGOLOGY TENTENT OF THE OR ALTHONY A SOLUTION OF THE OR ALTHONY A SOL		ID PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	ATE	(X5) COMPLETION
TAG	standby power systemergency plan somethis section and in procedures plan somethis section and (ii) and (ii) of this section se	et forth in paragraphs (b)(1) ection.		TAG	DEFICIENCY		DATE
	The [LTC facility a implement emerge systems based on	d standby power systems.					
	Emergency generator must be the location requir Care Facilities Control Interim Amendment 12-4, TIA 12-5, and Code (NFPA 101) Amendments TIA	e located in accordance with ements found in the Health de (NFPA 99 and Tentative ints TIA 12-2, TIA 12-3, TIA d TIA 12-6), Life Safety and Tentative Interim 12-1, TIA 12-2, TIA 12-3, d NFPA 110, when a new when an existing					
	Emergency gener. The [hospital, CAI implement the em inspection, testing requirements foun	3.73(e)(2), §485.625(e)(2) ator inspection and testing. If and LTC facility] must ergency power system and [maintenance] If in the Health Care TPA 110, and Life Safety					
	Emergency generated and LTC facilities] source to power e	3.73(e)(3), §485.625(e)(3) ator fuel. [Hospitals, CAHs that maintain an onsite fuel mergency generators must w it will keep emergency					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621

Facility ID: 000249

If continuation sheet

Page 12 of 35

	OF CORRECTION	IDENTIFICATION NUMBER 155358	A. BUILDING B. WING	JNSTRUCTION 	COME	PLETED 1/2023
	ROVIDER OR SUPPLIER		3300 P	ADDRESS, CITY, STATE, ZIP (OPLAR ST E HAUTE, IN 47803	COD	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF COI (EACH CORRECTIVE ACTION S CROSS-REFERENCED TO THE DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE
	emergency, unless					
	§483.73(g), and C The standards incomplished this section are appreference by the D Federal Register in 552(a) and 1 CFR the material from the You may inspect a Information Resource and Recomplished the Marchives and	price Center, 7500 Security ore, MD or at the National ords Administration mation on the availability of RA, call 202-741-6030, or es.gov/federal_register/code ations/ibr_locations.html. this edition of the Code are ference, CMS will publish a ederal Register to nges. Protection Association, 1 C, et al., www.nfpa.org, et al., Care Facilities Code, ed August 11, 2011.				
	2014.		1			I

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet

Page 13 of 35

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358		(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY A. BUILDING COMPLETED B. WING 05/01/2023			
	PROVIDER OR SUPPLIER		3300 F	ADDRESS, CITY, STATE, ZIP COD POPLAR ST E HAUTE, IN 47803	
(X4) ID PREFIX	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	
TAG	(vii) NFPA 101, Lite edition, issued Automition (viii) TIA 12-1 to N 11, 2011. (ix) TIA 12-2 to NF 30, 2012. (x) TIA 12-3 to NF 22, 2013. (xi) TIA 12-4 to NF 22, 2013. (xii) NFPA 110, S Standby Power Sy including TIAs to a 2009. Based on record reversal factorial formulation of the Health 110, and Life Safety CFR 483.73(e)(2). The arrangement of the transfer of th	FPA 101, issued August FPA 101, issued October PA 101, issued October FPA 101, issued October FPA 101, issued October tandard for Emergency and ystems, 2010 edition, chapter 7, issued August 6, Fiew and interview, the facility the emergency power system and maintenance requirements Care Facilities Code, NFPA of Code in accordance with 42 This deficient practice could friew with the Maintenance 3 from 10:05 a.m. to 12:52 p.m., reckly generator testing prior available for review, the or confirmed there was no reckly generator testing prior	E 0041	It is the practice of this facility monitor the emergency gener on a weekly basis. The corrective action taken those residents found to be affected by the deficient practice. There are no identification residents. How other residents that ha the potential to be affected by the same defective practice will be identified and what corrective action will be taken: All residents have the potential to be affected but no were identified. What measures will be put into place and what systemic changes will be made to ensure that the deficient practice does not recur: The Maintenance director reeducation the deficient practice. The Emergency generators was to	for fied ve by one

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet

Page 14 of 35

PRINTED: 06/01/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358		(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY A. BUILDING COMPLETED B. WING 05/01/2023			ETED		
	PROVIDER OR SUPPLIE		•	3300 P	ADDRESS, CITY, STATE, ZIP COD OPLAR ST HAUTE, IN 47803		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE SICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	(X5) COMPLETION DATE
					on 5-14-2023 and will continue be tested weekly. How the corrective action we be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be posinto place: An audit will be conducted monthly with the quality assurance committee to assure that the Emergency Generator is being tested week and documentation is completed at the time of testing. Documentation of these tests be reviewed by the quality assurance committee. Execution is expected by the conduction of these tests be reviewed by the quality assurance committee.	ill ity ut o ekly ded	
K 0000 Bldg. 01							
Bidg. 01	Licensure Survey of Department of Hea 483.90(a). Survey Date: 05/0 Facility Number: 0 Provider Number: 100 At this Life Safety Deming Park was a Requirements for Facility Redicare/Medicaid Life Safety From F	200249 155358 267640 Code survey, Majestic Care of Found not in compliance with	K 00	000	By submitting the enclosed materials, we are not admitting truth or accuracy of any specifindings or allegations. We resthe right to contest the findings allegations as part of any proceedings and submit these responses pursuant to our regulatory obligations. The farequest that the plan of correct be considered our allegation of compliance effective 6-01-23 tife safety survey completed of 5-1-2023. We respectfully rectain additional information requested.	fic serve s or cility ction of to the n quest e any	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621

Facility ID: 000249

If continuation sheet

Page 15 of 35

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION (IDENTIFICATION NUMBER) 155358		(X2) MULTIPLE CO A. BUILDING B. WING	onstruction 01	(X3) DATE SURVEY COMPLETED 05/01/2023	
	ROVIDER OR SUPPLIER		3300 P	ADDRESS, CITY, STATE, ZIP COD POPLAR ST E HAUTE, IN 47803	
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OR	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	(X5) COMPLETION DATE
K 0291 SS=D Bldg. 01	This one story facilidetermined to be of fully sprinklered. The system with hard we resident sleeping roopen to the corridor 86 and had a census. All areas where residence were sprinklered. Asservices were sprinklered.	npleted on 05/04/23 ng ng g of at least 1-1/2-hour ed automatically in	K 0291	It is the responsibility of the facility to ensure battery powered emergency lights maintained. The corrective action taken those residents found to be affected by the deficient practice includes: There are identified residents. How other residents that has the potential to be affected the same defective practice will be identified and what corrective action will be take All residents have the potent be affected but none were	are for e no ave by cen.

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet Page 16 of 35

i ´		· /	(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER		JILDING	01	COMPLETED
		155358	B. W	ING		05/01/2023
NAME OF I	PROVIDER OR SUPPLIER	·	_	STREET A	ADDRESS, CITY, STATE, ZIP COD	•
					OPLAR ST	
MAJEST	IC CARE OF DEMII	NG PARK		TERRE	HAUTE, IN 47803	
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION	(X5)
PREFIX	`	CY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	COMPLETION
TAG		R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY	DATE
	Findings include:				identified. The batteries were	
	D 1 1	tal at more than			replaced in the emergency ba	-
		on with the Maintenance			operated light in the generator	
		3 during a tour of the facility			also the boiler room. Both ligh	
	_	1:46 p.m., the battery operated			were added to the monthly an	
		the generator failed to function test button was pushed three			annually battery-operated ligh check audits.	l
	_	, a battery operated light			What measures will be put in	nto
	-	r room failed to function when			place and what systemic	110
		utton was pushed three times.			changes will be made to	
	Based on interview	-			ensure that the deficient	
		laintenance Director confirmed			practice does not recur:	
	· ·	operated lights failed to		The ED and maintenance director		
	-	respective test button was			were reeducated on the deficie	
	pushed.			practice. The batteries were		
	1			replaced in the emergency battery		
	2. Based on record	review, observation and			operated light in the generator	-
		ty failed to ensure 3 of 3			also the boiler room. Both ligh	
		ts were tested monthly and			were added to the monthly an	
	annually for 90 min	utes over the past year to		annually battery-operated light		
	ensure the light wou	uld provide lighting during		check audits.		
	periods of power ou	itages and a written record of			How the corrective action wi	II
	visual inspections a	nd tests was provided.			be monitored to	
	Section 7.9.3.1.1 (1) requires functional testing			ensure the deficient practice	
		monthly, with a minimum of 3			will not recur, i.e., what quali	ity
		num of 5 weeks between tests,			assurance program will be p	ut
		seconds, (3) Functional			into place:	
	_	ducted annually for a minimum			The maintenance director and	d/or
		e emergency lighting system is			designee will check the	
		d (5) Written records of visual			battery-operated lights monthl	•
	_	s shall be kept by the owner			30 seconds and annually for 9	
	for inspection by th				minutes. The monthly audit w	/III
		eficient practice could affect			be checked by the ED for 6	
	staff.				months and brought to the	
	Findings include:				monthly QA meeting. Negative	re
	Findings include:				findings will be immediately remedied.	
	Based on record res	view on 05/01/23 from 10:05			remedied.	
a.m. to 12:32 p.m. with the Maintenance Director, there was no monthly or annual Battery Operated						

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA					(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. Bl	A. BUILDING 01 COMPLETED			
		155358	B. W	ING		05/01/2023	
	PROVIDER OR SUPPLIER			3300 P	ADDRESS, CITY, STATE, ZIP COD OPLAR ST E HAUTE, IN 47803		
(X4) ID	SUMMARY S	STATEMENT OF DEFICIENCIE		ID	NEGLIDERIC DI ANI OF CORRECTION	(X5)	
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA		
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)	DATE	
	Emergency Light To Based on interview the Maintenance Di battery operated em but documentation of annual test was not observations during Maintenance Direct to 1:46 p.m., the face emergency light on generator. Additional emergency lights were Based on interview Director, he stated rowas available for the These findings were	esting available for review. at the time of record review, rector stated the facility has a ergency light at the generator for the monthly test and available for review. Based on a tour of the facility with the or on 05/01/23 from 12:32 p.m. cility has a battery operated the exterior wall by the ally, two battery operated ere located in the boiler room. with the Maintenance no monthly or annual testing e two lights in the boiler room. e reviewed with the Executive enance Director at the exit			="" p=""> ="" a.<="" p=""> ="" p="">="" p=""> ="" p="">="" a.<="" p="">		
K 0321	NFPA 101						
SS=E	Hazardous Areas						
Bldg. 01	Hazardous Areas						
		are protected by a fire					
	•	our fire resistance rating rated doors) or an					
	`	rated doors) or an nguishing system in					
		3.7.1 or 19.3.5.9. When the					
		ic fire extinguishing system					
	• •	areas shall be separated					
	· ·	by smoke resisting					
		rs in accordance with 8.4.					
	Doors shall be sel						
		and permitted to have					
	_	ipplied protective plates that					
		inches from the bottom of					
	the door.						
		and zone locations of					

AND PLAN OF CORRECTION DENTIFICATION NUMBER 155358 NAME OF PROVIDER OR SUPPLIER MAJESTIC CARE OF DEMING PARK (X4) ID SUMMARY STATEMENT OF DEFICIENCIE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION PAZARdous areas that are deficient in REMARKS. 19.3.2.1, 19.3.5.9 A. BUILDING D1 STREET ADDRESS, CITY, STATE, ZIP COD 3300 POPLAR ST TERRE HAUTE, IN 47803 (X5) PROVIDERS PLAN OF CORRECTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) DATE A. BUILDING D1 STREET ADDRESS, CITY, STATE, ZIP COD 3300 POPLAR ST TERRE HAUTE, IN 47803 (X5) COMPLETION DATE
NAME OF PROVIDER OR SUPPLIER MAJESTIC CARE OF DEMING PARK (X4) ID PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION REMARKS. 19.3.2.1, 19.3.5.9 STREET ADDRESS, CITY, STATE, ZIP COD 3300 POPLAR ST TERRE HAUTE, IN 47803 (X5) PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) DATE ATAGORY STREET ADDRESS, CITY, STATE, ZIP COD 3300 POPLAR ST TERRE HAUTE, IN 47803 (X5) COMPLETION DATE
MAJESTIC CARE OF DEMING PARK (X4) ID SUMMARY STATEMENT OF DEFICIENCIE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION hazardous areas that are deficient in REMARKS. 19.3.2.1, 19.3.5.9
MAJESTIC CARE OF DEMING PARK (X4) ID SUMMARY STATEMENT OF DEFICIENCIE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION hazardous areas that are deficient in REMARKS. 19.3.2.1, 19.3.5.9
MAJESTIC CARE OF DEMING PARK (X4) ID SUMMARY STATEMENT OF DEFICIENCIE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION hazardous areas that are deficient in REMARKS. 19.3.2.1, 19.3.5.9 TERRE HAUTE, IN 47803 (X5) PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) DATE (X5) COMPLETION DATE
(X4) ID SUMMARY STATEMENT OF DEFICIENCIE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION hazardous areas that are deficient in REMARKS. 19.3.2.1, 19.3.5.9
PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION hazardous areas that are deficient in REMARKS. 19.3.2.1, 19.3.5.9
PREFIX TAG (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) DATE (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) DATE (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) DATE (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) DATE
TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG DEFICIENCY) hazardous areas that are deficient in REMARKS. 19.3.2.1, 19.3.5.9
REMARKS. 19.3.2.1, 19.3.5.9
19.3.2.1, 19.3.5.9
Area Automatic Sprinkler
Separation N/A
a. Boiler and Fuel-Fired Heater Rooms
b. Laundries (larger than 100 square feet)
c. Repair, Maintenance, and Paint Shops
d. Soiled Linen Rooms (exceeding 64
gallons)
e. Trash Collection Rooms
(exceeding 64 gallons)
f. Combustible Storage Rooms/Spaces
(over 50 square feet)
g. Laboratories (if classified as Severe
Hazard - see K322)
Based on observation and interview, the facility $K 0321$ It is the responsibility of the $05/31/2023$
failed to ensure the corridor door to 2 of over 8 facility to ensure that corridor
hazardous areas, such as a storage room of doors for hazardous areas,
combustible supplies over 50 square feet in size, such as storage rooms with
was provided with a self-closing device which combustible supplies are
would cause the door to automatically close and provied with a self-closing
latch into the door frame. This deficient practice device mechanism.
could affect as many as 14 residents and 3 staff. The corrective action taken for
those residents found to be
Findings include: affected by the deficient proction includes. There are no
Based on observations made during a tour of the practice includes: There are no identified residents
facility on 05/01/23 at 12:45 p.m. with the
Maintenance Director, the corridor door to How other residents that have
resident rooms #122 and #125 had been converted the potential to be affected by
to storage. These rooms contained assorted items to storage. These rooms contained assorted items the same defective practice
including: recliners, wooden furniture and will be identified and what
dressers, rolls of flooring, and other assorted corrective action will be taken.
combustible items creating hazardous areas. Both All residents have the potential to
rooms also measured well over the 50 square feet. All residents have the potential to be affected but none were
The lack of a self-closing device being installed identified. The supplies that were
on the corridor doors to each of these converted being stored in the two rooms
rooms was confirmed by the Maintenance identified have been cleaned out.

PRINTED: 06/01/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358		(X2) MULTIPLE CO A. BUILDING B. WING	onstruction <u>01</u>	(X3) DATE SURVEY COMPLETED 05/01/2023	
	ROVIDER OR SUPPLIER		3300 P	ADDRESS, CITY, STATE, ZIP COD OPLAR ST E HAUTE, IN 47803	
(X4) ID PREFIX TAG	SUMMARY SEARCH DEFICIEN REGULATORY OR Director at the time This finding was re-	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDERS PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY) What measures will be put in place and what systemic changes will be made to ensure that the deficient practice does not recur: The ED and maintenance directly were reeducated on the deficient practice. Full audit of all room the facility were observed and other doors met criteria for self-closing mechanisms to be added. How the corrective action with be monitored to ensure the deficient practice will not recur, i.e., what qual assurance program will be pinto place: The maintenance director and designee will tour bldg monthly 6 months to assure rooms that must need self-closing mechanisms are properly placed. The monthly audit will be checked by the E	DATE DATE DATE DATE DATE DATE
K 0345 SS=F Bldg. 01	in accordance with	•		for 6 months and brought to the monthly QA meeting. Negative findings will be immediately remedied.	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet

Page 20 of 35

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION (IDENTIFICATION NUMBER) 155358		(X2) MULTIPLE (A. BUILDING B. WING	O1	(X3) DATE SURVEY COMPLETED 05/01/2023	
MAJEST	PROVIDER OR SUPPLIEF		3300	FADDRESS, CITY, STATE, ZIP COD POPLAR ST E HAUTE, IN 47803	
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OF	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
TAG	National Electric C National Fire Alarn Records of system and testing are re 9.6.1.3, 9.6.1.5, N 1. Based on record facility failed to ens annual testing of all fire alarm system w National Fire Alarn Section 14.6.2.4 rec inspections, testing provided that include regarding tests and requested in Figure include a listing of type, address, locate (1) Date (2) Test frequency (3) Name of proper (4) Address (5) Name of person maintenance, tests, affiliation, business number (6) Name, address, approving agency ((7) Designation of to (8) Functional test of (9)*Functional test operations (10) Check of all sr (11) Loop resistance line-type heat detect (12) Functional test control units	Code, and NFPA 72, m and Signaling Code. n acceptance, maintenance adily available. IFPA 70, NFPA 72 review and interview, the sure the documentation for the I devices connected to 1 of 1 ras complete. NFPA 72, n Code, the 2010 Edition, at quires a record of all , and maintenance shall be des the following information all the applicable information 14.6.2.4. The record shall all devices tested with device ion and test results indicated: ty performing inspection, or combination thereof, and address, and telephone and representative of ies) the detector(s) tested of detectors of required sequence of moke detectors e for all fixed-temperature,	K 0345	It is the practice of this facility have an annual testing of all devices. The corrective action taken those residents found to be affected by the deficient practice includes: There are identified residents. How other residents that have the potential to be affected by the deficient the same defective practice will be identified and what corrective action will be take All residents have the potential be affected but none were identified. A Semi-Annual Firal Alarm Inspection was comple on 9.23.2022, 3.2.2023 and 3.6.2023. On 11.09.2021. a sensitivity test was completed Koorsen Fire and Security. Sea Attachments. Koorsen is also scheduled to come back 5-26-2023 to complete another sensitivity test. What measures will be put in place and what systemic changes will be made to ensure that the deficient	to 05/16/2023 for eno ve oy en. al to e ted l by ee
		s of ability of mass notification re alarm notification appliances		practice does not recur: The maintenance director was reeducated getting records from	

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY			URVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. B	A. BUILDING 01 COMPLET			TED
		155358	B. W	ING	05/01/2023		2023
		1		STREET A	ADDRESS, CITY, STATE, ZIP COD	<u> </u>	
NAME OF P	PROVIDER OR SUPPLIER	8			OPLAR ST		
MAJEST	IC CARE OF DEMII	NG PARK			HAUTE, IN 47803		
			1				
(X4) ID		STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA		(X5)
PREFIX	`	ICY MUST BE PRECEDED BY FULL		PREFIX	CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG		R LSC IDENTIFYING INFORMATION	-	TAG			DATE
	` '	gibility of mass notification			Koorsen Fire and Security as	I	
	system speakers	required by the equipment			as keeping documentation on	tne	
	manufacturer's publ				fire alarm system How the corrective action will	ha	
	-	required by the authority			monitored to	be	
	having jurisdiction	equired by the authority				,iII	
		ester and approved authority			ensure the deficient practice v not recur, i.e., what quality	VIII	
	representative	ester and approved authority			assurance program will be put	tinto	
	-	problems identified during test			place:	11110	
	(e.g., system owner	-			piace.		
	corrected/successfu				An audit will be conducted		
	abandoned in place	-			quarterly by the ED to ensure	the	
	- '	ice could affect all occupants			maintenance director is getting		
	in the facility.	coura arrow arr			inspection reports and maintain	-	
	, -				records of all inspections. Re	-	
	Findings include:				will be brought to the quarterly		
	S				meeting to discuss and review		
	Based on record rev	view on 05/01/23 at 11:20 a.m.			Administrator to monitor.		
	with the Maintenan	ce Director present, the most					
	recent fire alarm sys	stem inspection and testing					
	report was dated 03	/25/22. There was no					
	documentation of a	n annual fire alarm inspection					
	since 03/25/22 for r	review at the time of the survey.					
	Based on interview	with the Maintenance Director					
	at the time of record	d review, he confirmed that a					
		n report within the last 12					
	months was not ava	ilable for review at the time of					
	the survey.						
		review and interview, the					
	•	sure documentation was					
		nat all 89 smoke detectors in					
	~ ·	of the facility were sensitivity					
	_	st 24 months or prior. NFPA					
	· ·	larm Code, 2010 Edition,					
		states detector sensitivity shall					
		l year of installation, and every					
	•	after. After the second					
	-	test, if sensitivity tests					
indicate that the detector has remained within its							

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet Page 22 of 35

	IT OF DEFICIENCIES OF CORRECTION	XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155358	(X2) MULTIPLE CO A. BUILDING B. WING	onstruction 01	COM	TE SURVEY TPLETED 11/2023
NAME OF P	PROVIDER OR SUPPLIER			ADDRESS, CITY, STATE, ZIP	COD	
MAJEST	IC CARE OF DEMI	NG PARK		HAUTE, IN 47803		
(X4) ID PREFIX		STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CO	DRRECTION SHOULD BE	(X5)
TAG	`	CY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	PREFIX TAG	(EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	E APPROPRIATE	COMPLETION DATE
	listed and marked s	ensitivity range, the length of				
		ration tests shall be permitted				
		maximum of 5 years. If the				
		ed, records of detector caused				
		d subsequent trends of these				
		ntained. In zones or areas				
		rms show an increase over the				
		ration tests shall be performed. smoke detector is within its				
		ensitivity range, it shall be				
	tested using any of					
	(1) Calibrated test r					
	* *	calibrated sensitivity test				
	instrument.	canorated sensitivity test				
		quipment arranged for the				
	purpose.	11				
	* *	fire alarm control unit				
	* /	by the detector causes a signal				
	-	where its sensitivity is outside				
	its listed sensitivity					
	(5) Other calibrated	sensitivity method acceptable				
	to the authority hav	ing jurisdiction.				
	Detectors found to	have sensitivity outside the				
	listed and marked s	ensitivity range shall be				
	cleaned and recalib	rated or replaced.				
		vity cannot be tested or				
		spray device that administers				
		centration of aerosol into the				
		ient practice could affect all				
	residents, staff, and	visitors in the facility.				
	Findings include:					
	Based on record rev	view on 05/01/23 between 10:05				
		with the Maintenance Director,				
	-	ble to produce a smoke				
	-	report for all smoke detectors				1
		th period. Based on interview				
		d review, the Maintenance				
	Director confirmed	there was no smoke detector				
			1	Ī		I

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621

Facility ID: 000249

If continuation sheet

Page 23 of 35

PRINTED: 06/01/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358		(X2) MULTIPLE A. BUILDING B. WING	CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED 05/01/2023	
	PROVIDER OR SUPPLIE		3300	ET ADDRESS, CITY, STATE, ZIP POPLAR ST RE HAUTE, IN 47803	COD
(X4) ID PREFIX	(EACH DEFICIE	STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL	ID PREFIX	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO TH	SHOULD BE COMPLETION
TAG	 	R LSC IDENTIFYING INFORMATION documentation available for of the survey.	TAG	DEFICIENCY)	DATE
	facility failed to m in accordance with Code as required by 9.6. NFPA 72, See otherwise permitte shall be performed schedules in Table by the authority has tates that the followinspected semi-annal. Control unit troub. Remote annuncic. Initiating device fire alarm boxes, hetc.) d. Notification apple. Magnetic hold-control this deficient pracoccupants. Findings include: During record reviron documentation visual semi-annual fire review was dated to the time of record in accordance of the control	able signals ators s (e.g. duct detectors, manual eat detectors, smoke detectors, bliances open devices tice could affect all building ew with the Maintenance 23 from 10:05 a.m. to 12:32 p.m., could be provided regarding a fire alarm system inspection. e alarm inspection available for 03/25/22. Based on interview at review, the Maintenance at documentation of a visual ection of the fire alarm system			
		re reviewed with the Executive tenance Director at the exit			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621

Facility ID: 000249

If continuation sheet

Page 24 of 35

	STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155358		(X2) MULTIPLE C A. BUILDING B. WING	ONSTRUCTION 01	(X3) DATE SURVEY COMPLETED 05/01/2023
	PROVIDER OR SUPPLIER		3300 F	ADDRESS, CITY, STATE, ZIP COD POPLAR ST E HAUTE, IN 47803	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT DEFICIENCY)	(X5) COMPLETION DATE
K 0353 SS=F Bldg. 01	Sprinkler System Automatic sprinkler are inspected, tes accordance with Nappection, Testing Water-based Fire Records of system inspection and test secure location are a) Date sprinkler. b) Who provided b) Who provided c) Water system Provide in REMAR coverage for any reautomatic sprinkler successed on record revidence the sprink been inspected and 4.6.12.1 requires an required for complimaintained in according requirements. Spring maintained in according to the Inspection, The Water-Based Fire Parameters of the Inspections, tests, and components and sha authority having juring the second inspections, tests, and authority having juring testing the second inspections, tests, and authority having juring testing the second inspections, tests, and authority having juring testing the second inspections, tests, and authority having juring testing t	supply source RKS information on non-required or partial or system.	K 0353	It is the practice of this facility thave the sprinkler system tests on a quarterly basis. The corrective action taken for those residents found to be affected by the deficient practice includes: There are identified residents. How other residents that have the potential to be affected by the same defective practice will be identified and what corrective action will be taken. All residents have the	or no e

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet

Page 25 of 35

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358		(X2) MULTIPLE CO A. BUILDING B. WING	onstruction <u>01</u>	(X3) DATE SURVEY COMPLETED 05/01/2023
	PROVIDER OR SUPPLIER	3300 P	ADDRESS, CITY, STATE, ZIP COD OPLAR ST E HAUTE, IN 47803	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
	performed (e.g., inspection, test, or maintenance), the organization that performed the work, the results, and the date. NFPA 25, 5.2.5 requires that waterflow alarm devices shall be inspected quarterly to verify they are free of physical damage. NFPA 25, 5.3.3.1 requires the mechanical waterflow alarm devices including, but not limited to, water motor gongs, shall be tested quarterly. 5.3.3.2 requires vane-type and pressure switch-type waterflow alarm devices shall be tested semiannually. This deficient practice could affect all residents, staff, and visitors in the facility. Findings include: Based on review of the quarterly sprinkler system inspection records on 05/01/23 at 11:21 a.m. with the Maintenance Director present, there were no quarterly sprinkler system inspection report available for the first (January, February, March) and second (April, May, June) of 2023. The most recent sprinkler inspection report available to review was dated 12/09/22. During an interview at the time of record review, the Maintenance Director agreed there was no written documentation available to show the sprinkler system had been inspected the first and second quarter of 2023 at the time of the survey. This finding was reviewed with the Executive Director and Maintenance Director at the exit conference.		potential to be affected but not were identified. A quarterly sprinkler system inspection was completed on 3.2.2023. Koors Fire and Safety will return to facility in June to complete the second quarterly inspection, the was confirmed by the Maintenance Director. See Attachment What measures will be put in place and what systemic changes will be made to ensure that the deficient practice does not recur: The maintenance director was reeducated on getting records from Koorsen Fire and Securit well as keeping documentation the sprinkler system inspection. How the corrective action will monitored to ensure the deficient practice wont recur, i.e., what quality assurance program will be put place: An audit will be conducted quarterly by the ED to ensure maintenance director is getting inspection reports and maintain records of all inspections.	ne as en his to y as n on ns. be vill into
K 0355 SS=F Bldg. 01	NFPA 101 Portable Fire Extinguishers Portable Fire Extinguishers Portable fire extinguishers are selected,			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet

Page 26 of 35

ì ´		ſ ′	r í		(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER		A. BUILDING 01 COMPLE			
		155358	B. W	ING		05/01/	2023
NAME OF F	PROVIDER OR SUPPLIER				ADDRESS, CITY, STATE, ZIP COD	_	
					OPLAR ST		
MAJEST	IC CARE OF DEMII	NG PARK		TERRE	E HAUTE, IN 47803		
(X4) ID		STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	`	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	COMPLETION
TAG		LSC IDENTIFYING INFORMATION	-	TAG	DEFICIENC!)		DATE
	installed, inspected, and maintained in accordance with NFPA 10, Standard for						
	Portable Fire Extir						
	18.3.5.12, 19.3.5.	•					
		ation and interview, the facility	K U	355	It is the responsibility of the		05/10/2023
		f 20 portable fire extinguishers	1 1 1		facility to ensure portable fir	_	03/10/2023
		in accordance with NFPA 10,			extinguishers are not	~	
		le Fire Extinguishers, 2010			obstructed and are inspecte	d	
		.3.3 states portable fire			monthly.	-	
		not be obstructed or obscured			The corrective action taken to	or	
	_	ficient practice could affect			those residents found to be		
	staff in the garage.	•			affected by the deficient		
					practice includes: There are	no	
	Findings include:				identified residents		
		on during a tour of the facility			How other residents that have	/e	
		ce Director on 05/01/23 at 1:10			the potential to be affected by	у	
	1	ble fire extinguisher located in			the same defective practice		
	1	ked by an eight foot and six			will be identified and what		
		on interview at the time of			corrective action will be take		
		nintenance Director confirmed			All residents have the potentia	al to	
	I -	r was blocked and removed the			be affected but none were		
	ladders from in from	nt of the fire extinguisher.			identified. The ladder was mo		
	2 Dagad an aba	ation and intervious the facility			away from blocking the portat		
	failed to inspect 20	of 20 portable fire			fire extinguisher in the garage		
	_	facility each month. NFPA 10,			portable fire extinguishers have been inspected and signed off on		
	1	le Fire Extinguishers, Section			each of the 20 portable	ı OII	
		stinguishers shall be inspected			extinguishers.		
		by means of an electronic			What measures will be put in	nto	
	1	-			place and what systemic		
device / system at a minimum of 30-day intervals. Section 7.2.2 states periodic inspection or				changes will be made to			
	Section 7.2.2 states periodic inspection or electronic monitoring of fire extinguishers shall include a check of at least the following items:				ensure that the deficient		
					practice does not recur:		
	(1) Location in desi	_			The ED and maintenance dire	ector	
		to access or visibility			were reeducated on the defici		
		reading or indicator in the			practice. The ladder was mov		
	operable range or po	_			away from blocking the portal		
		ined by weighing or hefting for			fire extinguisher in the garage		
	self expelling-type				portable fire extinguishers have		

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358		(X2) MULTIPLE C A. BUILDING B. WING	onstruction <u>01</u>	(X3) DATE SURVEY COMPLETED 05/01/2023	
	PROVIDER OR SUPPLIER		3300 F	ADDRESS, CITY, STATE, ZIP COD POPLAR ST E HAUTE, IN 47803	
	SUMMARY: (EACH DEFICIEN REGULATORY OR cartridge-operated of (5) Condition of tire nozzle for wheeled (6) Indicator for nor using push to test pr Section 7.2.4.1 state inspections shall ke extinguishers inspections shall ke extinguishers inspection or conducted, the date performed and the it performing the insp Section 7.2.4.4 requirare conducted, reconshall be kept on a ta extinguisher, on an maintained on file, Section 7.2.4.5 requirated monstrate that at inspections have be practice could affect and visitors. Findings include: Based on an observ Director on 05/01/2 the monthly inspect	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION extinguishers, and pump tanks es, wheels, carriage, hose, and extinguishers nrechargeable extinguishers	3300 F	POPLAR ST	mill e lity but id/or ally for at s are y ED he
	2023. The annual potesting was conduct interview at the tim Maintenance Direct	monthly inspections for April ortable fire extinguishers and on 03/30/23. Based on e of observations, the for confirmed that monthly been documented on any of rs in the facility.			
	_	e reviewed with the Executive enance Director at the exit			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet

Page 28 of 35

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358		(X2) MULTIPLE CO A. BUILDING B. WING	ONSTRUCTION 01	(X3) DATE SURVEY COMPLETED 05/01/2023	
	ROVIDER OR SUPPLIER		3300 P	ADDRESS, CITY, STATE, ZIP COD OPLAR ST E HAUTE, IN 47803	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE
K 0712 SS=F Bldg. 01	NFPA 101 Fire Drills Fire Drills Fire drills include to alarm signal and so conditions. Fire drills around to an and unexpected to conditions, at least The staff is familia aware that drills aroutine. Where dried 9:00 PM and 6:00 announcement manualible alarms. 19.7.1.4 through 1.1. Based on record of facility failed to prodocumentation for 2 quarters. This deficit residents, as well as facility. Findings include: Based on review of on 05/01/23 between the Maintenance Dilacked fire drill doc shifts and quarters of period: a. First shift (days) February, March) of b. First shift (days) August, and Septements.	ay be used instead of 9.7.1.7 review and interview, the vide quarterly fire drill 2 of 3 shifts during 3 of 4 ient practice could affect all staff and visitors in the the facility's fire drill reports in 10:05 a.m. and 12:32 p.m. with rector present, the facility umentation for the following during the past 12 month of the first quarter (January, f 2023 of the third quarter (July, aber) of 2022 light) of the fourth quarter	K 0712	It is the responsibility of this facility to conduct quarterly fire drills on unexpected days and unexpected times under varying conditions. The corrective action taken those residents found to be affected by the deficient practice includes: There are identified residents. How other residents that have the potential to be affected by the same defective practice will identified and what corrective action will be taken. All residents have the potential to affected but none were identified. A fire drill was conducted on 5/11/23. What measures will put into place and what systemic changes will be marked.	for no no er ne be re o be ied.

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet

Page 29 of 35

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155358 NAME OF PROVIDER OR SUPPLIER		(X2) MULTIPLE CO A. BUILDING B. WING	ONSTRUCTION 01 ADDRESS, CITY, STATE, ZIP COD	(X3) DATE COMPL 05/01/	ETED	
	IC CARE OF DEMII			OPLAR ST EHAUTE, IN 47803		
	SUMMARY: (EACH DEFICIEN REGULATORY OR Based on interview the Maintenance Di fire drill reports dur shifts and quarters. 2. Based on record a facility failed to ense the verification of the signal to the monitor conducted between last 4 quarters. LSC health care occupant transmission of a fin of emergency fire of practice affects all r as staff and visitors. Findings include: Based on record rev with the Maintenant 10:42 a.m., the fire shift of the first qua documentation verification of the o alarm signal was no	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION at the time of record review, rector confirmed the lack of ing the previously mentioned review and interview, the sure 2 of 12 fire drills included ransmission of the fire alarm ring station in fire drills 6:00 a.m. and 9:00 p.m. for the 19.7.1.4 requires fire drills in cies shall include the re alarm signal and simulation onditions. This deficient residents in the facility as well riew of the facility Fire Drills ce Director on 05/01/23 at drill forms for second and third	3300 P	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAL DEFICIENCY) to ensure that the deficient practice does not recur: The maintenance director was inserviced that fire drills must held every month on staggerind dates and times throughout the month. Every quarter a drill must be conducted on each shift. Duthat occur on the night shift wisilent alarm must be reviewed alarm sounding the following of the transmission of a fire alarm si and simulation of emergency for conditions must occur and will documented on fire drill paperwork. How the correcting action will be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be pure into place: The maintenance director and/or his designee we conduct monthly fire drills that on different shifts and stagger throughout the month, quarter year. The times will also be staggered through a 24 hour period so they all dont' fall at the same time on the same shift.	he be ng e nust rills th a and day. ignal fire be ve ve vill are ed and he Fire	(X5) COMPLETION DATE
	_	e reviewed with the Executive enance Director during the exit		drill paperwork will be complet in its entirety. Documentation the transmission of signal and outcome of simulation. Drills to be brought to the quarterly QA meetings for review and signe attendees. Administrator to monitor.	of will	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621

Facility ID: 000249

If continuation sheet

Page 30 of 35

PRINTED: 06/01/2023 FORM APPROVED

CENTERS FOR	R MEDICARE & MEDIC	AID SERVICES			OMB NO. 0938-039	
STATEMEN	T OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) MULTIPLE C	ONSTRUCTION	(X3) DATE SURVEY	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BUILDING	01	COMPLETED	
		155358	B. WING		05/01/2023	
	PROVIDER OR SUPPLIER		3300 F	ADDRESS, CITY, STATE, ZIP COD POPLAR ST E HAUTE, IN 47803		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CORRECTION	(X5)	
PREFIX	(EACH DEFICIEN	ICY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE COMPLETION	
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATION	TAG	DEFICIENCY)	DATE	
K 0918	NFPA 101					
SS=F	Electrical Systems	s - Essential Electric Syste				
Bldg. 01	Electrical Systems	s - Essential Electric				
	System Maintena	nce and Testing				
	l -	other alternate power				
	I -	iated equipment is capable				
		ce within 10 seconds. If the				
		n is not met during the				
		ocess shall be provided to				
		his capability for the life				
	I -	branches. Maintenance				
	1	generator and transfer				
	I -	ormed in accordance with				
	NFPA 110.	mina in accordance man				
		e inspected weekly,				
		oad 30 minutes 12 times a				
		intervals, and exercised				
	1 .	onths for 4 continuous hours.				
	I	ider load conditions include				
		ated cold start and				
	•	ual transfer of all EES				
		nducted by competent				
	I	nance and testing of stored				
		rces (Type 3 EES) are in				
		NFPA 111. Main and feeder				
		e inspected annually, and a				
	' ' '	dically exercising the				
	· ·	tablished according to				
		uirements. Written records				
		nd testing are maintained				
		ble. EES electrical panels				
		arked, readily identifiable,				
	1	n normal power circuits.				
		ssibility of damage of the				
	emergency power	source is a design				
	consideration for r	new installations.				
	6.4.4, 6.5.4, 6.6.4	(NFPA 99), NFPA 110,				
	NFPA 111, 700.10	0 (NFPA 70)				
	1. Based on record	review and interview, the	K 0918	It is the practice of this facility	to 05/16/2023	

facility failed to maintain a complete written record

have a written record of monthly

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		X2) MULTIPLE CONSTRUCTION		ONSTRUCTION	(X3) DATE SURVEY		
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	A. BUILDING <u>01</u> COMPLETE			ETED
		155358	B. W	ING		05/01/	/2023
		<u> </u>		STREET A	ADDRESS, CITY, STATE, ZIP COD	1	
NAME OF P	PROVIDER OR SUPPLIEF	8			OPLAR ST		
MAJEST	IC CARE OF DEMI	NG PARK			HAUTE, IN 47803		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	ICY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG	REGULATORY OF	R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	of monthly generate	or load testing for 2 of the last			generator load testing.		
	12 months. Chapte	r 6.4.4.1.1.4(a) of 2012 NFPA 99					
	requires monthly te	sting of the generator serving			The corrective action taken f	or	
		trical system to be in			those residents found to be		
		FPA 110, the Standard for			affected by the deficient		
		ndby Powers Systems, Chapter			practice includes: There are	no	
		4 states spark-ignited (LP Gas)			identified residents.		
		be exercised at least once a					
		ilable EPSS load for 30 minutes			How other residents that have		
		emperature and the oil pressure			the potential to be affected b	У	
		apter 6.4.4.2 of NFPA 99			the same defective practice		
	requires a written re	-			will be identified and what		
	•	ising period, and repairs for the			corrective action will be		
	-	ılarly maintained and available			taken. All residents have the		
	for inspection by th				potential to be affected but no	ne	
	jurisdiction. This d	leficient practice could affect all			were identified.		
	occupants.						
					What measures will be put ir	ito	
	Findings include:				place and what systemic		
					changes will be made to		
		view with the Maintenance			ensure that the deficient		
		3 at 12:05 p.m., documentation			practice does not recur: The	;	
		tor load testing was provided,			maintenance director was re		
	_	ete. The monthly load test log		educated on weekly and monthly			
		load percentage column for the			maintenance on the generator.		
		sed on an interview at the time			Weekly and monthly maintena	nce	
		ne Maintenance Director			was completed on 5/14/2023		
		available EPSS load for the last				_	
		documented on the generator			How the corrective action will	be	
	monthly test log she	eet.			monitored to		
					ensure the deficient practice v	VIII	
		review and interview, the			not recur, i.e., what quality		
	-	sure a written record of weekly			assurance program will be put	into	
		generator was maintained for			place:		
		FPA 99, 6.4.4.1.3 requires onsite			An audit will be conducted		
	_	maintained in accordance with			monthly with the quality		
	•	rd for Emergency and Standby			assurance committee to assur		
	<u> </u>	FPA 110, 8.4.1 requires an			that the Emergency Generator		
		Supply System (EPSS)			being tested weekly monthly a		
	Lincluding all appurt	enant components, shall be	1		documentation is completed a	t tho	I

PRINTED: 06/01/2023 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION AND PLAN OF CORRECTION 155358		(X2) MULTIPLE C A. BUILDING B. WING	onstruction <u>01</u>	COMP	E SURVEY PLETED 1/2023	
	PROVIDER OR SUPPLIEF		3300 F	ADDRESS, CITY, STATE, ZIP POPLAR ST E HAUTE, IN 47803	COD	
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OF	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION : CROSS-REFERENCED TO THE DEFICIENCY)	ORRECTION SHOULD BE APPROPRIATE	(X5) COMPLETION DATE
	99, 6.4.4.2 requires performance, exerc generator to be regu for inspection by th	eficient practice could affect all		time of testing. Docui these tests will be rev quality assurance con Executive Director to	iewed by the nmittee.	
	Director on 05/01/2 documentation of w to 03/06/23 was not an interview at the Maintenance Direct documentation of w to 03/06/23 availab These findings were	riew with the Maintenance 3 from 10:05 a.m. to 12:52 p.m., reekly generator testing prior available for review. Based on time of record review, the for confirmed there was no reekly generator testing prior le for review. The reviewed with the Executive enance Director at the exit				
K 0923 SS=D Bldg. 01	Storag Gas Equipment - Storage Greater than or ec Storage locations and ventilated in a and 5.1.3.3.3. >300 but <3,000 c Storage locations enclosure or withi space of non- or li construction, with	Cylinder and Container Cylinder and Container qual to 3,000 cubic feet are designed, constructed, accordance with 5.1.3.3.2 cubic feet are outdoors in an an enclosed interior mited- combustible door (or gates outdoors) ed. Oxidizing gases are not				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

XNG621 Facility ID: 000249

If continuation sheet Page 33 of 35

NAME OF PROVIDER OR SUPPLIER MAJESTIC CARE OF DEMINIS PARK (CA) ID SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION STORMATION STORMATI	STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) M	(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVE			SURVEY	
NAME OF PROVIDER OR SUPPLIER MAJESTIC CARE OF DEMING PARK (X3) ID SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY PULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG PRICED (CARE OF DEMING PARK) TAG REGULATORY OR LSC IDENTIFYING INFORMATION Stored with flammables, and are separated from combustibles by 20 feet (5 feet if sprinklered) or enclosed in a cabinet of noncombustible construction having a minimum 1/2 hr. fire protection rating, Less than or equal to 300 cubic feet In a single smoke compartment, individual cylinders available for immediate use in patient care areas with an aggregate volume of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders are used empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this			A. BU				ETED	
MAJESTIC CARE OF DEMING PARK (X4) ID SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION TAG Stored with flammables, and are separated from combustibles by 20 feet (5 feet if sprinklered) or enclosed in a cabinet of noncombustible construction having a minimum 1/2 hr. fire protection rating. Less than or equal to 300 cubic feet In a single smoke compartment, individual cylinders available for immediate use in patient care areas with an aggregate volume of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility X551 STORED WITHIN NO SMOKING." STORED WITHIN NO SMOKING." Storage is planned so cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility			155358	B. W	B. WING 05/0		05/01/	/2023
PREFIX TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG REGISTRATE INFORMATION DATE stored with flammables, and are separated from combustibles by 20 feet (5 feet if sprinklered) or enclosed in a cabinet of noncombustible construction having a minimum 1/2 hr. fire protection rating. Less than or equal to 300 cubic feet In a single smoke compartment, individual cylinders available for immediate use in patient care areas with an aggregate volume of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility				<u> </u>	3300 P	OPLAR ST		
PREFIX TAG REGULATORY OR LSC IDENTIFYING INFORMATION TAG REGISTRATION TO THE APPROPRIATE REPRESENTED TO THE APPROPRIATE REPRESENTED TO THE APPROPRIATE REPRESENTED THE APPROPRIATE CROSS-REFERENCE TO THE APPROPRIATE	(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID			(X5)
stored with flammables, and are separated from combustibles by 20 feet (5 feet if sprinklered) or enclosed in a cabinet of noncombustible construction having a minimum 1/2 hr. fire protection rating. Less than or equal to 300 cubic feet In a single smoke compartment, individual cylinders available for immediate use in patient care areas with an aggregate volume of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are less gregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this						(EACH CORRECTIVE ACTION SHOULD BE		
from combustibles by 20 feet (5 feet if sprinklered) or enclosed in a cabinet of noncombustible construction having a minimum 1/2 hr. fire protection rating. Less than or equal to 300 cubic feet In a single smoke compartment, individual cylinders available for immediate use in patient care areas with an aggregate volume of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this		*				CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	IE	
from combustibles by 20 feet (5 feet if sprinklered) or enclosed in a cabinet of noncombustible construction having a minimum 1/2 hr. fire protection rating. Less than or equal to 300 cubic feet In a single smoke compartment, individual cylinders available for immediate use in patient care areas with an aggregate volume of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this		stored with flamm	ables, and are separated					
sprinklered) or enclosed in a cabinet of noncombustible construction having a minimum 1/2 hr. fire protection rating. Less than or equal to 300 cubic feet In a single smoke compartment, individual cylinders available for immediate use in patient care areas with an aggregate volume of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this			· ·					
noncombustible construction having a minimum 1/2 hr. fire protection rating. Less than or equal to 300 cubic feet In a single smoke compartment, individual cylinders available for immediate use in patient care areas with an aggregate volume of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this			•					
minimum 1/2 hr. fire protection rating. Less than or equal to 300 cubic feet In a single smoke compartment, individual cylinders available for immediate use in patient care areas with an aggregate volume of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this								
Less than or equal to 300 cubic feet In a single smoke compartment, individual cylinders available for immediate use in patient care areas with an aggregate volume of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this			_					
cylinders available for immediate use in patient care areas with an aggregate volume of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this								
patient care areas with an aggregate volume of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this								
of less than or equal to 300 cubic feet are not required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this		_						
required to be stored in an enclosure. Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this		patient care areas	with an aggregate volume					
Cylinders must be handled with precautions as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this		of less than or equ	ual to 300 cubic feet are not					
as specified in 11.6.2. A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this		required to be sto	red in an enclosure.					
A precautionary sign readable from 5 feet is on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this		Cylinders must be	handled with precautions					
on each door or gate of a cylinder storage room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this		as specified in 11.	.6.2.					
room, where the sign includes the wording as a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this		A precautionary s	ign readable from 5 feet is					
a minimum "CAUTION: OXIDIZING GAS(ES) STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this		_	-					
STORED WITHIN NO SMOKING." Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this								
Storage is planned so cylinders are used in order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this			` '					
order of which they are received from the supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this								
supplier. Empty cylinders are segregated from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this			-					
from full cylinders. When facility employs cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this			-					
cylinders with integral pressure gauge, a threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this								
threshold pressure considered empty is established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this		-						
established. Empty cylinders are marked to avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this		-						
avoid confusion. Cylinders stored in the open are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this 05/10/2023		•	• •					
are protected from weather. 11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this 05/10/2023		•	• •					
11.3.1, 11.3.2, 11.3.3, 11.3.4, 11.6.5 (NFPA 99) Based on observation and interview, the facility K 0923 It is the responsibility of this 05/10/2023			•					
99) Based on observation and interview, the facility K 0923 It is the responsibility of this 05/10/2023		•						
Based on observation and interview, the facility $K0923$ It is the responsibility of this $05/10/2023$.s.s, 11.s.4, 11.b.5 (NFPA					
				17.0	000			05/10/2022
			-	KU	923	· · · · · · · · · · · · · · · · · · ·		05/10/2023
, , , , , , , , , , , , , , , , , , , ,								
falling. NFPA 99, Health Care Facilities Code, 2012 Edition, Section 11.3.3 states storage for from falling. The corrective action taken for						_	for	
nonflammable gases with a total volume equal to those residents found to be			_				IUI	
or less than 8.5 cubic meters (300 cubic feet) shall affected by the deficient		_	•					
comply with 11.3.3.1 and 11.3.3.2. NFPA 99, practice includes: There are no						_	no	
Section 11.3.3.2 states precautions in handling identified residents How other						I -		
cylinders specified in 11.3.3.1 shall be in residents that have the			-				•	
accordance with 11.6.2. Section 11.6.2.3(11) states potential to be affected by the		-					e	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: XNG621 Facility ID: 000249

If continuation sheet Page 34 of 35

PRINTED: 06/01/2023 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MI	X2) MULTIPLE CONSTRUCTION			SURVEY	
AND PLAN OF CORRECTION IDENTIFICATION NUMBER		r í	A. BUILDING 01			(X3) DATE SURVEY COMPLETED	
AND PLAN	OF CORRECTION	155358	B. WI		01		
100006			B. WI	NG		05/01/	2023
NAME OF I	PROVIDER OR SUPPLIER			STREET A	ADDRESS, CITY, STATE, ZIP COD		
NAME OF F	ROVIDER OR SUFFLIER	L.		3300 P	OPLAR ST		
MAJESTIC CARE OF DEMING PARK			TERRE	HAUTE, IN 47803			
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	(EACH DEFICIEN	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPR	IATE	COMPLETION
TAG	REGULATORY OF	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	freestanding cylind	ers shall be properly chained			same defective practice will	be	
	or supported in a pr	oper cylinder stand or cart.			identified and what correcti	ve	
	This deficient pract	ice could affect staff in the			action will be taken. All		
	vicinity of the oxyg	en storage and transfilling			residents have the potential t	o be	
	room in the garage.				affected but none were identi	fied.	
					All staff were inserviced on the	nis	
	Findings include:				deficient practice. The 2 cyli	nders	
					were properly placed in secu	red	
	Based on observation	ons with the Maintenance			racks. What measures will be		
	Director during a to	our of the facility from 12:32			put into place and what		
	p.m. to 1:46 p.m. or	n 05/01/23, two of 47 'E' type			systemic changes will be m	ade	
	oxygen cylinders w	ere freestanding on the floor in			to ensure that the deficient		
	the oxygen storage	and transfilling room and were			practice does not recur:	ΑII	
	not properly chaine	d or supported in a proper			staff were inserviced on this		
	cylinder stand or ca	rt. Based on interview at the			deficient practice. The 2 cyli	nders	
	time of the observat	tions, the Maintenance			were properly placed in secu		
	Director agreed the	two oxygen cylinders were not			racks. How the corrective		
	properly chained or	supported in a proper cylinder			action will be monitored to		
	stand or cart.				ensure the deficient practic	е	
					will not recur, i.e., what qua	lity	
	This finding was re	viewed with the Executive			assurance program will be	-	
	_	aintenance Director during the			into place: The maintenance		
	exit conference.	-			director and/or his designee		
					conduct weekly audits of the		
	3.1-19(b)				oxygen room and free standi	ng	
					cylinders for 3 months and th	•	
					monthly audits for 3 months.		
					deficient practices will be		
					immediately remedied and re	sults	
					brought to the attention of the		
					Audit results will be shared w		
					the monthly QAPI team.		

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: XNG621 Facility ID: 000249 If continuation sheet Page 35 of 35