CENTERS FOR STATEMEN	T OF HEALTH AND HUR MEDICARE & MEDICARE & MEDICIT OF DEFICIENCIES OF CORRECTION			ULTIPLE CC JILDING	ONSTRUCTION 		RM APPROVED IB NO. 0938-039 SURVEY	122
		155207	B. W.	ING		08/15/2022		
NAME OF PROVIDER OR SUPPLIER  MAJESTIC CARE OF NEW HAVEN  ON THE SUMMARY STATEMENT OF DEFICIENCIES			STREET ADDRESS, CITY, STATE, ZIP COD 1201 DALY DRIVE NEW HAVEN, IN 46774					
(X4) ID PREFIX TAG	(EACH DEFICIE)	STATEMENT OF DEFICIENCIE NCY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	ATE	(X5) COMPLETION DATE	
E 0000								
Bldg	conducted by the I accordance with 42 Survey Date: 08/1 Facility Number: Provider Number: AIM Number: 100	5/22 000114 155207	E 00	)00	We do not submit this plan of correction as admittance or dof the alleged incidents. We respectfully request desk revas we have attempted to include all documentation required as evidence of correction.	lenial iew, ude		

At this Emergency Preparedness survey, Majestic Care of New Haven was found not in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73. The facility has a capacity of 120 and had a census of 82 at the time of this survey.

Quality Review completed on 08/17/22

E 0004 SS=F Bldg. --

403.748(a), 416.54(a), 418.113(a), 441.184(a), 482.15(a), 483.475(a), 483.73(a), 484.102(a), 485.625(a), 485.68(a), 485.727(a), 485.920(a), 486.360(a),

491.12(a), 494.62(a) Develop EP Plan, Review and Update Annually §403.748(a), §416.54(a), §418.113(a), §441.184(a), §460.84(a), §482.15(a),

§483.73(a), §483.475(a), §484.102(a), §485.68(a), §485.625(a), §485.727(a), §485.920(a), §486.360(a), §491.12(a), §494.62(a).

The [facility] must comply with all applicable Federal, State and local emergency preparedness requirements. The [facility]

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

000114

(X6) DATE

Any defiency statement ending with an asterisk (\*) denotes a deficency which the institution may be excused from correcting providing it is determin other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclodays following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155207		(X2) MULTIPLE C A. BUILDING B. WING	ONSTRUCTION	(X3) DATE SURVEY COMPLETED 08/15/2022	
	PROVIDER OR SUPPLIE		1201 🛭	ADDRESS, CITY, STATE, ZIP COD DALY DRIVE HAVEN, IN 46774	
(X4) ID PREFIX TAG	(EACH DEFICIE	STATEMENT OF DEFICIENCIE  NCY MUST BE PRECEDED BY FULL  DELSC IDENTIFYING INFORMATION	ID PREFIX	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPRO DEFICIENCY)	O BE COMPLETION
TAG	must develop est comprehensive e program that med section. The emergency P develop and main preparedness pla and updated at le must do all of the * [For hospitals a §485.625(a):] Emor CAH] must dovelop and main preparedness reception, utilizing a * [For LTC Facilit Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For LTC Facilit Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plandevelop and main preparedness pla and updated at let * [For ESRD Face Emergency Plan	lan. The [facility] must ntain an emergency an that must be [reviewed], east every 2 years. The plant of following:  It §482.15 and CAHs at mergency Plan. The [hospital mply with all applicable and local emergency quirements. The [hospital or op and maintain a mergency preparedness ets the requirements of this an all-hazards approach.  It §483.73(a):]  The LTC facility must ntain an emergency and that must be reviewed, east annually.  It is \$494.62(a):]  The ESRD facility must ntain an emergency and that must be [evaluated], east every 2 years.	TAG		DATE
	failed to review an Preparedness Plan	wiew and interview, the facility d update the Emergency (EPP) at least annually in 2 CFR 483.73(a). This deficient	E 0004	The Emergency     Preparedness Plan (EPP)     reviewed on 8/24/2022     This deficient practic	

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

i i		UILDING	NSTRUCTION	(X3) DATE COMPL <b>08/15</b> /	ETED		
	ROVIDER OR SUPPLIER		•	1201 D	ADDRESS, CITY, STATE, ZIP COD ALY DRIVE AVEN, IN 46774		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	ΓE	(X5) COMPLETION DATE
E 0013 SS=F Bldg	practice could affect  Findings include:  Based on records re and Maintenance Deam., the EEP had a documentation could was reviewed and use Based on an interviewed or updated be found.  This finding was revand Maintenance Deconference.  403.748(b), 416.5441.184(b), 482.1484.102(b), 485.6485.727(b), 485.66485.727(b), 485.66483.73(b), §446.8481.184(b), §4608481.184(b), §4608481.184(b), §485.68(b), §48	view with the Administrator frector on 08/15/22 at 10:41 revision date of 2019, no other d be found to show the EPP pdated within the last year. Ew during records review, the Maintenance Director stated on show the EEP has been director during the exit viewed with the Administrator frector during the exit viewed with			the potential to affect all reside 3. The Maintenance Direct and Executive Director were educated on 8/24/2022 to revia and update the EPP annually the Senior Executive Director. 4. Executive Director/desig will review Monthly for 6 month that all required documents and the EPP binder. This informati will be presented to the QAPI committee during the monthly meeting.	or ew by nee ns e in	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 3 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

	OF CORRECTION	IDENTIFICATION NUMBER  155207	A. BUILDI B. WING			COMPL 08/15/	ETED
	PROVIDER OR SUPPLIER		12	01 DA	DDRESS, CITY, STATE, ZIP COD LLY DRIVE		
MAJEST	IC CARE OF NEW	HAVEN 	I NI	-VV HA	AVEN, IN 46774		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION	ID PREI TA	IX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	be reviewed and u years.	updated at least every 2					
	and procedures. T develop and imple preparedness poli on the emergency (a) of this section, paragraph (a)(1) of communication pla section. The polic be reviewed and u	s at §483.73(b):] Policies The LTC facility must ement emergency cies and procedures, based a plan set forth in paragraph risk assessment at of this section, and the ean at paragraph (c) of this cies and procedures must updated at least annually. The ements for PACE and					
	procedures. The develop and imple preparedness poli on the emergency (a) of this section, paragraph (a)(1) of communication plasection. The policiaddress managen nonmedical emergimited to: Fire; eq failure; care-related disasters likely to safety of the partic.	PACE organization must ement emergency cies and procedures, based plan set forth in paragraph risk assessment at of this section, and the en at paragraph (c) of this cies and procedures must ment of medical and gencies, including, but not uipment, power, or water and emergencies; and natural threaten the health or cipants, staff, or the public. Procedures must be atted at least every 2 years.					
	and procedures. develop and imple preparedness poli	ties at §494.62(b):] Policies The dialysis facility must ement emergency cies and procedures, based plan set forth in paragraph					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 4 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTIFICATION NUMBER  155207  AND PLAN OF CORRECTION IDENTIFICATION NUMBER  A. BUILDING  B. WING		INSTRUCTION	COMPLETED 08/15/2022				
	PROVIDER OR SUPPLIER			1201 D	ADDRESS, CITY, STATE, ZIP COD ALY DRIVE AVEN, IN 46774		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	TE	(X5) COMPLETION DATE
E 0029	paragraph (a)(1) or communication plasection. The policible reviewed and users. These emenot limited to, fire, failures, care-relatively interruption likely to occur in the area.  Based on record review and Preparedness Plan's at least annually in 483.73(a). This definoccupants.  Findings include:  Based on records reand Maintenance Da.m., the EEP had a documentation coul Policies and Procedupdated within the linterview during record and Maintenance Da. documentation to she procedures have been the last year could retain the finding was reviewed.	now the EEP Policies and en reviewed or updated within not be found.  viewed with the Administrator irector during the exit	E 0	013	1. The Emergency Preparedness Plan's (EPP) Pound Procedures was reviewed 8/24/2022 2. This deficient practice has the potential to affect all reside 3. The Maintenance Direct and Executive Director were educated on 8/24/2022 to reviand update the EPP Policy and Procedures annually by the Se Executive Director. 4. Executive Director/design will review Monthly for 6 month that all required documents are the EPP binder. This information will be presented to the QAPI committee during the monthly meeting.	as ents. cor ew d enior gnee ens e in	09/09/2022
SS=F Bldg		5(c), 483.475(c), 483.73(c), 25(c), 485.68(c),					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 5 of 28

	NT OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	· ′		NSTRUCTION	(X3) DATE	
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER 155207	A. BUILD B. WING	DING	<del></del>	COMPL 08/15/	
		100207		TDEET A	DDDEGG CITY CTATE ZID COD	00/10/	2022
NAME OF F	PROVIDER OR SUPPLIEF	R			DDRESS, CITY, STATE, ZIP COD ALY DRIVE		
MAJEST	IC CARE OF NEW	HAVEN	NEW HAVEN, IN 46774				
(X4) ID		STATEMENT OF DEFICIENCIE	П		PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX TAG	ì ·	ICY MUST BE PRECEDED BY FULL		EFIX AG	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT DEFICIENCY)	ΓE	COMPLETION DATE
IAU	491.12(c), 494.62 Development of C §403.748(c), §416 §441.184(c), §460 §483.73(c), §483. §485.68(c), §485. §485.920(c), §486 §494.62(c).  (c) The [facility] m an emergency preplan that complies local laws and mulat least every 2 years failed to review and Preparedness Plan's least annually in acute 483.73(a). This definition occupants.  Findings include:  Based on records read Maintenance D a.m., the EEP had a documentation could Communication Plawithin the last years records review, the Maintenance Direct to show the EEP Coreviewed or updated be found.  This finding was records	communication Plan 6.54(c), §418.113(c), 0.84(c), §482.15(c), 475(c), §484.102(c), 625(c), §485.727(c), 6.360(c), §491.12(c),  ust develop and maintain eparedness communication is with Federal, State and est be reviewed and updated ears [annually for LTC  view and interview, the facility in update the Emergency is (EPP) Communication Plan at cordance with 42 CFR icient practice could affect all  eview with the Administrator irrector on 08/15/22 at 10:41 irrevision date of 2019, no other id be found to show the EPP in was reviewed and updated in Based on an interview during	E 0029		1. The Emergency Preparedness Plan's (EPP) Communication Plan was revie on 8/24/2022 2. This deficient practice hat the potential to affect all reside 3. The Maintenance Direct and Executive Director were educated on 8/24/2022 to revie and update the EPP Communication Plan annually the Senior Executive Director. 4. Executive Director/desig will review Monthly for 6 month that all required documents are the EPP binder. This informatic will be presented to the QAPI committee during the monthly meeting.	as ents. or ew by nee ns e in	09/09/2022

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet Page 6 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155207		(X2) MULTIPLE ( A. BUILDING B. WING	CONSTRUCTION	(X3) DATE SURVEY  COMPLETED  08/15/2022	
		100201	<u> </u>	T ADDRESS, CITY, STATE, ZIP CO	-
	PROVIDER OR SUPPLIER		1201	DALY DRIVE HAVEN, IN 46774	
	T			1	ave)
(X4) ID PREFIX		STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL	ID PREFIX	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SHO	
TAG	· ·		TAG	CROSS-REFERENCED TO THE API DEFICIENCY)	PROPRIATE DATE
E 0036	403.748(d), 416.5				
SS=F		5(d), 483.475(d), 483.73(d),			
Bldg	484.102(d), 485.6	25(d), 485.68(d),			
	485.727(d), 485.9				
	491.12(d), 494.62	• •			
	EP Training and T	•			
		6.54(d), §418.113(d),			
		).84(d), §482.15(d), 475(d), §484.102(d),			
	. , .	625(d), §485.727(d),			
	. , .	6.360(d), §491.12(d),			
	§494.62(d).	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
	*[For RNCHIs at §	403.748, ASCs at §416.54,			
		13, PRTFs at §441.184,			
		Hospitals at §482.15,			
		2, CORFs at §485.68,			
		5, "Organizations" under			
		at §485.920, OPOs at IC/FHQs at §491.12:] (d)			
	-	ng. The [facility] must			
	_	tain an emergency			
	-	ning and testing program			
	that is based on th	ne emergency plan set forth			
	in paragraph (a) o				
		ragraph (a)(1) of this			
		nd procedures at paragraph			
	1 ' '	and the communication			
		(c) of this section. The g program must be			
	_	ated at least every 2 years.			
		atou at loadt 6voly 2 years.			
	*[For LTC facilities	s at §483.73(d):] (d) Training			
	-	_TC facility must develop			
		mergency preparedness			
		g program that is based on			
the emergency plan set forth in paragraph (a)					
		k assessment at paragraph			
		on, policies and procedures			
	at paragraph (b) o	f this section, and the	1		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 7 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

	T OF DEFICIENCIES OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155207	(X2) MULTIPLE CO A. BUILDING B. WING	NSTRUCTION	(X3) DATE SURVEY COMPLETED 08/15/2022			
	ROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD  1201 DALY DRIVE  NEW HAVEN, IN 46774					
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE			
	section. The train	an at paragraph (c) of this ing and testing program and updated at least						
	testing. The ICF/II maintain an emergand testing progratemergency plans this section, risk a (a)(1) of this section at paragraph (b) ocommunication plasection. The train must be reviewed 2 years. The ICF/II	D must develop and gency preparedness training am that is based on the et forth in paragraph (a) of ssessment at paragraph on, policies and procedures of this section, and the an at paragraph (c) of this ing and testing program and updated at least every ID must meet the evacuation drills and training						
	Training, testing, a dialysis facility mu emergency preparand patient orients on the emergency (a) of this section, paragraph (a)(1) of procedures at parand the communic of this section. The orientation programupdated at every 2 Based on record reversible to review and Preparedness Plan's Plan at least annual.	ties at §494.62(d):] and orientation. The st develop and maintain an redness training, testing ation program that is based replan set forth in paragraph risk assessment at of this section, policies and agraph (b) of this section, cation plan at paragraph (c) he training, testing and m must be evaluated and 2 years. Friew and interview, the facility I update the Emergency (EPP) Training and Testing ly in accordance with 42 CFR cient practice could affect all	E 0036	The Emergency Preparedness Plan's (EPP) Training and Testing was revie on 8/24/2022 This deficient practice h				
	occupants.			the potential to affect all reside 3. The Maintenance Direct	ents.			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 8 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTIFICATION NUMBER  155207			A. BUILDING  B. WING	INSTRUCTION	COMPLETED  08/15/2022		
	PROVIDER OR SUPPLIER	EN	STREET ADDRESS, CITY, STATE, ZIP COD  1201 DALY DRIVE  NEW HAVEN, IN 46774				
(X4) ID PREFIX TAG	(EACH DEFICIENCY M REGULATORY OR LSC	EMENT OF DEFICIENCIE UST BE PRECEDED BY FULL IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA' DEFICIENCY)	(X5) COMPLETION DATE		
	documentation could be Training and Testing Pla updated within the last y interview during records and Maintenance Direct documentation to show to Testing Plan has been retthe last year could not be	or on 08/15/22 at 10:41 ion date of 2019, no other found to show the EPP n was reviewed and ear. Based on an review, the Administrator or stated the the EEP Training and viewed or updated within found.		and Executive Director were educated on 8/24/2022 to revide and update the EPP Training a Testing annually by the Senior Executive Director.  4. Executive Director/desigwill review Monthly for 6 month that all required documents and the EPP binder. This information will be presented to the QAPI committee during the monthly meeting.	and gnee ns e in		
K 0000							
Bldg. 01	483.90(a).  Survey Date: 08/15/22  Facility Number: 00011 Provider Number: 15520 AIM Number: 1002666  At this Life Safety Code New Haven was found n Requirements for Particip Medicare/Medicaid, 42 C Life Safety from Fire and	accordance with 42 CFR  4 07 40 survey, Majestic Care of ot in compliance with pation in CFR Subpart 483.90(a), I the 2012 edition of the Association (NFPA) 101, Chapter 19, Existing	K 0000	We do not submit this plan of correction as admittance or de of the alleged incidents. We respectfully request desk revie as we have attempted to include all documentation required as evidence of correction.	ew,		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 9 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTIFICATION NUMBER  155207		A. BUILDING B. WING	01	COMP	LETED 5/2022	
	ROVIDER OR SUPPLIER		1201 D	ADDRESS, CITY, STATE, ZIP COD ALY DRIVE  AVEN, IN 46774		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPF DEFICIENCY)	LD BE	(X5) COMPLETION DATE
K 0222 SS=E Bldg. 01	Type V (000) constr sprinklered. The facility sprinklered smoke detection to the corridors and operated smoke detection to the corridors and operated smoke detection to the corridors and operated smoke detection of the survey.  All areas where the access were sprinkled facility services were exception of a detact emergency generated maintenance equipmed.  Quality Review community Review Communi	d means of egress shall not a latch or a lock that f a tool or key from the s using one of the following				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 10 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155207		(X2) MULTIPLE CO A. BUILDING B. WING	ONSTRUCTION 01	(X3) DATE SURVEY  COMPLETED  08/15/2022			
		ROVIDER OR SUPPLIER		1201 D	ADDRESS, CITY, STATE, ZIP COD ALY DRIVE IAVEN, IN 46774	•	
	4) ID		STATEMENT OF DEFICIENCIE	ID	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOUL	.D BE	(X5)
		*			CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		
	EFIX TAG	REGULATORY OF  18.2.2.2.5.1, 18.2  19.2.2.6  SPECIAL NEEDS  ARRANGEMENT: Where special loc safety needs of the the Clinical or Sec are being met. In a electrical locks that release upon loss building is protected automatic sprinkle space is protected detection system at an attended loc space); and both a systems are arran upon activation.  18.2.2.2.5.2, 19.2  DELAYED-EGRE ARRANGEMENT: Approved, listed of systems installed 7.2.1.6.1 shall be assemblies servin contents in buildin an approved, supe detection system of automatic sprinkle 18.2.2.2.4, 19.2.2  ACCESS-CONTR LOCKING ARRAN Access-Controlled installed in accord be permitted.  18.2.2.2.4, 19.2.2	king arrangements for the e patient are used, all of curity Locking requirements addition, the locks must be at fail safely so as to of power to the device; the ed by a supervised er system and the locked d by a complete smoke (or is constantly monitored cation within the locked the sprinkler and detection aged to unlock the doors  2.2.5.2, TIA 12-4 SS LOCKING S lelayed-egress locking in accordance with permitted on door g low and ordinary hazard ags protected throughout by ervised automatic fire or an approved, supervised er system. 2.4 COLLED EGRESS NGEMENTS d Egress Door assemblies lance with 7.2.1.6.2 shall  2.4 BY EXIT ACCESS	PREFIX TAG	CROSS-REFERENCED TO THE APPR	D BE OPRIATE	COMPLETION DATE
		Elevator lobby exi	t access door locking in 7.2.1.6.3 shall be permitted				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet Page 11 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTIFICATION NUMBER  155207		A. BUILDING 01  B. WING		COMPLETED 08/15/2022	
	PROVIDER OR SUPPLIER		1201	T ADDRESS, CITY, STATE, ZIP COD DALY DRIVE HAVEN, IN 46774	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	E COMPLETION
K 0232	throughout by an a automatic fire determination and particular the surface of the building dischar and the courtyard gawith a chain and particular the surface of the surfa	es in buildings protected approved, supervised ection system and an seed automatic sprinkler  2.4  In and interview, the facility means of egress through 1 of purtyard was readily within a required means of equipped with a latch or lock to of a tool or key from the therwise permitted by LSC icient practice could affect over  on with the Maintenance  2 at 12:48 p.m., two exits from ged through the courtyard, atte on the exit path was locked dlock. Based on interview at ion, the Maintenance Director lock the padlock was carried or and Maintenance only, and the building the gate could not wiewed with the Administrator irector during the exit	K 0222	1. The identified padlock removed and replaced with a combination lock that has the code engraved in it.  2. This deficient practice the potential to affect all residual for the potential to affect all residual executive Director were educated on 8/24/2022 to enall gate locks are able to be unlocked during an emergent the Senior Executive Director/deswill review monthly with the monthly Fire Drills for 6 monthat the identified lock is appropriate and in working of the QAPI committee during monthly meeting.	has dents. ector  nsure ncy by or. signee ths order. ented
SS=E Bldg. 01	Aisle, Corridor, or Aisle, Corridor or F 2012 EXISTING				

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 12 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTIFICATION NUMBER  155207		A. BUILDING B. WING	COMPLETED 08/15/2022			
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 1201 DALY DRIVE NEW HAVEN, IN 46774			
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	(X5) COMPLETION DATE	
K 0321	at least 4 feet and convenient remove on stretchers, excer 19.2.3.4, exception 19.2.3.4, 19.2.3.5 Based on observation failed to meet 1 of 8 requirement exception 19.2.3.4(1) requires adjunct areas not into treatment, or use of than 44 inches in clot This deficient praction the exit outside of the Findings include:  Based on observation Director on 08/15/2 p.m., in the 8-foot extensive at the time Maintenance Director picked up the next of and cart across from required clear width.  This finding was revealed the conference.	on and interview, the facility sexit corridors clear width on per 19.2.3.4(1). LSC aisles, corridors, and ramps in tended for the housing, inpatients shall not be less ear and unobstructed width. It is could 20 residents using the dining room.  On with the Maintenance 2 at 12:30 p.m. and again at 2:30 xit corridor by the dining room cart by the exit door reducing tess than 44 inches. Based on the of observation, the or stated the bed was to be lay and agreed there was bed in each other reducing the	K 0232	1. The identified items lim the exits egress were removed 2. This deficient practice is the potential to affect all residdar. The management team were educated on 8/24/2022 ensure all egresses are not blocked or limited by items/equipment by the Senion Executive Director.  4. Executive Director/desimil review weekly, for 4 weeks then monthly for 5 months the egresses are not limited or blocked by items/equipment. Information will be presented the QAPI committee during the monthly meeting.	ed. nas leents. n to  gnee as and at  This	
K 0321 SS=E Bldg. 01						

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155207		(X2) MULTIPLE CO A. BUILDING B. WING	(X3) DATE SURVEY  COMPLETED  08/15/2022			
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 1201 DALY DRIVE NEW HAVEN, IN 46774			
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE	
	(with 3/4 hour fire automatic fire exti accordance with 8 approved automatic option is used, the from other spaces partitions and doo Doors shall be sel automatic-closing nonrated or field-ado not exceed 48 the door.  Describe the floor hazardous areas to REMARKS.  19.3.2.1, 19.3.5.9	rated doors) or an nguishing system in 3.7.1 or 19.3.5.9. When the tic fire extinguishing system areas shall be separated by smoke resisting rs in accordance with 8.4. f-closing or and permitted to have applied protective plates that inches from the bottom of that are deficient in				
	b. Laundries (large c. Repair, Mainter d. Soiled Linen Ro gallons) e. Trash Collection (exceeding 64 gal f. Combustible Sto (over 50 square fe	e-Fired Heater Rooms er than 100 square feet) nance, and Paint Shops doms (exceeding 64 n Rooms lons) dorage Rooms/Spaces eet) classified as Severe				
	Based on observation failed to ensure 1 or were not obstructed practice could affect Findings include:  Based on observation	on and interview, the facility f 1 laundry room corridor doors from closing. This deficient t staff in the service hall.	K 0321	The identified laundry corridor door had the item rem that was restricting it from close.     This deficient practice he the potential to affect all reside 3. The Maintenance Direct Environmental Supervisor and Executive Director were educated.	sing. as ents. dor, lated	
		Oirector on 08/15/22 at 12:10 om door was propped open		on 8/24/2022 to ensure doors a corridor that are to automatic		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet Page 14 of 28

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY			SURVEY			
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BUILDING <u>01</u> COMPLETE			ETED		
		155207	B. W	ING		08/15/	2022	
		<u> </u>		STREET A	ADDRESS, CITY, STATE, ZIP COD			
NAME OF P	PROVIDER OR SUPPLIER		1201 DALY DRIVE					
MAJESTI	IC CARE OF NEW	HAVEN		NEW HAVEN, IN 46774				
(X4) ID				ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	`	CY MUST BE PRECEDED BY FULL		PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		COMPLETION	
TAG		LSC IDENTIFYING INFORMATION		TAG			DATE	
		The laundry was equipped			close with a fire alarm are not	L		
	area. Based on inter	rs making this a hazardous			blocked/propped from closing	бу		
		intenance Director agreed the			the Senior Executive Director. <b>4.</b> Executive Director/design	noo		
		lor door was propped open			4. Executive Director/design will review weekly, for 4 weeks			
	and released the doc				then monthly for 5 months that			
	and released the doc				corridor doors are not	<u>.</u>		
	This finding was rev	viewed with the Administrator			blocked/propped. This informa	tion		
	-	irector during the exit			will be presented to the QAPI			
	conference.	8			committee during the monthly			
					meeting.			
	3.1-19(b)				Ğ			
K 0324	NFPA 101						! 	
SS=E	Cooking Facilities							
Bldg. 01	Cooking Facilities							
-	Cooking equipmer							
		IFPA 96, Standard for						
	Ventilation Contro	I and Fire Protection of						
	Commercial Cook	ing Operations, unless:						
	* residential cookii	ng equipment (i.e., small						
	appliances such a	s microwaves, hot plates,						
	toasters) are used	for food warming or limited						
	_	ance with 18.3.2.5.2,						
	19.3.2.5.2							
	-	open to the corridor in						
	· ·	ents with 30 or fewer						
		ith the conditions under						
	18.3.2.5.3, 19.3.2.							
	_	in smoke compartments						
	· ·	atients comply with						
		8.3.2.5.4, 19.3.2.5.4.						
		protected according to						
	· ·	3 are not required to be						
		dous areas, but shall not						
	be open to the cor							
	through 19.3.2.5.5	1 18.3.2.5.4, 19.3.2.5.1						
	•	on and interview, the facility	K 0	224	1. The identified cooktop w	rill	09/09/2022	
		f had access to the shutoff	~ 0	324	have a shutoff switch installed		U9/U9/2U22	
	ianea to ensure star	i nad access to the shutter			nave a shuton switch installed	11.1		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 15 of 28

STATEMEN	T OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) M	ULTIPLE CO	ONSTRUCTION	(X3) DATE	SURVEY
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	JILDING	01	COMPL	LETED
		155207	B. W	ING		08/15	/2022
				STREET	ADDRESS, CITY, STATE, ZIP COD	<u> </u>	
NAME OF P	PROVIDER OR SUPPLIEF	₹			ALY DRIVE		
MAJEST	IC CARE OF NEW	HAVEN	NEW HAVEN, IN 46774				
IVIAJEOT	IO OAKE OF NEW	1 1/ ( V F 1 A		INLVVII	/ ( v L i v , i i v + O / / +		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID PROVIDER'S PLAN OF CORRECTION			(X5)
PREFIX	(EACH DEFICIEN	ICY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG		R LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
		ok tops in the therapy gym.			the therapy gym.		
		es within a smoke compartment,			<ol><li>This deficient practice h</li></ol>	as	
		nercial cooking equipment that			the potential to affect all reside	ents.	
		neals for 30 or fewer persons			<ol><li>The Maintenance Direct</li></ol>	tor,	
		provided that the cooking			Therapy Director and Executiv	/e	
		ith all of the following			Director were educated on		
	conditions:				8/22/2022 to ensure that a shu	ut off	
		ining the cooking equipment			for the cook top must be prese	ent	
	is not a sleeping roo				for cooktops and its function b	-	
		ining the cooking equipment			the Senior Executive Director.		
	•	rom the corridor by partitions			4. Executive Director/design	•	
		3.6.2 through 19.3.6.5.			will review monthly for 6 month	hs	
		ts of 19.3.2.5.3(1) through (10)			that the installed shut off is		
	and (13) are met.				functioning and staff are awar	е	
		A switch meeting all of the			how to use it. This information	will	
	following is provide	ed:			be presented to the QAPI		
		, or a switch located in a			committee during the monthly		
		is provided within the cooking			meeting.		
	1	ates the cooktop or range.					
	(b) The switch is us	sed to deactivate the cooktop					
	_	the kitchen is not under staff					
	supervision.						
	_	ice could affect 8 residents in					
	the therapy gym.						
	Findings include:						
		on with the Maintenance					
		2 at 1:25 p.m., there was a new					
		apy gym that was separated					
		out staff were unable to					
		top from power. Based on					
		e of observation, the					
		tor was asked if staff were able					
		oktop and lock the switch.					
		irector stated the shut off					
		trical room in a breaker box,					
	but staff did not hav	ve access to the breaker box.					
	This finding was re	viewed with the Administrator	1				1

STATEMEN	T OF DEFICIENCIES	X1) PROVIDER/SUPPLIER/CLIA	(X2) M	ULTIPLE CO	ONSTRUCTION	(X3) DATE	SURVEY
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BU	JILDING	01	COMPI	LETED
		155207	B. W	ING		08/15	/2022
				STREET A	ADDRESS, CITY, STATE, ZIP COD		
NAME OF F	PROVIDER OR SUPPLIEF	L			ALY DRIVE		
MAJEST	IC CARE OF NEW	HAVEN		NEW H	IAVEN, IN 46774		
(X4) ID	SUMMARY	STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX	·	CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG		LSC IDENTIFYING INFORMATION	+	TAG	DEFICIENCY)		DATE
		irector during the exit					
	conference.						
	3.1-19(b)						
K 0353	0353 NFPA 101						
SS=E		- Maintenance and Testing					
Bldg. 01	Sprinkler System	- Maintenance and Testing					
	Automatic sprinkler and standpipe systems						
are inspected, tested, and maintained in accordance with NFPA 25, Standard for the							
	Inspection, Testing, and Maintaining of						
		Protection Systems.					
	Records of system design, maintenance, inspection and testing are maintained in a						
	1	_					
		nd readily available.					
	a) Date sprinkler	system last checked					
	b) Who provided system test						
	c) Water system	c) Water system supply source					
	Provide in REMAR	RKS information on					
	coverage for any i	non-required or partial					
	automatic sprinkle	r system.					
	9.7.5, 9.7.7, 9.7.8						
		on and interview, the facility	K 0	353	The identified sprinklers		09/09/2022
		f 5 sprinklers in the lounge			be moved to meet the fire cod	e.	
		cordance with NFPA 13, 2010			2. This deficient practice h		
		5.3.4.1 states unless the			the potential to affect all reside		
	_	.3.4.2, 8.6.3.4.3, or 8.6.3.4.4 are			3. The Maintenance Direc	tor	
		l be spaced not less than 6 ft			and Executive Director were		
		his deficient practice could			educated on 8/22/2022 that al		
	affect 20 residents in one smoke compartment.				sprinklers must be installed in		
	Findings :11				accordance to NFPA 12, 2010		
	Findings include:				the Senior Executive Director.		
	Dagad an al	on with the Maintenance			4. Executive Director/designal regions monthly for 6 month	-	
		2 at 1:50 p.m., in the resident			will review monthly for 6 mont that sprinklers are installed in	115	
		wo sprinklers only two feet			accordance with NFPA 12, 20	10	
ı	1	o opinimiono omij two roct	1		I accordance with the LA LA, ZU	10.	ì

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 17 of 28

PRINTED: 09/01/2022 FORM APPROVED

CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-039 X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER A. BUILDING 01 COMPLETED 155207 B. WING 08/15/2022 STREET ADDRESS, CITY, STATE, ZIP COD NAME OF PROVIDER OR SUPPLIER 1201 DALY DRIVE MAJESTIC CARE OF NEW HAVEN NEW HAVEN, IN 46774

MAJESI	IC CARE OF NEW HAVEN	NEW HAVEN, IN 46774				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE		
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION  apart. Based on interview at the time of the observations, the Maintenance Director measured the distance of the sprinkler heads of two feet distance apart from each other.  This finding was reviewed with the Administrator and Maintenance Director during the exit conference.  3.1-19(b)  NFPA 101  Portable Fire Extinguishers  Portable Fire extinguishers are selected, installed, inspected, and maintained in accordance with NFPA 10, Standard for Portable Fire Extinguishers.  18.3.5.12, 19.3.5.12, NFPA 10  Based on observation and interview, the facility failed to ensure 2 of 30 portable fire extinguishers was given maintenance at periods not more than one year apart. NFPA 10, the Standard for Portable Fire Extinguishers, at Section 7.3.1.1.1 requires that fire extinguishers shall be subjected	PREFIX	This information will be presented to the QAPI committee during the monthly meeting.  1. The identified fire extinguishers received the needed maintenance. 2. This deficient practice has the potential to affect all residents. 3. The Maintenance Director	COMPLETION		
	to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. Section 3.3.15 defines extinguisher maintenance as a thorough examination of the fire extinguisher that is intended to give maximum assurance that a fire extinguisher will operate effectively and safely and to determine if physical damage or condition will prevent its operation, if any repair or replacement is necessary, and if hydrostatic testing or internal maintenance is required. Section 7.3.3 states each fire extinguisher shall have a tag or label securely attached that indicates the month and year the maintenance was		and Executive Director were educated on 8/24/2022 that all fire extinguishers need to receive needed maintenance in no longer of a period than 1 year by the Senior Executive Director.  4. Executive Director/designee will review weekly, for 4 weeks and then monthly for 5 months that all fire extinguishers are serviced at a period of no longer than 1 year. This information will be presented to the QAPI committee during the monthly meeting.			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 18 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

		X1) PROVIDER/SUPPLIER/CLIA				(X3) DATE	SURVEY
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER		JILDING	01	COMPL	
		155207	B. WI	NG		08/15/	/2022
NAME OF P	ROVIDER OR SUPPLIER		•		ADDRESS, CITY, STATE, ZIP COD		
					ALY DRIVE		
MAJESTI	C CARE OF NEW I	HAVEN	NEW HAVEN, IN 46774				
(X4) ID		STATEMENT OF DEFICIENCIE		ID	PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX		CY MUST BE PRECEDED BY FULL		PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION
TAG		LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE
	-	es the person performing the					
	work, and identifies the name of the agency performing the work. This deficient practice could						
		moke shack and staff using					
	the staff exit.	moke snack and starr using					
	Findings include:						
	Based on observation	on with the Maintenance					
		2 at 12:13 p.m. and 12:45 p.m.,					
		xtinguisher in the generator					
	room had an annual inspection date of July 2018, and the fire extinguisher in the smoke shack had						
	an annual inspection	n date of July 2019. Based on					
	interview at the time	es of observation, the					
		or agreed both extinguishers					
	were past due for th	e annual inspections.					
	This finding was rev	viewed with the Administrator					
		irector during the exit					
	conference.						
	3.1-19(b)						
K 0363	NFPA 101						
SS=E	Corridor - Doors						
Bldg. 01	Corridor - Doors						
	Doors protecting of	corridor openings in other					
		osures of vertical openings,					
	exits, or hazardous	s areas resist the passage					
	of smoke and are	made of 1 3/4 inch					
	solid-bonded core	wood or other material					
	capable of resistin	g fire for at least 20					
	minutes. Doors in	fully sprinklered smoke					
	compartments are	only required to resist the					
		e. Corridor doors and doors					
	to rooms containing	_					
		rials have positive latching					
		atches are prohibited by					
	CMS regulation. T	hese requirements do not					

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 19 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTIFICATION NUMBER  155207		A. BUILDING B. WING	01	COMPLETED 08/15/2022			
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 1201 DALY DRIVE NEW HAVEN, IN 46774				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION  (EACH CORRECTIVE ACTION SHOULD BE  CROSS-REFERENCED TO THE APPROPRIATE			
	apply to auxiliary signammable or comic Clearance between covering is not exceed a covering of the door closed with a covering of the door release when the covering is closing of the door release when the covering is covered a covering is covered a co	spaces that do not contain bustible material. In bottom of door and floor ceeding 1 inch. Powered with 7.2.1.9 are permissible device capable of keeping men a force of 5 lbf is no impediment to the rs. Hold open devices that door is pushed or pulled are red protective plates of re permitted. Dutch doors of are permitted. Door beled and made of steel or compliance with 8.3,	K 0363	1. The identified doors had holes filled to prevent smoke a resist fire passage for 20 minu 2. This deficient practice hithe potential to affect all reside 3. The Maintenance Direct and Executive Director were educated on 8/24/2022 that all corridor doors need to have no limitations in structure that wor allow smoke passage and to ensure they resist fire passage 20 minutes by the Senior	and tes. as ents. or		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 20 of 28

f ´		(X2) MULTIPLE CONSTRUCTION (X3) DATE SUR					
AND PLAN	OF CORRECTION	IDENTIFICATION NUMBER	A. BUILDING 01			COMPLETED	
		155207	B. WING 08/15/2022				2022
	ROVIDER OR SUPPLIER		12	201 DA	DDRESS, CITY, STATE, ZIP COD ALY DRIVE AVEN, IN 46774		
(X4) ID	SUMMARY S	STATEMENT OF DEFICIENCIE	ID	)	NEGLIDERIC DI ANI OF CORRECTION		(X5)
PREFIX		CY MUST BE PRECEDED BY FULL	PRE	FIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA		COMPLETION
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION	TA	AG	DEFICIENCY)	DEFICIENCY)	
K 0521 SS=F Bldg. 01	utility room had two through the doors. E of observation, the M the holes were due thandles.  The finding was rev and the Maintenance conference.  3.1-19(b)  NFPA 101 HVAC HVAC Heating, ventilation comply with 9.2 ar accordance with the specifications. 18.5.2.1, 19.5.2.1, Based on record rev interview; the facility damper systems were necessary maintenant instillation and at le accordance with NF heating, ventilating ductwork and relate	o half inch holes that went Based on interview at the time Maintenance Director stated the switching of the door  iewed with the Administrator the Director during the exit  on, and air conditioning shall and shall be installed in the manufacturer's  9.2 tiew, observation, and ty failed to ensure 1 of 1 fire tre inspected and provided the after the first year after ast every four years in TPA 90A. LSC 9.2.1 requires and air conditioning (HVAC) d equipment shall be in	K 0521		Executive Director.  4. Executive Director/design will review weekly, for 4 weeks then monthly for 5 months that corridor doors will have no limitations in structure that would allow smoke passage and to ensure they resist fire passage 20 minutes. This information who be presented to the QAPI committee during the monthly meeting.  1. The identified fire dampedered in the potential to affect all reside 3. The Maintenance Direct and Executive Director were educated on 8/24/2022 that all dampers need inspected per fire	ers as ents. or fire	09/09/2022
	accordance with NFPA 90A, Standard for the Installation of Air-Conditioning and Ventilating Systems. NFPA 90A, 2012 Edition, Section 5.4.8.1 states fire dampers shall be maintained in accordance with NFPA 80, Standard for Fire				code NFPA 90A by the Senior Executive Director.  4. Executive Director/desig will review Monthly for 6 month that all required documents are	nee is	
	2010 Edition, Section shall be tested and in installation. Section inspection frequency	pening Protectives. NFPA 80, on 19.4.1 states each damper inspected 1 year after in 19.4.1.1 states the test and y shall be every 4 years except the frequency is every 6 years.			maintained for fire dampers are that they are inspected per coordinated to the QAPI committee during monthly meeting.	nd de. ited	

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet Page 21 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION IDENTIFICATION NUMBER  155207		A. BUILDING  B. WING	01	COMPLETED 08/15/2022	
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP COD 1201 DALY DRIVE NEW HAVEN, IN 46774		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORR (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE AP DEFICIENCY)	OULD BE COMPLETION
K 0522	link shall be remove closure and lock-indamper shall not be way. All inspection documented, indica damper, date of instance deficiencies discove have a space to indideficiencies were controlled to the practice could affect affect.  Based on records reduced to the practice of the practi	view with the Maintenance			
SS=E Bldg. 01	HVAC - Any Heati HVAC - Any Heati Any heating devic heating plant, is do combustible mate	_			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 22 of 28

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155207		(X2) MULTIPLE C A. BUILDING B. WING	onstruction <u>01</u>	(X3) DATE SURVEY  COMPLETED  08/15/2022	
	PROVIDER OR SUPPLIEF		1201 🛭	ADDRESS, CITY, STATE, ZIP COD DALY DRIVE HAVEN, IN 46774	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE CY MUST BE PRECEDED BY FULL LISC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	(X5) COMPLETION DATE
K 0741	fuel fired, the devi * is chimney or ve * takes air for com * provides for a co from occupied are 19.5.2.2 Based on observation failed to ensure 1 of provided with intak outside for rooms of This deficient pract rich with carbon mo physical problems for Findings include:  Based on observation Director on 08/15/2 room had fuel-fired that was 90% cover condition does not a enter the room. Bas of observation, the the intake was cove to be cleaned.  This finding was re	ature or ignition failure. If ce also: nt connected. bustion from outside. bubustion system separate	K 0522	1. The identified lint traps cleaned to provide intake combustible air. 2. This deficient practice the potential to affect all resid 3. The Maintenance Direct Environmental Service staff, and Executive Director were educed on 8/24/2022 that lint traps of the cleaned to provide clean in combustible air by the Senior Executive Director.  4. Executive Director/desicular will review daily for 2 weeks, weekly for 4 weeks and mont for 4 months that all lint traps clean of lint and dirt. This information will be presented the QAPI committee during the monthly meeting.	has lents. ctor, and cated lust intake dignee thly are
SS=E Bldg. 01	Smoking Regulati Smoking Regulati Smoking regulation				

STATEMENT OF DEFICIENCIES XI) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155207		(X2) MULTIPLE C A. BUILDING B. WING	ONSTRUCTION  01	(X3) DATE SURVEY COMPLETED 08/15/2022			
	F PROVIDER OR SUPPLIED		STREET ADDRESS, CITY, STATE, ZIP COD 1201 DALY DRIVE NEW HAVEN, IN 46774				
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	(X5) COMPLETION DATE		
	ward, or compartr liquids, combustitused or stored an location, and such signs that read No posted with the insmoking.  (2) In health care smoking is prohib prominently place secondary signs was smoking shall not (3) Smoking by paresponsible shall (4) The requirement apply where the pare supervision.  (5) Ashtrays of not safe design shall where smoking is (6) Metal contained devices into which shall be readily as smoking is permit 18.7.4, 19.7.4	atients classified as not be prohibited. ent of 18.7.4(3) shall not eatient is under direct encombustible material and be provided in all areas permitted. ers with self-closing cover in ashtrays can be emptied vailable to all areas where ted.					
	failed to ensure cor stored in 1 of 3 smo	on and interview; the facility inbustible gases were not beking areas. This deficient out 10 residents using the ing area	K 0741	<ol> <li>The identified combusting were removed from the smoke area.</li> <li>This deficient practice has the potential to affect all residuals.</li> <li>The Maintenance Direct and Executive Director were</li> </ol>	as ents.		
	Based on observati Director on 08/15/2 smoking area by th propane tanks sittir smoking area. Base	on with the Maintenance 22 at 12:00 p.m., in the resident e dining room, there were two ag inside the designated ed on interview at the time of aintenance Director sated the		educated on 8/24/2022 that all combustibles are removed fro the smoke area by the Senior Executive Director.  4. Executive Director/designal review weekly, for 4 week then monthly for 5 months that	m gnee s and		

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet Page 24 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

AND PLAN OF CORRECTION  AND PLAN OF CORRECTION  155207		ì í	ULTIPLE CO UILDING ING	ONSTRUC 01	CTION	(X3) DATE S COMPLI 08/15/2	ETED	
	NAME OF PROVIDER OR SUPPLIER  MAJESTIC CARE OF NEW HAVEN  CHANARY STATEMENT OF DEFICIENCE		STREET ADDRESS, CITY, STATE, ZIP COD 1201 DALY DRIVE NEW HAVEN, IN 46774					
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIE ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION		ID PREFIX TAG	(EA CROS	PROVIDER'S PLAN OF CORRECTION ACH CORRECTIVE ACTION SHOULD BE SS-REFERENCED TO THE APPROPRIAT DEFICIENCY)	TE	(X5) COMPLETION DATE
	sitting inside the sm  This finding was rev	ne grill and agreed they were noking area.  viewed with the Administrator during the exit			smok be pr	oustibles are removed from we areas. This information resented to the QAPI mittee during the monthly ting.		
K 0920 SS=E Bldg. 01	Extens Electrical Equipme Extension Cords Power strips in a pused for compone patient-care-relate (PCREE) assembl assembled by qua the conditions of 1 the patient care via non-PCREE (e.g., except in long-term do not use PCREE meet UL 1363A or for non-PCREE in (outside of vicinity non-patient care ro other UL standard used with general cords are not used wiring of a structur temporarily are rer completion of the pinstalled and meet 10.2.3.6 (NFPA 98 (NFPA 70), 590.3( #1. Based on observ facility failed to ens	ent - Power Cords and ent - Power Cords and coatient care vicinity are only ents of movable ed electrical equipment les that have been alified personnel and meet 10.2.3.6. Power strips in cinity may not be used for personal electronics), m care resident rooms that E. Power strips for PCREE r UL 60601-1. Power strips the patient care rooms by meet UL 1363. In coms, power strips meet ls. All power strips are precautions. Extension d as a substitute for fixed re. Extension cords used moved immediately upon purpose for which it was ts the conditions of 10.2.4. ly), 10.2.4 (NFPA 99), 400-8 (D) (NFPA 70), TIA 12-5 vation and interview, the sure 2 of 2 flexible cords were tute for fixed wiring.	K 09	920		The identified extension s were removed or replace medical grade cords.		09/09/2022

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet Page 25 of 28

STATEMENT OF DEFICIENCIES X1) PROVIDER/SUPPLIER/CLI AND PLAN OF CORRECTION IDENTIFICATION NUMBER 155207			(X2) MULTIPLE CONSTRUCTION  A. BUILDING  B. WING		(X3) DATE SURVEY COMPLETED 08/15/2022			
NAME OF PROVIDER OR SUPPLIER  MAJESTIC CARE OF NEW HAVEN			STREET ADDRESS, CITY, STATE, ZIP COD 1201 DALY DRIVE NEW HAVEN, IN 46774					
(X4) ID PREFIX TAG	(EACH DEFICIEN REGULATORY OR NFPA-70/2011, 400 permitted in 400.7 front be used for (1) a This deficient pract residents in two smeares frindings include:  Based on observation Director on 08/15/2 refrigerators were prower by extension in the Case Manage the time of observation acknowledged extendid remove the extension in the Case Manage that time of observation acknowledged extendid remove the extension in the Case Manage that time of observation acknowledged extendid remove the extension in patient care rating of 1363A or affects two resident Findings include:  Based on observation Director on 08/15/2 room 402 was in us care area that did not Based on interview Maintenance Direct use in a resident care or 60601-1.  The findings were resident for the findings were resident care or 60601-1.	on with the Maintenance 2 at 11:50 a.m. and at 2:05 p.m., lugged into and supplied cords in the Payroll office and r office. Based on interview at tion, the Maintenance Director asion cords were in use and ansion cords.  vation and interview, the ture 1 of 1 flexible cords power e locations met the required UL 60601-1. This deficient practice	ID PREFIX TAG	PROVIDERS PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)  2. This deficient practice in the potential to affect all residuals. The Maintenance Direct and Executive Director were educated on 8/24/2022 that flexible extension cords are to used in place of fixed wiring at that extension cords are not to within six feet of a resident ca area without being medical group by the Senior Executive Director/designation will review weekly, for 4 week then monthly for 5 months that extension cords in offices and residents' rooms are used in accordance with fire code. The information will be presented the QAPI committee during the monthly meeting.	DATE  plas ents. tor  place pl			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 26 of 28

STATEMENT OF DEFICIENCIES		X1) PROVIDER/SUPPLIER/CLIA				(X3) DATE SURVEY		
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER	A. BUILDING <u>01</u> B. WING		COMPLETED 08/15/2022			
155207			B. WI	2022				
NAME OF PROVIDER OR SUPPLIER  MAJESTIC CARE OF NEW HAVEN			STREET ADDRESS, CITY, STATE, ZIP COD 1201 DALY DRIVE NEW HAVEN, IN 46774					
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIE			ID	PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL			PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA	TE	COMPLETION	
TAG	REGULATORY OR	LSC IDENTIFYING INFORMATION		TAG	DEFICIENCY)		DATE	
K 0927 SS=E	NFPA 101	Transfilling Ordindon				ļ		
SS-⊑ Bldg. 01		Transfilling Cylinders						
Blug. 01		Transfilling Cylinders gen from one cylinder to						
		rdance with CGA P-2.5,						
		n Pressure Gaseous						
		Respiration. Transfilling of						
		cylinder to another is						
		nt care rooms. Transfilling						
		ontainers or to portable						
	containers over 50	) psi comply with conditions						
	under 11.5.2.3.1 (	NFPA 99). Transfilling to						
		ainers or to portable						
	containers under 5	· · · · · · · · · · · · · · · · · · ·						
		11.5.2.3.2 (NFPA 99).						
	11.5.2.2 (NFPA 99				l			
		on and interview, the facility	K 0	927	The identified oxygen		09/09/2022	
		sfilling of oxygen took place			transfer room was cleaned to	_		
		nsfilling rooms that are portion of a facility, NFPA 99			permit staff to fill oxygen in the	;		
	-	.3.1, Transfilling to liquid			room 2. This deficient practice h	20		
		oir containers or to liquid			the potential to affect all reside			
		ntainers over 344.74 kPa (50			3. The Maintenance Direct			
	psi) shall include the	· · · · · · · · · · · · · · · · · · ·			Director of Nursing and Execu			
	* '	ea separated from any portion			Director were educated on			
	of a facility wherein	patients are housed,			8/24/2022 that oxygen transfe	r		
	examined, or treated	d by a fire barrier of 1 hour			must occur inside the oxygen			
	fire-resistive constru	uction.			room, and equipment stored to	)		
	(2) The area is mechanically ventilated, is sprinklered, and has ceramic or concrete flooring.				permit this by the Senior			
					Executive Director.			
		ed with signs indicating that			4. Executive Director/design			
	_	ring and that smoking in the			will review weekly, for 4 weeks			
	immediate area is no	-			then monthly for 5 months tha			
		ransfilling the container(s) has			oxygen transfer must occur in			
	been properly traine procedures.	tu iii me transiining			the oxygen room, and equipm stored to permit it. This	ะกเ		
	_	ice could affect up to 21			information will be presented t			
	residents in one smo	-			the QAPI committee during the			
	TISTECTION ON SHIP	<del></del>			monthly meeting	-		
	Findings include:				,			

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID:

YT8I21

Facility ID: 000114

If continuation sheet

Page 27 of 28

PRINTED: 09/01/2022 FORM APPROVED OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 155207	(X2) MULTIPLE CONSTRUCTION  A. BUILDING  B. WING		(X3) DATE SURVEY COMPLETED 08/15/2022			
NAME OF PROVIDER OR SUPPLIER  MAJESTIC CARE OF NEW HAVEN			STREET ADDRESS, CITY, STATE, ZIP COD 1201 DALY DRIVE NEW HAVEN, IN 46774					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE		

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: YT8I21 Facility ID: 000114 If continuation sheet Page 28 of 28