



# Pavement Condition Report

---

## Columbus Municipal Airport

Project 1480370

**Prepared for:**

Indiana Department of Transportation  
Office of Aviation  
100 N. Senate Ave.  
Indianapolis, IN 46204  
Indiana Department of Transportation

**Prepared by:**

Applied Research Associates, Inc.  
6314 Odana Rd.  
Madison, WI 53719  
(608) 274-6409

**January 2014**





## Executive Summary

### Background

Since 1995, airports have been required to implement a pavement maintenance-management program to receive funding for any project constructed using Federal money. To assist individual airports in meeting this requirement and help improve airport pavement conditions statewide, the Indiana Department of Transportation, Office of Aviation contracted with Applied Research Associates, Inc. to provide pavement evaluation surveys at local airports. This report documents pavement condition at Columbus Municipal Airport in August 2013.


A primary objective of the pavement management program is to determine maintenance and rehabilitation needs by comparing pavement condition to a standardized benchmark called the minimum service level (MSL), defined as the minimum pavement condition acceptable in managing Indiana’s airfield pavements. The benchmark MSL values used to trigger rehabilitation are shown below.

Runway	Taxiway	Apron
60	55	55

### Pavement Condition

The overall Pavement Condition Index (PCI) for the airfield pavements was 63. Runways had an average inspected PCI of 84 and were above the desired MSL of 60. Taxiways had an average inspected PCI of 78, and ramps had an average inspected PCI of 41.

The “West Ramp” (feature 3020) represents over 30 percent of the airfield pavement and is in poor condition. If feature 3020 is excluded from average calculations, the average overall airfield PCI changes to 83, and the average Apron PCI changes to 87. Runways and taxiways are unchanged at 84 and 78.



### The West Ramp

The west ramp is approximately 1.6 million square feet of airside PCC pavement in poor condition (PCI = 18). Outside of defined taxilanes, the west ramp sees minor use and is therefore not a high priority to receive repairs. The rehabilitation needs for the west ramp are provided below. Because the west ramp disproportionately skews overall airfield numbers, it has been excluded from the remainder of this report.

- The recommended \$20 million west ramp reconstruction is almost 10 times the projected 10-year costs for the rest of the airfield.
- The identified maintenance needs of 130,000 linear feet of cracking sealing, and 260,000 square feet of patching & slab replacement at an estimated cost of \$3.5 million are over 16 times the projected maintenance needs for the rest of the airport.

### Capital Improvement Program

The table below provides a summary of the projected pavement rehabilitation needs for the next 5 years of the capital improvement program, starting in 2013. The estimated cost for the rehabilitation actions that provide the greatest increase in pavement service life is approximately \$1.4 million in 2013 dollars. If no action is taken, the overall PCI is projected to drop from 83 to 76 by 2017.

Project Year	Calendar Year	Amount
Year 1	2013	1,372,101
Year 2	2014	7,128
Year 3	2015	-
Year 4	2016	38,250
Year 5	2017	-
<b>5-Year Total</b>		<b>\$ 1,417,479</b>

Excludes the west ramp

### Maintenance

Analysis of potential maintenance projects identified approximately 1,000 square feet of patching needs and approximately 170,000 linear feet of crack sealing and crack repair needs, at an estimated total cost of approximately \$220,000.


Specific recommendations to help prioritize airfield maintenance are found in chapter 4 of this report. A summary of all identified maintenance needs is shown in the table below and in the figure on the following page.

Work Item	Quantity	Unit	Cost
AC PATCH	993	SF	8,614
AC RESTORATIVE CRACK REPAIR	169,673	LF	210,395
AC SUSTAINING CRACK REPAIR	3,987	LF	3,450
PCC PATCHING	37	SF	620
<b>Total:</b>			<b>\$ 223,079</b>

AC = asphalt concrete; PCC = portland cement concrete; S.F. = square feet; L.F. = linear feet

Excludes the west ramp

COLUMBUS MUNICIPAL AIRPORT  
2013 PCI Inspection



## Table of Contents

---

1. Introduction .....	1
1.1 Objective and Scope .....	1
1.2 Description of Tasks Performed.....	1
2. Pavement Condition Evaluation .....	7
2.1 Overview.....	7
2.2 Distress Types and Frequency .....	12
2.3 PCI Summary.....	13
2.4 Analysis Commentary .....	14
3. Capital Improvement Program.....	17
3.1 Analysis .....	17
3.2 Cost Estimates .....	17
3.3 Capital Improvement Strategies .....	21
4. Maintenance Management Program.....	25
4.1 General Comments .....	25
4.2 Recommended Maintenance Actions.....	25
4.3 Pavement Deterioration .....	29
4.4 Best Practices.....	32
4.5 Pavement Repair Materials .....	35
4.6 Pavement Repair Equipment.....	35
Appendix A. AIRPAV Software.....	37
Appendix B. Feature Analysis.....	39
Appendix C. General Maintenance Techniques.....	107
Appendix D. PCI Summary.....	115
Appendix E. Distress Identification .....	123
Appendix F. Airport Responsibilities.....	131

## Table of Figures

---

Figure 1-1. Pavement Numbering System .....	3
Figure 1-2. PCI Value and Descriptive Rating .....	4
Figure 2-1. Inspected Pavement Condition .....	8
Figure 2-2. Pavement Condition by Branch Use .....	9
Figure 2-3. Typical Good PCC Pavement (Feature 6105).....	9
Figure 2-4. Typical Good AC Pavement (Feature 105) .....	10
Figure 2-5. Typical Fair AC Pavement (Feature 420) .....	10
Figure 2-6. Typical Poor AC Pavement (Feature 3003).....	11
Figure 2-7. AC Swell (Feature 5005) .....	11
Figure 3-1. Programmed CIP .....	21
Figure 4-1. Recommended Maintenance .....	28

## Table of Tables

---

Table 1-1. Minimum Service Levels .....	1
Table 1-2. Inspection Density .....	3
Table 2-1. Definition and Distribution of PCI Ratings .....	7
Table 2-2. Distress Frequency in AC Pavement .....	12
Table 2-3. Distress Frequency in PCC Pavement .....	12
Table 2-4. PCI Results .....	13
Table 2-5. Runway Condition Distribution .....	14
Table 2-6. Taxiway Condition Distribution .....	15
Table 2-7. Apron Condition Distribution .....	16
Table 3-1. Unit Costs.....	18
Table 3-2. Most Comprehensive Repair .....	21
Table 3-3. Lowest Annual Cost Repair .....	22
Table 3-4. All Viable Options .....	22
Table 4-1. Recommend Maintenance Actions .....	25
Table 4-2. Recommend PCC Patching.....	26
Table 4-3. Recommend AC Patching .....	26
Table 4-4. Recommend AC Sustaining Crack Repair.....	27
Table 4-5. Recommend AC Restorative Crack Repair.....	27
Table 4-6. General Maintenance Policy (AC).....	33
Table 4-7. General Maintenance Policy (PCC) .....	34

## GLOSSARY OF ABBREVIATIONS

AC	- asphalt concrete
ACC	- asphalt overlay on existing asphalt
APC	- asphalt overlay on existing concrete
APMS	- airport pavement management system
ARA	- Applied Research Associates, Inc.
CADD	- computer-aided design and drafting
CIP	- capital improvement program
FAA	- Federal Aviation Administration
FOD	- foreign object damage
GIS	- geographic information system
INDOT	- Indiana Department of Transportation
L&T	- longitudinal and transverse
LTD	- longitudinal, transverse, and diagonal
M&R	- maintenance and rehabilitation
MSL	- minimum service level
PCC	- portland cement concrete
PCI	- Pavement Condition Index
PCN	- Pavement Classification Number
PDF	- portable electronic document

## 1. Introduction

### 1.1 Objective and Scope

The Indiana Department of Transportation, Office of Aviation (INDOT) retained Applied Research Associates, Inc., (ARA) to provide airfield pavement inspection, pavement evaluation, and pavement management services for Indiana’s statewide network of airfield pavements. The pavement evaluations documented in this report were performed under purchase order number 14803170.

A primary objective of INDOT’s ongoing pavement evaluation and management program is to determine maintenance and rehabilitation (M&R) needs by comparing the Pavement Condition Index (PCI) to a standardized benchmark called the minimum service level (MSL). The MSL is defined as the minimum pavement condition acceptable in managing INDOT’s airside pavement. The benchmark MSL values used to trigger rehabilitation vary by airport classification and are shown in Table 1-1.

Table 1-1. Minimum Service Levels

Facility	Primary	Commercial Service	Large GA > 3600’Rwy	Large GA < 3600’Rwy
Runway	70	65	60	55
Taxiway	65	60	55	50
Apron	65	60	55	50

Additional goals of this project were to implement a software program to manage the pavement network, develop performance curves based on historical rates of pavement deterioration, forecast future pavement conditions, identify and recommend specific M&R actions to address the root cause of the documented pavement distress, and estimate the cost and ideal timing of the recommend M&R. The following tasks were performed in support of the project goals:

- Review record documents
- Define the pavement network
- Conduct an airfield condition survey
- Update the AIRPAV database & software
- Develop a 5-year airfield M&R work plan
- Report findings to INDOT

### 1.2 Description of Tasks Performed

#### 1.2.1 Records Review

A detailed records review was performed to determine the airport’s construction history and the as-built cross section for each pavement feature. Plan sets for recent projects were provided to ARA in computer-aided design and drafting (CADD) format. Older plans sets were provided as hard copies or in portable electronic document (PDF) format.

### 1.2.2 Define Pavement Network

Prior to the field survey, a pavement network map was developed using available aerial photography and construction plans. The map was divided into facilities, features, and sample units. A facility is defined as a complete area of the airfield that is used for a particular type of operation. Facilities are typically named for complete functional elements of pavement, such as Runway 11-29, Taxiway A, or North Terminal Apron. After facilities are defined, they are divided into features based on pavement type, construction, structure, and usage. Note that the terms branch and section may be used interchangeably with facility and feature throughout this report.

Features are divided into sample units as prescribed by ASTM D5340-12, *Standard Test Method for Airport Pavement Condition Index Surveys*. A sample unit is a subdivision of a section used exclusively to aid in the inspection process and reduce the effort needed to determine distress quantities and the PCI. The specified sample unit size for an asphalt concrete (AC) pavement is  $5,000 \text{ ft}^2 \pm 2,000 \text{ ft}^2$ . Sample units on portland cement concrete (PCC) pavements contain  $20 \pm 8$  slabs.

To allow users to search, sort, and identify airport pavement quickly, a numbering system is used in conjunction with the facility, feature, and sample unit convention. The format starts with facility, then feature, and finally identifies the sample unit. The number 1605.300 is parsed as an example in Figure 1-1. Most pavement references in this report are presented in this format.

Using statistical sampling methods, the PCI procedure provides a high confidence level in evaluating overall pavement condition while sampling only a portion of the pavement surface. Figure 1-2 shows the network-level inspection density used on this project. Where appropriate, “additional sample units” were identified and inspected to record pavement areas with distress patterns not representative of the overall pavement condition. The unique distress types documented in additional sample units are not extrapolated across the entire feature.

As the surveyors inspected the pavement, they were mindful to ensure that the pre-survey airfield map depicted the actual pavement, otherwise known as a “ground-truth” survey. Noticeable differences between what was present in the field and what was displayed on the maps were adjusted by a CADD technician.




Figure 1-1. Pavement Numbering System

Table 1-2. Inspection Density

Sample Unit in Feature	Inspected Sample Units
1-2	ALL
3-4	2
5-7	3
8-10	4
11-14	5
15-19	6
20-25	7
26-30	8
31-37	9
38-45	10
46-55	11
56-80	12
> 80	15%

### 1.2.3 Conduct Airfield Condition Survey

The pavement condition surveys were performed in accordance with ASTM D5340-12. The procedure is based on the identification and measurement of visible distress at the pavement surface. Each PCI distress will deduct from the pavement's perfect condition of 100. Using pavement management software (or curves provided in ASTM D5340-12), a deduct value is determined for each combination of distress type, severity, and measured quantity. The PCI value is then determined from the unique combination of these variables.

A primary benefit of the PCI procedure is the ability to perform objective evaluations and compare pavement condition with an easy-to-understand numerical rating. Because the combined impact of multiple distresses is not cumulative, ASTM D5340-12 provides an additional family of curves to adjust for multiple distresses. The PCI is determined by applying the individual deduct value for each distress type along with any required correction factors to account for multiple distress types.

Figure 1-2 shows the relationship between PCI values, descriptive ratings, and typical repair actions. Generally, pavement maintenance is most cost-effective when the pavement is still in satisfactory condition. Rehabilitation, such as an asphalt mill and inlay, is typically performed for pavements with PCI values between 55 and 70. When the PCI value drops below 55, a mill an inlay may not provide the desired performance and complete reconstruction often becomes the most cost-effective means of repairing the pavement.




Figure 1-2. PCI Value and Descriptive Rating

#### **1.2.4 Update AIRPAV Database & Software**

The network definition, construction history, and data from the survey were entered into the AIRPAV pavement management system (APMS) software. After all data were entered, family curves were developed to model the change in pavement condition over time. These family curves are used to estimate future pavement condition. Typically, several curves are developed, with separate curves defined for different pavement surface types, such as AC, PCC, asphalt overlay on existing asphalt (ACC), and asphalt overlay on existing concrete (APC). The latest version of AIRPAV containing all survey data, deterioration curves, M&R policies, budgets, and construction history, was provided to INDOT on CD-ROM.

#### **1.2.5 Develop 5-Year Airfield M&R Work Plans**

A 5-year capital improvement program (CIP) was developed showing the year that each pavement feature was expected to fall below the MSL. The 5-year plan detailed in chapter 3 shows rehabilitation alternatives for each feature based on the PCI and the individual distress types observed during the pavement evaluation. The timing of each project is shown as the year that the PCI falls below the MSL and does not consider other important factors. Using reports like this for each airport in the State, INDOT engineers and planners develop a final 5-year statewide CIP plan that balances the sometimes conflicting priorities of pavement condition, operational constraints, construction staging considerations, and available funding.

#### **1.2.6 Report Finding to INDOT**

This report includes background information, PCI results and recommendations, and M&R budget scenarios. Photographs depicting typical pavement conditions observed during the survey are included in chapter 2. Appendix A contains general information about the AIRPAV pavement management software. Appendix B provides an analysis of each pavement section based on recorded distress. Appendix C contains a summary of general maintenance techniques and best practices. Appendix D provides a detailed summary of the airfield pavement condition. Appendix E describes common airfield distress types, and Appendix F contains exhibits to help the airport owner manage the airfield pavement system.



## 2. Pavement Condition Evaluation

### 2.1 Overview

Using statistical sampling methods, approximately 810,000 square feet of airside pavement was surveyed as part of this assessment. The average inspected PCI for all pavements was 83 (Satisfactory). The average inspected PCI for the runways, taxiways, and ramps were as follows: 84 (Satisfactory), 78 (Satisfactory), and 87 (Good). Table 2-1 provides a general description of the PCI rating categories, including a simplified rating scale of Good, Fair, and Poor. This table also shows the associated distress levels and general M&R requirements for each rating category.

Table 2-1. Definition and Distribution of PCI Ratings

Simplified PCI Rating	PCI Range	Definition	Pavement Area (ft <sup>2</sup> )	Pavement Area (%)
Good	86-100	GOOD: Pavement has minor or no distresses and requires only routine maintenance.	2,241,009	61
	71-85	SATISFACTORY: Pavement has scattered low-severity distresses that need only routine maintenance.	592,150	16
Fair	56-70	FAIR: Pavement has a combination of generally low- and medium-severity distresses. M&R needs are routine to major in the near future.	51,261	1
Poor	41-55	POOR: Pavement has low-, medium-, and high-severity distresses that probably cause some operational problems. Near-term maintenance and repair needs may range from routine up to a requirement for reconstruction.	694,527	19
	26-40	VERY POOR: Pavement has predominantly medium- and high-severity distresses that cause considerable maintenance and operational problems. Near-term maintenance and repair needs will be intensive in nature.	74,766	2
	11-25	SERIOUS: Pavement has mainly high-severity distresses that cause operational restrictions; immediate repairs are needed.	-	-
	0-10	FAILED: Pavement deterioration has progressed to the point that safe operations are no longer possible; complete reconstruction is required.	-	-

Seven pavement sections, representing approximately 21 percent of the total area, had a PCI rating of poor. While maintenance will be able to restore some many of these sections above the MSL, the life extension will be relatively short lived and more extensive rehabilitation will still be needed within the next 5 years.

The pavement within each of the PCI condition categories is shown in Figure 2-1. The inspected PCI is summarized by branch use in Figure 2-2, and the photographs in Figure 2-3 through Figure 2-7 provide examples of the condition categories.

COLUMBUS MUNICIPAL AIRPORT  
2013 PCI Inspection




Figure 2-1. Inspected Pavement Condition




Figure 2-2. Pavement Condition by Branch Use



Figure 2-3. Typical Good PCC Pavement (Feature 6105)



Figure 2-4. Typical Good AC Pavement (Feature 105)



Figure 2-5. Typical Fair AC Pavement (Feature 420)



Figure 2-6. Typical Poor AC Pavement (Feature 3003)



Figure 2-7. AC Swell (Feature 5005)

## 2.2 Distress Types and Frequency

The inspectors surveyed approximately 610,000 ft<sup>2</sup> of AC pavement. The frequency of each distress type is shown in Table 2-2. The most common distress types were longitudinal and transverse (L&T) cracking, alligator cracking, ravelling, and swell. L&T cracking and ravelling are climate-related distresses, and alligator cracking is a load related distress.

Table 2-2. Distress Frequency in AC Pavement

Distress	Sample Units	% Inspected Sample Units
L&T CRACKING	113	86
ALLIGATOR CRACKING	28	21
SWELL	25	19
RAVELING	23	17
JOINT REFLECTION	17	13
BLOCK CRACKING	16	12
PATCHING	7	5
RUTTING	1	1
SHOVING FROM PCC	1	1

The inspectors surveyed approximately 200,000 ft<sup>2</sup> of PCC pavement. The frequency of each distress type is shown in Table 2-3. Recorded distress types were small and large patches, shrinkage cracks, and LTD cracks.

Table 2-3. Distress Frequency in PCC Pavement

Distress	Sample Units	% Inspected Sample Units	Slabs	% Inspected Slabs
PATCHING SMALL	8	16	30	3
PATCHING LARGE	2	4	6	1
SHRINKAGE CRACKS	2	4	3	0
SCALING/CRAZING/MAP CRACK	1	2	2	0

## 2.3 PCI Summary

The branch and section PCI values are shown below, along with the surface type, area, and last year construction occurred.

Table 2-4. PCI Results

Branch ID	Branch PCI	Section	Surface	Area (sf)	Built	2010 PCI	2013 PCI
100	86	105	AC	133,959	2004	99	99
		114	AC	5,903	2010	100	88
		115	AC	76,312	1995	83	71
		120	AC	88,558	1997	83	78
		125	AC	115,358	1997	92	87
		140	AC	17,680	2010	100	87
		145	AC	11,850	2010	100	94
200	67	201	AC/PCC	20,676	1975	76	67
300	74	301	AC/PCC	28,266	1975	59	38
		310	AC/PCC	208,442	2001	84	79
		320	AC	159,417	2004	86	80
		325	AC/PCC	50,302	2001	58	45
		330	AC	59,421	2004	82	79
		340	AC	12,500	2010	100	94
400	89	401	AC/PCC	46,038	1975	47	44
		410	AC	189,719	2012	-	100
		420	AC	4,950	1988	62	57
		425	AC	15,568	2010	100	93
500	70	515	AC	25,635	1997	73	70
700	42	701	AC	103,762	1975	43	42
3000	87	3002	AC/PCC	37,981	1975	59	52
		3003	AC/PCC	46,500	1975	36	33
		3025	AC	411,675	2007	97	91
		3030	PCC	151,175	2007	96	93
		3035	PCC	25,560	2008	100	99
		3040	AC	156,938	2008	99	92
5000	54	5005	AC	456,444	1992	59	51
		5015	AC	30,124	2010	100	95
6100	100	6105	PCC	642,000	2010	100	100
		6110	PCC	321,000	2010	100	100

## 2.4 Analysis Commentary

The following pages provide a brief overview of the 2013 inspected pavement conditions for each facility. Comments are based primarily on the AIRPAV analysis but also include field notes and remarks from the pavement condition inspectors. Where appropriate, individual pavement sections are referenced within the larger facility.

Features 114 and 140, constructed in 2010, experienced a 12 and 13 point drop in PCI. It is expected that the deterioration rate will stabilize, but these features should be monitored for signs of additional pavement deterioration.

Feature 301 had a 21 point PCI drop since the last inspection due to the development of block cracking and medium severity L&T cracking. This pavement features is past the point where maintenance will be cost effective and should be considered for rehabilitation.

### 2.4.1 Runways

The runways consisted of 2 sections of AC pavement and 2 sections of PCC pavement. The runways had a total area of 1,449,568 ft<sup>2</sup> with an area-weighted average PCI of 84 (Good).

Table 2-5. Runway Condition Distribution

PCI Range	Rating	Number of Sections	Pavement Area (ft <sup>2</sup> )	Pavement Area (%)
100-71	Good	3	993,124	69
70-56	Fair	-	-	-
55-0	Poor	1	456,444	31

#### 2.4.1.1 Runway 14-32

Runway 14-32 consisted of 2 sections of AC pavement. The branch had a total area of 486,568 ft<sup>2</sup> with an area-weighted average PCI of 54 (Poor). The dominant distresses types were alligator cracking, L&T cracking, and swell.

#### 2.4.1.2 Runway 5-23

Runway 5-23 consisted of 2 sections of PCC pavement. The branch had a total area of 963,000 ft<sup>2</sup> with an area-weighted average PCI of 100 (Good). The runway was newly reconstructed at the time of inspection with nominal recorded distress.

## 2.4.2 Taxiways

The taxiways consisted of six branches containing 15 sections of AC and 5 sections of APC pavement. The total area of the taxiways was 1,374,316 <sup>2</sup>. The area-weighted average PCI was 78 (Good).

Table 2-6. Taxiway Condition Distribution

PCI Range	Rating	Number of Sections	Pavement Area (ft <sup>2</sup> )	Pavement Area (%)
100-71	Good	13	1,094,687	80
70-56	Fair	3	51,261	4
55-0	Poor	4	228,368	17

### 2.4.2.1 100 Series

The 100 series taxiways consisted of 7 sections of AC pavement. The branch had a total area of 449,620 ft<sup>2</sup> with an area-weighted average PCI of 86 (Good). The recorded distresses included L&T cracking, alligator cracking, and swell.

### 2.4.2.2 200 Series

The 200 series taxiways consisted of 1 sections of APC pavement. The branch had a total area of 20,676 ft<sup>2</sup> with an area-weighted average PCI of 67 (Fair). The recorded distresses included L&T cracking and joint reflective cracking.

### 2.4.2.3 300 Series

The 300 series taxiways consisted of 3 sections of AC and 3 sections of APC pavement. The branch had a total area of 518,348 ft<sup>2</sup> with a PCI of 74 (Good). The recorded distresses included alligator cracking, block cracking, L&T and joint reflective cracking, ravelling, patches, and swell.

### 2.4.2.4 400 Series

The 400 series taxiways consisted of 3 sections of AC and 1 section of APC pavement. The branch had a total area of 256,275 ft<sup>2</sup> with an area-weighted average PCI of 89 (Good). Dominant recorded distresses included L&T cracking, joint reflective cracking, and block cracking.

### 2.4.2.5 500 Series

The 500 series taxiways consisted of 1 section of AC pavement. The branch had a total area of 25,635 ft<sup>2</sup> with an area-weighted average PCI of 70 (Fair). The recorded distresses included L&T cracking, raveling, and swell.

### 2.4.2.6 700 Series

The 700 series taxiways consisted of 1 section of AC pavement. The branch had a total area of 103,762ft<sup>2</sup> with an area-weighted average PCI of 42 (Poor). The recorded distresses included alligator cracking, block cracking, L&T cracking, patching, raveling, and swell.

### 2.4.3 Aprons

The aprons consisted of 2 sections of AC pavement, 2 sections of APC pavement, and 2 sections of PCC pavement. The total area of apron pavements was 829,829 ft<sup>2</sup>, and the area-weighted average PCI was 87 (Good). The distribution of pavement area and sections by PCI range are shown in Table 2-7.

Table 2-7. Apron Condition Distribution

PCI Range	Rating	Number of Sections	Pavement Area (ft <sup>2</sup> )	Pavement Area (%)
100-71	Good	4	745,348	90
70-56	Fair	-	-	-
55-0	Poor	2	84,481	10

### **3. Capital Improvement Program**

---

#### **3.1 Analysis**

The individual feature analyses shown in appendix B document viable rehabilitation projects that address the causes of each pavement section failure while restoring the pavement to a condition above the desired MSL. The recommended timing of each improvement action is defined as the year that the pavement condition is projected to reach the MSL. By establishing benchmark MSL targets, it is possible to plan objectively for future needs against a standard set of performance criteria. This section categorizes the identified viable options into CIP strategies based on cost and expected service life.

The airport may find it desirable to adjust the timing of projects detailed in the CIP to meet fiscal and operational constraints. For example, if different sections of a runway were projected to reach the MSL in various years ranging from 2013 to 2015, it is not operationally feasible to stage rehabilitation over a 3-year period. Instead, runway rehabilitation would be programmed in a manner that balanced the need to minimize the length of the runway closure while maximizing the remaining service life.

#### **3.2 Cost Estimates**

Project costs were estimated based on the pavement area and the unit costs shown in Table 3-1 for specific M&R activities. Project costs are presented so planners and managers can compare the relative magnitude of funding required for various alternatives. The two-page AIRPAV feature analysis (see appendix B) provides cost estimates for each identified project. These cost estimates are for planning purposes only and do not constitute an engineering estimate.

Furthermore, these costs estimates represent the improvement of existing pavement structures and associated incidental work only. Other potential project line items, such as lighting, navigational aids, and drainage modifications are not included, and estimates for those items must be developed separately and incorporated into an overall project cost.

Typical examples of work that might be included in alternatives evaluated by AIRPAV are outlined on the following pages. These example projects would meet the requirements for each selected option; however, the descriptions are not intended to imply required, or even preferred, design configurations. Rehabilitation decisions, such as overlay thickness design, should be made in conjunction with engineering design analysis.

Table 3-1. Unit Costs

Rigid Pavement (PCC)	
Reconstruction	\$12.90 /sf
Slab Replacement & Full Depth Patching	\$12.48 /sf
Patching (Partial Depth)	\$16.70 /sf
Slab Repair & Overlay	\$4.69 /sf + \$0.41 /sf/in > 4"
Joint Seal Replacement	\$2.24 /lf
Joint Seal Repair	\$0.87 /lf
Undersealing	\$4.16 /sf
Flexible Pavement (AC)	
Reconstruction	\$5.36 /sf
Resurfacing	\$1.44 /sf
Structural Overlay	\$2.25 /sf + \$0.41 /sf/in > 4"
Surface Treatment	\$0.39 /sf
Patching	\$9.78 /lf
Crack Repair (Restorative)	\$1.24 /lf
Crack Repair (Sustaining)	\$0.85 /lf

### 3.2.1 Rigid Pavement Work Descriptions

The following descriptions provide additional information about the typical work items covered by the unit costs shown in Table 3-1.

#### 3.2.1.1 Reconstruction

Reconstruction is recommended when the pavement defects would not be corrected by less extensive measures. Unit prices assume removal of the existing pavement to the subgrade and reconstruction pavement with 8 inches of high strength PCC pavement on 6 inches of aggregate subbase.



#### 3.2.1.2 Repair and Overlay

This procedure usually consists of a crack and seat process, where the existing pavement is broken into segments of approximately 2 ft on a side by dropping a heavy breaker bar onto the pavement. Properly done, aggregate interlock between pavement segments is retained and reflective cracking is reduced. A flexible surface is then placed over the recycled PCC base.



### 3.2.1.3 Slab Replacement

Slab replacements are typically required for high-severity blow ups, scaling, and shattered slabs. Unit prices assume removal of the selected slab to the subgrade. Prepare subgrade to bearing strength equivalent to surrounding subgrade. Provide subbase support equivalent to existing and install load transfer steel as required. Place PCC pavement level with existing surface.



### 3.2.1.4 Patching (Partial Depth)

While partial depth patching is most commonly used to repair joint and corner spalls, it is effective for a wide variety of distress types. Saw cut and remove area of pavement to sound concrete above reinforcing steel. Treat existing concrete to ensure firm bond. Place PCC level with existing surface.



### 3.2.1.5 Joint Seal Replacement

Rout joints and cracks to a depth of at least 1-1/4 inches, clean joint wall surfaces to expose fresh vital concrete, install backing rope, and apply rubberized sealant meeting ASTM D3405 specification, or equivalent.



### 3.2.1.6 Joint Seal Repair

Press existing sealant into joint for use as backer material; apply joint sealant meeting ASTM D3405 specification, or equivalent.

### 3.2.1.7 Undersealing

Undersealing is used to repair faulting between slabs or when corner breaks have settled relative to the slab. High-pressure injection is used to force material into the underlying voids and continues until the settled pavement is restored to its original elevation. Several materials have been used for undersealing, including cement grout, asphalt slurries, and proprietary formulations of expansive Styrofoam.



### 3.2.2 Flexible Pavement Work Descriptions

#### 3.2.2.1 Reconstruction

Reconstruction is recommended when the pavement defects would not be corrected by less extensive measures. Unit prices assume removal of existing pavement to subgrade. Scarify and compact subgrade to 6-inch depth. Construct 4 inches of P401 AC surface course on 8 inches of aggregate base course.



#### 3.2.2.2 Resurfacing

Resurfacing assumes a nominal 2-inch asphalt mill and inlay on existing prepared pavement.



#### 3.2.2.3 Structural Overlay

Structural overlays are used to address load related distress or to increase pavement load bearing capacity. Apply a 4-inch AC overlay on existing prepared pavement. Add additional thickness as needed to achieve required strength.

#### 3.2.2.4 Surface Treatment

Apply a high-quality, penetrating rejuvenating sealer



#### 3.2.2.5 Patching

High-performance cold patching products can be used for short term repairs. Long-term patches should be made with plant mixed hot asphalt meeting FAA P401 specs.

#### 3.2.2.6 Crack Repair (Restorative)

Rout existing crack to a minimum depth of 1-1/4 inches, install backing rope and apply rubberized crack filler meeting ASTM D3405 specification.

#### 3.2.2.7 Crack Repair (Sustaining)

This is typically spot repairs of existing crack sealant.



### 3.3 Capital Improvement Strategies

Figure 3-1 shows a projection of the overall airport pavement condition for the next 10 years based on implementing one of three capital improvement strategies:

- No Action: No capital improvement action is undertaken
- Longest Life: The most comprehensive repair and longest life rehabilitation option
- Lowest Cost: The rehabilitation option with the projected lowest annual cost




Figure 3-1. Programmed CIP

The longest life CIP scenario is projected to cost approximately **\$1.9 million** over the next 10 years. The lowest annual cost scenario is projected to cost approximately **\$1.3 million** over the next 10 years. Examples of each capital improvement strategy and a complete listing of all viable capital projects are presented in Table 3-2 through Table 3-4.

Table 3-2. Most Comprehensive Repair

Feature	Built	Description	Action Yr	Work Item	Cost, \$
115	1995	TAXIWAY A	2023	Resurfacing	109,889
140	2010	TAXIWAY A3	2023	Resurfacing	25,459
201	1975	TAXIWAY D	2016	Structural Overlay	38,250
301	1975	CONNECTOR TAXIWAY	2013	Resurfacing	40,703
310	2001	TAXIWAY C	2022	Resurfacing	300,156
325	2001	TAXIWAY C	2013	Structural Overlay	93,058
401	1975	TAXIWAY D	2013	Structural Overlay	85,170
420	1988	TAXIWAY D	2014	Resurfacing	7,128
515	1997	TAXIWAY D	2023	Resurfacing	36,914
701	1975	TAXIWAY A4	2013	Structural Overlay	191,959
3002	1975	TERMINAL RAMP	2013	Resurfacing	54,692

Feature	Built	Description	Action Yr	Work Item	Cost, \$
3003	1975	TERMINAL RAMP	2013	Reconstruction	249,240
5005	1992	RUNWAY 14-32	2013	Resurfacing	657,279
				<b>Total</b>	<b>1,889,897</b>

Excludes the west ramp

Table 3-3. Lowest Annual Cost Repair

Feature	Built	Description	Action Yr	Work Item	Cost, \$
115	1995	TAXIWAY A	2023	Crack Repair	3,572
140	2010	TAXIWAY A3	2023	Crack Repair	683
201	1975	TAXIWAY D	2016	Structural Overlay	38,250
301	1975	CONNECTOR TAXIWAY	2013	Resurfacing	40,703
310	2001	TAXIWAY C	2022	Surface Treatment	85,002
325	2001	TAXIWAY C	2013	Structural Overlay	93,058
401	1975	TAXIWAY D	2013	Surface Treatment	23,560
420	1988	TAXIWAY D	2014	Resurfacing	7,128
515	1997	TAXIWAY D	2023	Resurfacing	36,914
701	1975	TAXIWAY A4	2013	Structural Overlay	191,959
3002	1975	TERMINAL RAMP	2013	Resurfacing	54,692
3003	1975	TERMINAL RAMP	2013	Structural Overlay	86,025
5005	1992	RUNWAY 14-32	2013	Resurfacing	657,279
				<b>Total</b>	<b>1,318,825</b>

Excludes the west ramp

Table 3-4. All Viable Options

Feature	Built	Description	Action Yr	Work Item	Cost, \$
105	2004	TAXIWAY E	2013	No Action	-
114	2010	TAXIWAY A	2013	No Action	-
115	1995	TAXIWAY A	2023	Crack Repair	3,572
115	1995	TAXIWAY A	2023	Resurfacing	109,889
120	1997	TAXIWAY A	2013	No Action	-
125	1997	TAXIWAY A	2013	No Action	-
140	2010	TAXIWAY A3	2023	Crack Repair	683
140	2010	TAXIWAY A3	2023	Resurfacing	25,459
145	2010	TAXIWAY A4	2013	No Action	-
201	1975	TAXIWAY D	2016	Crack Repair	2,235
201	1975	TAXIWAY D	2016	Structural Overlay	38,250
301	1975	CONNECTOR TAXIWAY	2013	Crack Repair	13,963
301	1975	CONNECTOR TAXIWAY	2013	Resurfacing	40,703
310	2001	TAXIWAY C	2022	Surface Treatment	85,002
310	2001	TAXIWAY C	2022	Crack Repair	16,570
310	2001	TAXIWAY C	2022	Resurfacing	300,156
320	2004	TAXIWAY B & B1	2013	No Action	-
325	2001	TAXIWAY C	2013	Surface Treatment	26,319
325	2001	TAXIWAY C	2013	Crack Repair	9,436

Feature	Built	Description	Action Yr	Work Item	Cost, \$
325	2001	TAXIWAY C	2013	Structural Overlay	93,058
330	2004	TAXIWAY C	2013	No Action	-
340	2010	TAXIWAY B	2013	No Action	-
401	1975	TAXIWAY D	2013	Surface Treatment	23,560
401	1975	TAXIWAY D	2013	Structural Overlay	85,170
410	2012	TAXIWAY D	2013	No Action	-
420	1988	TAXIWAY D	2014	Crack Repair	2,027
420	1988	TAXIWAY D	2014	Resurfacing	7,128
425	2010	TAXIWAY D	2013	No Action	-
515	1997	TAXIWAY D	2023	Surface Treatment	11,349
515	1997	TAXIWAY D	2023	Crack Repair	3,303
515	1997	TAXIWAY D	2023	Resurfacing	36,914
701	1975	TAXIWAY A4	2013	Surface Treatment	59,660
701	1975	TAXIWAY A4	2013	Structural Overlay	191,959
3002	1975	TERMINAL RAMP	2013	Surface Treatment	17,507
3002	1975	TERMINAL RAMP	2013	Crack Repair	14,933
3002	1975	TERMINAL RAMP	2013	Resurfacing	54,692
3003	1975	TERMINAL RAMP	2013	Structural Overlay	86,025
3003	1975	TERMINAL RAMP	2013	Surface Treatment	25,542
3003	1975	TERMINAL RAMP	2013	Reconstruction	249,240
3025	2007	TERMINAL RAMP	2013	No Action	-
3030	2007	TERMINAL RAMP	2013	No Action	-
3035	2008	TERMINAL RAMP	2013	No Action	-
3040	2008	TERMINAL RAMP	2013	No Action	-
5005	1992	RUNWAY 14-32	2013	Surface Treatment	218,189
5005	1992	RUNWAY 14-32	2013	Resurfacing	657,279
5015	2010	RUNWAY 14-32	2013	No Action	-
6105	2010	RUNWAY 5-23 WINGS	2013	No Action	-
6110	2010	RUNWAY 5-23 KEEL	2013	No Action	-

Excludes the west ramp



## 4. Maintenance Management Program

### 4.1 General Comments

Most pavement distress is classified by severity (low, medium, or high). As a general rule, high-severity distresses should be patched, and medium-severity distress should be sealed. A detailed matrix of recommended maintenance policies to address various distress types is provided near the end of this section.

#### 4.1.1 Inspected Crack Severity

Of the inspected pavement, 66 percent of the cracks were rated at low severity and require no maintenance beyond ongoing inspection and spot repair. About 34 percent of the cracks were rated at medium severity and would benefit from sealing and repair. None of the cracks were rated at high severity.

#### 4.1.2 Other Distress

In asphalt pavement, area measured distresses such as rutting, depressions, fatigue cracks, and ravelling were recorded at low severity levels 75 percent of the time, and medium severity 25 percent of the time.

### 4.2 Recommended Maintenance Actions

The following illustrations and tables show pavement areas that have maintenance and repair needs. Ongoing development of capital improvement projects may address some of these maintenance needs. To help budgeting and prevent duplication of effort, all pavement features recommended for maintenance should be compared to planned improvements prior to finalizing a maintenance program strategy.

Table 4-1. Recommend Maintenance Actions

Work Item	Quantity	Unit	Cost
AC PATCH	993	SF	8,614
AC RESTORATIVE CRACK REPAIR	169,673	LF	210,395
AC SUSTAINING CRACK REPAIR	3,987	LF	3,450
PCC PATCHING	37	SF	620
<b>Total:</b>			<b>\$ 223,079</b>

Excludes the west ramp

In the following tables, pavement features shown in **grey** text cannot be raised above MSL via maintenance alone, and need only be included in a maintenance plan to provide continued safety or serviceability until their programmed major rehabilitation is implemented.

Note that several features including 301, 325, 401, 701, and 3003 can be brought above the MSL with maintenance and are therefore not shown in grey. However, because of the very low PCI of these features, the maintenance efforts required to improve them to the MSL would be extensive and rehabilitation may provide a more cost effective long term repair strategy.

#### 4.2.1 Patching

Table 4-2. Recommend PCC Patching

Feature	Work Item	Amount	Insp. PCI	Change	Est. PCI
3030	PCC PATCHING	37 S.F.	93		93
EQUIPMENT: SAW, AIR COMPRESSOR, JACK HAMMER, MIXER, HAND TOOLS					
EST. MATERIALS: 1 CUBIC YARDS CONCRETE MIX					
EST. MATERIAL COST: \$98					
EST. CREW HOURS: 3.7					
EST. CREW COST: \$522					
<b>EST. PROJECT COST: \$620</b>					

Excludes the west ramp

Table 4-3. Recommend AC Patching

Feature	Work Item	Amount	Insp. PCI	Change	Est. PCI
115	AC PATCH	7	71	2	73
120	AC PATCH	504	78	0	78
320	AC PATCH	60	80	1	81
325	AC PATCH	50	45	4	49
3003	AC PATCH	209	33	15	48
5005	AC PATCH	162	51	4	55
	TOTAL:	993	S.F.		
EQUIPMENT: SAW, AIR COMPRESSOR, HEATING KETTLE, HAND TOOLS					
EST. MATERIALS: 12 TONS ASPHALT PATCH					
EST. MATERIAL COST: \$1,237					
EST. CREW HOURS: 28.4					
EST. CREW COST: \$7,376					
<b>EST. PROJECT COST: \$8,614</b>					

#### 4.2.2 Crack Seal

Table 4-4. Recommend AC Sustaining Crack Repair

Feature	Work Item	Amount	Insp. PCI	Change	Est. PCI
114	AC SUSTAINING CRACK REPAIR	21	88	N/A	88
140	AC SUSTAINING CRACK REPAIR	82	87	N/A	87
310	AC SUSTAINING CRACK REPAIR	2,004	79	N/A	79
420	AC SUSTAINING CRACK REPAIR	168	57	N/A	57
3002	AC SUSTAINING CRACK REPAIR	1,201	52	N/A	52
3040	AC SUSTAINING CRACK REPAIR	509	92	N/A	92
	TOTAL:	3,987	L.F.		
EQUIPMENT: AIR COMPRESSOR, HEATING KETTLE, HAND TOOLS					
EST. MATERIALS: 797 POUNDS ASTM D3405 SEALANT OR EQUIVALENT					
EST. MATERIAL COST: \$797					
EST. CREW HOURS: 17.3					
EST. CREW COST: \$2,652					
<b>EST. PROJECT COST: \$3,450</b>					

Table 4-5. Recommend AC Restorative Crack Repair

Feature	Work Item	Amount	Insp. PCI	Change	Est. PCI
115	AC RESTORATIVE CRACK REPAIR	2,876	71	5	76
120	AC RESTORATIVE CRACK REPAIR	2,131	78	14	92
125	AC RESTORATIVE CRACK REPAIR	1,880	87	7	94
201	AC RESTORATIVE CRACK REPAIR	1,803	67	9	76
301	AC RESTORATIVE CRACK REPAIR	9,225	38	18	56
320	AC RESTORATIVE CRACK REPAIR	5,704	80	7	87
325	AC RESTORATIVE CRACK REPAIR	7,610	45	15	60
330	AC RESTORATIVE CRACK REPAIR	2,234	79	8	87
401	AC RESTORATIVE CRACK REPAIR	11,726	44	10	54
515	AC RESTORATIVE CRACK REPAIR	2,664	70	4	74
701	AC RESTORATIVE CRACK REPAIR	19,038	42	9	51
3003	AC RESTORATIVE CRACK REPAIR	9,240	33	10	43
3025	AC RESTORATIVE CRACK REPAIR	8,787	91	2	93
5005	AC RESTORATIVE CRACK REPAIR	84,753	51	6	57
	TOTAL:	169,673	L.F.		
EQUIPMENT: AIR COMPRESSOR, HEATING KETTLE, HAND TOOLS					
EST. MATERIALS: 33,935 POUNDS ASTM D3405 SEALANT OR EQUIVALENT					
EST. MATERIAL COST: \$33,934					
EST. CREW HOURS: 848.4					
EST. CREW COST: \$176,460					
<b>EST. PROJECT COST: \$210,395</b>					

COLUMBUS MUNICIPAL AIRPORT  
2013 PCI Inspection




Figure 4-1. Recommended Maintenance

## 4.3 Pavement Deterioration

Before attempting maintenance and repairs, it helps to understand pavement performance and pavement deterioration. The factors that contribute most to deterioration are environmental, materials, and/or load related. Brief discussions of each are presented in the following sections.

### 4.3.1 *Environmental/Age-Related Deterioration*

Seasonal and daily temperature changes cause expansion and contraction of the pavement materials. The shear stresses created by expansion and contraction can cause transverse cracking in flexible pavement and mid-slab cracking in rigid pavement. Further, expansion and contraction will cause cracks, and rigid pavement joints, to open and close with changes in temperature.

Flexible pavement oxidizes as it ages, losing its lighter, volatile, components and becoming brittle with time. Surface treatments and seal coats are designed, in part, to provide a protective barrier and prevent this type of oxidation.

Subsurface water can have the greatest impact on pavement deterioration. A wet subgrade greatly reduces the ability of a pavement to support wheel loads, and the results often show up as rutting and cracking of flexible pavement. The fine materials in a wet base can be pumped up through the cracks and eventually result in a loss of support. This loss of support can be evidenced as corner breaks and faulting in rigid pavement. Moisture inside a pavement system expands when it freezes, creating stresses that cause the pavement surface to heave. Subsequent freeze-thaw cycles leave voids in the pavement structure that enable further rutting and breaking. Repeated freeze-thaw cycles eventually cause the pavement to disintegrate. Freeze-thaw deterioration requires frost-susceptible material, sub-zero temperatures, and water. If we remove one of these factors, freeze-thaw damage will not occur. One of the best ways to ensure pavement longevity is to provide drainage and keep it dry.

### 4.3.2 *Materials-Related Deterioration*

The pavement thickness and type of subgrade play a large role in the formation and spacing of transverse cracks. If the subgrade and base materials are smooth or rounded and allow for relatively free movement of the pavement surface, transverse cracks will often be spaced far apart (>60 feet). If the subgrade and base material are rough or angular and provide greater resistance to movement of the pavement surface, transverse cracks will be spaced more closely (<40 feet). The distance between transverse cracks also depends on the pavement thickness, as a thicker pavement can resist cracking for longer lengths. At general aviation airport pavements, around 50 feet is typical transverse crack spacing.

Aggregate is the biggest component of any pavement structure, and it is the contact between the aggregate particles that actually transfers the load and provides the strength. Aggregate durability and shape are major factors affecting pavement performance. Durability is the ability of the aggregate to perform satisfactorily over time and resist deterioration. Sharp, well-angled aggregates that interlock, compact densely, and resist movement are the most desirable.

In flexible pavement, the selection of asphalt cement can have a significant impact on pavement performance. Asphalt is visco-elastic, which means it is stiff at low temperatures and flows at high temperatures. With this in mind, we expect asphalt pavement to remain stiff on hot summer days to resist plastic deformation (rutting and shoving). In addition, we expect asphalt pavement to have

sufficient cold temperature flexible on cold winter days to resist transverse cracking. The proper selection of asphalt cement grade and maintaining adequate mix volumetrics (air voids, voids in the mineral aggregate, etc.) are key factors in the performance of flexible pavement.

As water freezes, it expands and occupies a greater volume than in a liquid state. In PCC pavement, interconnected, well-distributed air voids are required to allow for expansion of moisture with the PCC. PCC mixes with insufficient air entrainment are susceptible to freeze-thaw damage, as the expansive forces have been shown to cause concrete deterioration. Small, closely spaced, interconnected air voids provide the greatest degree of protection.

Asphalt paving mixes also require air voids, but for reasons different than for PCC pavement. When a well-constructed asphalt pavement is subjected to vehicle loading, it will nevertheless experience some minor secondary consolidation. Air voids allow for the safe movement of the asphalt binder within the mix. With insufficient air voids, the asphalt binder will migrate to the surface of the pavement—it will in essence, get squeezed out of the mix. This phenomenon is called flushing. In addition, these mixes become unstable and are prone to rutting in the wheel paths.


However, if the air voids become too high, air and water can penetrate the pavement, reducing both durability and flexibility. Air infiltration will accelerate oxidization of the binder, while water penetration will increase the moisture susceptibility of the mix (i.e., stripping of the asphalt cement from the aggregate). Air voids in flexible pavement should be kept low enough to prevent water and air from penetrating the asphalt layers, but high enough to minimize the potential of plastic deformation.

Regardless of whether the pavement binder is AC or PCC, binder materials are mixed with aggregate to coat all aggregate particles with a thin binder film. Durability of flexible asphalt pavement is increased with a thicker binder film, and the pavement becomes more resistant to age hardening; however, if the film is too thick, the asphalt acts like a lubricant, promoting ruts, shoving, and bleeding. Each asphalt mix should be customized for materials available locally.

With a concrete pavement, aggregate interlock supports the wheel loads, and the hydrated cement binder further interlocks the aggregate particles to inhibit all movement. “Hydration” is the term for the chemical reaction of portland cement with water. In the hydration process, dry cement particles react with water to form gels, and then crystals, that grow and bond with the aggregate and form a rigid interlocking structure. Hydration can continue for years, but much of the ultimate strength will be reached within 28 days. Hydration is a sensitive chemical process. Typically, any admixtures used to accelerate the hydration process will reduce durability, and admixture use should be considered carefully or avoided.

### 4.3.3 Load-Related Deterioration

As illustrated below, rigid and flexible pavements differ in the way loads are distributed. A concrete slab resists bending and transfers loads evenly, while an asphalt pavement is designed to bend, gradually spreading loads over wider areas.



Load-related cracks can start at the top or bottom of a pavement section. In asphalt sections, load-related (fatigue) cracks start at the bottom. If a load-related crack reaches the surface, it usually indicates structural deficiency. In rigid pavement, corner breaks are caused by tensile forces at the top of the slab, and the crack propagates downward. Mid-slab LTD cracks are distress examples resulting from tensile forces at the bottom of the slab.

Both wheel loads and environmental factors can cause spalls anytime there is movement between adjacent slabs. If non-compressible material (such as a small rock) is allowed into a joint, stresses will build up between adjacent slabs and can cause a spall. Keeping joint and crack sealant intact can help to reduce the infiltration of non-compressible material and minimize spalling.

## 4.4 Best Practices

### 4.4.1 Flexible Pavement

L&T cracks at medium severity should be filled with a good quality crack sealant material. High-severity cracks normally must be patched.

Cracks rated at low severity may be narrow unsealed cracks or sealed cracks up to 3 inches wide. The PCI procedure does not distinguish between narrow unfilled cracks and wider filled cracks. Some L&T cracks at low severity are included in the estimated sealing quantities and costs in this maintenance plan. In general, when medium- or high-severity cracking constitutes less than 25 percent of the total crack quantity, sustaining maintenance usually is more cost-effective. When 25 percent or more of the total crack quantity is at medium or high severity, a restorative program typically becomes more cost-effective.

Existing patches rated as medium and high severity should be replaced with new patches. Small areas (usually less than 100 square feet per patch) of alligator cracking and rutting at medium and high severity also may be repaired cost-effectively by patching. Larger patches should be considered if equipment can be made available to accomplish the work. Patching to repair up to 10 percent of the surface of a pavement feature that is otherwise serviceable can result in significant cost savings as compared to rehabilitation of the entire feature.

An example maintenance policy treatment matrix for flexible pavement is shown in Table 4-6. Examples of various maintenance techniques are provided in appendix C.

### 4.4.2 Rigid Pavement

Joint seal damage rated at medium and high severity should be repaired. If medium- and high-severity damage is limited to less than about 25 percent of the total joint length, sustaining maintenance is recommended. If medium- and high-severity damage exceeds 25 percent of the total joint length, the joint sealant should be removed and replaced under a restorative repair project.

LTD cracks at low and medium severity should be considered for sealing as part of the joint sealing project. High-severity LTD cracks require sealing, patching, or slab replacement, depending on the extent of deterioration.

Small patches are typically used to repair medium- and high-severity spalls or to replace deteriorated older patches. Restorative small patches are typically partial-depth repairs, usually to a maximum depth of 1/3 of the slab thickness. Large patches and corner breaks at medium and high severity should be repaired by full-depth large patches.

High-severity LTD cracks and shattered slabs are candidates for patching and slab replacement. Low-severity shattered slabs can be left in place pending further deterioration.

An example maintenance policy treatment matrix for rigid pavement is shown in Table 4-6. Examples of various maintenance techniques are provided in appendix C.

Table 4-6. General Maintenance Policy (AC)

Distress Type	Distress Severity	Maintenance Action
Alligator Cracking	Low	Crack Sealing - AC
	Medium	Patching - AC Deep
	High	Patching - AC Deep
Bleeding	N/A	Monitor
Depression	Low	Monitor
	Medium	Patching - AC Shallow
	High	Patching - AC Deep
Jet Blast	N/A	Patching - AC Shallow
Longitudinal, Transverse, Joint Reflective, & Block Cracking	Low	Monitor
	Medium	Crack Sealing - AC
	High	Patching - AC Deep
Oil Spill	N/A	Patching - AC Shallow
Patching	Low	Monitor
	Medium	Crack Sealing - AC
	High	Patching - AC Deep
Polished Aggregate	N/A	Monitor
Weathering / Raveling	Low	Monitor
	Medium	Surface Treatment
	High	Patching - AC Shallow
Rutting, Corrugation and Swell	Low	Monitor
	Medium	Patching - AC Deep
	High	Patching - AC Deep
Shoving	Low	Monitor
	Medium	Patching - AC Shallow
	High	Patching - AC Deep
Slippage Cracking	N/A	Patching - AC Shallow

Table 4-7. General Maintenance Policy (PCC)

Distress Type	Distress Severity	Maintenance Action
Blow Up	Low	Patching - PCC Partial Depth
	Medium	Slab Replacement - PCC
	High	Slab Replacement - PCC
Longitudinal, Transverse & Diagonal Cracking	Low	Monitor
	Medium	Crack Sealing - PCC
	High	Patching - PCC Full Depth
Durability Cracking	Low	Monitor
	Medium	Patching - PCC Full Depth
	High	Slab Replacement - PCC
Large Patch & Corner Break	Low	Monitor
	Medium	Patching - PCC Full Depth
	High	Patching - PCC Full Depth
Popout / Shrinkage Cracks	N/A	Monitor
Scaling	Low	Monitor
	Medium	Patching - PCC Partial Depth
	High	Slab Replacement - PCC
Faulting	Low	Monitor
	Medium	Grinding (Localized)
	High	Grinding (Localized)
Shattered Slab	Low	Monitor
	Medium	Crack Sealing - PCC
	High	Slab Replacement - PCC
Joint Spall, Corner Spall & Small Patch	Low	Monitor
	Medium	Patching - PCC Partial Depth
	High	Patching - PCC Partial Depth
Alkali Silica Reactivity	Low	Monitor
	Medium	Slab Replacement - PCC
	High	Slab Replacement - PCC

## **4.5 Pavement Repair Materials**

New pavement repair materials are introduced and improved regularly. This section provides information on products compatible with airport needs.

### **4.5.1 Joint and Crack Sealer**

Hot-poured, pressure-injected, polymeric rubberized asphalt sealant meeting ASTM D3405 specifications is suitable for most sealing requirements. This product is relatively inexpensive, durable, and suitable for both rigid and flexible pavements. Other, more expensive, hot-applied sealants that promise longer life are being developed for specialty applications. Twin component cold applied sealants also have been used with success. Contact your local distributor.

### **4.5.2 Flexible Pavement Patch**

High-performance plant mixed cold patching products that can be stockpiled on-site can be used for short term repairs to maintain safety. Long-term patches should be made with high-quality plant mixed hot asphalt having a ¾-inch maximum aggregate size and meeting Federal Aviation Administration (FAA) P401, or highest quality highway specifications. Low-quality packaged materials available from local hardware type stores should be avoided.

### **4.5.3 Rigid Pavement Patch**

Permanent patches in rigid pavement should be made with air-entrained concrete with 1-inch maximum size aggregate. If the area must be quickly opened to traffic, high early concrete should be considered. Concrete should have zero slump and a coarse texture. As with asphalt patches, low-quality packaged materials should be used only as temporary patches to maintain safety and service until a more permanent repair can be made.

## **4.6 Pavement Repair Equipment**

Many pavement repair and sealing products are available. Specialized tools and equipment help ensure high-quality repairs. This section discusses equipment compatible with airport needs.

### **4.6.1 Air Compressor**

Used to remove non-compressible sand and debris from prepared cracks and joints, the compressor should have a sustained capacity of 120 cubic feet per minute with a nozzle velocity of 100 psi. Trailer-mounted compressors typically have capacities in this range.

### **4.6.2 Concrete Saw**

A saw capable of making a minimum 3-inch-deep cut is required. The saw should be capable of making cuts in both asphalt and concrete. Gasoline-powered 5- to 25-hp wheel-mounted saws typically are preferred for this type of work, but electric and pneumatic tools also are available.

#### **4.6.3 Heating Kettle**

Applying sealant is the most time-consuming operation, and a sealing machine with heating and pressure application capabilities is a critical item in a successful sealing program. The capacity of the sealing equipment dictates the rate at which a crew progresses. For large sealing projects, a minimum 100-gallons/hour sustained capacity is recommended. The unit should be a double boiler type, with mechanical agitators or continuous recirculation. Kettle temperature must be monitored to ensure that the sealant is not “burned.” Overheating the sealant will prematurely age harden the material.

#### **4.6.4 Router**

A concrete saw can be used to prepare joints, but for random cracking, a mechanical router with a vertical impact mechanism is preferred. When cracks are being routed, this activity will dictate the speed of the crew. Crack routers in the 25-hp range are commonly used and are available from a variety of manufacturers.

#### **4.6.5 Sand Cleaner**

A sand blaster helps to clean loose particles and dust from prepared cracks. The unit must have sufficient force to expose fresh, vital pavement to bond with sealant and patching materials.

#### **4.6.6 Vibratory Roller or Plate Compactor**

Required to compact plant mixed and packaged patching materials properly. Small rollers are best for pothole type applications; plate compactors are best for large areas.

#### **4.6.7 Other Equipment**

Other general use equipment that can be helpful in a maintenance program includes bucket loaders, dump trucks, water tanks, and a power sweeper unit.

## Appendix A. AIRPAV Software

---

### The Software

Data analysis was performed using the AIRPAV pavement evaluation and management software. In addition to calculating and documenting PCI values, AIRPAV evaluates the collected inspection data and recommends rehabilitation actions that address the cause of pavement distress. AIRPAV can incorporate traffic and structural capacity evaluations into the pavement evaluation matrix, and AIRPAV also performs preliminary life cycle cost analysis of the various rehabilitation alternatives, providing guidance on the lowest annual cost repair strategy.



A complete database, along with an updated version of AIRPAV, is provided on INDOT computers for ongoing management of the INDOT pavement systems.

### *Capital Improvements*

AIRPAV creates interactive CIPs, providing the user with the ability to control unit costs, develop new projects, move projects between years, and even increase or decrease the scope and cost of individual projects.

## Maintenance

AIRPAV calculates and develops maintenance work orders organized by type of work. Maintenance work orders can be printed and issued directly to maintenance crews.

## Traffic

AIRPAV provides the ability to model aircraft ground movements. Traffic can be sorted by airline, aircraft type, destination gate or ramp, and runway used. The program graphically displays each taxi path, accumulates total operations, automatically determines design aircraft, and calculates structural overlay requirements for each pavement feature. The software can provide Pavement Classification Numbers (PCN) for each pavement feature or report results directly as inches of overlay required.

## Maps

AIRPAV permits viewing and printing of PCI maps. Inspection layout, pavement condition, and other views are available from within the software.

## Query

The AIRPAV query function is a powerful search tool that allows users to extract useful reports meeting various criteria. As examples, lists can be created for taxiway pavement, asphalt pavement, or areas below MSL at the time of inspection.

## Global Information System (GIS) Integration

AIRPAV is fully GIS-enabled. A single click in AIRPAV exports all data to an MS Access database that can be linked to shape files used in an ESRI product. In this way, virtually all data in the pavement management database can be accessed in GIS format.



## Appendix B. Feature Analysis


### Pavement Performance Models

Projected performance is determined by relating current pavement condition to expected pavement condition. Projected performance varies based on pavement type. There are four pavement types in Indiana: AC, PCC, ACC, and APC. Each pavement type has a unique deterioration curve, created by plotting all data for that group as PCI vs. age and then finding a performance curve to best fit the data. These curves represent the historic performance of pavement in the group and become the baseline for future projections. The baseline curves are modeled with a third order polynomial equation as shown below.

$$PCI = X(\text{Age})^3 + Y(\text{Age})^2 + Z(\text{Age}) + C$$

#### Current Condition (rotating the curves)


Starting with the baseline curve for comparison, current pavement condition is plotted, and the baseline curve is rotated to meet the current condition. The rotated curve provides the starting point for projecting the future pavement condition.



#### Advanced Analysis (accounting for distress)


Some types of pavement distress have a greater impact on pavement deterioration than others. Rutting and alligator (fatigue) cracking are major structural failures and can lead to rapid pavement deterioration. Other distress types, like L&T cracking, develop slowly over time and typically do not cause a significant deviation from the baseline curve.

After current condition is accounted for with the curve rotation, pavement distress is addressed in the advanced analysis by compressing or expanding the baseline curve to account for the expected rate of pavement deterioration.



**Projected PCI (near term vs. longer term)**

Projecting pavement condition with advanced analysis is a combination of rotating, expanding, and contracting the baseline curves. This projection method provides good short-term results for all pavement sections and fair long-term projections on pavement sections with conditions near the baseline model. The long-term accuracy of outlier data is discussed on the following page.




**Projected PCI (why some features have unexpected projections)**

Long-term PCI projections can be very useful for planning purposes. However, projections in excess of 10 years are well beyond the intended scope of the PCI procedure. FAA Advisory Circular 150/5380-6B establishes a maximum 3-year interval between detailed PCI surveys.

Curve rotation, expansion, and contraction are performed to produce the best possible accuracy of future pavement condition over the next 3 to 5 years. This methodology can overemphasize certain performance trends in the long term. This is especially true for outlier data, such as pavement features that are performing much better or worse than is typical.

The curve below shows an example of a performance trend being overemphasized in the long-term projection. Because the pavement feature is performing much better than the baseline curve, the long-term projection shows the pavement lasting an additional 30+ years before reaching the MSL. Rotation of the curve to provide the most accurate projection over 3 to 5 years has resulted in a long-term projection that is likely unrealistic.



When long-term projections such as this are encountered, airport managers should not rely on projections in excess of 10 years. Managers can be confident that the pavement is performing much better than average and will not require rehabilitation within the current 5-year CIP planning window. As new distress develops over time, future PCI surveys will determine the ideal timing for rehabilitation.

## Feature Analysis

As part of the PCI evaluation, a detailed analysis is presented for each airside pavement feature using the two-page format depicted below.

### Page 1

The first page of the analysis is a feature summary. Located near the top left-hand corner is the feature number and pavement description. Construction history and inspector comments are listed below, along with a photo of the pavement section if available. Distress totals recorded during the PCI survey are listed next, and an approximation of the cause of the pavement deterioration is shown at the bottom. If the pavement is projected to fall below the desired MSL during the next 12 years, the analysis year will be shown along with the optimum year for pavement rehabilitation.

AIRPAV

AIRPORT: BLOOMINGTON/MONROE COUNTY  
AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

**FEATURE: 5007**

ANALYSIS YEAR: 2011    **OPTIMIZED FOR: 2019**

PAVEMENT TYPE: AC  
FEATURE AREA: 1,278,750  
INSPECTED AREA: 40,000  
MINIMUM SERVICE LEVEL: 0.5

**DESCRIPTION: RUNWAY 17-35 KEEL**

INSPECTION DATE: 8-11-11  
FEATURE'S HIGH PCI: 72  
FEATURE'S LOW PCI: 59  
AVERAGE PCI: 69 GOOD  
ESTIMATED PCI IS: 65 in 2019

COMMENTS/HISTORY FOR FEATURE 5007, RUNWAY 17-35 KEEL

1989: 4" P401 / 5" P401 / 13" P209  
\*  
\*

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF ALL DISTRESS
ALLIGATOR CRACKING	LOW	66	2,199	S.F.	8.3
LONG & TRANS. CRACK	MED	995	31,808	L.F.	30.4
LONG & TRANS. CRACK	LOW	2,824	90,279	L.F.	34.8
RAVELING/WEATHERING	LOW	9,450	302,104	S.F.	26.3

BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS: 8 %  
 APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS: 52 %  
 APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS: 39 %

PAGE 1

**Description & Feature #** →


**Optimized Rehab Year** →

**Construction History** ←

**Distress Totals** ←

The second page is a graphic analysis of pavement deterioration. Pavement deterioration is forecast based on historic deterioration of similar Indiana pavement types. Remaining life is projected by stretching and rotating the baseline curves to fit the current condition determined from the PCI survey.

When pavement condition drops below the desired MSL, the software selects rehabilitation actions that address the cause of the pavement failure while restoring the pavement to a condition above the MSL. A NO ACTION recommendation indicates that the feature is expected to remain serviceable during the 12-year forecasting period without major repairs. NO ACTION recommendations do not diminish the need for regular maintenance.



**Recommended Actions**

**Graphic Analysis**

## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 105

DESCRIPTION: TAXIWAY E

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC +

FEATURE'S HIGH PCI: 100

FEATURE AREA: 133,959

FEATURE'S LOW PCI: 96

INSPECTED AREA: 35,000

AVERAGE PCI: 99 GOOD

MINIMUM SERVICE LEVEL: 55

ESTIMATED PCI IS: 92 in 2013

## COMMENTS/HISTORY FOR FEATURE 105, TAXIWAY E

2004 AC 7.5" P-401/8" P-209/8" P-154

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 105

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	LOW	53	202	L.F.	100

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 105

DESCRIPTION: TAXIWAY E

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC +

AVERAGE PCI AT INSPECTION: 99 GOOD

CONSTRUCTION YEAR: 2004

ESTIMATED PCI IS: 92 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 87

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 114	<b>DESCRIPTION:</b> TAXIWAY A
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC	<b>FEATURE'S HIGH PCI:</b> 89
<b>FEATURE AREA:</b> 5,903	<b>FEATURE'S LOW PCI:</b> 88
<b>INSPECTED AREA:</b> 5,600	<b>AVERAGE PCI:</b> 88 GOOD
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 88 in 2013

## COMMENTS/HISTORY FOR FEATURE 114, TAXIWAY A

2010: 2" P401 Mill and INlay  
 1995: 7" P401 ON 16" P209  
 \*  
 \*

## DISTRESS QUANTITIES FOR FEATURE 114

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	MED	8	8	L.F.	38.3
LONG.& TRANS. CRACK	LOW	131	138	L.F.	61.6

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 114

DESCRIPTION: TAXIWAY A

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 88 GOOD

CONSTRUCTION YEAR: 2010

ESTIMATED PCI IS: 88 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 91

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 115	<b>DESCRIPTION:</b> TAXIWAY A
<b>ANALYSIS YEAR:</b> 2013 <b>OPTIMIZED FOR:</b> 2023	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC	<b>FEATURE'S HIGH PCI:</b> 82
<b>FEATURE AREA:</b> 76,312	<b>FEATURE'S LOW PCI:</b> 63
<b>INSPECTED AREA:</b> 30,000	<b>AVERAGE PCI:</b> 71 SATISFACTORY
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 53 in 2023

## COMMENTS/HISTORY FOR FEATURE 115, TAXIWAY A

1995: 7" P401 ON 16" P209

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 115

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
ALLIGATOR CRACKING	LOW	301	765	S.F.	42.7
LONG.& TRANS. CRACK	HIGH	2	5	L.F.	3.1
LONG.& TRANS. CRACK	MED	615	1,564	L.F.	38.2
LONG.& TRANS. CRACK	LOW	516	1,312	L.F.	15.8

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	43 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	38 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	19 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 115

DESCRIPTION: TAXIWAY A

ANALYSIS YEAR: 2013 OPTIMIZED FOR: 2023

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 71 SATISFACTORY

CONSTRUCTION YEAR: 1995

ESTIMATED PCI IS: 53 in 2023


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 45

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$109,889	23 YEARS
▼	CRACK REPAIR	\$3,572	1 YEAR
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 120

DESCRIPTION: TAXIWAY A

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC +

FEATURE'S HIGH PCI: 84

FEATURE AREA: 88,558

FEATURE'S LOW PCI: 73

INSPECTED AREA: 30,000

AVERAGE PCI: 78 SATISFACTORY

MINIMUM SERVICE LEVEL: 55

ESTIMATED PCI IS: 78 in 2013

## COMMENTS/HISTORY FOR FEATURE 120, TAXIWAY A

1997: 1.5" P401 / 5.5" P401 / 16" P209

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 120

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	HIGH	114	336	L.F.	41.7
LONG.& TRANS. CRACK	MED	538	1,588	L.F.	47.1
LONG.& TRANS. CRACK	LOW	184	543	L.F.	11

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 120

DESCRIPTION: TAXIWAY A

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC +

AVERAGE PCI AT INSPECTION: 78 SATISFACTORY

CONSTRUCTION YEAR: 1997

ESTIMATED PCI IS: 78 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 79

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 125

DESCRIPTION: TAXIWAY A

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC +

FEATURE'S HIGH PCI: 98

FEATURE AREA: 115,358

FEATURE'S LOW PCI: 77

INSPECTED AREA: 30,000

AVERAGE PCI: 87 GOOD

MINIMUM SERVICE LEVEL: 55

ESTIMATED PCI IS: 87 in 2013

## COMMENTS/HISTORY FOR FEATURE 125, TAXIWAY A

1997: 1.5" P401 / 5.5" P401 / 16" P209

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 125

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	MED	328	1,261	L.F.	76.8
LONG.& TRANS. CRACK	LOW	161	619	L.F.	23.1

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 125

DESCRIPTION: TAXIWAY A

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC +

AVERAGE PCI AT INSPECTION: 87 GOOD

CONSTRUCTION YEAR: 1997

ESTIMATED PCI IS: 87 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 79

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 140	<b>DESCRIPTION:</b> TAXIWAY A3
<b>ANALYSIS YEAR:</b> 2013 <b>OPTIMIZED FOR:</b> 2023	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC	<b>FEATURE'S HIGH PCI:</b> 93
<b>FEATURE AREA:</b> 17,680	<b>FEATURE'S LOW PCI:</b> 85
<b>INSPECTED AREA:</b> 11,250	<b>AVERAGE PCI:</b> 87 GOOD
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 54 in 2023

## COMMENTS/HISTORY FOR FEATURE 140, TAXIWAY A3

2010: 2" P401 Mill and Inaly  
 1988 P401 ON  
 1975 3-5" P401 ON 1942 8-6-8" P501  
 \*

## DISTRESS QUANTITIES FOR FEATURE 140

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	MED	35	55	L.F.	34.2
LONG.& TRANS. CRACK	LOW	316	496	L.F.	59.9
SWELL	LOW	14	22	S.F.	5.7

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	69 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	31 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 140

DESCRIPTION: TAXIWAY A3

ANALYSIS YEAR: 2013 OPTIMIZED FOR: 2023

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 87 GOOD

CONSTRUCTION YEAR: 2010

ESTIMATED PCI IS: 54 in 2023


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 71

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$25,459	23 YEARS
▼	CRACK REPAIR	\$683	1 YEAR
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 145	<b>DESCRIPTION:</b> TAXIWAY A4
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC +	<b>FEATURE'S HIGH PCI:</b> 95
<b>FEATURE AREA:</b> 11,850	<b>FEATURE'S LOW PCI:</b> 93
<b>INSPECTED AREA:</b> 7,500	<b>AVERAGE PCI:</b> 94 GOOD
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 94 in 2013

## COMMENTS/HISTORY FOR FEATURE 145, TAXIWAY A4

2010: 2" P401 Mill and Inaly  
 1988 P401 ON  
 1975 4" P401 ON 5" P208  
 \*

## DISTRESS QUANTITIES FOR FEATURE 145

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF ALL DISTRESS
LONG.& TRANS. CRACK	LOW	126	199	L.F.	100

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 145

DESCRIPTION: TAXIWAY A4

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC +

AVERAGE PCI AT INSPECTION: 94 GOOD

CONSTRUCTION YEAR: 2010

ESTIMATED PCI IS: 94 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 95

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 201	<b>DESCRIPTION:</b> TAXIWAY D
<b>ANALYSIS YEAR:</b> 2013 <b>OPTIMIZED FOR:</b> 2016	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC on PCC	<b>FEATURE'S HIGH PCI:</b> 70
<b>FEATURE AREA:</b> 20,676	<b>FEATURE'S LOW PCI:</b> 65
<b>INSPECTED AREA:</b> 9,000	<b>AVERAGE PCI:</b> 67 FAIR
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 51 in 2016

## COMMENTS/HISTORY FOR FEATURE 201, TAXIWAY D

1975 3-5" P401 ON  
 1942 8-6-8" P501  
 \*  
 \*

## DISTRESS QUANTITIES FOR FEATURE 201

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
JOINT REF. CRACKING	MED	174	399	L.F.	34.5
JOINT REF. CRACKING	LOW	188	431	L.F.	13.9
LONG.& TRANS. CRACK	MED	243	558	L.F.	37.4
LONG.& TRANS. CRACK	LOW	181	415	L.F.	14

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	83 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	17 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 201

DESCRIPTION: TAXIWAY D

ANALYSIS YEAR: 2013 OPTIMIZED FOR: 2016

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC on PCC

AVERAGE PCI AT INSPECTION: 67 FAIR

CONSTRUCTION YEAR: 1975

ESTIMATED PCI IS: 51 in 2016


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 0

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	STRUCTURAL OVERLAY	\$38,250	18 YEARS
▼	CRACK REPAIR	\$2,235	1 YEAR
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 301

DESCRIPTION: CONNECTOR TAXIWAY

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC on PCC

FEATURE'S HIGH PCI: 40

FEATURE AREA: 28,266

FEATURE'S LOW PCI: 37

INSPECTED AREA: 7,875

AVERAGE PCI: 38 VERY POOR

MINIMUM SERVICE LEVEL: 55

ESTIMATED PCI IS: 38 in 2013

## COMMENTS/HISTORY FOR FEATURE 301, CONNECTOR TAXIWAY

1975 3-5" P401  
 1942 8-6-8" P501  
 \*  
 \*

## DISTRESS QUANTITIES FOR FEATURE 301

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF ALL DISTRESS
ALLIGATOR CRACKING	LOW	42	150	S.F.	10.8
BLOCK CRACKING	MED	1,185	4,253	S.F.	17.4
BLOCK CRACKING	LOW	705	2,530	S.F.	10.5
JOINT REF. CRACKING	MED	250	897	L.F.	10.5
JOINT REF. CRACKING	LOW	50	179	L.F.	1.6
LONG.& TRANS. CRACK	MED	522	1,873	L.F.	24.7
LONG.& TRANS. CRACK	LOW	1,182	4,242	L.F.	24

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS: 11 %  
 APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS: 45 %  
 APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS: 44 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 301

DESCRIPTION: CONNECTOR TAXIWAY

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC on PCC

AVERAGE PCI AT INSPECTION: 38 VERY POOR

CONSTRUCTION YEAR: 1975

ESTIMATED PCI IS: 38 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 0

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$40,703	18 YEARS
▼	CRACK REPAIR	\$13,963	1 YEAR
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 310

DESCRIPTION: TAXIWAY C

ANALYSIS YEAR: 2013 OPTIMIZED FOR: 2022

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC on PCC

FEATURE'S HIGH PCI: 83

FEATURE AREA: 208,442

FEATURE'S LOW PCI: 75

INSPECTED AREA: 45,000

AVERAGE PCI: 79 SATISFACTORY

MINIMUM SERVICE LEVEL: 55

ESTIMATED PCI IS: 54 in 2022

## COMMENTS/HISTORY FOR FEATURE 310, TAXIWAY C

2001: 1.5" P401 SURFACE ON 6" P401 BASE ON 6" RUBBLIZED PCC

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 310

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	MED	646	2,992	L.F.	45.2
LONG.& TRANS. CRACK	LOW	2,239	10,371	L.F.	53
RAVELING	LOW	55	254	S.F.	1.6

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	66 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	34 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 310

DESCRIPTION: TAXIWAY C

ANALYSIS YEAR: 2013 OPTIMIZED FOR: 2022

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC on PCC

AVERAGE PCI AT INSPECTION: 79 SATISFACTORY

CONSTRUCTION YEAR: 2001

ESTIMATED PCI IS: 54 in 2022


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 41

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$300,156	18 YEARS
▼	SURFACE TREATMENT	\$85,002	7 YEARS
◆	CRACK REPAIR	\$16,570	1 YEAR
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 320

DESCRIPTION: TAXIWAY B &amp; B1

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

FEATURE'S HIGH PCI: 86

FEATURE AREA: 159,417

FEATURE'S LOW PCI: 75

INSPECTED AREA: 47,000

AVERAGE PCI: 80 SATISFACTORY

MINIMUM SERVICE LEVEL: 55

ESTIMATED PCI IS: 80 in 2013

## COMMENTS/HISTORY FOR FEATURE 320, TAXIWAY B &amp; B1

2004: 1.5" P401 / 5.5" P401/ 8" P209 / 8" P154

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 320

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	HIGH	12	40	L.F.	4.8
LONG.& TRANS. CRACK	MED	829	2,811	L.F.	58.6
LONG.& TRANS. CRACK	LOW	853	2,893	L.F.	26.6
PATCH & UTILITY CUT	LOW	319	1,082	S.F.	9.8

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	7 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	63 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	30 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 320

DESCRIPTION: TAXIWAY B & B1

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 80 SATISFACTORY

CONSTRUCTION YEAR: 2004

ESTIMATED PCI IS: 80 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 78

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 325

DESCRIPTION: TAXIWAY C

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC on PCC

FEATURE'S HIGH PCI: 48

FEATURE AREA: 50,302

FEATURE'S LOW PCI: 37

INSPECTED AREA: 18,750

AVERAGE PCI: 45 POOR

MINIMUM SERVICE LEVEL: 55

ESTIMATED PCI IS: 45 in 2013

## COMMENTS/HISTORY FOR FEATURE 325, TAXIWAY C

2001: 1.5" P401 SURFACE ON 6" P401 BASE ON 6" RUBBLIZED PCC

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 325

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
ALLIGATOR CRACKING	MED	19	51	S.F.	5.1
ALLIGATOR CRACKING	LOW	2	5	S.F.	1.5
JOINT REF. CRACKING	MED	1,101	2,953	L.F.	33.5
JOINT REF. CRACKING	LOW	425	1,140	L.F.	6.5
LONG.& TRANS. CRACK	MED	914	2,452	L.F.	27.6
LONG.& TRANS. CRACK	LOW	397	1,065	L.F.	7.8
RAVELING	HIGH	9	24	S.F.	6.4
RAVELING	MED	250	670	S.F.	5.6
RAVELING	LOW	400	1,073	S.F.	3.3
SWELL	LOW	122	327	S.F.	2.3

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS: 7 %  
 APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS: 71 %  
 APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS: 22 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 325

DESCRIPTION: TAXIWAY C

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC on PCC

AVERAGE PCI AT INSPECTION: 45 POOR

CONSTRUCTION YEAR: 2001

ESTIMATED PCI IS: 45 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 70

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	STRUCTURAL OVERLAY	\$93,058	18 YEARS
▼	SURFACE TREATMENT	\$26,319	5 YEARS
◆	CRACK REPAIR	\$9,436	1 YEAR
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 330

DESCRIPTION: TAXIWAY C

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

FEATURE'S HIGH PCI: 82

FEATURE AREA: 59,421

FEATURE'S LOW PCI: 75

INSPECTED AREA: 28,000

AVERAGE PCI: 79 SATISFACTORY

MINIMUM SERVICE LEVEL: 55

ESTIMATED PCI IS: 79 in 2013

## COMMENTS/HISTORY FOR FEATURE 330, TAXIWAY C

2004: 1.5" P401 / 5.5" P401/ 8" P209 / 8" P154

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 330

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	MED	626	1,328	L.F.	67.1
LONG.& TRANS. CRACK	LOW	427	906	L.F.	25.2
PATCH & UTILITY CUT	LOW	98	208	S.F.	7.5

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	5 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	64 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	31 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 330

DESCRIPTION: TAXIWAY C

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 79 SATISFACTORY

CONSTRUCTION YEAR: 2004

ESTIMATED PCI IS: 79 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 78

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 340	<b>DESCRIPTION:</b> TAXIWAY B
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC	<b>FEATURE'S HIGH PCI:</b> 94
<b>FEATURE AREA:</b> 12,500	<b>FEATURE'S LOW PCI:</b> 94
<b>INSPECTED AREA:</b> 12,500	<b>AVERAGE PCI:</b> 94 GOOD
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 91 in 2013

## COMMENTS/HISTORY FOR FEATURE 340, TAXIWAY B

2010: 2" P401 Mill and Inaly on existing  
 2004: 1.5" P401 / 5.5" P401/ 8" P209 / 8" P154  
 \*  
 \*

## DISTRESS QUANTITIES FOR FEATURE 340

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	LOW	230	230	L.F.	100

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 340

DESCRIPTION: TAXIWAY B

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 94 GOOD

CONSTRUCTION YEAR: 2010

ESTIMATED PCI IS: 91 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 91

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 401	<b>DESCRIPTION:</b> TAXIWAY D
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC on PCC	<b>FEATURE'S HIGH PCI:</b> 49
<b>FEATURE AREA:</b> 46,038	<b>FEATURE'S LOW PCI:</b> 36
<b>INSPECTED AREA:</b> 22,500	<b>AVERAGE PCI:</b> 44 POOR
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 44 in 2013

## COMMENTS/HISTORY FOR FEATURE 401, TAXIWAY D

1987 - CRACKS SEALED  
 1975 - 3" BIT. OVERLAY  
 1942 - 8"-6"-8" PCC  
 \*

## DISTRESS QUANTITIES FOR FEATURE 401

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
BLOCK CRACKING	LOW	900	1,841	S.F.	4.2
JOINT REF. CRACKING	MED	1,745	3,570	L.F.	34.2
JOINT REF. CRACKING	LOW	1,130	2,312	L.F.	11.2
LONG.& TRANS. CRACK	MED	465	951	L.F.	14.6
LONG.& TRANS. CRACK	LOW	2,122	4,341	L.F.	22.2
RAVELING	HIGH	33	67	S.F.	2.9
RAVELING	LOW	465	951	S.F.	4.2
SWELL	MED	100	204	S.F.	3.8
SWELL	LOW	174	356	S.F.	2.4

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	79 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	21 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 401

DESCRIPTION: TAXIWAY D

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC on PCC

AVERAGE PCI AT INSPECTION: 44 POOR

CONSTRUCTION YEAR: 1975

ESTIMATED PCI IS: 44 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 0

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	STRUCTURAL OVERLAY	\$85,170	18 YEARS
▼	SURFACE TREATMENT	\$23,560	5 YEARS
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 410	<b>DESCRIPTION:</b> TAXIWAY D
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC	<b>FEATURE'S HIGH PCI:</b> 100
<b>FEATURE AREA:</b> 189,719	<b>FEATURE'S LOW PCI:</b> 100
<b>INSPECTED AREA:</b> 41,250	<b>AVERAGE PCI:</b> 100 GOOD
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 97 in 2013

## COMMENTS/HISTORY FOR FEATURE 410, TAXIWAY D

2012: 8" P401 / 20" P209 / 18" LT Subgrade

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 410

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
---------------	----------	-------------------	--------------------------	-------	----------------------------

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	0 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 410

DESCRIPTION: TAXIWAY D

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 100 GOOD

CONSTRUCTION YEAR: 2012

ESTIMATED PCI IS: 97 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 96

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 420	<b>DESCRIPTION:</b> TAXIWAY D
<b>ANALYSIS YEAR:</b> 2013 <b>OPTIMIZED FOR:</b> 2014	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC	<b>FEATURE'S HIGH PCI:</b> 57
<b>FEATURE AREA:</b> 4,950	<b>FEATURE'S LOW PCI:</b> 57
<b>INSPECTED AREA:</b> 4,950	<b>AVERAGE PCI:</b> 57 FAIR
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 55 in 2014

## COMMENTS/HISTORY FOR FEATURE 420, TAXIWAY D

1988 UNKNOWN P401 SECTION

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 420

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
BLOCK CRACKING	LOW	1,710	1,710	S.F.	36.6
LONG.& TRANS. CRACK	MED	250	250	L.F.	36.2
LONG.& TRANS. CRACK	LOW	359	359	L.F.	27

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	42 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	58 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 420

DESCRIPTION: TAXIWAY D

ANALYSIS YEAR: 2013 OPTIMIZED FOR: 2014

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 57 FAIR

CONSTRUCTION YEAR: 1988

ESTIMATED PCI IS: 55 in 2014


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 50

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$7,128	23 YEARS
▼	CRACK REPAIR	\$2,027	3 YEARS
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 425	<b>DESCRIPTION:</b> TAXIWAY D
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC	<b>FEATURE'S HIGH PCI:</b> 97
<b>FEATURE AREA:</b> 15,568	<b>FEATURE'S LOW PCI:</b> 88
<b>INSPECTED AREA:</b> 14,380	<b>AVERAGE PCI:</b> 93 GOOD
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 92 in 2013

## COMMENTS/HISTORY FOR FEATURE 425, TAXIWAY D

2010: 2" P401 Mill and Inlay  
 1988: UNKNOWN P401 SECTION  
 \*  
 \*

## DISTRESS QUANTITIES FOR FEATURE 425

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	LOW	299	323	L.F.	100

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 425

DESCRIPTION: TAXIWAY D

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 93 GOOD

CONSTRUCTION YEAR: 2010

ESTIMATED PCI IS: 92 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 91

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 515	<b>DESCRIPTION:</b> TAXIWAY D
<b>ANALYSIS YEAR:</b> 2013 <b>OPTIMIZED FOR:</b> 2023	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC	<b>FEATURE'S HIGH PCI:</b> 71
<b>FEATURE AREA:</b> 25,635	<b>FEATURE'S LOW PCI:</b> 69
<b>INSPECTED AREA:</b> 14,250	<b>AVERAGE PCI:</b> 70 FAIR
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 54 in 2023

## COMMENTS/HISTORY FOR FEATURE 515, TAXIWAY D

1997: AC Pavement Est.

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 515

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	MED	606	1,090	L.F.	54.8
LONG.& TRANS. CRACK	LOW	875	1,574	L.F.	40.9
RAVELING	LOW	10	18	S.F.	1.6
SWELL	LOW	45	80	S.F.	2.5

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %

AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 515

DESCRIPTION: TAXIWAY D

ANALYSIS YEAR: 2013 OPTIMIZED FOR: 2023

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 70 FAIR

CONSTRUCTION YEAR: 1997

ESTIMATED PCI IS: 54 in 2023


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 50

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$36,914	23 YEARS
▼	SURFACE TREATMENT	\$11,349	7 YEARS
◆	CRACK REPAIR	\$3,303	1 YEAR
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 701	<b>DESCRIPTION:</b> TAXIWAY A4
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC	<b>FEATURE'S HIGH PCI:</b> 48
<b>FEATURE AREA:</b> 103,762	<b>FEATURE'S LOW PCI:</b> 33
<b>INSPECTED AREA:</b> 31,500	<b>AVERAGE PCI:</b> 42 POOR
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 42 in 2013

## COMMENTS/HISTORY FOR FEATURE 701, TAXIWAY A4

1987 - CRACKS SEALED  
 1975 4" P401 ON 5" P208  
 \*  
 \*

## DISTRESS QUANTITIES FOR FEATURE 701

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF ALL DISTRESS
ALLIGATOR CRACKING	LOW	1,138	3,748	S.F.	29.8
BLOCK CRACKING	MED	6,300	20,752	S.F.	20.8
BLOCK CRACKING	LOW	5,890	19,401	S.F.	18.1
LONG.& TRANS. CRACK	MED	919	3,027	L.F.	17.1
LONG.& TRANS. CRACK	LOW	1,204	3,966	L.F.	10.7
PATCH & UTILITY CUT	MED	3	9	S.F.	.9
PATCH & UTILITY CUT	LOW	64	210	S.F.	.6
RAVELING	LOW	300	988	S.F.	1.1
SWELL	LOW	40	131	S.F.	.5

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	31 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	20 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	49 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 701

DESCRIPTION: TAXIWAY A4

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 42 POOR

CONSTRUCTION YEAR: 1975

ESTIMATED PCI IS: 42 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 6

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	STRUCTURAL OVERLAY	\$191,959	23 YEARS
▼	SURFACE TREATMENT	\$59,660	3 YEARS
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 3002	<b>DESCRIPTION:</b> TERMINAL RAMP
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC on PCC	<b>FEATURE'S HIGH PCI:</b> 58
<b>FEATURE AREA:</b> 37,981	<b>FEATURE'S LOW PCI:</b> 44
<b>INSPECTED AREA:</b> 18,800	<b>AVERAGE PCI:</b> 52 POOR
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 52 in 2013

## COMMENTS/HISTORY FOR FEATURE 3002, TERMINAL RAMP

1975 3" P401 ON  
 1942 - 8"-6"-8" PCC  
 \*  
 \*

## DISTRESS QUANTITIES FOR FEATURE 3002

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
ALLIGATOR CRACKING	LOW	13	26	S.F.	3.4
BLOCK CRACKING	MED	448	905	S.F.	6.5
BLOCK CRACKING	LOW	6,212	12,549	S.F.	27.9
LONG.& TRANS. CRACK	MED	807	1,630	L.F.	25
LONG.& TRANS. CRACK	LOW	1,159	2,341	L.F.	18.6
RAVELING	MED	200	404	S.F.	3.9
RAVELING	LOW	3,300	6,666	S.F.	14.4

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	3 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	35 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	61 %

AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3002

DESCRIPTION: TERMINAL RAMP

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC on PCC

AVERAGE PCI AT INSPECTION: 52 POOR

CONSTRUCTION YEAR: 1975

ESTIMATED PCI IS: 52 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 0

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$54,692	18 YEARS
▼	SURFACE TREATMENT	\$17,507	5 YEARS
◆	CRACK REPAIR	\$14,933	1 YEAR
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 3003	<b>DESCRIPTION:</b> TERMINAL RAMP
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC on PCC	<b>FEATURE'S HIGH PCI:</b> 39
<b>FEATURE AREA:</b> 46,500	<b>FEATURE'S LOW PCI:</b> 29
<b>INSPECTED AREA:</b> 20,000	<b>AVERAGE PCI:</b> 33 VERY POOR
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 33 in 2013

## COMMENTS/HISTORY FOR FEATURE 3003, TERMINAL RAMP

1993 - CRACKS SEALED  
 1975 3" P401 ON  
 1942 - 8"-6"-8" PCC  
 \*

## DISTRESS QUANTITIES FOR FEATURE 3003

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
ALLIGATOR CRACKING	MED	90	209	S.F.	9
ALLIGATOR CRACKING	LOW	710	1,650	S.F.	23.7
JOINT REF. CRACKING	MED	1,430	3,324	L.F.	24.5
JOINT REF. CRACKING	LOW	200	465	L.F.	2.2
LONG.& TRANS. CRACK	MED	1,140	2,650	L.F.	19.5
LONG.& TRANS. CRACK	LOW	1,205	2,801	L.F.	11.8
RAVELING	LOW	900	2,092	S.F.	4
SHOVING BY PCC SLAB	MED	100	232	S.F.	3.6
SWELL	LOW	110	255	S.F.	1.3

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	33 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	54 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	13 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3003

DESCRIPTION: TERMINAL RAMP

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC on PCC

AVERAGE PCI AT INSPECTION: 33 VERY POOR

CONSTRUCTION YEAR: 1975

ESTIMATED PCI IS: 33 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 0

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RECONSTRUCTION	\$249,240	24 YEARS
▼	STRUCTURAL OVERLAY	\$86,025	18 YEARS
◆	SURFACE TREATMENT	\$25,542	3 YEARS
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 3020	<b>DESCRIPTION:</b> WEST RAMP
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> PCC	<b>FEATURE'S HIGH PCI:</b> 35
<b>FEATURE AREA:</b> 1,600,264	<b>FEATURE'S LOW PCI:</b> 2
<b>INSPECTED AREA:</b> 187,500	<b>AVERAGE PCI:</b> 18 SERIOUS
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 18 in 2013

## COMMENTS/HISTORY FOR FEATURE 3020, WEST RAMP

1975 est P501 SECTION

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 3020

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
CORNER BREAK	HIGH	1	8	SLABS	.4
CORNER BREAK	MED	3	25	SLABS	.9
CORNER BREAK	LOW	3	25	SLABS	.6
LONG/TRAN/DIAG CRK.	HIGH	13	110	SLABS	6.6
LONG/TRAN/DIAG CRK.	MED	188	1,604	SLABS	33.9
LONG/TRAN/DIAG CRK.	LOW	24	204	SLABS	4.1
'D' CRACKING	MED	3	25	SLABS	.5
JOINT SEAL DAMAGE	HIGH	275	2,347	SLABS	7.7
PATCH<5 SF	MED	1	8	SLABS	.1
SCALING/CRAZING	HIGH	8	68	SLABS	5.4
SCALING/CRAZING	MED	6	51	SLABS	1.1
SCALING/CRAZING	LOW	3	25	SLABS	0
SETTLEMENT/FAULT	HIGH	7	59	SLABS	3.5
SETTLEMENT/FAULT	MED	12	102	SLABS	3.6
SETTLEMENT/FAULT	LOW	11	93	SLABS	1.9
DIVIDED SLAB	HIGH	2	17	SLABS	3.3
DIVIDED SLAB	MED	10	85	SLABS	6.7
DIVIDED SLAB	LOW	3	25	SLABS	1.1
SHRINKAGE CRACKS	N/A	1	8	SLABS	0
SPALLING-JOINTS	HIGH	29	247	SLABS	13.2
SPALLING-JOINTS	MED	5	42	SLABS	.8
SPALLING-CORNERS	HIGH	10	85	SLABS	2.2
SPALLING-CORNERS	MED	4	34	SLABS	.6
SPALLING-CORNERS	LOW	3	25	SLABS	.3

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	41 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	16 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	43 %

AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3020

DESCRIPTION: WEST RAMP

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: PCC

AVERAGE PCI AT INSPECTION: 18 SERIOUS

CONSTRUCTION YEAR: 1975

ESTIMATED PCI IS: 18 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 31

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RECONSTRUCTION	\$20,643,400	31 YEARS
▼	REPAIR AND/OR OVERLAY	\$8,817,454	18 YEARS
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3025

DESCRIPTION: TERMINAL RAMP

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC +

FEATURE'S HIGH PCI: 100

FEATURE AREA: 411,675

FEATURE'S LOW PCI: 78

INSPECTED AREA: 52,000

AVERAGE PCI: 91 GOOD

MINIMUM SERVICE LEVEL: 55

ESTIMATED PCI IS: 91 in 2013

## COMMENTS/HISTORY FOR FEATURE 3025, TERMINAL RAMP

2007: 8" P401 on 15" P209

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 3025

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	MED	288	2,280	L.F.	48.4
LONG.& TRANS. CRACK	LOW	822	6,507	L.F.	51.5

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3025

DESCRIPTION: TERMINAL RAMP

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC +

AVERAGE PCI AT INSPECTION: 91 GOOD

CONSTRUCTION YEAR: 2007

ESTIMATED PCI IS: 91 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 91

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 3030	<b>DESCRIPTION:</b> TERMINAL RAMP
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> PCC	<b>FEATURE'S HIGH PCI:</b> 100
<b>FEATURE AREA:</b> 151,175	<b>FEATURE'S LOW PCI:</b> 84
<b>INSPECTED AREA:</b> 40,500	<b>AVERAGE PCI:</b> 93 GOOD
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 93 in 2013

## COMMENTS/HISTORY FOR FEATURE 3030, TERMINAL RAMP

2007: 12" P501 on 6" Stabilized Base on comp. s.g.

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 3030

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
PATCH<5 SF	MED	2	7	SLABS	8.1
PATCH<5 SF	LOW	37	138	SLABS	39.1
PATCH>5 SF/UTIL.CUT	LOW	8	29	SLABS	31.3
SCALING/CRAZING	MED	2	7	SLABS	16.9
SHRINKAGE CRACKS	N/A	3	11	SLABS	4.2

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	10 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	56 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	34 %

AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3030

DESCRIPTION: TERMINAL RAMP

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: PCC

AVERAGE PCI AT INSPECTION: 93 GOOD

CONSTRUCTION YEAR: 2007

ESTIMATED PCI IS: 93 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 96

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 3035	<b>DESCRIPTION:</b> TERMINAL RAMP
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> PCC	<b>FEATURE'S HIGH PCI:</b> 100
<b>FEATURE AREA:</b> 25,560	<b>FEATURE'S LOW PCI:</b> 98
<b>INSPECTED AREA:</b> 14,400	<b>AVERAGE PCI:</b> 99 GOOD
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 99 in 2013

## COMMENTS/HISTORY FOR FEATURE 3035, TERMINAL RAMP

2008 12" P501 on 6" STABILIZED BASE on COMP. S.G.

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 3035

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
PATCH<5 SF	LOW	3	5	SLABS	100

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %

AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3035

DESCRIPTION: TERMINAL RAMP

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: PCC

AVERAGE PCI AT INSPECTION: 99 GOOD

CONSTRUCTION YEAR: 2008

ESTIMATED PCI IS: 99 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 96

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 3040	<b>DESCRIPTION:</b> TERMINAL RAMP
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC +	<b>FEATURE'S HIGH PCI:</b> 100
<b>FEATURE AREA:</b> 156,938	<b>FEATURE'S LOW PCI:</b> 80
<b>INSPECTED AREA:</b> 41,700	<b>AVERAGE PCI:</b> 92 GOOD
<b>MINIMUM SERVICE LEVEL:</b> 55	<b>ESTIMATED PCI IS:</b> 92 in 2013

## COMMENTS/HISTORY FOR FEATURE 3040, TERMINAL RAMP

2008 AC 8" P-401/ 15" P-209 IN THREE LIFTS

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 3040

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
LONG.& TRANS. CRACK	MED	54	203	L.F.	14.6
LONG.& TRANS. CRACK	LOW	848	3,191	L.F.	74.7
RUTTING	LOW	2	7	S.F.	10.6

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	7 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	63 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	30 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 3040

DESCRIPTION: TERMINAL RAMP

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC +

AVERAGE PCI AT INSPECTION: 92 GOOD

CONSTRUCTION YEAR: 2008

ESTIMATED PCI IS: 92 in 2013


MINIMUM SERVICE LEVEL: 55

NORMAL PCI FOR THIS AGE: 92

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 55		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 5005	<b>DESCRIPTION:</b> RUNWAY 14-32
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC	<b>FEATURE'S HIGH PCI:</b> 62
<b>FEATURE AREA:</b> 456,444	<b>FEATURE'S LOW PCI:</b> 31
<b>INSPECTED AREA:</b> 70,000	<b>AVERAGE PCI:</b> 51 POOR
<b>MINIMUM SERVICE LEVEL:</b> 60	<b>ESTIMATED PCI IS:</b> 51 in 2013

## COMMENTS/HISTORY FOR FEATURE 5005, RUNWAY 14-32

1992 UNKNOWN P401 SECTION

\*  
\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 5005

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
ALLIGATOR CRACKING	MED	16	104	S.F.	2.3
ALLIGATOR CRACKING	LOW	515	3,358	S.F.	16.4
BLOCK CRACKING	LOW	1,700	11,085	S.F.	2.2
LONG.& TRANS. CRACK	HIGH	6	39	L.F.	.6
LONG.& TRANS. CRACK	MED	4,963	32,361	L.F.	37.3
LONG.& TRANS. CRACK	LOW	7,525	49,067	L.F.	29.2
RAVELING	HIGH	25	163	S.F.	1.5
RAVELING	LOW	225	1,467	S.F.	.9
SWELL	HIGH	113	736	S.F.	3.4
SWELL	MED	72	469	S.F.	3
SWELL	LOW	457	2,979	S.F.	2.7

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	19 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	55 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	26 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 5005

DESCRIPTION: RUNWAY 14-32

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC

AVERAGE PCI AT INSPECTION: 51 POOR

CONSTRUCTION YEAR: 1992

ESTIMATED PCI IS: 51 in 2013


MINIMUM SERVICE LEVEL: 60

NORMAL PCI FOR THIS AGE: 60

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
▲	RESURFACING	\$657,279	20 YEARS
▼	SURFACE TREATMENT	\$218,189	5 YEARS
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 60		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 5015	<b>DESCRIPTION:</b> RUNWAY 14-32
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> AC +	<b>FEATURE'S HIGH PCI:</b> 100
<b>FEATURE AREA:</b> 30,124	<b>FEATURE'S LOW PCI:</b> 86
<b>INSPECTED AREA:</b> 15,000	<b>AVERAGE PCI:</b> 95 GOOD
<b>MINIMUM SERVICE LEVEL:</b> 60	<b>ESTIMATED PCI IS:</b> 95 in 2013

## COMMENTS/HISTORY FOR FEATURE 5015, RUNWAY 14-32

2010: 2" P401 Mill and INlay on Existing

1988: 8-11" P401 on 8" P501

\*

\*

## DISTRESS QUANTITIES FOR FEATURE 5015

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF ALL DISTRESS
LONG.& TRANS. CRACK	LOW	8	16	L.F.	23.7
SWELL	MED	18	36	S.F.	67
SWELL	LOW	4	8	S.F.	9.2

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	92 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	8 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 5015

DESCRIPTION: RUNWAY 14-32

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: AC +

AVERAGE PCI AT INSPECTION: 95 GOOD

CONSTRUCTION YEAR: 2010

ESTIMATED PCI IS: 95 in 2013


MINIMUM SERVICE LEVEL: 60

NORMAL PCI FOR THIS AGE: 95

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 60		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

<b>FEATURE:</b> 6105	<b>DESCRIPTION:</b> RUNWAY 5-23 WINGS
<b>ANALYSIS YEAR:</b> 2013	<b>INSPECTION DATE:</b> 8-12-13
<b>PAVEMENT TYPE:</b> PCC	<b>FEATURE'S HIGH PCI:</b> 100
<b>FEATURE AREA:</b> 642,000	<b>FEATURE'S LOW PCI:</b> 99
<b>INSPECTED AREA:</b> 101,250	<b>AVERAGE PCI:</b> 100 GOOD
<b>MINIMUM SERVICE LEVEL:</b> 60	<b>ESTIMATED PCI IS:</b> 100 in 2013

## COMMENTS/HISTORY FOR FEATURE 6105, RUNWAY 5-23 WINGS

2010: 10" P501 on Bond Breaker on Existing  
variable 8-13" P401 on 6-8" crack and seated PCC on 4-6" subbase


\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 6105

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
PATCH<5 SF	LOW	1	6	SLABS	100

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	67 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	33 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 6105

DESCRIPTION: RUNWAY 5-23 WINGS

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: PCC

AVERAGE PCI AT INSPECTION: 100 GOOD

CONSTRUCTION YEAR: 2010

ESTIMATED PCI IS: 100 in 2013


MINIMUM SERVICE LEVEL: 60

NORMAL PCI FOR THIS AGE: 98

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 60		

PROJECTED PERFORMANCE



## AIRPORT: COLUMBUS MUNICIPAL

## AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 6110

DESCRIPTION: RUNWAY 5-23 KEEL

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: PCC

FEATURE'S HIGH PCI: 100

FEATURE AREA: 321,000

FEATURE'S LOW PCI: 100

INSPECTED AREA: 48,750

AVERAGE PCI: 100 GOOD

MINIMUM SERVICE LEVEL: 60

ESTIMATED PCI IS: 100 in 2013

## COMMENTS/HISTORY FOR FEATURE 6110, RUNWAY 5-23 KEEL

2010: 10" P501 on Bond Breaker on Existing  
variable 8-13" P401 on 6-8" crack and seated PCC on 4-6" subbase

\*  
\*

## DISTRESS QUANTITIES FOR FEATURE 6110

DISTRESS TYPE	SEVERITY	MEASURED QUANTITY	ESTIMATED TOTAL QUANTITY	UNITS	PERCENTAGE OF All DISTRESS
---------------	----------	-------------------	--------------------------	-------	----------------------------

## BASIC DISTRESS CAUSES

APPROXIMATE AMOUNT OF DISTRESS RELATED TO LOAD ON THE PAVEMENT IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO MATERIALS PROBLEMS IN THE FEATURE IS:	0 %
APPROXIMATE AMOUNT OF DISTRESS RELATED TO AGE OF PAVEMENT AND TRAFFIC REPETITIONS IS:	0 %



AIRPORT: COLUMBUS MUNICIPAL

AIRPAV FEATURE ANALYSIS PROGRAM OUTPUT

FEATURE: 6110

DESCRIPTION: RUNWAY 5-23 KEEL

ANALYSIS YEAR: 2013

INSPECTION DATE: 8-12-13

PAVEMENT TYPE: PCC

AVERAGE PCI AT INSPECTION: 100 GOOD

CONSTRUCTION YEAR: 2010

ESTIMATED PCI IS: 100 in 2013


MINIMUM SERVICE LEVEL: 60

NORMAL PCI FOR THIS AGE: 98

THE FOLLOWING PROJECTS HAVE BEEN SELECTED AS VIABLE ALTERNATIVES

LEGEND	DESCRIPTION	COST	LIFE EXTENSION
●	NO ACTION	N/A	N/A
-	MINIMUM SERVICE LEVEL, CURRENTLY 60		

PROJECTED PERFORMANCE






## Appendix C. General Maintenance Techniques

### Crack Sealing

- Cracks over ¼ inches wide should be sealed.
- Cracks wider than 3 inches should be patched.
- Sealant depth above the backer rope should be equal to the width of the reservoir, or as recommended by the manufacturer.
- Routed cracks should be sand blasted, to prepare for bonding with the sealant.
- Clean cracks with compressed air prior to sealing.
- Backing material should always be placed into the cracks. Commercial products are available. Several sizes of rope should be available to accommodate various crack sizes.
- Apply sealant after placing the backer rope. Follow the manufacturer's instructions. Sealant should be applied to within ¼ inch of the pavement surface.
- The final activity is to clean the surrounding pavement areas. A vacuum sweeper works well for this. Allow the sealant time to set before using a broom.
- Consider hot-applied, pourable patch material for cracks > ½ inch and any subsidence or depressions.



## Overband Technique


An alternate crack sealing technique using the procedures outlined below.

### Material

- Blend grade 20 or equivalent asphalt cement and latex rubber at 5 percent by weight asphalt.
- Again, at 5 percent by weight of asphalt, add polyester fibers into agitator tank.
- Maintain blended asphalt temperature at least 20 degrees below flash point.
- Continuously recycle hot blended asphalt through pumps and hoses when heating kettle is in standby mode.


### Application

- Sealant should be applied to dry pavement, with ambient temperatures above 40 degrees.
- Cracks should be sand cleaned and blown free of debris immediately before sealing.
- Application of sealant immediately follows cleaning of the crack.
- Sealant should be pressure applied from a wand-type applicator with “overband” nozzle.
- Seat the sealant with a steel-wheeled roller immediately after placement.
- In wider cracks, a backer rope is recommended to limit material quantities required.




## Joint Repair (portland cement)

- Rout a reservoir for the sealant ½ inch wide and 1 inch deep.
- Cracks wider than ½ inch should have reservoirs ¼ inch wider than the crack. Reservoir height above backer rope should be less than reservoir width, or as recommended by manufacturer.
- Routed cracks should be cleaned to expose fresh, vital pavement on the vertical crack edge.
- Cracks should be cleaned to remove all sand, debris, and other materials from the crack.
- Backing material should be placed into the crack.
- Apply sealant to within ¼ inch of pavement surface, following manufacturer’s instructions.
- Clean the surrounding pavement area.





Typical failed joint sealant, w/ debris and incompressibles.

Clean joints exposing fresh, clean concrete and stone. Retain existing resevoir shape.



## Patching (bituminous material)


- Examine distressed area and mark patch outline.
- Cut patch area with saw, no less than 3 inches deep.
- Remove enclosed pavement, leaving the vertical sawed edges undamaged.
- Clean sides and bottom and blow out with compressed air
- Paint sides and bottom with rapid curing asphalt tack coat. Prevent pooling on bottom.
- Allow tack coat to cure until it reaches a gummy consistency.
- Place hot mixed asphalt concrete and mound slightly, allowing for compaction.
- Compact with vibratory roller or plate compactor, in layers no greater than 6 inches.



## Patching (pourable materials)

Hot-applied, pourable materials generally are used to repair deficiencies larger than can be repaired by sealants, but smaller than those where traditional techniques would be required. Suggested uses for this type of repair include cracks over 2 inches wide, potholes less than 4 inches deep, as a leveling for small depressions, as a cap for settled utility cuts, and as a skin patch for areas of alligator cracking.



- Examine and mark the patch outline. Boundaries should extend to sound pavement.
- Apply patch material to clean, dry surfaces.
- A heating lance to preheat or dry existing pavement is recommended in cold or wet conditions.
- Patch material should be poured into the area to be repaired and leveled as appropriate.
- Patch edges should be sealed after application to assure good adhesion, preventing surface moisture from migrating under patch edges.



## Patching (PCC)

The technique outlined here simulates a thin bonded PCC overlay. This procedure has been proven effective in service throughout the country.

- Examine and mark patch outline.
- Saw cut area to a depth of 2 inches. The enclosed area is then chipped or jack hammered to solid pavement, but not less than a 2-inch nominal depth.
- The sides and bottom are sand cleaned and air-blasted to expose vital, clean concrete.
- A 25 percent solution of muriatic acid is applied to all exposed surfaces within the patch.
- The muriatic acid solution is thoroughly flushed from the patch area with water.
- Compressed air is used to remove excess water from the area, but exposed concrete must be maintained in a moist condition.
- The sides and bottom of the area are then coated with approximately a 1/16-inch layer of cement grout applied at the consistency of paste. The grout acts as an adhesive to bond the fresh concrete to existing concrete.
- If the patch is adjacent to joints, the continuity of the joint must be maintained by placing inserts approximately the shape of the desired joint against the wall of the patch.
- Before concrete grout begins to dry, concrete is placed in the patch area and is compacted into position with hand tampers or a vibrating plate tamper.
- When the patch has been struck to the proper slope and elevation, a surface texture is applied to approximate the texture of adjacent pavement.
- Joint edges may be edged slightly to remove sharp edges. The patch should be covered with polyethylene or sprayed with a curing compound.
- Clean the surrounding pavement before concrete spillover has a chance to set up.
- The patch may be open to traffic in 72 hours.





## Appendix D. PCI Summary

The PCI summary provides an index of pavement conditions at the airport. The letter in the first column indicates the type of pavement, asphalt or portland cement. The last column lists the distress types found in each sample unit. The distress types are listed by a numbering code for each type of pavement, shown at the beginning of the summary.

AIRPAV						
CONDITION SURVEY SUMMARY						
AIRPORT: 417 GREENCASTLE-PUTNAM COUNTY				DATE: 12-30-2009		
"A" FLEXIBLE PAVEMENT DISTRESS CODES				"T" RIGID PAVEMENT DISTRESS CODES		
1. ALLIGATOR CRACKING 2. BLEEDING 3. BLOCK CRACKING 4. CORRUGATION 5. DEPRESSION 6. JET BLAST EROSION 7. JOINT REFL. CRACKING 8. LONG. & TRANS. CRACKING 9. OIL SPILL 10. PATCHING 11. POLISHED AGGREGATE 12. RAVELLING/WEATHERING 13. RUTTING 14. SHOIVING FROM PCC SLAB 15. SLIPPAGE CRACKING 16. SWELLING				1. BLOW UP 2. CORNER BREAK 3. LTD CRACKING 4. "D" CRACKING 5. JOINT SEAL DAMAGE 6. SMALL PATCH 7. LARGE PATCH 8. POPOUTS 9. PUMPING 10. SCALING-MAP CRACKING/CRAZING 11. FAULTING 12. SHATTERED SLAB 13. SHRINKAGE CRACKING 14. JOINT SPALLING 15. CORNER SPALLING		
FEATURE:	SAMPLE UNIT:	AREA:	DATE:	SURVEYED BY:	PCI:	DISTRESSES PRESENT:
	105 A	105.100	8-16-09	JB	83	8 12
	105 A	105.103	8-16-09	JB	79	8 12
	105 A	105.105	8-16-09	JB	63	5 8 10 12*
	105 A	105.106	8-16-09	AN	79	1 8
	105 A	105.109	8-16-09	AN	86	8
	105 A	105.112	8-16-09	AN	84	8 12
MEAN FEATURE PCI = 81 BASED ON A SAMPLED AREA OF 21250 SQUARE FEET - PCI SPREAD FOR FEATURE = 22.74 DESCRIPTION: TAXIWAY A						
	110 A	110.102	8-16-09	JB	100	
	110 A	110.106	8-16-09	JB	100	
	110 A	110.110	8-16-09	JB	100	
	110 A	110.112	8-16-09	JB	100	
	110 A	110.114	8-16-09	JB	100	
	110 A	110.118	8-16-09	JB	94	8
AVERAGE FEATURE PCI = 99 BASED ON A SAMPLED AREA OF 19250 SQUARE FEET - PCI SPREAD FOR FEATURE = 6.20 DESCRIPTION: TAXIWAY A						
	115 A	115.118	8-16-09	JB	94	8
	115 A	115.122	8-16-09	JB	95	8
	115 A	115.126	8-16-09	JB	96	8
	115 A	115.130	8-16-09	JB	96	8
	115 A	115.134	8-16-09	JB	96	8
	115 A	115.136	8-16-09	JB	94	8
	115 A	115.138	8-16-09	JB	96	8
	115 A	115.142	8-16-09	AN	93	8
AVERAGE FEATURE PCI = 95 BASED ON A SAMPLED AREA OF 26250 SQUARE FEET - PCI SPREAD FOR FEATURE = 3.38 DESCRIPTION: TAXIWAY A						
	210 A	210.200	8-16-09	AN	94	8
	210 A	210.201	8-16-09	AN	94	8
	210 A	210.202	8-16-09	AN	86	8
AVERAGE FEATURE PCI = 91 BASED ON A SAMPLED AREA OF 8190 SQUARE FEET - PCI SPREAD FOR FEATURE = 7.93 DESCRIPTION: CONNECTOR TAXIWAY B						

Sample units marked with an asterisk (\*) are additional sample units. Additional sample units do not represent the typical condition of surrounding sample units in the pavement features.

The PCI summary provides a quick overview of the pavement condition and consistency. Are the distress types similar? Do the individual sample units have consistent PCI ratings? Answering these questions is a start to understanding your dynamic pavement system.

## CONDITION SURVEY SUMMARY

AIRPORT: BAK COLUMBUS MUNICIPAL

DATE: 12-21-2013

## "A" FLEXIBLE PAVEMENT DISTRESS CODES

1. ALLIGATOR CRACKING
2. BLEEDING
3. BLOCK CRACKING
4. CORRUGATION
5. DEPRESSION
6. JET BLAST EROSION
7. JOINT REFL. CRACKING
8. LONG. & TRANS. CRACKING
9. OIL SPILL
10. PATCHING
11. POLISHED AGGREGATE
12. RAVELLING
13. RUTTING
14. SHOVING FROM PCC SLAB
15. SLIPPAGE CRACKING
16. SWELLING
17. WEATHERING

## "P" RIGID PAVEMENT DISTRESS CODES

1. BLOW UP
2. CORNER BREAK
3. LTD CRACKING
4. "D" CRACKING
5. JOINT SEAL DAMAGE
6. SMALL PATCH
7. LARGE PATCH
8. POPOUTS
9. PUMPING
10. SCALING/MAP CRACKING/CRAZING
11. FAULTING
12. SHATTERED SLAB
13. SHRINKAGE CRACKING
14. JOINT SPALLING
15. CORNER SPALLING
16. ALKALI SILICA REACTION

FEATURE:	SAMPLE UNIT:	AREA:	DATE:	SURVEYED BY:	PCI:	DISTRESSES PRESENT:
105 A	105.103	5000	8-12-13	ARA	100	
105 A	105.106	5000	8-12-13	ARA	100	
105 A	105.109	5000	8-12-13	ARA	100	
105 A	105.112	5000	8-12-13	EOJ	96	8
105 A	105.115	5000	8-12-13	EOJ	100	
105 A	105.118	5000	8-12-13	ARA	97	8
105 A	105.121	5000	8-12-13	EOJ	100	

AVERAGE FEATURE PCI = 99

BASED ON A SAMPLED AREA OF 35000 SQUARE FEET - PCI SPREAD FOR FEATURE = 4.36

DESCRIPTION: TAXIWAY E

114 A	114.100	2500	8-12-13	ARA	88	8
114 A	114.200	3100	8-12-13	ARA	89	8

AVERAGE FEATURE PCI = 88

BASED ON A SAMPLED AREA OF 5600 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.67

DESCRIPTION: TAXIWAY A

115 A	115.102	5000	8-12-13	ARA	63	1 8
115 A	115.103	5000	8-12-13	ARA	68	1 8
115 A	115.105	5000	8-12-13	ARA	70	1 8
115 A	115.107	5000	8-12-13	ARA	63	1 8
115 A	115.109	5000	8-12-13	ARA	82	8
115 A	115.111	5000	8-12-13	ARA	78	8

AVERAGE FEATURE PCI = 71

BASED ON A SAMPLED AREA OF 30000 SQUARE FEET - PCI SPREAD FOR FEATURE = 19.53

DESCRIPTION: TAXIWAY A

120 A	120.114	5000	8-12-13	ARA	84	8
120 A	120.116	5000	8-12-13	ARA	79	8
120 A	120.120	5000	8-12-13	ARA	73	8
120 A	120.123	5000	8-12-13	ARA	76	8
120 A	120.125	5000	8-12-13	ARA	75	8
120 A	120.126	5000	8-12-13	ARA	80	8

AVERAGE FEATURE PCI = 78

BASED ON A SAMPLED AREA OF 30000 SQUARE FEET - PCI SPREAD FOR FEATURE = 10.61

DESCRIPTION: TAXIWAY A

**FEATURE:            SAMPLE UNIT:            AREA:            DATE:            SURVEYED BY:            PCI:            DISTRESSES PRESENT:**

125 A	125.132	5000	8-12-13	ARA	89	8
125 A	125.135	5000	8-12-13	ARA	85	8
125 A	125.137	5000	8-12-13	ARA	98	8
125 A	125.139	5000	8-12-13	ARA	87	8
125 A	125.141	5000	8-12-13	ARA	87	8
125 A	125.146	5000	8-12-13	ARA	77	8

**AVERAGE FEATURE PCI = 87  
 BASED ON A SAMPLED AREA OF 30000 SQUARE FEET - PCI SPREAD FOR FEATURE = 20.72  
 DESCRIPTION: TAXIWAY A**

140 A	140.100	3750	8-12-13	ARA	93	8 16
140 A	140.101	3750	8-12-13	ARA	85	8 16
140 A	140.102	3750	8-12-13	ARA	85	8

**AVERAGE FEATURE PCI = 87  
 BASED ON A SAMPLED AREA OF 11250 SQUARE FEET - PCI SPREAD FOR FEATURE = 7.79  
 DESCRIPTION: TAXIWAY A3**

145 A	145.100	3750	8-12-13	ARA	95	8
145 A	145.102	3750	8-12-13	ARA	93	8

**AVERAGE FEATURE PCI = 94  
 BASED ON A SAMPLED AREA OF 7500 SQUARE FEET - PCI SPREAD FOR FEATURE = 2.39  
 DESCRIPTION: TAXIWAY A4**

201 A	201.132	4500	8-12-13	ARA	65	7 8
201 A	201.133	4500	8-12-13	ARA	70	7 8

**AVERAGE FEATURE PCI = 67  
 BASED ON A SAMPLED AREA OF 9000 SQUARE FEET - PCI SPREAD FOR FEATURE = 5.43  
 DESCRIPTION: TAXIWAY D**

301 A	301.198	2625	8-12-13	ARA	38	3 8
301 A	301.199	2625	8-12-13	ARA	37	1 7 8
301 A	301.200	2625	8-12-13	ARA	40	1 3 8

**AVERAGE FEATURE PCI = 38  
 BASED ON A SAMPLED AREA OF 7875 SQUARE FEET - PCI SPREAD FOR FEATURE = 2.62  
 DESCRIPTION: CONNECTOR TAXIWAY**

310 A	310.105	3750	8-12-13	ARA	78	8 12
310 A	310.110	3750	8-12-13	ARA	81	8
310 A	310.116	3750	8-12-13	ARA	78	8
310 A	310.120	3750	8-12-13	ARA	75	8
310 A	310.125	3750	8-12-13	ARA	80	8
310 A	310.129	3750	8-12-13	ARA	83	8
310 A	310.132	3750	8-12-13	ARA	76	8 12
310 A	310.133	3750	8-12-13	ARA	81	8
310 A	310.139	3750	8-12-13	ARA	80	8
310 A	310.145	3750	8-12-13	ARA	80	8
310 A	310.148	3750	8-12-13	ARA	81	8
310 A	310.153	3750	8-12-13	ARA	79	8

**AVERAGE FEATURE PCI = 79  
 BASED ON A SAMPLED AREA OF 45000 SQUARE FEET - PCI SPREAD FOR FEATURE = 7.94  
 DESCRIPTION: TAXIWAY C**

320 A	320.101	5000	8-12-13	ARA	76	8
320 A	320.105	5000	8-12-13	ARA	80	8 10
320 A	320.109	5000	8-12-13	ARA	75	8 10
320 A	320.112	5000	8-12-13	ARA	84	8
320 A	320.115	5000	8-12-13	ARA	80	8 10
320 A	320.118	5000	8-12-13	ARA	80	8
320 A	320.121	5000	8-12-13	ARA	81	8 10
320 A	320.124	5000	8-12-13	ARA	86	8
320 A	320.131	7000	8-12-13	ARA	78	8

**AVERAGE FEATURE PCI = 80  
 BASED ON A SAMPLED AREA OF 47000 SQUARE FEET - PCI SPREAD FOR FEATURE = 11.56  
 DESCRIPTION: TAXIWAY B & B1**

FEATURE:	SAMPLE UNIT:	AREA:	DATE:	SURVEYED BY:	PCI:	DISTRESSES PRESENT:
325 A	325.156	3750	8-12-13	ARA	48	1 7 8 16
325 A	325.159	3750	8-12-13	ARA	37	7 8 12 16
325 A	325.162	3750	8-12-13	ARA	44	7 8 12 16
325 A	325.165	3750	8-12-13	ARA	48	7 8 12
325 A	325.167	3750	8-12-13	ARA	47	7 8 12

**AVERAGE FEATURE PCI = 45**  
**BASED ON A SAMPLED AREA OF 18750 SQUARE FEET - PCI SPREAD FOR FEATURE = 11.56**  
**DESCRIPTION: TAXIWAY C**

330 A	330.101	7000	8-12-13	ARA	75	8 10
330 A	330.102	7000	8-12-13	ARA	82	8
330 A	330.104	7000	8-12-13	ARA	76	8 10
330 A	330.105	7000	8-12-13	ARA	82	8

**AVERAGE FEATURE PCI = 79**  
**BASED ON A SAMPLED AREA OF 28000 SQUARE FEET - PCI SPREAD FOR FEATURE = 7.50**  
**DESCRIPTION: TAXIWAY C**

340 A	340.127	6250	8-12-13	ARA	94	8
340 A	340.129	6250	8-12-13	ARA	94	8

**AVERAGE FEATURE PCI = 94**  
**BASED ON A SAMPLED AREA OF 12500 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.31**  
**DESCRIPTION: TAXIWAY B**

401 A	401.177	4500	8-12-13	ARA	47	7 8 12
401 A	401.180	4500	8-12-13	ARA	44	7 8 12 16
401 A	401.182	4500	8-12-13	ARA	49	7 8 12 16
401 A	401.185	4500	8-12-13	ARA	43	3 7 8 12 16
401 A	401.186	4500	8-12-13	ARA	36	7 8 12 16

**AVERAGE FEATURE PCI = 44**  
**BASED ON A SAMPLED AREA OF 22500 SQUARE FEET - PCI SPREAD FOR FEATURE = 13.12**  
**DESCRIPTION: TAXIWAY D**

410 A	410.106	3750	8-12-13	DMY	100	
410 A	410.110	3750	8-12-13	DMY	100	
410 A	410.115	3750	8-12-13	DMY	100	
410 A	410.120	3750	8-12-13	DMY	100	
410 A	410.125	3750	8-12-13	DMY	100	
410 A	410.130	3750	8-12-13	DMY	100	
410 A	410.135	3750	8-12-13	DMY	100	
410 A	410.140	3750	8-12-13	DMY	100	
410 A	410.145	3750	8-12-13	DMY	100	
410 A	410.150	3750	8-12-13	DMY	100	
410 A	410.153	3750	8-12-13	DMY	100	

**AVERAGE FEATURE PCI = 100**  
**BASED ON A SAMPLED AREA OF 41250 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.00**  
**DESCRIPTION: TAXIWAY D**

420 A	420.188	4950	8-12-13	ARA	57	3 8
-------	---------	------	---------	-----	----	-----

**AVERAGE FEATURE PCI = 57**  
**BASED ON A SAMPLED AREA OF 4950 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.00**  
**DESCRIPTION: TAXIWAY D**

425 A	425.100	6840	8-12-13	ARA	88	8
425 A	425.200	7540	8-12-13	ARA	97	8

**AVERAGE FEATURE PCI = 93**  
**BASED ON A SAMPLED AREA OF 14380 SQUARE FEET - PCI SPREAD FOR FEATURE = 8.89**  
**DESCRIPTION: TAXIWAY D**

515 A	515.127	4250	8-12-13	ARA	71	8 12
515 A	515.128	5000	8-12-13	ARA	70	8
515 A	515.228	5000	8-12-13	ARA	69	8 16

**AVERAGE FEATURE PCI = 70**  
**BASED ON A SAMPLED AREA OF 14250 SQUARE FEET - PCI SPREAD FOR FEATURE = 2.83**  
**DESCRIPTION: TAXIWAY D**

FEATURE:	SAMPLE UNIT:	AREA:	DATE:	SURVEYED BY:	PCI:	DISTRESSES PRESENT:
701 A	701.210	4500	8-12-13	ARA	46	1 3 8 16
701 A	701.211	4500	8-12-13	ARA	39	1 3 8
701 A	701.215	4500	8-12-13	ARA	42	1 3 8
701 A	701.220	4500	8-12-13	ARA	42	1 3 8
701 A	701.223	4500	8-12-13	ARA	48	1 3 8 12
701 A	701.225	4500	8-12-13	ARA	45	1 3 8
701 A	701.230	4500	8-12-13	ARA	33	1 3 8 10 16

**AVERAGE FEATURE PCI = 42**

**BASED ON A SAMPLED AREA OF 31500 SQUARE FEET - PCI SPREAD FOR FEATURE = 15.28**

**DESCRIPTION: TAXIWAY A4**

3002 A	3002.156	4700	8-12-13	EOJ	51	1 3 8 12
3002 A	3002.194	4700	8-12-13	EOJ	57	3 8 12
3002 A	3002.226	4700	8-12-13	EOJ	44	3 8 12
3002 A	3002.227	4700	8-12-13	EOJ	58	3 8 12

**AVERAGE FEATURE PCI = 52**

**BASED ON A SAMPLED AREA OF 18800 SQUARE FEET - PCI SPREAD FOR FEATURE = 13.85**

**DESCRIPTION: TERMINAL RAMP**

3003 A	3003.103	5000	8-12-13	DMY	35	1 7 8 12
3003 A	3003.134	5000	8-12-13	DMY	29	1 7 8 12 16
3003 A	3003.140	5000	8-12-13	DMY	29	1 7 8 12 16
3003 A	3003.142	5000	8-12-13	DMY	39	1 7 8 14

**AVERAGE FEATURE PCI = 33**

**BASED ON A SAMPLED AREA OF 20000 SQUARE FEET - PCI SPREAD FOR FEATURE = 9.48**

**DESCRIPTION: TERMINAL RAMP**

3020 P	3020.105	15625	8-12-13	DMY	2	3 5 10 11 14 15
3020 P	3020.107	15625	8-12-13	DMY	30	3 5 10 11 14
3020 P	3020.203	15625	8-12-13	DMY	19	2 3 5 6 12 14 15
3020 P	3020.206	15625	8-12-13	DMY	19	3 5 10 11 14

**AVERAGE FEATURE PCI = 17**

**BASED ON A SAMPLED AREA OF 62500 SQUARE FEET - PCI SPREAD FOR FEATURE = 28.30**

**DESCRIPTION: WEST RAMP**

3025 A	3025.097	5000	8-12-13	ABN	98	8
3025 A	3025.105	5000	8-12-13	ABN	78	8
3025 A	3025.208	2750	8-12-13	ABN	100	
3025 A	3025.306	4000	8-12-13	ABN	84	8
3025 A	3025.310	4750	8-12-13	EOJ	89	8
3025 A	3025.405	4500	8-12-13	ABN	95	8
3025 A	3025.408	2750	8-12-13	ABN	100	
3025 A	3025.510	4750	8-12-13	EOJ	93	8
3025 A	3025.606	4000	8-12-13	ABN	89	8
3025 A	3025.705	4500	8-12-13	ABN	98	8
3025 A	3025.808	5000	8-12-13	ABN	85	8
3025 A	3025.810	5000	8-12-13	ABN	86	8

**AVERAGE FEATURE PCI = 91**

**BASED ON A SAMPLED AREA OF 52000 SQUARE FEET - PCI SPREAD FOR FEATURE = 21.94**

**DESCRIPTION: TERMINAL RAMP**

3030 P	3030.201	5400	8-12-13	EOJ	84	6 7
3030 P	3030.203	5400	8-12-13	EOJ	84	6 7 13
3030 P	3030.301	4500	8-12-13	EOJ	99	6
3030 P	3030.304	4500	8-12-13	EOJ	85	6 7 10
3030 P	3030.401	4500	8-12-13	EOJ	99	6
3030 P	3030.502	4500	8-12-13	EOJ	95	6 13
3030 P	3030.600	5400	8-12-13	EOJ	98	6
3030 P	3030.702	6300	8-12-13	EOJ	100	

**AVERAGE FEATURE PCI = 93**

**BASED ON A SAMPLED AREA OF 40500 SQUARE FEET - PCI SPREAD FOR FEATURE = 16.02**

**DESCRIPTION: TERMINAL RAMP**

**FEATURE:            SAMPLE UNIT:            AREA:            DATE:            SURVEYED BY:            PCI:            DISTRESSES PRESENT:**

3035 P	3035.100	5400	8-12-13	EOJ	98	6
3035 P	3035.102	5400	8-12-13	EOJ	100	
3035 P	3035.104	3600	8-12-13	EOJ	100	

**AVERAGE FEATURE PCI = 99  
 BASED ON A SAMPLED AREA OF 14400 SQUARE FEET - PCI SPREAD FOR FEATURE = 1.65  
 DESCRIPTION: TERMINAL RAMP**

3040 A	3040.102	5000	8-12-13	ABN	91	8
3040 A	3040.200	5000	8-12-13	ABN	100	
3040 A	3040.203	5000	8-12-13	ABN	90	8
3040 A	3040.301	3350	8-12-13	ABN	97	8
3040 A	3040.400	5000	8-12-13	ABN	100	
3040 A	3040.501	3350	8-12-13	ABN	96	8
3040 A	3040.503	5000	8-12-13	ABN	90	8
3040 A	3040.700	5000	8-12-13	ABN	84	8
3040 A	3040.703	5000	8-12-13	ABN	80	8 13

**AVERAGE FEATURE PCI = 92  
 BASED ON A SAMPLED AREA OF 41700 SQUARE FEET - PCI SPREAD FOR FEATURE = 20.27  
 DESCRIPTION: TERMINAL RAMP**

5005 A	5005.104	5000	8-12-13	ARA	54	1 8 16
5005 A	5005.109	5000	8-12-13	ARA	47	1 8 16
5005 A	5005.115	5000	8-12-13	ARA	62	8 16
5005 A	5005.126	5000	8-12-13	ARA	31	1 8 12 16
5005 A	5005.131	5000	8-12-13	ARA	54	8 12 16
5005 A	5005.139	5000	8-12-13	ARA	42	1 8 12 16
5005 A	5005.156	5000	8-12-13	ARA	52	3 8 16
5005 A	5005.162	5000	8-12-13	ARA	46	1 8 16
5005 A	5005.168	5000	8-12-13	ARA	48	1 8
5005 A	5005.174	5000	8-12-13	ARA	58	1 8
5005 A	5005.180	5000	8-12-13	ARA	54	1 8
5005 A	5005.186	5000	8-12-13	ARA	59	8 16
5005 A	5005.192	5000	8-12-13	ARA	45	1 8 16
5005 A	5005.198	5000	8-12-13	ARA	60	8

**AVERAGE FEATURE PCI = 51  
 BASED ON A SAMPLED AREA OF 70000 SQUARE FEET - PCI SPREAD FOR FEATURE = 31.75  
 DESCRIPTION: RUNWAY 14-32**

5015 A	5015.145	5000	8-12-13	ARA	98	8
5015 A	5015.146	5000	8-12-13	ARA	86	8 16
5015 A	5015.152	5000	8-12-13	ARA	100	

**AVERAGE FEATURE PCI = 95  
 BASED ON A SAMPLED AREA OF 15000 SQUARE FEET - PCI SPREAD FOR FEATURE = 14.47  
 DESCRIPTION: RUNWAY 14-32**

6105 P	6105.106	3750	8-12-13	ARA	100	
6105 P	6105.112	3750	8-12-13	ARA	100	
6105 P	6105.118	3750	8-12-13	ARA	100	
6105 P	6105.124	3750	8-12-13	ARA	100	
6105 P	6105.130	3750	8-12-13	ARA	100	
6105 P	6105.136	3750	8-12-13	ARA	100	
6105 P	6105.142	3750	8-12-13	ARA	100	
6105 P	6105.148	3750	8-12-13	ARA	100	
6105 P	6105.154	3750	8-12-13	ARA	100	
6105 P	6105.155	3750	8-12-13	ARA	99	6
6105 P	6105.160	3750	8-12-13	ARA	100	
6105 P	6105.166	3750	8-12-13	ARA	100	
6105 P	6105.172	3750	8-12-13	ARA	100	
6105 P	6105.178	3750	8-12-13	ARA	100	
6105 P	6105.506	3750	8-12-13	ARA	100	
6105 P	6105.512	3750	8-12-13	ARA	100	
6105 P	6105.518	3750	8-12-13	ARA	100	
6105 P	6105.524	3750	8-12-13	ARA	100	
6105 P	6105.530	3750	8-12-13	ARA	100	
6105 P	6105.536	3750	8-12-13	ARA	100	

FEATURE:	SAMPLE UNIT:	AREA:	DATE:	SURVEYED BY:	PCI:	DISTRESSES PRESENT:
6105 P	6105.542	3750	8-12-13	ARA	100	
6105 P	6105.548	3750	8-12-13	ARA	100	
6105 P	6105.554	3750	8-12-13	ARA	100	
6105 P	6105.560	3750	8-12-13	ARA	100	
6105 P	6105.566	3750	8-12-13	ARA	100	
6105 P	6105.572	3750	8-12-13	ARA	100	
6105 P	6105.578	3750	8-12-13	ARA	100	

**AVERAGE FEATURE PCI = 100**

**BASED ON A SAMPLED AREA OF 101250 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.53**

**DESCRIPTION: RUNWAY 5-23 WINGS**

6110 P	6110.307	3750	8-12-13	EOJ	100	
6110 P	6110.313	3750	8-12-13	EOJ	100	
6110 P	6110.319	3750	8-12-13	EOJ	100	
6110 P	6110.325	3750	8-12-13	EOJ	100	
6110 P	6110.331	3750	8-12-13	EOJ	100	
6110 P	6110.337	3750	8-12-13	EOJ	100	
6110 P	6110.343	3750	8-12-13	EOJ	100	
6110 P	6110.349	3750	8-12-13	EOJ	100	
6110 P	6110.355	3750	8-12-13	EOJ	100	
6110 P	6110.361	3750	8-12-13	EOJ	100	
6110 P	6110.367	3750	8-12-13	EOJ	100	
6110 P	6110.373	3750	8-12-13	EOJ	100	
6110 P	6110.379	3750	8-12-13	EOJ	100	

**AVERAGE FEATURE PCI = 100**

**BASED ON A SAMPLED AREA OF 48750 SQUARE FEET - PCI SPREAD FOR FEATURE = 0.00**

**DESCRIPTION: RUNWAY 5-23 KEEL**

**TOTAL NUMBER OF INSPECTED FEATURES = 31**

**TOTAL NUMBER OF INSPECTED SAMPLE UNITS = 199**

**TOTAL AREA OF INSPECTED PAVEMENT = 931,205 S.F.**

\* INDICATES "ADDITIONAL" SAMPLE UNITS.



## Appendix E. Distress Identification

This chapter describes pavement distress types commonly identified during airport PCI inspections.

### Rigid Pavement Distress

#### *Longitudinal, Transverse & Diagonal Cracking*

LTD cracking is often a result of load or temperature deformations. External loads cause flexure. Temperature changes can cause curling. When any of these stresses exceed the slab strength, cracking occurs.

LTD cracking is recorded at low, medium, or high severity, depending on the width of crack opening and degree of deterioration.

At low severity, a crack is less than 1/8 inch wide with little spalling, and no corrective action is indicated. At medium severity, LTD cracks can be up to 1 inch wide with moderate spalling and should be repaired using procedures similar to joint sealing. At high severity, cracks exceed 1 inch in width and may be severely spalled. High-severity LTD cracking is evidence of serious load failure, and correction may require patching or slab replacement. If distress occurs in several adjacent slabs at medium or high severity, major rehabilitation of that area is indicated.

A slab divided into four or more pieces is said to be “divided” or “shattered.” Shattered slab is a separate distress category and indicates a significant structural failure. A shattered slab has lost its ability to distribute loads. Shattered slabs are rated in three severities, but the recommended action in any case is slab replacement.



### Shrinkage Cracking

Shrinkage cracks are small, non-working cracks visible at the pavement surface but not penetrating the full depth of concrete. Shrinkage cracks most commonly occur shortly after construction due to concrete shrinkage during the curing process.

Shrinkage cracks are usually so small that they are not visible until staining or loss of material at crack edges begins to take place. Shrinkage cracks do not represent structural weakness, and no corrective action is prescribed.



### Durability Cracking

Durability cracking (D-cracking) is caused by environmental factors, the most common being freeze/thaw. D-cracking usually appears as either a pattern of hairline cracks running parallel to a joint or crack, or in a corner, where water tends to collect. D-cracking eventually leads to disintegration of the pavement, creating foreign object damage (FOD) potential.

At low severity, D-cracking is evident, but no disintegration has occurred. Medium severity is evident over a significant area of the slab, and some disintegration and FOD potential exist. High-severity D-cracking is evidenced by extensive cracking with loose and missing pieces and significant FOD potential.



### *Joint Spall and Corner Spall*

Spalls at slab joints and corners are caused by excessive internal stress in the pavement. Spalls occur when these stresses exceed the shear strength of the concrete.

Spalling usually results from thermal expansion during hot weather when slabs push and expand against one another. If the joints are filled with incompressible material, such as sand, stresses can become severe, causing spalls. Spalling can be reduced significantly by maintenance of joint sealant.

Spall repair requires patching. The extent and severity of spalling suggests the appropriate action. At low severity, spalled concrete remains securely in place in the slab. A low-severity spall should be monitored closely for further deterioration and should be patched when spalled particles become loose, or during the next scheduled patching activity. Medium- and high-severity spalls should be repaired immediately to prevent FOD. If the pavement can be restored to serviceable condition, spalls should be patched for long-term service. If the pavement is beyond repair, temporary patching should be considered to control FOD.



### *Patches, Large and Small*

Large and small patches, by PCI inspection criteria, are distress conditions. Patches indicate deterioration and aging of pavement that contributes to shortened service life. However, patching also indicates that pavement is being maintained.

A patch that is performing well and shows no outward distress is recorded at low severity, and no corrective action is required. Medium-severity patches are serviceable but are beginning to deteriorate. Maintenance or replacement is indicated. At high severity, replacement is indicated.

By definition, small patches are smaller than 5 square feet in surface area, and they usually result from spall repair at slab joints and corners.

Large patches also may be the result of spall repair, but they often indicate more serious deficiencies, such as corner breaks or other full-depth failure smaller than panel size.



## Joint Seal Damage

When joint sealant is in perfect condition (no damage), there is no distress.

At low severity, at least 10 percent of the sealant is debonded but still in contact with the joint edges. Medium-severity joint seal damage is recorded when at least 10 percent of the sealant has visible gaps smaller than 1/8 inch and is an indicator that replacement should be programmed as soon as is practical. In the meantime, aggressive inspection and sustaining maintenance is recommended to minimize subsurface damage from moisture penetration. At high severity, visible gaps exceed 1/8 inch, and the amount and degree of joint seal damage typically requires complete removal and replacement of the existing sealant.

On serviceable pavement, deteriorated joint sealant should be repaired or replaced to preserve pavement and subgrade integrity and prolong service life. The issue is not so clear-cut with unserviceable pavement. Pavement that can be restored to serviceable condition by maintenance activities such as patching and joint seal repair, or by slab replacement, should be so maintained as long as the process is cost-effective. However, when age and condition preclude economical return to serviceable condition by such means, joint seal repair would no longer be cost-effective and should be suspended except for an interim maintenance program to control FOD potential.



## Flexible Pavement Distress

### *Longitudinal & Trans. Cracking*

L&T cracks are caused by age, construction, and subsurface conditions. Age-related cracking occurs as oxidizing pavement loses components to the atmosphere and becomes more brittle. Consistent application of seal coats can help to prevent age-related cracks.

Construction-related cracking often develops along paving joints. Ensuring that joints are made when both sides are still hot, and near the same temperature, is one of the best ways to mitigate this potential problem.

Seasonal movement caused by changes in subsurface moisture or temperature differences also can cause pavement cracking. Asphalt pavement placed over a PCC pavement or cement stabilized base course may evidence reflective cracking from the underlying material. Wheel loads do not cause L&T cracks, although traffic may worsen their condition.

Low-severity L&T cracks are less than ¼ inch wide, or if sealed with suitable filler material in satisfactory condition can be any width less than 3 inches, if they are not spalled. Maintenance usually is not indicated for low-severity cracking. Moderately spalled cracks and cracks wider than ¼ inch which are not satisfactorily sealed are at medium severity. Medium-severity cracks should be sealed with a high-quality crack filling material. Severely spalled cracks and cracks wider than 3 inches are at high severity. High-severity L&T cracks normally require patching.



## Alligator Cracking

Alligator cracks are a series of interconnected load-related cracks caused by fatigue of the asphalt surface. Alligator cracking is a significant structural distress and develops only in places subject to traffic loads. These cracks typically initiate at the bottom of the asphalt layer and propagate upward. Once a fatigue crack is visible at the surface, significant damage has already occurred.

At low severity, alligator cracks are evidenced by a series of parallel hairline cracks (usually in a wheel path). Medium-severity alligator cracking is a well-defined pattern of interconnected cracks, and some spalling may be present. High-severity alligator cracks have lost aggregate interlock between adjacent pieces, and the cracks may be severely spalled with FOD potential. Most likely, the pieces will move freely under traffic.

Alligator cracking is a serious structural failure that cannot be repaired with sealant. The proper repair is patching.



### Raveling/Weathering

Raveling and weathering are the wearing away of the pavement surface. Failure can be caused by the dislodging of aggregate particles or the loss of asphalt binder. These distresses are usually evident over large areas and may indicate that the asphalt binder has hardened significantly.

Raveling is the loss of coarse aggregate, weathering is the loss of fine aggregate or binder.

Raveling: At low severity, 5 to 20 coarse aggregate particles are missing per square yard. Medium severity is defined by 20 to 40 missing coarse aggregate particles per square yard. At high severity, more than 40 coarse aggregate particles are missing per square yard, and the top layer of aggregate has eroded away.

Weathering: At low severity, edges of coarse aggregate are exposed less than 1 mm. At medium severity, loss of fine aggregate is noticeable and edges of coarse aggregate are exposed up to 6 mm (1/4 inch). High severity weathering has edges of coarse aggregate exposed > 6 mm, with considerable loss of fine aggregate matrix and potential for loss of coarse aggregate.



### Rutting

Ruts are localized areas of pavement having elevations lower than the surrounding sections.

Rutting is due to base and subgrade consolidation caused by excessive wheel loads or poor compaction. Ruts indicate structural failure and can cause hydroplaning.

At low severity, ruts have an average depth of ¼ to ½ inches. At medium severity, ruts have an average depth of ½ to 1 inch. At high severity, ruts have an average depth greater than 1 inch. Patching is the appropriate repair for ruts.



## Appendix F. Airport Responsibilities

### Grant Assurances

In 1995, Congress mandated that the FAA require, as a condition of grant funding, that airport sponsors prepare documentation of a maintenance management program on pavement that has been constructed, reconstructed, or repaired with Federal assistance.

This report fulfills many of the grant assurance requirements, including documenting:

- Locating all runways, taxiways, and aprons.
- Documenting pavement dimensions.
- Documenting types of pavement.
- Documenting year of construction or most recent major rehabilitation.

The airport owners must be an active participant in maintaining compliance. Actions taken to ensure compliance include:

- Annotating areas constructed or repaired with Federal aid.
- Conducting monthly drive-by inspections to detect changes in pavement condition.
- Recording each drive-by inspection and any maintenance performed as a result.
- Keeping complete records of all maintenance activities.
- Keeping records for 5 years.
- Documenting detailed inspection information with a history of recorded pavement deterioration by PCI survey (e.g., this report).

ASSURANCES Airport Sponsors	
<b>A. General.</b>	<ol style="list-style-type: none"> <li>1. These assurances shall be complied with in the performance of grant agreements for airport development, airport planning, and noise compatibility program grants for airport sponsors.</li> <li>2. These assurances are required to be submitted as part of the project application by sponsors requesting funds under the provisions of Title 49, U.S.C., subtitle VII, as amended. As used herein, the term "public agency sponsor" means a public agency with control of a public-use airport; the term "private sponsor" means a private owner of a public-use airport; and the term "sponsor" includes both public agency sponsors and private sponsors.</li> <li>3. Upon acceptance of the grant offer by the sponsor, these assurances are incorporated in and become part of the grant agreement.</li> </ol>
<b>B. Duration and Applicability.</b>	<ol style="list-style-type: none"> <li>1. <b>Airport development or Noise Compatibility Program Projects Undertaken by a Public Agency Sponsor.</b> The terms, conditions and assurances of the grant agreement shall remain in full force and effect throughout the useful life of the facilities developed or equipment acquired for an airport development or noise compatibility program project, or throughout the useful life of the project items installed within a facility under a noise compatibility program project, but in any event not to exceed twenty (20) years from the date of acceptance of a grant offer of Federal funds for the project. However, there shall be no limit on the duration of the assurances regarding Exclusive Rights and Airport Revenue so long as the airport is used as an airport. There shall be no limit on the duration of the terms, conditions, and assurances with respect to real property acquired with federal funds. Furthermore, the duration of the Civil Rights assurance shall be specified in the assurances.</li> <li>2. <b>Airport Development or Noise Compatibility Projects Undertaken by a Private Sponsor.</b> The preceding paragraph 1 also applies to a private sponsor except that the useful life of project items installed within a facility or the useful life of the facilities developed or equipment acquired under an airport development or noise compatibility program project shall be no less than ten (10) years from the date of acceptance of Federal aid for the project.</li> <li>3. <b>Airport Planning Undertaken by a Sponsor.</b> Unless otherwise specified in the grant agreement, only Assurances 1, 2, 3, 5, 6, 13, 18, 30, 32, 33, and 34 in section C apply to planning projects. The terms, conditions, and assurances of the grant agreement shall remain in full force and effect during the life of the project.</li> </ol>
<b>C. Sponsor Certification.</b>	<p>The sponsor hereby assures and certifies, with respect to this grant that:</p> <ol style="list-style-type: none"> <li>1. <b>General Federal Requirements.</b> It will comply with all applicable Federal laws, regulations, executive orders, policies, guidelines, and requirements as they relate to the application, acceptance and use of Federal funds for this project including but not limited to the following: <ul style="list-style-type: none"> <li><b>Federal Legislation</b> <ol style="list-style-type: none"> <li>a. Title 49, U.S.C., subtitle VII, as amended.</li> <li>b. Davis-Bacon Act - 40 U.S.C. 276(a), <i>et seq.</i><sup>1</sup></li> <li>c. Federal Fair Labor Standards Act - 29 U.S.C. 201, <i>et seq.</i></li> <li>d. Hatch Act - 5 U.S.C. 1501, <i>et seq.</i><sup>2</sup></li> </ol> </li> </ul> </li> </ol>
<hr/> <small>Airport Assurances (3/2005)</small>	




The table on the following pages is available for maintaining a record of drive-by inspections and maintenance repairs.









JB	2013 REVISIONS
Rev.	Description
<b>PCI Inspection Map</b>	
INDIANA DEPARTMENT OF TRANSPORTATION COLUMBUS MUNICIPAL AIRPORT COLUMBUS, INDIANA gnd 121.6	
	Page: 1/2





JB	2010 REVISIONS
Rev.	Description
<b>PCI Inspection Map</b>	
INDIANA DEPARTMENT OF TRANSPORTATION COLUMBUS MUNICIPAL AIRPORT COLUMBUS, INDIANA gnd 121.6	
	Page: 2/2

COLUMBUS MUNICIPAL AIRPORT  
2013 PCI Inspection



PCI LEGEND

100-86	Good	
85-71	Satisfactory	
70-56	Fair	
55-41	Poor	
40-26	Very Poor	
25-11	Serious	
10-0	Failed	

