

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G746	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED 03/07/2022
--	---	--	---

NAME OF PROVIDER OR SUPPLIER RES CARE SOUTHEAST INDIANA	STREET ADDRESS, CITY, STATE, ZIP CODE 16609 SIMA GRAY RD HENRYVILLE, IN 47126
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 0000 Bldg. 01	<p>A Post Survey Revisit (PSR) to the Life Safety Code Recertification Survey conducted on 12/08/21 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.470(j).</p> <p>Survey Date: 03/07/22</p> <p>Facility Number: 011664 Provider Number: 15G746 AIM Number: 200902010</p> <p>At this PSR survey, Res Care Southeast Indiana was found not in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies.</p> <p>This one story facility was fully sprinkled. The facility has a fire alarm system with smoke detection in the corridors, common living areas and all client sleeping rooms. It was determined there was no heat detection in the attic of this fully sprinklered facility. The facility has a capacity of 4 and had a census of 4 at the time of this survey.</p> <p>Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Prompt with an E-Score of 0.7.</p> <p>Quality Review completed on 03/10/22</p>	K 0000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G746	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED 03/07/2022
--	---	--	---

NAME OF PROVIDER OR SUPPLIER RES CARE SOUTHEAST INDIANA	STREET ADDRESS, CITY, STATE, ZIP CODE 16609 SIMA GRAY RD HENRYVILLE, IN 47126
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K S351 Bldg. 01	<p>NFPA 101 Sprinkler System - Installation Sprinkler System - Installation Where an automatic sprinkler system is installed, for either total or partial building coverage, the system shall be in accordance with Section 9.7 and shall initiate the fire alarm system in accordance with Section 9.6, as modified below. The adequacy of the water supply shall be documented. In Prompt Evacuation facilities, an automatic sprinkler system in accordance with NFPA 13D, Standard for the Installation of Sprinkler Systems in One and two Family Dwellings and Manufactured Homes, shall be permitted. Automatic sprinklers shall not be required in closets not exceeding 24 square feet and in bathrooms not exceeding 55 square feet, provided that such spaces are finished with lath and plaster or materials providing a 15-minute thermal barrier. In Prompt Evacuation Capability facilities where an automatic sprinkler system is in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems, automatic sprinklers shall not be required in closets not exceeding 24 square feet and in bathrooms not exceeding 55 square feet, provided that such spaces are finished with lath and plaster or material providing a 15-minute thermal barrier. In Prompt Evacuation Capability facilities in buildings four or fewer stories above grade plane, systems in accordance with NFPA 13R, Standard for the Installation of Sprinkler Systems in</p>			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G746	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED 03/07/2022
--	---	--	---

NAME OF PROVIDER OR SUPPLIER RES CARE SOUTHEAST INDIANA	STREET ADDRESS, CITY, STATE, ZIP CODE 16609 SIMA GRAY RD HENRYVILLE, IN 47126
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>Residential Occupancies up to and including Four Stories in Height, shall be permitted.</p> <p>Initiation of the fire alarm system shall not be required for existing installations in accordance with 33.2.3.5.6. Where an automatic sprinkler is installed, attics used for living purposes, storage, or fuel-fired equipment are sprinkler protected by July 5, 2019. Attics not used for living purposes, storage, or fuel-fired equipment meet one of the following:</p> <ol style="list-style-type: none"> 1. Protected by heat detection system to activate the fire alarm system according to 9.6. 2. Protected by automatic sprinkler system according to 9.7. 3. Constructed of noncombustible or limited-combustible construction; or 4. Constructed of fire-retardant-treated wood according to NFPA 703. <p>33.2.3.5.3, 33.2.3.5.3.1, 33.2.3.5.3.3, 33.2.3.5.3.4, 33.2.3.5.3.6, 33.2.3.5.7</p> <p>Based on record review, observation, and interview; the facility failed to install heat detection devices in 1 of 1 attic space. LSC 33.2.3.5.7.1 All facilities where a sprinkler system is installed, attics used for living purposes, storage, or fuel-fired equipment shall have sprinkler coverage. LSC 33.2.3.5.7.2 Attics not used for these purposes shall meet one of the following:</p> <p>Protected by heat detection system to activate the fire alarm system according to 9.6</p> <p>Protected by automatic sprinkler system according to 9.6</p> <p>Constructed of noncombustible or limited-combustible construction</p> <p>Constructed of fire-retardant-treated wood according to NFPA 703</p>	K S351	To correct the deficient practice ResCare staff has confirmed there is heat detection in the attic of the facility. The service provider inspected the heat detectors on 3-18-22. ResCare staff will obtain an inspection report as soon as it is available. All supervisors have been re-trained on ensuring the service provider inspects all LSC devices timely. Ongoing monitoring will be achieved through a monthly LSC inspection checklist completed by the Area Supervisor.	04/07/2022

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G746		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 03/07/2022	
NAME OF PROVIDER OR SUPPLIER RES CARE SOUTHEAST INDIANA				STREET ADDRESS, CITY, STATE, ZIP CODE 16609 SIMA GRAY RD HENRYVILLE, IN 47126			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K S353 Bldg. 01	<p>This deficient practice could affect all clients.</p> <p>Findings include:</p> <p>Based on record review on 03/07/22 between 12:30 p.m. and 1:00 p.m. with the Area Supervisor present, there was no documentation provided in the fire alarm system inspection reports to indicate the attic was protected with a heat detection system for this sprinklered home. Based on observation at 12:40 p.m. during a tour of the attic space with the Area Supervisor, there was not a heat detection system in the attic. Based on interview at the time of observation, the Area Supervisor agreed the attic space was not provided with a heat detection system and said the fire alarm system vendor is supposed to be at the facility to install heat detection in the attic sometime soon.</p> <p>This finding was reviewed with the Area Supervisor during the exit conference.</p> <p>NFPA 101 Sprinkler System - Maintenance and Testing Sprinkler System - Maintenance and Testing 2012 EXISTING (Prompt) NFPA 13 and 13R Systems All sprinkler systems installed in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems, and NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies Up To and Including Four Stories in Height, are inspected, tested and maintained in accordance with NFPA 25, Standard for Inspection, Testing and Maintenance of Water Based Fire Protection System. NFPA 13D Systems Sprinkler systems installed in accordance</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G746	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED 03/07/2022
--	---	--	---

NAME OF PROVIDER OR SUPPLIER RES CARE SOUTHEAST INDIANA	STREET ADDRESS, CITY, STATE, ZIP CODE 16609 SIMA GRAY RD HENRYVILLE, IN 47126
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>with NFPA 13D, Standard for the Installation of Sprinkler Systems in One- and Two-Family Dwellings and Manufactured Homes, are inspected, tested and maintained in accordance with the following requirements of NFPA 25:</p> <ol style="list-style-type: none"> 1. Control valves inspected monthly (NFPA 25, section 13.3.2). 2. Gauges inspected monthly (NFPA 25, section 13.2.71). 3. Alarm devices inspected quarterly (NFPA 25, section 5.2.6). 4. Alarm devices tested semiannually (NFPA 25, section 5.3.3). 5. Valve supervisory switches tested semiannually (NFPA 25, section 13.3.3.5). 6. Visible sprinklers inspected annually ((NFPA 25, section 5.2.1). 7. Visible pipe inspected annually (NFPA 25, section 5.2.2). 8. Visible pipe hangers inspected annually (NFPA 25, section 5.2.3). 9. Buildings inspected annually prior to freezing weather for adequate heat for water filled piping (NFPA 25, section 5.2.5). 10. A representative sample of fast response sprinklers are tested at 20 years (NFPA 25, section 5.3.1.1.1.2). 11. A representative sample of dry pendant sprinklers are tested at 10 years (NFPA 25, section 5.3.1.1.15). 12. Antifreeze solutions are tested annually (NFPA 25, section 5.3.4). 13. Control valves are operated through their full range and returned to normal annually (NFPA 25, section 13.3.3.1). 14. Operating stems of OS&Y valves are lubricated annually (NFPA 25, section 13.3.4). 15. Dry pipe systems extending into 			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G746	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED 03/07/2022
--	---	--	---

NAME OF PROVIDER OR SUPPLIER RES CARE SOUTHEAST INDIANA	STREET ADDRESS, CITY, STATE, ZIP CODE 16609 SIMA GRAY RD HENRYVILLE, IN 47126
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>unheated portions of the building are inspected, tested and maintained (NFPA 25, section 13.4.4).</p> <p>A. Date sprinkler system last checked and necessary maintenance provided.</p> <p>_____</p> <p>B. Show who provided the service.</p> <p>_____</p> <p>C. Note the source of the water supply for the automatic sprinkler system.</p> <p>_____</p> <p>(Provide in REMARKS information on coverage for any non-required or partial automatic sprinkler system.) 33.2.3.5.3, 33.2.3.5.8, 9.7.5, 9.7.7, 9.7.8, and NFPA 25</p> <p>Based on observation and interview, the facility failed to ensure 5 of over 30 sprinkler heads in the facility were maintained. NFPA 13, Standard for the Installation of Sprinkler Systems, 2010 Edition, Section 6.2.7.1 states plates, escutcheons, or other devices used to cover the annular space around a sprinkler shall be metallic or shall be listed for use around a sprinkler. This deficient practice could affect all clients and staff in the facility.</p> <p>Findings include:</p> <p>Based on observations on 03/07/22 between 12:30 p.m. and 1:00 p.m. during a tour of the facility with the Area Supervisor, drop down type sprinkler heads in the following locations were missing their cover plates: the garage, kitchen, staff office, bathroom, and short hall outside the pantry. Based on interview at the time of observations, the Area Supervisor agreed the cover plates were missing from the previously mentioned sprinkler head locations.</p>	K S353	To correct the deficient practice the sprinkler heads without covers will be replaced. All site staff will be trained to ensure the sprinkler heads are appropriately maintained. To prevent further occurrences the AS will conduct a LSC audit each month to ensure all features and paperwork are present and functional.	04/07/2022

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G746	X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____		X3) DATE SURVEY COMPLETED 03/07/2022
NAME OF PROVIDER OR SUPPLIER RES CARE SOUTHEAST INDIANA			STREET ADDRESS, CITY, STATE, ZIP CODE 16609 SIMA GRAY RD HENRYVILLE, IN 47126		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
	<p>This finding was reviewed with the Area Supervisor during the exit conference.</p> <p>This deficiency was cited on 12/08/21. The facility failed to implement a systemic plan of correction to prevent recurrence.</p>				