

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/14/2022

FORM APPROVED

OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G749	X2) MULTIPLE CONSTRUCTION A. BUILDING -- _____ B. WING _____	X3) DATE SURVEY COMPLETED 08/30/2022
--	---	--	---

NAME OF PROVIDER OR SUPPLIER  RES CARE SOUTHEAST INDIANA	STREET ADDRESS, CITY, STATE, ZIP COD 16613 SIMA GRAY RD HENRYVILLE, IN 47126
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
E 0000  Bldg. --	<p>An Emergency Preparedness Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.475.</p> <p>Survey Date: 08/30/22</p> <p>Facility Number: 011595 Provider Number: 15G749 AIM Number: 200905630</p> <p>At this Emergency Preparedness survey, Res Care Southeast Indiana was found in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.475.</p> <p>The facility has 4 certified beds. All 4 beds are certified for Medicaid. At the time of the survey, the census was 4.</p> <p>Quality Review completed on 08/31/22</p>	E 0000		
K 0000  Bldg. 01	<p>A Life Safety Code Certification and Environmental Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.470(j).</p> <p>Survey Date: 08/30/22</p> <p>Facility Number: 011595 Provider Number: 15G749 AIM Number: 200905630</p> <p>At this Life Safety Code survey, Res Care</p>	K 0000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosed days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G749	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED  08/30/2022
--	---	--	---

NAME OF PROVIDER OR SUPPLIER  RES CARE SOUTHEAST INDIANA	STREET ADDRESS, CITY, STATE, ZIP COD 16613 SIMA GRAY RD HENRYVILLE, IN 47126
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K S362  Bldg. 01	<p>Southeast Indiana was found not in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2012 Edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies.</p> <p>This one story facility was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors, common living areas and in client sleeping rooms. The facility has heat detectors installed in the attic. The facility has a capacity of 4 and had a census of 4 at the time of this survey.</p> <p>Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Prompt with an E-Score of 0.5.</p> <p>Quality Review completed on 08/31/22</p> <p>NFPA 101 Corridors - Construction of Walls Corridors - Construction of Walls 2012 EXISTING (Prompt) Unless otherwise indicated below, corridor walls shall meet all of the following: * Walls separating sleeping rooms have a minimum 1/2-hour fire resistance rating, which is considered to be achieved if the partitioning is finished on both sides with lath and plaster or materials providing a 15-minute thermal barrier. * Sleeping room doors are substantial doors, such as those of 1-3/4 inch thick, solid-bonded wood-core construction or other construction of equal or greater stability and fire integrity.</p>			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G749	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED  08/30/2022
NAME OF PROVIDER OR SUPPLIER  RES CARE SOUTHEAST INDIANA			STREET ADDRESS, CITY, STATE, ZIP CODE 16613 SIMA GRAY RD HENRYVILLE, IN 47126		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
	<p>* Any vision panels are fixed fire window assemblies in accordance with 8.3.4 or are wired glass not exceeding 9 square feet each in area and installed in approved frames. This requirement shall not apply to corridor walls that are smoke partitions in accordance with 8.4 and that are protected by automatic sprinklers in accordance with 33.2.3.5 on both sides of the wall and door. In such instances, there shall be no limitation on the type or size of glass panels.</p> <p>In Prompt Evacuation facilities, all sleeping rooms shall be separated from the escape route by smoke partitions in accordance with 8.2.4.</p> <p>Sleeping arrangements that are not located in sleeping rooms shall be permitted for nonresident staff members, provided that the audibility of the alarm in the sleeping area is sufficient to awaken staff that might be sleeping.</p> <p>In previously approved facilities, where the group achieves an E-score of three or less using the board and care methodology of NFPA 101A, Guide on Alternative Approaches to Life Safety, sleeping rooms shall be separated from escape routes by walls and doors that are smoke resistant.</p> <p>33.2.3.6 Based on observation and interview, the facility failed to ensure corridor doors to 1 of 4 client bedrooms would resist the passage of smoke. This deficient practice could affect all clients, staff and visitors.</p> <p>Findings include:</p> <p>Based on observations with Program Director during a tour of the facility from 12:50 p.m. to 1:10 p.m. on 08/30/22, a one inch gap was noted in</p>	K S362	To correct the deficient practice the door will be repaired to ensure there is no gap when latched. All staff responsible for home maintenance will be trained to ensure that all doors latch appropriately without significant gaps. Ongoing monitoring will be achieved through a monthly LSC inspection to ensure all LSC features are operational and	09/30/2022	

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/14/2022  
FORM APPROVED  
OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G749	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED  08/30/2022
NAME OF PROVIDER OR SUPPLIER  RES CARE SOUTHEAST INDIANA			STREET ADDRESS, CITY, STATE, ZIP CODE 16613 SIMA GRAY RD HENRYVILLE, IN 47126		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
	<p>between the face of the door and the door stop on the door frame for the corridor door to the southwest bedroom (NG's bedroom) when the door was in the fully closed and latched position. Based on interview at the time of the observations, the Program Director Aide agreed the corridor door to the southwest bedroom would not resist the passage of smoke.</p> <p>This finding was reviewed with the Program Director during the exit conference.</p>		correct.		