

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155333	X2) MULTIPLE CONSTRUCTION A. BUILDING -- _____ B. WING _____	X3) DATE SURVEY COMPLETED 06/01/2021
--	---	--	---

NAME OF PROVIDER OR SUPPLIER PAOLI HEALTH AND LIVING COMMUNITY	STREET ADDRESS, CITY, STATE, ZIP CODE 559 W LONGEST ST PAOLI, IN 47454
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
E 0000 Bldg. --	<p>An Emergency Preparedness Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.73.</p> <p>Survey Date: 06/01/21</p> <p>Facility Number: 000226 Provider Number: 155333 AIM Number: 100267730</p> <p>At this Emergency Preparedness survey, Paoli Health and Living Community was found in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73</p> <p>The facility has 109 certified beds, with a current census of 86.</p> <p>Quality Review completed on 06/04/21</p>	E 0000	<p>Submission of this plan of correction in no way constitutes an admission by Paoli Health and Living or its management company that the allegations contained in the survey report is a true and accurate portrayal of the provision of nursing care or other services provided in this facility. The Plan of Correction is prepared and executed solely because it is required by Federal and State Law.</p> <p>This statement of deficiencies and plan of correction will be reviewed at the Monthly Quality Assurance/Assessment Committee meeting.</p>	
K 0000 Bldg. 01	<p>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a).</p> <p>Survey Date: 06/01/21</p> <p>Facility Number: 000226 Provider Number: 155333 AIM Number: 100267730</p> <p>At this Life Safety Code survey, Paoli Health and</p>	K 0000	<p>Submission of this plan of correction in no way constitutes an admission by Paoli Health and Living or its management company that the allegations contained in the survey report is a true and accurate portrayal of the provision of nursing care or other services provided in this facility. The Plan of Correction is prepared and executed solely because it is required by Federal</p>	

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155333		X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____		X3) DATE SURVEY COMPLETED 06/01/2021	
NAME OF PROVIDER OR SUPPLIER PAOLI HEALTH AND LIVING COMMUNITY				STREET ADDRESS, CITY, STATE, ZIP CODE 559 W LONGEST ST PAOLI, IN 47454			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
K 0321 SS=E Bldg. 01	<p>Living Community Inc. was found not in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>This one story facility with a basement was determined to be of Type V (111) construction and was sprinklered. The facility has a fire alarm system with hard wired smoke detectors in the corridors, spaces open to the corridors, and in resident sleeping rooms in the 400 and 500 halls, furthermore, battery operated smoke detectors were located in all other resident sleeping rooms. The facility has a capacity of 109 and had a census of 86 at the time of this survey.</p> <p>All areas where residents have customary access were sprinklered and all areas providing facility services were sprinklered, except two detached wood sheds and one metal shed used for facility storage.</p> <p>Quality Review completed on 06/04/21</p> <p>NFPA 101 Hazardous Areas - Enclosure Hazardous Areas - Enclosure Hazardous areas are protected by a fire barrier having 1-hour fire resistance rating (with 3/4 hour fire rated doors) or an automatic fire extinguishing system in accordance with 8.7.1 or 19.3.5.9. When the approved automatic fire extinguishing system option is used, the areas shall be separated from other spaces by smoke resisting partitions and doors in accordance with 8.4.</p>		<p>and State Law.</p> <p>This statement of deficiencies and plan of correction will be reviewed at the Monthly Quality Assurance/Assessment Committee meeting.</p>				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155333		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 06/01/2021	
NAME OF PROVIDER OR SUPPLIER PAOLI HEALTH AND LIVING COMMUNITY				STREET ADDRESS, CITY, STATE, ZIP CODE 559 W LONGEST ST PAOLI, IN 47454			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
	<p>Doors shall be self-closing or automatic-closing and permitted to have nonrated or field-applied protective plates that do not exceed 48 inches from the bottom of the door.</p> <p>Describe the floor and zone locations of hazardous areas that are deficient in REMARKS. 19.3.2.1, 19.3.5.9</p> <p>Area Automatic Sprinkler Separation N/A</p> <p>a. Boiler and Fuel-Fired Heater Rooms b. Laundries (larger than 100 square feet) c. Repair, Maintenance, and Paint Shops d. Soiled Linen Rooms (exceeding 64 gallons) e. Trash Collection Rooms (exceeding 64 gallons) f. Combustible Storage Rooms/Spaces (over 50 square feet) g. Laboratories (if classified as Severe Hazard - see K322)</p> <p>Based on observation and interview, the facility failed to ensure 2 of over 10 hazardous areas such as combustibile storage rooms (over 50 square feet in size) were separated from other spaces by smoke resistant partitions and doors. Doors shall be self closing or automatic closing in accordance with 7.2.1.8. This deficient practice could affect over 10 residents, staff, and visitors in the vicinity of the Dining Room by 200 Hall & Medical Records.</p> <p>Findings include:</p> <p>Based on observations with the Maintenance Director during a tour of the facility from 1:43 p.m. to 3:40 p.m. on 06/01/21, the following was noted:</p>	K 0321	<p>K 321</p> <p>I. The corrective actions to be accomplished for those residents found to have been affected by the deficient practice.</p> <p>Observation A- The Medical Records office is being used for more storage and needs a self-closing device. Observation B- The south door from the kitchen to dining room would not latch properly.</p>	06/21/2021			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155333	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED 06/01/2021
--	---	--	---

NAME OF PROVIDER OR SUPPLIER PAOLI HEALTH AND LIVING COMMUNITY	STREET ADDRESS, CITY, STATE, ZIP CODE 559 W LONGEST ST PAOLI, IN 47454
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>a. the corridor door to the Medical Records office, a room of over 50 square feet, in the basement was being used to store over 25 combustible boxes and Personal Protective Equipment (PPE). The corridor door to Medical Records office was not equipped with a self-closing device.</p> <p>b. the door from the kitchen to the dining room was equipped with a self-closing device but would not close and latch after five (5) attempts. Based on observation, the protective metal covering at the bottom of the door was bent out by the hinge, preventing the door from latching. Based on interview at the time of observation, the Maintenance Director acknowledged the door would not latch and stated the carts used for meals hit the door and bent out the protective metal covering. The kitchen had two partially filled 32 gallon trash containers and combustible storage.</p> <p>Based on interview at the time of the observations, the Maintenance Director agreed the aforementioned hazardous areas were not separated from other spaces by smoke resistant partitions and doors.</p> <p>This finding was reviewed with the Administrator during the exit conference.</p> <p>3.1-19(b)</p>		<p>II. The facility will identify other residents that may potentially be affected by the deficient practice.</p> <p>All Residents and staff could be affected by this deficient practice.</p> <p>III. The facility will put into place the following systematic changes to ensure that the deficient practice does not recur.</p> <p>Observation A- The Maintenance Supervisor has installed a self-closing device on the Medical Records door. See attached picture labeled "medical records door closure"</p> <p>Observation B- The Maintenance Supervisor has adjusted the metal kick plate on the kitchen door so it will latch properly. See attached picture labeled "kitchen door latch"</p> <p>IV The facility will monitor the corrective action by implementing the following measures.</p> <p>There is a Monthly TELS Task to inspect all doors and self-closing devices monthly. See attached TELS Task labeled "door</p>	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155333	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED 06/01/2021
--	---	--	---

NAME OF PROVIDER OR SUPPLIER PAOLI HEALTH AND LIVING COMMUNITY	STREET ADDRESS, CITY, STATE, ZIP CODE 559 W LONGEST ST PAOLI, IN 47454
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
--------------------	--	---------------	---	----------------------

K 0353 SS=E Bldg. 01	<p>NFPA 101 Sprinkler System - Maintenance and Testing Sprinkler System - Maintenance and Testing Automatic sprinkler and standpipe systems are inspected, tested, and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintaining of Water-based Fire Protection Systems. Records of system design, maintenance, inspection and testing are maintained in a secure location and readily available.</p> <p>a) Date sprinkler system last checked _____</p> <p>b) Who provided system test _____</p> <p>c) Water system supply source _____</p> <p>Provide in REMARKS information on coverage for any non-required or partial automatic sprinkler system. 9.7.5, 9.7.7, 9.7.8, and NFPA 25 1. Based on record review and interview, the facility failed to maintain automatic sprinkler systems in accordance with NFPA 25. LSC 9.7.5 requires all sprinkler systems shall be inspected, tested, and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems. NFPA 25, 2011 Edition, Section</p>	K 0353	<p>inspection".</p> <p>V. Plan of Correction completion date.</p> <p>Plan of Completion date is June 21st, 2021.</p> <p>K 353</p> <p>I. The corrective actions to be accomplished for those residents found to have been affected by the deficient practice.</p>	08/31/2021
----------------------------	--	--------	---	------------

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155333	X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	X3) DATE SURVEY COMPLETED 06/01/2021
--	---	---	---

NAME OF PROVIDER OR SUPPLIER PAOLI HEALTH AND LIVING COMMUNITY	STREET ADDRESS, CITY, STATE, ZIP CODE 559 W LONGEST ST PAOLI, IN 47454
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>5.3.1.1.1.6 states dry sprinklers that have been in service for 10 years shall be replaced or representative samples shall be tested and then retested at 10-year intervals. NFPA 25, 4.3.1 requires records shall be made for all inspections, tests, and maintenance of the system components and shall be made available to the authority having jurisdiction upon request. This deficient practice could affect all residents, staff, and visitors in the facility.</p> <p>Findings include:</p> <p>Based on review of "Report of Inspection/Test" documentation dated 04/12/2021 during record review with the Maintenance Director from 9:50 a.m. to 12:00 p.m. on 06/01/2021, the 'Dry-type sprinklers replaced or successfully sampled within last 10 years" was marked "No". Under the "Deficiencies-General Questions" section, it was noted "Unknown if dry sprinklers dated 1988 have been sample tested. Based on interview at the time of record review, the Maintenance Director stated the facility has a dry sprinkler system and a wet sprinkler system. He further stated the facility changed sprinkler vendors within the last few months, and this was the first time he had seen the dry sprinkler sampling noted on an inspection report. The Maintenance Director stated he did not know if the dry sprinklers had been sample tested in the past.</p> <p>This finding was reviewed with the Administrator at the exit conference.</p> <p>2. Based on observation and interview, the facility failed to ensure 3 of over 100 sprinkler heads in the facility were free of corrosion. NFPA 25, Standard for the Inspection, Testing,</p>		<p>Observation A- The Dry Pipe sprinkler system has not had its 10 year dry pipe sprinkler head testing completed.</p> <p>Observation B- There are 2 sprinkler heads in the 500 Hall shower and 2 in the kitchen freezer that have excess debris on them and need to be replaced.</p> <p>II. The facility will identify other residents that may potentially be affected by the deficient practice.</p> <p>All Residents and staff could be affected by this deficient practice.</p> <p>III. The facility will put into place the following systematic changes to ensure that the deficient practice does not recur.</p> <p>Observation A- The Maintenance Supervisor has contacted Advantage Fire to get a proposal for the Dry pendant inspections. We have filed a waiver for these repairs to request an extension due to manufacturing and testing delays. We will send documentation to State Life Safety once received.</p> <p>Observation B- The Maintenance Supervisor has contacted</p>	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155333		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 06/01/2021	
NAME OF PROVIDER OR SUPPLIER PAOLI HEALTH AND LIVING COMMUNITY				STREET ADDRESS, CITY, STATE, ZIP CODE 559 W LONGEST ST PAOLI, IN 47454			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
	<p>and Maintenance of Water-Based Fire Protection Systems, 2011 Edition, Section 5.2.1.1.1 states sprinklers shall not show signs of leakage; shall be free of corrosion, foreign materials, paint, and physical damage; and shall be installed in the correct orientation (e.g., up-right, pendent, or sidewall). Furthermore, Section 5.2.1.1.2 states any sprinkler that shows signs of any of the following shall be replaced:</p> <ol style="list-style-type: none"> (1) Leakage (2) Corrosion (3) Physical Damage (4) Loss of fluid in the glass bulb heat responsive element (5) Loading (6) Painting unless painted by the sprinkler manufacturer. <p>In lieu of replacing sprinklers that are loaded with dust, it is permitted to clean sprinklers with compressed air or by a vacuum provided that the equipment does not touch the sprinkler.</p> <p>This deficient practice could affect over 10 residents and staff in the 500 hall and vicinity of the kitchen.</p> <p>Findings include:</p> <p>Based on observation on 06/01/21 during a tour of the facility from 1:43 p.m. to 3:40 p.m. with the Maintenance Director, the following was noted:</p> <ol style="list-style-type: none"> a. two sprinklers in the 500 Hall shower room were covered with corrosion. b. the wax covered sidewall sprinkler in the kitchen freezer has had a portion of the wax removed and the sprinkler contains corrosion. <p>Based on interview at the time of observation, the Maintenance Director agreed the sprinkler heads in the above mentioned locations were covered with corrosion.</p>		<p>Advantage Fire to replace the 3 deficient sprinkler heads. We have filed a waiver for these repairs to request an extension due to manufacturing delays. We will send documentation and pictures to State Life Safety once completed.</p> <p>IV The facility will monitor the corrective action by implementing the following measures.</p> <p>The Maintenance Supervisor will inspect all sprinkler heads quarterly to ensure that they are debris free.</p> <p>V. Plan of Correction completion date.</p> <p>Plan of Completion date is August 31, 2021..</p>				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155333	X2) MULTIPLE CONSTRUCTION A. BUILDING <u>01</u> B. WING _____	X3) DATE SURVEY COMPLETED 06/01/2021
--	---	---	---

NAME OF PROVIDER OR SUPPLIER PAOLI HEALTH AND LIVING COMMUNITY	STREET ADDRESS, CITY, STATE, ZIP CODE 559 W LONGEST ST PAOLI, IN 47454
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 0914 SS=F Bldg. 01	<p>These findings were reviewed with the Administrator at the exit conference.</p> <p>3.1-19(b)</p> <p>NFPA 101 Electrical Systems - Maintenance and Testing Electrical Systems - Maintenance and Testing Hospital-grade receptacles at patient bed locations and where deep sedation or general anesthesia is administered, are tested after initial installation, replacement or servicing. Additional testing is performed at intervals defined by documented performance data. Receptacles not listed as hospital-grade at these locations are tested at intervals not exceeding 12 months. Line isolation monitors (LIM), if installed, are tested at intervals of less than or equal to 1 month by actuating the LIM test switch per 6.3.2.6.3.6, which activates both visual and audible alarm. For LIM circuits with automated self-testing, this manual test is performed at intervals less than or equal to 12 months. LIM circuits are tested per 6.3.3.3.2 after any repair or renovation to the electric distribution system. Records are maintained of required tests and associated repairs or modifications, containing date, room or area tested, and results.</p> <p>6.3.4 (NFPA 99) Based on observation, record review and interview; the facility failed to ensure complete documentation was available for all nonhospital-grade electrical receptacles in all resident room locations tested at least annually. NFPA 99, Health Care Facilities Code 2012</p>	K 0914	<p>K 914</p> <p>I. The corrective actions to be accomplished for those residents found to have been affected by the deficient</p>	06/22/2021

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155333		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 06/01/2021	
NAME OF PROVIDER OR SUPPLIER PAOLI HEALTH AND LIVING COMMUNITY				STREET ADDRESS, CITY, STATE, ZIP CODE 559 W LONGEST ST PAOLI, IN 47454			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
	<p>Edition, Section 6.3.4.1.3 states receptacles not listed as hospital-grade, at patient bed locations and in locations where deep sedation or general anesthesia is administered, shall be tested at intervals not exceeding 12 months. Additionally, Section 6.3.3.2, Receptacle Testing in Patient Care Rooms requires the physical integrity of each receptacle shall be confirmed by visual inspection. The continuity of the grounding circuit in each electrical receptacle shall be verified. Correct polarity of the hot and neutral connections in each electrical receptacle shall be confirmed; and retention force of the grounding blade of each electrical receptacle (except locking-type receptacles) shall be not less than 115 grams (4 ounces). This deficient practice could affect all residents.</p> <p>Findings include:</p> <p>Based on record review on 06/01/21 between 9:50 a.m. and 12:00 p.m. with the Maintenance Director present, there was documentation available of an annual resident room receptacle test for non-hospital-grade receptacles, however, it was incomplete. The documentation provided lacked the following information:</p> <p>a. Receptacles in each room were not listed individually, only a room number was provided. Based on interview at the time of record review, the Maintenance Director said the Regional Facilities Manager conducts the annual receptacle testing. He further stated that he replaces failed resident room receptacles with hospital grade receptacles, but that is not documented as far as he knew. Based on observations between 1:43 p.m. and 3:40 p.m. during a tour of the facility with the Maintenance Director, there were at least four to six electrical receptacles in each of the resident rooms.</p>		<p>practice.</p> <p>Observation A- The Building failed to ensure that the outlet inspection in skilled resident rooms was completed properly.</p> <p>II. The facility will identify other residents that may potentially be affected by the deficient practice.</p> <p>All Residents and staff could be affected by this deficient practice.</p> <p>III. The facility will put into place the following systematic changes to ensure that the deficient practice does not recur.</p> <p>Observation A- The Executive Director of Facilities has reviewed the current report on file from 9 of 2020 and have attached it to this POC. The next one is scheduled for Sept 1st, 2021. Please let me know what other documentation is needed at this time.</p> <p>IV The facility will monitor the corrective action by implementing the following measures.</p>				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155333		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 06/01/2021	
NAME OF PROVIDER OR SUPPLIER PAOLI HEALTH AND LIVING COMMUNITY				STREET ADDRESS, CITY, STATE, ZIP CODE 559 W LONGEST ST PAOLI, IN 47454			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 0920 SS=E Bldg. 01	<p>This finding was reviewed with the Administrator at the exit conference.</p> <p>3.1-19(b)</p> <p>NFPA 101 Electrical Equipment - Power Cords and Extens Electrical Equipment - Power Cords and Extension Cords Power strips in a patient care vicinity are only used for components of movable patient-care-related electrical equipment (PCREE) assemblies that have been assembled by qualified personnel and meet the conditions of 10.2.3.6. Power strips in the patient care vicinity may not be used for non-PCREE (e.g., personal electronics), except in long-term care resident rooms that do not use PCREE. Power strips for PCREE meet UL 1363A or UL 60601-1. Power strips for non-PCREE in the patient care rooms (outside of vicinity) meet UL 1363. In non-patient care rooms, power strips meet other UL standards. All power strips are used with general precautions. Extension cords are not used as a substitute for fixed wiring of a structure. Extension cords used</p>				<p>The Regional Maintenance Director completes these audits annually during the community CQR. He has updated his report showing that he inspects each room when entering from left to right including the bathroom GFI. The new report will list how many outlets are in each room.</p> <p>V. Plan of Correction completion date.</p> <p>Plan of Completion date is June 22nd, 2021.</p>		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155333	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED 06/01/2021
--	---	--	---

NAME OF PROVIDER OR SUPPLIER PAOLI HEALTH AND LIVING COMMUNITY	STREET ADDRESS, CITY, STATE, ZIP CODE 559 W LONGEST ST PAOLI, IN 47454
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>temporarily are removed immediately upon completion of the purpose for which it was installed and meets the conditions of 10.2.4. 10.2.3.6 (NFPA 99), 10.2.4 (NFPA 99), 400-8 (NFPA 70), 590.3(D) (NFPA 70), TIA 12-5</p> <p>Based on observation and interview, the facility failed to ensure 1 of 1 extension cords including power strips were not used as a substitute for fixed wiring. LSC 19.5.1 requires utilities to comply with Section 9.1. LSC 9.1.2 requires electrical wiring and equipment to comply with NFPA 70, National Electrical Code, 2011 Edition. NFPA 70, Article 400.8 requires that, unless specifically permitted, flexible cords and cables shall not be used as a substitute for fixed wiring of a structure. LSC Section 4.5.7 states any building service equipment or safeguard provided for life safety shall be designed, installed, and approved in accordance with all applicable NFPA standards. NFPA 99, Standard for Health Care Facilities, 2012 edition, defines patient care areas as any portion of a health care facility wherein patients are intended to be examined or treated. Patient care vicinity is defined as a space, within a location intended for the examination and treatment of patients, extending 6 ft (1.8 m) beyond the normal location of the bed, chair, table, treadmill, or other device that supports the patient during examination and treatment. A patient care vicinity extends vertically to 7 ft 6 in. (2.3 m) above the floor. NFPA 99, Section 10.4.2.3 states household or office appliances not commonly equipped with grounding conductors in their power cords shall be permitted provided they are not located within the patient care vicinity. This deficient practice could affect over 10 residents, staff, and visitors.</p>	K 0920	<p>K920</p> <p>I. The corrective actions to be accomplished for those residents found to have been affected by the deficient practice.</p> <p>Observation 1 – The facility failed to ensure that there were no power strips being used in the patient care area. Room 207 had a power strip attached to the wall next to the bed.</p> <p>II. The facility will identify other residents that may potentially be affected by the deficient practice.</p> <p>The resident in room 207 could be affected by this deficient practice.</p> <p>III. The facility will put into place the following systematic changes to ensure that the deficient practice does not recur.</p> <p>The power strip has been relocated outside of the patient care area. See attached picture</p>	06/21/2021

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155333	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 06/01/2021
NAME OF PROVIDER OR SUPPLIER PAOLI HEALTH AND LIVING COMMUNITY			STREET ADDRESS, CITY, STATE, ZIP CODE 559 W LONGEST ST PAOLI, IN 47454		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
	<p>Findings include:</p> <p>Based on observations with the Maintenance Director during a tour of the facility from at 1:43 p.m. to 3:40 p.m. on 06/01/21 a foot splint, a television, and a cell phone charging cable were plugged into a power strip mounted on the wall three feet from the resident bed nearest the window in Room 207. The UL listing of the power strip was 1363A.</p> <p>Based on interview at the time of the observations, the Maintenance Director agreed power strips were being used in resident sleeping rooms for non-PCREE and as a substitute for fixed wiring at the aforementioned locations.</p> <p>This finding was reviewed with the Administrator at the exit conference.</p> <p>3.1-19(b)</p>		<p>labeled "power strip"</p> <p>IV The facility will monitor the corrective action by implementing the following measures.</p> <p>There is a current monthly TELS task to inspect rooms for proper power strip use. See attached task labeled "TELS Power Strip Task"</p> <p>V. Plan of Correction completion date.</p> <p>Plan of Completion date is June 21st, 2021.</p>		