



INDIANA UTILITY REGULATORY COMMISSION  
101 W. WASHINGTON STREET, SUITE 1500E  
INDIANAPOLIS, INDIANA 46204-3407

<http://www.in.gov/iurc>  
Office: (317) 232-2701  
Facsimile: (317) 232-6758

## Pipeline Safety Division Investigation Report

### Investigation regarding: Miller Pipeline

UPPAC Database Record ID: 4446

Report Date: 7/16/2013

Investigator: Mike Orr

Damage Date: 1/31/2013 4:45:13 PM

Damage Address: 213 S Dexter Ave, Knight, Vanderburgh

### The Parties

Excavator: **Miller Pipeline**

Address: 8850 Crawfordsville Rd, Indianapolis, In 46234

Facility Owner: **Vectren**

### Pipeline Facility

Facility Type: Natural Gas

Facility Function: Service/Drop

Type of Equipment: Backhoe/Trackhoe

Type of Work Performed: Natural Gas

### Damage Impact

Product Release: Yes

Ignition: No

Service Interruption: True

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): \$1264

### Excavator Activities/Cause of Damage Information:

Excavator Request Locates: Yes  
1/18/2013

Indiana 811 Ticket Number: 1301160652

Original Start Date:

Locate Instructions: PAINT AND FLAG ENTIRE PROPERTY AND BOTH SIDE OF S DEXTER AVE

Follow-Up Locate Instructions (if applicable):

**Synopsis:** Excavator struck and damaged an underground natural gas service tee while performing natural gas work.

**Findings:** Reported by Indiana 811; excavator's response to initial notice was received on 4/12/2013. The excavator had a valid locate ticket; however, the gas operator self reported a failure to locate the service facility.

**Conclusion:** There was a failure to provide service line locate markings

**Violation: IC 8-1-26-18(f) Operator failed to locate or provided incorrect locate markings.**



# DAMAGE INFORMATION REPORT – PIPELINE SAFETY DIVISION

State Form 54122 (R2 / 7-11)  
INDIANA UTILITY REGULATORY COMMISSION

INITIAL DOCUMENTS -  
OPERATOR

CASE # 4446

Submitted to IURC-Pipeline Safety on: 04/03/2013

## Who is submitting this information?

Name of person providing this information: Darlene Kulhanek

Business address (number and street): 1 Main Street

City, State, and ZIP code: Evansville, IN 47711

Telephone number (area code): 812-491-4227

Fax number (area code): 812-491-4504

E-mail address: dkulhanek@vectren.com

## Excavator Information, if known

Full name: Miller Pipeline

Business address (number and street): 8850 Crawfordsville Rd

City, State, and ZIP code: Indianapolis, IN 46234

Telephone number (area code): 317-295-6417

Fax number (area code): 317-295-6418

E-mail address: Unknown

## Excavation or Demolition Information

Excavator type: Contractor

Excavation or demolition equipment: Backhoe/Trackhoe

Type of work performed: Natural Gas

---

## Date and Location of Damage

Date of damage (*month, day, year*): 1-31-2013

County: Vanderburgh

City: Evansville

Street address (*number and street, city, state, and ZIP code*):  
213 S Dexter Avenue, Evansville, IN

Nearest intersection: Unknown

Right of way where damage occurred: Public - City Street

Was there a release of product? Yes

If yes, was there an ignition of product? No

Were evacuations necessary as a result of release? No

If yes, how many evacuated? 0

Was there a customer service interruption? Yes

If yes, how many affected? 1

Time to restore service (*in hours*): 1

Enter number of injuries, if applicable and known: 0

Enter number of fatalities, if applicable and known: 0

Property damage, Estimate \$ 1,263.85

---

## Affected Facility Information

What type of pipeline was damaged? Natural Gas

What was the affected facility? Service/Drop

What was the depth of the facility, in inches? \_\_\_\_\_

---

## Notification, Locating, Marking

Did excavator request locates prior to commencing work? Yes

Enter Indiana 811 ticket number, if known: 1301160652

Was the locate request completed within two working days? Yes

If locates were performed, were they done so by a contractor or pipeline employee? Contract Locator

If a contractor locator, enter the company name, if known: USIC

Were facility marks visible in the area of excavation? Yes

Were facilities marked correctly? No

Type of markings used: Paint

If other, please specify: None

Was site marked by "White Lining"? No

Were special instructions part of the locate request? Unknown/Other

Were maps used to complete the locate request? Unknown/Other

Were pipeline company representatives on site during excavation? No

Did the excavator notify the operator in the event of this damage? Yes

Did the excavator notify Indiana 811 in the event of this damage? Yes

Did the excavator notify 911 in the event of a release of product? Unknown/Other

---

### **Description of Cause**

Select from the list the most accurate cause for the damage: --Facility marking or location not sufficient

---

### **Additional Comments**

1/2" plastic service tee pulled from main. Broken or No Tracer Wire.

Miller Pipeline

FDS 17444

Task No: 1030510 Capital / O & M (circle one)  
Date of Damage 1 / 31 / 13  
Cost Center # 5854  
Time Occurred 2:10 am / pm  
Time Found 2:20 am / pm  
Latitude 37.9748 Longitude: -87.51314

Vectren Claim Number: \_\_\_\_\_  
Police Report / MO #: \_\_\_\_\_

# FACILITIES DAMAGE REPORT

## GAS

Vectren Claims Camera:  
**VE03767**  
4

DAMAGE SITE:  
Address 213 S. DEXTER AVE Lot # \_\_\_\_\_  
County VANDERBURGH City EVANSVILLE State IN Township Knight City

FACILITY TYPE:  
 Distribution  Propane  
 Service  Storage  
 Transmission: (include supplemental report)

FACILITIES DAMAGED:	ORIFICE SIZE(S):	(1)	(2)	(3)
<input type="checkbox"/> Farm Tap	0.50 inch	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Heater	5/8 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Main	0.75 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Residential)	1.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Meter (Industrial / Commercial)	1.25 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Odorizer	2.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Regulator Station	3.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Relief Valve	4.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Riser	5.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Service Line	6.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Valve	10.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	12.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	16.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	20.00 inch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Other	Other			

VISUAL OBSERVATION AT DAMAGE SITE: 2/4  
Visual Observation:  Above Ground  Below Ground  
Locate Applicable  Yes  No  N/S  
Facilities Properly Marked  Yes  No  N/S  
Marking Methods:  Conventional  Flags  None  
 Offset  Paint  Stakes  Whiskers  
Locate Marking Faded:  Yes  No  N/S  
Wrong Address Requested  Yes  No  N/S

Facilities Improperly Located:  
 Qualified Locator Could Not Have Accurately Located  
 Inaccurate Maps / Cards  
 Broken or No Tracer Wire (Plastic)  
 Insulation Preventing Accurate Locate

Locator Error:  
 Failure to Follow Policy  
 Inappropriate Site Markings  
 Incomplete Locate  
 No Locates Performed  
 Qualified Locator Could Have Accurately Located  
 Wrong Address Located  
 Marking Off By: \_\_\_\_\_ (Feet / Inches)

TYPE OF MATERIAL: **DAMAGE TYPE:**  
 Cast Iron  Severed  
 Plastic (HDPE)  Not Cut  
 Plastic (MDPE)  Severed  
 Steel Size \_\_\_\_\_ x \_\_\_\_\_  
 Other PLASTIC - ALDYL

PRESSURE:  
 25 PSIG  
 40 PSIG  
 50 PSIG  
 55 PSIG  
 60 PSIG  
 6 WC (.2163)  
 7 WC (252)  
 Other

3.144

PROTECTION IN PLACE:  
 Building  Fence  None  
 Post  Rail  Vault  N/A  
 Other

DURATION OF ESCAPING GAS:  
Minutes: 5

LEAK REPORT NUMBER: \_\_\_\_\_

EFV Activated  Yes  No  N/S

Were Facility Marks Visible  Yes  No  
Was Area White Lined  Yes  No  Destroyed  
Positive Response  Yes  No  Destroyed  
Tolerance Zone Violated  Yes  No  
Part of Project  Yes  No  
Company Representative On-Site  Yes  No

FEED TYPE:  
 One-Way Feed  
 Two-Way Feed

Number of Customers Affected: 1  
Total Hours Service  
Was Off: \_\_\_\_\_

Observation by (ID#): 0460

Name of Locator: \_\_\_\_\_  
**LOCATING ORGANIZATION:**  
 Contract Locator  
 Unknown / Other  
 Utility Owner

SERVICE ORDER NUMBER: \_\_\_\_\_

DAMAGED BY:  
 Company Crew  
 Contractor  
 County  
 Developer  
 Farmer  
 Municipality  
 Property Owner/ Tenant  
 Railroad  
 State  
 Unknown  
 Utility  
 Vehicle Accident  
 Other

TYPE OF CONSTRUCTION:  
 Agriculture  
 Building Construction  
 Building Demolition  
 Cable TV  
 Curbs / Sidewalk  
 Drainage  
 Driveway  
 Electric  
 Engineering / Surveying  
 Fencing  
 Grading  
 Irrigation  
 Landscaping  
 Liquid Pipeline  
 Milling  
 Pole  
 Natural Gas  
 Public Transit Authority  
 Railroad Maintenance  
 Other

NOTIFICATIONS AND OTHER DETAILS OF LOCATE:

Locate Ticket: \_\_\_\_\_  
Date: \_\_\_\_\_ Time: \_\_\_\_\_ am / pm

TYPE OF REQUEST:  
 Regular Request  Emergency Request  
 Locate Company Notified  
Contact Name: \_\_\_\_\_  
Time Called: \_\_\_\_\_ am / pm  
Time Locator Arrived at the Site: \_\_\_\_\_ am / pm

Company Notified of Locate Near Critical Facilities  
 Yes  No  N/S  
Copy of Mark Out Request Provided Within 2 Working Days  
 Yes  No  N/S

ONE-CALL CENTER:  
 IUPPS  
 OUPS  
 Unknown

Vectren Claim Number: \_\_\_\_\_

**TYPE OF EQUIPMENT:**

- Auger
- Backhoe / Track hoe
- Boring
- Drilling
- Explosives
- Farm Equipment
- Grader / Scraper
- Hand Tools
- Milling Equipment
- Plow
- Probing Device
- Trencher
- Vacuum Equipment
- Vehicle
- Other \_\_\_\_\_

**ROOT DAMAGING CAUSE:**

- Abandoned Facility
- Deteriorated Facility
- Facility Could Not be Found/ Located
- Facility Was Not Located / Marked
- Failure to Maintain Clearance
- Failure to Maintain Marks
- Failure to Support Exposed Facility
- Failure to Use Hand Tools Where Required
- Improper Backfilling
- Incorrect Records / Maps
- Marking or Location Not Sufficient
- No Notification Made to One-Call
- One-Call Notification Error
- Previous Damage
- Wrong Information Provided
- Other \_\_\_\_\_

**CONTRACTOR REPAIRS:**

- Contractor Working for Vectren Made Repairs at Own Expense  
 Yes  No  N/S
- Contractor Repaired Damage  
 Yes  No  N/S

Name of Contractor: \_\_\_\_\_  
 # of Regular Hours; \_\_\_\_\_  
 # of Overtime Hours; \_\_\_\_\_  
 # of Regular Hours; \_\_\_\_\_  
 Crew Type: \_\_\_\_\_

**MATERIALS OR ROAD WORK:**

- Meter was replaced \_\_\_\_\_ (Stores Code)
- Regulator Was Replaced \_\_\_\_\_ (Stores Code)
- Temporary Asphalt Repair: \_\_\_\_\_ (sq. ft.)
- Permanent Asphalt Repair: \_\_\_\_\_ (sq. ft.)

**RIGHT OF WAY:**

- Dedicated Utility Easement
- Federal Utility Easement
- Pipeline
- Power / Transmission Line
- Private - Business
- Private - Easement
- Private - Land Owner
- Public - County Road
- Public - Interstate Highway
- Public - Other
- Public - State Highway
- Public - City Street
- Unknown

Did Excavator Notify You

- Yes  No

Excavation Required

- Yes  No

Media at Site

- Yes  No

Was There Ignition of Gas?

- Yes  No

INVOICE:

- Yes  No  N/S

**DAMAGING PARTY:**

Name: Miller Pipeline  
 Address: \_\_\_\_\_  
 City/ State/ Zip: \_\_\_\_\_  
 Phone: ( ) \_\_\_\_\_  
 Prepared / Investigated By: \_\_\_\_\_ Date: \_\_\_\_\_

**PARTY TO INVOICE:**

Name: \_\_\_\_\_  
 Address: \_\_\_\_\_  
 City/ State/ Zip: \_\_\_\_\_  
 Phone: ( ) \_\_\_\_\_  
 Reviewed by Field Supervisor: H. R. [Signature] Date: 2/4/13

1/4 Service Valve Tee Plastic - 169753

NORMAL NOTICE JOB EXTENSION JOB EXTENSION

Ticket : 1301160652 Date: 01/16/2013 Time: 10:16 Oper: SARAH.HEMINGER Chan:000  
 Old Tkt: 1301020903 Date: 01/02/2013 Time: 10:47 Oper: SARAH.HEMINGER Rev: 00A

State: IN Cnty: VANDERBURGH Twp: KNIGHT  
 Cityname: EVANSVILLE Inside: Y Near: N  
 Subdivision:

Address : 213  
 Street : S DEXTER AVE  
 Cross 1 : SYCAMORE ST Within 1/4 mile: Y  
 Location: PAINT AND FLAG ENTIRE PROPERTY AND BOTH SIDE OF S DEXTER AVE  
 \*\*\*Boring Where = S DEXTER AVE

:  
 Grids : 3758B8730A 3758B8730B 3758C8730A 3758C8730B  
 Boundary: n 37.975964 s 37.973225 w -87.513916 e -87.512222

Work type : RENEW GAS SERVICE  
 Done for : VECTREN  
 Start date: 01/18/2013 Time: 10:30 Hours notice: 48/048 Priority: NORM  
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N  
 Duration : 1 DAY Depth: 4FT

Company : MILLER PIPE LINE Type: CONT  
 Co addr : 8850 CRAWFORDSVILLE RD  
 City : INDIANAPOLIS State: IN Zip: 46234  
 Caller : SARAH HEMINGER Phone: (317)295-6417  
 Contact : TRAVIS WILKE CELL Phone:  
 BestTime:  
 Mobile : (812)568-9815  
 Fax : (317)295-6418  
 Email : SARAH.HEMINGER@MILLERPIPELINE.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 NEED ALL UTILITIES TO RETURN AND REMARK PREVIOUS TICKET 1301020903  
 Will you be white-lining the dig site area? NO  
 :

Submitted date: 01/16/2013 Time: 10:16  
 Members: ID0716 ID0723 ID2470 ID5347 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
EVANSVILLE WATER & SEWER UTILITY	SEWER & WATER
INSIGHT COMMUNICATIONS OF EVANSVILLE	CABLE TV
VECTREN - EVANSVILLE	GAS & ELECTRIC
WIDE OPEN WEST	CABLE TV



Property of United States Infrastructure Corporation  
Photo taken on 1/17/2013 11:12:12 AM



Property of United States Infrastructure Corporation  
Photo taken on 1/17/2013 11:12:16 AM



Property of United States Infrastructure Corporation  
Photo taken on 1/17/2013 11:12:20 AM



Property of United States Infrastructure Corporation  
Photo taken on 1/31/2013 4:22:16 PM



Property of United States Infrastructure Corporation  
Photo taken on 2/1/2013 8:01:31 AM

Thursday, February 7, 2013

# Service Order Status

**Enter Service Order Number:**

2179698



[Clear Form](#) [Refresh Data](#)

**Banner Instance:**  CS03PROD  CS01PROD  CS02PROD

**Order Number:** S2179698

**Order Type:** INVE

**Order Status:** Completed

**Customer:** 300354758 - HOUSTON LARRY N  
**Prem:** 1161883 - 213 S DEXTER AVE

**Technician:** 0460 - Ellis, Keith

**Order Dates and Times**

**Need Date:** 1/31/2013 2:19:00 PM  
**Time Created:** 1/31/2013 2:15:05 PM  
**Time Dispatched:** 1/31/2013 2:15:05 PM  
**Time In Route:** 1/31/2013 2:15:25 PM  
**Time On-Site:** 1/31/2013 2:22:48 PM  
**Tech Complete:** 1/31/2013 3:09:11 PM  
**Time Closed:** 1/31/2013 3:09:11 PM

**Events Performed/Completion Code**

IVEG - CMP

**Meter Information****Current ReadStatus**

**Old Meter:**

**New Meter:**

**Completion Notes**

crew on site

**Request Notes**

01/31/13 DON BURNS # 812-568-5238 W/ VECTREN CALLED AND ADV MILLER CREW ISON SITE AND HIT A SVC 'T' IN 1.25 INCH PLASTIC MAIN. WILL BE ON SITE.XST-- WALUT

**MDSI Event Dates and Times**

Event	Date/Time	User
AsnAssignmentEnRoute_evt	1/31/2013 2:15:25 PM	Ellis, Keith
AsnAssignmentManualAck_evt	1/31/2013 2:15:27 PM	Ellis, Keith
AsnAssignmentOnSite_evt	1/31/2013 2:22:48 PM	Ellis, Keith
OrdOrderComplete_evt	1/31/2013 3:09:11 PM	Ellis, Keith

NOTE: The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.



Property of United States Infrastructure Corporation  
Photo taken on 1/17/2013 11:12:24 AM



Property of United States Infrastructure Corporation  
Photo taken on 1/17/2013 11:12:30 AM

DAMAGE SEE REMARK

Ticket : 1301311685 Date: 01/31/2013 Time: 16:41 Oper: SPEOPLES Chan:036

State: IN Cnty: VANDERBURGH Twp: KNIGHT  
 Cityname: EVANSVILLE Inside: Y Near: N  
 Subdivision:

Address : 213  
 Street : S DEXTER AVE  
 Cross 1 : E SYCAMORE ST Within 1/4 mile: Y  
 Location: PAINT AND FLAG ENTIRE PROPERTY AND BOTH SIDE OF S DEXTER AVE  
 \*\*\*Boring Where = S DEXTER AVE

:  
 Grids : 3758B8730A 3758B8730B 3758C8730A 3758C8730B  
 Boundary: n 37.975964 s 37.973225 w -87.513916 e -87.512222

Work type : RENEW GAS SERVICE  
 Done for : VECTREN  
 Start date: 01/31/2013 Time: 16:42 Hours notice: 0/000 Priority: EMER  
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: Y  
 Duration : 1 DAY Depth: 4 FEET


Company : MILLER PIPE LINE Type: CONT  
 Co addr : 8850 CRAWFORDSVILLE RD  
 City : INDIANAPOLIS State: IN Zip: 46234  
 Caller : TRAVIS WILKE Phone: (317)295-6417  
 Contact : TRAVIS WILKE CELL Phone:  
 BestTime:  
 Mobile : (812)568-9815  
 Fax : (317)295-6418  
 Email : SARAH.HEMINGER@MILLERPIPELINE.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 PER TRAVIS - GAS LINE IS DAMAGED - UTILITY IS VECTREN - LINE WAS DAMAGED ON THE  
 EAST SIDE OF THE PROPERTY IN THE STREET AT 213 S DEXTER AVENUE - DESCRIPTION OF  
 LINE IS APPROX 1/2 INCH AND PLASTIC AND GREY IN COLOR - HAVE NOT CALLED 911 -  
 HAVE ADVISED TO CALL 911 - CREW IS ON SITE - VECTREN HAS BEEN NOTIFIED AND IS  
 CURRENTLY ON SITE - PREVIOUS TICKET NUMBER 1301160652 - THANK YOU  
 Will you be white-lining the dig site area? NO


:

Submitted date: 01/31/2013 Time: 16:41  
 Members: ID0716 ID0723 ID2470 ID5347 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
EVANSVILLE WATER & SEWER UTILITY	SEWER & WATER
INSIGHT COMMUNICATIONS OF EVANSVILLE	CABLE TV
VECTREN - EVANSVILLE	GAS & ELECTRIC
WIDE OPEN WEST	CABLE TV




Property of United States Infrastructure Corporation  
Photo taken on 1/31/2013 4:22:44 PM




Property of United States Infrastructure Corporation  
Photo taken on 1/31/2013 4:23:30 PM



Property of United States Infrastructure Corporation  
Photo taken on 1/31/2013 4:23:38 PM



Property of United States Infrastructure Corporation  
Photo taken on 1/31/2013 4:23:46 PM



Property of United States Infrastructure Corporation  
Photo taken on 1/31/2013 4:24:26 PM



Property of United States Infrastructure Corporation  
Photo taken on 1/31/2013 4:24:36 PM



Property of United States Infrastructure Corporation  
Photo taken on 1/31/2013 4:24:52 PM



Property of United States Infrastructure Corporation  
Photo taken on 1/31/2013 4:25:24 PM



Property of United States Infrastructure Corporation  
Photo taken on 2/1/2013 8:01:59 AM



Property of United States Infrastructure Corporation  
Photo taken on 2/1/2013 8:03:51 AM



**INFORMATION REQUEST**

State Form 54909 (R / 3-13)

INDIANA UTILITY REGULATORY COMMISSION – PIPELINE SAFETY DIVISION

Case Number: 4446

Date of Damage (month, day, year): January 31, 2013

---

**Location of Damage:**

Address (number and street): 213 S. Dexter Ave

City, State and ZIP Code: Evansville, IN

Nearest Intersection: S. Dexter and Sycamore Str.

---

**Excavator Information:**

Business Name: Miller Pipeline

Responsible Party Personal Name: Joseph Cansdale

Title (if any): Foreman

Address (number and street): 8850 Crawfordsville Rd.

City, State and ZIP Code: Indianapolis, IN 46234

Preferred Telephone Number (area code): 317 293 0278

Email Address: info@millerpipeline.com

---

**Utility Information:**

Utility Name: Vectren

Contact Person: \_\_\_\_\_

Title (if any): \_\_\_\_\_

**Cause of Damage Information**

Type of Equipment (*select one*):

Backhoe/Trackhoe

Type of Work Performed (*select one*):

Natural Gas

Repair Cost: \$ \_\_\_\_\_

Did a leak result from damage:  Yes  No

Was there ignition:  Yes  No

Excavator Notify 911 due to leak:  Yes  No

Excavator Notify 811 upon damage:  Yes  No

Excavator Notify Utility upon Damage:  Yes  No

---

**Locate Information**

Excavator Request Locate:  Yes  No

Indiana 811 Locate Ticket Number: 1301160652

Locate Marks Visible:  Yes  No

Locate Marks Correct:  Yes  No

Excavator "White Lined":  Yes  No

Was Locate Provided within Two (2) Working Days:  Yes  No

Utility Employees On-site during Excavation:  Yes  No

---

**Incident Information:**

Fire Department Response:  Yes  No

Police Department Response:  Yes  No

Ambulance Response:  Yes  No

---

**Additional Information / Comments**

We were digging a bell hole for a service renewal and hand spotted main and found service tee for house across the street (214 S. Dexter). We began digging down 2 feet away from main and locate marks and when back-hoe operator curled his bucket he struck gas service 45" away from locate marks. see drawing and photos enclosed

Printed Name: Ralph Miller

Signature: Ralph Miller

Date (month, day, year): April 10, 2013

*\*If submitting this form electronically, typing your name in the signature box will act as an electronic signature.*

**Please return completed form to:**

**[PipelineDamageCase@urc.in.gov](mailto:PipelineDamageCase@urc.in.gov)**

**Or mail to:**

**Indiana Utility Regulatory Commission  
Pipeline Safety Division - Case Number 4446  
101 West Washington Street, 1500E  
Indianapolis, IN 46204**

**Or fax to:  
317-233-2410**

NORMAL NOTICE JOB EXTENSION JOB EXTENSION

Ticket : 1301160652 Date: 01/16/2013 Time: 10:16 Oper: SARAH.HEMINGER Chan:000  
 Old Tkt: 1301020903 Date: 01/02/2013 Time: 10:47 Oper: SARAH.HEMINGER Rev: 00A

State: IN Cnty: VANDERBURGH Twp: KNIGHT  
 Cityname: EVANSVILLE Inside: Y Near: N  
 Subdivision:

Address : 213  
 Street : S DEXTER AVE  
 Cross 1 : SYCAMORE ST Within 1/4 mile: Y  
 Location: PAINT AND FLAG ENTIRE PROPERTY AND BOTH SIDE OF S DEXTER AVE  
 \*\*\*Boring Where = S DEXTER AVE  
 :  
 Grids : 3758B8730A 3758B8730B 3758C8730A 3758C8730B  
 Boundary: n 37.975964 s 37.973225 w -87.513916 e -87.512222

Work type : RENEW GAS SERVICE  
 Done for : VECTREN  
 Start date: 01/18/2013 Time: 10:30 Hours notice: 48/048 Priority: NORM  
 Ug/Oh/Both: U Blasting: N Boring: Y Railroad: N Emergency: N  
 Duration : 1 DAY Depth: 4FT

Company : MILLER PIPE LINE Type: CONT  
 Co addr : 8850 CRAWFORDSVILLE RD  
 City : INDIANAPOLIS State: IN Zip: 46234  
 Caller : SARAH HEMINGER Phone: (317)295-6417  
 Contact : TRAVIS WILKE CELL Phone:  
 BestTime:  
 Mobile : (812)568-9815  
 Fax : (317)295-6418  
 Email : SARAH.HEMINGER@MILLERPIPELINE.COM

Remarks : All tickets are taken and processed on Eastern Daylight Time  
 NEED ALL UTILITIES TO RETURN AND REMARK PREVIOUS TICKET 1301020903  
 Will you be white-lining the dig site area? NO  
 :

Submitted date: 01/16/2013 Time: 10:16  
 Members: ID0716 ID0723 ID2470 ID5347 SBCIN SM

Member Name	Facility Types
AT&T - DISTRIBUTION	COMMUNICATIONS
EVANSVILLE WATER & SEWER UTILITY	SEWER & WATER
INSIGHT COMMUNICATIONS OF EVANSVILLE	CABLE TV
VECTREN - EVANSVILLE	GAS & ELECTRIC
WIDE OPEN WEST	CABLE TV

Dmg Tk# 130131685











# Case 4496 Drawing

213 S. Dexter Evansville IN

