

Indiana State Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>005106</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____  B. WING: _____	(X3) DATE SURVEY COMPLETED  <b>01/10/2022</b>
NAME OF PROVIDER OR SUPPLIER  <b>COMMUNITY HOSPITAL</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>901 MACARTHUR BLVD MUNSTER, IN 46321</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S 000	<p><b>INITIAL COMMENTS</b></p> <p>This visit was for a licensure review of negative pressure patient rooms per ISDH CSHCR: Program Advisory Letter Number: AC-2020-01-HOSP.</p> <p>Facility Number: 005106</p> <p>Date Of Survey: 1/11/2022</p> <p>The following patient rooms at Community Hospital were successfully verified as negative pressure: 3rd floor - Parkview Tower - Rooms: 3001, 3002, 3003, 3004, 3005, 3006, 3007, 3008, 3009, 3010, 3011, 3031 and 3032. 4th floor - Parkview Tower - Rooms: 4022, 4023, 4024 and 4025. 6th floor - Parkview Tower - Rooms: 6006, 6007, 6008 and 6009. 6th floor - West - Rooms: 685, 686 and 689. 3rd floor - South - Rooms: 343, 345, 346, 347, 348, 349, 350, 351 and 352. 3rd floor - North - Rooms: 301, 302, 303, 304, 305, 306, 307, 308 and 310.</p> <p>The following patient rooms failed to be successfully verified as negative pressure: None.</p> <p>The facility lacked visual pressure monitoring mechanism indicating the air pressure status of the rooms at all times, however facility checks the rooms daily, using a Wand Velocity Meter (Vaneometer) and maintains a log for same.</p> <p>QA: 01/14/2022</p>	S 000		

Indiana State Department of Health

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE