

SHARP-CRESTED WEIR
(No-End Contractions)

Figure 35-6A