STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G148	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING	(X3) DATE SURVEY COMPLETED 11/06/2013

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
CDC INC	107 S COUNTRYBROOK MONTICELLO, IN 47960

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K010000	A Life Safety Code Recertification Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j). Survey Date: 11/06/13 Facility Number: 000684 Provider Number: 15G148 AIM Number: 100243120 Surveyors: Dennis Austill, Life Safety Code Specialist; Brett Overmyer, Life Safety Code Specialist; Libby Fruth, Life Safety Code Specialist At this Life Safety Code survey, CDC Inc. was found not in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies. This one story facility was determined to be nonsprinklered. The facility has a fire alarm system with smoke detection in corridors, in client rooms and in common living areas. The facility has the capacity for 7 and had a census of 6 at the time of	K010000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE (X6) DATE

Any defiencystatement ending with an asterisk (*) denotes a deficency which the institution may be excused from correcting providing it is determined that other safegaurds provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G148	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING	(X3) DATE SURVEY COMPLETED 11/06/2013
NAME OF PROVIDER OR SUPPLIER CDC INC		STREET ADDRESS, CITY, STATE, ZIP CODE 107 S COUNTRYBROOK MONTICELLO, IN 47960	

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 3.6. Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 11/14/13. The facility was found not in compliance with the aforementioned regulatory requirements as evidenced by:			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	X2) MULTIPLE CONSTRUCTION	X3) DATE SURVEY COMPLETED
	15G148	A. BUILDING 01 B. WING	11/06/2013

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
CDC INC	107 S COUNTRYBROOK MONTICELLO, IN 47960

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K01S150	483.470(j)(1)(i) LIFE SAFETY CODE STANDARD New draperies, curtains, and other similar loosely hanging furnishings and decorations in board and care facilities are in accordance with provisions of 10.3.1. 32.7.5.1, 33.7.5.1 Based on interview and observation, the facility failed to ensure 2 of 2 sets of curtains in bedroom # 3 were flame resistant. LSC Section 10.3.1 requires draperies, curtains, and other similar loosely hanging furnishings and decorations shall be flame resistant as demonstrated by testing in accordance with NFPA 701, Standard Methods of Fire Tests for Flame Propagation of Textiles and Films. This deficient practice could affect all clients in the facility. Findings include Based on observation with the Health & Safety Specialist during a tour of the facility from 12:45 p.m. to 1:30 p.m. on 11/06/13, two sets of window curtains were provided in bedroom # 3 which lacked documentation of flame resistance. Based on interview it was acknowledged by the Health & Safety Specialist at the time of observation, the curtains were new and documentation of flame resistance for the window curtains was not available and indicated the curtains	K01S150	Tag K0150Upon surveyors leaving the Health & Safety Specialistcontacted Goodwin Fire Equipment to see what was needed to implement safetyimmediately. A checklist was implemented and trained on for staff to ensurethat the curtains will remain flame resistance. Group home staff removedcurtains washed and dried according to label and sprayed with flame retardantagent. Monitoring of the checklist will be done by Group home Supervisor, ifthe curtains needed to be laundered the staff would reapply agent and chart onchecklist. Group home Supervisor will be notified that the curtains have beensprayed with agent. Health & Safety will monitor this also bi-monthly fromhouse inspection checklist and Quality Inspection reports.	11/30/2013

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G148	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING	(X3) DATE SURVEY COMPLETED 11/06/2013

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
CDC INC	107 S COUNTRYBROOK MONTICELLO, IN 47960

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	would be treated with a flame retardant.			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G148	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING	X3) DATE SURVEY COMPLETED 11/06/2013
NAME OF PROVIDER OR SUPPLIER CDC INC		STREET ADDRESS, CITY, STATE, ZIP CODE 107 S COUNTRYBROOK MONTICELLO, IN 47960	

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K01S155	483.470(j)(1)(i) LIFE SAFETY CODE STANDARD Where a required fire alarm system is out of service for more than 4 hours in a 24-hour period, the authority having jurisdiction shall be notified, and the building shall be evacuated or an approved fire watch shall be provided for all parties left unprotected by the shutdown until the fire alarm system has been returned to service. 9.6.1.8			
	Based on record review and interview, the facility did not have a complete policy to address the fire alarm system being out of service for four hours or more in a 24 hour period to protect 4 of 4 clients. This deficient practice could affect all occupants of the facility if a fire should occur while the fire alarm system was not working. Findings include: Based on a review of the "Fire Watch Policy and Procedure" with the Health & Safety Specialist on 11/06/13 at 1:00 p.m., the following was noted: a. The policy and procedure lacked complete verbiage indicating the fire watch notification would occur when the fire alarm is out of service for "four hours or more in a 24 hour period." Instead , the policy and procedure indicated notification will occur when the fire alarm is out of service for more than four hours. b. The policy and procedure did not	K01S155	Tag K0155Upon surveyors leaving the Health & Safety Specialistupdated the Fire Watch Policy and Procedure. A training of staff was done byGroup Home Supervisor to ensure all staff knows how, when to implement the policy.Monitoring to ensure staff knows how to implement the policy will be donebi-monthly by Qualified Supervisor Staff. Monitoring will be done by QualityInspections and verbal assessment of staff. Health & Safety will beinformed of policy needing updated as needed.	11/30/2013

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15G148	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING	(X3) DATE SURVEY COMPLETED 11/06/2013

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
CDC INC	107 S COUNTRYBROOK MONTICELLO, IN 47960

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	indicate the person conducting the fire watch will be trained and will perform no other duties while conducting the fire watch. Based on interview at the time of record review, the Health & Safety Specialist acknowledged the policy and procedure lacked the verbiage of "four hours or more in a 24 hour period" and the person conducting the fire watch will be trained and will perform no other duties while conducting the fire watch.			