| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: | (X2) MULTIPLE CONSTRUCTION | (X3) DATE SURVEY COMPLETED |
|---|---|---|---|
| | 155836 | A. BUILDING **01**<br>B. WING _____ | **06/18/2025** |

| NAME OF PROVIDER OR SUPPLIER | STREET ADDRESS, CITY, STATE, ZIP CODE |
|---|---|
| **CUMBERLAND TRACE HEALTH & LIVING COMMUNITY** | **1925 REEVES ROAD**<br>**PLAINFIELD, IN 46168** |

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETION DATE |
|---|---|---|---|---|
| E 000 | Initial Comments<br><br>An Emergency Preparedness Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.73.<br><br>Survey Date: 06/18/25<br><br>Facility Number: 013455<br>Provider Number: 155836<br>AIM Number: 201293440<br><br>At this Emergency Preparedness survey, Cumberland Trace Health and Living Community was found in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73<br><br>The facility has 104 certified beds. At the time of the survey, the census was 100.<br><br>Quality Review completed on 06/23/25 | E 000 | | |
| K 000 | INITIAL COMMENTS<br><br>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a).<br><br>Survey Date: 06/18/25<br><br>Facility Number: 013455<br>Provider Number: 155836<br>AIM Number: 201293440<br><br>At this Life Safety Code survey, Cumberland Trace Health and Living Community was found in compliance with Requirements for Participation | K 000 | | |

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE | (X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: | (X2) MULTIPLE CONSTRUCTION | (X3) DATE SURVEY COMPLETED |
|---|---|---|---|
| | 155836 | A. BUILDING **01**<br>B. WING _____ | **06/18/2025** |

| NAME OF PROVIDER OR SUPPLIER | STREET ADDRESS, CITY, STATE, ZIP CODE |
|---|---|
| **CUMBERLAND TRACE HEALTH & LIVING COMMUNITY** | **1925 REEVES ROAD**<br>**PLAINFIELD, IN 46168** |

| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) | (X5) COMPLETION DATE |
|---|---|---|---|---|
| K 000 | Continued From page 1<br>Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety From Fire and the 2012 Edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.<br><br>This one-story facility was determined to be of Type V (111) construction and fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors, in all areas open to the corridors and has hard wired smoke detectors installed in all resident rooms. The facility has a capacity of 104 and had a census of 100 at the time of this visit.<br><br>All areas where residents have customary access were sprinklered. All areas providing facility services were sprinklered except for one detached storage building which was not sprinklered.<br><br>Quality Review completed on 06/23/25 | K 000 | | |