STATE of INDIANA

INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

http://www.in.gov/iurc
Office: (317) 232-2701
Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Anderson Construction

UPPAC Database Record ID: 1119

Investigator: Howard Friend
Telephone: (317) 232-2717
Report Date: 01/17/2012

Damage Date: 08/09/2010
Damage Address: 118 N East St
City: Greenfield
County: Hancock

The Parties

Excavator: Anderson Construction
Commercial Business
Contact: Carlos Anderson
Address: 2586 S State Road 9, Greenfield, In 46140
Telephone: (317) 727-5840

Facility Owner: Vectren
Contact: Darlene Kulhanek, Manager, Facilities Damages
Address: 1 N Main Street, Evansville, IN 47702

Pipeline Facility

Facility Type: Natural Gas
Facility Function: Service/Drop

Pipeline Safety Division Investigation Report

Investigation regarding: **Anderson Construction**

UPPAC Database Record ID: 1119

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: Yes

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): $802

Excavator Activities

Indiana 811 Locate Request Number: NA

Excavation Equipment: Backhoe/Trackhoe

Nature of Excavation: Curb/Sidewalk

Synopsis: 1 1/4" steel low pressure natural gas service damaged by backhoe during the removal of a section of sidewalk.

Findings: Reported by Indiana 811; excavator signed for initial mailing on 09/27/2011. From documents submitted, it seems that the service was directly under the sidewalk, however, excavator failed to request locates prior to beginning work.

Conclusion: Excavator failed to provide notice of excavation.

Violation: IC 8-1-26-16(g): Failure to provide notice of excavation.

Anderson Construction has no other damage reports in the record.

NO

LOCATE

TICKET

PROVIDED

STATE of INDIANA

INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

http://www.in.gov/iurc
Office: (317) 232-2701
Facsimile: (317) 232-6758

September 20, 2011

Ms. Darlene Kulhanek
Vectren
1 N Main Street
Evansville, IN 47702

RECEIVED
SEP 23 2011
INDIANA UTILITY
REGULATORY COMMISSION

Subject: Investigation Request for Information

Date of Event: 8/9/2010

Event Location: 118 N East St., Greenfield

Facility Owner: Vectren

Excavator: Anderson Construction

Other Party: N/A

Pipeline Division Case No. 1119

Dear Ms. Kulhanek:

Pursuant to Indiana Code 8-1-26, the *Indiana Damage to Underground Facilities Act*, the Pipeline Safety Division of the Indiana Utility Regulatory Commission ("Pipeline Division") is required to investigate reported incidents of alleged statutory violations involving underground pipeline safety. The purpose of this statute is to promote excavation and pipeline safety and to reduce the imminent danger to life, health, property, or loss of service associated with unsafe digging practices. Please note that the investigation does not entail determining criminal liability or a civil determination of fault or damages; however, it does determine whether any statutory violations were committed regarding public safety.

The Pipeline Division received information regarding potential statutory violations regarding the date and location referenced above. You were identified as a person or entity that might have information that would assist the Pipeline Division in its investigation. Therefore, we have contacted you in order to receive the full account of information in order to make a fair determination related to the circumstances of this incident.

We have asked all involved parties, entities and witnesses to provide *written* information within *30 days* in order to meet legal deadlines to conclude our investigation. **Please consider this letter as a formal request to receive any and all information and evidence (including a narrative, documentation,**

maps, photographs or any other written information) you can access regarding anything you may know about the incident referenced above.

Please promptly provide your information to: Pipeline Safety Division – Case No. 1119, Indiana Utility Regulatory Commission, 101 West Washington Street, # 1500E, Indianapolis, IN 46204. Also, please include the Investigation Number referenced above on your materials. In the alternative, if you would prefer to scan the materials and send them electronically, please send the documents to: *PipelineDamageCase@urc.in.gov.*

Although you are not a formal party in this investigation, please treat this request for information seriously, because the potential civil penalties for violations include: a potential civil fine up to $10,000.00; mandatory education and training for employees regarding pipeline safety; a required development plan to avoid future violations; or a warning letter for certain homeowner/tenants who are first time offenders. Consequently, your input will assist the Pipeline Division with its determination and may have a substantial impact on the case.

After the investigation is completed, the Pipeline Division will prepare an Investigation Report with findings and forward it to the Underground Plant Protection Advisory Committee ("Advisory Committee"). This is a statutory committee, comprised of excavators, facility operators, investor and municipal utilities, the 811 Association and facility locate marking companies, whose role is to evaluate the Pipeline Division's findings and make a recommendation for a civil penalty. In the event there is disagreement regarding the Advisory Committee's recommendation to the Commission, parties are entitled to request a hearing before the full Commission. If there is a violation, the Indiana Utility Regulatory Commission ("Commission") will impose the penalty. Any fines imposed are statutorily required to be spent funding the Commission's training and educational programming to promote excavation and pipeline safety.

Thank you for your *prompt* assistance in providing written information to the Pipeline Division regarding the previously referenced incident. Any information received after the deadlines will not be considered in the investigation, will be unavailable to the Advisory Committee and will result in a lack of full information being made available; hence, your participation is vital to serving the interests of justice and enhancing the public's safety. In an effort to assist you, please find an enclosure entitled "Information Request." Should you have procedural or legal questions regarding the Underground Plant Protection Advisory Committee or the Indiana Utility Regulatory Commission, please contact David L. Welch, Assistant General Counsel, at (317) 234-4715. Should you have questions regarding the pipeline damage identified above, or our investigation, please contact me at (317) 232-2718. Thank you for your assistance.

Sincerely,

William Boyd

William Boyd
Director, Pipeline Safety Division

Enclosure: Information Request

Information Request

Pipeline Safety Division
Indiana Utility Regulatory Commission

The Pipeline Safety Division of the Indiana Utility Regulatory Commission requests any and all information you can provide regarding the following criteria:

The Parties:

Excavator Infonnation:
Business Name: **Anderson Construction**

Responsible Party Personal Name: **Uknown**

Title (if any): Unknown

Address: 2586 S. State Rd 9

City, State Zip: Greenfield, IN 46140

Preferred Telephone:

Cell Phone Number:

Email Address:

Facility Information:
Business Name: **Vectren Energy**

Responsible Party Personal Name: **Darlene Kulhanek**

Title (if any): **Manager Facilities Damages**

City, State, Zip **Evansville, IN 47711**

Address: **1 Main Street**

Preferred Telephone: **812-491-4227**

Cell Phone Number: **812-568-5235**

Email Address: **Dkulhanek@vectren.com**

Locator Senrice Information:
Business Name: **USIC Inc.**

Responsible Patty Personal Name: **Tim Sanders**

Title (if any): **Southern Indiana District Manager**

Address: **3818 E Morgan Avenue**

City, State Zip: **Evansville, IN 47715**

Preferred Telephone: **812-479-9236**

Cell Phone Number:

Email Address: **timsanders@usicinc.com**

Other (Witness, Police, Fire, Othea·) Information: **Warrick Co Sheriff's Dept.**
Personal Contact: Business/Organization Name: N/A

Title (if any)

Address:

City, State, Zip

Preferred Telephone:

Cell Phone Number:

Emai l Address:

Utility Line Impact:

Product Type (circle one):
Natural Gas
Liquid Pipeline
Unk nown/Other

Facility Type (circle one):
Distribution
Gathering
Service/Drop
Transmission
Unknown/Other

Size (Diametea·/etc.): 1.25"

Pressure (PSIG/Inches): .2163 psig

Interruption in Service: Yes / No Numbea· of Customer·s Affected: 1

Evacuation: Yes / No If yes, How Many Evacuated? 0

Repair Cost (if known): $ 802.18

Cause of Damage Information:

Type of Equipment (circle one):
Auger
13ackhoe/Trackhoe
Boring /Drilling
Directional Drilling
Explosives
Farm Equipment
Grader/Scrapper
Hand Tools
Milling Equipment
Probing Device
Trencher
Vacuum Equipment
Unknown/Other

Type of Worl{ Performed (circle one):
Agriculture Cable
TV Curb/Sidewalk
Bldg. Construction
Bldg. Demolition
Drainage
Driveway Electric
Engineering/Surveying
Fencing
Grading
Irrigation
Landscaping
Liquid Pipeline
Milling
Natural Gas
Pole
Public Transit Authority
Railroad Maintenance
Road Work
Sewer (Sanitary/Stom1)
Site Development
Steam
Storm Drain/Culvert
Street Light
Telecommunications
Traffic Signal
Traffic Sign
Water
Waterway Improvement
Unknown/Other

Release of Product: Yes / No

Ignition and/or Fire: Yes / No

Excavator Notify 811: Yes / No

Locate Information:

Excavator Request Locate: Yes / No

Indiana 811 Locate Ticket Number: ___0

Locate Marks Visible: Yes / No

Locate Marl<s Correct: Yes/No

Excavator "White Lined": Yes / No

Maps Used to Mark Facilities: Yes / No

Was Locate Provided within Two (2) Worldng Days: Yes / No

Operator Employees On-site during Excavation: Yes / No

Incident Impact Information:

Number of Outpatient Treated: 0

Number of Inpatient Treated: 0

Number of Fatalities: 0

Fire Department Response: Yes / No

Police Department Response: Yes / No

Ambulance Response: Yes / No

Additional Information/Comments:

1.25" steel service severed by backhoe. Did not request locates.

VECTREN

Vectren Corporation
P.O. Box 209
Evansville, Indiana 47702-0209

November 25, 2010

VIA CERTIFIED MAIL; RETURN RECEIPT REQUESTED

ANDERSON CONSTRUCTION
2586 S. STATE ROAD 9,
GREENFIELD, IN 46140

Re:
Invoice #: FDS0012999
Description: 118 N East Street, Greenfield - 1 1/4" Steel Servcie Severed By Backhoe. Did Not Request Locates.
Damage Date: 8/9/2010
Balance: $802.18

Dear Sir or Madam:

You were notified on 9/1/2010 and again on 9/23/2010 regarding the above balance.

NOTICE: Payment must be made by December 7, 2010. If you fail to make payment, your account will be turned over to our collection agency.

To protect your credit rating and avoid any embarrassment this action will create, make payment by return mail or call me at 1-877-902-2934.

Sincerely,

Darlene Kulhanek
Manager Of Facilities Damages

cc: Laura Pamplin, General Counsel

NOW DUE

FINAL
$802.18

2 VECTREN ENERGY DELIVERY OF INDIANA - NORTH

ANDERSON CONSTRUCTION
2586 S. STATE ROAD 9,
GREENFIELD, IN 46140

Type: GAS
Invoice: FDS0012999
BillToID: 29040
Billing Date: 9/23/2010
Date of Loss: 8/9/2010
5833 103.0510

Please return this portion with your remittance.

Mail Payment To: VECTREN ENERGY DELIVERY OF INDIANA - NORTH
Vectren Utilities Holding Group, Inc.
1239 Reliable Parkway
Chicago, IL 60686-0012
Inquiries: 1-877-902-2934, Mon.-Fri., 8-5
Risk Management/Claims Department

NOW DUE
FINAL
$802.18

ANDERSON CONSTRUCTION
2586 S. STATE ROAD 9,
GREENFIELD, IN 46140

Type: GAS
Invoice: FDS0012999
BillToID: 29040
Billing Date: 9/23/2010
Date of Loss: 8/9/2010

Invoice For Costs to Repair and Reconstruct Damaged Property

Address: 118 N EAST STREET, GREENFIELD
1 1/4" STEEL SERVCIE SEVERED BY BACKHOE. DID NOT REQUEST LOCATES.

Material:	$89.36
Company Labor:	$640.65
Contract Labor:	$0.00
Transportation/Equipment:	$57.98
Misc:	$0.00
Gas Loss:	$14.19
Adjustments:	$0.00
Payments:	$0.00
Total:	$802.18

5833 103.0510

Remember, call two (2) working days before digging. Contact I.U.P.P.S. at 1-800-382-5544.

FACILITIES DAMAGE REPORT GAS
Vectren Corporation
Form 3112 (Rev. 10/04)

Task No.: 103.0510 Capital / O&M (circle one) FDS 0012999

☒ Indiana Gas
☐ Sigeco
☐ Vectren Energy Delivery of Ohio

TIME: 3:00 AM/PM DATE OF DAMAGE: 8/9/10

Cost Center No.: 5833

DAMAGE SITE ADDRESS: 118 N EAST ST.

LOT #: CITY: GREENFIELD

FACILITIES DAMAGED
☐ MAIN
☒ SERVICE
☐ REGUALTOR STATION
☐ FARM TAP
☐ RESIDENTIAL METER
☐ METER INDUSTRIAL/COMMERICAL
☐ OTHER

1.410

SIZE(S)
☐ 0.50 INCH
☐ 0.75 INCH
☐ 1.00 INCH
☐ 2.00 INCH
☐ 4.00 INCH
☐ 6.00 INCH
☒ OTHER 1¼

TYPE OF MATERIAL
☐ PLASTIC
☒ STEEL
☐ CAST IRON
☐ OTHER

DAMAGE TYPE
☒ SEVERED
☐ NOT CUT
☐ PUNCTURE
SIZE ____ X ____

PRESSURE
☐ 25 PSIG
☐ 40 PSIG
☐ 50 PSIG
☐ 60 PSIG
☒ 6 WC
☐ OTHER

1.100

PROTECTION IN PLACE
☐ RAIL ☐ POST ☐ NONE ☒ N/A

LEAK REPORT
539940
☒ ONE-WAY FEED
☐ TWO-WAY FEED

DURATION OF ESCAPING GAS
MINUTES 1 HR
EFV ACTIVATED ☐ YES ☒ NO

DAMAGED BY
☒ CONTRACTOR
☐ MUNICIPALITY/UTILITY
☐ VEHICULAR ACCIDENT
☐ COMPANY CREW
☐ UNKNOWN
☐ PROPERTY OWNER/TENANT
☐ OTHER

TYPE OF CONSTRUCTION
☐ SEWER/DRAIN
☐ WATER
☐ ELECTRIC
☐ TELEPHONE
☐ CEMENT/PAVING
☐ TV CABLE
☐ FENCING
☐ FOOTERS
☒ OTHER SIDEWALK

WORKING FOR
☒ CITY ☐ STATE ☐ PROPERTY OWNER
☐ OTHER
NAME ~~ANDERSON CONST.~~ City of Greenfield

TYPE OF EQUIPMENT
☒ BACKHOE
☐ TRACKHOE
☐ PLOW
☐ TRENCHER
☐ BULLDOZER
☐ POSTHOLE DIGGERS
☐ BORE
☐ AUGER
☐ STAKE/SHOVEL
☐ OTHER

DAMAGING PARTY
☒ DID NOT REQUEST LOCATES
☐ DID NOT HAND DIG
☐ USED EXPIRED LOCATES
☐ OTHER

NUMBER OF CUSTOMERS AFFECTED: 1

TOTAL HOURS SERVICE WAS OFF: 2.50

INVOICE: YES ☒ NO ☐

DAMAGING PARTY
NAME: ANDERSON CONST.
ADDRESS: 2586 S. St Rd 9
CITY/STATE/ZIP: GREENFIELD IN 46140

JACE GRINSTEAD 8-9-10
PREPARED BY DATE

VISUAL OBSERVATION AT DAMAGE SITE 1.10
☐ LOCATE NOT APPLICABLE (Above Ground Damage Only)
☐ FACILITIES PROPERLY MARKED
MARKING METHODS: ☐ CONVENTIONAL ☐ OFFSET ☐ FLAGS ☐ PAINT ☐ STAKES ☐ WHISKERS
LOCATE MARKINGS FADED: ☐ YES ☐ NO
☐ WRONG ADDRESS REQUESTED
☐ FACILITIES IMPROPERLY LOCATED
☐ QUALIFIED LOCATOR COULD NOT HA /E ACCURATELY LOCATED
☐ INACCURATE MAPS/CARDS
☐ BROKEN OR NO TRACER WIRE (PLASTIC)
☐ INSULATION PREVENTING ACCURATE LOCATE
☐ LOCATOR ERROR
☐ QUALIFIED LOCATOR COULD HAVE ACCURATELY LOCATED
☐ INCOMPLETE LOCATE
☐ MARKINGS OFF BY ____ (FEET/INCHES)
☐ INAPPROPRIATE SITE MARKINGS
☒ NO LOCATE PERFORMED
☐ FAILURE TO FOLLOW POLICY
☐ WRONG ADDRESS LOCATED
OBSERVATION BY: JACE GRINSTEAD
NAME OF LOCATOR:
☐ COPY OF MARKOUT REQUEST PROVIDED WITHIN 2 WORKING DAYS

AUG 17 2010

NOTIFICATION AND OTHER DETAILS OF LOCATE
☐ LOCATE TICKET #:
DATE: TIME: AM/PM
☐ REGULAR REQUEST ☐ EMERGENCY REQUEST
☐ LOCATE COMPANY NOTIFIED
CONTACT NAME:
TIME CALLED: AM/PM
TIME LOCATOR ARRIVED AT SITE: AM/PM
COMPANY NOTIFIED OF LOCATE NEAR CRITICAL FACILITIES:
☐ YES ☐ NO

CONTRACTOR REPAIRS
☐ CONTRACTOR WORKING FOR VECTREN MADE REPAIRS AT OWN EXPENSE
☐ CONTRACTOR REPAIRED DAMAGE
NAME OF CONTRACTOR:
OF REGULAR HOURS
OF OVERTIME HOURS
CREW TYPE

MATERIALS OR ROAD WORK
☐ METER WAS REPLACED ____ (STORES CODE)
☐ REGULATOR WAS REPLACED ____ (STORES CODE)
☐ TEMPORARY ASPHALT REPAIR ____ (SQ. FT.)
☐ PERMANENT ASPHALT REPAIR ____ (SQ. FT.)

PARTY TO INVOICE
NAME: ANDERSON CONST.
ADDRESS: 2586 S ST RD 9
CITY/STATE/ZIP: GREENFIELD IN 46140

8-12-10
REVIEWED BY FIELD SUPERVISOR DATE

INCLUDE ANY OBSERVATIONS ON BACK OF FORM OVER

CONTRACTOR DIDN'T CALL COLATES

Service Order Status

Thursday, September 22, 2011

Enter Service Order Number:
4504542 Go

Banner Instance: ○ CS03PROD ○ CS01PROD ◉ CS02PROD

Order Number: N4504542
Order Type: INVE
Order Status: Completed

Customer: 600449004 - MOORE ROBERT E
Prem: 5483195 - 118 N EAST ST

Technician: 6839 - Hicks, Jeremy

Order Dates and Times

Need Date:	8/9/2010 3:09:00 PM
Time Created:	8/9/2010 3:08:48 PM
Time Dispatched:	8/9/2010 3:08:48 PM
Time In Route:	8/9/2010 5:18:31 PM
Time On-Site:	8/9/2010 5:18:35 PM
Tech Complete:	8/9/2010 5:18:44 PM
Time Closed:	8/9/2010 5:18:44 PM

Events Performed/Completion Code
IVEG - CMP

Meter Information

	Current ReadStatus
Old Meter:	
New Meter:	

Completion Notes
GAS ON...CONT. HIT SERV. LINE...CREW FIXED THE SERV. ..RELIT AFTER REPAIRS WAS MADE...ALL LEAK TESTS ARE GOOD..APPL. ARE ALL RUNNING GOOD...LEFT SAFE...ARRIVED AT 3:10PM...

Request Notes
8-9-10 PER 811-HIT LINE BY ANDERSON CONST. NO LOC#. MTR ? PET? XST NORTH.CREW ONSITE.

MDSI Event Dates and Times

Event	Date/Time	User
AsnAssignmentEnRoute_evt	8/9/2010 4:21:24 PM	Hicks, Jeremy
AsnAssignmentManualAck_evt	8/9/2010 4:21:25 PM	Hicks, Jeremy
AsnAssignmentOnSite_evt	8/9/2010 4:21:33 PM	Hicks, Jeremy
AsnAssignmentEnRoute_evt	8/9/2010 5:18:31 PM	Hicks, Jeremy
AsnAssignmentOnSite_evt	8/9/2010 5:18:35 PM	Hicks, Jeremy
OrdOrderComplete_evt	8/9/2010 5:18:44 PM	Hicks, Jeremy

NOTE:The Reporting database replicates in near real-time; it has been approximately 0 minute(s) since the last transaction replicated.

MISCELLANEOUS CASH RECEIPT

(PLEASE ATTACH A COPY OF ALL CHECKS TO THIS FORM AND USE PAPER CLIPS/DO NOT STAPLE CHECKS TO FORM)

PROCESS ROUTING FOR ALL VECTREN COMPANIES INCLUDING UTILITIES AND NON_REGULATED SUBSIDIARIES: SEND COMPLETED FORM, ORIGINAL CHECK AND COPY OF CHECK TO REBECCA MINEAR IN FINANCIAL ACCOUNTING, BRAUN BUILDING, EVANSVILLE. RETAIN COPY OF CHECK AND FORM FOR YOUR RECORDS. PLEASE INCLUDE PROPER ACCOUNTING SO RECEIPT MAY BE CREDITED ACCURATELY. PLEASE INCLUDE YOUR PHONE NUMBER SO THE RECEIPT MAY BE EASILY RESEARCHED BY THE FINANCIAL ACCOUNTING GROUP.

Activity Date:	**12/20/2010 12:00:00 AM**
Your Name, not your initials (employee):	**DARLENE Kulhanek**
Your Phone Number (employee):	**812-491-4227**
Party Check Received From (Check Payor):	
Address of Check Writer (Check Payor):	

BATCH1-THE CINCINNATI INSURANCE COMPANY

Check Number	**211662859**
Amount of Check	**$802.18**
Utility/Company Name	**VECTREN ENERGY DELIVERY OF INDIANA - NORTH**
Task Number	**103.0510**
Job Number	**FDS0012999**

Date Printed: 12/27/2010

Transaction Information G-2337774 CHI-861239 2010/12/20

Back to Table of Contents

Transaction Level Details

Env Num	1	Envelope	G-2337774
Transaction	G-2337774	Lockbox	CHI-861239
Date	2010/12/20	Time	04:00
Batch	1	Batch Item	1
Check	1	Amount	$802.18
ABA/RT	042100272	Account Num	7480494827
Check Num	211662859		

Envelope and Check Image

PO BOX 145496 THE CINCINNATI INSURANCE COMPANY THE CINCINNATI INDEMNITY COMPANY
CINCINNATI OH 45250-5496 THE CINCINNATI CASUALTY COMPANY

Claim No:1441836 Date:12/15/2010 Check No: 211662859
Payable at The Fifth Third Bank Cincinnati,OH (513)870-0012

Amount: **********EIGHT HUNDRED TWO 18/100 DOLLARS

$ *********802.18

Pay To The Order Of VECTREN UTILITIES HOLDING GROUP IN
1239 RELIABLE PARKWAY
CHICAGO IL 60686

Steven J. Johnston

⑈211662859⑈ ⑆042100272⑆ 7480494827⑈

THE
CINCINNATI INSURANCE COMPANIES
THE CINCINNATI INSURANCE COMPANY THE CINCINNATI INDEMNITY COMPANY
THE CINCINNATI CASUALTY COMPANY THE CINCINNATI LIFE INSURANCE COMPANY
THE CINCINNATI SPECIALTY UNDERWRITERS INSURANCE COMPANY
PO BOX 145496
CINCINNATI OHIO 45250-5496
ADDRESS SERVICE REQUESTED

ADDRESS SERVICE REQUESTED

FIRST CLASS

UNITED STATES POSTAGE PITNEY BOWES
02 1M $ 00.44⁰
0004279151 DEC 15 2010
MAILED FROM ZIP CODE 45014

Transaction Level Keyed Data

Remitter Name : THE CINCINNATI INSURANCE COMPANY Check Date : 2010/12/15

Invoice Level Keyed Data

Invoice Number	Reference Number
FDS0012999	9999999

3342089

Check No 211662859

VECTREN UTILITIES HOLDING GROUP INC
1239 RELIABLE PARKWAY
CHICAGO IL 60686

Check No 211662859

CLAIM No	Policy Holder	Policy No	Loss Date	Claimant	Amount
1441836	ANDERSON CONSTRUCTION CO	05EPP0019945	08/09/2010	VECTREN UTILITIE	802.18
COVERAGE:CPP GL, BI & PD-Occur INVOICE: FOR:FDS0012999					
				Total	802.18

Mail: Pipeline Safety Division – Case No. 1119
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 E
Indianapolis, IN 46204

Email: PipelineDamageCase@urc.in.gov

RECEIVED
NOV 21 2011
INDIANA UTILITY
REGULATORY COMMISSION

ATTN: Bill Boyd - Director 317-232-2718
wboyd@urc.in.gov

Mr. Boyd,

I am asking for an extention - on case #1119 - Vectren - Anderson Construction
Loc: 118 N. East St. Greenfield, IN 46140

- Would some one meet me on the job?
- I'd like a chance to show someone this > I am not at fault on the damage to the gas line in Question!
  > The gas line is not burried - (CODE? GUIDE LINES)
  > This is not concidered a "DIG"
  > Replacing side walk - only lifted concre

The gas line in question was not under ground - and was Repaired just as installed - And I do not feel I am responcable for damage on their "improperly installed" gas line that should be under ground (not skimmed over by a very few inches of dirt.) Is nt there a safty code to gas line's? (DEPTH?)

* PLEASE CONTACT: CARLOS ANDERSON @ 317-727-5840
OPERATOR - OWNER

RECEIVED
AUG 21 2011
INDIANA UTILITY
REGULATORY COMMISSION

Mail: Pipeline Safety Division – Case No. 1119
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 E
Indianapolis, IN 46204

Email: PipelineDamageCase@urc.in.gov

Telephone 11/22/2011

ATTN: Bill Boyd - Director 317-232-2718
wboyd@urc.in.gov

Mr. Boyd,

I am asking for an extention - on case #1119 - Vectren - Anderson Construction
Loc: 118 N. East St. Greenfield, In 46140

- Would some one meet me on the Job?
- I'd like a chance to show someone this > I am not at fault on the damage to the gas line in Question!
  > The gas line is not burried - (CODE? GUIDE LINES)
  > This is not concidered a "DIG"
  > Replacing side walk - only lifted Concret

The gas line in question was not under ground - and was Repaired just as installed - And I do not feel I am responcable for damage on their "improperly - installed" gas line that should be under ground (not skimmed over by a very few inchis of dirt.) Is nt there a safty code to gas line's? (DepTA?)

Please contact me - Carlos Anderson 317-727-5840

PENCE, LOW & BROOKS INSURANCE
P.O. Box 825
Greenfield, IN 46140
Phone (317) 462-9204
Fax (317) 462-7284

To whom it may concern,

I was called by Carlos Anderson on 8-9-10 to 118 N. East St to look at a damaged gas line. The line was directly under the sidewalk. I would estimate about 6" under ground.

The gas company had several employees there and they also could not believe it was that shallow.

Gary L Pence
Pence Low Brooks Ins.

From the desk of:
Gary Pence

STATE OF INDIANA

INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500E
INDIANAPOLIS, INDIANA 46204-3407

http://www.in.gov/iurc
Office: (317) 232-2701
Facsimile: (317) 232-6758

February 10, 2012

Subject: In Re the Investigation of Anderson Construction
Case No.: 1119

Dear Anderson Construction,

As Legal Advisor to the Indiana Underground Plant Protection Advisory Committee ("Advisory Committee"), I write to provide you a copy of the Investigation Report and Findings filed by the Division of Pipeline Safety of the Indiana Utility Regulatory Commission ("IURC") regarding the matter referenced above.

As the Respondent in this matter, you have the right to appear at the meeting of the Advisory Committee when your case will be considered. As you may know, the Advisory Committee's consideration of your case is not a hearing and there will not be an opportunity to present additional evidence or witnesses. Pursuant to 170 IAC 5-5-3(e), you have the right to send additional evidence (correspondence, documents, photos, maps or drawings or whatever written materials you may wish to submit) as long as it is received by the Pipeline Safety Division at least seven (7) days prior to the date the Advisory Committee will decide your case. If any information is not received by the Pipeline Safety Division by that deadline, it will not be copied and provided to the members of the Advisory Committee for consideration.

Please forward any documentation to the following address or you may scan the materials and send them electronically. Be sure to include your assigned Pipeline Safety Division Case Number on all communications. Please add your Case Number and denote "INITIAL DOCUMENTS - EXCAVATOR" at the top of your materials or in the subject heading of your email.

Mail: Pipeline Safety Division – Case No. 1119
Indiana Utility Regulatory Commission
101 West Washington Street, Suite 1500 E
Indianapolis, IN 46204

Email: PipelineDamageCase@urc.in.gov

Your case is scheduled before the Advisory Committee on:

Date: Tuesday, February 28, 2012
Time: 10:00 a.m. Local Time
Location: Indiana 811 Office – 1433 Holey Moley Way, Greenwood, IN 46142

Earlier you were provided a copy of the Summary of Procedures and Respondent's Rights which provides an explanation of your rights regarding these matters. You can access this document at http://www.in.gov/iurc/2335.htm. Enclosed is a copy of the directions to the Indiana 811 Office.

Sincerely,

DeAnna L. Poon

DeAnna L. Poon
Legal Advisor, Advisory Committee
Assistant General Counsel, IURC

Attachments: Investigation Summary Report
Directions to Advisory Committee Meeting

STATE OF INDIANA

INDIANA UTILITY REGULATORY COMMISSION
101 W. WASHINGTON STREET, SUITE 1500B
INDIANAPOLIS, INDIANA 46204-3407

http://www.in.gov/iurc
Office: (317) 232-2701
Facsimile: (317) 232-6758

Pipeline Safety Division Investigation Report

Investigation regarding: Anderson Construction

UPPAC Database Record ID: 1119

Investigator: Howard Friend
Telephone: (317) 232-2717
Report Date: 01/17/2012

Damage Date: 08/09/2010
Damage Address: 118 N East St
City: Greenfield
County: Hancock

The Parties

Excavator: Anderson Construction
Commercial Business
Contact: Carlos Anderson
Address: 2586 S State Road 9, Greenfield, In 46140
Telephone: (317) 727-5840

Facility Owner: Vectren
Contact: Darlene Kulhanek, Manager, Facilities Damages
Address: 1 N Main Street, Evansville, IN 47702

Pipeline Facility

Facility Type: Natural Gas
Facility Function: Service/Drop

Pipeline Safety Division Investigation Report

Investigation regarding: Anderson Construction

UPPAC Database Record ID: 1119

Damage Impact

Product release: Yes

Ignition: No

Service Interruption: Yes

Number of Customers Affected: 1

Injuries: 0

Fatalities: 0

Repair Cost (if known): $802

Excavator Activities

Indiana 811 Locate Request Number: NA

Excavation Equipment: Backhoe/Trackhoe

Nature of Excavation: Curb/Sidewalk

Synopsis: 1 1/4" steel low pressure natural gas service damaged by backhoe during the removal of a section of sidewalk.

Findings: Reported by Indiana 811; excavator signed for initial mailing on 09/27/2011. From documents submitted, it seems that the service was directly under the sidewalk, however, excavator failed to request locates prior to beginning work.

Conclusion: Excavator failed to provide notice of excavation.

Violation: IC 8-1-26-16(g): Failure to provide notice of excavation.

Anderson Construction has no other damage reports in the record.

From Indianapolis: Take I65 South to exit 99 (Main Street) Turn right on Main Street and go West to Emerson Avenue. Turn Right on Emerson Avenue and go to Sierra Drive (Just Past Greenwood Self Storage) Turn Right on Sierra Drive and go to Holey Moley Way. Turn Right on Holey Moley Way to address 1433 Holey Moley Way.



From Louisville:Take I65 North to exit 99 Main Street) Turn left on Main Street and go West to Emerson Avenue. Turn Right on Emerson Avenue and go to Sierra Drive (Just Past Greenwood Self Storage) Turn Right on Sierra Drive and go to Holey Moley Way. Turn Right on Holey Moley Way to address 1433 Holey Moley Way.

RECEIVED
FEB 21 2012
INDIANA UTILITY REGULATORY COMMISSION

Indiana Pipeline Safety Div.
Advisory Comm. Case #1119 Anderson Const.

Dear Committee -

I would love to be at this hearing - But previous plans wont let me. Due to my flight send. 2-22-2012 and be out of State untill 3-7-2012. How ever I have asked my insurance agent to fax you the Photo's taken on site. They are located aprox - 3 blocks from the site. If more information is needed contact: Gary Pence 317-462-9204 @ the office of Pence, Lowe & Brooks Insurance - Greenfield

I would also like to know if the Gas Company codes they are to go by?

They Repaired this line at that location and left it the same way - If not worse - Making me having to Alter the Elevation by two or three inches to keep it from being in the concrete - And made a high spot in the Sidewalk.

When Replacing Sidewalks - All we do is lift up old concrete - Not fill or Diet

This line was only 4" to 6" from the "Top" of concrete - And is still that way.

On the side next to A small bank - there is a landscape timber - Aprox 6"-8" thic had to be "notched-out" in order for this gas line to go through the bottom.

They seem to Run their gas lines (in our area) Any way they want to) No Inspectors! (seems to turn them lose)
I would gladly Remove this section of Sidewalk (@ my expence) To let you see for your self. In the past — I also have had them to put their service gas line in the Same ditch with my water latteral ditch. I have called the local office to report it. And all they do is show up & look and do nothing. This was a private contractor they hired (Millers Pipeline) thats before they bought them out -
Thats why I'd like to know what their codes are on Depth and distance between other utility's - I have done this for almost 25 yrs. and Always called for locates if there was Any excavating that had to be done. I will be AVALible by phone if you have any Questions:

Carlos Anderson 317-727-5840
Anderson Construction Inc.
Greenfield In. 46140