STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	005023	A. BUILDING: _____ B. WING _____	04/20/2020

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ESKENAZI HEALTH	720 ESKENAZI AVENUE INDIANAPOLIS, IN 46202

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S 000	INITIAL COMMENTS This visit was for a licensure review of negative pressure patient rooms per ISDH CSHCR: Program Advisory Letter Number: AC-2020-01-HOSP. Facility Number: 005023 Survey Date: 4/20/2020 The following patient rooms were successfully verified as negative pressure: 5305, 5307, 5309, 5205, 5206, 5208, 5209, 5210, 5211, 5212, 6203, 6205, 6207, 6211. 6212, 6214, 6216, 6218, 6220, 6222, 7101, 7103, 7105, 7109, 7111, 7104, 7106, 7108, 7110, 7112, 7114, 5715, 5717, 5723, 5725, 5727, 5729, 5731, 5733, 5735, 5737, and 5739. The Building Management System (BMS) allows for activation of negative pressure and airflow monitoring in relation to corridors. "Neighborhoods" of 12 individual rooms that approximate units and halls are provided with 1 visual negative air pressure monitor as opposed to individual monitors for each room. The facility engineering staff checks and records vanometer recordings twice daily on a written log. The following patient rooms failed to be successfully verified as negative pressure and will be rescheduled: 1801, 1802, 1803, 1804, 1805, 1806, 1807, 1809, 1811, 1812, 1813, 1808, 1810, 1701, 1702, 1703, 1704, 1705, 1706, 1707, and 6213. QA: 4/27/2020	S 000		