STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155535	A. BUILDING **01, 02** B. WING _____	R **04/18/2023**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
WILLOW CROSSING HEALTH & REHABILITATION CENTER	**3550 CENTRAL AVE** **COLUMBUS, IN 47203**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{E 000}	Initial Comments A Post Survey Revisit (PSR) to the Emergency Preparedness Survey conducted on 03/20/23 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.73. Survey Date: 04/18/23 Facility Number: 000572 Provider Number: 155535 AIM Number: 100267710 At this PSR to the Emergency Preparedness survey, Willow Crossing Health & Rehabilitation Center was found in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73. The facility has 112 certified beds. At the time of the survey, the census was 93. Quality Review completed on 05/08/23	{E 000}		
{K 000}	INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Certification and State Licensure Survey conducted on 03/20/23 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a). Survey Date: 04/18/23 Facility Number: 000572 Provider Number: 155535 AIM Number: 100267710 At this PSR survey, Willow Crossing Health &	{K 000}		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE | (X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155535	A. BUILDING **01, 02** B. WING _____	R **04/18/2023**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
WILLOW CROSSING HEALTH & REHABILITATION CENTER	**3550 CENTRAL AVE** **COLUMBUS, IN 47203**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{K 000}	Continued From page 1 Rehabilitation Center was found in compliance with Requirements for Participation Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety From Fire and the 2012 Edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. This one story facility was determined to be of Type V (111) construction and fully sprinklered. The facility has a fire alarm system with]smoke detection in the corridors, all areas open to corridor and hard wired smoke detectors in all resident rooms. The facility has a capacity of 112 and had a census of 93 at the time of the survey. All areas where residents have customary access were sprinklered. All areas providing facility services were sprinklered. Quality Review completed on 05/08/23	{K 000}		
{K 000}	INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Certification and State Licensure Survey conducted on 03/20/23 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a). The new 300 Hall unit consists of occupational & physical therapy rooms and a 16 resident room, 32-bed locked unit, including resident rooms 301-318. Survey Date: 04/18/23 Facility Number: 000572 Provider Number: 155535	{K 000}		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155535	A. BUILDING **01, 02** B. WING _____	R **04/18/2023**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
WILLOW CROSSING HEALTH & REHABILITATION CENTER	**3550 CENTRAL AVE** **COLUMBUS, IN 47203**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{K 000}	Continued From page 2 AIM Number: 100267710 At this PSR survey, Willow Crossing Health and Rehabilitation Center was found in compliance with Requirements for Participation in Medicare, 42 CFR Subpart 483.90(a), Life Safety from Fire and the 2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 18, New Health Care Occupancies. This one story building was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridor and in all areas open to the corridor. The facility has smoke detectors hard wired to the building electrical system in the 300 Hall resident rooms with battery backup which report to the 300 Hall nurses' station. The facility has a capacity of 112 and had a census of 93 at the time of this survey. All areas where residents have customary access were sprinklered. All areas providing facility services were sprinklered. Quality Review completed on 05/08/23	{K 000}		