STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155196	A. BUILDING **01, 02** B. WING _____	R **10/17/2022**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ALTENHEIM HEALTH & LIVING COMMUNITY	**3525 E HANNA AVE** **INDIANAPOLIS, IN 46237**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{E 000}	Initial Comments A Post Survey Revisit (PSR) to the Emergency Preparedness Survey conducted on 08/15/22 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.73. Survey Date: 10/17/22 Facility Number: 000103 Provider Number: 155196 AIM Number: 100290000 At this PSR to the Emergency Preparedness survey, Altenheim Health and Living Community was found in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73. The facility has 87 certified beds. At the time of the survey, the census was 73. Quality Review completed on 10/17/22	{E 000}		
{K 000}	INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 08/15/22 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a). Survey Date: 10/17/22 Facility Number: 000103 Provider Number: 155196 AIM Number: 100290000 At this PSR to the Life Safety Code survey,	{K 000}		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE | (X6) DATE

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155196	A. BUILDING **01, 02** B. WING _____	R **10/17/2022**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ALTENHEIM HEALTH & LIVING COMMUNITY	**3525 E HANNA AVE** **INDIANAPOLIS, IN 46237**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{K 000}	Continued From page 1 Altenheim Health and Living Community was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety from Fire and the 2012 Edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. This facility consists of Building 01 and Building 02. Building 01 consists of the A, B and C wings of the first floor of a three story building with a basement and was determined to be of Type II (222) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection on all levels in the corridors and in all areas open to the corridor. The facility has smoke detectors hard wired to the building electrical system in the A, B and C wings. The two residential wings of the first floor were also surveyed due to lack of 2 hour separation. Building 02 consists of the one story Rehabilitation Wing constructed in 2014 and was determined to be of Type V (111) construction and was fully sprinklered. The Rehabilitation Wing has a fire alarm system with smoke detection in the corridors, in all areas open to the corridor and has smoke detectors hard wired to the fire alarm system in resident sleeping rooms. The facility has a capacity of 87 and had a census of 73 at the time of this survey. All areas where residents have customary access were sprinklered. All areas providing facility services were sprinklered. Quality Review completed on 10/17/22	{K 000}		
{K 000}	INITIAL COMMENTS	{K 000}		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155196	A. BUILDING **01, 02** B. WING _____	R **10/17/2022**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ALTENHEIM HEALTH & LIVING COMMUNITY	**3525 E HANNA AVE** **INDIANAPOLIS, IN 46237**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{K 000}	Continued From page 2 A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 08/15/22 was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a). Survey Date: 10/17/22 Facility Number: 000103 Provider Number: 155196 AIM Number: 100290000 At this PSR to the Life Safety Code survey, Altenheim Health and Living Community was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety from Fire and the 2012 Edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. This facility consists of Building 01 and Building 02. Building 01 consists of the A, B and C wings of the first floor of a three story building with a basement and was determined to be of Type II (222) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection on all levels in the corridors and in all areas open to the corridor. The facility has smoke detectors hard wired to the building electrical system in the A, B and C wings. The two residential wings of the first floor were also surveyed due to lack of 2 hour separation. Building 02 consists of the one story Rehabilitation Wing constructed in 2014 and was determined to be of Type V (111) construction and was fully sprinklered. The Rehabilitation Wing has a fire alarm system with smoke detection in	{K 000}		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155196	A. BUILDING **01, 02** B. WING _____	R **10/17/2022**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ALTENHEIM HEALTH & LIVING COMMUNITY	**3525 E HANNA AVE** **INDIANAPOLIS, IN 46237**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{K 000}	Continued From page 3 the corridors, in all areas open to the corridor and has smoke detectors hard wired to the fire alarm system in resident sleeping rooms. The facility has a capacity of 87 and had a census of 73 at the time of this survey. All areas where residents have customary access were sprinklered. All areas providing facility services were sprinklered. Quality Review completed on 10/17/22	{K 000}		