

RECEIVED

JUN 0 8 2021

COMMISSION STAFF

- INSTRUCTIONS: 1. Only a TYPED copy will be accepted.
  - 2. Dashed-line through-material to be deleted; underline or bold face material to be added.
  - 3. Use a second sheet for any material requiring more space.
  - 4. Return this completed form to: Indiana Department of Homeland Security, Code Services, 402 West Washington Street, Room W246, Indianapolis, Indiana 46204.



FOR OFFICE USE ONLY				
Received 6/8/202/ Code 675 IAC 21-/ Proposal number				
Code title				
Regulated lifting device -out of service if past due on safety test				
Section number and title 675IAC 21-1				Page number
Proponent  Bart Giesler  Representing (if applicable)  EIWPF				
Address (number and street, city, state, and ZIP code) 135 N Pennsylvania Street # 1175 Indianapolis, IN 46204				Telephone number ( 317 ) 696-1664
PROPOSED CODE CHANGE (check one)				
☐ Change to read as follows				
		T AND FISCAL IMPACT		
The Division needs to see firsthand an elevator operating without a permit and therefore cannot shutdown the regulated lifting device. If the owner had to put the lifting device out of service if it was more than 45days past the required test, the Division could then determine the regulated lifting device was not in compliance without actually seeing the device operate. Since the code says that an elevator that does not have a valid safety test is not in compliance, this simply has the owner take the device out of service.				
REVIEW RECOMMENDATION				
Approve				
Reject				
Approve as amended				
Further study				