




PROPOSAL FOR CODE CHANGE

State Form 41186 (R3 / 5-10)

RECEIVED IDHS JUN 08 2021 COMMISSION STAFF



- INSTRUCTIONS:**
1. Only a **TYPED** copy will be accepted.
 2. ~~Dashed-line through material to be deleted~~; underline or bold face material to be added.
 3. Use a second sheet for any material requiring more space.
 4. Return this completed form to: Indiana Department of Homeland Security, Code Services, 402 West Washington Street, Room W246, Indianapolis, Indiana 46204.

FOR OFFICE USE ONLY					
Received	6/8/2021	Code	675 IAC 21-1	Proposal number	

Code title		Edition	
Temporary elevator mechanic qualification -			
Section number and title		Page number	
675IAC 21-1-			
Proponent		Representing (if applicable)	
Bart Giesler		EIWPF	
Address (number and street, city, state, and ZIP code)			Telephone number
135 N Pennsylvania Street # 1175 Indianapolis, IN 46204			(317) 696-1664

PROPOSED CODE CHANGE (check one)

Change to read as follows
 Add to read as follows
 Delete and substitute as follows
 Delete without substitution

A temporary mechanic who fails the licensing exam offered by the state is not eligible for a temporary mechanic license. If the applicant has a temporary mechanic license, it shall be revoked as the applicant has demonstrated they do not have sufficient knowledge.

REASON STATEMENT AND FISCAL IMPACT

Since the mechanic failed the exam, they demonstrated that they do not have the experience and education to perform elevator construction, maintenance, or service and repair.

REVIEW RECOMMENDATION

Approve

Reject

Approve as amended

Further study