

Company		Mine
Gibson County Coal		Gibson South Mine
Inspection Date:	Wednesday, January 12, 2022 3rd Shift	
Areas Inspected:	Unit #3	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Thursday, January 20, 2022	
Areas Inspected:	3A, 3A5 beltlines and primary escapeways.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Monday, January 24, 2022	
Areas Inspected:	2A, 2B, 2A3, 2B11 beltlines and primary escapeways.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, February 1, 2022	
Areas Inspected:	2nd South East 2 Main beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Thursday, February 10, 2022	
Areas Inspected:	Unit #1	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	The unit looked great!	
Inspection Date:	Wednesday, February 16, 2022	
Areas Inspected:	4A, 4B 4C beltlines and 2C12, 2B8, 2A4 primary escapeways.	
Findings / Law(s) Violated:	75.1731(a)	
Corrective Actions Taken:	Addressed with management.	
Recommendation(s):	4A beltline needs dusted soon.	

cont...

Gibson County Coal		Gibson South Mine
Inspection Date:	Tuesday, February 22, 2022	
Areas Inspected:	2nd Southeast Main beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	Beltline looked great.	
Inspection Date:	Monday, February 28, 2022	
Areas Inspected:	1st Southeast #1 beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, March 9, 2022	
Areas Inspected:	Unit #4	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, March 16, 2022	
Areas Inspected:	4th North East beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, March 23, 2022	
Areas Inspected:	1st Northeast 3 beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, March 30, 2022	
Areas Inspected:	1st Southeast 2 beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	Beltline needs rock dusted.	

Company		Mine
Peabody Midwest Mining		Francisco Mine
Inspection Date:	Tuesday, January 4, 2022	
Areas Inspected:	2 Left 4 West submain and 4 Right off of 2 Left beltlines and primary escapeways.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, January 11, 2022	
Areas Inspected:	4th West Submain beltline and primary escapeway.	
Findings / Law(s) Violated:	75.1731(a), 75.363(b), 75.1100(2)(b)	
Corrective Actions Taken:	Addressed with management.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, January 26, 2022	
Areas Inspected:	Belt transformers 5006, 5018. 480v pumps #3, #4, #5, #6, #7. 110v pump XC 3 5 West beltline.	
Findings / Law(s) Violated:	18.67c, 75.512-2	
Corrective Actions Taken:	Both pumps were taken out of service.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, February 2, 2022	
Areas Inspected:	4th West Main belting and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, February 8, 2022	
Areas Inspected:	Unit #1	
Findings / Law(s) Violated:	75.323(b)(1)(ii)	
Corrective Actions Taken:	The operator hung the wing curtain and the face was monitored and methane was reduced.	
Recommendation(s):	None.	
Inspection Date:	Monday, February 14, 2022	
Areas Inspected:	Outby equipment permissibility	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	Good Job!	

cont...

Peabody Midwest Mining		Francisco Mine
Inspection Date:	Wednesday, February 23, 2022 -- 2nd Shift	
Areas Inspected:	Unit #3	
Findings / Law(s) Violated:	75.330(b)(2)	
Corrective Actions Taken:	The operator hung the needed ventilation curtain.	
Recommendation(s):	None.	
Inspection Date:	Thursday, March 3, 2022	
Areas Inspected:	8th Main West beltline	
Findings / Law(s) Violated:	75.1731(a)	
Corrective Actions Taken:	Addressed with management.	
Recommendation(s):	None.	
Inspection Date:	Monday, March 7, 2022	
Areas Inspected:	3rd Right beltline and primary escapeway, Unit #1	
Findings / Law(s) Violated:	75.333(c)(3), 75.211(d), 75.515	
Corrective Actions Taken:	Addressed with management.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, March 15, 2022	
Areas Inspected:	7th Main West beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Thursday, March 24, 2022	
Areas Inspected:	6th Main West beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Monday, March 28, 2022	
Areas Inspected:	5th Main West beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	

Company		Mine
Sunrise Coal		Oaktown Fuels #1 Mine
Inspection Date:	Tuesday, January 18, 2022	
Areas Inspected:	P1-15 and S1-D Beltlines and primary escapeways, BT-19 diesel scoop	
Findings / Law(s) Violated:	75.1100-3	
Corrective Actions Taken:	Fire extinguisher was taken out of service.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, January 25, 2022	
Areas Inspected:	M5A, M6, M7, M10, M15, M16, M7 secondary escapeways. M5, M5A beltlines and primary escapeways.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, February 9, 2022 2nd Shift	
Areas Inspected:	Unit #1	
Findings / Law(s) Violated:	75.809, 75.211(d)	
Corrective Actions Taken:	The breaker and receptacle was labeled and a slate bar was provided for the roof bolter.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, February 15, 2022	
Areas Inspected:	PM 16, PM 17 beltlines and primary escapeways.	
Findings / Law(s) Violated:	75.1722(b), 75.204(c)(1), 75.1722(b), 75.809	
Corrective Actions Taken:	The guarding was fixed, the bad roof bolt was dangered out, and the circuit breaker was labeled.	
Recommendation(s):	None.	
Inspection Date:	Monday, February 22, 2022	
Areas Inspected:	S4N, S4O beltlines and primary escapeways, Unit #4.	
Findings / Law(s) Violated:	75.515, 75.809	
Corrective Actions Taken:	Addressed with management.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, March 1, 2022	
Areas Inspected:	M17 beltline and primary escapeway.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	

cont...

Sunrise Coal		Oaktown Fuels #1 Mine
Inspection Date:	Thursday, March 10, 2022	
Areas Inspected:	Unit #3	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Monday, March 14, 2022	
Areas Inspected:	S1-D beltline and primary escapeway.	
Findings / Law(s) Violated:	75.1722(a), 75.380(d)(7)(vi), 75.601-1	
Corrective Actions Taken:	The violations were corrected by the operator.	
Recommendation(s):	None.	
Inspection Date:	Monday, March 21, 2022	
Areas Inspected:	M16, M9 1st Right, SC1 beltlines and primary escapeways.	
Findings / Law(s) Violated:	75.1731(a), 75.1731(a), 75.400, 75.380(d)(7)(vi)	
Corrective Actions Taken:	Addressed with management.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, March 29, 2022	
Areas Inspected:	M15 beltline and primary escapeway.	
Findings / Law(s) Violated:	75.601-1, 75.515	
Corrective Actions Taken:	Addressed with Management.	
Recommendation(s):	None.	
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company		Mine
Sunrise Coal		Oaktown Fuels #2 Mine
Inspection Date:	Wednesday, January 5, 2022	
Areas Inspected:	M10, M11 beltlines and primary escapeways, LBT14, LPDB-01, DVB#1, LBT29.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	The beltlines looked great.	
Inspection Date:	Wednesday, January 19, 2022 2nd Shift	
Areas Inspected:	M-8 and M-9 beltlines and primary escapeways.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Monday, January 31, 2022	
Areas Inspected:	PM 16, PM 16 1st left, S2C, S2D beltlines and primary escapeways.	
Findings / Law(s) Violated:	75.1403-5(g), 75.380(d)(7)(VI)	
Corrective Actions Taken:	Addressed with Management.	
Recommendation(s):	None.	
Inspection Date:	Monday, February 7, 2022	
Areas Inspected:	Unit #2	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Thursday, February 17, 2022	
Areas Inspected:	M7 beltline and intake air course.	
Findings / Law(s) Violated:	75.1731(a), 75.202(a)	
Corrective Actions Taken:	The operator scaled down the loose rib.	
Recommendation(s):	None.	
Inspection Date:	Thursday, February 24, 2022	
Areas Inspected:	M6 beltline and intake.	
Findings / Law(s) Violated:	75.380(d)(7)(vi)	
Corrective Actions Taken:	The operator removed the mandoor indicator from the lifeline.	
Recommendation(s):	None.	

cont...

Sunrise Coal		Oaktown Fuels #2 Mine
Inspection Date:	Wednesday, March 2, 2022	
Areas Inspected:	PM16 left return and beltline, S2C, S2D left and right returns.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, March 8, 2022	
Areas Inspected:	Unit #2	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Thursday, March 17, 2022	
Areas Inspected:	M4 beltline and primary escapeway.	
Findings / Law(s) Violated:	75.380(d)(7)(vi)	
Corrective Actions Taken:	The operator corrected the lifeline.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, March 22, 2022	
Areas Inspected:	M2, M3 beltlines and intake.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		