



NOTE: A CUTTING DIAGRAM CAN ALSO BE USED WHEN STIRRUPS ARE PLACED AT TWO DIFFERENT SPACINGS WITH TWO SEPARATE BAR MARKS. "NO. OF BARS" AND CUTTING DIAGRAM DIMENSIONS FOR EACH BAR MARK CAN BE SHOWN IN A TABLE.

CUTTING DIAGRAM

BENDING DIAGRAM

1901n X L
(1 BAR CUTS 2 STIRRUPS)

CUTTING DIAGRAM
(Hammerhead Stem Pier)
Figure 62-2CC