

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G721	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED  04/02/2014
--	---	--	---

NAME OF PROVIDER OR SUPPLIER  AWS	STREET ADDRESS, CITY, STATE, ZIP CODE 6835 W CR 950 N SCIPIO, IN 47273
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
--------------------	--	---------------	---	----------------------

K010000	<p>A Life Safety Code Recertification Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j).</p> <p>Survey Date: 04/02/14</p> <p>Facility Number: 004492 Provider Number: 15G721 AIM Number: 200512660</p> <p>Surveyor: Mark Bugni, Life Safety Code Specialist</p> <p>At this Life Safety Code survey, AWS was found not in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 32, New Residential Board and Care Occupancies.</p> <p>This one story facility was fully sprinkled. The facility has a fire alarm system with smoke detection in the corridors, in common living areas and hard wired smoke detectors in all client sleeping rooms. The facility has a capacity of 4 and had a census of 4 at the time of this survey.</p>	K010000		
---------	---	---------	--	--

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G721	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED  04/02/2014
--	---	--	---

NAME OF PROVIDER OR SUPPLIER  AWS	STREET ADDRESS, CITY, STATE, ZIP CODE 6835 W CR 950 N SCIPIO, IN 47273
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
--------------------	--	---------------	---	----------------------

	<p>Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Slow with an E-Score of 2.32.</p> <p>Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 04/07/14.</p> <p>The facility was found not in compliance with the aforementioned regulatory requirements as evidenced by the following:</p>			
--	--	--	--	--

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G721		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED  04/02/2014	
NAME OF PROVIDER OR SUPPLIER  AWS				STREET ADDRESS, CITY, STATE, ZIP CODE 6835 W CR 950 N SCIPIO, IN 47273			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
K01S056	<p>483.470(j)(1)(i) LIFE SAFETY CODE STANDARD PROMPT</p> <p>Where an automatic sprinkler system is installed, for either total or partial building coverage, the system is in accordance with Section 9.7 and initiates the fire alarm system in accordance with 32.2.3.4.1, 32.2.3.5.2. The adequacy of the water supply is documented to the authority having jurisdiction.</p> <p>Exception No. 1: In prompt evacuation facilities, an automatic sprinkler system in accordance with NFPA 13D, Standard for the Installation of Sprinkler Systems in One and Two Family Dwellings and Manufactured Homes, is permitted. Facilities with more than eight residents are permitted. Facilities with more than eight residents are treated as two-family dwellings with regard to water supply. Additionally, entrance foyers are sprinklered.</p> <p>Exception No. 2: Not applicable</p> <p>Exception No. 3: In prompt and slow evacuation capability facilities where an automatic sprinkler system is in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems, automatic sprinklers are not required in closets not exceeding 24 sq. ft and in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or material providing a 15 minute thermal barrier.</p> <p>Exception No. 4: In prompt and slow evacuation capability facilities up to and including four stories in height, systems in accordance with NFPA 13R, Standard for the Installation of Sprinkler Systems in</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G721	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED  04/02/2014
--	---	--	---

NAME OF PROVIDER OR SUPPLIER  AWS	STREET ADDRESS, CITY, STATE, ZIP CODE 6835 W CR 950 N SCIPIO, IN 47273
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	<p>Residential Occupancies up to an Including Four Stories in Height, are permitted.</p> <p>Exception No. 5: Not applicable</p> <p>Exception No. 6: Initiation of the fire alarm system is not required for existing installations in accordance with 33.2.3.5.5.</p> <p>SLOW Where an automatic sprinkler system is installed, for either total or partial building coverage, the system is in accordance with Section 9.7 and initiates the fire alarm system in accordance with 32.2.3.4.1. The adequacy of the water supply is documented to the authority having jurisdiction.</p> <p>Exception No. 2: In slow and impractical evacuation capability facilities, an automatic sprinkler system in accordance with NFPA 13D, Standard for the Installation of Sprinkler Systems in One and Two Family Dwellings and Manufactured Homes, with a 30 minute water supply, is permitted. All habitable areas and closets are sprinklered. Facilities with more than eight residents are treated as two family dwellings with regard to water supply.</p> <p>Exception No. 3: In prompt and slow evacuation capability facilities where an automatic sprinkler system is in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems, automatic sprinklers are not required in closets not exceeding 24 sq. ft. and in bathrooms not exceeding 55 sq. ft., provided that such spaces are finished with lath and plaster or material providing a 15 minute thermal barrier.</p> <p>Exception No. 4: In prompt and slow</p>			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G721	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED  04/02/2014
--	---	--	---

NAME OF PROVIDER OR SUPPLIER  AWS	STREET ADDRESS, CITY, STATE, ZIP CODE 6835 W CR 950 N SCIPIO, IN 47273
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
--------------------	--	---------------	---	----------------------

	<p>evacuation capability facilities up to and including four stories in height, systems in accordance with NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stories in Height, are permitted.</p> <p>Exception No. 5: Not Applicable</p> <p>Exception No. 6: Initiation of the fire alarm system is not required for existing installations in accordance with 32.2.3.5.5.</p> <p>MPRACTICAL Where an automatic sprinkler system is installed, for either total or partial building coverage, the system is in accordance with Section 9.7 and shall initiate the fire alarm system in accordance with 32.2.3.4.1. The adequacy of the water supply is documented to the authority having jurisdiction. 32.2.3.5.2.</p> <p>Exception No. 1: Not Applicable.</p> <p>Exception No. 2: In slow and impractical evacuation capability facilities, an automatic sprinkler system in accordance with NFPA 13D, Standard for the Installation of Sprinkler system in One and Two Family Dwellings and Manufactured Homes, with a 30 minute water supply, is permitted. All habitable areas and closets are sprinklered. Facilities with more than eight residents are treated as two family dwellings with regard to water supply.</p> <p>Exception No. 3: Not Applicable.</p> <p>Exception No. 4: Not Applicable.</p> <p>Exception No. 5: In impractical evacuation</p>			
--	---	--	--	--

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G721		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED  04/02/2014	
NAME OF PROVIDER OR SUPPLIER  AWS				STREET ADDRESS, CITY, STATE, ZIP CODE 6835 W CR 950 N SCIPIO, IN 47273			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
	<p>capability facilities up to and including four stores in height, systems in accordance with NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stores in Height, are permitted. All habitable areas and closets are sprinklered.</p> <p>Exception No. 6: Initiation of the fire alarm system is not required for existing installations in accordance with 33.2.3.5.5.</p> <p>1. Based on record review and interview, the facility failed to ensure sprinkler waterflow alarm devices were tested for 4 of 4 quarters over the past year. LSC 32.2.3.5.2 refers to LSC section 9.7. LSC 9.7.5 refers to NFPA 25, the Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems. NFPA 25 at 2-3.3 requires waterflow alarm devices including but not limited to mechanical water motor gongs and pressure switches that provide audible or visual signals be tested quarterly. Vane-type waterflow devices may be tested semi-annually. This deficient practice could affect all clients and staff.</p> <p>Findings include:</p> <p>Based on review of Koorsen Inc. Report of Inspection on 04/02/14 at 11:10 a.m. with the program manager, the only documentation available for quarterly inspections of waterflow alarm devices</p>	K01S056	<p>Koorsen Fire &amp; Safety Company will complete the following services to the sprinkler system at this group home: A new headwrench for the spare sprinkler headbox. Replacement of the missing sprinkler escutcheon. Pipe adjustments to raise the sprinkler head up. The AWS Director will monitor to ensure that Koorsen Fire &amp; Safety Company perform all inspections prior to the required annual or quarterly due date to ensure compliance with all sprinkler and fire safety equipment standards. Koorsen will forward all reports and findings to the AWS Director for review.</p>	05/02/2014			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G721		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED  04/02/2014	
NAME OF PROVIDER OR SUPPLIER  AWS				STREET ADDRESS, CITY, STATE, ZIP CODE 6835 W CR 950 N SCIPIO, IN 47273			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
	<p>for the sprinkler system was dated 03/19/13. Furthermore, the sprinkler riser inspection tags were inspected at the time of record review and they indicated the last date of a sprinkler system inspection was 03/19/13. The lack of quarterly sprinkler waterflow alarm device tests over the past year was acknowledged by the program manager at the exit conference on 04/02/14 at 11:50 a.m.</p> <p>2. Based on observation and interview, the facility failed to provide a sprinkler wrench in the spare sprinkler cabinet. LSC 32.2.3.5.2 refers to LSC section 9.7. LSC 9.7.5 refers to NFPA 25, the Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems. NFPA 25 in Section 2-4.1.6 requires a special sprinkler wrench to be provided and kept in the cabinet to be used in the removal and installation of sprinklers. One sprinkler wrench shall be provided for each type of sprinkler installed. This deficient practice could affect all clients in the facility.</p> <p>Findings include:</p> <p>Based on observation on 04/02/14 at</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G721		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED  04/02/2014	
NAME OF PROVIDER OR SUPPLIER  AWS				STREET ADDRESS, CITY, STATE, ZIP CODE 6835 W CR 950 N SCIPIO, IN 47273			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
	<p>11:15 a.m. with the program manager, there was no sprinkler wrench in the spare sprinkler cabinet which was located in the garage. This was acknowledged by the program manger at the time of observation and at the exit conference on 04/02/14 at 11:50 a.m.</p> <p>3. Based on observation and interview, the facility failed to ensure 2 of 32 sprinkler heads in the facility were maintained. LSC 32.2.3.5.2 refers to LSC section 9.7. LSC 9.7.5 refers to NFPA 25, the Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems. NFPA 25 at 2-2.1 says sprinklers shall be free of physical damage. This deficient practice could 2 clients who reside in the northwest sleeping room.</p> <p>Findings include:</p> <p>Based on observation on 04/02/14 at 11:20 a.m. with the program manager, the northwest client sleeping room sprinkler above the bed was missing the sprinkler escutcheon and the northwest client sleeping room bathroom sprinkler in the center of the ceiling was missing the sprinkler escutcheon. This was verified the program manager at the time of observation and acknowledged at the exit conference on 04/02/14 at 11:50 a.m.</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G721	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED  04/02/2014
--	---	--	---

NAME OF PROVIDER OR SUPPLIER  AWS	STREET ADDRESS, CITY, STATE, ZIP CODE 6835 W CR 950 N SCIPIO, IN 47273
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE