

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G697	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED  01/19/2012
--	---	--	---

NAME OF PROVIDER OR SUPPLIER  DEVELOPMENTAL SERVICES INC	STREET ADDRESS, CITY, STATE, ZIP CODE 4251 RIVER RD COLUMBUS, IN 47203
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PERCEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
--------------------	--	---------------	---	----------------------

K0000	<p>A Life Safety Code Recertification Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j).</p> <p>Survey Date: 01/19/12</p> <p>Facility Number: 003184 Provider Number: 15G697 AIM Number: 200368720</p> <p>Surveyor: Phillip Komsiski, Life Safety Code Specialist</p> <p>At this Life Safety Code survey, Developmental Services Inc. was found not in compliance with Requirements for Participation in Medicaid, 42 CFR subpart 483.470(j), Life Safety from Fire, and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies.</p> <p>This one story facility was not sprinklered. The facility has a fire alarm system with smoke detection in the corridors, common living areas and all resident sleeping rooms. The facility has a capacity of six and had a census of six at the time of this survey.</p>	K0000		
-------	--	-------	--	--

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ (X6) DATE \_\_\_\_\_

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G697	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED  01/19/2012
--	---	--	---

NAME OF PROVIDER OR SUPPLIER  DEVELOPMENTAL SERVICES INC	STREET ADDRESS, CITY, STATE, ZIP CODE 4251 RIVER RD COLUMBUS, IN 47203
--	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
--------------------	--	---------------	---	----------------------

	<p>Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101 A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Prompt with an E-score of 0.4.</p> <p>Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 01/23/12.</p> <p>The facility was found not in compliance with the aforementioned regulatory requirements as evidenced by the following:</p>			
--	--	--	--	--

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  15G697	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED  01/19/2012
NAME OF PROVIDER OR SUPPLIER  DEVELOPMENTAL SERVICES INC			STREET ADDRESS, CITY, STATE, ZIP CODE 4251 RIVER RD COLUMBUS, IN 47203		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
KS018	<p>Doors are provided with latches or other mechanisms suitable for keeping the doors closed. No doors are arranged to prevent the occupant from closing the door. 32.2.3.6.3, 32.2.3.6.4, 33.2.3.6.3, 33.2.3.6.4</p> <p>Doors are self-closing or automatic closing in accordance with 7.2.1.8</p> <p>Exception: Door closing devices are not required in buildings protected throughout by an approved automatic sprinkler system in accordance with 32.2.3.5.1 and 33.2.3.5.2.</p> <p>Based on observation and interview, the facility failed to ensure 4 of 4 sleeping room doors would close and latch into the door frame. This deficient practice could affect all clients in the facility as well as visitors and staff.</p> <p>Findings include:</p> <p>Based on observations on 01/19/12 at 1:55 p.m. with the House Manager, all four client sleeping room doors were not equipped with self closing devices. Based on interview on 1/19/12 at 1:59 p.m., it was acknowledged by the House Manager none of the client bedroom doors would self close.</p>	KS018	<p>K0018</p> <p>Property manager has been contacted regarding the need for self closing devices on the four bedrooms cited in this survey report. These doors will be equipped with such devices. All group homes not protected throughout by an approved automatic sprinkler system will be inspected for the need for such devices on the bedroom doors and will be repaired to include such devices.</p> <p>Responsible for QA: SGL Manager</p>	02/18/2012	