

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/01/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155787</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>06/24/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>INDIANA VETERANS HOME</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>3851 N RIVER RD WEST LAFAYETTE, IN 47906</b>	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 000	<p>INITIAL COMMENTS</p> <p>A Life Safety Code and Environmental Preoccupancy Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a) for the renovation of resident rooms 224, 225, 324, 325, 424 and 425 into lounge areas .</p> <p>Survey Date: 06/24/15</p> <p>Facility Number: 001134 Provider Number: 155787 AIM Number: 200817200</p> <p>At this Life Safety Code and Environmental Preoccupancy survey, Indiana Veterans Home was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire, and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies with 410 IAC 16.2-3.1-19, Environmental and Physical Standards of the Indiana Health Facilities Rules for Comprehensive care facilities.</p> <p>This facility located in three buildings identified as Mitchell Hall (3 story), Pyle Hall (3 story) and MacArthur Hall (4 story) was determined to be of Type 1 (443) construction and was fully sprinklered. The buildings were surveyed as one since they were all constructed prior to March 1, 2003. MacArthur and Pyle Halls have basements. There is a partial basement under the mechanical room on Mitchell Hall. The facility has a fire alarm system with smoke detection in the corridors, spaces open to the corridors and hard wired smoke detectors in all resident</p>	K 000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients . (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/01/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155787</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>06/24/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>INDIANA VETERANS HOME</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>3851 N RIVER RD WEST LAFAYETTE, IN 47906</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 000	Continued From page 1 sleeping rooms. The facility has a capacity of 331 and had a census of 164 at the time of this survey.  All areas where residents have customary access were sprinklered. All areas providing facility services except for one detached generator building and maintenance shop which were not sprinklered.	K 000		