

**Agency Correction**

LSA Document #09-501(AC)

Under [IC 4-22-2-38](#), corrects the following typographical, clerical, or spelling errors in Indiana Administrative Code:

In [675 IAC 13-1-10](#), after subsection (cc), insert "(dd) Amend Section 6-2 to read as follows: 6-2 Power Source(s). Power shall be supplied to the electric motor-driven fire pump by a reliable source or two or more approved independent sources, all of which shall make compliance with Section 6-4 possible.

Exception: Where electric motors are used and the height of the structure is beyond the pumping capacity of the fire department apparatus, a second source in accordance with 6-2.3 shall be provided." and redesignate the remaining subsections accordingly.

*Filed with Publisher: July 10, 2009, 8:07 a.m.*

*Under [IC 4-22-2-38\(g\)\(2\)](#), this correction takes effect 45 days from the date and time filed with the Publisher.*

*Posted: 07/29/2009 by Legislative Services Agency*

An [html](#) version of this document.