

Company		Mine
<b>Gibson County Coal</b>		<b>Gibson South Mine</b>
Inspection Date:	<b>Wednesday, April 21, 2021</b>	
Areas Inspected:	<b>1st SE, 2A4,2B8 beltlines, primaries, secondary escapeways. Unit #2 faces and equipment.</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Monday, May 3, 2021</b>	
Areas Inspected:	<b>4D2, 1E3, 1F4, 1G1 primary escapeways and beltlines. Unit #1 faces. Power Centers.</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>Pry down loose rocks and ribs along beltlines.</b>	
Inspection Date:	<b>Monday, May 10, 2021</b>	
Areas Inspected:	<b>Belt transformers: CR8671, CR8620A, CR8649, CR8645A, CR8650, CR8643</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Tuesday, May 18, 2021</b>	
Areas Inspected:	<b>Unit #1 air readings, 4A3 Submain left and right returns and intake air readings.</b>	
Findings / Law(s) Violated:	<b>75.517</b>	
Corrective Actions Taken:	<b>Repairs were made to the damaged cable.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Tuesday, May 25, 2021</b>	
Areas Inspected:	<b>Records</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Wednesday, June 2, 2021</b>	
Areas Inspected:	<b>Prep plant, surface belts</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	

cont...

<b>Gibson County Coal</b>		<b>Gibson South Mine</b>
Inspection Date:	<b>Thursday, June 17, 2021</b>	
Areas Inspected:	<b>North Main and 1st North East Main beltlines and primary escapeways</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Monday, June 21, 2021</b>	
Areas Inspected:	<b>1st North East Main #2 primary escapeways, secondary escapeways, and beltlines</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company		Mine
<b>Peabody Midwest Mining</b>		<b>Francisco Mine</b>
Inspection Date:	<b>MONDAY, APRIL 19, 2021</b>	
Areas Inspected:	<b>Unit #3 equipment, faces, rescue chambers, 7th Right beltline, primary escapeway, #817 fuel storage.</b>	
Findings / Law(s) Violated:	<b>75.515</b>	
Corrective Actions Taken:	<b>Hazards have been addressed with management and corrected.</b>	
Recommendation(s):	<b>Check fire extinguisher for proper locking device to prevent accidental discharge. Remind miners that unattended equipment needs wheels to be blocked from motion.</b>	
Inspection Date:	<b>Wednesday, April 28, 2021</b>	
Areas Inspected:	<b>*Records-- Fire Drills, Seal Examinations, Weekly Escapeways, Preshift Book, Belts, Ventilation, etc.</b>	
Findings / Law(s) Violated:	<b>None.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>Include location numbers of pumps to help identify locations more clearly in records.</b>	
Inspection Date:	<b>Tuesday, May 4, 2021</b>	
Areas Inspected:	<b>2, 3, and 4 Main West primary escapeways and beltlines. Power centers, Pumps.</b>	
Findings / Law(s) Violated:	<b>75.518-1</b>	
Corrective Actions Taken:	<b>Hazards have been addressed with management and corrected.</b>	
Recommendation(s):	<b>None</b>	
Inspection Date:	<b>Tuesday, May 11, 2021</b>	
Areas Inspected:	<b>4th West and 2nd East air readings at intake and returns.</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Wednesday, May 19, 2021</b>	
Areas Inspected:	<b>3rd SE Mains, 1st East Panels, SE Mains, 2nd SW Mains SEALS.</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Monday, May 24, 2021</b>	
Areas Inspected:	<b>Prep Plant, Surface Belts, Load-out</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>Make sure fire extinguishers adhere to 30 CFR Part 77.1110</b>	

cont...

<b>Peabody Midwest Mining</b>		<b>Francisco Mine</b>
Inspection Date:	<b>Tuesday, June 15, 2021</b>	
Areas Inspected:	<b>Unit #1 - faces, ram cars, bolters, fuel tank. 2 Left Submain belt drive</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>When performing permissibility, check power cables and trailing cables to ensure they are properly fastened by the packing glands or strain reliefs.</b>	
Inspection Date:	<b>Tuesday, June 22, 2021</b>	
Areas Inspected:	<b>Slope, 1st Main West, and 2nd Main West beltlines, primary escapeways, and secondary escapeways.</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>Have belt examiners train belts to avoid friction with belt structure.</b>	
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company		Mine
<b>Sunrise Coal</b>		<b>Oaktown Fuels #1 Mine</b>
Inspection Date:	Tuesday, April 20, 2021	
Areas Inspected:	M10, M10 1st Left, Panel 2-4 Beltlines and primary escapeways. Unit #2 power centers and equipment.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	Check labels on 120v cables. Batteries for mobile haulage equipment should be locked while in use.	
Inspection Date:	Monday, April 26, 2021	
Areas Inspected:	M11 Primary escapeway, beltline, M12 Primary escapeway, beltline, M8 Seals, M15 Beltdrive,	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	Make sure electrical conductors adhere to 30CFR part 75.513-1	
Inspection Date:	Thursday, May 6, 2021	
Areas Inspected:	Power Centers: BT22, BT14, KVT08, LBT33, BT15, BT19, BT07	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Wednesday, May 12, 2021	
Areas Inspected:	Unit #1 air readings, M9 1st Right return air readings and intake air reading, M9 1st Right Seals.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Monday, May 17, 2021	
Areas Inspected:	Unit #3 air readings, M-11 Split return air readings and intake air readings.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, June 1, 2021	
Areas Inspected:	M5, M5A primary escapeways and beltlines. 3rd East seals, South M5 seals.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	

cont...

<b>Sunrise Coal</b>		<b>Oaktown Fuels #1 Mine</b>
Inspection Date:	<b>Wednesday, June 9, 2021</b>	
Areas Inspected:	<b>M-1, M-2, M-3 Primary escapeways and Beltlines. Belt Transformers #3 and #10.</b>	
Findings / Law(s) Violated:	<b>75.1100-3, 75.1731(a), 75.809, 75.1100-2(b), 75.515</b>	
Corrective Actions Taken:	<b>Violations were addressed with management</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Wednesday, June 16, 2021</b>	
Areas Inspected:	<b>Surface Belts</b>	
Findings / Law(s) Violated:	<b>77.400(a)</b>	
Corrective Actions Taken:	<b>Violation was addressed with management</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Monday, June 28, 2021</b>	
Areas Inspected:	<b>M7 xc 95 to 137 beltline and primary escapeway.</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:	<b>Wednesday, June 30, 2021</b>	
Areas Inspected:	<b>Coal prep plant</b>	
Findings / Law(s) Violated:	<b>No Violations Noted.</b>	
Corrective Actions Taken:	<b>None.</b>	
Recommendation(s):	<b>None.</b>	
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company		Mine
<b>Sunrise Coal</b>		<b>Oaktown Fuels #2 Mine</b>
Inspection Date:	Wednesday, April 14, 2021	
Areas Inspected:	2A, 2B BELTLINES. UNIT #2. 2A, 2B PRIMARIES.	
Findings / Law(s) Violated:	No violations noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, April 27, 2021	
Areas Inspected:	M10, M11, M12 beltlines and primary escapeways. Belt transformers	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	Make sure cables are entering cat heads through approved bushings and strain reliefs.	
Inspection Date:	Wednesday, May 5, 2021	
Areas Inspected:	S1-A, S1-G primary escapeways and beltlines.	
Findings / Law(s) Violated:	No violations noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	
Inspection Date:	Thursday, May 13, 2021	
Areas Inspected:	Unit #2 air readings, S2A left and right returns and intake air readings.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	Make sure that curtains on the working sections are installed properly.	
Inspection Date:	Wednesday, May 26, 2021	
Areas Inspected:	S1-J, S1-H, S1-G Beltlines and primary excapeways, Unit #1	
Findings / Law(s) Violated:	75.173(a), 75.211(d)	
Corrective Actions Taken:	Hazards have been addressed with management and corrected.	
Recommendation(s):	None.	
Inspection Date:	Tuesday, June 8, 2021	
Areas Inspected:	M-1, M-2, M-3 Primary escapeways and beltlines, M-1 Seals.	
Findings / Law(s) Violated:	No Violations Noted.	
Corrective Actions Taken:	None.	
Recommendation(s):	None.	

cont...

<b>Sunrise Coal</b>		<b>Oaktown Fuels #2 Mine</b>
Inspection Date:	Wednesday, June 16, 2021	
Areas Inspected:	Surface Belts	
Findings / Law(s) Violated:	77.1104	
Corrective Actions Taken:	Violation was addressed with management	
Recommendation(s):	None.	

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		