

Company		Mine
<b>Alliance Coal</b>		<b>Gibson County Coal South</b>
Inspection Date:	Friday, January 5, 2024	
Areas Inspected:	Unit #4, 2nd Northwest Submain Primary, 2nd NorthWest Submain Belt, Northwest main travelway	
Findings / Law(s) Violated:	75.333(b), 75.202(a)	
Corrective Actions Taken:	The holes in the stopping were repaired immediately. The B.O. area was dangered off	
Recommendation(s):	2A transfer point needs cleaned, Dust adjacent intake entieres on the 2nd Northwest Primary	
Inspection Date:	Wednesday, January 10, 2024	
Areas Inspected:	1 SE Belt and Travelway, 1 SE2 Belt and Travelway, SCSR Cach3 XC-60, CR 8641, CR 8624A	
Findings / Law(s) Violated:	75.1100-3	
Corrective Actions Taken:	The Fire extinguisher was examined and properly tagged	
Recommendation(s):	Continue dusting 1SE Belt and shovel to XC-10, transfer sprays need to be working while product is in motion.	
Inspection Date:	Wednesday, January 17, 2024	
Areas Inspected:	Books/Records	
Findings / Law(s) Violated:	Good	
Corrective Actions Taken:	None	
Recommendation(s):	None	
Inspection Date:	Thursday, January 25, 2024	
Areas Inspected:	1st SoutheastSub Main Belt and travelway XC-82 to the end, CR 8645-1, LP 8445 D, 3A Belt and travelway	
4 Findings / Law(s) Violated:	75.202(a)	
Corrective Actions Taken:	Addressed the area with the mine operator	
Recommendation(s):	1st SE Submain belt needs spot celaned and broomed under the belt, belt sprays need attention, rock dust the transfer points	
Inspection Date:	Thursday, February 1, 2024	
Areas Inspected:	1 SouthEast Intake and Right Return, I Seals, R Seals	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:		
Recommendation(s):	XC-110 to XC-111 belt line needs spot cleaned on intake side of belt	
Inspection Date:	Friday, February 9, 2024	
Areas Inspected:	1st SouthEast left retun, E seals, G seals, W seals, X seals	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	W seals could use a little maitenance.	

cont...

<b>Alliance Coal</b>		<b>Gibson County Coal South</b>	
Inspection Date:	Thursday, February 15, 2024		
Areas Inspected:	1 SouthEast 2 Beltand haulage XC-80 to tail, 4A4 Panel Neutrals		
Findings / Law(s) Violated:	None		
Corrective Actions Taken:	None		
Recommendation(s):	None		
Inspection Date:	Thursday, February 22, 2024		
Areas Inspected:	Unit #1		
Findings / Law(s) Violated:	75.370(a)(1), 75.370(b)(2), 75.370(a)(1)		
Corrective Actions Taken:	Ventilation controls were adjusted properly		
Recommendation(s):	Maintain ventilation controls in accordance with the approved mine ventilation plan.		
Inspection Date:	Wednesday, February 28, 2024		
Areas Inspected:	2NW Submain belt and travelway, 2A Panel Belt and travelway, CR8689A, MCI 8480, CR8659A		
Findings / Law(s) Violated:	75.362(g)(1), 75.809		
Corrective Actions Taken:	The cable was properly Identified. The operator has agreed to hold a safety meeting with examiners.		
Recommendation(s):	None		
Inspection Date:	Monday, March 11, 2024		
Areas Inspected:	1st SW Main Belt and travelway, 1st SW 2 Main Belt and travelway, CR8681, MCI 18479, CR8600		
Findings / Law(s) Violated:	75.807		
Corrective Actions Taken:	Management was checking into guarding supplies.		
Recommendation(s):	Need to rock dust from belt drive 10 cross cuts inby and piggyback drive area		
Inspection Date:	Monday, March 18, 2024		
Areas Inspected:	Unit #2, MCI8891, CR8207		
Findings / Law(s) Violated:	75.208		
Corrective Actions Taken:	The area was properly dangered off		
Recommendation(s):	Train on the proper method of gas checks at the face.		
Inspection Date:	Wednesday, March 27, 2024		
Areas Inspected:	1st NorthEast Main Neutral, CR8643, H Seals, Y Seals		
Findings / Law(s) Violated:	None		
Corrective Actions Taken:	None		
Recommendation(s):	None		

Company		Mine
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

cont...

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Company		Mine
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

cont...

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Company		Mine
<b>Peabody Midwest Mining</b>		<b>Francisco Mine</b>
Inspection Date:	<b>Wednesday, January 3, 2024</b>	
Areas Inspected:	<b>Unit #1</b>	
Findings / Law(s) Violated:	<b>75.220(a)(1), 75.220(a)(1) Section 5 of the approved roof control plan.</b>	
Corrective Actions Taken:	<b>The operator began spot bolting the mine roof in affected areas.</b>	
Recommendation(s):	<b>Met with maintenance and roof bolter operators about properly adjusting the booms on the machines.</b>	
Inspection Date:	<b>Sunday, January 7, 2024</b>	
Areas Inspected:	<b>Unit #1, Main West 10 travelway, Main West 10 Right return</b>	
Findings / Law(s) Violated:	<b>75.220(a)(1) Section 5 of the approved roof control plan</b>	
Corrective Actions Taken:	<b>Areas were spot bolted</b>	
Recommendation(s):	<b>Need to double check existing roof bolt spacing/patterns. Remove trash and unused materials from the right return ouby the unit.</b>	
Inspection Date:	<b>Tuesday, January 30, 2024</b>	
Areas Inspected:	<b>9 West Primary to XC-70, XC-7Rescuer Cache, 9 West Left Return to XC-70</b>	
Findings / Law(s) Violated:	<b>None</b>	
Corrective Actions Taken:	<b>None</b>	
Recommendation(s):	<b>9 West intake needs added roof support in nitch at xc-10, Primary could use more rock dust from XC-23 to XC-70.</b>	
Inspection Date:	<b>Monday, January 22, 2024</b>	
Areas Inspected:	<b>9 West Belt and travelway, BT 5022, Bt 5104, BT 5054, BT 5103</b>	
Findings / Law(s) Violated:	<b>None</b>	
Corrective Actions Taken:	<b>None</b>	
Recommendation(s):	<b>Continue to rock dust the belt lines, Need to change B.O&gt; rollers</b>	
Inspection Date:	<b>Wednesday, February 7, 2024</b>	
Areas Inspected:	<b>Records</b>	
Findings / Law(s) Violated:	<b>None</b>	
Corrective Actions Taken:	<b>None</b>	
Recommendation(s):	<b>None</b>	
Inspection Date:	<b>Wednesday, February 14, 2024</b>	
Areas Inspected:	<b>2 Left Panel Belt and travelway, 5 West Submain Belt and travelway, BT; 2058,5000,5040,5015,5016,5102</b>	
Findings / Law(s) Violated:	<b>None</b>	
Corrective Actions Taken:	<b>None</b>	
Recommendation(s):	<b>2L panel and 5W belt lines need rock dusted soon.</b>	

cont...

<b>Peabody Midwest Mining</b>		<b>Francisco Mine</b>
Inspection Date:	<b>Tuesday, February 20, 2024</b>	
Areas Inspected:	<b>Unit #3, 1st Right Belt and travelway, 4 left Belt and travelway</b>	
Findings / Law(s) Violated:	<b>75.370(a)(1), 75.323, 75.402</b>	
Corrective Actions Taken:	<b>ventilation adjustments were made. Float dust issues at belt drive were being addressed.</b>	
Recommendation(s):		
Inspection Date:	<b>Monday, February 26, 2024</b>	
Areas Inspected:	<b>5 West SubMain; 2 Left Panel; 4 Left; 1st Right Intakes &amp; Left Retruns</b>	
Findings / Law(s) Violated:	<b>None</b>	
Corrective Actions Taken:	<b>None</b>	
Recommendation(s):	<b>Some of these areas need rock dusted.</b>	
Inspection Date:	<b>Tuesday, March 5, 2024</b>	
Areas Inspected:	<b>Main West 8 Belt and travelway, XC-115 Cache, BT: 5037, 5021, 5011, 5026, VB 5042</b>	
Findings / Law(s) Violated:	<b>75.601-1</b>	
Corrective Actions Taken:	<b>The instantaneous over-current setting were adjusted properly.</b>	
Recommendation(s):	<b>MW-8 XC-126 needs cleaned out so that the personnel door will be accessible.</b>	
Inspection Date:	<b>Wednesday, March 13, 2024</b>	
Areas Inspected:	<b>8 Main West Intake and Return</b>	
Findings / Law(s) Violated:	<b>None</b>	
Corrective Actions Taken:	<b>None</b>	
Recommendation(s):	<b>Maintain rock dusting in Retruns</b>	
Inspection Date:	<b>Wednesday, March 20, 2024</b>	
Areas Inspected:	<b>7 West Main Belt and travelway, VB-5105 and 5110, BT 5036 and 5019</b>	
Findings / Law(s) Violated:	<b>75.202(a)</b>	
Corrective Actions Taken:	<b>The area was dangered off</b>	
Recommendation(s):	<b>Keep replacing belt rollers, &amp; West belt needs spot cleaned. Keep belts properly trained.</b>	
Inspection Date:	<b>Monday, March 25, 2024</b>	
Areas Inspected:	<b>Unit #1, 1st right belt and travelway, UT5001, UT5004, BT5043</b>	
Findings / Law(s) Violated:	<b>75.370(a)(1)</b>	
Corrective Actions Taken:	<b>Ventilation was restored.</b>	
Recommendation(s):	<b>Keep curtain work and ahnd dusting current.</b>	



Company		Mine
<b>Peabody Midwest Mining</b>		<b>Francisco Mine</b>
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

cont...

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Company		Mine
<b>Sunrise Coal</b>		<b>Oaktown Fuels #1 Mine</b>
Inspection Date:	Thursday, January 4, 2024	
Areas Inspected:	Unit #4, Emergency Sled P4-4, SG-4, SF-4 belts and travelways, BT#2, T #8, BT 1, KBT 32, UT#1	
Findings / Law(s) Violated:	75.1100-3	
Corrective Actions Taken:	The fire extinguisher tag was updated.	
Recommendation(s):	Keep ventilation controls in place on the unit to avoid the build-up of Methane, clean P4-4 belt, grade the travelways from SD-4 to unit #4	
Inspection Date:	Tuesday, January 9, 2024	
Areas Inspected:	P3-3 Belt to XC-20, P3-3 travelway to XC-20, S3E Belt and travelway, S3C Belt and travelway XC-76 to end	
Findings / Law(s) Violated:	75.323	
Corrective Actions Taken:	Equipment in the area was de-energized and the ventilation wa adjusted.	
Recommendation(s):	Protect communication cables and make repairs immediately, Spot clean S3C Xc 76 to tail	
Inspection Date:	Tuesday, January 16, 2024	
Areas Inspected:	S3C Belt and travelway, LBT07, MC-6, BT28	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	MC-6 cable splices need re-insulated. Make sure equipment cables are properly labeled at transformers. S3C belt could be raised and spot cleaned.	
Inspection Date:	Wednesday, January 24, 2024	
Areas Inspected:	P3-2 Return loop, P3-2 Right reutrnr, T-14 VCB, T-22	
Findings / Law(s) Violated:	75.364(b)(2), 75.202(a)	
Corrective Actions Taken:	The area is being examiner by the operator	
Recommendation(s):	Have a meeting with all examiners informing them of their responsibilities. Make sure the map data on the surface accurately rfects the data in the mine.	
Inspection Date:	Monday, February 5, 2024	
Areas Inspected:	S3c Intake and return, XC-24 and 73 SCSR Cache	
Findings / Law(s) Violated:	75.333(b)(1)	
Corrective Actions Taken:	Addressed with management	
Recommendation(s):	Use sealant on wall after they have been breached for waterlines, cables, and such.	
Inspection Date:	Tuesday, February 13, 2024	
Areas Inspected:	P3-1 Return Loop	
Findings / Law(s) Violated:	75.1200	
Corrective Actions Taken:	Changes were made to the mine map on the surface	
Recommendation(s):	The map on the surface must reflect ventilation controls underground.	

cont...

<b>Sunrise Coal</b>		<b>Oaktown Fuels #1 Mine</b>
Inspection Date:	Wednesday, February 21, 2024	
Areas Inspected:	Unit #1, P1-5 Belt and travelway, UT-3, KBT-31	
Findings / Law(s) Violated:	75.202(a), 75.811, 75.904, 75.202(a), 75.202(a)	
Corrective Actions Taken:	All dangerous areas were dangered out and being addressed. The circuit breaker was properly identified. The highline tub was properly grounded.	
Recommendation(s):	Rocks need removed from the walkway along the P1-5 belt line.	
Inspection Date:	Tuesday, February 27, 2024	
Areas Inspected:	S3-B belt and travelway, M-17 Belt and travelway tail to XC-35, BT12, LDVB10, T27, DBB-1	
Findings / Law(s) Violated:	75.202(a)	
Corrective Actions Taken:	Area was dangered off, a ker-thob was installed on the roof bolt	
Recommendation(s):	Grade and water roads to units #1 and #4	
Inspection Date:	Monday, March 4, 2024	
Areas Inspected:	M-17 1st Right belt and Travelway, M-17 Belt to XC-35	
Findings / Law(s) Violated:	75.371 (u)(8) of the approved ventilation plan	
Corrective Actions Taken:	A mechanic was called to repair the belt transfer spray	
Recommendation(s):	M-17 1st Right Belt needs trained and cleaned. M-17 Needs dusted XC_15 to XC-25	
Inspection Date:	Tuesday, March 12, 2024	
Areas Inspected:	S3-B Intake and Return, M17 Intake and return End to Xc-53	
Findings / Law(s) Violated:	75.220(a)(1) Appendix B of the approved roof control plan	
Corrective Actions Taken:	The area was flagged off/dangered out.	
Recommendation(s):	S3-B xc-13-17 could use floor to roof support. S3-B xc-5 could use additional roof support at mandoor. Make sure to seal stoppings after the reulator has been filed.	
Inspection Date:	Tuesday, March 19, 2024	
Areas Inspected:	Unit #2, UT-13, 2 East Intake, 2 East Right Return	
Findings / Law(s) Violated:	75.202(a)	
Corrective Actions Taken:	The area was dangered out.	
Recommendation(s):	Need to tighten-up face ventilation, make sure that electrical connection points are properly identified.	
Inspection Date:	Tuesday, March 26, 2024	
Areas Inspected:	M16 Belt and travelway, M15 Belt and travelway. T24, 17, and 3. BT 4, 18, and 37. MC 2	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	M15 belt needs properly trained, M16 XC-79 gob needs cleaned for better access between haulage and belt to the mandoor.	

Company		Mine
<b>Sunrise Coal</b>		<b>Oaktown Fuels #2 Mine</b>
Inspection Date:	Tuesday, January 2, 2024	
Areas Inspected:	S1-2 Primary, S1-2 Belt to XC20, Unit 1, Unit 1 Emergency sled	
Findings / Law(s) Violated:	75.333(b)(3)	
Corrective Actions Taken:	Addressed the issued with management	
Recommendation(s):	S1-2 Primary, pump water at XC-10 and 20 , Croosbars shoul;d be supported by floors to roof support.	
Inspection Date:	Thursday, January 11, 2024	
Areas Inspected:	M9 Belt and travelway, m10 Belt and travelway, M11 Belt and travelway to XC-69	
Findings / Law(s) Violated:	75.1100-3	
Corrective Actions Taken:	The fire extinguisher was inspected and properly tagged.	
Recommendation(s):	M9 belt needs rock dusted, M9 XC-1 madoor to the primary escapeway needs maintained, M10 drive to XC-14 needs spot cleaned.	
Inspection Date:	Thursday, January 18, 2024	
Areas Inspected:	M8 Belt and travelway, Kbt 17, T-7, DVB-08, LBT 21	
Findings / Law(s) Violated:	75.1403-5(g)	
Corrective Actions Taken:	Addressed with management	
Recommendation(s):	Make sure transfer sprays are working while product is on the belt. Clear walkways btween haulage and belt where manddoors are located to access the primary escapeway.	
Inspection Date:	Monday, January 29, 2024	
Areas Inspected:	M8 Intake and Return, M7 XC-72, XC-15 Self rescuer cache	
Findings / Law(s) Violated:	75.202(a), 75.333(b), 75.333(c)(3)	
Corrective Actions Taken:	The walkway was cleared. A timber was set at the B.O. roof bolt, the leaky stoppings were addressed with management.	
Recommendation(s):		
Inspection Date:	Friday, January 26, 2024	
Areas Inspected:	M8 Belt and travelway, KBT17, T7, DVB08, LBT21, XC_13 SCSR cache	
Findings / Law(s) Violated:	75.1403-5(g)	
Corrective Actions Taken:	Addressed with management	
Recommendation(s):	Maintain belts sprays, keep walkways clear between haulage and belt where manddoors are located.	
Inspection Date:	Thursday, February 8, 2024	
Areas Inspected:	M10 Left return, M9 Seals and left return	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	None	

cont...

<b>Sunrise Coal</b>		<b>Oaktown Fuels #2 Mine</b>
Inspection Date:	<b>Monday, February 19, 2024</b>	
Areas Inspected:	<b>Unit #1, S1-2 Belt and travelway XC-20 to tail, S1-3 Belt and travelway</b>	
Findings / Law(s) Violated:	<b>75.370 Appendix B Sketch 3, 75.202(a), 75.1725(a)</b>	
Corrective Actions Taken:	<b>The bad area was flagged off. The curtain was rolled down. The bolter is being repaired</b>	
Recommendation(s):	<b>Maintain proper ventilation controls.</b>	
Inspection Date:	<b>Thursday, February 29, 2024</b>	
Areas Inspected:	<b>M7 Belt and travelway, LUT-03, T-49</b>	
Findings / Law(s) Violated:	<b>75.601-1</b>	
Corrective Actions Taken:	<b>The instantaneous trip setting was adjusted correctly.</b>	
Recommendation(s):	<b>None</b>	
Inspection Date:	<b>Wednesday, March 6, 2024</b>	
Areas Inspected:	<b>M-7 Intake and Return</b>	
Findings / Law(s) Violated:	<b>None</b>	
Corrective Actions Taken:	<b>None</b>	
Recommendation(s):	<b>None</b>	
Inspection Date:	<b>Thursday, March 14, 2024</b>	
Areas Inspected:	<b>Unit #1</b>	
Findings / Law(s) Violated:	<b>None</b>	
Corrective Actions Taken:	<b>None</b>	
Recommendation(s):	<b>Watch for the slips just outby the last open</b>	
Inspection Date:	<b>Thursday, March 21, 2024</b>	
Areas Inspected:	<b>S1-A, M-7A, and M8-A Seals</b>	
Findings / Law(s) Violated:	<b>None</b>	
Corrective Actions Taken:	<b>None</b>	
Recommendation(s):	<b>S1-A Seals, a ziggy bar needs straightened up ay #6 seal.</b>	
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company		Mine
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

cont...

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	



Company		Mine
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

cont...

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	