

Indiana State Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15C0001031		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING	(X3) DATE SURVEY COMPLETED 10/27/2022
NAME OF PROVIDER OR SUPPLIER MARION EYE SPECIALISTS SURGERY C		STREET ADDRESS, CITY, STATE, ZIP CODE 711 W GARDNER DR , MARION, Indiana, 46952			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
S0000	<p>INITIAL COMMENTS</p> <p>This visit was for a state licensure survey of an Ambulatory Surgery Center.</p> <p>Facility Number: 005975</p> <p>Survey Date: 10-26-2022 to 10-27-2022</p> <p>QA: 11/03/2022</p>	S0000			
S0400	<p>INFECTION CONTROL PROGRAM</p> <p>CFR(s): 410 IAC 15-2.5-1</p> <p>410 IAC 15-2.5-1(a)</p> <p>(a) The center shall provide a safe and healthful environment that minimizes infection exposure and risk to patients, health care workers, and visitors.</p> <p>This LICENSURE REQUIREMENT is NOT MET as evidenced by:</p> <p>Based on document review observation and interview, the facility failed to implement an environment that minimizes infection exposure and risk to patients and healthcare workers by not ensuring operating room walls were able to be cleaned to be free from contamination for 1 of 2 operating rooms. (Operating Room #2)</p> <p>Findings include:</p> <p>1. A review of facility policy titled "CLEANING OF</p>	S0400			

Office of Primary Care and Health Systems Management

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
---	-------	-----------

Indiana State Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15C0001031		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING	(X3) DATE SURVEY COMPLETED 10/27/2022
NAME OF PROVIDER OR SUPPLIER MARION EYE SPECIALISTS SURGERY C		STREET ADDRESS, CITY, STATE, ZIP CODE 711 W GARDNER DR , MARION, Indiana, 46952			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
S0400	<p>Continued from page 1</p> <p>OPERATING ROOMS" last approved 8/10/22 indicated the following: "...Policy: Operating rooms shall be cleaned so aseptic technique can be maintained to reduce the potential for infection...Function: Provide an environment as clean and free from contamination as possible for patients and staff..."</p> <p>2. A review of facility policy titled "HOUSEKEEPING SERVICES" last approved 8/10/22 indicated the following: "...Policy: All areas of the Center shall be maintained at an appropriate level of cleanliness relative to their function...Practice & Procedures...7. Cleaning Procedures...Operating Rooms...Scope of Work...Wipe down walls...Monthly..."</p> <p>3. During facility tour with N4 (Director of Nursing) of Operating Room #2 on 10/27/22 at approximately 1:40 p.m., the operating room wall located to the right upon entering the room was observed to have a wall mounted C-locker and bubbling/wrinkled tan wall covering/wallpaper. Upon further examination, the wall covering/wallpaper was observed to be pulled away from the wall. While feeling the wall with palm of hand, brown and white particles fell from behind the loose wall covering/wallpaper. The loose wall covering/wallpaper flap was lifted up and observed to have brown and white loose material along with black spots on the back of the wall covering/wallpaper and the wall underneath. A red airway cart in front of the same wall was moved and additional loose wall covering/wallpaper was observed. The tan colored wall covering/wallpaper also had a pink/purple discoloration on the top side of the wall covering/wallpaper. The loose wall covering/wallpaper flap was lifted up and observed to have brown and white loose material along with a pink/purple discoloration and black spots on the back of the wall covering/wallpaper and the wall underneath. The wall was approximately 16 feet in length and approximately 9 feet in height. The wall covering/wallpaper was loose from the bottom of the wall covering/wallpaper at the metal trim for approximately 16 feet in length. The wall covering/wallpaper was loose approximately 4 feet high from the metal trim on the wall for approximately 8 feet in length of the wall.</p> <p>4. During an interview with N4 on 10/27/22 at 2:42 p.m., he/she verified that the wall covering in the operating rooms should be intact, easily</p>	S0400			

Indiana State Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 15C0001031		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING	(X3) DATE SURVEY COMPLETED 10/27/2022
NAME OF PROVIDER OR SUPPLIER MARION EYE SPECIALISTS SURGERY C		STREET ADDRESS, CITY, STATE, ZIP CODE 711 W GARDNER DR , MARION, Indiana, 46952			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
S0400	Continued from page 2 cleanable/disinfected.	S0400			